

# Unit # BTP 84 CASE SKIDSTEER 1845C

Mileage \_\_\_\_\_

Hrs 4919.7 BHLB

F01-23

SERIAL # JAF0251288

Date	Description of Work	Parts Costs	Labour Costs
May/13 WO#0041	Service and change oil in engine, change oil in chain boxes (80W90), repair bracket for bucket broom, check throttle linkage (repair put new spring), check tire pressures (50pst), wash. (Gilbert/Leo)		
Nov 5/13	Wash, change oil engine, repair lights, check all tires (air pressure) 4328.2 hrs (Leo/Gilbert)		
Mar/14 WO#0109	Repair wiring harness (Yves Brousseau)		
Apr 6/16 WO#0211	Wash, service, repair left front tire (new tube)		
Nov 10/17 WO#0251	Wash. Service engine. New air & fuel filters. Check & service chain boxes. Change oil in both chain boxes. Install two new drain covers & seals. Repair seat. Adjust drive chains. Install new pins & bushings in quick attach. 5237 Hours	5237	
Nov 4/19 WO#0312	Change oil and air filter. Wash. Check all fluids. Change head light. Grease. 5853 Hours	5853	Hours
Mar 5/20 WO#0337	Change fan belt.		
May29/20 WO#0353	No start fuel rack. Not opening to deliver fuel to injectors, pulled injection pump and sent to GCL Diesel Edmonton.		
June 12/20	Install injection pump, replaced water pump, alternator timing cover gasket and seal, hyd pump drive and pump.		
June16/20	Complete BTP84. Had to re3wire one relay Leo had changed, replaced fuel filter and start unit.		
June17/20	Pulled injectors, ordered new from Hammer.		
June22/20 WO#0353	Cleaned injector holes and installed.		
July 2/20 WO#0368	Compression test on engine. Pull injectors, #1 cyl 410PSI #2 cyl 4015PSI #3 cyl 400PSI #4 cyl 400PSI. Pull engine and removed injection pump to send to GCL in Edmonton. Installed pump and timing cover, installed engine in unit, start and adjust governor.		
Mar23/21 WO#0395	Disassembled and start assembly, and waiting for Swisco to finish handles. Completed assembly and waiting for shocks. Completed assembly and made all adjustments. Replaced work lites with LED lites. Wash. Service engine. Check all fluids. Repair hyd and steer linkage. Install new lights (work). 6017 Hours	6017	Hours
Date	Description of Work	Parts Costs	Labour Costs

BTP 84