

EOI-37
Blues

Unit # BTP 87

ARNES END DUMP

Mileage _____

Hrs _____

Serial # 2A9073225VA003228

Date	Description of Work	Parts Costs	Labour Costs
JAN16/13 WO#0007	Repair all lights, fill wheel with oil, CVIP & B&D, Put new brakes and drums both axles, re-line box with $\frac{3}{4}$ plywood (16 ft.), 4 wheel seals	188.12	
	Install new backing plates on axles. Sent out invoice	(LEO & GILBERT)	477.75
Nov 21/13 WO#0087	Repair tarp (new cables, slider, board & bearings) Install new flap in front of box. Repair lights.		
Jan 14/14 WO#0099	CVIP, change some reflective tape. Weld crack in box on right side. Install grease line for hyd. cylinder. (LEO & GILBERT)		
Jan13-15	CVIP replace stroke indicator LHS. RHS #1 Axle hub cover leaking (replace) install new light bar left side. Install new junction box.		
Feb 11/16 WO#0200	Repair reflective tape on bulk head (rear of box). CVIP B&D Industrial CVIP		
Jan 17/17	CVIP Done by B&D Industrial Service – Invoice #22297	298.71	
Jan17/17 WO#0223	Remove wheels for CVIP, install new seals and fill with oil, service grease, put new bulkhead tape.		
Mar28/17 WO#0237	Replace floor on end dump renn trailer, install new bulkhead tape, install new plywood lining.		
Jan10/18	CVIP done by B & D Industrial: Invoice 24232	324.96	
Feb 5/18 WO#0272	CVIP. Replace plugin for light cable. Install screens on glade hands. Install reflector tape on rear.		
Mar25/19 WO#0307	CVIP. Put on new reflective tape. Check and repair air leak. Put new stem valve cover.		
Feb05/2020 WO#0331	CVIP. Check all lights. Repair mud flaps.		
Dec14/2020 WO#0414	CVIP. No repairs.		
Nov9/21 WO#0440	CVIP. Change reflective tape on bulk head. Weld cracks under box on frame. Grease.		

