

EOI-38
BLUE**Unit # BTP 89****RENN END DUMP**

Mileage _____

Hrs _____

SERIAL# 1019387

Date	Description of Work	Parts Costs	Labour Costs
JAN/13 WO#0002	INSTALL NEW SHOE & BRAKE CHUM #4 AXLE RIGHT SIDE (LEO)	208.00	
JAN/13 WO#0010	CUIP & B&D Industries – Install brake pot plug, check and repair all lights, re-line box with $\frac{3}{4}$ plywood (16 ft.) (LEO)		
Nov /13	Repair tarp (new bearings and cable), install new side boards, install stainless steel chainsaw drive motor (Leo/Gilbert)		
Jan/14	CVIP, repair all air lines at axles, repair ABS wiring & secure.		
Nov 28/14	Repair landing gear. Repair all lights.		
Jan 12/15	CVIP, repair ABS light, repair crack in crossmember at cylinder. Repair crack at frame rail where suspension welded on. #2 axle left inner tire (replace). Change wheel sensor or ABS brakes.		
Feb 11/2016	CVIP done by B&D Industrial		
Mar14/17 WO#0232	Check all brakes, repair hyd cylinder, install new brake on left #2 axle and drum, install new plywood in box, weld crack on frame, install new bulk head tape.		
Mar14/17	CVIP done by B&D Industrial		284.49
Jan12/18 WO#0262	CVIP done. Install new air trip valve.		
Jan 19/18	CVIP done by B & D Industrial: Invoice 24218	324.96	
Dec10/18 WO#0286	CVIP. RH side rear brake pot. Weld up crack on cross members and box frame. Landing gear binding. Replace RHside rear tire(used from Fountain Tire)	210.00	
Jan20/20 WO#0319	CVIP. Change reflective tape on box. Install reflectors on mud flaps. Weld up fender brackets.		
June25- 26/20 WO#0363	Pulled unit in shop and removed top boards on end dump. Ordered new pressure treated boards from Co-op to be delivered.Cut and drill new boards, paint and install.		

