

E01-55
BLUE

Unit # BTP 112

2000 FORD F450

Mileage _____

Hrs _____

SERIAL # YB47227

Date	Description of Work	Parts Costs	Labour Costs
JUN/13 WO #48	Install and paint gravel box and hoist, wire lights on truck and box, install trailer plug in and brake controls CVIP (B&D), check all fluids, fabricate pintole hitch, repair power steering hose, install new water pump, install new alternator, new oil pressure sender (LEO) Mileage 140,282		
Sept/13	Repair passenger door latch (LEO) Mileage 140,411		
Oct/13	Install new engine (Long Block Zarowny's), install 2 new engine motor mounts, install new pinion seal front diff (ZAROWNYS) MILEAGE 140,456		
Aug27/14	CVIP repair, repair cooler lines, weld up rad support (cracks), replace right side U joint and new seals, repair pak bache, repair electric horn, repair lights (dash) and repair mirror		
Feb3-15	Service, CVIP, rear diff seal leaking, install new seal, repair brake booster (install new). Install new battery. Repair heater switch, selector switch. Engine not working. Install new long block warranty. Install new power steering pump. Zarowny's also installed new starter. Remove tint from driver side window. 140467 kms		
Feb 26-15	Repair windshield wipers. Install new motor (windshield wiper). Unsieze mechanism. Send truck to Zarowny's for engine light problem. Send back on march 2 for engine oil leak. Engine oil cooler leaking – repaired by Zarowny's. Mileage: 140514		
Feb 2-2016 WO#0197	CVIP. Repair air bag. Repair cab lights. Replace bulk head tape. Install master switch. CVIP done by B&D Industrial		
Feb22/17	CVIP done by B&D Industrial		318.88
Feb24/17 WO0231	Remove all wheels for CVIP, check all tire pressures, repair flat, repair wipers, install new blades and check and repair drive line (out of phase). MILEAGE 140771		
Jan 30/18 WO#0271	CVIP done. Repair windshield wiper. Install new arm.		
Jan29/18	CVIP done by B & D Industrial: Invoice 24353	385.96	
Jan14/19 WO#0296	CVIP. Wash. Install new throttle cable. Install new RH front spring bushing. Install new rubber boot on calipers. Install new RF seal axle. MILEAGE 141350		
Jan27/2020 WO#0324	CVIP. Repair brake pedal (install pad). Repair RH front axle seal leak. MILEAGE 141555		
May29/20 WO#0354	Roman called to indicate BTP112 has a miss in engine. Checked over, checked plugs..new. Found carbon canister has a vacuum leak. Removed hose to canister and plugged off.		

