

Lot-83
GR-FEB

Unit	Model	Date	Work Order Details
1097	777F	6/9/2023	Drained 20l of coolant from oil pan. Barred engine over to make sure it wasn't locked up. Stripped for wash.
1097	777F	6/10/2023	Check over unit
1097	777F	6/26/2023	Remove damaged chock mount. Modified and installed new chock mount
1097	777F	9/29/2023	Drain oil and remove pan, coolant leaking on inside of liner cyl 7 and 8, remove rocker shaft and injector on cyl 8, roll engine over to bdc, inspect with camera, can see coolant creeping in at top of liner or possible head gasket, begin engine disassembly