



Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

H14-1
GR-FEB
Work Order #: 52

CREATED BY	DATE
Nathan Bower	28 Feb 2023
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
4,362.00	

Description of Work

-Replace Transmission accumulator-
920923 FINNING D6T 6162 13817527 TRANS ACCUMULATOR \$708.78

Summary of Labour

Date	Employee	Work Type	Description	Hours
28 Feb 2023	Kirk Russell	Shop Mechanic	replace accumulator	2.00



Work Order #: 68

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nathan Bower	29 Mar 2023
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
4,363.00	

Description of Work

PM-2 SERVICE AND SPRING CHECKOVER

-Change engine oil and all filters including inner/outer air filters, sampled all oils. Replaced ether solenoid from stock. Repaired positive air shutoff not working, replaced module and connector with ordered parts from Headwind Solutions, and replaced 30AMP circuit breaker. Removed and replaced broken bolts on LHS C-frame step. Dropped and cleaned stump pans. Bent front idler rock guards back into position and painted. Detailed cab.

Summary of Labour

Date	Employee	Work Type	Description	Hours
14 Mar 2023	Connor Tiller	Shop Mechanic	Checkover machine	10.00
15 Mar 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	10.00
21 Mar 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	10.00
22 Mar 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	4.00
16 Mar 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	8.00
17 Mar 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	2.00
13 Mar 2023	Connor Tiller	Shop Mechanic	pm-2 service	4.00
20 Mar 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	4.00



Work Order #: 204

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nathan Bower	3 Jun 2023
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
4,577.00	

Description of Work

Replace failed RH front idler in field. Torqued idler and track master link to specifications.
922642 2-Jun-23 FINNING D6 6162 PI000088762 LF TRACK IDLER \$2,061.51

Summary of Labour

Date	Employee	Work Type	Description	Hours
3 Jun 2023	Nathan Bower	Field Mechanic	replace idler	3.00
3 Jun 2023	Connor Tiller	Field Mechanic	replace idler	3.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	14 Jun 2023
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
4,661.00	0.00

Description of Work
PM-1 Service (250hr) - Completed pm-1 check over service. Greased machine.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
14 Jun 2023	Dexter Reese	Field Mechanic	Service	0.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	28 Aug 2023
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
4,928.00	0.00

Description of Work
PM-4 Service (2000hrs) - Completed a pm-4 service. Changed all the oil and filters. Greased machine.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
28 Aug 2023	Dexter Reese	Shop Mechanic	Service	0.00



Work Order #: 345

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	31 Aug 2023
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
4,997.00	

Description of Work

Undercarriage Repairs - Split tracks and replaced segments. Pushed cat onto new rails. Replaced three rollers before connecting tracks. FLHS, FRHS and a double flange on the LHS. Connected tracks and adjust tracks to spec.

Summary of Labour

Date	Employee	Work Type	Description	Hours
31 Aug 2023	Connor Tiller	Field Mechanic	Undercarriage repairs	12.00



Work Order #: 346

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	1 Sep 2023
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
5,123.00	

Description of Work

Differential pressure sensor code. R/I differential pressure sensor and ran aftertreatment functional test. Code went away.

Summary of Labour

Date	Employee	Work Type	Description	Hours
1 Sep 2023	Connor Tiller	Field Mechanic	T/R Differential pressure sensor	2.00



Work Order #: 1842

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	19 Oct 2023
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
5,206.00	0.00

Description of Work

PM-1 Service (250hr) - Completed pm-1 check over service. Greased machine.

Summary of Labour

Date	Employee	Work Type	Description	Hours
19 Oct 2023	Dexter Reese	Field Mechanic	Service	0.00



Work Order #: 343

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	2 Jan 2024
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
5,476.00	

Description of Work

PM-2 service. 500hr.

Replaced engine belt. Attached dust ejector hose.

Summary of Labour

Date	Employee	Work Type	Description	Hours
2 Jan 2024	Connor Tiller	Shop Mechanic	PM-2 service / Minor repairs.	0.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	28 Aug 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
7,116.00	0.00

Description of Work
Replace Rear Crank Seal / Check over repairs - Drop and clean stump pans. Replace rear engine seal. Replace RH door wiper arms and blades. Drained all powertrain oil. Removed powertrain hoses. Removed cooler tubs. Removed drive shaft. Removed torque relief valve. Removed test port assembly. Unhooked wiring. Dropped torque. Removed flywheel. Removed center gear. Removed rear seal. Removed wear sleeve on crank. Clean up crank. Installed new seal. Cleaned up bell housing. Replaced trans filter. Drained and replaced engine oil. - Total 55 Hrs.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
28 Aug 2025	Cody Davidson	Shop Mechanic	Repairs	0.00



Work Order #: 1636

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	24 Sep 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
7,261.00	0.00

Description of Work

PM-1 service (250hr) / Repair hyd leak / adjust cab doors - Complete PM-1 Service. Check all fluids and top up as needed. Blow out engine and cab filters. Grease. Verify leak at fitting on lift cylinder. Remove line and found blown o-ring. Replaced all and reinstall line. Verify no more leaks. Adjust both cab door handles

Summary of Labour

Date	Employee	Work Type	Description	Hours
24 Sep 2025	Kyler Carlson	Field Mechanic	Repairs / Service	2.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	6 Oct 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
7,334.00	0.00

Description of Work
Check over / Drop pans - checked all levels, checked lights, greased machine, cleaned dirt from trans filter panel, replaced cab filters and outer air filter, replaced one double flange roller on LHS, adjust tracks

Summary of Labour				
Date	Employee	Work Type	Description	Hours
6 Oct 2025	Cody Davidson	Field Mechanic	Check over	2.50



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	31 Oct 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
7,500.00	0.00

Description of Work
PM-2 Service (500hrs) - Completed a pm-2 service. Changed engine oil and all the filters including air. Greased machine.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
31 Oct 2025	Dexter Reese	Field Mechanic	Service	3.00



Work Order #: 1845

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	4 Dec 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
7,727.00	0.00

Description of Work

PM-1 Service (250hr) - Completed a pm-1 check over service. Greased machine.

Summary of Labour

Date	Employee	Work Type	Description	Hours
4 Dec 2025	Kohl Kromrey	Shop Mechanic	Service	0.00



Work Order #: 1807

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	20 Dec 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
7,732.00	0.00

Description of Work

Check over / Edges / Emission Code - Replaced engine output nox sensor that failed. Ran after functional test and codes went away. Replaced edges that needed to be changed. Replaced a roller that was cow belled.

Summary of Labour

Date	Employee	Work Type	Description	Hours
20 Dec 2025	Dexter Reese	Shop Mechanic	Repairs	0.00



Work Order #: 1834

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	14 Jan 2026
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
7,811.00	0.00

Description of Work

Auction Check Over and Repairs - Completed a full machine checkover. Removed fire ext. and unit numbers. Replaced lh door wiper blade and repaired sprayer. Replaced ether bottle. Straightened handle on the c-frame. Completed a engine oil change service. Replace fuel filters and air filters. Greased the machine. Replaced damaged decals. Replaced broken step on the c-frame. Replaced cab door window that was cracked. Replaced rhs roller that was almost cow belled.

Summary of Labour

Date	Employee	Work Type	Description	Hours
14 Jan 2026	Cody Davidson	Shop Mechanic	Check over repairs	4.50
15 Jan 2026	Cody Davidson	Shop Mechanic	Check over repairs	7.50
16 Jan 2026	Cody Davidson	Shop Mechanic	Check over repairs	6.50



Work Order #: 1844

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	13 May 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
6,650.00	0.00

Description of Work

PM-1 Service (250hr) - Completed a pm-1 check over service and greased machine.

Summary of Labour

Date	Employee	Work Type	Description	Hours
13 May 2025	Nathan Bower	Field Mechanic	Service	0.00



Work Order #: 1314

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	18 May 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
6,676.00	0.00

Description of Work

Ash Service - Ash Service complete - first ash service on machine

Summary of Labour

Date	Employee	Work Type	Description	Hours
18 May 2025	Kyler Carlson	Field Mechanic	Repairs	3.50



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	9 Jul 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
6,860.00	0.00

Description of Work
LHS Lift cylinder hose - blew LHS lift cylinder line. Remove line, replace with rebuilt one. Replace o-rings, install cover top hydraulic oil up. Check for leaks

Summary of Labour				
Date	Employee	Work Type	Description	Hours
9 Jul 2025	Kohl Kromrey	Field Mechanic	Repairs	3.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	21 Jul 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
6,925.00	0.00

Description of Work
PM-3 Service (1000hrs) - Complete PM-3 Service. Drain engine, trans and finals. Change all filters then refill fluids to verify levels. Grease machine. Replace cutting edges, corner vits and hardware

Summary of Labour				
Date	Employee	Work Type	Description	Hours
21 Jul 2025	Dexter Reese	Shop Mechanic	Service	4.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	21 Jul 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
6,925.00	0.00

Description of Work
PM-3 Service (1000hrs) - Complete PM-3 Service. Drain engine, trans and finals. Change all filters then refill fluids to verify levels. Grease machine. Replace cutting edges, corner vits and hardware

Summary of Labour				
Date	Employee	Work Type	Description	Hours
21 Jul 2025	Dexter Reese	Shop Mechanic	Service	4.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	27 Aug 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
7,115.00	0.00

Description of Work
Replace tilt cylinder pin retainer - Snap ring for the tilt cylinder barrel end pin failed and dropped. Replaced pin and retainer with the updated parts.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
27 Aug 2025	Kyler Carlson	Field Mechanic	Repairs	2.00



Work Order #: 344

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	29 Jan 2024
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
5,604.00	

Description of Work

R/I RHS idlers - Both Rhs idlers where squeaking and getting hot. Split the track and removed old idlers. Clean mounting surface and installed new idlers. Torque mounting bolts to spec and connected track. Adjusted track to spec.

Summary of Labour

Date	Employee	Work Type	Description	Hours
29 Jan 2024	Kyler Carlson	Field Mechanic	R/I RHS idlers	4.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	6 Mar 2024
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
5,738.00	0.00

Description of Work
PM-1 Service (250hr) - Completed pm-1 service check over. Greased machine.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
6 Mar 2024	Kyler Carlson	Field Mechanic	Service	0.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	10 Apr 2024
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
5,744.00	

Description of Work

Spring Check over / Repairs - Dropped stump pans and cleaned the dirt out. Starter motor was leaking, removed starters and replaced gasket and oring. Replaced front wiper assembly. Rebuilt pitch link. Removed tilt cylinder and sent into Gir-del for reseal. Installed cylinder once it was rebuilt. Replaced RHS c-frame step. Replaced ripper teeth. Replaced leaking powertrain hose. Cut corks.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
12 Apr 2024	Connor Tiller	Shop Mechanic	Repairs	10.00
11 Apr 2024	Connor Tiller	Shop Mechanic	Repairs	10.00
15 Apr 2024	Connor Tiller	Shop Mechanic	Repairs	10.00
16 Apr 2024	Connor Tiller	Shop Mechanic	Repairs	10.00
17 Apr 2024	Connor Tiller	Shop Mechanic	Repairs	10.00
10 Apr 2024	Connor Tiller	Shop Mechanic	Repairs	10.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	20 Jun 2024
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
5,933.00	

Description of Work
Pm-3 Service (1000hr) / Roller - Completed pm-3 and service check over. Replaced RLHS roller.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
20 Jun 2024	Kohl Kromrey	Field Mechanic	Service / Repairs	5.00



Work Order #: 849

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	31 Aug 2024
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
6,207.00	

Description of Work
PM-1 Service (250hr) - Completed pm-1 and service check over. Replaced grease fittings on lhs angle cylinder and pitch link.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
31 Aug 2024	Kohl Kromrey	Field Mechanic	Service	1.00



Work Order #: 971

Precision Contractors

Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	11 Oct 2024
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
6,442.00	

Description of Work
PM-2 Service (500hr) / T/R Emissions code - Completed pm-2 and service check over. 3655-12 nox sensor failure. Replaced nox sensor and ran aftertreatment functional test and code went away.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
11 Oct 2024	Connor Tiller	Field Mechanic	Repairs / Service	4.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	28 Oct 2024
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
6,584.00	

Description of Work
T/R Transmission noise - 535 Total Hrs - rebuild transmission with updated clutch piston; minor repairs done with checkover; replaced equalizer bar center bushing and pin; repaired front track guide; replaced lower rollers - LHS #2 double; #7 double - RHS #8 single

Summary of Labour				
Date	Employee	Work Type	Description	Hours
28 Oct 2024	Nathan Bower	Field Mechanic	Repairs	24.00
28 Oct 2024	Kyler Carlson	Field Mechanic	Repairs	24.00



Precision Contractors
Box 10578
Lloydminster, Alberta T9V 3A7
Canada

CREATED BY	DATE
Nick Kempton	6 May 2025
MAKE	MANUF. S/N
D6 LGP DOZER	RDC00623
MODEL / DESCRIPTION	UNIT #
	6162
SERVICE METER	KM
6,646.00	

Description of Work
Troubleshoot Transmission Leak - Remove drive shaft and new yoke. Reinstall old yoke and drive shaft. Test and verify speed sensor reading. Code is gone

Summary of Labour				
Date	Employee	Work Type	Description	Hours
6 May 2025	Kyler Carlson	Shop Mechanic	Repairs	2.50