



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

H14-5  
GR-FEB

**Work Order #: 135**

CREATED BY	DATE
Nathan Bower	26 Apr 2023
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
4,448.00	

**Description of Work**

Spring checkover

SEG 01) PM-2 service-Changed engine oil and filters, sampled all oil compartments

SEG 02) Checkover machine-Found bad batteries, stump pans full, tracks and segments needing replacement; starter and torque output seals leaking

SEG 03) Repairs- Replaced both batteries and cleaned battery box, cleaned stump pans, resealed starter, replaced tracks and segments with new hardware. Replaced torque converter output seal and wear sleeve. Install stump pans.

921927 30-Nov-22 FINNING D6T 6171 ST02468 NEW TRACK LINKS \$17,255.62

922426 25-Apr-23 FINNING D6T 6171 14247118 SPROCKET SEGMENTS / HARDWARE \$1,991.33

922428 26-Apr-23 FINNING D6T 6171 01C044951 (2) 153-5710 BATTERIES \$1,031.23

922436 27-Apr-23 FINNING D6T 6171 14250970 torque converter seals \$313.62

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
27 Apr 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	10.00
26 Apr 2023	Connor Tiller	Shop Mechanic	Checkover and service	9.50
2 May 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	10.00
28 Apr 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	9.00
1 May 2023	Connor Tiller	Shop Mechanic	Checkover Repairs	10.00



Work Order #: 164

**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nathan Bower	26 May 2023
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
4,604.00	

**Description of Work**

Troubleshoot E1025 code; ARD fail to ignite. Confirmed there was fuel and spark at ARD head, Internal ARD head failure. Replaced ARD head and ran manual DPF regeneration to confirm repair.

922584 26-May-23 Finning D6T 6171 01C047356 ard head, gaskets and spark plug (FR SK) \$5,146.26 1296.55 CORE CHRG

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
26 May 2023	Nick Kempton	Field Mechanic	T/S and repair regen system	6.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 176**

CREATED BY	DATE
Nathan Bower	27 Jun 2023
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
4,448.00	

**Description of Work**

Track link Replacement at Finning Saskatoon. Replace dry track links, swap pads to new rails . Track links replaced on machine at 4448 hours April 26, 2023 W/O #135  
922819 29-Jun-23 FINNING D6T 6171 ST03438 TRACK LINK REPLACEMENT AT 4448 HOURS \$17,368.68



Work Order #: 618

**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	20 Jul 2023
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
4,918.00	

Description of Work
PM-3 (1000hr) Service - Completed pm-3 and service check over.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
20 Jul 2023	Connor Tiller	Field Mechanic	Service	3.00



Work Order #: 598

**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	13 Aug 2023
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
5,053.00	

**Description of Work**

T/R Hyd. Leak - troubleshoot hyd. leak coming from under the seat. Replaced hyd. line #450-0994. Assembled cab.

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
13 Aug 2023	Connor Tiller	Field Mechanic	Repairs	5.00



**Precision Contractors**  
Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	29 Aug 2023
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
5,160.00	0.00

Description of Work
PM-1 Service (250hr) - Completed pm-1 check over service. Greased machine. Blew out rads.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
29 Aug 2023	Nick Kempton	Field Mechanic	Service	2.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 313**

CREATED BY	DATE
Nick Kempton	5 Oct 2023
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
5,384.00	

Description of Work
PM-2 service. 500hr. Tightened tracks and complete service check over.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
5 Oct 2023	Connor Tiller	Field Mechanic	PM-2 service	4.00





Work Order #: 315

**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	6 Nov 2023
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
5,590.00	

**Description of Work**

PM-1 sample service. 250hr. Completed service check over.

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
3 Jan 2024	Kohl Kromrey	Field Mechanic	Pm-1 sample service	2.00





**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 312**

CREATED BY	DATE
Nick Kempton	19 Jan 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
5,775.00	

**Description of Work**

T/R DEF system. Exhaust fluid temp. not responding. E1441 causing a E1389-3 derate. Found coolant lines bypassed for the def tank manifold. Connected lines and ran machine to thaw out the tank. Ran aftertreatment functional test and codes went away.

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
19 Jan 2024	Nathan Bower	Field Mechanic	T/R def fluid temp	8.00



Work Order #: 643

Precision Contractors

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	25 Jan 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
5,830.00	

Description of Work

PM-4 (2000hr) Service - Completed pm-4 and service check over.

Summary of Labour

Date	Employee	Work Type	Description	Hours
25 Jan 2024	Connor Tiller	Field Mechanic	Service	10.00
25 Jan 2024	Kohl Kromrey	Field Mechanic	Service	10.00



Work Order #: 639

**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	5 Feb 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
5,842.00	

**Description of Work**

LHS Final Rebuild - Final drive magnet was collecting bearing material and needed to be rebuilt before failure. Removed lhs final drive. Replaced bearings, seals and reaction hub. All the gears and pins looked good. Installed final drive, added oil and connected track. Adjust to spec.

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
8 Feb 2024	Connor Tiller	Shop Mechanic	Repairs	10.00
7 Feb 2024	Connor Tiller	Shop Mechanic	Repairs	10.00
5 Feb 2024	Connor Tiller	Shop Mechanic	Repairs	4.00
6 Feb 2024	Connor Tiller	Shop Mechanic	Repairs	10.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 716**

CREATED BY	DATE
Nick Kempton	24 May 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
6,038.00	

Description of Work
PM-1 Service (250hr) - Completed pm-1 and service check over.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
24 May 2024	Kyler Carlson	Field Mechanic	Repairs	1.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 922**

CREATED BY	DATE
Nick Kempton	24 Jun 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
6,291.00	

Description of Work
PM-1 Oil change Service (250hr) - Completed pm-1 oil change and service check over.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
24 Jun 2024	Dexter Reese	Field Mechanic	Service	2.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 791**

CREATED BY	DATE
Nick Kempton	10 Jul 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
6,331.00	

**Description of Work**

T/R Trans. code 1401-5. Transmission had a active code for solenoid 1 current below normal. Removed trans cover plate and had found the connector had lost its lock tension and wiggled out. Replaced electrical connector. No more codes after the repair.

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
10 Jul 2024	Dexter Reese	Field Mechanic	Repairs	1.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 921**

CREATED BY	DATE
Nick Kempton	25 Jul 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
6,460.00	

Description of Work
PM-2 Service (500hr) - Completed pm-2 and service check over.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
25 Jul 2024	Kyler Carlson	Field Mechanic	Service	2.00





**Precision Contractors**  
Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 920**

CREATED BY	DATE
Nick Kempton	14 Sep 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
6,750.00	

Description of Work
PM-1 Service (250hr) - Completed pm-1 and service check over.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
14 Sep 2024	Dexter Reese	Field Mechanic	Service	1.00



Work Order #: 919

**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	21 Sep 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
6,772.00	

Description of Work
Seized A/C compressor - A/C compressor seized and blew the belt. Evacuated system and replaced compressor. Charged to spec. and tested good after repair.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
21 Sep 2024	Kyler Carlson	Field Mechanic	Repairs	2.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 992**

CREATED BY	DATE
Nick Kempton	21 Oct 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
6,965.00	

**Description of Work**

PM-3 service (1000hr) - Completed pm-3 service. Changed engine, trans, and final drive oils. Changed all the oil and air filters. Greased the machine.

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
21 Oct 2024	Kyler Carlson	Field Mechanic	Service	4.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 1055**

CREATED BY	DATE
Nick Kempton	21 Nov 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
7,186.00	

Description of Work
Repair Coolant Leak - Steel line going to the heater core rubbed through on the bracket. Replaced steel line from a machine in the shop. Topped up coolant no more leaks.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
21 Nov 2024	Kohl Kromrey	Field Mechanic	Repairs	4.00



**Precision Contractors**  
Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 1858**

CREATED BY	DATE
Nick Kempton	3 Dec 2024
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
7,203.00	0.00

Description of Work
PM-1 Service (250hr) - Completed a pm-1 check over service. Topped up fluids and greased the machine.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
3 Dec 2024	Kohl Kromrey	Field Mechanic	Service	0.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 1300**

CREATED BY	DATE
Nick Kempton	12 May 2025
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
7,274.00	0.00

**Description of Work**

Undercarriage repairs / 2025 spring check over - replace RHS dash panel in cab; replace broken wires to positive air module; topped up fluids; replace RRHS light; flipped edges; replaced ripper teeth; clean battery box; replace all rollers, idlers, segments, tracks, buff all components - total of 85 hrs

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
12 May 2025	Kohl Kromrey	Shop Mechanic	Repairs	0.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 1371**

CREATED BY	DATE
Nick Kempton	11 Jun 2025
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
7,410.00	0.00

Description of Work
PM-2 Service (500hrs) - Complete PM-2 Service - drain engine oil, change all oil filters, refill engine oil and run machine to confirm fluid levels. Blew out rads

Summary of Labour				
Date	Employee	Work Type	Description	Hours
11 Jun 2025	Dexter Reese	Field Mechanic	Service	2.00





**Precision Contractors**  
Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	19 Jun 2025
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
7,442.00	0.00

Description of Work

E1025 Failed ARD Fail Ignite - removed DPF and sent to Kenworth for cleaning. Assembled machine and cleared lockout codes - 28 hrs



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 1425**

CREATED BY	DATE
Nick Kempton	2 Jul 2025
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
7,641.00	0.00

Description of Work
PM-4 Service (2000hrs) / Replace 6 Injectors and High pressure pump / Repair 5v code / Rebuild LHS Final - removed hood. Emissions and cleaned all lift from valve cover area. Removed EGR valve and all fuel lines. Remove and replace all injectors along with injector lines. Did a valve set and replaced injector harness. Remove and replace fuel injection pump.. Cleaned front cover and installed. Hooked up lines to fuel pump. Remove and replace engine harness. Install EGR valve and all piping then install all accessory brackets. Total 82 hrs

Summary of Labour				
Date	Employee	Work Type	Description	Hours
18 Sep 2025	Dexter Reese	Shop Mechanic		0.00
2 Jul 2025	Cody Davidson	Shop Mechanic	Repairs	0.00



**Precision Contractors**  
Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	27 Aug 2025
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
7,658.00	0.00

Description of Work
Troubleshoot Low Power / Replace Failed EGR Cooler - Remove exhaust-coolant on exhaust side of turbo. EGR leaking. Suck out coolant on Intake side of head. Checked all Push Rods for straightness. Replaced EGR. Remove and clean air valve. Clean coolant from turbo. Drained engine oil. Replaced filter and filled up engine oil. Filled cooling system. Installed axles. Total 56 hrs.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
27 Aug 2025	Cody Davidson	Shop Mechanic	Repairs	0.00
27 Aug 2025	Dexter Reese	Field Mechanic	Repairs	0.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 1617**

CREATED BY	DATE
Nick Kempton	19 Sep 2025
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
7,795.00	0.00

**Description of Work**

PM-1 Service (250hr) - Complete PM-1 Service. Check fluids and grease machine

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
19 Sep 2025	Dexter Reese	Shop Mechanic	Service	1.00



**Precision Contractors**

Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

**Work Order #: 1652**

CREATED BY	DATE
Nick Kempton	1 Oct 2025
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
7,840.00	0.00

**Description of Work**

Replace Nox Inlet Sensor 3655-12 - Verify code for inlet Nox sensor failure. Remove sensor and install new one. Hook up ET and run after treatment verification test - passed. Code cleared

**Summary of Labour**

Date	Employee	Work Type	Description	Hours
1 Oct 2025	Kyler Carlson	Field Mechanic	Repairs	1.00



**Precision Contractors**  
Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	31 Oct 2025
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
8,027.00	0.00

Description of Work
PM-2 Service (500hrs) - Complete PM-2 service. Check over machine. Wash and blow out cab. Replaced 2 rubber light mounts on LH lift cyl light bracket. Replace fire extinguisher and rubber plugs in bracket

Summary of Labour				
Date	Employee	Work Type	Description	Hours
31 Oct 2025	Nathan Bower	Shop Mechanic	Service	4.00



**Precision Contractors**  
Box 10578  
Lloydminster, Alberta T9V 3A7  
Canada

CREATED BY	DATE
Nick Kempton	19 Jan 2026
MAKE	MANUF. S/N
D6 LGP DOZER	K1R00251
MODEL / DESCRIPTION	UNIT #
	6171
SERVICE METER	KM
8,094.00	0.00

Description of Work
Auction Check over and repairs - Completed a full machine check over. Dropped pans and cleaned them out. Replaced decals that where starting to peel. Cleaned out the battery box. Repaired burnt out light. Replaced cracked console pieces inside the cab. Replaced washer fluid pumps. Replaced wiper blades. Bent back the grade control bracket on the lift cylinder. Replaced cab filters. Detailed the cab. Repaired LHS master pad bolt threads. installed Heli coil and torque to spec. Replaced ripper tips. Replaced trans pump mounting oring.

Summary of Labour				
Date	Employee	Work Type	Description	Hours
21 Jan 2026	Cody Davidson	Shop Mechanic	Check over repairs	10.00
20 Jan 2026	Cody Davidson	Shop Mechanic	Check over repairs	10.00
19 Jan 2026	Cody Davidson	Shop Mechanic	Check over repairs	0.00
23 Jan 2026	Cody Davidson	Shop Mechanic	Check over repairs	10.00
22 Jan 2026	Cody Davidson	Shop Mechanic	Check over repairs	10.00