

T23-6  
BAWE - MAR

FRONT  
LEFT SHOE 18.5  
DRUM 420

FRONT  
RIGHT SHOE 19  
DRUM 420

WORK ORDER



Job# \_\_\_\_\_  
Mechanic's name TR  
Date DEC 19 2023  
Unit TR 215  
K.M. 124078 H.M. 12810  
Location ACH GPHV2127 2015

Quan	Part Number	Description	Cost
6	MR782E	SPRING PIN BUSHING	
1	100061	TEFLON PLAT	
6		DRUMS	
6		SHOE 18.5	
6	12105	DIRT VALVE	
1	AF26424	Fuel Tank Filter	
	66724C	W	

- ✓ E-VIP UNIT
- ✓ #1 DIFF W/ PLT YOK LOOSE
- ✓ SPRING PIN BUSHINGS #1-#2-#3 ARE
- ✓ ENGINE OIL LEAK AT PAN ~~PLATE~~ SEAL
- ✓ HOSE LOOSE ON BOTTOM OF HYD PUMP
- ✓ DRIVES DOOR HINGERS
- ✓ CAB LIGHTS
- ✓ MIRROR LIGHTS
- ✓ TOP RAD HOSE LEAKS
- ✓ STEERING WHL
- ✓ ALL TIRES
- ✓ SERVICE TOP UP DI

SUBLET

<del>WASH UNIT</del>			
WASH UNIT			✓
5 WHEEL TEFLOW PLAT			✓
DIFF FILTERS			✓
TOP UP DIFF OILS			✓
RE-MOUNT BEAN FENDER			✓
HYD OIL LEAK AT TANK VALVE			✓
TURN FUEL TANK			✗

SUBLET:	Sublet	Shop Time:	Shop	Total Hours:	Parts	Total Hours	Total

TIGHTEN DASH ✓ PRI  
DASH SWITCHES ✓ MISAD GN  
REWORK DIESEL METER

- ✓ CWI - wheels on.
- ✓ Service
- ✓ D/S worn
- ✓ D/S Seat Belt Frayed
- Wear check engine Brake
- Stop Pass the Side
- Stop Harness
- ~~check seat~~
- ✓ Coolant leak LF
- ✓ Cab mounts
- ✓ Work Lights on Bunk
- ✓ Hood Repair
- ✓ Air Filters
- ✓ DA Chrome + Sa
- ✓ LRD Brakes pot
- ✓ Air Dryer Filter
- Stop Fitt
- ✓ PTO Seal on Shaft.
- ✓ LRD Dust cover
- ✓ Cab Filters
- ✓ All oils Diff Preu Doc → did Trans
- ~~check plate~~
- ✓ Remove Dome.
- ✓ O/S Windshield
- ~~check tank water valve~~
- ✓ Coolant Boost Pump.
- ✓ Batt Box Stop Baslin's N/E
- ✓ JMD Brakes N/W
- ✓ LH Hood Marker Light
- Power Box Loose on Blower