

BREAK AWAY SYSTEM IS NOT WORKING [141739]

[3114 \[UBD816 DUMP TRAILER DAY RATE\]](#)

Z10-16
MAY

Closed: [3114 - 01/15/2026 \[77927\]](#)
Requested by OOM JARUSSIRIRAT on 1/15/2026

Location

Type

Trailer Work Order

Problem Code

Priority

HIGH

Notes

▼ **Comments**

Comment

Install new brake away switch and battery and test, GTG all brakes work

BROKEN BREAKAWAY SWITCH, DEAD BATTERY AS A RESULT. REPLACE BATTERY, WAITING ON SWITCH

Added By

Blake Hopkins

Blake Hopkins

Added On

1/15/2026

1/15/2026

▼ **Attachments**

There are no attachments on this request.

LIGHTS ISSUE [137475]

3114 [UBD816 DUMP TRAILER DAY RATE]

Closed: 3114 - 11/05/2025 [75308]

Requested by OOM JARUSSIRAT on 11/6/2025

Location

Type

Trailer Work Order

Problem Code

Priority

MED

Notes

▼ Comments

Comment

Fixed rear marker lights and license plate light.

▼ Attachments

There are no attachments on this request.

Added By

Joshua Bota

Added On

11/6/2025

BENT REAR AXLE [137302]

[3114 \[UBD816 DUMP TRAILER DAY RATE\]](#)

Closed: [3114 - 11/05/2025 \[75308\]](#)

Requested by OOM JARUSSIRIRAT on 11/4/2025

Location

Type

Trailer Work Order

Problem Code

Priority

LOW

Notes

▼ Comments

Comment	Added By	Added On
Removed rear axle have to get new one left side bent.	Joshua Bota	11/5/2025
Installing new axle	Joshua Bota	11/24/2025
Layout new axle mounts, R&R axle mounts, weld out, prime mounts and install, install brakes and hubs with josh, wi...	Damian Myers	11/24/2025



▼ Attachments

There are no attachments on this request.



NEED NEW SAFETY CHAINS [134291]

3114 [UBD816 DUMP TRAILER DAY RATE]

Closed: 3114 - 09/30/2025 - CVIP [73838]

Requested by OOM_JARUSSIRAT on 9/30/2025

Location

Type

Trailer Work Order

Problem Code

Priority

MED

Notes

▼ Comments

Comment

Replaced safety chains and hooks. WK 09/30/25

+

Added By

Wayne Kirk

Added On

9/30/2025

▼ Attachments

There are no attachments on this request.

+