

M/12-9  
MAY

5/1/2018	Engines	Cooling sys	Rad repaired by McGibbons
11/20/2018	Hydraulics	cylinders	Reseal LH blade lift cylinder
3/2/2020	Engines	General service	Perform engine valve set, reseal valve cover and base and fuel lines
3/2/2020	Powertrain	Torque Converter	
3/15/2021	Undercarriage	other	Remove left track and swing frame to repair cracked hardbar, made 3 new pins for h
3/15/2021	Electronics	Starting sys	Replaced starter due to failed ground stud and repaired alt. ground strap
3/15/2021	Hydraulics	cylinders	Resealed right side lift cylinder on machine and checked all fluid levels
5/30/2022	Frame/Body/Work Tools	Blade & C frame	new edges and corners
7/13/2022	Engines	Cooling sys	Blow out rad, repair fuel filter housing for missing bolts and tighten fan belt
7/28/2022	Hydraulics	Hose/Fittings	Remove engine side guards to repair hyd. leak at tee fitting to blade lift cyl.
3/17/2023	Engines	Fuel and Exhaust Sys	old fuel and jelled, clean out and replace filters.
8/16/2023	Engines	Cooling sys	rebuild fan hub replaced bearings and hard ware