

Maintenance History (All work types) - TQ940

Custom Date Range: 1/1/2023 - 4/14/2026

Work Order ID	Description	Direct Labor \$	Sublet Vendor Labor \$	Part \$	Total \$	Total Labor Hrs	Status Date
73790	1 - REPLACE OIL THERMOSTAT 2 - ADJUST PARAMETERS 3 - VALVE SET 4 - RIG UP 5 - WELDING 6 - INSTALL CENTER BEARING 7 - CHECK OVER TRUCK 8 - REPLACE AXLE #2 AND #3 BRAKE POTS 9 - REPLACE AXLE #2 AND #3 AIRBAGS 10 - REPLACE BUMPER 11 - DELETE 12 - CHECK ENGINE LIGHT ON 13 - REPAIR AIR LEAK	\$5,287.50	\$146.80	\$2,823.51	\$8,257.81	70.50	9/26/2025
73806	1 - REPLACE STEER TIRES	\$32.50	\$0.00	\$1,340.00	\$1,372.50	0.50	9/22/2025
73893	1 - REPLACE REVERSE ALARM	\$37.50	\$0.00	\$46.74	\$84.24	0.50	9/24/2025
74023	1 - REPLACE TURBO 2 - REPLACE PUMP SHIFT CYLINDER 3 - REPLACE BATTERIES 4 - REPLACE RADIATOR 5 - A SERVICE 6 - REPLACE AXLE #2 DRIVERS SIDE AXLE GASKET 7 - REPLACE KING PIN CAP	\$1,837.50	\$0.00	\$1,905.41	\$3,742.91	24.50	10/8/2025
75369	1 - SUNDANCE RADIO COMMUNICATIONS: INSTALL RADIOS	\$0.00	\$954.98	\$0.00	\$954.98	0.00	2/19/2026
74039	1 - REPAIR CROSSMEMBER	\$300.00	\$0.00	\$0.00	\$300.00	4.00	10/8/2025
74555	- A SERVICE 2 - REPLACE COOLANT HOSE	\$225.00	\$154.14	\$299.44	\$678.58	3.00	11/3/2025
74706	1 - REPAIR STABILITY LIGHT 2 - REPAIR ABS LIGHT ON 3 - REPAIR CHECK ENGINE LIGHT ON	\$262.50	\$0.00	\$100.73	\$363.23	3.50	11/10/2025
74815	1 - REPLACE HYDRAULIC PUMP	\$225.00	\$0.00	\$669.64	\$894.64	3.00	11/17/2025
74964	1 - REPLACE PINTLE SHOE AND POT	\$93.75	\$0.00	\$146.95	\$240.70	1.25	11/24/2025
75636	1 - PRO-WEST: INSTALL WEBASTO	\$0.00	\$698.52	\$0.00	\$698.52	0.00	2/19/2026
75139	1 - A SERVICE 2 - REPLACE STEADING BEARING YOKE STRAP KIT 3 - REPLACE AXLE #2 LEFT SIDE WHEEL SEAL 4 - REPLACE AXLE #1 RIGHT SIDE BRAKE LINE	\$562.50	\$161.48	\$514.93	\$1,238.91	7.50	12/4/2025

75234	1 - REPLACE TAILGATE CYLINDER 2 - REPLACE TANK SUPPORT BEAM	\$187.50	\$0.00	\$621.60	\$809.10	2.50	12/9/2025
75295	1 - REPLACE CLUTCH BRAKE	\$56.25	\$0.00	\$50.13	\$106.38	0.75	12/11/2025
75377	1 - REPLACE LEFT SIDE WINDOW REGULATOR AND MIRROR SWITCH	\$93.75	\$0.00	\$299.83	\$393.58	1.25	12/16/2025
75908	1 - CVIP 2 - REPAIR RIGHT SIDE EXHAUST PIPE 3 - REPLACE BRAKE DRUMS 4 - REPLACE AXLE #2 RIGHT AND AXLE #3 LEFT SIDE WHEEL SEALS 5 - REPLACE AXLE #1 RIGHT SIDE SLACK ADJUSTER 6 - DELETE EMISSIONS 7 - A SERVICE 8 - REPLACE STEADY BEARING U-JOINT	\$1,893.75	\$0.00	\$1,427.99	\$3,321.74	25.25	2/4/2026
76533	1 - B SERVICE 2 - REPLACE TARP 3 - REPAIR COOLANT LEAK	\$450.00	\$0.00	\$146.87	\$596.87	6.00	3/12/2026
76800	1 - PREP FOR AUCTION 2 - CVIP 3 - RESEAL #1 DIFF	\$3,075.00	\$0.00	\$45.86	\$3,120.86	41.00	4/8/2026
76550	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	\$0.00	\$100.00	\$0.00	\$100.00	0.00	4/15/2026
76906	1 - PATCH HOLES, NEW FLOOR, HEADBOARD	\$937.50	\$0.00	\$730.13	\$1,667.63	12.50	4/9/2026
76928	1 - RIG UP	\$225.00	\$0.00	\$92.19	\$317.19	3.00	4/9/2026
76939	1 - PREP FOR AUCTION	\$1,387.50	\$0.00	\$359.58	\$1,747.08	18.50	4/9/2026
76978	1 - REPAIR AIR LEAK 1 - PREP FOR AUCTION	\$75.00	\$0.00	\$0.00	\$75.00	1.00	4/10/2026
77003	2 - ABS LIGHT ON 3 - REMOVE BOX SUPPORT ARMS	\$562.50	\$0.00	\$545.80	\$1,108.30	7.50	4/14/2026
77033	1 - MISCELLANEOUS REPAIRS	\$75.00	\$0.00	\$0.00	\$75.00	1.00	4/14/2026
76628	1 - CLEAR FINISH POLISHING: FULL TRUCK, NO BACK, BUMPER OR STAINLESS	\$0.00	\$1,199.00	\$0.00	\$1,199.00	0.00	4/15/2026
75278	1 - PHOENIX CUSTOM AUTO DESIGNS: SUPPLY AND INSTALL DECALS	\$0.00	\$747.00	\$0.00	\$747.00	0.00	2/19/2026
Totals:		\$22,232.50	\$9,801.92	\$12,342.10	\$44,376.52	296.50	