

# Maintenance History (All work types) - WT463

Work Order ID	Description	Direct Labor \$	Sublet Vendor Labor \$	Part \$	Total \$	Total Labor Hrs	Status Date
56146	1 - TCB TRAILER SERVICES: CVIP	\$0.00	\$372.44	\$0.00	\$372.44	0.00	1/4/2023
58361	1 - REPLACE AXLE #2 RIGHT SIDE AIRBAG	\$37.50	\$0.00	\$151.52	\$189.02	0.50	4/26/2023
58713	1 - A SERVICE	\$187.50	\$0.00	\$100.29	\$287.79	2.50	5/25/2023
59377	1 - A SERVICE 2 - REPLACE AXLE #2 LEAF SPRINGS	\$1,068.75	\$0.00	\$391.95	\$1,460.70	14.25	7/10/2023
59597	1 - REBUILD WATER PUMP	\$337.50	\$0.00	\$0.00	\$337.50	4.50	7/18/2023
59970	1 - REPLACE HYDRAULIC TANK 2 - REPLACE EXHAUST MUFFLER	\$712.50	\$0.00	\$536.96	\$1,249.46	9.50	8/1/2023
60021	1 - REPLACE REAR TOP LIGHT	\$112.50	\$0.00	\$0.00	\$112.50	1.50	8/4/2023
60204	1 - A SERVICE 2 - REPLACE AXLE #2 RIGHT SIDE BRAKE POT 3 - REPAIR FENDER LIGHT WIRING	\$300.00	\$0.00	\$129.17	\$429.17	4.00	8/15/2023
60602	1 - REPAIR COOLANT LEAK	\$150.00	\$0.00	\$0.00	\$150.00	2.00	9/7/2023
60971	1 - A SERVICE	\$225.00	\$0.00	\$65.73	\$290.73	3.00	10/4/2023
61883	1 - B SERVICE	\$187.50	\$0.00	\$0.00	\$187.50	2.50	11/21/2023
61901	1 - REPAIR DRIVERS SEAT AIR LEAK 2 - CHECK ENGINE LIGHT ON	\$112.50	\$0.00	\$0.00	\$112.50	1.50	11/23/2023
61140	1 - CVIP 2 - REPLACE AXLE #1 RIGHT SIDE WHEEL SEAL 3 - REPLACE STACK BUSHINGS 4 - REPAIR LEFT SIDE MIRROR HEAT 5 - ADJUST PITMAN ARM ON STEERING BOX 6 - ABS LIGHT ON 7 - REPLACE AXLE #2 TORQUE ROD 8 - REPLACE AXLE #2 RELAY VALVE 9 - REPLACE AXLE #3 BRAKE SHOES 10 - REPLACE AXLE #3 U-BOLTS	\$2,325.00	\$0.00	\$724.76	\$3,049.76	31.00	11/24/2023
63942	1 - CLEAR FINISH POLISHING: POLISH	\$0.00	\$985.00	\$0.00	\$985.00	0.00	3/28/2024
64872	1 - A-SERVICE 2 - REPAIR WORK LIGHT FRONT SWITCH 3 - REPLACE ROOF CLEARANCE LIGHT 4 - CLEAN BATTERY CABLE	\$281.25	\$0.00	\$108.84	\$390.09	3.75	5/27/2024
65086	1 - PHOENIX CUSTOM AUTO DESIGN	\$0.00	\$183.03	\$0.00	\$183.03	0.00	5/30/2024
65222	1 - PET AUTOBODY	\$0.00	\$5,053.05	\$0.00	\$5,053.05	0.00	5/31/2024
65805	1 - A SERVICE	\$150.00	\$0.00	\$58.60	\$208.60	2.00	7/2/2024
65849	1 - REPAIR TRANSMISSION WIRING	\$112.50	\$0.00	\$0.00	\$112.50	1.50	7/4/2024

66032	1 - REPLACE A/C LINE	\$112.50	\$0.00	\$329.79	\$442.29	1.50	7/12/2024
66587	1 - A-SERVICE 2 - REPLACE LHS MARKER LIGHT 3 - CLEAN BATTERIES	\$225.00	\$0.00	\$89.87	\$314.87	3.00	8/8/2024
66574	1 - REPAIRS	\$112.50	\$0.00	\$52.71	\$165.21	1.50	8/8/2024
66636	1 - REPLACE SPRAYER HEADS	\$75.00	\$0.00	\$729.20	\$804.20	1.00	8/9/2024
66987	1 - REPLACE PASSENGER SIDE FLEX PIPE 2 - RESEAL #1 DIFF 3 - SHORTEN WASHER DISCHARGE HOSE	\$356.25	\$0.00	\$102.39	\$458.64	4.75	8/28/2024
67116	1 - REPLACE STEERING BOX	\$150.00	\$0.00	\$28.40	\$178.40	2.00	9/6/2024
67461	1 - A SERVICE	\$225.00	\$0.00	\$33.63	\$258.63	3.00	9/26/2024
67870	1 - REPLACE PARK BRAKE PRESSURE SWITCH	\$75.00	\$0.00	\$99.25	\$174.25	1.00	10/17/2024
68151	1 - CVIP 2 - REPLACE LEFT SIDE MIRROR 3 - REPAIR FENDER SIGNALS INOPERABLE 4 - REPLACE RIGHT SIDE TANK MOUNT BOLT	\$656.25	\$0.00	\$56.15	\$712.40	8.75	10/31/2024
71260	1 - A SERVICE 2 - CLEAN BATTERIES 3 - REPLACE WATER GATE VALVE 4 - REPAIR BEACON LIGHT WIRING	\$318.75	\$0.00	\$114.57	\$433.32	4.25	4/29/2025
71279	1 - WELD DIFF	\$56.25	\$0.00	\$0.00	\$56.25	0.75	4/30/2025
71303	1 - REPAIR A/C	\$100.00	\$0.00	\$0.00	\$100.00	1.00	5/1/2025
72378	1 - A SERVICE	\$187.50	\$0.00	\$100.79	\$288.29	2.50	7/3/2025
72702	1 - REPAIR WATER PUMP LEAK 2 - REPAIR HYDRAULIC LEAK 3 - REPAIR WORK LIGHTS	\$262.50	\$0.00	\$0.00	\$262.50	3.50	7/18/2025
73403	1 - REPAIR AIR LEAK	\$112.50	\$0.00	\$0.00	\$112.50	1.50	8/28/2025
73581	1 - A SERVICE 2 - REPLACE TANK MOUNT BOLTS	\$262.50	\$73.40	\$86.54	\$422.44	3.50	9/9/2025
73988	1 - REPLACE EXHAUST MANIFOLD GASKETS 2 - B SERVICE 3 - REPAIR COOLANT LEAK 4 - REPLACE RADIATOR 5 - REPLACE COOLANT LINE	\$900.00	\$0.00	\$237.75	\$1,137.75	12.00	10/6/2025
74423	1 - A SERVICE 2 - REPAIR COOLANT LEAK 3 - DELETE WEBASTO AND HEATER	\$393.75	\$0.00	\$84.16	\$477.91	5.25	10/27/2025
74442	1 - CVIP 2 - CVIP REPAIRS	\$562.50	\$0.00	\$141.09	\$703.59	7.50	10/27/2025
76116	1 - REPLACE BATTERIES 2 - INSTALL BUG DEFLECTOR 3 - REPLACE CB RADIO ANTENNA	\$281.25	\$0.00	\$649.09	\$930.34	3.75	2/18/2026
75873	1 - PET AUTO BODY: PAINT	\$0.00	\$4,555.00	\$0.00	\$4,555.00	0.00	2/19/2026

76151	1 - PHOENIX CUSTOM AUTO DESIGNS: INSTALL DECALS	\$0.00	\$148.82	\$0.00	\$148.82	0.00	2/19/2026
76165	1 - CLEAR FINISH POLISHING: POLISH	\$0.00	\$900.00	\$0.00	\$900.00	0.00	2/19/2026
76141	1 - REPLACE STARTER 2 - CVIP 3 - RIG UP 4 - REPLACE AXLE #2 RIGHT SIDE SHOCK 5 - REPAIR HYDRAULIC LEAK	\$1,143.75	\$0.00	\$151.68	\$1,295.43	15.25	2/24/2026
76297	1 - REPLACE HEADLIGHT 2 - INSTALL SEAT COVERS	\$187.50	\$200.00	\$0.00	\$387.50	2.50	2/27/2026
76864	1 - CVIP 2 - REPLACE HOOD PIVOT BUSHINGS	\$862.50	\$0.00	\$348.86	\$1,211.36	11.50	4/7/2026
76934	1 - REPAIR EXCESSIVE SMOKE REPLACE 6 INJECTORS	\$975.00	\$0.00	\$2,567.49	\$3,542.49	13.00	4/9/2026
76553	1 - PET AUTO BODY: PAINT	\$0.00	\$995.00	\$0.00	\$995.00	0.00	4/15/2026
<b>Totals:</b>		<b>\$14,893.75</b>	<b>\$13,465.74</b>	<b>\$8,271.24</b>	<b>\$36,630.73</b>	<b>198.25</b>	

Filter:

Thursday, April 16, 2026