

Maintenance History (All work types) - TRE538

Custom Date Range: 1/1/2023 - 4/14/2026

Work Order ID	Description	Direct Labor \$	Sublet Vendor Labor \$	Part \$	Total \$	Total Labor Hrs	Status Date
58380	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	4/26/2023
58700	1 - CVIP 2 - REPLACE AXLE #1 RIGHT SIDE AIRBAG	\$412.50	\$0.00	\$50.88	\$463.38	5.50	5/24/2023
59675	1 - B SERVICE	\$93.75	\$0.00	\$7.06	\$100.81	1.25	7/21/2023
59913	1 - B SERVICE	\$75.00	\$0.00	\$0.00	\$75.00	1.00	7/31/2023
61238	1 - REMOVE PASSENGER SIDE TARP ARM, STRAIGHTEN AND REINFORCE, REMOVE REAR CROSS PIPE, WELD BACK TOGETHER AND REINFORCE AND REINSTALL	\$150.00	\$0.00	\$0.00	\$150.00	2.00	10/27/2023
61570	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	11/10/2023
61929	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	11/22/2023
62198	1 - B SERVICE	\$112.50	\$0.00	\$5.38	\$117.88	1.50	12/7/2023
64352	1 - CVIP 2 - REPLACE AXLE #2 AND #3 LEFT SIDE WHEEL SEAL 3 - REPLACE ALL BRAKE SHOES 4 - REPLACE AXLE #3 PIVOT BUSHING WASHERS	\$600.00	\$0.00	\$734.87	\$1,334.87	8.00	4/26/2024
64778	1 - B-SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	5/21/2024
65041	1 - STRAIGHTEN BENT GATE LATCHES, WELD LOOP FOR DOLLY LEG HANDLE, STRAIGHTEN PASSENGER SIDE REAR LIGHT BOX, REPLACE 3 SHEET PLYWOOD ON EACH SIDE. MAKE AND INSTALL INSIDE STEP	\$787.50	\$0.00	\$387.60	\$1,175.10	10.50	5/30/2024
65320	1 - B-SERVICE	\$93.75	\$0.00	\$11.03	\$104.78	1.25	6/5/2024
65487	1 - B-SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	6/13/2024
65720	1 - B-SERVICE 2 - REPLACE AXLE #3 DRIVER SIDE BRAKE POT 3 - REPLACE AXLE #2 PASSENGER SIDE AND AXLE #3 DRIVER SIDE HUB CAP 4 - REPLACE HYD QUICK COUPLER REMALE	\$243.75	\$0.00	\$64.35	\$308.10	3.25	6/26/2024
66271	1 - B-SERVICE	\$112.50	\$0.00	\$0.00	\$112.50	1.50	7/24/2024
67046	1 - B SERVICE 2 - REPLACE TARP 3 - REPLACE SIDEBOARD	\$281.25	\$0.00	\$0.00	\$281.25	3.75	9/3/2024
67379	1 - B SERVICE 2 - REPLACE TARP ARM BEARING	\$187.50	\$0.00	\$33.44	\$220.94	2.50	9/19/2024
67703	1 - B SERVICE	\$75.00	\$0.00	\$0.00	\$75.00	1.00	10/8/2024

70905	1 - CVIP 2 - REPLACE AXLE #3 RIGHT SIDE WHEEL SEAL 3 - REPLACE AXLE #1 AND #2 BRAKE DRUMS 4 - REPLACE AXLE #1 LEFT SIDE AIRBAG	\$525.00	\$0.00	\$376.49	\$901.49	7.00	4/15/2025
74481	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	10/28/2025
76770	1 - CVIP 2 - REPLACE AXLE #1 AND #3 RIGHT SIDE WHEEL SEALS 3 - TEARDOWN	\$975.00	\$0.00	\$136.54	\$1,111.54	13.00	3/25/2026
76941	1 - RIG UP	\$1,162.50	\$0.00	\$38.27	\$1,200.77	15.50	4/9/2026
76968	1 - PREP FOR PAINT	\$300.00	\$0.00	\$0.00	\$300.00	4.00	4/10/2026
Totals:		\$6,750.00	\$0.00	\$1,845.92	\$8,595.92	90.00	

Filter:
Thursday, April 16, 2026