

Maintenance History (All work types) - TSD916

Custom Date Range: 1/1/2023 - 4/14/2026

Work Order ID	Description	Direct Labor \$	Sublet Vendor Labor \$	Part \$	Total \$	Total Labor Hrs	Status Date
71356	1 - PHOENIX CUSTOM AUTO DESIGNS: SUPPLY UNIT NUMBERS	\$0.00	\$47.16	\$0.00	\$47.16	0.00	5/9/2025
71613	1 - REPLACE TARP	\$1,687.50	\$0.00	\$0.00	\$1,687.50	22.50	5/22/2025
72989	1 - REPLACE RIGHT SIDE REAR MUDFLAP	\$37.50	\$0.00	\$0.00	\$37.50	0.50	8/1/2025
73171	1 - REPLACE ALL TIRES	\$195.00	\$0.00	\$4,800.00	\$4,995.00	3.00	8/13/2025
73427	1 - REINFORCE CORNERS AND PIVOT POINTS	\$2,906.25	\$0.00	\$25.75	\$2,932.00	38.75	9/4/2025
73451	1 - REPAIR HYDRAULIC VALVE	\$112.50	\$0.00	\$0.00	\$112.50	1.50	8/29/2025
73568	1 - INSTALL HYDRAULIC VALVE	\$187.50	\$0.00	\$0.00	\$187.50	2.50	9/9/2025
73935	1 - B SERVICE 2 - REPLACE AXLE #1 RIGHT SIDE SHOCK	\$112.50	\$0.00	\$49.09	\$161.59	1.50	9/26/2025
74175	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	10/15/2025
74470	1 - B SERVICE 2 - TIGHTEN HYDRAULIC PLUG	\$225.00	\$0.00	\$16.14	\$241.14	3.00	10/28/2025
74743	1 - REPLACE REAR TARP SPRING	\$75.00	\$0.00	\$405.09	\$480.09	1.00	11/11/2025
75254	1 - INSTALL JUNCTION BOX 2 - REPAIR ABS LIGHT ON	\$337.50	\$0.00	\$109.43	\$446.93	4.50	12/10/2025
75431	1 - B SERVICE 2 - REPLACE JUNCTION BOX	\$195.00	\$0.00	\$55.86	\$250.86	2.60	1/5/2026
75780	1 - B SERVICE	\$93.75	\$0.00	\$0.00	\$93.75	1.25	1/26/2026
76058	1 - WELD CRACKS	\$1,012.50	\$0.00	\$0.00	\$1,012.50	13.50	2/17/2026
76478	1 - CVIP 2 - REPLACE ALL BRAKE SHOES AND DRUMS 3 - REPLACE HYDRAULIC LINES 4 - WELDING	\$1,162.50	\$0.00	\$1,621.63	\$2,784.13	15.50	3/10/2026
76859	1 - REPLACE ALL TIRES AND FENDERS	\$975.00	\$0.00	\$1,007.06	\$1,982.06	13.00	4/7/2026
76940	1 - RIG UP	\$281.25	\$0.00	\$3.92	\$285.17	3.75	4/9/2026
Totals:		\$9,690.00	\$47.16	\$8,093.95	\$17,831.11	129.60	

Filter:

Thursday, April 16, 2026