

S20-13

23A



3 - 380 RIVERSIDE ROAD • ABBOTSFORD, BC V2S 7M4 • (604) 504-5904



SERVICE INVOICE	
R401019768:01	
Invoiced:	31-Mar-2025
PO No:	
Terms:	NET30
Prorate#	BC03976-001

BILL TO
 SPRUCE HOLLOW HEAVY HAUL LTD.
 2511 GUILFORD DRIVE
 ABBOTSFORD BC V2S 5L9
 P: (604) 852-4179
 F:

DELIVER TO
 SPRUCE HOLLOW HEAVY HAUL LTD.
 2511 GUILFORD DRIVE
 ABBOTSFORD BC V2S 5L9
 P: (604) 852-4179
 F:

DATE CREATE	JEID	ADVISOR	VIN ID	MODEL #	SERIAL #	ORIG. DOCUMENT	SALES TYPE
27-Mar-2025	2481650	EM DT	101756	FONTAINE SPECIA	4LF4S7955S3504151		SRET GST
HOURS	ODOM IN	ODOM OUT	CUSTOMER UNIT #				
0	1	1	23A				

Sold Operations

JOB #1 50-MVI TRAIL MVI TRAILER

COMPLAINT MVI TRAILER
 CAUSE
 CORRECTION PERFORM MVI ON TRAILER
 PASSED WITH DECAL # GB54300
 EXPIRES MARCH 2026

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOUR MVI TRAILER	MOTOR VEHICLE INSPECTION TRAILER	G	
				Package \$199.00

JOB #2 54-OTHER-31- FRAME FASTENERS

COMPLAINT FREE UP SEIZED REAR KINGPIN
 CAUSE
 CORRECTION COULD NOT REMOVE SEIZED KING PIN. ATTEMPT TO HEAT UP KING PIN WITH TORCH, WOULD NOT HEAT DUE TO THICK METAL. HAD TO HEAT FOR SEVERAL HOURS TO REMOVE. BUFF OUT BOTH KINGPIN HOLES TO INSTALL NEW KINGPIN.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOUR OTHER-31-00-100	FRAME FASTENERS INSTALLATION	G	836.00
Prepay: \$0.00 Parts: \$0 Labour: \$836.00 [3.80] Misc: \$0 Sublet: \$0				\$836.00

JOB #3 54-OTHER-31- FRAME ASSEMBLY

COMPLAINT WELD CRACKS IN CROSSMEMBER BY HYDRAULIC RAMS AND 6 CRACKED WELDS ON FRONT OF TRAILER
 CAUSE
 CORRECTION GRIND OUT CRACKS AND WELD CRACKS IN FORWARD TRAILER CROSSMEMBER ON FLIP DOWN SECTION LEFT AND RIGHT SIDES.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOUR OTHER-31-03-100	FRAME ASSEMBLY REPAIRING FRAME RAILS	G	616.00
Prepay: \$0.00 Parts: \$0 Labour: \$616.00 [2.80] Misc: \$0 Sublet: \$0				\$616.00

JOB #4 50-DIAG AIRL DIAGNOSTICS AIR LEAKS



Sold Operations (Cont.)

COMPLAINT REPAIR AIR LEAK ON BRAKE APP IN LEFT FRAME RAIL
 CAUSE
 CORRECTION REPLACED LEAKING QUICK CONNECT UNION WITH A COMPRESSION UNION. NO MORE LEAKS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	401X/FV-1460-6	3/8 FERRULE	G 0.27	0.27
2	401X/FV-1462-6	3/8 TUBE UNION	G 2.52	5.04
2	401X/FV-1468-4C	FITTING	G 2.76	5.52
	LABOUR EA-00	DIAGNOSTICS	G	88.00

Prepay: \$0.00 Parts: \$10.83 Labour: \$88.00 [0.40] Misc: \$0 Sublet: \$0

\$98.83

JOB #5 50-DIAG AIRL DIAGNOSTICS AIR LEAKS

COMPLAINT REPLACE SPLIT SERVICE AIR LINE AT RIGHT REAR
 CAUSE
 CORRECTION REPLACED LEAKING SERVICE LINE. REPLACED BROKEN VALVE AND AIR LINE. TEST, OK

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	401X/FV-1468-6C	3/8NPT - 3/8TUBE FITTING	G 3.29	3.29
2	401X/FV-1485-6-100	3/8 PLASTIC AIR LINE	G 0.91	1.82
1	401X/FV-BY2103-B	1/4 BALL VALVE	G 14.85	14.85
	LABOUR EA-00	DIAGNOSTICS	G	176.00

Prepay: \$0.00 Parts: \$19.96 Labour: \$176.00 [0.80] Misc: \$0 Sublet: \$0

\$195.96

JOB #6 50-DIAG AIRL DIAGNOSTICS AIR LEAKS

COMPLAINT REPLACE #2 LEFT AIR BAG
 CAUSE
 CORRECTION RE AND RE #2 LEFT AND AIR BAG. SEVERAL BOLTS AND NUTS SEIZED, DIFFICULT TO REMOVE.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	401X 64352	AIR BAG (FI W01 358 9158)	G 558.77	558.77
3	401X/FC-120-000-108Z	1/2NCNUT	G 0.27	0.81
6	401X/FC-120-000-255S	1/2LKWSH	G 0.23	1.38
6	401X/FC-120-000-297Z	1/2 FLT WASHER	G 0.31	1.86
3	401X/FC-120-100-008Z	1/2XINC	G 0.46	1.38
1	401X/FV-103-B	1/4 NPT COUPLER	G 0.92	0.92
1	401X/FV-113-B1-1/2	FITTING	G 1.39	1.39
	LABOUR EA-00	DIAGNOSTICS	G	286.00
	LABOUR EA-00	DIAGNOSTICS CHASSIS	G	66.00

Prepay: \$0.00 Parts: \$566.51 Labour: \$352.00 [1.60] Misc: \$0 Sublet: \$0

\$918.51

JOB #7 54-OTHER-42-1 AIR LINES AND FITTINGS

COMPLAINT SECURE AIR LINES AT #3 AXLE
 CAUSE
 CORRECTION SECURE AIR LINES AT #3 AXLE

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
4	401X/76-2890PK-1	14" HD ZIP TIE SINGLE	G 0.43	1.72
	LABOUR OTHER-42-07-050	AIR LINES AND FITTINGS MISC	G	66.00

Prepay: \$0.00 Parts: \$1.72 Labour: \$66.00 [0.30] Misc: \$0 Sublet: \$0

\$67.72

JOB #8 03-FL-42-11 EATON BRAKES



Sold Operations (Cont.)

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	EN0018	ENVIRONMENTAL FEE	G 0.18	0.18
	LABOUR OTHER-35-01-050	REAR AXLE WHEEL HUBS, BRAKE DRUMS, AND WHEEL BEARINGS		572.00
Prepay: \$0.00 Parts: \$129.86 Labour: \$572.00 [2.60] Misc: \$0.18 Sublet: \$0				\$702.04

JOB #12 54-OTHER-33 FRONT AXLE WHEEL HUBS, BRAKE DRUMS, AND WHEEL BEARINGS

COMPLAINT REPLACE LEAKING #3 RIGHT WHEEL SEAL

CAUSE

CORRECTION REPLACED LEAKING WHEEL SEAL ON #3 RIGHT SIDE. REASSEMBLE, TORQUE ALL TO SPEC.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	401D/ABP SBN SET413	BEARING-WHEEL.SET	G 26.72	26.72
1	401D/ABP SBN SET414	BEARING	G 35.96	35.96
1	401D/CHR 46305	SEAL	G 36.32	36.32
1	401D/STM 330 3009	HUB CAP GASKET *D	G 3.04	3.04
10	401D/TDA R005977R	NUT, RIGHT HAND *D	G 1.85	18.50
10	401D/TDA R007895R	NUT, RIGHT HAND *D	G 2.93	29.30
	LABOUR OTHER-33-01-050	FRONT AXLE WHEEL HUBS, BRAKE DRUMS, AND WHEEL BEARINGS		220.00
Prepay: \$0.00 Parts: \$149.84 Labour: \$220.00 [1.00] Misc: \$0 Sublet: \$0				\$369.84

JOB #13 03-WS-32-00 FRONT LEAF-SPRING SUSPENSION

COMPLAINT REPLACE BROKEN #2 RIGHT SHOCK

CAUSE

CORRECTION REPLACED BROKEN SHOCK ON #2 RIGHT SIDE

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	401D/GBL 85014	GABRIEL SHOCK *D	G 137.75	137.75
2	401X/FC-340-000-173Z	3/4NCSTOV	G 1.24	2.48
4	401X/FC-340-000-297Z	3/4 FLT WASHER	G 0.57	2.28
2	401X/FC-340-312-008Z	3/4X31/2NC	G 3.39	6.78
	LABOUR DTN-32-00-050	FRONT LEAF-SPRING SUSPENSION MISC		176.00
Prepay: \$0.00 Parts: \$149.29 Labour: \$176.00 [0.80] Misc: \$0 Sublet: \$0				\$325.29

Sold Operations Sub-Totals

Prepay: \$0.00 Parts: \$1,369.24 Labour: \$4,027.00 Misc: \$0.18 Sublet: \$0.00

\$5,396.42

*** DO NOT PAY THIS AMOUNT - SEE BOTTOM OF LAST PAGE FOR INVOICE TOTAL ***





3 - 380 RIVERSIDE ROAD ♦ ABBOTSFORD, BC V2S 7M4 ♦ (604) 504-5904

TRH 2/24

SERVICE INVOICE	
R401017935:01	
Invoiced:	19-Apr-2024
PO No:	
Terms:	NET30
Prorate#	BC03976-001



BILL TO
 SPRUCE HOLLOW HEAVY HAUL LTD.
 2511 GUILFORD DRIVE
 ABBOTSFORD BC V2S 5L9
 P: (604) 852-4179
 F:

DELIVER TO
 SPRUCE HOLLOW HEAVY HAUL LTD.
 2511 GUILFORD DRIVE
 ABBOTSFORD BC V2S 5L9
 P: (604) 852-4179
 F:

DATE CREATE	JE ID	ADVISOR	VIN ID	MODEL #	SERIAL #	ORIG. DOCUMENT	SALES TYPE
18-Apr-2024	2217099	EM EM	101756	FONTAINE SPECIA	4LF4S7955S3504151		SRET GST
HOURS	ODOM IN	ODOM OUT	CUSTOMER UNIT #				
0	1	1	23A				

Sold Operations

JOB #1 50-MVI TRAIL MVI TRAILER

COMPLAINT MVI TRAILER
 CAUSE
 CORRECTION PERFORM MVI. PASSED. DECAL #GB54019 EXPIRES APRIL 30 2025

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
Sold	LABOUR MVI TRAILER	MOTOR VEHICLE INSPECTION TRAILER	G	
				Package \$199.00

JOB #2 50-GREASE GREASE CHASSIS

COMPLAINT GREASE CHASSIS
 CAUSE
 CORRECTION GREASED CHASSIS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOUR GREASE	GREASE CHASSIS	B	105.50
Prepay: \$0.00 Parts: \$0 Labour: \$105.50 [0.50] Misc: \$0 Sublet: \$0				\$105.50

JOB #3 54-OTHER-42- TANDEM BRAKE CHAMBERS

COMPLAINT REPLACE RUSTED OUT #3 LEFT BRAKE POT
 CAUSE
 CORRECTION REPLACED ROTTED OUT BRAKE POT AND SEIZED HOSE. ADJUST BRAKE AND CHECK FOR LEAKS, OK.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	401D/23-14393-005	UNION-PTC,.38 NT TO .38 NT	G 4.72	4.72
1	401D/ABP N42A 30SCND	BRAKE CHAMBER *D	G 42.09	42.09
1	401D/TDA R810019	CLEVIS-KIT,LIGHTWEIGHT,20,2 *D	G 19.20	19.20
1	401X/FV-120-CB	3/8 X 1/4 NPT RED ADPT	G 1.75	1.75
1	401X/FV-4134-6C	FITTING	G 1.11	1.11
1	401X/FV-HAB-6-26C	HOSE	G 8.00	8.00
	LABOUR OTHER-42-03-050	TANDEM BRAKE CHAMBERS MISC	G	253.20
Prepay: \$0.00 Parts: \$76.87 Labour: \$253.20 [1.20] Misc: \$0 Sublet: \$0				\$330.07

