

JONNYS

LIGHT OILFIELD HAULING

1107 - 11 Street, Nisku, AB T9E 0C6
 Phone / Fax: 780-955-9399
 Email: info@jonnys.ca

B22-37
 MAY



20240401-6649

GARAGE REPAIR ORDER

5763

QTY	PART NO. AND DESCRIPTION	PRICE
	COMPLETE SERVICE (OIL ONLY)	
	REPAIRED R.S. FENDER	
	REPAIRED P.S FOG LIGHT	
	REPLACED BOTH ENGINE BELTS	

Date: April 01/26 Unit #: Driver's Name: Justin Plomp
 Year: 2016 Odometer: 1,272,724.4 km Hours: 27138
 VIN #: BU2904 Make: W/STAR
 Lic. #: OUB428 Model: 4900 SF.
 Work Performed by: TYLER T.

HRS.	WORK PERFORMED	COST
	1) Service ✓	27.00
	2) Right front fog lamp not working ✓	27.00
	3 straight Right side Rear fender (please) ✓	27.00
		27138
		250
		SER DUE - 27388 HRS.

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

Authorized by _____

Total Parts	
Total Labour	
Shop Supply	
Misc.	
Subtotal	
GST 855519435RT0001	
TOTAL	

JONNYS

LIGHT OILFIELD HAULING

1107 - 11 Street, Nisku, AB T9E 0C6
 Phone / Fax: 780-955-9399
 Email: info@jonnys.ca



20240401-6649

GARAGE REPAIR ORDER

5610

QTY	PART NO. AND DESCRIPTION	PRICE
	* Service done.	
	* Chain hanger	
	Bracket has been fixed.	

Date: Feb 08/26 Unit #: 118 Driver's Name: Dustin Plomf
 Year: 2016 Odometer: 256596.4km Hours: 26615 HRS
 VIN #: GC2904 Make: W/STAR
 Lic. #: @-UB428 Model: 4905F

Work Performed by:

HRS.	WORK PERFORMED	COST
	= Service (own hrs)	
	- Drivers side chain hanger, Rrt Bracket is broke, have a look. (Fix) 3	
	current HRS: 26615 HRS	

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

Authorized by _____

Total Parts	
Total Labour	
Shop Supply	
Misc.	
Subtotal	
GST 855519435RT0001	
TOTAL	

JONNYS

LIGHT OILFIELD HAULING

1107 - 11 Street, Nisku, AB T9E 0C6
 Phone / Fax: 780-955-9399
 Email: info@jonnys.ca



20240401-6649

GARAGE REPAIR ORDER

5522

QTY	PART NO. AND DESCRIPTION	PRICE
Date: <u>Jan 17/26</u> Unit #: <u>118</u> Driver's Name: <u>Dustin</u> Year: <u>2016</u> Odometer: _____ Hours: _____ VIN #: <u>B U 2 9 0 4</u> Make: <u>W/STAR</u> Lic. #: <u>0-UB428</u> Model: <u>4900SF.</u> Work Performed by: <u>Tyler W</u>		
HRS.	WORK PERFORMED	COST
	Pass side howl/burn burnt out ✓ might be ground wire in beam along left frame ✓ cooling system gets very cold when idling (TTCSTAT?) ✓ fine when driving, to New fan stat New fan stat ✓	
	* Turbo or waste gate? ✓ no boost under load when warm Blacksmoke idling white smoke.	
Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.		Total Parts
I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.		Total Labour
		Shop Supply
		Misc.
		Subtotal
		GST 855519435RT0001
_____ Authorized by		TOTAL

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

5457

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	246317KM	Unit #:	118
			Year: 2016	Odometer: 244558	Hours: 26222	26251
			VIN #: 6U2904	Make: W/STAR.		
			Lic. #: 0-W3428	Model: 4900SF		
	COMPLETE SERVICE AT 26251 HRS.		Work Performed by:			
			HRS.	WORK PERFORMED		COST
			22	Service. ✓		
	REPLACED THE LOWER P.S. MIRROR BRACKET WITH A GOOD USED ONE.		22	Drivers mirror bracket cracked again. ✓		
	REPLACED THE P.S LOWER WORK LAMP		22	Right side (pass) work light not working. ✓		
	REPAIRED WIRING ON P.S. TAIL LAMP		22	Right rear tail light (red) not working ✓		
	TOPPED UP ENGINE COOLANT - WAS LOW.		22	Truck cools down when parked, even at high idol. ✓		
				<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>		
				<p>Authorized by _____</p>		
				<p>Total Parts</p>		
				<p>Total Labour</p>		
				<p>Shop Supply</p>		
				<p>Misc.</p>		
				<p>Subtotal</p>		
				<p>GST 855519435RT0001</p>		
				<p>TOTAL</p>		

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

5435

QTY	PART NO. AND DESCRIPTION	PRICE	Date: Dec 28/25		Unit #: 118
			Year: 2016	Odometer:	Hours:
			VIN #: BU2904	Make: W/STAR	
			Lic. #: O-UB428	Model: 4900 SP.	
	SERVICED UNIT JAN 7 AT 26251 HRS.		Work Performed by:		
			HRS.	WORK PERFORMED	COST
				Dustin P.	
			20	1) Service. ✓	
	REPLACED WORK LAMP - P.S. LOWER.		20	2) passenger side Rear work light not working (upper light) ✓	
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>		
			<p>Authorized by _____</p>		
			Total Parts		
			Total Labour		
			Shop Supply		
			Misc.		
			Subtotal		
			GST 855519435RT0001		
			TOTAL		

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

5314

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <i>Nov 25/25</i>		Unit #: <i>118</i>
			Year: <i>2016</i>	Odometer:	Hours: <i>25818</i>
			VIN #: <i>6U2904</i>	Make: <i>W/STAR</i>	
			Lic. #: <i>0-UB428</i>	Model: <i>4900 SF</i>	
Work Performed by:					
HRS.	WORK PERFORMED				COST
	<i>Dustin G.</i>				
	<i>Service / done</i>				
	<i>Drivers side upper Running Board / chain hanger, at Back is broke or Bracket</i>				
	<i>added metal piece to upper a step</i>				
<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>					Total Parts Total Labour Shop Supply Misc.
_____ Authorized by					Subtotal GST 855519435RT0001 TOTAL

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
Nisku, AB T9E 8A2
Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

5206

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:
			Nov 04/25	118
			Year: 2016	Odometer:
			VIN #: G62904	Make: W/STAR
			Lic. #: 0-U3428	Model: 4900 SF.
			Work Performed by: Paul	
HRS.	WORK PERFORMED	COST		
	- Right front tire (steer) inside tread wearing down to wear mark. Dustin P.	PP		
	- Truck shakes & shimmys & hops on bumps, hard banging on big cracks & R/R tracks. (shocks?)	PP		
	* checked the drive line, Ubolts, hop gangs, shocks, tires and all is fine. - front line replacing all stem nuts - Retorque when 575-7km	PP		
<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>			<p>Total Parts</p> <p>Total Labour</p> <p>Shop Supply</p> <p>Misc.</p> <p>Subtotal</p> <p>GST 855519435RT0001</p> <p>TOTAL</p>	
<p>Authorized by _____</p>				

012220

~~012220~~

12/10/01

11/10

W
W
T

2,100.00

PAID TO

11/10

2,100.00

0210002

10/11

012220

012220

012220

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

5004

QTY	PART NO. AND DESCRIPTION	PRICE	Date: July 14/25		Unit #: 118
			Year: 2016	Odometer: 197047	Hours: 24955
			VIN #: 6U2904	Make: W/STAR	
			Lic. #: OUB 428	Model: 4900 SF.	
			Work Performed by: TYLER T.		
			HRS.	WORK PERFORMED	COST
				Passenger side Rear fender bolts broke (trailer landed on the fender) have strap holding up ✓ <i>Dustin</i>	
				REPLACED THE BOLTS ON THE PASSENGER SIDE FENDER - UPSIZED TO 3/8" BOLTS.	
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>		
			<p>Authorized by _____</p>		<p>Total Parts</p> <p>Total Labour</p> <p>Shop Supply</p> <p>Misc.</p> <p>Subtotal</p> <p>GST 855519435RT0001</p> <p>TOTAL</p>

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

4954

QTY	PART NO. AND DESCRIPTION	PRICE	Date: June 24/25		Unit #: 158 (Dustin)
			Year: 2016	Odometer: 18	Hours:
			VIN #:	Make: W/STAR	
			Lic. #:	Model: 4900ff.	
			Work Performed by:		
			HRS.	WORK PERFORMED	COST
				NOTE, see CVSA Level #1 inspection in dispatch.	
				- Air Lines worn through.	
				- Air tack between drive axles hoses.	
				- Power steering pump heating when running.	
				-	
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>		Total Parts Total Labour Shop Supply Misc. Subtotal GST 855519435RT0001 TOTAL
			_____ Authorized by		

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
Nisku, AB T9E 8A2
Ph/Fax: 780-955-9399 Email: info@jonnys.ca



GARAGE REPAIR ORDER

4912

20150520 - 0033

★ CV8370021 ★

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:
★	TORQUED WHEELS TO 500 FT/LBS AND PUT A RETORQUE TAG IN THE TRUCK ★		JUNE 10 2025	118
			Year: 2016	Odometer: 1185296 KM
			VIN #: 5KJJAED17GPGU2904	Hours: 24723
			Lic. #: 0BU 428	Make: WESTERN STAR
			Model: CONVENTIONAL	
			Work Performed by: TYLER TOKAREK	
HRS.	WORK PERFORMED	COST		
	★ ALL WHEELS REMOVED AT THE TIME OF INSPECTION ★			
	HAD ALTA-TEC REPLACE BOTH WINDSHIELDS.			
	INSTALLED A REBUILD KIT INTO THE FAN HUB			
	INSTALLED A REBUILD KIT INTO THE 5TH WHEEL			
	REPLACED THE INPUT SEAL ON THE FRONT DIFF			
	REPLACED THE BACK-UP ALARM			
	REPLACED POWER STEER FILTER AND OIL			
	ADJUSTED TIRE PRESSURES			
	RE MOUNTED LICENSE PLATE			
	REPLACED DIFF FILTER AND TOPPED UP THE OIL			
	GREASED UNIT, SET BRAKES			
	TOPPED UP ALL FLUIDS.			
<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>			Total Parts	
			Total Labour	
<p>Authorized by _____</p>			Shop Supply	
			Misc.	
			Subtotal	
			GST 855519435RT0001	
			TOTAL	

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



GARAGE REPAIR ORDER

4853

20150520 - 0033

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:	
			MAY 13 / 25	118	
			Year: 2016	Odometer: 182272	
				Hours: 24636	
			VIN #: 6U290Y	Make: W/star	
			Lic. #:	Model: 4900 Sf	
			Work Performed by: TYLER T.		
			HRS.	WORK PERFORMED	COST
	ROTATED STEER TIRES FROM SIDE TO SIDE			1) Staking & shimming as if it out of balance (steers?) Tires changed but cupping again.	
	ADJUSTED TIRE PRESSURES ON THE STEERS TO 120 PSI			Front Right tire cupping Front Left tire separated ✓ 22	
	REMOVED AND SENT OUT THE P.S. CHAIN HANGER TO BE WELDED.			2) Passenger side chain hanger can't be loose at front bracket.	
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>		
				Total Parts	
				Total Labour	
				Shop Supply	
				Misc.	
				Subtotal	
				GST 855519435RT0001	
				TOTAL	
			<p>_____ Authorized by</p>		

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

4771

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:
			April 07/15	118
			Year: 2016	Odometer: 1: 178591
			VIN #: GU2904	Hours: 24550
			Lic. #: 0-UB428	Make: W/Star
				Model: 4900 SF
	COMPLETE SERVICE (OIL ONLY)		Work Performed by:	
			HRS.	WORK PERFORMED
				COST
				Service ✓ 22 SERDUE 24800
	REPAIRED P.S. TIRE CHAIN HANGER			Right side upper foot rail at back, cracked broken for chain hanger. ✓ 22
	WILL PROBABLY DO THE DRIVE TIRES DURING CVI (JUNE) *IF THEY LAST THAT LONG *			check drive tires for wear. ✓ 22
	SENT OUT INTER-AXLE DRIVESHAFT OUT FOR REPAIR.		<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>	
			<p>Total Parts</p> <p>Total Labour</p> <p>Shop Supply</p> <p>Misc.</p> <p>Subtotal</p> <p>GST 855519435RT0001</p> <p>TOTAL</p>	
			<p>Authorized by _____</p>	

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

4579

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <i>MAR 07/25</i>		Unit #: <i>118</i>
			Year: <i>2016</i>	Odometer: <i>1,165,906</i>	Hours: <i>24,215</i>
			VIN #: <i>GU 2904</i>	Make: <i>W/STAR</i>	
			Lic. #: <i>0-UB428</i>	Model: <i>4900 SF</i>	
Work Performed by:					
HRS.	WORK PERFORMED				COST
	<i>Dist.</i>				
	<i>Service ✓ 22</i>				
	<i>COMPLETE SERVICE - OIL ONLY.</i>				
				<i>24215</i>	
				<i>250</i>	
				<i>SER DUE - 24465 HRS</i>	
<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>					<p>Total Parts</p> <p>Total Labour</p> <p>Shop Supply</p> <p>Misc.</p>
<p>_____</p> <p>Authorized by</p>					<p>Subtotal</p> <p>GST 855519435RT0001</p> <p>TOTAL</p>



20150520 - 0033

GARAGE REPAIR ORDER

4048

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:
			Feb 03/25	118
			Year: 2016	Odometer:
			VIN #: BU 2904	Hours:
			Lic. #: 0-U3 428	Make: W/STAR
				Model: 4900 SF
	REPLACED THE HEATER CONTROL PANEL AND THE HEATER MOTOR.		Work Performed by:	
			HRS.	WORK PERFORMED
				COST
	REPLACED FUEL FILTERS			1) No Dash Heat, only cold air. ✓
				2) loses power as it starving for fuel, will not respond to foot feed (acc pedal) and slows down. ✓
				Runs fine at idle, but loses power when accelerating. ✓
				Dustin P.
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>	
				Total Parts
				Total Labour
				Shop Supply
				Misc.
				Subtotal
				GST 855519435RT0001
				TOTAL
			Authorized by _____	

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

4088

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <u>Jan 14 / 25</u>		Unit #: <u>118</u>
	<u>Service + Lube</u>		Year: <u>2016</u>	Odometer:	Hours:
	<u>RX module Replaced</u>		VIN #: <u>GU2904</u>	Make: <u>W/STAR</u>	
	<u>Tighten / Clean Batt Connections</u>		Lic. #: <u>O-4B428</u>	Model: <u>4900 SP.</u>	
	<u>Check every fuse in unit</u>		Work Performed by:		
	<u>Replace 11 Weak Resettable fuse</u>		HRS.	WORK PERFORMED	COST
				<u>Dustin P.</u>	
				<u>Dash gauges not working</u>	<u>New RX</u>
				<u>high beam shorts out occasionally</u>	<u>module</u>
				<u>but more & more. ✓ TW</u>	
				<u>(might be module)</u>	
				<u>- Bunk heater fan not working ✓ TW</u>	
				<u>- Service. service 3 Lube ✓ TW</u>	
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>		<p>Total Parts</p> <p>Total Labour</p> <p>Shop Supply</p> <p>Misc.</p> <p>Subtotal</p> <p>GST 855519435RT0001</p> <p>TOTAL</p>
			<p>_____ Authorized by</p>		

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

4223

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:
			Dec 08/24	118 Justin.
			Year: 2016	Odometer:
			VIN #: Bu 2904	Make: W/STAR
			Lic. #: D-WB428 AS	Model: 4900 SR.
			Work Performed by:	
			HRS.	WORK PERFORMED
				1) Does NOT start after shut off over night. ✓
	REPLACED ALL 4 BATTERIES.			2) H2S or rotten egg smell coming from batteries ✓
				3) Right signal light keeps shorting out
	SUPPLIED TIRE CHAINS.			4) Need 2 sets of tire chains old one stretched & broken ✓
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>	
			<p>Authorized by _____</p>	
			Total Parts	
			Total Labour	
			Shop Supply	
			Misc.	
			Subtotal	
			GST 855519435RT0001	
			TOTAL	

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

4196

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <u>Nov 24/24</u>		Unit #: <u>118</u>
			Year: <u>2016</u>	Odometer:	Hours: <u>23365.5h.</u>
			VIN #: <u>6U2904</u>	Make: <u>W/STAR</u>	
			Lic. #: <u>D-U3428</u>	Model: <u>4900 SF.</u>	
			Work Performed by:		
			HRS.	WORK PERFORMED	COST
	REPLACED FRONT BUMPER WITH A GOOD USED ONE			SER V138 ✓ <u>JD</u> . SERVICED UNIT - OIL ONLY	
				- Broken Rod bumper, ✓ <u>JD</u>	
				- Small coolant leak, centre behind bumper, ✓ <u>JD</u>	
				SER DUE -	23369 HRS
					250
	COULD NOT LOCATE COOLANT LEAK			Justin	23619 HRS.
				Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.	Total Parts
				I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.	Total Labour
					Shop Supply
					Misc.
					Subtotal
					GST 855519435RT0001
				Authorized by _____	TOTAL

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

3725

QTY	PART NO. AND DESCRIPTION	PRICE	Date: Oct 26/24		Unit #: 118
			Year: 2016	Odometer: 127698	Hours: 23049
			VIN #:	Make: W/STAIR	
			Lic. #: O-UB428 AR.	Model: 4900 \$	
Work Performed by:					
HRS.	WORK PERFORMED				COST
	Roads Service - ✓				
	COMPLETE SERVICE - OIL ONLY				
				23049 HRS	
				250	
				SERDUE-23300 HRS	
<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p> <p>_____</p> <p>Authorized by</p>					Total Parts
					Total Labour
					Shop Supply
					Misc.
					Subtotal
					GST 855519435RT0001
					TOTAL

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

4430

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <i>Oct 01/24</i>		Unit #: <i>118</i>
			Year: <i>2016</i>	Odometer: <i>117301</i>	Hours: <i>22798</i>
			VIN #: <i>6U2904</i>	Make: <i>W/S</i>	
			Lic. #:	Model: <i>4900 SF</i>	
			Work Performed by: <i>TYLER TOKAREK</i>		
HRS.	WORK PERFORMED	COST			
	<i>Needs A Service</i>				
	<i>Fog Lamps. (if time permits)</i>				
	<i>- SERVICED UNIT - OIL ONLY</i>				
	<i>- INSTALLED NEW FOG LAMPS</i>	<i>22798</i>			
		<i>250</i>			
		<i>SER DUE - 23048 hrs</i>			
<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>			<p>Total Parts</p>		
			<p>Total Labour</p>		
			<p>Shop Supply</p>		
			<p>Misc.</p>		
			<p>Subtotal</p>		
			<p>GST 855519435RT0001</p>		
			<p>TOTAL</p>		
			<p>Authorized by _____</p>		

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

4346

QTY	PART NO. AND DESCRIPTION	PRICE	Date:	Unit #:	
	TORQUED WHEEL TO 500 FT/LBS. AND PUT A RETORQUE TAG IN THE TRUCK.		Aug 25/24	118	
			Year: 2016	Odometer: 103670 KM.	Hours: 22539 ?
			VIN #:	Make: Western Star	
			Lic. #:	Model: 4900 SF	
			Work Performed by:	TYLER T.	
	HRS.	WORK PERFORMED	COST		
		1 - Driver side, Rear axel, inside Dual flat, off. bead.			
		2. Needs service.			
				22542 HRS	
				250	
				SER DUE - 22792 HRS	
		COMPLETE SERVICE - OIL ONLY			
		REMOVED DS. REAR INSIDE TIRE			
		HAD TIRE REPAIRED AND PUT BACK ON.			
		<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p> <p>_____</p> <p>Authorized by</p>	Total Parts		
			Total Labour		
			Shop Supply		
			Misc.		
			Subtotal		
			GST 855519435RT0001		
		TOTAL			

Jonny's Light Oilfield Hauling Ltd.

PO Box #214, 2120 Sparrow Drive
Nisku, AB T9E 8A2
Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

3947

QTY	PART NO. AND DESCRIPTION	PRICE	Date: <u>June 21/24</u> <u>June 28/24</u> Unit #: <u>118</u>		
			Year: <u>2016</u>	Odometer: <u>82163</u>	Hours: <u>86094</u>
			VIN #:	Make: <u>w/s</u>	
			Lic. #: <u>0-4B428 AS.</u>	Model: <u>4900</u>	
			Work Performed by: <u>Tyler S.</u>		
			HRS.	WORK PERFORMED	COST
				1) When headlights are on The Right signal light does not work, when headlights are off it does fixed wiring	
				2.) d/side bumper marker light and Rubber insert fell out and went missing.	
				- Replaced garmet, pig tail and light on LHS	
				- Replaced pig tail and light on RHS	
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>		
				Total Parts	
				Total Labour	
				Shop Supply	
				Misc.	
				Subtotal	
				GST 855519435RT0001	
				TOTAL	
			<p>_____ Authorized by</p>		

JANOT
EST 2
1912

Handwritten text, possibly a name or address, written vertically.

Handwritten text, possibly a name or address, written vertically.

Handwritten text, possibly a name or address, written vertically.

Handwritten text, possibly a name or address, written vertically.

Handwritten text, possibly a name or address, written vertically.

Handwritten text, possibly a name or address, written vertically.

1912

Jonny's Light Oilfield Hauling Ltd.

CUI # CV8033441

PO Box #214, 2120 Sparrow Drive
 Nisku, AB T9E 8A2
 Ph/Fax: 780-955-9399 Email: info@jonnys.ca



20150520 - 0033

GARAGE REPAIR ORDER

3695

QTY	PART NO. AND DESCRIPTION	PRICE	Date: 06/11/24	Unit #: 118
			Year:	Odometer: 1077986
			VIN #:	Hours:
			Lic. #:	Make:
			Model:	
			Work Performed by: Alex D	
			HRS.	WORK PERFORMED
				COST
				CUIP Inspection & Repairs
				Perform deletes
				Perform oil & Fuel change
				New air filters
				New diff filter
				Front diff oil swap
				New signal lights
				New high beams
				All wheel seals, s-cams, & s-cam seals
				New junction box & light bar at rear
				Retorque tag put in truck
			<p>Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.</p> <p>I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.</p>	
				Total Parts
				Total Labour
				Shop Supply
				Misc.
				Subtotal
				GST 855519435RT0001
				TOTAL
			<p>Authorized by _____</p>	

