

Vegreville Mechanical Ltd.

P.O. BOX 67

Vegreville, AB

T9C 1R1

Tel.#: (780) 632-4140 Fax: (780) 632-6021

CARIBOO RAIL SHOP
BRANDON MIKI
6565 Industrial Way
Prince George, BC V2N5S6

0 TR-07 TRAILER
Plate :
ODO :
V.I.N. :
Unit #:
Engine:

INV # : 88999
Date : 06/07/2024
Time : 01:19PM
PO # :
GST # : 133447649RT
Tech. : Multiple/

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
1.00		7POLE SOCKET Part #: 82-1056B	19.18	19.18		GST	19.18	
1.00		BULB Part #: GEL 67	1.13	1.13		GST	1.13	
2.00		FENDR MRKR LGT-ABB/RED/CLR Part #: S90-0000-1	7.80	15.60		GST	15.60	
2.00		CHROME WIRE GUIDE Part #: S90-0C00-1	2.64	5.28		GST	5.28	
3.90		FIX LIGHTS			585.00	GST	585.00	
		FIX GROUND +REPLACE TRAILER CONNECTOR				GST		
		REPLACE LICENCE PLATE BULB				GST		
		REPLACE FENDER LIGHTS				GST		
		Shop Supplies			35.10	GST	35.10	

WO# 95461 05/29/2024 05:50PM

Copyright 2024 Autogence Inc. - LANKAR 11.18.4

NO LIGHTS WORKING

CUSTOMER SIGNATURE

06/07/2024 A/R 694.35

ALL ESIMATES ARE FOR LABOUR ONLY - MATERIALS ADDITIONAL.
THIS COMPANY IS NOT RESPONSIBLE FOR OIL LEAKS CAUSED BY
THE WORK DONE BY IT, OR ITS SERVANTS, OR AGENTS ON YOUR
VEHICLE, WHETHER THE SAME RESULTED FROM THE NEGLIGENCE
OF ITS SERVANTS OR AGENTS OR OTHERWISE UNLESS SUCH LEAKS
ARE REPORTED TO THE COMPANY, IN WRITING, WITHIN SEVEN
(7) DAYS FROM COMPLETEION OF SERVICE. THIS COMPANY SHALL
NOT BE RESPONSIBLE FOR LOSS OR DAMAGE TO THE VEHICLE OR
ARTICALS LEFT IN THE VEHICLE WHETHER CAUSED BY FIRE,
THEFT OR ANY OTHER CAUSE WHATSOEVER, INCLUDING
NEGLIGENCE ON THE PART OF ITS SERVANTS, OR AGENTS.
VEHICLES DRIVEN BY OUR EMPLOYEES AT OWNERS RISK.

Sub Tot.	41.19	620.10	661.29
	GST		33.06
	PST		0.00
	Deductible		0.00
	Total		694.35

Page

1 of 1