



### SHOP REPAIR SHEETS



<b>START DATE:</b> 11/13/2025	<b>HOURS:</b> 19693
<b>UNIT #:</b> 36 - Tridem Tractor	<b>KMS:</b> 753092
<b>MAKE/MODEL:</b> Kenworth	<b>NEXT SERVICE:</b> 19943

**WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate):** Yes

**If YES, Deficiency Requiring Attention Please Indicate Reported Date:**

-

**If NO, Deficiency Requiring Attention:**

Description of work done	Vendor	Part #
Remove hydraulic pump, pto and transmission, remove damaged rear structure, remove 3rd busted cross member, remove engine motor mount bracket (egg out)	-	
Remove and replace bolts for 2nd cross member and install new flange bolts, install new 3rd cross member with new flange bolts, remove and replace worn out tie rod ends.	-	
Inspect clean the used rear structure, clean all holes and surface, install rear structure with new gasket and rear main seal and torque to specs, install flywheel and torque to specs, install transmission and set clutch to specs, install pto and hydraulic pump and drive line, install remain external air tanks	-	
Install new tie rod end and set toe Fill transmission with cd50 check for leaks and verify all repairs	-	


**END DATE:** 11/25/2025

**Notes:**

Frame needs to be aligned

**Mechanic:**

Raphie Laurente



RL

SIGNATURE:



# SHOP REPAIR SHEETS



START DATE: 10/26/2025	HOURS: 9507
UNIT #: 36 - Tridem Tractor	KMS: 385170
MAKE/MODEL: Kenworth	NEXT SERVICE: 9674

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): **Yes**

If YES, Deficiency Requiring Attention Please Indicate Reported Date:  
10/24/25

If NO, Deficiency Requiring Attention:



Description of work done	Vendor	Part #
Perform service, remove and replace A3 brake shoes on both sides, remove and replace hub on A3L (wheel seal leaking and bearing are starting to pitted) Diagnose coolant leaks	-	

END DATE: 10/26/2025



Notes:

Mechanic:  
Raphie Laurent

RL

SIGNATURE:



# SHOP REPAIR SHEETS



START DATE: 09/17/2025 HOURS: 19968

UNIT #: 36 - Tridem Tractor KMS: 764523

MAKE/MODEL: Kenworth NEXT SERVICE: 20199

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): Yes

If YES, Deficiency Requiring Attention Please Indicate Reported Date:  
08/24/25 and 09/10/25

If NO, Deficiency Requiring Attention:



Description of work done	Vendor	Part #
Changed air dryer cartridge, found rad cap was not sealing no pin hole in resivor replaced rad cap, replaced all shocks replaced u-joint to first diff, got blower motor working	Jrf, napa, artic	U-joint, shocks, rad cap.

END DATE: 09/18/2025



Notes:

Mechanic:  
Scott Belcourt

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 09/15/2025	HOURS: 19957
UNIT #: 36 - Tridem Tractor	KMS: 764024
MAKE/MODEL: Kenworth	NEXT SERVICE: 20199

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:  
Broken flex pipe off turbo

Description of work done	Vendor	Part #
Replaced 4" broken flex pipe, and 4" step clamps, plus turbo clamp and gasket	JRF, the diesel shop	4" flex pipe, 4" step clamp, turbo out let clamp and gasket

END DATE: 09/15/2025

Notes:

Mechanic:  
Scott Belcourt

SIGNATURE:



# Inspection & Maintenance Record



**TRUCK**

Date: 08/04/2025

Unit: 36 - Tridem  
Tractor

Odometer: 753092

Hours: 19693

SCHEDULE

Hours: ✓

Monthly:

Other:

TRUCK	Schedule 2 – Inspected Components
✓	Body & Chassis
✓	Cab Interior & Seat
✓	Windows & Mirrors
✓	Steering Column & Box
✓	Steering Linkage
✓	Windshield Wipers & Washers
✓	Heating & Defrosting Systems
✓	Starting Switch
✓	Lamps & Reflectors
✓	Underbody
✓	Drive Shaft
✓	Mechanical Components
✓	Air Break System
✓	Parking Brake
✓	Brake System
✓	Engine Controls
✓	Suspension
✓	Electrical Components
✓	Tires
✓	Fifth Wheel Coupling Device
✓	Trailer Hitch, Mounts & Connecting Device
LUBRICANTS	
✓	Change Engine Oil & Filter
	Change Fuel Filter
	Change Differential Filter
	Change Coolant Filter
✓	Unit Greased
✓	Fluids Topped Up
✓	<b>RECHECK OIL LEVELS</b>
✓	<b>CHECK FOR ACTIVE LEAKS OIL/GREASE</b>
Additional Comments	

Work Completed By: Raphie Laurente

Next Service Due: 19943

RL

Signature:



# Inspection & Maintenance Record



**TRUCK**

Date: 08/04/2025

Unit: 36 - Tridem  
Tractor

Odometer: 753092

Hours: 19693

SCHEDULE

Hours: ✓

Monthly:

Other:

TRUCK	Schedule 2 – Inspected Components
✓	Body & Chassis
✓	Cab Interior & Seat
✓	Windows & Mirrors
✓	Steering Column & Box
✓	Steering Linkage
✓	Windshield Wipers & Washers
✓	Heating & Defrosting Systems
✓	Starting Switch
✓	Lamps & Reflectors
✓	Underbody
✓	Drive Shaft
✓	Mechanical Components
✓	Air Break System
✓	Parking Brake
✓	Brake System
✓	Engine Controls
✓	Suspension
✓	Electrical Components
✓	Tires
✓	Fifth Wheel Coupling Device
✓	Trailer Hitch, Mounts & Connecting Device
LUBRICANTS	
✓	Change Engine Oil & Filter
	Change Fuel Filter
	Change Differential Filter
	Change Coolant Filter
✓	Unit Greased
✓	Fluids Topped Up
✓	<b>RECHECK OIL LEVELS</b>
✓	<b>CHECK FOR ACTIVE LEAKS OIL/GREASE</b>
Additional Comments	

Work Completed By: Raphie Laurente

Next Service Due: 19943

RL

Signature:



### SHOP REPAIR SHEETS



START DATE: 07/22/2025

HOURS:

UNIT #: 36 - Tridem Tractor

KMS:

MAKE/MODEL: Kenworth

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
Diagnose no jbrakes	-	

END DATE: 07/22/2025

Mechanic: Raphie Laurente

RL

SIGNATURE:



# SHOP REPAIR SHEETS



START DATE: 07/02/2025	HOURS: 19495
UNIT #: 36 - Tridem Tractor	KMS: 745088
MAKE/MODEL: Kenworth	NEXT SERVICE: 19650

WAS THERE A DEFICENTCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:

Trip issue

Description of work done	Vendor	Part #
Trip issue - diagnosed trip, found trip plug was shorted out, removed and replaced plug with new	JRF	*1 6 wire male plug

END DATE: 07/02/2025

Mechanic: Landen LaPierre

SIGNATURE:



# SHOP REPAIR SHEETS



START DATE: 06/25/2025	HOURS: 19438
UNIT #: 36 - Tridem Tractor	KMS: 742307
MAKE/MODEL: Kenworth	NEXT SERVICE: 19650

WAS THERE A DEFICENTCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
Exhaust broken - removed and replaced flex pipe on d/s stack	JRF/napa	*2 5" stepped exhaust clamps *1 2ft of 5" flex pipe
Coolant line going into bunk - removed and replaced coolant line going into bunk	JRF	*1 6" chunk of 5/8" heater hose
Cabin air filter - removed and replaced air filter with new	JRF	*1 cabin air filter
Blend door actuator - removed and replaced blend door actuator as it was shorted out causing the settings to not change	Kenworth	*1 actuator
Shifter boot - removed and replaced shifter boot with new as old one was ripped and had holes in it	ARTIC	*1 shift boot
Hydraulic line for winch - removed and replaced hydraulic line going into winch as it was broke off	Sid's	*1 new hydraulic line

END DATE: 06/26/2025

Mechanic: Landen LaPierre



# SHOP REPAIR SHEETS



START DATE: 06/17/2025	HOURS: 19399
UNIT #: 36 - Tridem Tractor	KMS: 740866
MAKE/MODEL: Kenworth	NEXT SERVICE: 19650

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:



Description of work done	Vendor	Part #
Service - completed service on unit, replaced oil filters, oil and both fuel filters, greased unit	JRF	*1 oil filter *2 fuel filters *44 l oil

END DATE: 06/17/2025



Mechanic: Landen LaPierre

SIGNATURE:



# Inspection & Maintenance Record



**TRUCK**

Date: 06/17/2025

Unit: 36 - Tridem

Odometer: 740866

Hours: 19399

Tractor

SCHEDULE

Hours:

Monthly:

Other:

TRUCK	Schedule 2 – Inspected Components
✓	Body & Chassis
✓	Cab Interior & Seat
✓	Windows & Mirrors
✓	Steering Column & Box
✓	Steering Linkage
✓	Windshield Wipers & Washers
✓	Heating & Defrosting Systems
✓	Starting Switch
✓	Lamps & Reflectors
✓	Underbody
✓	Drive Shaft
✓	Mechanical Components
✓	Air Break System
✓	Parking Brake
✓	Brake System
✓	Engine Controls
✓	Suspension
✓	Electrical Components
✓	Tires
✓	Fifth Wheel Coupling Device
	Trailer Hitch, Mounts & Connecting Device
LUBRICANTS	
✓	Change Engine Oil & Filter
✓	Change Fuel Filter
	Change Differential Filter
	Change Coolant Filter
✓	Unit Greased
✓	Fluids Topped Up
✓	<b>RECHECK OIL LEVELS</b>
✓	<b>CHECK FOR ACTIVE LEAKS OIL/GREASE</b>
Additional Comments	

Work Completed By: Landen LaPierre

Next Service Due: 19650

Signature:



SHOP REPAIR SHEETS



START DATE: 06/14/2025

HOURS:

UNIT #: 36 - Tridem Tractor

KMS:

MAKE/MODEL: Kenworth

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? No

If NO, Deficiency requiring attention:

Service call to 142 on FTR

Description of work done	Vendor	Part #
Main air compressor line - found line was rubbed through, removed and replaced with new built line from compressor to air dryer.	220 service truck	*2 -10 jic female ends *10ft of 1/2 steel braided hose
Air line rubbed through going into cab- found 1/4 air line rubbed through going into cab, install 1/4 air to air splicer	SERVICE TRUCK	* 1 1/4 air to air splicer

END DATE: 06/14/2025

Mechanic: Landen LaPierre

SIGNATURE:



# SHOP REPAIR SHEETS



START DATE: 05/15/2025	HOURS: 19198
UNIT #: 36 - Tridem Tractor	KMS: 731336
MAKE/MODEL: Kenworth t800	NEXT SERVICE: 19348

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:

Wheel pull cvip, plus repairs

Description of work done	Vendor	Part #
Did wheel pull cvip plus repairs, replaced front spring pins and bushings, #2rh,#3rh brake shoes, and drums, s-cams and s-cam bushings, replaced , steer axle s-cam and bushings, fixed all lights that failed, fixed back up alarm.	JRF artic	Lights, pigtailes, spring pins and bushings, s-cams, s-cam bushing kits, brake shoes, drums, back up alarm

END DATE: 05/28/2025

Mechanic: Scott Belcourt

SIGNATURE:



# SHOP REPAIR SHEETS



START DATE: 04/08/2025 HOURS: 19154

UNIT #: 36 - Tridem Tractor KMS: 729653

MAKE/MODEL: Kenworth NEXT SERVICE: 19222

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? No

If NO, Deficiency requiring attention:  
Hydraulic leak  
Lights out



Description of work done	Vendor	Part #
Hydraulic filter housing leaking - Removed and replaced winch hydraulic filter housing and installed new filters	1. Jrf 2. Napa 3. Drive products	1. Hydraulic fluid 2. Hydraulic filters 3. Filter housing
Filled hydraulic tank		
Lights out and missing  Missing a clearance light on drivers air cleaner lights. Installed new Amber 2" light  Drivers side walking deck light broken Removed and replaced	Jrf	Lights

END DATE: 04/09/2025



Mechanic: Connor Vanderveen

SIGNATURE:



# SHOP REPAIR SHEETS



START DATE: 04/17/2025	HOURS: 19160
UNIT #: 36 - Tridem Tractor	KMS: 729860
MAKE/MODEL: Kenworth	NEXT SERVICE: 19222

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
Diagnose low boost, check for more visual leaks, hook up lap top and diagnose, Replace egr clamp and straighten egr valve,	-	

END DATE: 04/17/2025

Mechanic: Raphie Laurente

RL

SIGNATURE:



### SHOP REPAIR SHEETS



START DATE: 03/09/2025	HOURS: 18984
UNIT #: 36 - Tridem Tractor	KMS: 720939
MAKE/MODEL: Kenworth	NEXT SERVICE: 19222

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:  
Serpentine belt is loose

Description of work done	Vendor	Part #
Found that the belt tensioner dowel pin was shredded off and not staying in the front cover. Removed and replaced front cover	Jrf	Belt tensioners

END DATE: 03/09/2025

Mechanic: Connor Vanderveen

Connor

SIGNATURE:



# Monthly Inspections

Please complete and hand-in on the first of every month

Unit Number: 36 - Tridem Tractor  
Mileage: 762010  
Hours: 19084

Date: 03/20/2025  
Next service Due: 19222

Registration?: Yes  
Insurance?: Yes  
Drivers Binder? Yes  
Has it been recently updated?: Yes  
Safety Fitness Certificate  
(needed only for GVW of 11,794)? Yes  
Company Emergency Contact sheet?: Yes  
CVIP Paperwork? Yes  
CVIP DATE: 05 07 2025  
Road Bonds?: Yes  
Unit Number Sticker?: Yes  
TARE/GVW? Yes  
Compare TARE/GVW to registration:   14400       63500  
  TARE       GVW

Hydraulic Hose (In good Condition)? No  
CSA First Aid Kit?: Yes  
Fire Extinguisher?: Yes  
Fire Extinguisher Certification Due Date?: 01 2025  
Roadside Flares? Yes  
PPE? Yes  
Flashlight?: Yes  
Ticket Book? Yes  
Functioning 2-way radio?: Yes  
Tool Kit?: Yes  
Tire Chains? Yes  
Spill Kit?: Yes

Ken Vande Voorde  
Inspector/Driver Name

Inspector Signature

Please Note:  
Both KMS & HRS/Next service date are required  
New Update: CSA First Aid Kits



# SHOP REPAIR SHEETS



START DATE: 03/08/2025	HOURS: 18981
UNIT #: 36 - Tridem Tractor	KMS: 720829
MAKE/MODEL: Kenworth w900	NEXT SERVICE: 19222

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:

Throwing codes

Description of work done	Vendor	Part #
CEL - hooked computer up, found EGR differential pressure sensor, fixed sensor plug	JRF	No parts

END DATE: 03/08/2025

Mechanic: Landen LaPierre

SIGNATURE:



### SHOP REPAIR SHEETS



START DATE: 03/07/2025

HOURS: 18972

UNIT #: 36 - Tridem Tractor

KMS: 720644

MAKE/MODEL: Kenworth

NEXT SERVICE: 19000

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? No

If NO, Deficiency requiring attention:

Coolant over flow

Description of work done	Vendor	Part #
Pressure tested, replace reservoir cap	-	

END DATE: 03/07/2025

Mechanic: Raphie Laurente

RL

SIGNATURE:



### SHOP REPAIR SHEETS



START DATE: 03/06/2025	HOURS: 18972
UNIT #: 36 - Tridem Tractor	KMS: 720644
MAKE/MODEL: Kenworth	NEXT SERVICE: 19000

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
Install new speed sensor, check continuity from the fire wall, rewire corroded wire	-	

END DATE: 03/06/2025

Mechanic: **Raphie Laurente**

RL

SIGNATURE:

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue

Edmonton, AB

T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:  
Kenworth Leduc  
8202 - 42 Street  
Leduc Alberta T9E 8M6  
Phone: 780-612-9855

Invoice: **06AP321154**  
Date / Time: 2/28/2025 12:17:00PM  
Parts Order: 321154  
Customer: **4446**  
Branch: Leduc  
Invoice Total: **\$ 6,970.22**  
\*\*\* Charge \*\*\*

Page 1 of 2

Bill To: JRF OILFIELD SERVICES LTD.  
PO BOX 7382  
EDSON, AB T7E 1V6

Ship To: JRF OILFIELD SERVICES LTD.  
PO BOX 7382  
EDSON, AB T7E 1V6  
Office Phone: (780) 728-5154  
Shop Phone: (780) 728-5154  
Email: admin@jrfoilfield.ca

Customer P/O: P/O: 36

Inside Slmn: Dpaynter

Delivery Method: ROCKET EXPRESS

Supplier	Part / Misc	Description / Ref Number	U/M	Quantity	Price	Ext Price
P0100	3103584CUM	HOUSING FLYWHEEL	EA	1	\$3,929.45	\$3,929.45
	IN STOCK					
						Bin Location: R014 B2
P0100	4393176CUM	GASKET, FLYWHEEL HOUSING	EA	1	\$147.86	\$147.86
	IN STOCK					
						Bin Location: R013 E
P0100	D13-1001-1	BUSHING-REAR ENGINE 100/MM	EA	2	\$140.28	\$280.56
	IN STOCK					
						Bin Location: 25C
P0100	K066-421	BUSHING-SNUBBER BAR 200/MM	EA	2	\$80.47	\$160.94
	IN STOCK					
						Bin Location: 25H02
M0047	HWC01079	BOLT-HEX M20-2.50X120 CL10.9 PHO	EA	2	\$25.76	\$51.52
	IN STOCK					
						Bin Location: 02L05
P0100	K169-163-20CA	NUT-HEX SL NYL M20-2.50X22.15T CAD	EA	2	\$20.05	\$40.10
	IN STOCK					
						Bin Location: 01F10D
M0047	HWC05722	WASHER-ROUND M20X37X4 HDND CAD	EA	12	\$3.71	\$44.52
	IN STOCK					
						Bin Location: 01E10
M0047	HWC04641	BOLT-HEX SL NYL 3/4-10NCX2-1/4 GR8	EA	8	\$10.90	\$87.20
	IN STOCK					
						Bin Location: 01I01B
P0100	4026684CUM	GASKET OIL PAN	EA	1	\$368.51	\$368.51
	in stock					
						Bin Location: R013 F
E0160	308925-25CA	EP 15.5, 2050 TORW, VCT DAMPER, 7-SPR 288	EA	1	\$1,565.74	\$1,565.74
						Bin Location: R046 F1
	PACCAR: Loyalty Card Program M25JANMAR7250 40					
	COUPON	LOYALTY CARD		-1	\$40.00	-\$40.00
P0100	K159-961	LEG-ENG REAR	EA	1	\$0.00	\$0.00

Item Backordered - Paccar Air

Customer Tax ID: 801394149RT0001

GST/HST Number:

Detail Tax Info:

GST REGISTRATION NUMBER: R101577278

\$333.82  
Total: \$333.82

\*\* See Last Page for Invoice Total \*\*

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue

Edmonton, AB

T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:  
Kenworth Leduc  
8202 - 42 Street  
Leduc Alberta T9E 8M6  
Phone: 780-612-9855

Invoice: **06AP321154**  
Date / Time: 2/28/2025 12:17:00PM  
Parts Order: 321154  
Customer: [REDACTED]  
Branch: Leduc  
Invoice Total: **\$ 6,970.22**  
\*\*\* Charge \*\*\*

Page 2 of 2

**Bill To:** JRF OILFIELD SERVICES LTD.  
PO BOX 7382  
EDSON, AB T7E 1V6

**Ship To:** JRF OILFIELD SERVICES LTD.  
PO BOX 7382  
EDSON, AB T7E 1V6  
Office Phone: (780) 728-5154  
Shop Phone: (780) 728-5154  
Email: admin@jrfofield.ca

Customer P/O: P/O: 36

Inside Srmn: Dpaynter

Delivery Method: ROCKET EXPRESS

Supplier	Part / Misc	Description / Ref Number	U/M	Quantity	Price	Ext Price
----------	-------------	--------------------------	-----	----------	-------	-----------

Total Parts:	\$6,676.40
Total Miscellaneous:	\$(40.00)
Invoice Subtotal:	\$6,636.40
Total Tax:	\$333.82
<b>Invoice Total:</b>	<b>\$6,970.22</b>

Payment Method:  
Charge

Payment Terms:  
Net 15th of month

Due Date:  
03/15/2025

1XKWP40X67J930794

Chassis: 930794 / W900 CONVENTIONAL Build Date: 09/22/06 Plant: Chillicothe

MODEL: W903B2

2007 KENWORTH

Please Provide Proof Of Purchase For Returns. A Minimum Restocking Charge of 15% May Be Assessed At Our Discretion. No Return On Electrical Components or Special Ordered Parts.  
Cores Not Drained and Cleaned Will Be Subject To A Cleaning Fee. Cores Must Be Returned Within 9 Months of Purchase Date. All Cores Are Subject To Vendor's Core Return Criteria.  
Prices Quoted Are Valid For 30 Days On In Store, In Stock Items Only.

UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

If the balance due isn't paid within Edmonton Kenworth's credit terms, I agree to pay interest at the rate of 2% per month (24% per annum).

SIGNATURE: \_\_\_\_\_

PRINT NAME: \_\_\_\_\_



Edmonton Main: 18020 - 118 Avenue, Edmonton, Alberta, T5S 2G2  
 P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173  
 Edmonton West: 11603 - 181 St. Edmonton, Alberta, T5S 2K5  
 P: 780.483.6666 TF: 800.252.7981 F: 780.484.2173  
 Fort McMurray: 340 MacKenzie Boulevard, Fort McMurray, Alberta, T9H 4C4  
 P: 780.715.3627 TF: 866.715.5111 F: 780.715.3657  
 Grande Prairie: 12020 - 101 Avenue, Grande Prairie, Alberta, T8V 8B1  
 P: 780.539.9991 TF: 888.538.5414 F: 780.539.9902  
 www.stahlpeterbilt.com

**PARTS INVOICE**  
**S1807398**  
**DATE**  
 02-21-25

**Sold To:**

JRF OILFIELD SERVICES LTD  
 JORDAN FINNER  
 BOX 7382  
 EDSON, AB T7E 1V6

**Ship To:**

JRF OILFIELD SERVICES LTD  
 JORDAN FINNER  
 BOX 7382  
 EDSON, AB T7E 1V6

**Tax ID:**

Customer Acct Number	Phone Number	Salesman	Ship Via	Customer Purchase Order				
3782	780 728-5154	TCN	ROCKET PM	36				
Loc	Part #	Description	Ord	Ship	B/O	List	Unit Price	Extension
	CSPN							
P06B03	4955422RXCUM	KIT,EGR VALVE	1	1		3367.52	1998.06	1998.06
P06B03	4955422RXCUM#	CORE	1	1			132.00	132.00
PLEASE SHIP OUT VIA ROCKET - PM RUN								

**POSTED**  
*[Signature]*

ASK ABOUT ORDERING PARTS ONLINE - PETERBILT ONLINE PARTS COUNTER  
 CORES MUST BE RETURNED WITHIN 30 DAYS OF PURCHASE  
 10:56AM PARTS TAX

CUSTOMER  
 GST#: 870331105 RT0001

2200.1

Sub Total	2130.06
Freight	0.00
GST	106.50
Sales tax	0.00
Please Pay	2236.56

**Terms and Conditions**

Purchase Acknowledgment: I, the undersigned owner or representative, acknowledge the indebtedness related to the purchase of parts and materials as detailed above. I confirm that I have the authority to bind the owner.  
 Payment Terms: Payment for a parts purchase is due upon receipt of the part(s) unless charged to customer's account. Payment of account is due in full by the 15<sup>th</sup> day of the month following the statement date. Unpaid balances will be charged interest of 2% per month compounded monthly (26.82% per annum)  
 Garage Keepers' Lien: By signing below you acknowledge and agree that the vehicle described below is subject to a garage keepers' lien in favor of Stahl Peterbilt Inc. for the amount of parts, accessories, materials, and services provided by Stahl Peterbilt Inc., as permitted under the *Garage Keepers' Lien Act* (Alberta), as amended from time to time.  
 Parts Returns: All parts returned must be unused, accompanied with original packaging and the original purchase invoice, and returned within 30 days of the purchase invoice date. There is absolutely no return or exchange on electrical or special order parts. A 20% re-stocking charge will apply on all returned parts.

Picked: \_\_\_\_\_ Checked: \_\_\_\_\_ Shipped: \_\_\_\_\_

Print Name: \_\_\_\_\_ Signature: X \_\_\_\_\_ Date: \_\_\_\_\_



# SHOP REPAIR SHEETS



START DATE: 02/21/2025	HOURS: 18908
UNIT #: 36 - Tridem Tractor	KMS: 718596
MAKE/MODEL: Kenworth W900	NEXT SERVICE: 19000

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
Heater control actuator for truck heater core - Diagnosed coolant leak found coolant actuator was smashed and missing electrical actuator	Artic	*1 heater control actuator *2 9/16" to 1-1/16" hose clamps *1 2ft chunk of 5/8" heater hose
Bunk heater control actuator - diag nosed coolant leak coming from cab bunk, found actuator was cracked and coolant hoses were disconnected, new actuator is ordered coming from kenworth	Edmonton kenworth	*1 heater control actuator
Check engine light - diagnosed CEL, found codes for EGR valve, tested connection and electrical going to valve, determined needed new EGR valve, orderd Peterbilt	Edmonton kenworth	*1 new egr valve + 1 exhaust gasket *1 new exhaust bellow (accordion style) *2 gaskets with clamps *1 larger clamp
Mirror heat switch - tested wires going to switch for light, found switch was NFG, Orderd new switch from kenworth	Edmonton kenworth	
# 4 axle needs tires - kal tire came and replaced 4 tires on rear axle	Kal tire	*4 new drive tires
Axle # 4 P/s torque rod - found bushing were blown out in torque rod, removed and replaced with new	Artic	*1 torque rod
Jake harness - diagnosed stage 3 Jake brake issue, tested #1,2 Jake solenoids found there were good, tested wires going to Jake solenoids, they tested good, found connections going to Jake solenoids were way to loose. removed and replaced with	Kenworth	*1 Jake harness



# Inspection & Maintenance Record



**TRUCK**

Date: 02/23/2025

Unit: 36 - Tridem  
Tractor

Odometer: 718596

Hours: 18908

SCHEDULE

Hours: ✓

Monthly: ✓

Other:

TRUCK	Schedule 2 – Inspected Components
✓	Body & Chassis
✓	Cab Interior & Seat
✓	Windows & Mirrors
✓	Steering Column & Box
✓	Steering Linkage
✓	Windshield Wipers & Washers
✓	Heating & Defrosting Systems
✓	Starting Switch
✓	Lamps & Reflectors
✓	Underbody
✓	Drive Shaft
✓	Mechanical Components
✓	Air Break System
✓	Parking Brake
✓	Brake System
✓	Engine Controls
✓	Suspension
✓	Electrical Components
✓	Tires
✓	Fifth Wheel Coupling Device
	Trailer Hitch, Mounts & Connecting Device
LUBRICANTS	
	Change Engine Oil & Filter
	Change Fuel Filter
	Change Differential Filter
	Change Coolant Filter
✓	Unit Greased
✓	Fluids Topped Up
✓	<b>RECHECK OIL LEVELS</b>
✓	<b>CHECK FOR ACTIVE LEAKS OIL/GREASE</b>
Additional Comments	

Work Completed By: Landen LaPierre

Next Service Due: 19000

Signature:



# SHOP REPAIR SHEETS



START DATE: 02/19/2025      HOURS: 18896

UNIT #: 36 - Tridem Tractor      KMS: 718270

MAKE/MODEL: Kenworth w900      NEXT SERVICE: 19000

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? No

If NO, Deficiency requiring attention:  
Light issues



Description of work done	Vendor	Part #
Found trailer cord was full of green corrosion, no light power to trailer, replaced 7-wire cord lights all work	JRF	7-wire cord

END DATE: 02/19/2025



Mechanic: Scott Belcourt

SIGNATURE:



# SHOP REPAIR SHEETS



START DATE: 02/18/2025	HOURS: 18886
UNIT #: 36 - Tridem Tractor	KMS: 718056
MAKE/MODEL: Kenworth	NEXT SERVICE: 19000

WAS THERE A DEFICENTCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
Found fifth wheel slide cylinder to be bypassing and leaking out the end	Artic	Fifth wheel cylinder

END DATE: 02/18/2025

Mechanic: Connor Vanderveen

SIGNATURE:



# Monthly Inspections

Please complete and hand-in on the first of every month

Unit Number: 36 - Tridem Tractor  
Mileage: 718596  
Hours: 18906

Date: 02/21/2025  
Next service Due: 19000

Registration?: Yes  
Insurance?: Yes  
Drivers Binder? Yes  
Has it been recently updated?: Yes  
Safety Fitness Certificate  
(needed only for GVW of 11,794)? Yes  
Company Emergency Contact sheet?: Yes  
CVIP Paperwork? Yes  
CVIP DATE: March 2025  
Road Bonds?: Yes  
Unit Number Sticker?: No  
TARE/GVW? Yes  
Compare TARE/GVW to registration:   14400       63500  
  TARE       GVW  
Hydraulic Hose (In good Condition)? Yes  
CSA First Aid Kit?: Yes  
Fire Extinguisher?: Yes  
Fire Extinguisher Certification Due Date?: Jan 2026  
Roadside Flares? Yes  
PPE? Yes  
Flashlight?: Yes  
Ticket Book? Yes  
Functioning 2-way radio?: Yes  
Tool Kit?: Yes  
Tire Chains? Yes  
Spill Kit?: Yes

Alexis Lapierre  
Inspector/Driver Name

Inspector Signature

Please Note:  
Both KMS & HRS/Next service date are required  
New Update: CSA First Aid Kits



WORK ORDER REPAIR SHEET



START DATE:

11/29/24

UNIT#/MAKE/MODEL

36 kW 7800

HOURS

18842

KMS

716507

CORRECTIVE ACTIONS/COMMENTS:

Repaired #2LH Brake pot, #4LH Dust Shield  
#4RH Torque Rod

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
air leak	Brake pot	JRF	Scott B	11/29/24
Axle	Dust cover Bolts	JRF	Scott B	11/29/24
Suspension	Torque Rod	Kenworth	Scott B	11/29/24

END DATE:

11/29/24

NEXT SERVICE DUE:

19000 HRS

HOURS/KMS

18842/716507

Supervisor Sign Off: \_\_\_\_\_



# WORK ORDER REPAIR SHEET



START DATE:

11/28/24

UNIT#/MAKE/MODEL

36 kW T800

HOURS

18839

KMS

716489

CORRECTIVE ACTIONS/COMMENTS:

Replaced ~~#2 Drive Ax~~ #2 RH Drive Axle  
hub, put Torque Tag In cab

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
Axle	hub	axle	Scott B	11/29/24
Axle	gearbox	DRF	Scott B	11/29/24
Axle	oil	DRF	Scott B	11/29/24

END DATE:

11/28/24

NEXT SERVICE DUE:

19000 HRS

HOURS/KMS

18839/716489

Supervisor Sign Off: \_\_\_\_\_



WORK ORDER REPAIR SHEET



START DATE:

11/27/24

UNIT#/MAKE/MODEL

36 hv/7800

HOURS

18839

KMS

716489

CORRECTIVE ACTIONS/COMMENTS:

Repaired #1 Drive Axle Suspension

Torqued everything to spec

put Torque Tag In Truck

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

Suspension

bedsichan polmax <sup>h/t</sup>

axle

Scott B

11/28/24

END DATE:

11/28/24

NEXT SERVICE DUE:

19000 HRS

HOURS/KMS

18839/716489

Supervisor Sign Off:



# SHOP REPAIR SHEET



START DATE:

Oct 29/24

UNIT#/MAKE/MODEL

36

HOURS

18 594

KMS

706 705

CORRECTIVE ACTIONS/COMMENTS:

Turbo waste gate Air accumulator was leaking removed and replaced  
Air accumulator

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

Turbo waste gate  
Air accumulator

Red con

Connor U

Oct 29/24

END DATE:

Oct 29/24

NEXT SERVICE DUE:

HRS

HOURS/KMS

Supervisor Sign Off:

Connor Underveen



Deficiency Reports



Report Date Oct 1

Unit Number 36

Make KW

KMS 700690

Model T8W

Hours 18425

Next Service Now 18700

Deficiency: ~~Check Engine and ABS lights~~

~~splitter shifts slow, doesn't engage fully~~

~~New tires on Drives~~

~~Thermostats stuck open runs cold.~~

~~winch does steer, winch line twisted, no high speed~~

~~No hoist cables~~

~~Entire plate for assembly loose~~

~~Water control face plate falling off~~

~~Bad rattle in/around steering column~~

Person Reporting (please print): Spencer

Corrective Action: level computer up fuel oil pressure sensor bad

Replaced it and cleared codes, ABS will set done @ CMP.

Blow shifter lines out, open water control valves

needs new water control face will order one monday

Tighten steering column cover plate, need new winch

Speed Switch order one monday, Fixed Lights

Completion Date: 10/06/24

Completed By: Scott B

KMS 701769

Hours 18463

18700



Deficiency Reports



Report Date Oct 2

Unit Number 36

Make MW

KMS 701769

Model 1800

Hours 18463

Next Service 18700

Deficiency: ~~Broken shock mounts~~  
~~No left tail light on skirt~~  
~~Needs service~~ Done already

Person Reporting(please print): Spencer Wisley

Corrective Action: Fixed side skirt light  
Fixed Broken shock Bolts not the mounts

Completion Date: 10/06/29

KMS 701769

Completed By: Scott B

Hours 18463



# SHOP REPAIR SHEET



START DATE:

10/05/24

UNIT#/MAKE/MODEL

B6 New TRBU

HOURS

18463

KMS

701769

CORRECTIVE ACTIONS/COMMENTS:

CRJ Sheet Repairs

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

Lights

postail

JRF

Scott B

10/06/24

engine

Sensor

JRF

Scott B

10/06/24

Tires

Tires

Hal Tire

Scott B

10/06/24

Shocks

Bolts

JRF

Scott B

10/06/24

END DATE:

10/06/24

HOURS/KMS

18463/701769

NEXT SERVICE DUE:

18700

HRS

Supervisor Sign Off:

\_\_\_\_\_





## Deficiency Reports



Report Date Sept 20 124

Unit Number 36

Make KW

KMS \_\_\_\_\_

Model w900

Hours \_\_\_\_\_

Next Service \_\_\_\_\_

Deficiency: - Needs motor mount bushing, when put into gear can feel tranny and motor pop up.

- lights out on skirt in Rear end.

- Big vibration in unit

Person Reporting (please print): Scott Finner

Corrective Action: - Replaced Both front and Rear motor mounts

- fixed lights out in skirt

- greased unit

- vibration

Completion Date: Sept 21 124

KMS 697, 264

Completed By: hanten lapierre

Hours 18, 335



# SHOP REPAIR SHEET



START DATE:

Sept 20 124

UNIT#/MAKE/MODEL

36

HOURS

18,335

KMS

697,264

CORRECTIVE ACTIONS/COMMENTS:

- motor mounts were replaced
- grease unit and repaired lights
- 
- 
- 
- 
- 

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
motor mounts	x1 set of Front + Rear mounts	Diesel shop		Sept 21
lights in skirt	x1 oval red marker light	JRF		↓
Grease unit	x 2 Tubes grease	JRF		
Vibration	_____	_____		

END DATE:

Sept 21 124

HOURS/KMS

Same

NEXT SERVICE DUE:

18,350 HRS

Supervisor Sign Off:



Inspection & Maintenance Record

TRUCK



Date: \_\_\_\_\_ Unit: \_\_\_\_\_ Odometer: \_\_\_\_\_ Hours: \_\_\_\_\_

SCHEDULE  250 HOURS  MONTHLY  OTHER \_\_\_\_\_

TRUCK	Schedule 2 – Inspected Components	COMMENTS
<input checked="" type="checkbox"/>	Body & Chassis	
<input checked="" type="checkbox"/>	Cab Interior & Seat	
<input checked="" type="checkbox"/>	Windows & Mirrors	
<input checked="" type="checkbox"/>	Steering Column & Box	
<input checked="" type="checkbox"/>	Steering Linkage	
<input checked="" type="checkbox"/>	Windshield Wipers & Washers	
<input checked="" type="checkbox"/>	Heating & Defrosting Systems	
<input checked="" type="checkbox"/>	Starting Switch	
<input checked="" type="checkbox"/>	Lamps & Reflectors	
<input checked="" type="checkbox"/>	Underbody	
<input checked="" type="checkbox"/>	Drive Shaft	
<input checked="" type="checkbox"/>	Mechanical Components	
<input checked="" type="checkbox"/>	Air Brake System	
<input checked="" type="checkbox"/>	Parking Brake	
<input checked="" type="checkbox"/>	Brake System	
<input checked="" type="checkbox"/>	Engine Controls	
<input checked="" type="checkbox"/>	Suspension	
<input checked="" type="checkbox"/>	Electrical Components	
<input checked="" type="checkbox"/>	Tires	
<input checked="" type="checkbox"/>	Fifth Wheel Coupling Device	
<input checked="" type="checkbox"/>	Trailer Hitch, Mount & Connecting Device	
	<b>LUBRICANTS</b>	
<input checked="" type="checkbox"/>	Change Engine Oil & Filter	
<input checked="" type="checkbox"/>	Change Fuel Filter	
<input checked="" type="checkbox"/>	Change Differential Filter	
<input checked="" type="checkbox"/>	Change Coolant Filter	
<input checked="" type="checkbox"/>	Unit Greased	
<input checked="" type="checkbox"/>	Fluids Topped Up	
<input checked="" type="checkbox"/>	<b>RECHECK OIL LEVELS</b>	
<input checked="" type="checkbox"/>	<b>CHECK FOR ACTIVE LEAKS OIL/GREASE</b>	

Work Completed By: harden hansen

Next Service Date: 18,380 HRS

Signature:



Deficiency Reports



Report Date Aug 23/24

Unit Number 36

Make Kenworth

KMS \_\_\_\_\_

Model W900

Hours \_\_\_\_\_

Next Service \_\_\_\_\_

Deficiency: Need service

Person Reporting(please print): Mark Pilon

Corrective Action: completed service

Completion Date: Aug 23/24

KMS 688460

Completed By: harden latic

Hours 18.132



# WORK ORDER REPAIR SHEET



START DATE:

Aug 23/24

UNIT#/MAKE/MODEL

36, Kw 10900

HOURS

18,132

KMS

688,460

CORRECTIVE ACTIONS/COMMENTS:

Completed Service

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

oil change

x1 LF1400000  
x 4L oil

JRF

Aug 23/24

fuel filters

x 2 F.Hrs FS1000  
LF2100

JRF

Aug 23/24

grease

x 3 Tubes  
grease

JRF

Aug 23/24

END DATE:

Aug 23/24

HOURS/KMS

Same

NEXT SERVICE DUE:

18,382 HRS

Supervisor Sign Off:



Inspection & Maintenance Record

TRUCK



Date: Aug 23/24 Unit: 36 Odometer: 658,460 Hours: 18,832

SCHEDULE [ ] 250 HOURS [ ] MONTHLY [ ] OTHER

Table with 3 columns: TRUCK, Schedule 2 - Inspected Components, and COMMENTS. Rows include Body & Chassis, Cab Interior & Seat, Windows & Mirrors, Steering Column & Box, Steering Linkage, Windshield Wipers & Washers, Heating & Defrosting Systems, Starting Switch, Lamps & Reflectors, Underbody, Drive Shaft, Mechanical Components, Air Brake System, Parking Brake, Brake System, Engine Controls, Suspension, Electrical Components, Tires (comment: AXE # 3 getting Bald), Fifth Wheel Coupling Device, Trailer Hitch, Mount & Connecting Device, LUBRICANTS, Change Engine Oil & Filter, Change Fuel Filter, Change Differential Filter, Change Coolant Filter, Unit Greased, Fluids Topped Up, RECHECK OIL LEVELS, CHECK FOR ACTIVE LEAKS OIL/GREASE.

Work Completed By: [Signature]

Next Service Date: 18,382 HRS

Signature: [Signature]



# WORK ORDER REPAIR SHEET



START DATE:

Aug 21/23

UNIT#/MAKE/MODEL

36

HOURS

KMS

CORRECTIVE ACTIONS/COMMENTS:

- No Head ache lights Found broken wiring in the head ache it was the brown wire that broke.

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

~~36~~ Electricall cometers

JRF

Conner U

Aug 21/23

END DATE:

NEXT SERVICE DUE:

HRS

HOURS/KMS

Supervisor Sign Off:

Conner U



# WORK ORDER REPAIR SHEET



START DATE:

07/30/24

UNIT#/MAKE/MODEL

1036 Ken Truck

HOURS

17899

KMS

678002

CORRECTIVE ACTIONS/COMMENTS:

u joint after steady bearing  
NFG

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
Drive shaft	u joint	Napa	Scott B	07/30/24

END DATE:

07/30/24

HOURS/KMS

17899/678002

NEXT SERVICE DUE:

\_\_\_\_ HRS

Supervisor Sign Off: \_\_\_\_\_



Deficiency Reports



Report Date 24/7/24

Unit Number 36

Make Kenworth

KMS \_\_\_\_\_

Model W900

Hours \_\_\_\_\_

Next Service \_\_\_\_\_

Deficiency: Needs service, is over due. Blower motor doesn't work.

↓  
check air filters + fuel filters

AC compressor failed

Person Reporting (please print): Mark Pilon

Corrective Action: Replaced Blower motor fuse,

DD Service plus air filters

Replaced AC compressor, Re-charged

Completion Date: 07/24/24

KMS 677278

Completed By: Scott B

Hours 17870



# WORK ORDER REPAIR SHEET



START DATE:

07/25/24

UNIT#/MAKE/MODEL

36 hr w900

HOURS

17870

KMS

677278

CORRECTIVE ACTIONS/COMMENTS:

Did service, RSR ac compressor

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

Service

oil + filters

JRF

Scott B

07/25/24

ac

Compressor

aslec

Scott B

07/25/24

END DATE:

07/25/24

HOURS/KMS

17870/677278

NEXT SERVICE DUE:

18010 HRS

Supervisor Sign Off:

\_\_\_\_\_



Inspection & Maintenance Record



TRUCK

Date: 07/25/24 Unit: 36 Odometer: 677278 Hours: 17870

SCHEDULE [X] 250 HOURS [ ] MONTHLY [ ] OTHER

Table with 3 columns: TRUCK, Schedule 2 - Inspected Components, COMMENTS. Rows include: Body & Chassis, Cab Interior & Seat, Windows & Mirrors, Steering Column & Box, Steering Linkage, Windshield Wipers & Washers, Heating & Defrosting Systems, Starting Switch, Lamps & Reflectors, Underbody, Drive Shaft, Mechanical Components, Air Brake System, Parking Brake, Brake System, Engine Controls, Suspension, Electrical Components, Tires, Fifth Wheel Coupling Device, Trailer Hitch, Mount & Connecting Device, LUBRICANTS, Change Engine Oil & Filter, Change Fuel Filter, Change Differential Filter, Change Coolant Filter, Unit Greased, Fluids Topped Up, RECHECK OIL LEVELS, CHECK FOR ACTIVE LEAKS OIL/GREASE.

Work Completed By: Scott B

Next Service Date: 07/25/24

Signature: [Handwritten Signature]



# WORK ORDER REPAIR SHEET



START DATE:

UNIT#/MAKE/MODEL

HOURS

KMS

CORRECTIVE ACTIONS/COMMENTS:

Replace #3 LH hub + Berds + wheel Seal

Torque wheel to Spec per

Torque Tag In unit

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

hub	Axle hub	artie	Scott B	07/23/24
o.i	75-90	JRF	Scott B	07/23/24
nuts	axle nuts	JRF	Scott B	07/23/24
AXLE	gas stud	JRF	Scott B	07/23/24

END DATE:

HOURS/KMS

NEXT SERVICE DUE:

Supervisor Sign Off: \_\_\_\_\_



# WORK ORDER REPAIR SHEET



START DATE:

07/17/24

UNIT#/MAKE/MODEL

36 kW 7500

HOURS

1772

KMS

673201

CORRECTIVE ACTIONS/COMMENTS:

fixed blower motor issues  
and patched left reel supply  
ordered parts

no parts used  
for blower motor  
fix

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date

END DATE:

07/17/24

HOURS/KMS

1772

NEXT SERVICE DUE:

17846 HRS

Supervisor Sign Off: \_\_\_\_\_

1772 / 673201



Deficiency Reports



Report Date 15/7/24

Unit Number 36

Make Kenworth

KMS \_\_\_\_\_

Model W900

Hours \_\_\_\_\_

Next Service \_\_\_\_\_

Deficiency: A/c doesn't work.

Person Reporting (please print): Mark Pilon

Corrective Action: High pressure switch pig tail is  
NFG, shanic order done July 16th

Replaced HP piston/ Tested AC working

Completion Date: 07/16/24

KMS 672937

Completed By: Scott B

Hours 17765



# WORK ORDER REPAIR SHEET



START DATE:

07/16/24

UNIT#/MAKE/MODEL

36 kW T800

HOURS

17765

KMS

672937

CORRECTIVE ACTIONS/COMMENTS:

Repair Hp piston for AC system

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

AC

Hp piston

artie

Scott B

07/16/24

END DATE:

07/16/24

NEXT SERVICE DUE:

HRS

HOURS/KMS

17765/672937

Supervisor Sign Off: \_\_\_\_\_



Deficiency Reports



Report Date May 14/24  
Make KW  
Model W900

Unit Number 36  
KMS 627412  
Hours 17419

Deficiency: A/C compressor not engaging  
Hood Bushing worn + Hinges Worn  
Hood Rubbing A/C condenser

Person Reporting (please print): \_\_\_\_\_

Corrective Action: Replaced A/C condenser and pump  
vac tested, filled refrigerant, tested

Completion Date: \_\_\_\_\_  
Completed By: \_\_\_\_\_

KMS \_\_\_\_\_  
Hours \_\_\_\_\_



# WORK ORDER REPAIR SHEET



START DATE:

June 10/24

UNIT#/MAKE/MODEL

36

HOURS

17524

KMS

662245

CORRECTIVE ACTIONS/COMMENTS:

-Marker light out on walking deck

-Replaced marker light

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
	Marker light	JRF	Conner U	June 10/24

END DATE:

June 10/24

HOURS/KMS

NEXT SERVICE DUE:

HRS

Supervisor Sign Off:

Conner Vederoven



Deficiency Reports



Report Date 05/17/24

Unit Number 36

Make HW

KMS 657412

Model T800

Hours 17420

Deficiency: \_\_\_\_\_

Head Bushes

Person Reporting (please print): Dustin T

Corrective Action: R&R Head Bushes

Completion Date: 05/17/24

KMS 657412

Completed By: Scott B

Hours 17420



# WORK ORDER REPAIR SHEET



START DATE:

05/17/24

UNIT#/MAKE/MODEL

36/ M/ T800

HOURS

17420

KMS

657412

CORRECTIVE ACTIONS/COMMENTS:

R312 hood Bushes

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

hood Bushes

hood Bushes

aRde

Scott/B

05/17/24

END DATE:

05/17/24

HOURS/KMS

17420/657412

Supervisor Sign Off: \_\_\_\_\_



Deficiency Reports



Report Date April 17/2024

Unit Number 36

Make Kenworth

KMS \_\_\_\_\_

Model \_\_\_\_\_

Hours \_\_\_\_\_

Deficiency: Jetties are weak on 3rd stage - Diesel shop.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Person Reporting (please print): TY

Corrective Action: \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Completion Date: \_\_\_\_\_

KMS \_\_\_\_\_

Completed By: \_\_\_\_\_

Hours \_\_\_\_\_



# Monthly Inspections

Please complete and hand-in on the first of every month

Unit Number: 36  
Mileage: 651905  
Hours: 17276.9

Date: Feb 16  
Next service Due: 17460

Registration?:  YES  NO  
Insurance?:  YES  NO  
Drivers Binder?:  YES  NO  
Has it been recently updated?:  YES  NO  
Safety Fitness Certificate  
(needed only for GVW of 11,794):  YES  NO  
Company Emergency Contact sheet?:  YES  NO  
CVIP Paperwork?  YES  NO  
CVIP DATE: 2003/05  
Road Bonds?:  YES  NO  
Unit Number Sticker?:  YES  NO  
TARE/GVW?  YES  NO  
Compare TARE/GVW to registration: 14400 63500

TARE                      GVW

Hydraulic Hose (In good Condition)?  YES  NO  
CSA First Aid Kit?:  YES  NO AB 2  
Fire Extinguisher?  YES  NO  
Fire Extinguisher Certification Due Date? Jan 2025  
Roadside Flares?  YES  NO  
PPE?  YES  NO  
Flashlight?:  YES  NO  
Ticket Book?  YES  NO  
Functioning 2-way radio?:  YES  NO  
Tool Kit?:  YES  NO  
Tire Chains?  YES  NO  
Spill Kit?:  YES  NO

*Handwritten notes:*  
1/16/25  
1/16/25

Alexis LaPiere  
Inspector/Driver Name

[Signature]  
Inspector Signature

Please Note:  
Both KMS & HRS/Next service date are required  
New Update: CSA First Aid Kits



Deficiency Reports



Report Date April 12<sup>th</sup> / 24

Unit Number 36

Make KW

KMS 657020

Model W900

Hours 17399

Deficiency: Drivers side Exhaust Stack ELBow Rusted  
Out. Hole in ELBow.  
Drivers Seat tilt Back Broken.

Person Reporting(please print): John Roberts

Corrective Action: Changed elbow and changed flex pipe underneath, Got seat  
to work

Completion Date: April 16

KMS \_\_\_\_\_

Completed By: Ryan

Hours \_\_\_\_\_



# Monthly Inspections

Please complete and hand-in on the first of every month

Unit Number: 36  
Mileage: 656390  
Hours: 17380.4

Date: Mar 25, 2024  
Next service Due: 17466 hrs

Registration?:  YES  NO  
Insurance?:  YES  NO  
Drivers Binder?:  YES  NO  
Has it been recently updated?:  YES  NO  
Safety Fitness Certificate  
(needed only for GVW of 11,794)?:  YES  NO  
Company Emergency Contact sheet?:  YES  NO  
CVIP Paperwork?  YES  NO  
CVIP DATE: 2023/05  
Road Bonds?:  YES  NO  
Unit Number Sticker?:  YES  NO  
TARE/GVW?  YES  NO  
Compare TARE/GVW to registration: 14400 63500  
TARE GVW

Hydraulic Hose (In good Condition)?  YES  NO  
CSA First Aid Kit?:  YES  NO  
Fire Extinguisher?:  YES  NO  
Fire Extinguisher Certification Due Date?: Jan 2025  
Roadside Flares?  YES  NO  
PPE?  YES  NO  
Flashlight?:  YES  NO  
Ticket Book?  YES  NO  
Functioning 2-way radio?:  YES  NO  
Tool Kit?:  YES  NO  
Tire Chains?  YES  NO  
Spill Kit?:  YES  NO

Alexis LaPierre  
Inspector/Driver Name

Inspector Signature

Please Note:  
Both KMS & HRS/Next service date are required  
New Update: CSA First Aid Kits

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue

Edmonton, AB

T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:  
Kenworth Leduc  
8202 - 42 Street  
Leduc Alberta T9E 8M6  
Phone: 780-612-9855

Invoice: 06AP272284  
Date / Time: 2/22/2024 12:08:48PM  
Parts Order: 272284  
Customer: [REDACTED]  
Branch: Leduc  
Invoice Total: \$6,058.87  
\*\*\* Charge \*\*\*

Page 1 of 1

Bill To: JRF OILFIELD SERVICES LTD.

PO BOX 7382

EDSON, AB T7E 1V6

Ship To: JRF OILFIELD SERVICES LTD.

PO BOX 7382

EDSON, AB T7E 1V6

Office Phone: (780) 728-5154

Shop Phone: (780) 728-5154

Email: admin@jrfoilfield.ca

Customer P/O: 36

*ak*

Inside Slmn: jshaw

Delivery Method: ROCKET EXPRESS

Supplier	Part / Misc	Description / Ref Number	U/M	Quantity	Price	Ext Price
P0100	2882571CUM	SHAFT LEVER ROCKER	EA	1	\$373.46	\$373.46
					Bin Location: R017 F	
P0100	2882570CUM	SHAFT LEVER ROCKER	EA	1	\$372.19	\$372.19
					Bin Location: R017 E	
P0100	4393087CUM	LEVER, ENGINE BRAKE	EA	2	\$837.45	\$1,674.90
					Bin Location: R019 F	
P0100	4393087CUM	LEVER, ENGINE BRAKE	EA	4	\$837.45	\$3,349.80
					Bin Location: R019 F	

Customer Tax ID: 801394149RT0001

GST/HST Number:

Detail Tax Info:

GST REGISTRATION NUMBER: R101577278

\$288.52

Total: \$288.52

Invoice Subtotal:	\$5,770.35
Total Tax:	\$288.52
<b>Invoice Total:</b>	<b>\$6,058.87</b>

Payment Method:

Charge

Payment Terms:

Net 15th of month

Due Date:

03/15/2024

Please Provide Proof Of Purchase For Returns. A Minimum Restocking Charge of 15% May Be Assessed At Our Discretion. No Return On Electrical Components or Special Ordered Parts.  
Cores Not Drained and Cleaned Will Be Subject To A Cleaning Fee. Cores Must Be Returned Within 9 Months of Purchase Date. All Cores Are Subject To Vendor's Core Return Criteria.  
Prices Quoted Are Valid For 30 Days On In Store, In Stock Items Only.

UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

If the balance due isn't paid within Edmonton Kenworth's credit terms, I agree to pay interest at the rate of 2% per month (24% per annum).

SIGNATURE: \_\_\_\_\_

PRINT NAME: \_\_\_\_\_



# Monthly Inspections

Please complete and hand-in on the first of every month

Unit Number: 36  
Mileage: 650015  
Hours: 17233.4

Date: Feb 3 2024  
Next service Due: 17,466 hrs

Registration?: YES NO  
Insurance?: YES NO  
Drivers Binder? YES NO  
Has it been recently updated?: YES NO  
Safety Fitness Certificate  
(needed only for GVW of 11,794)? YES NO  
Company Emergency Contact sheet?: YES NO  
CVIP Paperwork? YES NO  
CVIP DATE: 2023/05/12  
Road Bonds?: YES NO  
Unit Number Sticker?: YES NO  
TARE/GVW? YES NO  
Compare TARE/GVW to registration: 14400 63500  
TARE GVW

Hydraulic Hose (In good Condition)? YES NO  
CSA First Aid Kit?: YES NO  
Fire Extinguisher?: YES NO  
Fire Extinguisher Certification Due Date?: Jan 2025  
Roadside Flares? YES NO  
PPE? YES NO  
Flashlight?: YES NO  
Ticket Book? YES NO  
Functioning 2-way radio?: YES NO  
Tool Kit?: YES NO  
Tire Chains? YES NO  
Spill Kit?: YES NO

Inspector/Driver Name

Inspector Signature

Please Note:  
Both KMS & HRS/Next service date are required  
New Update: CSA First Aid Kits



# Shop Repair/Work Order



Date: Feb 4/24  
 Unit Number: 36  
 Make/Model: Kenworth

Kilometers: 650015  
 Hours: 17233

Work Order	Parts	Vendors
Front clearance fault - Electrical repair		
Wipers Intermittent Fault - Park Switch Fuse replaced		
oil cooler leaking - oil cooler Gasket replaced		
Missing dust covers - Replaced 3x dust covers		
Park Brake Pressure switch Fault - Replaced P.B.P.S.		
Rear Suspension loose/worn - Replaced Bushing and T-rod		
Axle 3 L/H Axle leaking - Replaced Gasket & Broken stud		
Axle 3 output leaking - Replaced Seal & U-joint		
Rear tail light Fault - Repaired wiring		
Trans oil leak - silicone count shaft cover		
Exhaust leaks - Replaced Exhaust clamps		

### Corrective Action Taken:

- Axle 2 Pinion seal leaking - Removed and sealed
- Axle 2 T-rod worn - Replaced Torque rod
- Fan belt cracked & frayed - Replaced
- Axle 4 R/H Brake Drum cracked - Replaced Drum
- Axle 4 R/H Slack adjuster stripped - Replaced slack
- Set Brakes, Torque wheels 500ft-lbs
- Service chassis & Grease



Deficiency Reports



Report Date Jan 26/24

Unit Number 36

Make Kenworth

KMS \_\_\_\_\_

Model W900

Hours \_\_\_\_\_

Deficiency:

- left front signal clearance

- Wipers only work on full

- oil cooler leaking coolant

- Starter

- Dust Shields

- Park Indicator Not coming on when Brakes on.

- Dingy when Door open and lights on when Daytime Switch

- Suspension caps moving on Left Rear and Right front

- Alignment.

- Right Middle Axle Contact.

- Clearance lights on Rear of truck.

Person Reporting (please print): Fraser Suburban

Corrective Action: \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Completion Date: \_\_\_\_\_

KMS \_\_\_\_\_

Completed By: \_\_\_\_\_

Hours \_\_\_\_\_



Deficiency Reports



Report Date Jan 16 / 24

Unit Number \_\_\_\_\_

Make Kenworth

KMS \_\_\_\_\_

Model W400

Hours \_\_\_\_\_

Deficiency: \_\_\_\_\_

- Dots covers  
- 5th wheel slide cylinder Bypassed and wont  
open Dots to slide.

Person Reporting(please print): Loetan Sabourin

Corrective Action: \_\_\_\_\_

Completion Date: \_\_\_\_\_

KMS \_\_\_\_\_

Completed By: \_\_\_\_\_

Hours \_\_\_\_\_



Deficiency Reports



Report Date Jan 10 / 2d  
Make Kenworth  
Model w900

Unit Number \_\_\_\_\_  
KMS \_\_\_\_\_  
Hours \_\_\_\_\_

- Deficiency: \_\_\_\_\_  
- Change Shocks - Brake Disc  
- Dust covers  
- Alignment  
- Change Mod Flaps on Steps  
- 5th wheel slide Airline.

Person Reporting (please print): Franken Schwin

Corrective Action: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Completion Date: \_\_\_\_\_  
Completed By: \_\_\_\_\_

KMS \_\_\_\_\_  
Hours \_\_\_\_\_



Inspection & Maintenance Record  
TRUCK



Date: 01/30/24 Unit: 36 Odometer: 649074 Hours: 17216

SCHEDULE  250 HOURS  MONTHLY  OTHER \_\_\_\_\_

TRUCK	Schedule 2 – Inspected Components	COMMENTS
/	Body & Chassis	
/	Cab Interior & Seat	
/	Windows & Mirrors	
/	Steering Column & Box	
/	Steering Linkage	
/	Windshield Wipers & Washers	
/	Heating & Defrosting Systems	
/	Starting Switch	
/	Lamps & Reflectors	
/	Underbody	
/	Drive Shaft	
/	Mechanical Components	
/	Air Brake System	
/	Parking Brake	
/	Brake System	
/	Engine Controls	
/	Suspension	
/	Electrical Components	
/	Tires	
/	Fifth Wheel Coupling Device	
/	Trailer Hitch, Mount & Connecting Device	
/	<b>LUBRICANTS</b>	
/	Change Engine Oil & Filter	
/	Change Fuel Filter	
/	Change Differential Filter	
/	Change Coolant Filter	
/	Unit Greased	
/	Fluids Topped Up	
/	<b>RECHECK OIL LEVELS</b>	
/	<b>CHECK FOR ACTIVE LEAKS OIL/GREASE</b>	

Work Completed By: Scott B. Ryan

Next Service Date: 250 h

Signature: [Signature]



# Shop Repair/Work Order



Date: ~~01/29/24~~ 01/30/24  
Unit Number: 36  
Make/Model: Kenworth / T800  
Kilometers: 649074  
Hours: 12216

Scott B  
Ry/n.

Work Order	Parts	Vendors
Service	Filters / oil	JRF / Napa
Light	Marker Light	JRF

**Corrective Action Taken:**

Oil Service, Fixed marker light on Truck

---

---

---

---

---

---

---

---

---

---



# Shop Repair/Work Order



Date: Jan 24  
 Unit Number: 36  
 Make/Model: \_\_\_\_\_

Kilometers: 646744 Kms  
 Hours: 1777

Work Order	Parts	Vendors
<del>Left</del> Fifth wheel cracked	Fifth wheel	N/A
Air bag down	Air bag	N/A

### Corrective Action Taken:

R/R Right Rear Air bag # 3 Drive Axle  
- R/R Fifth wheel as it was cracked.

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
Conner Anderson



Subcontractor to  
Diamond International  
Trucks Edmonton, AB

53428 RANGE ROAD 170  
YELLOWHEAD COUNTY, AB T7E 3K8  
Tel: 780-723-2333  
Tel: 1-855-574-5557  
Fax: 780-723-2382

CORES MUST BE RETURNED IN ORIGINAL BOX WITHIN 60 DAYS OR NO CORE CREDIT WILL BE ISSUED.  
AN EXPRESS GARAGEMAN'S LIEN IS ACKNOWLEDGED

DATE ENTERED 15 AUG 23	YOUR ORDER NO. 36-JORDAN	DATE SHIPPED 16 AUG 23	INVOICE DATE 16 AUG 23	INVOICE NUMBER 415653
---------------------------	-----------------------------	---------------------------	---------------------------	--------------------------

S  
O  
L  
D  
  
T  
O

ACCOUNT NO. 3097

JRF OILFIELD SERVICES LTD  
JORDAN FINNER  
PO BOX 7382  
EDSON, AB T7E 1V6

S  
H  
I  
P  
  
T  
O

PAGE 1 OF 1

SHIP VIA		SLSM. 157	B/L NO.	TERMS A/R	F.O.B. POINT EDSON, AB			
QTY	SHIP	B.O.	PART NO.	DESCRIPTION	LIST	NET	AMOUNT	
1	1	0	5658283PX	HEAD, CYLIN	7509.01	6946.38	6,946.38	
			CORE DEPOSIT			171.25	171.25	
			FREIGHT	125.00				
						PARTS	7,117.63	
						SUBLET		
						FREIGHT	125.00	
						GST	362.13	
PRINT						CUSTOMER'S SIGNATURE X	<b>TOTAL</b>	<b>\$7,604.76</b>

POSTED  
OK

GST # 89227 9696



gcldiesel.com

GCL Diesel Injection Service  
 15842-112th Avenue  
 Edmonton, Alberta, T5M 2W1  
 Phone: (780) 453-6786 Fax: (780) 447-5854  
 E-Mail:invoicing@gcldiesel.com

**INVOICE**

**827339**

Date 20-Sep-23  
 PO # UNIT 36

<b>Sold To</b> <b>JRF OILFIELD SERVICES LTD.</b> *EMAIL INVOICE AND CUST WILL PAY ONLINE BOX 7382 EDSON ALBERTA T7E1V6 (780) 728-5154	<b>Ship To</b> <b>JRF OILFIELD SERVICES LTD.</b> BOX 7382 EDSON ALBERTA T7E1V6 <b>Ship Via - ROCKET EXPRESS</b> <b>Ship Phone - (780) 429-0374</b>
--	---

Qty Ordered	Qty Backorder	Qty Shipped	Part Number and Description		Unit Price	Extended Price	
5	0	5	4088665R	ISX CUMMINS INJECTOR	\$717.45	\$3,587.25	
5	0	5	4088665R CORE	CORE CHARGE	\$250.00	\$1,250.00	
Sub-Total :						\$4,837.25	
Freight :						\$0.00	
HST :						\$0.00	
GST :						\$241.86	
<b>Other :</b>						<b>Total</b>	<b>\$5,079.11</b>

**Thank you for your business.**

GST/HST Registration Number: 10196-8246 RT 0001:

<b>Comments</b> THANKS	<b>Payment Terms</b> Cash Sale Payment Due  Please make remittance payable to GCL Diesel Injection Service
---------------------------	--

I HEREBY ACKNOWLEDGE MY INDEBTEDNESS OF THE TOTAL AMOUNT AS SHOWN ON THIS INVOICE AND ANY INTEREST CHARGES INCURRED. SEE RETURN INSTRUCTIONS BELOW PRIOR TO RETURNING ANY PRODUCT OR CORE. NO PARTS MAY BE RETURNED WITHOUT PRIOR AUTHORIZATION. PARTS RETURNS ARE SUBJECT TO A MINIMUM 15% RESTOCKING CHARGE. THIS PURCHASE ORDER AND INVOICE INCLUDES THE WARRANTIES AND THE EXCLUSIONS STATED BELOW. PURCHASER RESPONSIBLE FOR ALL LOCAL SALES TAX.

Ship/Pickup Date: \_\_\_\_\_ Waybill / Reference: \_\_\_\_\_

**Warranty Returns**

Before returning defective parts a RWA (Return Warranty Authorization) submission must be completed. The link to complete this process and obtain your RWA number can be found at: <https://gcldiesel.com/warranty>

**Core Returns**

Before returning cores a RCA (Return Core Authorization) submission must be completed. The link to complete this process and obtain your RCA number can be found at: <https://gcldiesel.com/core>

**Product Return**

Before returning any products purchased from GCL Diesel an RGA (Return Goods Authorization) submission must be completed. The link to complete this process and obtain your RGA number can be found at: <https://gcldiesel.com/return>

**Warranty and Exclusions: Warranties available through GCL Diesel can be reviewed at the following link on our website <https://gcldiesel.com/support/warranty>**

- |   |  |  |
|---|--|--|
| <p>1 GCL Diesel warrants its products to be free from defects in material and workmanship under normal use and service for one (1) year with unlimited mileage with the exception of the following: a. electrical components: the lesser of one (1) year or 20,000 km. b. certified refurbished: sixty (60) days exchange only.</p> <p>2 This warranty shall be limited to repairing or replacing, at our option, the part or parts claimed to be defective within one (1) year after the date of purchase. However, if circumstances preclude the remedying of warranted defects by repair or replacement, GCL Diesel shall, upon return of products, credit the customer part of the purchase price heretofore paid GCL Diesel.</p> | <p>3 Inspection shall, at the option of GCL Diesel, be performed at its plant in Edmonton, Alberta, and all related freight charges shall be paid by the customer</p> <p>4 If, during the warranty period, a defect in other material or workmanship of one of GCL Diesel's products is found to be conclusively defective, GCL Diesel will grant an adjustment. Nothing herein shall be construed to require GCL Diesel to grant such adjustment.</p> | <p>5 NO OTHER WARRANTY, WHETHER EXPRESSED OR IMPLIED (including any warranty of merchantability or fitness for a particular purpose), SHALL EXIST IN CONNECTION WITH THE PURCHASE OR USE OF SUCH PRODUCTS.</p> <p>6 GCL Diesel shall under no circumstances be liable for any incidental or consequential damage.</p> <p>7 NO EMPLOYEE OR REPRESENTATIVE IS AUTHORIZED TO CHANGE THIS WARRANTY IN ANY WAY OR GRANT ANY OTHER WARRANTY.</p> |
|---|--|--|