

D26-3
MAY



SHOP REPAIR SHEETS



START DATE: 03/26/2026	HOURS:
UNIT #: 68 - Tandem Tractor	KMS:
MAKE/MODEL: Kenworth	NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:
Fuel issue

Description of work done	Vendor	Part #
Fuel issue - diagnosed fuel issue as it wasn't equalizing, removed and replaced equalizer valve and good to go	Jrf	*1 equalizer Valve

END DATE: 03/26/2026

Notes:
Service call to RR120

Mechanic:
Landen LaPierre

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 03/27/2026

HOURS: 2182

UNIT #: 68 - Tandem Tractor

KMS: 107432

MAKE/MODEL: Kenworth

NEXT SERVICE: 2332

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Starter
Axle seal

Description of work done	Vendor	Part #
Changed starter Put new axle gasket on	JRF	

END DATE: 03/27/2026

Notes:

Mechanic:

Keegan Veldhouse

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 03/27/2026

HOURS: 2182

UNIT #: 68 - Tandem Tractor

KMS: 107432

MAKE/MODEL: Kenworth

NEXT SERVICE: 2432

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Fuel tank had hole in it

Description of work done	Vendor	Part #
Took fuel tank out got welded put fuel tank back in	JRF	

END DATE: 03/27/2026

Notes:

Mechanic:

Keegan Veldhouse

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 03/17/2026

HOURS:

UNIT #: 68 - Tandem Tractor

KMS:

MAKE/MODEL: Kenworth

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Brake pot is stripped

Description of work done	Vendor	Part #
Remove and replace brake pot on A2L	-	

END DATE: 03/16/2026

Notes:

Mechanic:

Raphie Laurente

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 03/12/2026

HOURS: 2081

UNIT #: 68 - Tandem Tractor

KMS: 106128

MAKE/MODEL: Kenworth

NEXT SERVICE: 2234

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Diagnosis transmission grinding

Description of work done	Vendor	Part #
Drained transmission oil removed PTO found gear teeth in PTO Replaced transmission reused clutch installed with new clutch brake Replaced transmission oil cooler and replaced PTO set clutch filled with oil provided with transmission Starter shorting out blew main ecm fuse replaced fuse Headlights not working replaced relay repaired broken ground wire	JRF Artic truck	

END DATE: 03/12/2026

Notes:

Mechanic:

Ryan Macinnis

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 02/26/2026

HOURS: 2107

UNIT #: 68 - Tandem Tractor

KMS: 107121

MAKE/MODEL: Kenworth

NEXT SERVICE: 2207

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Worn out bushings
Block heater not working

Description of work done	Vendor	Part #
Replaced front engine mount bushings Replaced block heater	Jrf	

END DATE: 02/26/2026

Notes:

Mechanic:
Ryan Macinnis

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 02/19/2026

HOURS: 2107

UNIT #: 68 - Tandem Tractor

KMS: 107121

MAKE/MODEL: Ken worth

NEXT SERVICE: 2357

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Oil change
Fifth wheel cross member broke

Description of work done	Vendor	Part #
Changed oil Welded fifth wheel cross members	JRF	

END DATE: 02/19/2026

Notes:

Mechanic:
Keegan Veldhouse

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 02/24/2026

HOURS: 2107

UNIT #: 68 - Tandem Tractor

KMS: 107121

MAKE/MODEL: Kenworth

NEXT SERVICE: 2257

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

- No dash lights
- No marker lights
- Engine oil leak
- Power steering leak
- Engine not running good sometimes sputtering

Description of work done	Vendor	Part #
Repaired dash and marker lights Replaced power steering pump return fitting was loose and worn out Removed engine oil pump resealed leak on pump and engine block Checked for engine codes did a injector cut out test all passed Replaced fuel filters	Jrf	

END DATE: 02/24/2026

Notes:

Mechanic:

Ryan Macinnis

R

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 01/27/2026	HOURS: 1900
UNIT #: 68 - Tandem Tractor	KMS: 101416
MAKE/MODEL: Kenworth	NEXT SERVICE: 1825

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): **No**

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:
Truck wont start

Description of work done	Vendor	Part #
Charged batteries for about and hour truck still would not start, replaced batteries, truck fired up	JRF	Batteries

END DATE: 01/27/2026

Notes:

Mechanic:
Scott Belcourt

SB

SIGNATURE:



SHOP REPAIR SHEETS




START DATE: 01/29/2026	HOURS:
UNIT #: 68 - Tandem Tractor	KMS:
MAKE/MODEL: Peterbilt	NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:
Air weigh gauge



Description of work done	Vendor	Part #
Air weigh - removed and replaced gauge with new as old one was NFG	Jrf	*1 new air weigh gauge

END DATE: 01/29/2026



Notes:

Mechanic:
Landen LaPierre

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 02/01/2026 HOURS:


UNIT #: 68 - Tandem Tractor KMS:

MAKE/MODEL: Kenworth NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): Yes


If YES, Deficiency Requiring Attention Please Indicate Reported Date:
02/02/26

If NO, Deficiency Requiring Attention:



Description of work done	Vendor	Part #
Remove replace airwiegh air line and replace air line from the truck to the trailer	-	

END DATE: 02/02/2026



Notes:

Mechanic:
Raphie Laurente

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 01/14/2026

HOURS: 1811

UNIT #: 68 - Tandem Tractor

KMS: 100039

MAKE/MODEL: Kenworth

NEXT SERVICE: 1825

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Won't build air

Description of work done	Vendor	Part #
Won't build air past 60psi found air dryer plugged and charge air line leaking replaced air line serviced air dryer cartridge and purge valve replaced and repaired air dryer heater	Artic jrf	10feet 1/2 steel braided line 2 JIC -10 fittings Purge valve air dryer filter heater pig tail

END DATE: 01/14/2026

Notes:

Air compressor getting weak found oil in air system

Mechanic:

Ryan Macinnis

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 12/15/2025

HOURS: 1802

UNIT #: 68 - Tandem Tractor

KMS: 999842

MAKE/MODEL: Peterbilt

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Headlights
Dash lights
Motor misses

Description of work done	Vendor	Part #
Headlights - removed and replaced both lights on the drivers side as they were shorted out causing the relay to continuously flicker	JRF	*1 Low beam headlight *1 high beam headlight
Dash lights - removed and replaced blown fuse and chased wire to see why fuse was blown, all was good	JRF	*15amp fuse

END DATE: 12/15/2025

Notes:

Mechanic:

Landen LaPierre

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 12/05/2025		HOURS:
UNIT #: 68 - Tandem Tractor		KMS:
MAKE/MODEL: Kenworth		NEXT SERVICE:
WAS THERE A DEFICENTCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No		
If YES, Deficiency Requiring Attention Please Indicate Reported Date:		
If NO, Deficiency Requiring Attention: Heater doesn't work		
Description of work done	Vendor	Part #
Diagnose heater blower doesn't work, replace resistor, remove and replace blower fan assembly, and verify repairs	-	
END DATE: 12/05/2025		
Notes:		
Mechanic: Raphie Laurente		

RL

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 10/23/2025	HOURS: 16630
UNIT #: 68 - Tandem Tractor	KMS: 934571
MAKE/MODEL: Kenworth	NEXT SERVICE: 1825

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:
Work light
Clutch

Description of work done	Vendor	Part #
Checked clutch adjustment found to be out of adjustment at 5/8 set to 1/2	JRF	
Replaced work light on c/s headache rack		

END DATE: 10/23/2025

Notes:

Mechanic:
Ryan Macinnis

R

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 11/06/2025	HOURS:
UNIT #: 68 - Tandem Tractor	KMS:
MAKE/MODEL: Kenworth	NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): **Yes**

If YES, Deficiency Requiring Attention Please Indicate Reported Date:
11/04/25

If NO, Deficiency Requiring Attention:

Description of work done	Vendor	Part #
Diagnose and trace wire for shorted cluster. Diagnose fuel gauge.. check all continuity and resistance (checks out fine) still ahve a short in the module,	-	

END DATE: 11/06/2025

Notes:

Mechanic:
Raphie Laurente

RL

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: Aug 10 HOURS: ~~10:00~~

UNIT #: 58 KMS: ~~1000~~

MAKE/MODEL: NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): YES NO

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention: replaced step



Description of work done	Vendor	Part #
replaced front driver lower step		

END DATE: Aug 10



Mechanic: Austin Heeg

SIGNATURE: Austin Heeg



SHOP REPAIR SHEETS



START DATE: 07/12/2025

HOURS:

UNIT #: 68 - Tandem Tractor

KMS:

MAKE/MODEL: Peterbilt

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Fuel leak

Description of work done	Vendor	Part #
Fuel leak - diagnosed fuel leak, found crossover valve was cracked, removed and replaced with new	Artic	*1 fuel crossover valve

END DATE: 07/12/2025

Notes:

Mechanic:

Landen LaPierre

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 06/26/2025	HOURS:
UNIT #: 68 - Tandem Tractor	KMS: -2
MAKE/MODEL: kenworth	NEXT SERVICE: -1

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
install new throttle sensor	kenworth	

END DATE: 06/26/2025

Mechanic: Jason Watson

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 06/23/2025	HOURS: 1311
UNIT #: 68 - Tandem Tractor	KMS: 75562
MAKE/MODEL: kenworth	NEXT SERVICE: 1556

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
-swapped ecm for running rough -installed new throttle position sensor for throttle	kenworth	

END DATE: 06/24/2025

Mechanic: Jason Watson

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 06/23/2025

HOURS: 1310

UNIT #: 68 - Tandem Tractor

KMS: 75519

MAKE/MODEL: Kenworth

NEXT SERVICE: 1556

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done

Vendor

Part #

Remove ECM from 68, remove ECM from -
63 (seized) install oem ecm for 63

END DATE: 06/23/2025

Mechanic: Raphie Laurente

12L

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 06/12/2025

HOURS: 1309

UNIT #: 68 - Tandem Tractor

KMS: 75497

MAKE/MODEL: Kenworth

NEXT SERVICE: 1556

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:

Hoist issues

Description of work done	Vendor	Part #
Replaced hoist valve	Artic	Hoist valve

END DATE: 06/12/2025

Mechanic: Scott Belcourt

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 06/13/2025

HOURS: 1309

UNIT #: 68 - Tandem Tractor

KMS: 15497

MAKE/MODEL: Kenworth

NEXT SERVICE: 1556

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:

Hoist issues

Description of work done	Vendor	Part #
Replaces pto/hoist control	Napa	Valve

END DATE: 06/13/2025

Mechanic: Scott Belcourt

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 06/07/2025 <i>af</i>		HOURS: 1285
UNIT #: 68 - Tandem Tractor		KMS: 74078
MAKE/MODEL: Kenworth		NEXT SERVICE: 1265
WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? Yes		
If NO, Deficiency requiring attention:		
Description of work done	Vendor	Part #
Diagnose an intermittent power loss on the cab and engine, trace locate faulty wire, Rewire power supply.. verify repairs..		
END DATE: 06/07/2025		
Mechanic: Raphie Laurente		

RL

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 06/10/2025

HOURS: 1306

UNIT #: 68 - Tandem Tractor

KMS: 75252

MAKE/MODEL: Kenworth

NEXT SERVICE: 1556

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? No

If NO, Deficiency requiring attention:

Clutch issues and service

Description of work done	Vendor	Part #
Look at tranny/clutch issues, checked drain plug and found no metal on it, oil coming out of drain was clear, removed clutch inspection cover and found nothing everything looks good, trannys and clutch are not that old, checked clutch free play it had none, set clutch free play to spec, and did service	JRF	Oil, filters, grease

END DATE: 06/10/2025

Mechanic: Scott Belcourt

SIGNATURE:



Inspection & Maintenance Record



TRUCK

Date: 06/10/2025

Unit: 68 - Tandem
Tractor

Odometer: 75252

Hours: 1306

SCHEDULE

Hours: ✓

Monthly:

Other:

TRUCK	Schedule 2 – Inspected Components
✓	Body & Chassis
✓	Cab Interior & Seat
✓	Windows & Mirrors
✓	Steering Column & Box
✓	Steering Linkage
✓	Windshield Wipers & Washers
✓	Heating & Defrosting Systems
✓	Starting Switch
✓	Lamps & Reflectors
✓	Underbody
✓	Drive Shaft
✓	Mechanical Components
✓	Air Break System
✓	Parking Brake
✓	Brake System
✓	Engine Controls
✓	Suspension
✓	Electrical Components
✓	Tires
✓	Fifth Wheel Coupling Device
	Trailer Hitch, Mounts & Connecting Device
LUBRICANTS	
✓	Change Engine Oil & Filter
	Change Fuel Filter
	Change Differential Filter
	Change Coolant Filter
✓	Unit Greased
✓	Fluids Topped Up
✓	RECHECK OIL LEVELS
✓	CHECK FOR ACTIVE LEAKS OIL/GREASE
Additional Comments	
Rear brake shoes are getting low cvip is in August, there is enough brake pad left to get to cvip.	

Work Completed By: Scott Belcourt

Next Service Due: 1556

Signature:



SHOP REPAIR SHEETS



START DATE: 03/25/2025	HOURS: 1205
UNIT #: 68 - Tandem Tractor	KMS: 71043
MAKE/MODEL: Kenworth	NEXT SERVICE: 1265

WAS THERE A DEFICENTCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
Left signal issue - diagnosed issue again, found harness for signal stat was melted, removed and replaced harness with new and all tested out good	JRF	*1 harness for signal stat

END DATE: 03/25/2025

Mechanic: Landen LaPierre

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 03/23/2025	HOURS: 1204
UNIT #: 68 - Tandem Tractor	KMS: 11043
MAKE/MODEL: Kenworth	NEXT SERVICE: 1265

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:
Diagnose left signal issue

Description of work done	Vendor	Part #
Left signal - diagnosed dim left signal, found signal stat switch was broken causing a draw internally, removed and replaced with new	Artic	*1 signal stat

END DATE: 03/24/2025

Mechanic: Landen LaPierre

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 03/13/2025	HOURS: 1120
UNIT #: 68 - Tandem Tractor	KMS: 67318
MAKE/MODEL: Kenworth	NEXT SERVICE: 1265

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:
 Right hand high beam flickering
 Trip not working

Description of work done	Vendor	Part #
Found the right hand head lights had a flicker on the low and high found there to be a loose Eletrical pin in the head lights assembly tightened up pin head lights were working good	N/a	N/a

END DATE: 03/13/2025

Mechanic: Connor Vanderveen

Connor

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 03/10/2025	HOURS: 1079
UNIT #: 68 - Tandem Tractor	KMS: 65640
MAKE/MODEL: Kenworth t800	NEXT SERVICE: 1265

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? No

If NO, Deficiency requiring attention:
High beam headlights



Description of work done	Vendor	Part #
Headlights - Orderd led highbeam headlights, removed and replaced with new	Peterbilt	*2 speaker led high beams

END DATE: 03/10/2025



Mechanic: Landen LaPierre

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 02/25/2025	HOURS: 1013
UNIT #: 68 - Tandem Tractor	KMS: 630055
MAKE/MODEL: Kenworth t800 h	NEXT SERVICE: 1265

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **Yes**

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
Service - completed service, changed oil filter and oil	JRF	*1 LF9009 oil filter *41 litres of oil
Turbo oil drain line is loose - tighten drain line on block and to turbo	Jrf	None

END DATE: 02/25/2025

Mechanic: Landen LaPierre

SIGNATURE:



Inspection & Maintenance Record



TRUCK

Date: 02/25/2025

Unit: 68 - Tandem

Odometer: 630055

Hours: 1013

Tractor

SCHEDULE

Hours: ✓

Monthly: ✓

Other:

TRUCK	Schedule 2 – Inspected Components
✓	Body & Chassis
✓	Cab Interior & Seat
✓	Windows & Mirrors
✓	Steering Column & Box
✓	Steering Linkage
✓	Windshield Wipers & Washers
✓	Heating & Defrosting Systems
✓	Starting Switch
✓	Lamps & Reflectors
✓	Underbody
✓	Drive Shaft
✓	Mechanical Components
✓	Air Break System
✓	Parking Brake
✓	Brake System
✓	Engine Controls
✓	Suspension
✓	Electrical Components
✓	Tires
✓	Fifth Wheel Coupling Device
	Trailer Hitch, Mounts & Connecting Device
LUBRICANTS	
✓	Change Engine Oil & Filter
	Change Fuel Filter
	Change Differential Filter
	Change Coolant Filter
✓	Unit Greased
✓	Fluids Topped Up
✓	RECHECK OIL LEVELS
✓	CHECK FOR ACTIVE LEAKS OIL/GREASE
Additional Comments	

Work Completed By: Landen LaPierre

Next Service Due: 1265

Signature:



SHOP REPAIR SHEETS



START DATE: 02/24/2025	HOURS: 1013
UNIT #: 68 - Tandem Tractor	KMS: 630055
MAKE/MODEL: Peterbilt	NEXT SERVICE: 1015

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:

No back up lights

Description of work done	Vendor	Part #
Back up lights - diagnosed lighting issue tested and found back up light switch was NFG	JRF	*1 push pull switch

END DATE: 02/24/2025

Mechanic: Landen LaPierre

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 02/10/2025	HOURS: 943
UNIT #: 68 - Tandem Tractor	KMS: 60266
MAKE/MODEL: Kenworth t800	NEXT SERVICE: 1025

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:
Heat issue and exhaust leak

Description of work done	Vendor	Part #
Got heat working, and fixed exhaust leak	JRF	5" step clamp

END DATE: 02/10/2025

Mechanic: Scott Belcourt

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 01/29/2025	HOURS: 858
UNIT #: 68 - Tandem Tractor	KMS: 572386
MAKE/MODEL: Peterbilt	NEXT SERVICE:

WAS THERE A DEFICENTCY REPORT ASSIGNED WITH THIS TASK? **No**

If NO, Deficiency requiring attention:
- left signal wasn't working

Description of work done	Vendor	Part #
Left signal harness for for signal stat	Jrf	*1 blue connector

END DATE: 01/29/2025

Mechanic: Landen LaPierre

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 01/27/2025	HOURS: 828
UNIT #: 68 - Tandem Tractor	KMS: 559928
MAKE/MODEL: Kenworth t800	NEXT SERVICE: 928

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? No

If NO, Deficiency requiring attention:
Repairs

Description of work done	Vendor	Part #
Fixed lights, signal stat, horn	JRF, napa, artic	Lights, pigtails, signal stat

END DATE: 01/27/2025

Mechanic: Scott Belcourt

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 08/07/2025

HOURS: 1493

UNIT #: 68 - Tandem Tractor

KMS: 84420

MAKE/MODEL: Kenworth

NEXT SERVICE: 1556

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Replace step

Description of work done	Vendor	Part #
Replace step	Not 100% sure had to order it in	

END DATE: 08/07/2025

Notes:

Mechanic:

Austin Hees

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 08/25/2025

HOURS: 1493

UNIT #: 68 - Tandem Tractor

KMS: 84423

MAKE/MODEL: Kenworth

NEXT SERVICE: 1556

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Cvip

Description of work done	Vendor	Part #
Did cvip plus repairs, replaced #3lh brake shoes and drum, replaced u-joint to first diff, grease u-joint, torqued tire put torque tag in truck and red torque tag on wheel	JRF artic	Brake shoes, drums, u-joint

END DATE: 08/25/2025

Notes:

Mechanic:

Scott Belcourt

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 09/24/2025	HOURS:
UNIT #: 68 - Tandem Tractor	KMS:
MAKE/MODEL: Kenworth	NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Diag lack of air flow from blower motor

Description of work done	Vendor	Part #
Made sure blower motor was good/unit sealed found cause to be only blowing on windshield further diag required	Jrf	

END DATE: 09/24/2025

Notes:

Mechanic:
Austin Hees

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 10/11/2025	HOURS: 1584
UNIT #: 68 - Tandem Tractor	KMS: 89138
MAKE/MODEL: Kenworth	NEXT SERVICE: 1825

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Pto and hydraulic not functioning

Description of work done	Vendor	Part #
Replace Melted airline on pto/hydraulic controls, verify repairs and testing hydraulics	-	

END DATE: 10/12/2025

Notes:

Mechanic:
Raphie Laurente

RL 1

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 10/23/2025	HOURS: 16630
UNIT #: 68 - Tandem Tractor	KMS: 934571
MAKE/MODEL: Kenworth	NEXT SERVICE: 1825

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Work light
Clutch

Description of work done	Vendor	Part #
Checked clutch adjustment found to be out of adjustment at 5/8 set to 1/2	JRF	
Replaced work light on c/s headache rack		

END DATE: 10/23/2025

Notes:

Mechanic:
Ryan Macinnis

R

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 09/02/2025

HOURS: 1494

UNIT #: 68 - Tandem Tractor

KMS: 84437

MAKE/MODEL: Kenworth

NEXT SERVICE: 1556

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

No air to the airbags

Description of work done	Vendor	Part #
Diagnose no air on the airbags, remove and - replace positive protection valve, verify repairs and test for air leaks		

END DATE: 09/02/2025

Notes:

Mechanic:

Raphie Laurente

RL

SIGNATURE:



SHOP REPAIR SHEET



START DATE:

10/18/24

UNIT#/MAKE/MODEL

68 New T800

HOURS

539

KMS

27554

CORRECTIVE ACTIONS/COMMENTS:

Diagnosed no takes or high IDLE
found a bad ecm female connector on plus
Replaced connector, every thing is working as know

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
engine	ecm female pin	The Diesel shop	Scott B	10/18/24

END DATE:

10/18/24

NEXT SERVICE DUE:

_____ HRS

HOURS/KMS

531 / 27554

Supervisor Sign Off: _____



SHOP REPAIR SHEET



START DATE:

09/18/24

UNIT#/MAKE/MODEL

68 hr 7800

HOURS

9558

KMS

383680

CORRECTIVE ACTIONS/COMMENTS:

2 way + Antenna

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

antenna

antenna

Tridon

Scott B

09/18/24

Radio

2 way

JRF

Scott B

09/18/24

END DATE:

07/18/24

NEXT SERVICE DUE:

9700 HRS

HOURS/KMS

9558/383682

Supervisor Sign Off: _____



WORK ORDER REPAIR SHEET



START DATE:

09/17/24

UNIT#/MAKE/MODEL

68 RW

HOURS

500

KMS

26713

CORRECTIVE ACTIONS/COMMENTS:

Replaced Fan Belts

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

engine

Fan Belts

Napa

Scott B

07/17/24

END DATE:

07/17/24

HOURS/KMS

500/26713

NEXT SERVICE DUE:

590

HRS

Supervisor Sign Off: _____



WORK ORDER REPAIR SHEET



START DATE:

Aug 26/24

UNIT#/MAKE/MODEL

68

HOURS

197.2

KMS

266,58 Km

CORRECTIVE ACTIONS/COMMENTS:

CUIP

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

Axle # 2 Scams + Bushing	x 2 Scams x 1 Bushing Kit	Artic		Aug 27
Axle # 3 Scams + Bushing	x 2 Scams x 1 Bushing Kit	Artic		Aug 27
Axle # 2, 3 Stacks	x 4 Stack	Artic		Aug 28
Axle # 2 Brake pots	x 2 life seal Brake pots	Artic		Aug 28
Axle # 3 Torque Rod	x 1 Torque Rod	Artic		Aug 28
Axle # 1 D/S low Drag link	x 1 Drag link	Artic		Aug 27
D/S Door cable	x 1 Door cable	Kenworth		Aug 28
D/S Stack Elbow	x 1 Elbow x 2 5" clamps	Kenworth	Scott, B	Aug 26
Axle # 2, 3 wheel seals	x 4 2106 seals	JRF / Artic		Aug 27

END DATE:

Aug 28/24

HOURS/KMS

Same

NEXT SERVICE DUE:

590 HRS

Supervisor Sign Off:



Inspection & Maintenance Record



TRUCK

Date: Aug 28/24 Unit: 68 Odometer: 26 658 Hours: 497

SCHEDULE [] 250 HOURS [] MONTHLY [] OTHER

Table with 3 columns: TRUCK, Schedule 2 - Inspected Components, COMMENTS. Rows include Body & Chassis, Cab Interior & Seat, Windows & Mirrors, Steering Column & Box, Steering Linkage, Windshield Wipers & Washers, Heating & Defrosting Systems, Starting Switch, Lamps & Reflectors, Underbody, Drive Shaft, Mechanical Components, Air Brake System, Parking Brake, Brake System, Engine Controls, Suspension, Electrical Components, Tires, Fifth Wheel Coupling Device, Trailer Hitch, Mount & Connecting Device, LUBRICANTS, Change Engine Oil & Filter, Change Fuel Filter, Change Differential Filter, Change Coolant Filter, Unit Greased, Fluids Topped Up, RECHECK OIL LEVELS, CHECK FOR ACTIVE LEAKS OIL/GREASE.

Work Completed By: Louisa Weber

Next Service Date: 590 HRS

Signature: [Handwritten Signature]



WORK ORDER REPAIR SHEET



START DATE:

June 7/24

UNIT#/MAKE/MODEL

68

HOURS

85 Hours

KMS

3797.4 Kms.

CORRECTIVE ACTIONS/COMMENTS:

-Removed and replaced Air compressor.

-engine oil service.

-greased truck.

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

Air compressor

Artic

Canner U

June 7/24

oil / oil Filter

JRF

U

U

grease truck

JRF

Coolant & jugs

JRF

END DATE:

July 7 24

HOURS/KMS

NEXT SERVICE DUE:

580 HRS HRS

Supervisor Sign Off:

Canner U



WORK ORDER REPAIR SHEET



START DATE:

08/22/24

UNIT#/MAKE/MODEL

68 Hw 7800

HOURS

435

KMS

23961

CORRECTIVE ACTIONS/COMMENTS:

R3R Starter

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
no start	starter	Kenworth	Scott B	08/22/24

END DATE:

08/22/24

HOURS/KMS

435/23961

NEXT SERVICE DUE:

590 HRS

Supervisor Sign Off: _____



WORK ORDER REPAIR SHEET



START DATE:

Aug 21/24

UNIT#/MAKE/MODEL

68

HOURS

435

KMS

23460

CORRECTIVE ACTIONS/COMMENTS:

Removed and Replaced drivers interior door handle as it was broken and couldn't be Fixed had to Replace.

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

RJR

interior door handle

Artic

Connor O

Aug 21/24

END DATE:

Aug 21/24

HOURS/KMS

NEXT SERVICE DUE:

HRS

Supervisor Sign Off:

Connor Vanderweien



WORK ORDER REPAIR SHEET



START DATE:

May 24/24.

UNIT#/MAKE/MODEL

68-

HOURS

1

KMS

144 431 3

CORRECTIVE ACTIONS/COMMENTS:

Removed and Replaced Speedometer

New speedometer is at 0 Kms old ~~was~~ one was at. ~~444~~ 1444 373 Kms when it was Replaced.

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off

Sign Off Date

Removed and Replaced

Speedometer

Ken worth.

Connor U

END DATE:

May 24/24.

NEXT SERVICE DUE:

HRS

HOURS/KMS

Supervisor Sign Off:

Coiff



WORK ORDER REPAIR SHEET



START DATE:

May 7

UNIT#/MAKE/MODEL

66

HOURS

3926

KMS

144436

CORRECTIVE ACTIONS/COMMENTS:

Multiple horizontal lines for corrective actions and comments.

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
	Tach gauge			
	Speed gauge			

END DATE:

HOURS/KMS

Supervisor Sign Off:



Shop Repair/Work Order



Date: 17/03/24
Unit Number: 68
Make/Model: K/W

Kilometers: 13758
Hours: 386

Work Order	Parts	Vendors
King pins		
Tie rods		

Corrective Action Taken:

Replaced Axle #1 King pins
Replaced Tie rod Assembly and set
toe slightly toed in.

Corrective Action Taken:

Unit 68 Feb 19/24

13333429 Kms

36,534 HRS

Repair wiring in RH Side ~~leg~~ Headset/Leg
lights for RH signal

Repaired PS leak and topped up
level

Greased Unit

Top up Engine Oil
check Diff Levels

Needs

DS Strg Dust Cover

2 Dust covers Brake Pots

1800 u-joint 1st Diff Input

Dust cover DS (Lockwell)

1 Speed Sensor on Flywheel

No transmission temp sensor hooked up

Dash Fixed

P.S. Convex Mirror

DS 2nd Axle S-Cam Tube repaired

Service for Eng. ? }
}



Shop Repair/Work Order



Date: Jan 22/24
 Unit Number: 68
 Make/Model: _____

Kilometers: 1273516
 Hours: 35077

Work Order	Parts	Vendors
- poor heat		
* Cabin air filter	Cabin air filter	JRF

Corrective Action Taken:

Found cabin air filter was plugged off full of
dirt creating poor heat Replaced cabin air filter. Better

Connor



Shop Repair/Work Order



Date: Jan 19/24
 Unit Number: 68
 Make/Model: High head T800

Kilometers: 1273516
 Hours: 35078

Work Order	Parts	Vendors
Poor Heat	Cabin Air Filter	JRF Re order one for stock.

Corrective Action Taken:

Found Cabin air Filter to be plugged causing poor heat flow
 Replaced Cabin air Filter & put winter Front on truck as well.



Shop Repair/Work Order



Date: Jan 15/21
 Unit Number: 68
 Make/Model: Kenworth

Scott B

Kilometers: ~~126468~~ 126463
 Hours: 3462

Work Order	Parts	Vendors
Tranny	Diesel stop, a/dic, paper	
Tranny		

Corrective Action Taken:
~~R3R~~ R3R Tranny changed clutches, R²B Rear main seal
 set clutches, filled Tranny with oil, Test Drive
