

FB2	3/24/25	FrameBodyWorkTools	other	Replace saw arbore on falling head. New arbore, nut, and bearings.
FB2	8/24/23	CabAndAccessories	Other	Replace cab tilt cylinder LH side.
FB2	6/11/23	Undercarriage	Tracks	New rails, sprockets from GW. Resealed both adjusters. Replace broken pads. New slides.
FB2	11/14/24	Engines	Starting sys	Replace batteries,
FB2	1/18/23	Hydraulics	cylinders	Replace grab arm cylinder.
FB2	6/10/23	FrameBodyWorkTools	Boom & Stick	Broken boom pin. Boom, and mount line bored, new pin. Stick to boom, line bored and new pin.
FB2	6/10/23	FrameBodyWorkTools	Boom & Stick	End of stick line bored and head coupling line bored, with new pin. Rotate bearing wear plate replace and tighten
FB2	4/14/22	Hydraulics	Motors	Replace both head rotate motors due to damaged gears and plates and rebearing both gear drives
FB2	4/14/22	Hydraulics	Pumps	Replace main implement pump due to excessive case drain and over filling gear case

M12-43  
MAY