

I35-1
MAY

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Nov 6, 2019	Other Maintenance		550.00	WO#3557-58 MONTHLY INSPECTION REPLACE EANGINE FAN REPLACE POVER STEERING RESERVOR CAP REPLACE MISING WASH BOTLE CAP REPLACE COMPRESOR GASCKET CHECK OVER	CAD	17163.0	652223.0
Nov 8, 2019	Other Maintenance		120.00	WO#3565-58 ORDER PARTS REPLACE TOP RAD HOSE TORQUE U-BOLTS AXLE 2 LH-RH CHECK OVER	CAD	17179.0	652569.0
Nov 25, 2019	Air system repair		250.00	WO#3581-58 REPLACE AIR BRAKE HOSE AXLE 3 LH INSTALL NEW LED HEAD LAMPS CHECK OVER	CAD	17277.0	655520.0
Nov 25, 2019	Headlamp Replacement		250.00	WO#3581-58 REPLACE AIR BRAKE HOSE AXLE 3 LH INSTALL NEW LED HEAD LAMPS CHECK OVER	CAD	17277.0	655520.0
Dec 9, 2019	Other Maintenance		150.00	WO 3528-58 REPLACE #4 RHS SHOCK INSPECT AXLE AND SUSPENSION FOR OTHER DAMAGE	CAD	17331.0	657044.0
Dec 14, 2019	Adjust Brakes		600.00	WO 3535-58 REPLACE CAB SIDE WORKLIGHT REPLACE ENGINE OIL FILTER GREASE UNIT CHANGE OIL ADJUST BRAKES FIX AIR LEAK CHECK FLUIDS	CAD	17371.0	658125.0
Dec 14, 2019	Monthly Insp.		600.00	WO 3535-58 REPLACE CAB SIDE WORKLIGHT REPLACE ENGINE OIL FILTER GREASE UNIT CHANGE OIL ADJUST BRAKES FIX AIR LEAK CHECK FLUIDS	CAD	17371.0	658125.0
Dec 14, 2019	Work Light Replacement		600.00	WO 3535-58 REPLACE CAB SIDE WORKLIGHT REPLACE ENGINE OIL FILTER GREASE UNIT CHANGE OIL ADJUST BRAKES FIX AIR LEAK CHECK FLUIDS	CAD	17371.0	658125.0
Dec 14, 2019	Grease Unit		600.00	WO 3535-58 REPLACE CAB SIDE WORKLIGHT REPLACE ENGINE OIL FILTER GREASE UNIT CHANGE OIL ADJUST BRAKES FIX AIR LEAK CHECK FLUIDS	CAD	17371.0	658125.0
Dec 14, 2019	Oil Change		600.00	WO 3535-58 REPLACE CAB SIDE WORKLIGHT REPLACE ENGINE OIL FILTER GREASE UNIT CHANGE OIL ADJUST BRAKES FIX AIR LEAK CHECK FLUIDS	CAD	17371.0	658125.0
Dec 14, 2019	Heater Blower Motor Replacement		600.00	WO 3535-58 REPLACE CAB SIDE WORKLIGHT REPLACE ENGINE OIL FILTER GREASE UNIT CHANGE OIL ADJUST BRAKES FIX AIR LEAK CHECK FLUIDS	CAD	17371.0	658125.0
Dec 17, 2019	Supplies Purchase		35.00	WO#3264-58 SUPPLAY 1,5 SCREEN FOR FILL GUNE	CAD	17375.0	658129.0
Dec 28, 2019	Rebuild Super Swivel		150.00	WO 3455-58 REBUILD SUPER SWIVEL ON HOSE REEL REPLACE 2" VIC SEAL ON PIPE ALIGN AND TIGHTEN VIC CLAMP	CAD	17451.0	660521.0
Jan 7, 2020	Replace Worklight(s)		550.00	WO#3282-58 MONTHLY INSPECTION REPLACE WORK LIGHTS REBULID HYDRAULIC COOLER REPLACE HYDRAULIC OIL CHECK OIL LEVEL TOP UP FLUIDS	CAD	17515.0	662373.0
Jan 7, 2020	Monthly Insp.		550.00	WO#3282-58 MONTHLY INSPECTION REPLACE WORK LIGHTS REBULID HYDRAULIC COOLER REPLACE HYDRAULIC OIL CHECK OIL LEVEL TOP UP FLUIDS	CAD	17515.0	662373.0
Jan 7, 2020	Hydraulics Repair		550.00	WO#3282-58 MONTHLY INSPECTION REPLACE WORK LIGHTS REBULID HYDRAULIC COOLER REPLACE HYDRAULIC OIL CHECK OIL LEVEL TOP UP FLUIDS	CAD	17515.0	662373.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Jan 7, 2020	Valve replacement		550.00	WO#3282-58 MONTHLY INSPECTION REPLACE WORK LIGHTS REBULID HYDRAULIC COOLER REPLACE HYDRAULIC OIL CHECK OIL LEVEL TOP UP FLUIDS	CAD	17515.0	662373.0
Jan 7, 2020	Other Maintenance		550.00	WO#3282-58 MONTHLY INSPECTION REPLACE WORK LIGHTS REBULID HYDRAULIC COOLER REPLACE HYDRAULIC OIL CHECK OIL LEVEL TOP UP FLUIDS	CAD	17515.0	662373.0
Jan 16, 2020	Electrical Wiring Repair		270.00	WO#3482-58 REPLACE TOGO SWICH ON SEE LEVEL GAUGE ORDER DIESEL HIGHE PRESURE PUMP GASCKET	CAD	17542.0	663089.0
Feb 2, 2020	Monthly Insp.		320.00	WO# 3320-58 MONTHLY INSPECTION OIL CHANGE LUBE JOB ORDER DUSTCH SCHIELD AND SIGNAL LIGHTS	CAD	17635.0	666018.0
Feb 2, 2020	Oil Change		320.00	WO# 3320-58 MONTHLY INSPECTION OIL CHANGE LUBE JOB ORDER DUSTCH SCHIELD AND SIGNAL LIGHTS	CAD	17635.0	666018.0
Feb 4, 2020	Marker Light Replacement		260.00	WO#3325-58 REPLACE 2 MARKINGS-SIGNAL LIGHTS ON QWATER FENDER LH-RH REPLACE DUSTH SHIELD AXLE 1 LH CHECK OVER	CAD	17651.0	666516.0
Feb 11, 2020	Electrical System Diagnostics		80.00	WO#3334-58 REPAIR WARING AND ELEC PLUGS REPLACE FUSES TROBOSHUTING ELECTRICAL SYSTEM	CAD	17679.0	667292.0
Feb 11, 2020	Other Maintenance		80.00	WO#3334-58 REPAIR WARING AND ELEC PLUGS REPLACE FUSES TROBOSHUTING ELECTRICAL SYSTEM	CAD	17679.0	667292.0
Mar 23, 2020	Air system repair		440.00	WO#3395-58 REPLACE AIR DRAYER REPLACE FLAT TIRE AXLE 3 LH REPLACE DUSTH SHIELD	CAD	17909.0	674402.0
Mar 23, 2020	Tire Service		440.00	WO#3395-58 REPLACE AIR DRAYER REPLACE FLAT TIRE AXLE 3 LH REPLACE DUSTH SHIELD	CAD	17909.0	674402.0
Mar 23, 2020	Other Maintenance		440.00	WO#3395-58 REPLACE AIR DRAYER REPLACE FLAT TIRE AXLE 3 LH REPLACE DUSTH SHIELD	CAD	17909.0	674402.0
Mar 28, 2020	PT- TK Pressure Test (P)		1150.00	WO#3399-58 TANK TEST V.K.I.P SERVICE OIL ,FILTERS.LUBE JOB REPAIR BROCKEN DRIVER SIDE FUELL STEP REPLACE DUSTH SHIELD REPAIR FLAT TIRE AXLE 3 LH INSIDE REPAIR WARING	CAD	17910.0	674402.0
Mar 28, 2020	PT - Leakage TK insp. (K)		1150.00	WO#3399-58 TANK TEST V.K.I.P SERVICE OIL ,FILTERS.LUBE JOB REPAIR BROCKEN DRIVER SIDE FUELL STEP REPLACE DUSTH SHIELD REPAIR FLAT TIRE AXLE 3 LH INSIDE REPAIR WARING	CAD	17910.0	674402.0
Mar 28, 2020	PT - Internal TK insp. (I)		1150.00	WO#3399-58 TANK TEST V.K.I.P SERVICE OIL ,FILTERS.LUBE JOB REPAIR BROCKEN DRIVER SIDE FUELL STEP REPLACE DUSTH SHIELD REPAIR FLAT TIRE AXLE 3 LH INSIDE REPAIR WARING	CAD	17910.0	674402.0
Mar 28, 2020	PT - External TK insp. (V)		1150.00	WO#3399-58 TANK TEST V.K.I.P SERVICE OIL ,FILTERS.LUBE JOB REPAIR BROCKEN DRIVER SIDE FUELL STEP REPLACE DUSTH SHIELD REPAIR FLAT TIRE AXLE 3 LH INSIDE REPAIR WARING	CAD	17910.0	674402.0
Mar 28, 2020	Monthly Insp.		1150.00	WO#3399-58 TANK TEST V.K.I.P SERVICE OIL ,FILTERS.LUBE JOB REPAIR BROCKEN DRIVER SIDE FUELL STEP REPLACE DUSTH SHIELD REPAIR FLAT TIRE AXLE 3 LH INSIDE REPAIR WARING	CAD	17910.0	674402.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Mar 28, 2020	Tank Inspection		1150.00	WO#3399-58 TANK TEST V.K.I.P SERVICE OIL ,FILTERS.LUBE JOB REPAIR BROCKEN DRIVER SIDE FUELL STEPL REPLACE DUSTH SHIELD REPAIR FLAT TIRE AXLE 3 LH INSIDE REPAIR WARING	CAD	17910.0	674402.0
Mar 28, 2020	Other Maintenance		1150.00	WO#3399-58 TANK TEST V.K.I.P SERVICE OIL ,FILTERS.LUBE JOB REPAIR BROCKEN DRIVER SIDE FUELL STEPL REPLACE DUSTH SHIELD REPAIR FLAT TIRE AXLE 3 LH INSIDE REPAIR WARING	CAD	17910.0	674402.0
Mar 28, 2020	Oil Change		1150.00	WO#3399-58 TANK TEST V.K.I.P SERVICE OIL ,FILTERS.LUBE JOB REPAIR BROCKEN DRIVER SIDE FUELL STEPL REPLACE DUSTH SHIELD REPAIR FLAT TIRE AXLE 3 LH INSIDE REPAIR WARING	CAD	17910.0	674402.0
Apr 15, 2020	Air system repair		1000.00	WO#3417-58 REPLACE 2X ABS AIR MODULERS VALVE REPLACE AIR VALVE Q7 REPLACE BRAKES AND DRUMS AXLE 4 LH/RH REPLACE 4 WORK LIGHTS REPLACE COUPLE AIR FITINGS AND AIR HOSE ADJUST BRAKES AND TORQUE WHEELS	CAD	18029.0	678042.0
Apr 15, 2020	Adjust Brakes		1000.00	WO#3417-58 REPLACE 2X ABS AIR MODULERS VALVE REPLACE AIR VALVE Q7 REPLACE BRAKES AND DRUMS AXLE 4 LH/RH REPLACE 4 WORK LIGHTS REPLACE COUPLE AIR FITINGS AND AIR HOSE ADJUST BRAKES AND TORQUE WHEELS	CAD	18029.0	678042.0
Apr 15, 2020	Brake Drum Replacement		1000.00	WO#3417-58 REPLACE 2X ABS AIR MODULERS VALVE REPLACE AIR VALVE Q7 REPLACE BRAKES AND DRUMS AXLE 4 LH/RH REPLACE 4 WORK LIGHTS REPLACE COUPLE AIR FITINGS AND AIR HOSE ADJUST BRAKES AND TORQUE WHEELS	CAD	18029.0	678042.0
Apr 15, 2020	Work Light Replacement		1000.00	WO#3417-58 REPLACE 2X ABS AIR MODULERS VALVE REPLACE AIR VALVE Q7 REPLACE BRAKES AND DRUMS AXLE 4 LH/RH REPLACE 4 WORK LIGHTS REPLACE COUPLE AIR FITINGS AND AIR HOSE ADJUST BRAKES AND TORQUE WHEELS	CAD	18029.0	678042.0
Apr 15, 2020	Torque Wheels		1000.00	WO#3417-58 REPLACE 2X ABS AIR MODULERS VALVE REPLACE AIR VALVE Q7 REPLACE BRAKES AND DRUMS AXLE 4 LH/RH REPLACE 4 WORK LIGHTS REPLACE COUPLE AIR FITINGS AND AIR HOSE ADJUST BRAKES AND TORQUE WHEELS	CAD	18029.0	678042.0
Apr 15, 2020	Brake Pad(s) Replacement		1000.00	WO#3417-58 REPLACE 2X ABS AIR MODULERS VALVE REPLACE AIR VALVE Q7 REPLACE BRAKES AND DRUMS AXLE 4 LH/RH REPLACE 4 WORK LIGHTS REPLACE COUPLE AIR FITINGS AND AIR HOSE ADJUST BRAKES AND TORQUE WHEELS	CAD	18029.0	678042.0
Apr 15, 2020	Brake Inspection		1000.00	WO#3417-58 REPLACE 2X ABS AIR MODULERS VALVE REPLACE AIR VALVE Q7 REPLACE BRAKES AND DRUMS AXLE 4 LH/RH REPLACE 4 WORK LIGHTS REPLACE COUPLE AIR FITINGS AND AIR HOSE ADJUST BRAKES AND TORQUE WHEELS	CAD	18029.0	678042.0
Apr 27, 2020	Other Maintenance		80.00	WO#3429-58 REPLACE 3 INCH VICK SEAL IN PUMP BOX INSTALL NEW T-E PUMP GASCKET FOR PLUMING	CAD	18068.0	679352.0
May 14, 2020	Tire Replacement		230.00	WO#3449-58 REPLACE 4 USE TIRES FROM BURN AXLE 4	CAD	18148.0	682205.0
May 26, 2020	Monthly Insp.		1100.00	WO#3918-58 SERVICE OIL AND FILTERS LUBE JOB MONTHLY INSPECTION REPLACE AC CONDENSER AND REFILE AC SYSTEM REPLACE 2 X 2INCH VIC CLAMPS CHECK OVER	CAD	18173.0	682996.0
May 26, 2020	Other Maintenance		1100.00	WO#3918-58 SERVICE OIL AND FILTERS LUBE JOB MONTHLY INSPECTION REPLACE AC CONDENSER AND REFILE AC SYSTEM REPLACE 2 X 2INCH VIC CLAMPS CHECK OVER	CAD	18173.0	682996.0
May 26, 2020	Oil Change		1100.00	WO#3918-58 SERVICE OIL AND FILTERS LUBE JOB MONTHLY INSPECTION REPLACE AC CONDENSER AND REFILE AC SYSTEM REPLACE 2 X 2INCH VIC CLAMPS CHECK OVER	CAD	18173.0	682996.0
May 26, 2020	A/C Condenser Replacement		1100.00	WO#3918-58 SERVICE OIL AND FILTERS LUBE JOB MONTHLY INSPECTION REPLACE AC CONDENSER AND REFILE AC SYSTEM REPLACE 2 X 2INCH VIC CLAMPS CHECK OVER	CAD	18173.0	682996.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Jun 8, 2020	Power Steering Repair		1550.00	WO#3932-58\tnREPLACE POVER STEERING BOX\tnREPLACE POVER STERING FLUID\tnTEST	CAD	18225.0	684877.0
Jun 8, 2020	Other Maintenance		1550.00	WO#3932-58\tnREPLACE POVER STEERING BOX\tnREPLACE POVER STERING FLUID\tnTEST	CAD	18225.0	684877.0
Jun 30, 2020	Air system repair		2500.00	WO#3706-58\tnCVIP\tnMONTHLY INSPECTION\tnREPLACE DRUMS AND SHOE AXLE 2,3 \tnREPLACE SHOE AXLE 1 \tnREPLACE U-BOLTS AXLE 2 RH \tnREPAIR SPRINGS \tnREPLACE TOP EXHOUST STAG BUSHINGS\tnREPAIR WARING\tnREPLACE 2 AIR BRAKE PODS HOSE\tnTORQUE WHEELS\tnRETORQE WHEELS	CAD	18231.0	687527.0
Jun 30, 2020	Adjust Brakes		2500.00	WO#3706-58\tnCVIP\tnMONTHLY INSPECTION\tnREPLACE DRUMS AND SHOE AXLE 2,3 \tnREPLACE SHOE AXLE 1 \tnREPLACE U-BOLTS AXLE 2 RH \tnREPAIR SPRINGS \tnREPLACE TOP EXHOUST STAG BUSHINGS\tnREPAIR WARING\tnREPLACE 2 AIR BRAKE PODS HOSE\tnTORQUE WHEELS\tnRETORQE WHEELS	CAD	18231.0	687527.0
Jun 30, 2020	Monthly Insp.		2500.00	WO#3706-58\tnCVIP\tnMONTHLY INSPECTION\tnREPLACE DRUMS AND SHOE AXLE 2,3 \tnREPLACE SHOE AXLE 1 \tnREPLACE U-BOLTS AXLE 2 RH \tnREPAIR SPRINGS \tnREPLACE TOP EXHOUST STAG BUSHINGS\tnREPAIR WARING\tnREPLACE 2 AIR BRAKE PODS HOSE\tnTORQUE WHEELS\tnRETORQE WHEELS	CAD	18231.0	687527.0
Jun 30, 2020	Brake Drum Replacement		2500.00	WO#3706-58\tnCVIP\tnMONTHLY INSPECTION\tnREPLACE DRUMS AND SHOE AXLE 2,3 \tnREPLACE SHOE AXLE 1 \tnREPLACE U-BOLTS AXLE 2 RH \tnREPAIR SPRINGS \tnREPLACE TOP EXHOUST STAG BUSHINGS\tnREPAIR WARING\tnREPLACE 2 AIR BRAKE PODS HOSE\tnTORQUE WHEELS\tnRETORQE WHEELS	CAD	18231.0	687527.0
Jun 30, 2020	Annual CVIP		2500.00	WO#3706-58\tnCVIP\tnMONTHLY INSPECTION\tnREPLACE DRUMS AND SHOE AXLE 2,3 \tnREPLACE SHOE AXLE 1 \tnREPLACE U-BOLTS AXLE 2 RH \tnREPAIR SPRINGS \tnREPLACE TOP EXHOUST STAG BUSHINGS\tnREPAIR WARING\tnREPLACE 2 AIR BRAKE PODS HOSE\tnTORQUE WHEELS\tnRETORQE WHEELS	CAD	18231.0	687527.0
Jun 30, 2020	Torque Wheels		2500.00	WO#3706-58\tnCVIP\tnMONTHLY INSPECTION\tnREPLACE DRUMS AND SHOE AXLE 2,3 \tnREPLACE SHOE AXLE 1 \tnREPLACE U-BOLTS AXLE 2 RH \tnREPAIR SPRINGS \tnREPLACE TOP EXHOUST STAG BUSHINGS\tnREPAIR WARING\tnREPLACE 2 AIR BRAKE PODS HOSE\tnTORQUE WHEELS\tnRETORQE WHEELS	CAD	18231.0	687527.0
Jun 30, 2020	Other Maintenance		2500.00	WO#3706-58\tnCVIP\tnMONTHLY INSPECTION\tnREPLACE DRUMS AND SHOE AXLE 2,3 \tnREPLACE SHOE AXLE 1 \tnREPLACE U-BOLTS AXLE 2 RH \tnREPAIR SPRINGS \tnREPLACE TOP EXHOUST STAG BUSHINGS\tnREPAIR WARING\tnREPLACE 2 AIR BRAKE PODS HOSE\tnTORQUE WHEELS\tnRETORQE WHEELS	CAD	18231.0	687527.0
Jun 30, 2020	Brake Pad(s) Replacement		2500.00	WO#3706-58\tnCVIP\tnMONTHLY INSPECTION\tnREPLACE DRUMS AND SHOE AXLE 2,3 \tnREPLACE SHOE AXLE 1 \tnREPLACE U-BOLTS AXLE 2 RH \tnREPAIR SPRINGS \tnREPLACE TOP EXHOUST STAG BUSHINGS\tnREPAIR WARING\tnREPLACE 2 AIR BRAKE PODS HOSE\tnTORQUE WHEELS\tnRETORQE WHEELS	CAD	18231.0	687527.0
Jun 30, 2020	Brake Inspection		2500.00	WO#3706-58\tnCVIP\tnMONTHLY INSPECTION\tnREPLACE DRUMS AND SHOE AXLE 2,3 \tnREPLACE SHOE AXLE 1 \tnREPLACE U-BOLTS AXLE 2 RH \tnREPAIR SPRINGS \tnREPLACE TOP EXHOUST STAG BUSHINGS\tnREPAIR WARING\tnREPLACE 2 AIR BRAKE PODS HOSE\tnTORQUE WHEELS\tnRETORQE WHEELS	CAD	18231.0	687527.0
Jul 13, 2020	Marker Light Replacement		420.00	WO#3714-58\tnREPLACE DAMAGE LED SIGNAL LIGHTS FRONT LH\tnTROBOSHUTING AC\tnRECHARGE AC \tnREPLACE COUPLE SEALS AC SYSTEM\tn	CAD	18357.0	688737.0
Jul 13, 2020	A/C Diagnosis		420.00	WO#3714-58\tnREPLACE DAMAGE LED SIGNAL LIGHTS FRONT LH\tnTROBOSHUTING AC\tnRECHARGE AC \tnREPLACE COUPLE SEALS AC SYSTEM\tn	CAD	18357.0	688737.0
Aug 13, 2020	Adjust Brakes		1400.00	WO3749.\tn-Wash Unit.\tn-Monthly Inspection.\tn-Service: oil, oil filter, fuel filters, grease undercarriage.\tn-Troubleshooting fuses and wiring.\tn-Remove replace steering Draglink LH.\tn-Remove replace Torsion bar axle #2 LH RH\tn-Adjust brakes.\tn-Top up / check fluids.	CAD	18512.0	693490.0
Aug 13, 2020	Monthly Insp.		1400.00	WO3749.\tn-Wash Unit.\tn-Monthly Inspection.\tn-Service: oil, oil filter, fuel filters, grease undercarriage.\tn-Troubleshooting fuses and wiring.\tn-Remove replace steering Draglink LH.\tn-Remove replace Torsion bar axle #2 LH RH\tn-Adjust brakes.\tn-Top up / check fluids.	CAD	18512.0	693490.0
Aug 13, 2020	Grease Unit		1400.00	WO3749.\tn-Wash Unit.\tn-Monthly Inspection.\tn-Service: oil, oil filter, fuel filters, grease undercarriage.\tn-Troubleshooting fuses and wiring.\tn-Remove replace steering Draglink LH.\tn-Remove replace Torsion bar axle #2 LH RH\tn-Adjust brakes.\tn-Top up / check fluids.	CAD	18512.0	693490.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Aug 13, 2020	Oil Change		1400.00	WO3749.\r\n-Wash Unit.\r\n-Monthly Inspection.\r\n-Service: oil, oil filter, fuel filters, grease undercarriage.\r\n-Troubleshooting fuses and wiring.\r\n-Remove replace steering Draglink LH.\r\n-Remove replace Torsion bar axle #2 LH RH\r\n-Adjust brakes.\r\n-Top up / check fluids.	CAD	18512.0	693490.0
Aug 27, 2020	Exhaust Manifold Replacement		120.00	WO#3963-58\r\nREPLACE UPPER STAG MANUFOLD BUSHINGS\r\nREPAIR MOUT BRACKET	CAD	18612.0	696747.0
Sep 12, 2020	VIC SEAL		450.00	WO3982.\r\n-Remove pump box plumbing, repair / weld.\r\n-Install plumbing with two VIC seals, two Keystone BUNA 3".\r\n-Function / pressure test.\r\n\r\n	CAD	18721.0	700437.0
Sep 12, 2020	Welding		450.00	WO3982.\r\n-Remove pump box plumbing, repair / weld.\r\n-Install plumbing with two VIC seals, two Keystone BUNA 3".\r\n-Function / pressure test.\r\n\r\n	CAD	18721.0	700437.0
Sep 12, 2020	Valve replacement		450.00	WO3982.\r\n-Remove pump box plumbing, repair / weld.\r\n-Install plumbing with two VIC seals, two Keystone BUNA 3".\r\n-Function / pressure test.\r\n\r\n	CAD	18721.0	700437.0
Sep 26, 2020	Air system repair		700.00	WO3997.\r\n-Monthly inspection.\r\n-Service: Oil, oil filter fuel filters, grease undercarriage.\r\n-Replace two 2" marker lights.\r\n-Check for and repair air leaks.\r\n-Zip tie all loose wiring and hoses under truck.\r\n-Top up fluids.\r\n-Rebuild tank fill gun.\r\n-Remove replace front windshield.	CAD	18804.0	702797.0
Sep 26, 2020	Monthly Insp.		700.00	WO3997.\r\n-Monthly inspection.\r\n-Service: Oil, oil filter fuel filters, grease undercarriage.\r\n-Replace two 2" marker lights.\r\n-Check for and repair air leaks.\r\n-Zip tie all loose wiring and hoses under truck.\r\n-Top up fluids.\r\n-Rebuild tank fill gun.\r\n-Remove replace front windshield.	CAD	18804.0	702797.0
Sep 26, 2020	Grease Unit		700.00	WO3997.\r\n-Monthly inspection.\r\n-Service: Oil, oil filter fuel filters, grease undercarriage.\r\n-Replace two 2" marker lights.\r\n-Check for and repair air leaks.\r\n-Zip tie all loose wiring and hoses under truck.\r\n-Top up fluids.\r\n-Rebuild tank fill gun.\r\n-Remove replace front windshield.	CAD	18804.0	702797.0
Sep 26, 2020	Windshield Replacement		700.00	WO3997.\r\n-Monthly inspection.\r\n-Service: Oil, oil filter fuel filters, grease undercarriage.\r\n-Replace two 2" marker lights.\r\n-Check for and repair air leaks.\r\n-Zip tie all loose wiring and hoses under truck.\r\n-Top up fluids.\r\n-Rebuild tank fill gun.\r\n-Remove replace front windshield.	CAD	18804.0	702797.0
Sep 26, 2020	Oil Change		700.00	WO3997.\r\n-Monthly inspection.\r\n-Service: Oil, oil filter fuel filters, grease undercarriage.\r\n-Replace two 2" marker lights.\r\n-Check for and repair air leaks.\r\n-Zip tie all loose wiring and hoses under truck.\r\n-Top up fluids.\r\n-Rebuild tank fill gun.\r\n-Remove replace front windshield.	CAD	18804.0	702797.0
Oct 2, 2020	Hydraulics Repair		600.00	WO4810.\r\n-Remove replace alternator.\r\n-Remove replace fan belt.\r\n-Clean all pedals.\r\n-Troubleshoot tank gauge connections.\r\n-Check hydraulic cooler for leaks.	CAD	18824.0	702916.0
Oct 2, 2020	Electrical Wiring Repair		600.00	WO4810.\r\n-Remove replace alternator.\r\n-Remove replace fan belt.\r\n-Clean all pedals.\r\n-Troubleshoot tank gauge connections.\r\n-Check hydraulic cooler for leaks.	CAD	18824.0	702916.0
Oct 2, 2020	Engine/Drive Belt(s) Replacement		600.00	WO4810.\r\n-Remove replace alternator.\r\n-Remove replace fan belt.\r\n-Clean all pedals.\r\n-Troubleshoot tank gauge connections.\r\n-Check hydraulic cooler for leaks.	CAD	18824.0	702916.0
Oct 2, 2020	Alternator Replacement		600.00	WO4810.\r\n-Remove replace alternator.\r\n-Remove replace fan belt.\r\n-Clean all pedals.\r\n-Troubleshoot tank gauge connections.\r\n-Check hydraulic cooler for leaks.	CAD	18824.0	702916.0
Oct 30, 2020	VIC SEAL		1000.00	WO4951.\r\n-Remove replace signal light front headlamp.\r\n-Repair hydraulic cooler.\r\n-Add hydraulic oil.\r\n-Repair wiring, troubleshoot heater box and work lights.\r\n-Remove replace 3 vic seals in pump box.\r\n-Remove replace 1 work light @ tank.\r\n-Supply sight glass.\r\n-Remove rebuild auto nozzle with new kit.\r\n\r\n	CAD	18967.0	706236.0
Oct 30, 2020	Supplies Purchase		1000.00	WO4951.\r\n-Remove replace signal light front headlamp.\r\n-Repair hydraulic cooler.\r\n-Add hydraulic oil.\r\n-Repair wiring, troubleshoot heater box and work lights.\r\n-Remove replace 3 vic seals in pump box.\r\n-Remove replace 1 work light @ tank.\r\n-Supply sight glass.\r\n-Remove rebuild auto nozzle with new kit.\r\n\r\n	CAD	18967.0	706236.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Oct 30, 2020	Work Light Replacement		1000.00	WO4951.\r\n-Remove replace signal light front headlamp.\r\n-Repair hydraulic cooler.\r\n-Add hydraulic oil.\r\n-Repair wiring, troubleshoot heater box and work lights.\r\n-Remove replace 3 vic seals in pump box.\r\n-Remove replace 1 work light @ tank.\r\n-Supply sight glass.\r\n-Remove rebuild auto nozzle with new kit.\r\n\r\n	CAD	18967.0	706236.0
Oct 30, 2020	Electrical Wiring Repair		1000.00	WO4951.\r\n-Remove replace signal light front headlamp.\r\n-Repair hydraulic cooler.\r\n-Add hydraulic oil.\r\n-Repair wiring, troubleshoot heater box and work lights.\r\n-Remove replace 3 vic seals in pump box.\r\n-Remove replace 1 work light @ tank.\r\n-Supply sight glass.\r\n-Remove rebuild auto nozzle with new kit.\r\n\r\n	CAD	18967.0	706236.0
Nov 26, 2020	Monthly Insp.		400.00	WO#4976-58\r\nMONTHLY \r\nSERVICE OIL AND FILTERS\r\nLUBE JOB\r\nREPAIR LIGHTS -MARKINS LIGHTS	CAD	19126.0	708376.0
Nov 26, 2020	Oil Change		400.00	WO#4976-58\r\nMONTHLY \r\nSERVICE OIL AND FILTERS\r\nLUBE JOB\r\nREPAIR LIGHTS -MARKINS LIGHTS	CAD	19126.0	708376.0
Dec 17, 2020	Supplies Purchase		150.00	WO#5003-58\r\nSUPPLAY 1INCH FILL GUN \r\nSUPPLAY COUPLE CAMLOCK FITINGS	CAD	19341.0	713559.0
Dec 17, 2020	Other Maintenance		150.00	WO#5003-58\r\nSUPPLAY 1INCH FILL GUN \r\nSUPPLAY COUPLE CAMLOCK FITINGS	CAD	19341.0	713559.0
Jan 2, 2021	TOOL BOX / FITTINGS INVENTORY		701.06	WO4913.\r\n-remove rebuild replace 1 1/2" super swivel.\r\n-remove 1 1/2" chemical transfer hose, thaw with steam, pressure test.\r\n-re-crimp 1 1/2" chemical transfer hose @the source.\r\n-install 1 1/2" chemical transfer hose, pressure test with h2O.\r\n-pick up 2x3 kamlok fxf, 2" spool adapater.	CAD	19557.0	717049.0
Jan 2, 2021	Rebuild Super Swivel		701.06	WO4913.\r\n-remove rebuild replace 1 1/2" super swivel.\r\n-remove 1 1/2" chemical transfer hose, thaw with steam, pressure test.\r\n-re-crimp 1 1/2" chemical transfer hose @the source.\r\n-install 1 1/2" chemical transfer hose, pressure test with h2O.\r\n-pick up 2x3 kamlok fxf, 2" spool adapater.	CAD	19557.0	717049.0
Jan 8, 2021	Air system repair		300.00	WO5031.\r\n-Remove replace Air dryer.\r\n-Remove replace Governor Valve.\r\n-Re-crimp Flush hose @ top of tank.	CAD	19558.0	717049.0
Jan 14, 2021	Dust Shield Replacement		500.00	WO5039.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Remove replace Air Dryer.\r\n-Install Dust shield Axle #1 LH.\r\n-Remove replace ABS sensor Axle #1 LH.\r\n-add hydraulic oil.\r\n-Remove replace Marker light on tank\r\n-Service call - remove replace purgue valve on air dryer.	CAD	19561.0	717049.0
Jan 14, 2021	Change crankcase filter		500.00	WO5039.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Remove replace Air Dryer.\r\n-Install Dust shield Axle #1 LH.\r\n-Remove replace ABS sensor Axle #1 LH.\r\n-add hydraulic oil.\r\n-Remove replace Marker light on tank\r\n-Service call - remove replace purgue valve on air dryer.	CAD	19561.0	717049.0
Jan 14, 2021	Monthly Insp.		500.00	WO5039.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Remove replace Air Dryer.\r\n-Install Dust shield Axle #1 LH.\r\n-Remove replace ABS sensor Axle #1 LH.\r\n-add hydraulic oil.\r\n-Remove replace Marker light on tank\r\n-Service call - remove replace purgue valve on air dryer.	CAD	19561.0	717049.0
Jan 14, 2021	Fuel Filter Replacement		500.00	WO5039.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Remove replace Air Dryer.\r\n-Install Dust shield Axle #1 LH.\r\n-Remove replace ABS sensor Axle #1 LH.\r\n-add hydraulic oil.\r\n-Remove replace Marker light on tank\r\n-Service call - remove replace purgue valve on air dryer.	CAD	19561.0	717049.0
Jan 14, 2021	Marker Light Replacement		500.00	WO5039.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Remove replace Air Dryer.\r\n-Install Dust shield Axle #1 LH.\r\n-Remove replace ABS sensor Axle #1 LH.\r\n-add hydraulic oil.\r\n-Remove replace Marker light on tank\r\n-Service call - remove replace purgue valve on air dryer.	CAD	19561.0	717049.0
Jan 14, 2021	Oil Change		500.00	WO5039.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Remove replace Air Dryer.\r\n-Install Dust shield Axle #1 LH.\r\n-Remove replace ABS sensor Axle #1 LH.\r\n-add hydraulic oil.\r\n-Remove replace Marker light on tank\r\n-Service call - remove replace purgue valve on air dryer.	CAD	19561.0	717049.0
Jan 14, 2021	A/C Compressor Replacement		500.00	WO5039.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Remove replace Air Dryer.\r\n-Install Dust shield Axle #1 LH.\r\n-Remove replace ABS sensor Axle #1 LH.\r\n-add hydraulic oil.\r\n-Remove replace Marker light on tank\r\n-Service call - remove replace purgue valve on air dryer.	CAD	19561.0	717049.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Feb 9, 2021	Battery Replacement		2000.00	WO4940.\r\n-Repair air leak driverside middle drive axle.\r\n-remove replace 3x batteries, repair/diagnose wiring.\r\n-remove replace sleeper cab air filter.\r\n-install winter front.\r\n-install tool box heater and blower passenger side above batteries.	CAD	19624.0	718418.0
Feb 9, 2021	Air system repair		2000.00	WO4940.\r\n-Repair air leak driverside middle drive axle.\r\n-remove replace 3x batteries, repair/diagnose wiring.\r\n-remove replace sleeper cab air filter.\r\n-install winter front.\r\n-install tool box heater and blower passenger side above batteries.	CAD	19624.0	718418.0
Feb 9, 2021	Other Maintenance		2000.00	WO4940.\r\n-Repair air leak driverside middle drive axle.\r\n-remove replace 3x batteries, repair/diagnose wiring.\r\n-remove replace sleeper cab air filter.\r\n-install winter front.\r\n-install tool box heater and blower passenger side above batteries.	CAD	19624.0	718418.0
Feb 16, 2021	T&E Pump Repair		50.00	WO4949.\r\n-remove re-seal replace T&E bolts.\r\n-repair radio power wiring	CAD	19644.0	718719.0
Feb 16, 2021	Electrical Wiring Repair		50.00	WO4949.\r\n-remove re-seal replace T&E bolts.\r\n-repair radio power wiring	CAD	19644.0	718719.0
Feb 18, 2021	T&E Pump Repair		200.00	WO5059\r\n-remove replace T&E bolts, thread tape and re-seal install.\r\n-remove and inspect super swivel 1 1/2", replace grease nipples x3\r\n-remove replace 1/2" T&E drain valve.	CAD	19696.0	720204.0
Feb 28, 2021	Monthly Insp.		200.00	WO5085.\r\n-change engine oil, crank case filter, fuel filter, fuel water seperator filter, grease undercarriage, grease T&E.\r\n-drain transmission fluid, fill with new sae50.\r\n\r\n	CAD	19728.0	721126.0
Feb 28, 2021	Grease Unit		200.00	WO5085.\r\n-change engine oil, crank case filter, fuel filter, fuel water seperator filter, grease undercarriage, grease T&E.\r\n-drain transmission fluid, fill with new sae50.\r\n\r\n	CAD	19728.0	721126.0
Feb 28, 2021	Oil Change		200.00	WO5085.\r\n-change engine oil, crank case filter, fuel filter, fuel water seperator filter, grease undercarriage, grease T&E.\r\n-drain transmission fluid, fill with new sae50.\r\n\r\n	CAD	19728.0	721126.0
Mar 2, 2021	Steady Bearing Replacement		500.00	WO5106.\r\n-Remove replace steady bearing #1\r\n-Inspect all bearings.\r\n-Repair coolant leak, tighten hose clamp.	CAD	19739.0	721557.0
Mar 3, 2021	Tire Replacement		1550.00	WO5096.\r\n@fountain tire, remove replace 2x steer tires.	CAD	19754.0	722124.0
Mar 5, 2021	T&E Pump Repair		300.00	WO5754.\r\n-remove replace hood cables x2.\r\n-remove T&E drain plumbing, pressure test / weld @TBWL, re- install, function test.	CAD	19762.0	722341.0
Mar 25, 2021	Air system repair		500.00	WO5119.\r\n-check over.\r\n-remove and replace air chamber bracket and pod @pintle hitch.\r\n-repair air leak.	CAD	19839.0	724740.0
Mar 25, 2021	Other Maintenance		500.00	WO5119.\r\n-check over.\r\n-remove and replace air chamber bracket and pod @pintle hitch.\r\n-repair air leak.	CAD	19839.0	724740.0
Mar 30, 2021	PT - Leakage TK insp. (K)		200.00	WO5798,\r\n-VK tank test complete.	CAD	19844.0	724786.0
Mar 30, 2021	PT - External TK insp. (V)		200.00	WO5798,\r\n-VK tank test complete.	CAD	19844.0	724786.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
May 1, 2021	Monthly Insp.		400.00	WO5840.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters, grease / inspect undercarriage.\r\n-Build and install engine bay hood safety cables.\r\n-Diagnose and repair wiring @ pump box, tool box.	CAD	19972.0	728837.0
May 1, 2021	Grease Unit		400.00	WO5840.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters, grease / inspect undercarriage.\r\n-Build and install engine bay hood safety cables.\r\n-Diagnose and repair wiring @ pump box, tool box.	CAD	19972.0	728837.0
May 1, 2021	Electrical Wiring Repair		400.00	WO5840.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters, grease / inspect undercarriage.\r\n-Build and install engine bay hood safety cables.\r\n-Diagnose and repair wiring @ pump box, tool box.	CAD	19972.0	728837.0
May 1, 2021	Other Maintenance		400.00	WO5840.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters, grease / inspect undercarriage.\r\n-Build and install engine bay hood safety cables.\r\n-Diagnose and repair wiring @ pump box, tool box.	CAD	19972.0	728837.0
May 1, 2021	Oil Change		400.00	WO5840.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters, grease / inspect undercarriage.\r\n-Build and install engine bay hood safety cables.\r\n-Diagnose and repair wiring @ pump box, tool box.	CAD	19972.0	728837.0
May 10, 2021	Pressure Test / Inspect Hose		30.00	WO4707.\r\n-Pressure test / hose inspection.\r\n-load hose (4).\r\n-chemical transfer hose (1).\r\n-install tags, complete paperwork.	CAD	19990.0	729563.0
Jun 7, 2021	A/C Recharge		1000.00	WO4652.\r\n-Check over.\r\n-Replace A/C compressor.\r\n-Recharge A/C system @TJ's A/C service.	CAD	20095.0	733870.0
Jun 7, 2021	A/C Condenser Replacement		1000.00	WO4652.\r\n-Check over.\r\n-Replace A/C compressor.\r\n-Recharge A/C system @TJ's A/C service.	CAD	20095.0	733870.0
Jun 25, 2021	Tank Flush		100.00	WO5184.\r\n-Flush and drain tank / plumbing.\r\n-Remove wash bar and 3" hose from unit #74.\r\n-Install wash bar and 3" hose on #58, function test.\r\n-Flush overheating hydraulic cooler.	CAD	20182.0	736941.0
Jun 25, 2021	Hydraulics Repair		100.00	WO5184.\r\n-Flush and drain tank / plumbing.\r\n-Remove wash bar and 3" hose from unit #74.\r\n-Install wash bar and 3" hose on #58, function test.\r\n-Flush overheating hydraulic cooler.	CAD	20182.0	736941.0
Jul 7, 2021	Hydraulics Repair		300.00	WO4674.\r\n-Inspect hydraulic system.\r\n-Replace hydraulic motor fan.\r\n-Replace hose, and hose clamps.\r\n-Replace pressure relief valve on valvebank.\r\n-Replace hydraulic oil.\r\n-Function test.	CAD	20303.0	739932.0
Jul 13, 2021	Service		1000.00	WO4678.\r\n-Monthly inspection complete.\r\n-Service complete, oil, oil filter, fuel filters, grease, inspect fluids.\r\n-CVIP complete:\r\n-Replace steady bearing #2.\r\n-Replace 4 shocks axle#2 axle #3 LH RH.\r\n-Replace RH steering draglink axle #1.\r\n-Replace air brake hose axle #1 LH.\r\n-Replace high beam lamp LH.\r\n-Replace tensioner bar bolts over axle #2.\r\n-Add fluids, torque wheels.\r\n-Replace 3" Teflon 3" keystone valve.\r\n-Retorque wheels.\r\n	CAD	20331.0	740894.0
Jul 13, 2021	Shock Absorber Replacement.		1000.00	WO4678.\r\n-Monthly inspection complete.\r\n-Service complete, oil, oil filter, fuel filters, grease, inspect fluids.\r\n-CVIP complete:\r\n-Replace steady bearing #2.\r\n-Replace 4 shocks axle#2 axle #3 LH RH.\r\n-Replace RH steering draglink axle #1.\r\n-Replace air brake hose axle #1 LH.\r\n-Replace high beam lamp LH.\r\n-Replace tensioner bar bolts over axle #2.\r\n-Add fluids, torque wheels.\r\n-Replace 3" Teflon 3" keystone valve.\r\n-Retorque wheels.\r\n	CAD	20331.0	740894.0
Jul 13, 2021	Annual CVIP		1000.00	WO4678.\r\n-Monthly inspection complete.\r\n-Service complete, oil, oil filter, fuel filters, grease, inspect fluids.\r\n-CVIP complete:\r\n-Replace steady bearing #2.\r\n-Replace 4 shocks axle#2 axle #3 LH RH.\r\n-Replace RH steering draglink axle #1.\r\n-Replace air brake hose axle #1 LH.\r\n-Replace high beam lamp LH.\r\n-Replace tensioner bar bolts over axle #2.\r\n-Add fluids, torque wheels.\r\n-Replace 3" Teflon 3" keystone valve.\r\n-Retorque wheels.\r\n	CAD	20331.0	740894.0
Jul 13, 2021	Valve replacement		1000.00	WO4678.\r\n-Monthly inspection complete.\r\n-Service complete, oil, oil filter, fuel filters, grease, inspect fluids.\r\n-CVIP complete:\r\n-Replace steady bearing #2.\r\n-Replace 4 shocks axle#2 axle #3 LH RH.\r\n-Replace RH steering draglink axle #1.\r\n-Replace air brake hose axle #1 LH.\r\n-Replace high beam lamp LH.\r\n-Replace tensioner bar bolts over axle #2.\r\n-Add fluids, torque wheels.\r\n-Replace 3" Teflon 3" keystone valve.\r\n-Retorque wheels.\r\n	CAD	20331.0	740894.0
Jul 13, 2021	Oil Change		1000.00	WO4678.\r\n-Monthly inspection complete.\r\n-Service complete, oil, oil filter, fuel filters, grease, inspect fluids.\r\n-CVIP complete:\r\n-Replace steady bearing #2.\r\n-Replace 4 shocks axle#2 axle #3 LH RH.\r\n-Replace RH steering draglink axle #1.\r\n-Replace air brake hose axle #1 LH.\r\n-Replace high beam lamp LH.\r\n-Replace tensioner bar bolts over axle #2.\r\n-Add fluids, torque wheels.\r\n-Replace 3" Teflon 3" keystone valve.\r\n-Retorque wheels.\r\n	CAD	20331.0	740894.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Aug 14, 2021	Electrical System Diagnostics		25.00	WO5235.\r\n-Repair RH rear turn signal circuit.	CAD	20482.0	747061.0
Aug 14, 2021	Electrical Wiring Repair		25.00	WO5235.\r\n-Repair RH rear turn signal circuit.	CAD	20482.0	747061.0
Aug 22, 2021	Service		400.00	WO4553.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Replace ABS sensor.\r\n-Replace Dust shield.\r\n-Replace 1 1/2 super swivel.\r\n-Lube job.\r\n-check over.\r\n-raise governor to 120km/hr.	CAD	20703.0	755127.0
Aug 22, 2021	ENGINE DIAGNOSTICS		400.00	WO4553.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Replace ABS sensor.\r\n-Replace Dust shield.\r\n-Replace 1 1/2 super swivel.\r\n-Lube job.\r\n-check over.\r\n-raise governor to 120km/hr.	CAD	20703.0	755127.0
Aug 22, 2021	Monthly Insp.		400.00	WO4553.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Replace ABS sensor.\r\n-Replace Dust shield.\r\n-Replace 1 1/2 super swivel.\r\n-Lube job.\r\n-check over.\r\n-raise governor to 120km/hr.	CAD	20703.0	755127.0
Aug 22, 2021	Electrical Wiring Repair		400.00	WO4553.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Replace ABS sensor.\r\n-Replace Dust shield.\r\n-Replace 1 1/2 super swivel.\r\n-Lube job.\r\n-check over.\r\n-raise governor to 120km/hr.	CAD	20703.0	755127.0
Aug 22, 2021	Oil Change		400.00	WO4553.\r\n-Monthly inspection.\r\n-Service oil, oil filter, fuel filters.\r\n-Replace ABS sensor.\r\n-Replace Dust shield.\r\n-Replace 1 1/2 super swivel.\r\n-Lube job.\r\n-check over.\r\n-raise governor to 120km/hr.	CAD	20703.0	755127.0
Sep 14, 2021	VIC SEAL		500.00	WO4572.\r\n-Remove plumbing from pump box.\r\n-Pressure test, clean and weld plumbing.\r\n-Replace 3" VIC seal.\r\n-Replace 3" valve.	CAD	20879.0	762517.0
Sep 14, 2021	Welding		500.00	WO4572.\r\n-Remove plumbing from pump box.\r\n-Pressure test, clean and weld plumbing.\r\n-Replace 3" VIC seal.\r\n-Replace 3" valve.	CAD	20879.0	762517.0
Sep 14, 2021	Valve replacement		500.00	WO4572.\r\n-Remove plumbing from pump box.\r\n-Pressure test, clean and weld plumbing.\r\n-Replace 3" VIC seal.\r\n-Replace 3" valve.	CAD	20879.0	762517.0
Sep 16, 2021	Replace Hydraulic Fluid		1500.00	WO4576.\r\n-Replace PTO.\r\n-Replace hydraulic pump.\r\n-Replace fittings.\r\n-Replace transmission fluid.\r\n-Replace hydraulic fluid.	CAD	20889.0	762842.0
Sep 16, 2021	PTO Replacement		1500.00	WO4576.\r\n-Replace PTO.\r\n-Replace hydraulic pump.\r\n-Replace fittings.\r\n-Replace transmission fluid.\r\n-Replace hydraulic fluid.	CAD	20889.0	762842.0
Sep 16, 2021	Hydraulics Repair		1500.00	WO4576.\r\n-Replace PTO.\r\n-Replace hydraulic pump.\r\n-Replace fittings.\r\n-Replace transmission fluid.\r\n-Replace hydraulic fluid.	CAD	20889.0	762842.0
Sep 16, 2021	Transmission Fluid Replacement		1500.00	WO4576.\r\n-Replace PTO.\r\n-Replace hydraulic pump.\r\n-Replace fittings.\r\n-Replace transmission fluid.\r\n-Replace hydraulic fluid.	CAD	20889.0	762842.0
Oct 19, 2021	Hydraulics Repair		3000.00	WO4609.\r\n-Replace Hydraulic cooler.\r\n-Replace Hydraulic T&E motor.\r\n-Replace all hydraulic hoses and connectors.\r\n-Replace hydraulic oil.\r\n-Replace convex mirror LH side.\r\n-Re-Shim T&E pump (75% life left).\r\n-Function / pressure test.	CAD	21157.0	771555.0
Oct 19, 2021	T&E Pump Repair		3000.00	WO4609.\r\n-Replace Hydraulic cooler.\r\n-Replace Hydraulic T&E motor.\r\n-Replace all hydraulic hoses and connectors.\r\n-Replace hydraulic oil.\r\n-Replace convex mirror LH side.\r\n-Re-Shim T&E pump (75% life left).\r\n-Function / pressure test.	CAD	21157.0	771555.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Nov 15, 2021	Monthly Insp.		500.00	WO4424.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter, fuel filters, grease undercarriage, T&E pump.\r\n-Remove axle #1 RH wheel, replace wheel hub seal, axle hub seal. add 75w90.\r\n-Torque axle #1 RH wheel 500lbs.\r\n-Repair hydraulic line @ T&E pump motor.	CAD	21333.0	778176.0
Nov 15, 2021	Hydraulics Repair		500.00	WO4424.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter, fuel filters, grease undercarriage, T&E pump.\r\n-Remove axle #1 RH wheel, replace wheel hub seal, axle hub seal. add 75w90.\r\n-Torque axle #1 RH wheel 500lbs.\r\n-Repair hydraulic line @ T&E pump motor.	CAD	21333.0	778176.0
Nov 15, 2021	Front Wheel Hub Gasket Replacement (P/S)		500.00	WO4424.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter, fuel filters, grease undercarriage, T&E pump.\r\n-Remove axle #1 RH wheel, replace wheel hub seal, axle hub seal. add 75w90.\r\n-Torque axle #1 RH wheel 500lbs.\r\n-Repair hydraulic line @ T&E pump motor.	CAD	21333.0	778176.0
Nov 15, 2021	Oil Pump Replacement		500.00	WO4424.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter, fuel filters, grease undercarriage, T&E pump.\r\n-Remove axle #1 RH wheel, replace wheel hub seal, axle hub seal. add 75w90.\r\n-Torque axle #1 RH wheel 500lbs.\r\n-Repair hydraulic line @ T&E pump motor.	CAD	21333.0	778176.0
Nov 17, 2021	TOOL BOX / FITTINGS INVENTORY		420.00	WO# 4633 - UNIT 58\r\nCHECK OVER, REPLACE HYD HOSE FROM BANK TO TE,\r\nREPLACE MISSING CAP PORT ON SIDE OF ENGINE, 2 INCH MM CAP,\r\n	CAD	21361.0	778720.0
Nov 17, 2021	Hydraulics Repair		420.00	WO# 4633 - UNIT 58\r\nCHECK OVER, REPLACE HYD HOSE FROM BANK TO TE,\r\nREPLACE MISSING CAP PORT ON SIDE OF ENGINE, 2 INCH MM CAP,\r\n	CAD	21361.0	778720.0
Nov 17, 2021	Other Maintenance		420.00	WO# 4633 - UNIT 58\r\nCHECK OVER, REPLACE HYD HOSE FROM BANK TO TE,\r\nREPLACE MISSING CAP PORT ON SIDE OF ENGINE, 2 INCH MM CAP,\r\n	CAD	21361.0	778720.0
Jan 16, 2022	Service		200.00	SERVICE OIL, OIL FILTER, 2 FUEL FILTER\r\nLUBE JOB\r\nMONTHLY INSPECTION\r\nTROUBLESHOOT ABS\r\nREPAIR WARNING\r\nTOP UP FLUIDS\r\nCHECK OIL LEVEL\r\nREPLACE 5 WORK LIGHTS	CAD	21915.0	796337.0
Jan 16, 2022	ABS Repair		200.00	SERVICE OIL, OIL FILTER, 2 FUEL FILTER\r\nLUBE JOB\r\nMONTHLY INSPECTION\r\nTROUBLESHOOT ABS\r\nREPAIR WARNING\r\nTOP UP FLUIDS\r\nCHECK OIL LEVEL\r\nREPLACE 5 WORK LIGHTS	CAD	21915.0	796337.0
Jan 16, 2022	Monthly Insp.		200.00	SERVICE OIL, OIL FILTER, 2 FUEL FILTER\r\nLUBE JOB\r\nMONTHLY INSPECTION\r\nTROUBLESHOOT ABS\r\nREPAIR WARNING\r\nTOP UP FLUIDS\r\nCHECK OIL LEVEL\r\nREPLACE 5 WORK LIGHTS	CAD	21915.0	796337.0
Jan 19, 2022	Service Call		1100.00	WO# 5885 - UNIT 58\r\nSERVICE CALL, TEST BATTERY,AND ALT,\r\nREPLACE ALT WIRE, AND BATTERY	CAD	21938.0	797421.0
Jan 19, 2022	Battery Replacement		1100.00	WO# 5885 - UNIT 58\r\nSERVICE CALL, TEST BATTERY,AND ALT,\r\nREPLACE ALT WIRE, AND BATTERY	CAD	21938.0	797421.0
Jan 19, 2022	Other Maintenance		1100.00	WO# 5885 - UNIT 58\r\nSERVICE CALL, TEST BATTERY,AND ALT,\r\nREPLACE ALT WIRE, AND BATTERY	CAD	21938.0	797421.0
Jan 19, 2022	Alternator Replacement		1100.00	WO# 5885 - UNIT 58\r\nSERVICE CALL, TEST BATTERY,AND ALT,\r\nREPLACE ALT WIRE, AND BATTERY	CAD	21938.0	797421.0
Feb 3, 2022	Air system repair		380.00	WO# 5271 - UNIT 58\r\nDIAGNOSS AIR ISSUES, REPLACE AIR DRYER	CAD	22109.0	802089.0
Feb 16, 2022	Rear Axle Seal Replacement		600.00	WO5281.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter.\r\n-Grease unit.\r\n-Repair stereo antenna cable.\r\n-Replace axle 2 RH side axle hub gasket.\r\n-Repair wiring @ RH side marker light middle.\r\n-Windshield replaced by Crystal Glass.\r\n	CAD	22202.0	805530.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Feb 16, 2022	Monthly Insp.		600.00	WO5281.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter.\r\n-Grease unit.\r\n-Repair stereo antenna cable.\r\n-Replace axle 2 RH side axle hub gasket.\r\n-Repair wiring @ RH side marker light middle.\r\n-Windshield replaced by Crystal Glass.\r\n	CAD	22202.0	805530.0
Feb 16, 2022	Grease Unit		600.00	WO5281.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter.\r\n-Grease unit.\r\n-Repair stereo antenna cable.\r\n-Replace axle 2 RH side axle hub gasket.\r\n-Repair wiring @ RH side marker light middle.\r\n-Windshield replaced by Crystal Glass.\r\n	CAD	22202.0	805530.0
Feb 16, 2022	Electrical Wiring Repair		600.00	WO5281.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter.\r\n-Grease unit.\r\n-Repair stereo antenna cable.\r\n-Replace axle 2 RH side axle hub gasket.\r\n-Repair wiring @ RH side marker light middle.\r\n-Windshield replaced by Crystal Glass.\r\n	CAD	22202.0	805530.0
Feb 16, 2022	Marker Light Replacement		600.00	WO5281.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter.\r\n-Grease unit.\r\n-Repair stereo antenna cable.\r\n-Replace axle 2 RH side axle hub gasket.\r\n-Repair wiring @ RH side marker light middle.\r\n-Windshield replaced by Crystal Glass.\r\n	CAD	22202.0	805530.0
Feb 16, 2022	Windshield Replacement		600.00	WO5281.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter.\r\n-Grease unit.\r\n-Repair stereo antenna cable.\r\n-Replace axle 2 RH side axle hub gasket.\r\n-Repair wiring @ RH side marker light middle.\r\n-Windshield replaced by Crystal Glass.\r\n	CAD	22202.0	805530.0
Feb 16, 2022	Oil Change		600.00	WO5281.\r\n-Monthly inspection complete.\r\n-Service oil, oil filter.\r\n-Grease unit.\r\n-Repair stereo antenna cable.\r\n-Replace axle 2 RH side axle hub gasket.\r\n-Repair wiring @ RH side marker light middle.\r\n-Windshield replaced by Crystal Glass.\r\n	CAD	22202.0	805530.0
Mar 5, 2022	PT - Leakage TK insp. (K)		600.00	wo 5346-54\r\ntank tests V,K,T.	CAD	22330.0	806225.0
Mar 5, 2022	PT - External TK insp. (V)		600.00	wo 5346-54\r\ntank tests V,K,T.	CAD	22330.0	806225.0
Mar 5, 2022	Tank Inspection		600.00	wo 5346-54\r\ntank tests V,K,T.	CAD	22330.0	806225.0
Mar 14, 2022	Tire Chains		1000.00	wo 5732-58\r\nreplace 3 windshields\r\nreplaced tire chains	CAD	22433.0	811900.0
Mar 14, 2022	Windshield Replacement		1000.00	wo 5732-58\r\nreplace 3 windshields\r\nreplaced tire chains	CAD	22433.0	811900.0
Apr 19, 2022	Adjust Clutch Linkage		550.00	wo 5356\r\nreplaced clutch brake \r\nadjusted clutch\r\nrepaired clutch linkages \r\ntightened leaking coolant lines	CAD	22656.0	821364.0
Apr 19, 2022	Replace Clutch Brake Disc		550.00	wo 5356\r\nreplaced clutch brake \r\nadjusted clutch\r\nrepaired clutch linkages \r\ntightened leaking coolant lines	CAD	22656.0	821364.0
Apr 19, 2022	Coolant System Repair		550.00	wo 5356\r\nreplaced clutch brake \r\nadjusted clutch\r\nrepaired clutch linkages \r\ntightened leaking coolant lines	CAD	22656.0	821364.0
May 9, 2022	Service		52000.00	wo 5366\r\nrebuild engine \r\nperformed cvip checks and repairs \r\nsteer tires replaced \r\n1/r1 wheel seals \r\n1/r1 brake drums replaced \r\n3 slack adjuster replaced \r\n3 u-bolts tightened and torqued \r\nall front spring pins and bushings replaced \r\nadjusted all brakes \r\ntorqued all wheels to 500 ft lbs \r\ninstalled new muffler in exhaust \r\nreplaced engine belts \r\nreplaced battery disconnects	CAD	22690.0	822455.0
May 9, 2022	ENGINE REPAIR		52000.00	wo 5366\r\nrebuild engine \r\nperformed cvip checks and repairs \r\nsteer tires replaced \r\n1/r1 wheel seals \r\n1/r1 brake drums replaced \r\n3 slack adjuster replaced \r\n3 u-bolts tightened and torqued \r\nall front spring pins and bushings replaced \r\nadjusted all brakes \r\ntorqued all wheels to 500 ft lbs \r\ninstalled new muffler in exhaust \r\nreplaced engine belts \r\nreplaced battery disconnects	CAD	22690.0	822455.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
May 9, 2022	Monthly Insp.		52000.00	wo 5366rebuild engine performvmd cvip checks and repairs steer tires replaced wheel seals brake drums replaced slack adjuster replaced u-bolts tightened and torqued front spring pins and bushings replaced adjusted all brakes torqued all wheels to 500 ft lbs installed new muffler in exhaust replaced engine belts replaced battery disconnects	CAD	22690.0	822455.0
May 9, 2022	Annual CVIP		52000.00	wo 5366rebuild engine performvmd cvip checks and repairs steer tires replaced wheel seals brake drums replaced slack adjuster replaced u-bolts tightened and torqued front spring pins and bushings replaced adjusted all brakes torqued all wheels to 500 ft lbs installed new muffler in exhaust replaced engine belts replaced battery disconnects	CAD	22690.0	822455.0
May 9, 2022	Tire Replacement		52000.00	wo 5366rebuild engine performvmd cvip checks and repairs steer tires replaced wheel seals brake drums replaced slack adjuster replaced u-bolts tightened and torqued front spring pins and bushings replaced adjusted all brakes torqued all wheels to 500 ft lbs installed new muffler in exhaust replaced engine belts replaced battery disconnects	CAD	22690.0	822455.0
May 9, 2022	Oil Change		52000.00	wo 5366rebuild engine performvmd cvip checks and repairs steer tires replaced wheel seals brake drums replaced slack adjuster replaced u-bolts tightened and torqued front spring pins and bushings replaced adjusted all brakes torqued all wheels to 500 ft lbs installed new muffler in exhaust replaced engine belts replaced battery disconnects	CAD	22690.0	822455.0
May 12, 2022	Tail Lamp Replacement		2700.00	wo 5663replaced cab shocksreplaced all dot tape retorque wheelsrepair warning and marker lampsreplaced tractor protection valve repaired hood	CAD	22715.0	823260.0
May 12, 2022	Shock Absorber Replacement		2700.00	wo 5663replaced cab shocksreplaced all dot tape retorque wheelsrepair warning and marker lampsreplaced tractor protection valve repaired hood	CAD	22715.0	823260.0
May 12, 2022	Coolant System Repair		2700.00	wo 5663replaced cab shocksreplaced all dot tape retorque wheelsrepair warning and marker lampsreplaced tractor protection valve repaired hood	CAD	22715.0	823260.0
May 12, 2022	Torque Wheels		2700.00	wo 5663replaced cab shocksreplaced all dot tape retorque wheelsrepair warning and marker lampsreplaced tractor protection valve repaired hood	CAD	22715.0	823260.0
May 12, 2022	Other Maintenance		2700.00	wo 5663replaced cab shocksreplaced all dot tape retorque wheelsrepair warning and marker lampsreplaced tractor protection valve repaired hood	CAD	22715.0	823260.0
Jun 6, 2022	Service		1725.00	wo 5674monthly inspection noil and filter change fuel filter change grease and check over replaced dust shield l2 r4 replaced 2 vic seals in pump box computer diagnostics replaced fuel rail relief valve repair wiring to coolant level sensor replaced power steering hose top up fluid	CAD	22871.0	825779.0
Jun 6, 2022	VIC SEAL		1725.00	wo 5674monthly inspection noil and filter change fuel filter change grease and check over replaced dust shield l2 r4 replaced 2 vic seals in pump box computer diagnostics replaced fuel rail relief valve repair wiring to coolant level sensor replaced power steering hose top up fluid	CAD	22871.0	825779.0
Jun 6, 2022	Dust Shield Replacement		1725.00	wo 5674monthly inspection noil and filter change fuel filter change grease and check over replaced dust shield l2 r4 replaced 2 vic seals in pump box computer diagnostics replaced fuel rail relief valve repair wiring to coolant level sensor replaced power steering hose top up fluid	CAD	22871.0	825779.0
Jun 6, 2022	ENGINE DIAGNOSTICS		1725.00	wo 5674monthly inspection noil and filter change fuel filter change grease and check over replaced dust shield l2 r4 replaced 2 vic seals in pump box computer diagnostics replaced fuel rail relief valve repair wiring to coolant level sensor replaced power steering hose top up fluid	CAD	22871.0	825779.0
Jun 6, 2022	Monthly Insp.		1725.00	wo 5674monthly inspection noil and filter change fuel filter change grease and check over replaced dust shield l2 r4 replaced 2 vic seals in pump box computer diagnostics replaced fuel rail relief valve repair wiring to coolant level sensor replaced power steering hose top up fluid	CAD	22871.0	825779.0
Jun 6, 2022	Electrical Wiring Repair		1725.00	wo 5674monthly inspection noil and filter change fuel filter change grease and check over replaced dust shield l2 r4 replaced 2 vic seals in pump box computer diagnostics replaced fuel rail relief valve repair wiring to coolant level sensor replaced power steering hose top up fluid	CAD	22871.0	825779.0
Jun 6, 2022	Power Steering Hose Replacement		1725.00	wo 5674monthly inspection noil and filter change fuel filter change grease and check over replaced dust shield l2 r4 replaced 2 vic seals in pump box computer diagnostics replaced fuel rail relief valve repair wiring to coolant level sensor replaced power steering hose top up fluid	CAD	22871.0	825779.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Jun 6, 2022	Oil Change		1725.00	wo 5674\nmonthly inspection \noil and filter change \nfuel filter change \ngrease and check over \nreplaced dust shield l2 r4 \nreplaced 2 vic seals in pump box \ncomputer diagnostics \nreplaced fuel rail relief valve \nrepair wiring to coolant level sensor \nreplaced power steering hose \ntop up fluid	CAD	22871.0	825779.0
Jul 24, 2022	Monthly Insp.		300.00	wo 5433\noil and filter change \ngreased and checked over \nchecked transmission for shifting issues	CAD	23248.0	843031.0
Jul 24, 2022	Oil Change		300.00	wo 5433\noil and filter change \ngreased and checked over \nchecked transmission for shifting issues	CAD	23248.0	843031.0
Aug 10, 2022	Valve replacement		40.00	wo 5553\nreplaced 4" keystone teflon valve in pump box	CAD	23392.0	849032.0
Aug 18, 2022	Tire Replacement		40.00	wo 5559\n tires replaced axle 4 and torqued to 500 ft-lbs	CAD	23470.0	852266.0
Aug 19, 2022	Rear Differential Repair		80.00	wo 5448\nreplaced pinion seal diff 3	CAD	23477.0	852632.0
Aug 24, 2022	Dust Shield Replacement		350.00	wo 5460 \noil and filter change \nfuel filters changed \nchecked air filter \nchecked all fluids \ngreased unit \ncomplete check over \nreplaced dust shield R/S steer	CAD	23533.0	854467.0
Aug 24, 2022	Monthly Insp.		350.00	wo 5460 \noil and filter change \nfuel filters changed \nchecked air filter \nchecked all fluids \ngreased unit \ncomplete check over \nreplaced dust shield R/S steer	CAD	23533.0	854467.0
Aug 24, 2022	Oil Change		350.00	wo 5460 \noil and filter change \nfuel filters changed \nchecked air filter \nchecked all fluids \ngreased unit \ncomplete check over \nreplaced dust shield R/S steer	CAD	23533.0	854467.0
Aug 30, 2022	Rear P/S Diff, Axle outer seal		100.00	wo 5569\nreplaced axle seal 2R \ntop up with 75w90 \ntorque axle nuts	CAD	23568.0	855365.0
Sep 1, 2022	Other Maintenance		150.00	WO#5469\n-replace Axle 4 LH wheel seal	CAD	23589.0	856309.0
Sep 4, 2022	Starter Replacement		1200.00	WO#5472\nSTARTER REPLACED	CAD	23610.0	856831.0
Sep 28, 2022	Replace T&E pump.		5000.00	WO#5494\nOIL CHANGE, SERVICE, MONTHLY INSP, FUEL FILTER CHANGE (X2), GREASED, REPLACED T&E	CAD	23816.0	862959.0
Sep 28, 2022	Service		5000.00	WO#5494\nOIL CHANGE, SERVICE, MONTHLY INSP, FUEL FILTER CHANGE (X2), GREASED, REPLACED T&E	CAD	23816.0	862959.0
Sep 28, 2022	Top up fluids		5000.00	WO#5494\nOIL CHANGE, SERVICE, MONTHLY INSP, FUEL FILTER CHANGE (X2), GREASED, REPLACED T&E	CAD	23816.0	862959.0
Sep 28, 2022	Monthly Insp.		5000.00	WO#5494\nOIL CHANGE, SERVICE, MONTHLY INSP, FUEL FILTER CHANGE (X2), GREASED, REPLACED T&E	CAD	23816.0	862959.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Sep 28, 2022	Fuel Filter Replacement		5000.00	WO#5494\r\nOIL CHANGE, SERVICE, MONTHLY INSP, FUEL FILTER CHANGE (X2), GREASED, REPLACED T&E	CAD	23816.0	862959.0
Sep 28, 2022	Grease Unit		5000.00	WO#5494\r\nOIL CHANGE, SERVICE, MONTHLY INSP, FUEL FILTER CHANGE (X2), GREASED, REPLACED T&E	CAD	23816.0	862959.0
Sep 28, 2022	Oil Change		5000.00	WO#5494\r\nOIL CHANGE, SERVICE, MONTHLY INSP, FUEL FILTER CHANGE (X2), GREASED, REPLACED T&E	CAD	23816.0	862959.0
Oct 7, 2022	Valve replacement		380.00	WO#5499\r\n- REPLACED 3" KEYSTONE BYPASS VALVE	CAD	23883.0	865438.0
Oct 17, 2022	Pressure Test / Inspect Hose		300.00	WO#4013\r\nPRESSURE TEST AND INSPECT ALL HOSES, WHEEL SEAL R4, ADJUST BRAKES, TORQUE WHEEL	CAD	23958.0	868224.0
Oct 17, 2022	Adjust Brakes		300.00	WO#4013\r\nPRESSURE TEST AND INSPECT ALL HOSES, WHEEL SEAL R4, ADJUST BRAKES, TORQUE WHEEL	CAD	23958.0	868224.0
Oct 17, 2022	Torque Wheels		300.00	WO#4013\r\nPRESSURE TEST AND INSPECT ALL HOSES, WHEEL SEAL R4, ADJUST BRAKES, TORQUE WHEEL	CAD	23958.0	868224.0
Oct 17, 2022	Other Maintenance		300.00	WO#4013\r\nPRESSURE TEST AND INSPECT ALL HOSES, WHEEL SEAL R4, ADJUST BRAKES, TORQUE WHEEL	CAD	23958.0	868224.0
Nov 3, 2022	Electrical Wiring Repair		150.00	WO#5523\r\n-repair wiring to hose reel and install switch	CAD	24095.0	873411.0
Nov 12, 2022	Service		550.00	WO#4459\r\nOil Change, Service, Grease Unit, repair air leaks, repair coolant leaks, replaced inside Axle4 PS tire with take-off	CAD	24201.0	876305.0
Nov 12, 2022	Coolant System Repair		550.00	WO#4459\r\nOil Change, Service, Grease Unit, repair air leaks, repair coolant leaks, replaced inside Axle4 PS tire with take-off	CAD	24201.0	876305.0
Nov 12, 2022	Air system repair		550.00	WO#4459\r\nOil Change, Service, Grease Unit, repair air leaks, repair coolant leaks, replaced inside Axle4 PS tire with take-off	CAD	24201.0	876305.0
Nov 12, 2022	Monthly Insp.		550.00	WO#4459\r\nOil Change, Service, Grease Unit, repair air leaks, repair coolant leaks, replaced inside Axle4 PS tire with take-off	CAD	24201.0	876305.0
Nov 12, 2022	Fuel Filter Replacement		550.00	WO#4459\r\nOil Change, Service, Grease Unit, repair air leaks, repair coolant leaks, replaced inside Axle4 PS tire with take-off	CAD	24201.0	876305.0
Nov 12, 2022	Grease Unit		550.00	WO#4459\r\nOil Change, Service, Grease Unit, repair air leaks, repair coolant leaks, replaced inside Axle4 PS tire with take-off	CAD	24201.0	876305.0
Nov 12, 2022	Tire Replacement		550.00	WO#4459\r\nOil Change, Service, Grease Unit, repair air leaks, repair coolant leaks, replaced inside Axle4 PS tire with take-off	CAD	24201.0	876305.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Nov 12, 2022	Oil Change		550.00	WO#4459\r\nOil Change, Service, Grease Unit, repair air leaks, repair coolant leaks, replaced inside Axle4 PS tire with take-off	CAD	24201.0	876305.0
Nov 20, 2022	Air system repair		800.00	WO#5903\r\nReplaced air tank	CAD	24264.0	877999.0
Nov 23, 2022	Suspension Repair		300.00	WO#4473\r\nFixed coolant leak, tightened and adjusted valves in pump box, replaced spring hanger PS Axles 3 (used off 39)	CAD	24294.0	878413.0
Nov 23, 2022	Coolant System Repair		300.00	WO#4473\r\nFixed coolant leak, tightened and adjusted valves in pump box, replaced spring hanger PS Axles 3 (used off 39)	CAD	24294.0	878413.0
Nov 23, 2022	Valve replacement		300.00	WO#4473\r\nFixed coolant leak, tightened and adjusted valves in pump box, replaced spring hanger PS Axles 3 (used off 39)	CAD	24294.0	878413.0
Nov 30, 2022	Other Maintenance		90.00	WO#4482\r\nREPAIR CHAIN ON HOSE REEL	CAD	24297.0	878416.0
Dec 1, 2022	Electrical Wiring Repair		106.00	WO#5918\r\nREPAIR WIRING FOR HEATER, REPLACE HOSE REEL SWITCH	CAD	24397.0	880409.0
Dec 1, 2022	Other Maintenance		106.00	WO#5918\r\nREPAIR WIRING FOR HEATER, REPLACE HOSE REEL SWITCH	CAD	24397.0	880409.0
Dec 7, 2022	Air system repair		500.00	WO#5927\r\n-repair air leaks\r\n-replace fan belt / ac belt\r\n-fill air system methanol pot\r\n-order engine fan and steer u-joint	CAD	24489.0	882358.0
Dec 7, 2022	Engine/Drive Belt(s) Replacement		500.00	WO#5927\r\n-repair air leaks\r\n-replace fan belt / ac belt\r\n-fill air system methanol pot\r\n-order engine fan and steer u-joint	CAD	24489.0	882358.0
Dec 11, 2022	Service		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Exhaust System Repair		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Air Dryer Replacement		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Coolant System Repair		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Dust Shield Replacement		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Air system repair		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Dec 11, 2022	Monthly Insp.		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Fuel Filter Replacement		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Grease Unit		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Electrical Wiring Repair		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Marker Light Replacement		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Steering Column U-Joint Replacement		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Dec 11, 2022	Oil Change		2150.00	WO#5937\r\nmonthly Insp, wash, oil change, fuel filters (2), replace steering u-joint, replace air dryer, repair air leaks, replace engine fan, repair coolant leak, replace exhaust flex pipe, replace yoke and seal on axle 4, top up all fluids, replace couple marker lights, ordered windshield	CAD	24514.0	883036.0
Jan 9, 2023	Wheel Rim Replacement		1200.00	WO#5974\r\nreplaced axle 4 rims due to loose wheel nuts	CAD	24856.0	889180.0
Jan 9, 2023	Torque Wheels		1200.00	WO#5974\r\nreplaced axle 4 rims due to loose wheel nuts	CAD	24856.0	889180.0
Jan 21, 2023	Service		450.00	WO#4277\r\nmonthly, service, oil change, fuel filter change, grease	CAD	24968.0	889298.0
Jan 21, 2023	Monthly Insp.		450.00	WO#4277\r\nmonthly, service, oil change, fuel filter change, grease	CAD	24968.0	889298.0
Jan 21, 2023	Fuel Filter Replacement		450.00	WO#4277\r\nmonthly, service, oil change, fuel filter change, grease	CAD	24968.0	889298.0
Jan 21, 2023	Grease Unit		450.00	WO#4277\r\nmonthly, service, oil change, fuel filter change, grease	CAD	24968.0	889298.0
Jan 27, 2023	Clutch Replacement		9000.00	WO#5986\r\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0
Jan 27, 2023	Adjust Clutch Linkage		9000.00	WO#5986\r\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0
Jan 27, 2023	Coolant System Repair		9000.00	WO#5986\r\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Jan 27, 2023	Driveline Repair		9000.00	WO#5986\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0
Jan 27, 2023	Grease Unit		9000.00	WO#5986\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0
Jan 27, 2023	Front Engine Mount Bolt Replacement		9000.00	WO#5986\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0
Jan 27, 2023	Driveshaft U-Joint Replacement (front)		9000.00	WO#5986\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0
Jan 27, 2023	Transmission Replacement		9000.00	WO#5986\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0
Jan 27, 2023	Transmission Fluid Replacement		9000.00	WO#5986\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0
Jan 27, 2023	Oil Change		9000.00	WO#5986\nreplace transmission (2 year warranty),replace rear engine mounts, installed new rear main seal and housing gasket, refaced fly wheel, new clutch, replaced oil pan gasket, repair and rebalance drive line, replaced coolant line to transmission cooler,, replaced speed sensor, change engine oil, add transmission fluid to new transmission, greased unit	CAD	24993.0	893920.0
Feb 3, 2023	Other Maintenance		600.00	WO#5988\nreplaced wiper motor	CAD	25025.0	894864.0
Feb 9, 2023	Exhaust System Repair		250.00	WO#4293\nReplace exhaust clamps and repair PTO Wiring	CAD	25086.0	896672.0
Feb 9, 2023	Electrical Wiring Repair		250.00	WO#4293\nReplace exhaust clamps and repair PTO Wiring	CAD	25086.0	896672.0
Feb 19, 2023	Coolant System Repair		250.00	WO#5998\nReplace upper coolant hose, replace 2.5" lower rad hose	CAD	25153.0	898788.0
Feb 25, 2023	ABS Repair		450.00	WO#6065\nwash, monthly insp, oil change, grease, top up fluids, adjust ABS, replace 2 work lights	CAD	25253.0	900603.0
Feb 25, 2023	Monthly Insp.		450.00	WO#6065\nwash, monthly insp, oil change, grease, top up fluids, adjust ABS, replace 2 work lights	CAD	25253.0	900603.0
Feb 25, 2023	Fuel Filter Replacement		450.00	WO#6065\nwash, monthly insp, oil change, grease, top up fluids, adjust ABS, replace 2 work lights	CAD	25253.0	900603.0
Feb 25, 2023	Work Light Replacement		450.00	WO#6065\nwash, monthly insp, oil change, grease, top up fluids, adjust ABS, replace 2 work lights	CAD	25253.0	900603.0
Feb 25, 2023	Grease Unit		450.00	WO#6065\nwash, monthly insp, oil change, grease, top up fluids, adjust ABS, replace 2 work lights	CAD	25253.0	900603.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Feb 25, 2023	Oil Change		450.00	WO#6065\r\nwash, monthly insp, oil change, grease, top up fluids, adjust ABS, replace 2 work lights	CAD	25253.0	900603.0
Feb 25, 2023	Car Wash		450.00	WO#6065\r\nwash, monthly insp, oil change, grease, top up fluids, adjust ABS, replace 2 work lights	CAD	25253.0	900603.0
Mar 18, 2023	PT - Leakage TK insp. (K)		400.00	WO#6036\r\nVK Tank Tests	CAD	25446.0	907970.0
Mar 18, 2023	PT - External TK insp. (V)		400.00	WO#6036\r\nVK Tank Tests	CAD	25446.0	907970.0
Mar 27, 2023	Monthly Insp.		3100.00	WO#6046\r\nOil Change, monthly insp, fuel filters changed, repair hood, replaced PS convex mirror, replace battery disconnects, replaced windshield, new tires on axle 3	CAD	25507.0	909598.0
Mar 27, 2023	Fuel Filter Replacement		3100.00	WO#6046\r\nOil Change, monthly insp, fuel filters changed, repair hood, replaced PS convex mirror, replace battery disconnects, replaced windshield, new tires on axle 3	CAD	25507.0	909598.0
Mar 27, 2023	Windshield Replacement		3100.00	WO#6046\r\nOil Change, monthly insp, fuel filters changed, repair hood, replaced PS convex mirror, replace battery disconnects, replaced windshield, new tires on axle 3	CAD	25507.0	909598.0
Mar 27, 2023	Tire Replacement		3100.00	WO#6046\r\nOil Change, monthly insp, fuel filters changed, repair hood, replaced PS convex mirror, replace battery disconnects, replaced windshield, new tires on axle 3	CAD	25507.0	909598.0
Mar 27, 2023	Other Maintenance		3100.00	WO#6046\r\nOil Change, monthly insp, fuel filters changed, repair hood, replaced PS convex mirror, replace battery disconnects, replaced windshield, new tires on axle 3	CAD	25507.0	909598.0
Mar 27, 2023	Oil Change		3100.00	WO#6046\r\nOil Change, monthly insp, fuel filters changed, repair hood, replaced PS convex mirror, replace battery disconnects, replaced windshield, new tires on axle 3	CAD	25507.0	909598.0
Apr 8, 2023	Other Maintenance		2500.00	WO#6154\r\nWash, replace tensioner belt, order fan hub, new floor mats	CAD	25587.0	912513.0
Apr 8, 2023	Engine/Drive Belt(s) Replacement		2500.00	WO#6154\r\nWash, replace tensioner belt, order fan hub, new floor mats	CAD	25587.0	912513.0
Apr 8, 2023	Engine Belt Inspection		2500.00	WO#6154\r\nWash, replace tensioner belt, order fan hub, new floor mats	CAD	25587.0	912513.0
Apr 26, 2023	Transmission Repair		2100.00	WO#6170\r\nPull transmission, flush transmission (x2), replace transmission fluid, replace transmission ABox gasket, replace transmission cooler	CAD	25705.0	916368.0
Apr 26, 2023	Transmission Service		2100.00	WO#6170\r\nPull transmission, flush transmission (x2), replace transmission fluid, replace transmission ABox gasket, replace transmission cooler	CAD	25705.0	916368.0
Apr 26, 2023	Transmission Fluid Replacement		2100.00	WO#6170\r\nPull transmission, flush transmission (x2), replace transmission fluid, replace transmission ABox gasket, replace transmission cooler	CAD	25705.0	916368.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
May 1, 2023	A/C Recharge		1400.00	WO#6172\r\nReplace AC Comdensor, refill ac system	CAD	25719.0	917236.0
May 1, 2023	A/C Condenser Replacement		1400.00	WO#6172\r\nReplace AC Comdensor, refill ac system	CAD	25719.0	917236.0
May 20, 2023	Adjust Brakes		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Monthly Insp.		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Brake Drum Replacement		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Fuel Filter Replacement		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Grease Unit		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Annual CVIP		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Valve replacement		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Tire Replacement		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Other Maintenance		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Oil Change		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
May 20, 2023	Brake Inspection		5600.00	WO#6250\r\nAnnual CVIP, monthly insp, oil change, fuel filter change, grease unit, Replaced all drive axle brake drums, replaced R1 slack adjuster, replaced torque rod axle 4, replaced axle 1 rear spring pins and bushings, replaced 3" valve in pump box	CAD	25830.0	920707.0
Jun 7, 2023	Other Maintenance		1350.00	WO#6319\r\nChange fan hub and hood latch	CAD	25896.0	922884.0
Jul 8, 2023	Air system repair		2200.00	WO#6601\r\noil change, monthly, pintle hitch, air dryer purge valve,FL mudflap, right front air line to brake pot, Replace axle 4 tires	CAD	26145.0	932297.0
Jul 8, 2023	Monthly Insp.		2200.00	WO#6601\r\noil change, monthly, pintle hitch, air dryer purge valve,FL mudflap, right front air line to brake pot, Replace axle 4 tires	CAD	26145.0	932297.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Jul 8, 2023	Tire Replacement		2200.00	WO#6601\noil change, monthly, pintle hitch, air dryer purge valve,FL mudflap, right front air line to brake pot, Replace axle 4 tires	CAD	26145.0	932297.0
Jul 8, 2023	Other Maintenance		2200.00	WO#6601\noil change, monthly, pintle hitch, air dryer purge valve,FL mudflap, right front air line to brake pot, Replace axle 4 tires	CAD	26145.0	932297.0
Jul 8, 2023	Oil Change		2200.00	WO#6601\noil change, monthly, pintle hitch, air dryer purge valve,FL mudflap, right front air line to brake pot, Replace axle 4 tires	CAD	26145.0	932297.0
Jul 18, 2023	VIC SEAL		90.00	WO#6610\nRepair plumbing leak on 2"	CAD	26222.0	935031.0
Jul 18, 2023	Welding		90.00	WO#6610\nRepair plumbing leak on 2"	CAD	26222.0	935031.0
Jul 18, 2023	Other Maintenance		90.00	WO#6610\nRepair plumbing leak on 2"	CAD	26222.0	935031.0
Jul 26, 2023	PTO Replacement		1960.00	WO#6618\nReplaced PTO	CAD	26288.0	937443.0
Aug 16, 2023	Monthly Insp.		300.00	WO#6629\nOil change, monthly insp, fuel filters changed, greased	CAD	26411.0	942354.0
Aug 16, 2023	Fuel Filter Replacement		300.00	WO#6629\nOil change, monthly insp, fuel filters changed, greased	CAD	26411.0	942354.0
Aug 16, 2023	Grease Unit		300.00	WO#6629\nOil change, monthly insp, fuel filters changed, greased	CAD	26411.0	942354.0
Aug 16, 2023	Oil Change		300.00	WO#6629\nOil change, monthly insp, fuel filters changed, greased	CAD	26411.0	942354.0
Aug 28, 2023	Service Call		250.00	WO#6421\nService call, repair air fitting on brake pot	CAD	26526.0	946487.0
Aug 28, 2023	Air system repair		250.00	WO#6421\nService call, repair air fitting on brake pot	CAD	26526.0	946487.0
Sep 14, 2023	Replace Clutch Brake Disc		750.00	WO#6355\noil change, fuel filters changed, grease unit, adjusted brakes, change clutch brake, repair coolant hose, repaired wiring left front signal light	CAD	26659.0	952144.0
Sep 14, 2023	Coolant System Repair		750.00	WO#6355\noil change, fuel filters changed, grease unit, adjusted brakes, change clutch brake, repair coolant hose, repaired wiring left front signal light	CAD	26659.0	952144.0
Sep 14, 2023	Adjust Brakes		750.00	WO#6355\noil change, fuel filters changed, grease unit, adjusted brakes, change clutch brake, repair coolant hose, repaired wiring left front signal light	CAD	26659.0	952144.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Sep 14, 2023	Monthly Insp.		750.00	WO#6355\r\noil change, fuel filters changed, grease unit, adjusted brakes, change clutch brake, repair coolant hose, repaired wiring left front signal light	CAD	26659.0	952144.0
Sep 14, 2023	Fuel Filter Replacement		750.00	WO#6355\r\noil change, fuel filters changed, grease unit, adjusted brakes, change clutch brake, repair coolant hose, repaired wiring left front signal light	CAD	26659.0	952144.0
Sep 14, 2023	Grease Unit		750.00	WO#6355\r\noil change, fuel filters changed, grease unit, adjusted brakes, change clutch brake, repair coolant hose, repaired wiring left front signal light	CAD	26659.0	952144.0
Sep 14, 2023	Electrical Wiring Repair		750.00	WO#6355\r\noil change, fuel filters changed, grease unit, adjusted brakes, change clutch brake, repair coolant hose, repaired wiring left front signal light	CAD	26659.0	952144.0
Sep 14, 2023	Oil Change		750.00	WO#6355\r\noil change, fuel filters changed, grease unit, adjusted brakes, change clutch brake, repair coolant hose, repaired wiring left front signal light	CAD	26659.0	952144.0
Oct 12, 2023	Windshield Replacement		600.00	WO#6477	CAD	26840.0	960749.0
Oct 22, 2023	ABS Repair		450.00	WO#6490\r\nmonthly, full service, grease, repair abs sensor	CAD	26911.0	963297.0
Oct 22, 2023	Monthly Insp.		450.00	WO#6490\r\nmonthly, full service, grease, repair abs sensor	CAD	26911.0	963297.0
Oct 22, 2023	Fuel Filter Replacement		450.00	WO#6490\r\nmonthly, full service, grease, repair abs sensor	CAD	26911.0	963297.0
Oct 22, 2023	Grease Unit		450.00	WO#6490\r\nmonthly, full service, grease, repair abs sensor	CAD	26911.0	963297.0
Oct 22, 2023	Oil Change		450.00	WO#6490\r\nmonthly, full service, grease, repair abs sensor	CAD	26911.0	963297.0
Oct 24, 2023	ABS Repair		5700.00	WO#6496\r\nReplaced ABS Sensor Axle 4 RH, Replace dustshield Axle 3 LH, Replace driveline Axle 3-4, Replace methanol pot, replaced air dryer, replaced governor valve, install air tank drain valve, replace shocks axle 3	CAD	26931.0	963791.0
Oct 24, 2023	Shock Absorber Replacement		5700.00	WO#6496\r\nReplaced ABS Sensor Axle 4 RH, Replace dustshield Axle 3 LH, Replace driveline Axle 3-4, Replace methanol pot, replaced air dryer, replaced governor valve, install air tank drain valve, replace shocks axle 3	CAD	26931.0	963791.0
Oct 24, 2023	Air Dryer Replacement		5700.00	WO#6496\r\nReplaced ABS Sensor Axle 4 RH, Replace dustshield Axle 3 LH, Replace driveline Axle 3-4, Replace methanol pot, replaced air dryer, replaced governor valve, install air tank drain valve, replace shocks axle 3	CAD	26931.0	963791.0
Oct 24, 2023	Dust Shield Replacement		5700.00	WO#6496\r\nReplaced ABS Sensor Axle 4 RH, Replace dustshield Axle 3 LH, Replace driveline Axle 3-4, Replace methanol pot, replaced air dryer, replaced governor valve, install air tank drain valve, replace shocks axle 3	CAD	26931.0	963791.0
Oct 24, 2023	Air system repair		5700.00	WO#6496\r\nReplaced ABS Sensor Axle 4 RH, Replace dustshield Axle 3 LH, Replace driveline Axle 3-4, Replace methanol pot, replaced air dryer, replaced governor valve, install air tank drain valve, replace shocks axle 3	CAD	26931.0	963791.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Oct 24, 2023	Driveline Repair		5700.00	WO#6496\r\nReplaced ABS Sensor Axle 4 RH, Replace dustshield Axle 3 LH, Replace driveline Axle 3-4, Replace methanol pot, replaced air dryer, replaced governor valve, install air tank drain valve, replace shocks axle 3	CAD	26931.0	963791.0
Oct 24, 2023	Car Wash		5700.00	WO#6496\r\nReplaced ABS Sensor Axle 4 RH, Replace dustshield Axle 3 LH, Replace driveline Axle 3-4, Replace methanol pot, replaced air dryer, replaced governor valve, install air tank drain valve, replace shocks axle 3	CAD	26931.0	963791.0
Oct 30, 2023	Windshield Replacement		650.00	WO#6497	CAD	26970.0	966045.0
Nov 13, 2023	Pressure Test / Inspect Hose		100.00	WO#6553	CAD	27093.0	970875.0
Nov 18, 2023	Exhaust System Repair		650.00	WO#6524\r\nfull service, monthly, grease, marker lamps (8), repair wiring, 2 worklights,replace exhaust clamps	CAD	27139.0	972277.0
Nov 18, 2023	Monthly Insp.		650.00	WO#6524\r\nfull service, monthly, grease, marker lamps (8), repair wiring, 2 worklights,replace exhaust clamps	CAD	27139.0	972277.0
Nov 18, 2023	Fuel Filter Replacement		650.00	WO#6524\r\nfull service, monthly, grease, marker lamps (8), repair wiring, 2 worklights,replace exhaust clamps	CAD	27139.0	972277.0
Nov 18, 2023	Electrical Wiring Repair		650.00	WO#6524\r\nfull service, monthly, grease, marker lamps (8), repair wiring, 2 worklights,replace exhaust clamps	CAD	27139.0	972277.0
Nov 18, 2023	Power Steering Pump Replacement		650.00	WO#6524\r\nfull service, monthly, grease, marker lamps (8), repair wiring, 2 worklights,replace exhaust clamps	CAD	27139.0	972277.0
Nov 18, 2023	Oil Change		650.00	WO#6524\r\nfull service, monthly, grease, marker lamps (8), repair wiring, 2 worklights,replace exhaust clamps	CAD	27139.0	972277.0
Nov 18, 2023	A/C Compressor Replacement		650.00	WO#6524\r\nfull service, monthly, grease, marker lamps (8), repair wiring, 2 worklights,replace exhaust clamps	CAD	27139.0	972277.0
Dec 5, 2023	Air system repair		125.00	repair air leaks	CAD	27242.0	975872.0
Dec 11, 2023	Replace Worklight(s)		200.00	PS convex mirror replaced, worklight PS on cab, replaced ps front tank hold down bolt	CAD	27290.0	977454.0
Dec 11, 2023	Other Maintenance		200.00	PS convex mirror replaced, worklight PS on cab, replaced ps front tank hold down bolt	CAD	27290.0	977454.0
Jan 5, 2024	Coolant System Repair		450.00	Full Service, greased, monthly, top up fluids	CAD	27465.0	983081.0
Jan 5, 2024	Top up fluids		450.00	Full Service, greased, monthly, top up fluids	CAD	27465.0	983081.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Jan 5, 2024	Monthly Insp.		450.00	Full Service, greased, monthly, top up fluids	CAD	27465.0	983081.0
Jan 5, 2024	Fuel Filter Replacement		450.00	Full Service, greased, monthly, top up fluids	CAD	27465.0	983081.0
Jan 5, 2024	Grease Unit		450.00	Full Service, greased, monthly, top up fluids	CAD	27465.0	983081.0
Jan 5, 2024	Oil Change		450.00	Full Service, greased, monthly, top up fluids	CAD	27465.0	983081.0
Jan 11, 2024	Air Dryer Replacement		2000.00	Service call, air pot frozen, removed frozen methanol pot, (Used 3rd party mechanic from Slave Lake area), replaced air dryer	CAD	27548.0	984733.0
Jan 11, 2024	Air system repair		2000.00	Service call, air pot frozen, removed frozen methanol pot, (Used 3rd party mechanic from Slave Lake area), replaced air dryer	CAD	27548.0	984733.0
Feb 10, 2024	Monthly Insp.		450.00	oil change, monthly, fuel filters, greased unit, repaired wiring to rear DS tail light	CAD	27793.0	994102.0
Feb 10, 2024	Fuel Filter Replacement		450.00	oil change, monthly, fuel filters, greased unit, repaired wiring to rear DS tail light	CAD	27793.0	994102.0
Feb 10, 2024	Grease Unit		450.00	oil change, monthly, fuel filters, greased unit, repaired wiring to rear DS tail light	CAD	27793.0	994102.0
Feb 10, 2024	Electrical Wiring Repair		450.00	oil change, monthly, fuel filters, greased unit, repaired wiring to rear DS tail light	CAD	27793.0	994102.0
Feb 10, 2024	Oil Change		450.00	oil change, monthly, fuel filters, greased unit, repaired wiring to rear DS tail light	CAD	27793.0	994102.0
Mar 11, 2024	TK Thickness Test		450.00	Tank Test VKT	CAD	28019.0	1003610.0
Mar 11, 2024	PT - Leakage TK insp. (K)		450.00	Tank Test VKT	CAD	28019.0	1003610.0
Mar 11, 2024	PT - External TK insp. (V)		450.00	Tank Test VKT	CAD	28019.0	1003610.0
Mar 24, 2024	Shock Absorber Replacement.		312.00	Replaced cab shocks, repair air leaks	CAD	28123.0	1007322.0
Mar 24, 2024	Air system repair		312.00	Replaced cab shocks, repair air leaks	CAD	28123.0	1007322.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Mar 26, 2024	Monthly Insp.		580.00	Monthly, oil change, fuel filters, greased, installed grease nipple on hose reel swivel (greased), replaced hi-beam light LH, replaced one work light	CAD	28137.0	1007691.0
Mar 26, 2024	Fuel Filter Replacement		580.00	Monthly, oil change, fuel filters, greased, installed grease nipple on hose reel swivel (greased), replaced hi-beam light LH, replaced one work light	CAD	28137.0	1007691.0
Mar 26, 2024	Work Light Replacement		580.00	Monthly, oil change, fuel filters, greased, installed grease nipple on hose reel swivel (greased), replaced hi-beam light LH, replaced one work light	CAD	28137.0	1007691.0
Mar 26, 2024	Grease Unit		580.00	Monthly, oil change, fuel filters, greased, installed grease nipple on hose reel swivel (greased), replaced hi-beam light LH, replaced one work light	CAD	28137.0	1007691.0
Mar 26, 2024	Headlamp Replacement		580.00	Monthly, oil change, fuel filters, greased, installed grease nipple on hose reel swivel (greased), replaced hi-beam light LH, replaced one work light	CAD	28137.0	1007691.0
Mar 26, 2024	Oil Change		580.00	Monthly, oil change, fuel filters, greased, installed grease nipple on hose reel swivel (greased), replaced hi-beam light LH, replaced one work light	CAD	28137.0	1007691.0
Apr 30, 2024	Replace T&E pump.		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	ABS Repair		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Suspension Repair		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Pressure Test / Inspect Hose		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Rebuild Super Swivel		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Adjust Brakes		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Brake Drum Replacement		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Annual CVIP		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Front Wheel Hub Gasket Replacement (D/S)		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Torque Wheels		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Apr 30, 2024	Tire Replacement		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Brake Pad(s) Replacement		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
Apr 30, 2024	Brake Inspection		17975.00	Annual CVIP, hose reel swivel rebuild, replace T&E pump, \nREPLACED\nR3 slack adjuster, all brake shoes and drums, all abs sensors, L1/L4 wheel seals, Axle2 lower torque rods, Axle2 upper torque rod shims, Axle2 spring wear plates, Axle2/3/4 tires, Axle2 brake valve.\n\n Adjusted all brakes, Torqued all wheels to 500ft/lbs, Hose test completed	CAD	28296.0	1013803.0
May 3, 2024	Retorque Wheels		100.00	Re-torque, install lug caps, replaced damaged air fitting on PTO	CAD	28303.0	1013956.0
May 3, 2024	Air system repair		100.00	Re-torque, install lug caps, replaced damaged air fitting on PTO	CAD	28303.0	1013956.0
May 17, 2024	Coolant System Repair		1100.00	Replaced coolant reservoir, replaced fan on bunk heater	CAD	28380.0	1016869.0
May 17, 2024	Heater Blower Motor Replacement		1100.00	Replaced coolant reservoir, replaced fan on bunk heater	CAD	28380.0	1016869.0
May 27, 2024	GPS REPAIR		1600.00	monthly, oil change, greased, fuel filter, repaired wiring, replaced PS marker lights, replace wipers, repair GPS	CAD	28422.0	1017851.0
May 27, 2024	Top up fluids		1600.00	monthly, oil change, greased, fuel filter, repaired wiring, replaced PS marker lights, replace wipers, repair GPS	CAD	28422.0	1017851.0
May 27, 2024	Monthly Insp.		1600.00	monthly, oil change, greased, fuel filter, repaired wiring, replaced PS marker lights, replace wipers, repair GPS	CAD	28422.0	1017851.0
May 27, 2024	Fuel Filter Replacement		1600.00	monthly, oil change, greased, fuel filter, repaired wiring, replaced PS marker lights, replace wipers, repair GPS	CAD	28422.0	1017851.0
May 27, 2024	Electrical Wiring Repair		1600.00	monthly, oil change, greased, fuel filter, repaired wiring, replaced PS marker lights, replace wipers, repair GPS	CAD	28422.0	1017851.0
May 27, 2024	Marker Light Replacement		1600.00	monthly, oil change, greased, fuel filter, repaired wiring, replaced PS marker lights, replace wipers, repair GPS	CAD	28422.0	1017851.0
May 27, 2024	Windshield Wiper(s) Replacement		1600.00	monthly, oil change, greased, fuel filter, repaired wiring, replaced PS marker lights, replace wipers, repair GPS	CAD	28422.0	1017851.0
May 27, 2024	Oil Change		1600.00	monthly, oil change, greased, fuel filter, repaired wiring, replaced PS marker lights, replace wipers, repair GPS	CAD	28422.0	1017851.0
Jun 26, 2024	ENGINE DIAGNOSTICS		150.00	DS front marker light out, check engine light on turbo inlet pressure showing(reset codes), fuel gauge acting up(ok)	CAD	28590.0	1023877.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Jun 26, 2024	Electrical Wiring Repair		150.00	DS front marker light out, check engine light on turbo inlet pressure showing(reset codes), fuel gauge acting up(ok)	CAD	28590.0	1023877.0
Jun 26, 2024	Marker Light Replacement		150.00	DS front marker light out, check engine light on turbo inlet pressure showing(reset codes), fuel gauge acting up(ok)	CAD	28590.0	1023877.0
Jul 10, 2024	Air system repair		1300.00	Repair L4 outside tire, replaced air tank	CAD	28669.0	1027491.0
Jul 10, 2024	Tire Service		1300.00	Repair L4 outside tire, replaced air tank	CAD	28669.0	1027491.0
Jul 20, 2024	Monthly Insp.		750.00	Oil change, monthly, fuel filter, greased, replace ball valve in pump box	CAD	28770.0	1030617.0
Jul 20, 2024	Fuel Filter Replacement		750.00	Oil change, monthly, fuel filter, greased, replace ball valve in pump box	CAD	28770.0	1030617.0
Jul 20, 2024	Grease Unit		750.00	Oil change, monthly, fuel filter, greased, replace ball valve in pump box	CAD	28770.0	1030617.0
Jul 20, 2024	Valve replacement		750.00	Oil change, monthly, fuel filter, greased, replace ball valve in pump box	CAD	28770.0	1030617.0
Jul 20, 2024	Oil Change		750.00	Oil change, monthly, fuel filter, greased, replace ball valve in pump box	CAD	28770.0	1030617.0
Aug 10, 2024	Replace Worklight(s)		260.00	repair worklight wiring and pigtails, repair junction box connections, replace back up lights	CAD	28883.0	1035014.0
Aug 10, 2024	Electrical Wiring Repair		260.00	repair worklight wiring and pigtails, repair junction box connections, replace back up lights	CAD	28883.0	1035014.0
Aug 21, 2024	Valve replacement		450.00	Replace 3" teflon valve in pump box	CAD	28936.0	1036804.0
Sep 6, 2024	Air system repair		500.00	Service call, Replaced air block axle #4 LH	CAD	29049.0	1040431.0
Sep 15, 2024	Repair reverse beacon		450.00	Monthly, oil change, greased, fuel filters, back up alarm replaced	CAD	29132.0	1043197.0
Sep 15, 2024	Monthly Insp.		450.00	Monthly, oil change, greased, fuel filters, back up alarm replaced	CAD	29132.0	1043197.0
Sep 15, 2024	Fuel Filter Replacement		450.00	Monthly, oil change, greased, fuel filters, back up alarm replaced	CAD	29132.0	1043197.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Sep 15, 2024	Grease Unit		450.00	Monthly, oil change, greased, fuel filters, back up alarm replaced	CAD	29132.0	1043197.0
Sep 15, 2024	Oil Change		450.00	Monthly, oil change, greased, fuel filters, back up alarm replaced	CAD	29132.0	1043197.0
Sep 16, 2024	Service Call		600.00	Service call, repair air line and replaced brake pot	CAD	29136.0	1043327.0
Sep 16, 2024	Air system repair		600.00	Service call, repair air line and replaced brake pot	CAD	29136.0	1043327.0
Sep 16, 2024	Brake Pot Replacement		600.00	Service call, repair air line and replaced brake pot	CAD	29136.0	1043327.0
Sep 22, 2024	Replace Super Swivel		500.00	Replaced hose reel super swivel, attached ground cable clamp, repaired interior lights	CAD	29169.0	1044356.0
Sep 22, 2024	Ground Cable Repair		500.00	Replaced hose reel super swivel, attached ground cable clamp, repaired interior lights	CAD	29169.0	1044356.0
Sep 22, 2024	Electrical Wiring Repair		500.00	Replaced hose reel super swivel, attached ground cable clamp, repaired interior lights	CAD	29169.0	1044356.0
Sep 23, 2024	Headlamp Replacement		1500.00	Replace low beam and high beam headlights	CAD	29169.0	1044356.0
Nov 9, 2024	Dust Shield Replacement		900.00	Monthly, oil change, fuel filters, grease units, top up fluids, air dryer valve change, dust shield axle 1	CAD	29430.0	1053069.0
Nov 9, 2024	Top up fluids		900.00	Monthly, oil change, fuel filters, grease units, top up fluids, air dryer valve change, dust shield axle 1	CAD	29430.0	1053069.0
Nov 9, 2024	Air system repair		900.00	Monthly, oil change, fuel filters, grease units, top up fluids, air dryer valve change, dust shield axle 1	CAD	29430.0	1053069.0
Nov 9, 2024	Monthly Insp.		900.00	Monthly, oil change, fuel filters, grease units, top up fluids, air dryer valve change, dust shield axle 1	CAD	29430.0	1053069.0
Nov 9, 2024	Fuel Filter Replacement		900.00	Monthly, oil change, fuel filters, grease units, top up fluids, air dryer valve change, dust shield axle 1	CAD	29430.0	1053069.0
Nov 9, 2024	Grease Unit		900.00	Monthly, oil change, fuel filters, grease units, top up fluids, air dryer valve change, dust shield axle 1	CAD	29430.0	1053069.0
Nov 9, 2024	Oil Change		900.00	Monthly, oil change, fuel filters, grease units, top up fluids, air dryer valve change, dust shield axle 1	CAD	29430.0	1053069.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Dec 26, 2024	Heater blower repair		1200.00	Monthly, oil change, fuel filters, replaced worklights, replaced dust shield, replace purge valve, replaced air dryer, replaced bunk heater fan, top up fluids	CAD	29712.0	1063964.0
Dec 26, 2024	Air Dryer Replacement		1200.00	Monthly, oil change, fuel filters, replaced worklights, replaced dust shield, replace purge valve, replaced air dryer, replaced bunk heater fan, top up fluids	CAD	29712.0	1063964.0
Dec 26, 2024	Dust Shield Replacement		1200.00	Monthly, oil change, fuel filters, replaced worklights, replaced dust shield, replace purge valve, replaced air dryer, replaced bunk heater fan, top up fluids	CAD	29712.0	1063964.0
Dec 26, 2024	Top up fluids		1200.00	Monthly, oil change, fuel filters, replaced worklights, replaced dust shield, replace purge valve, replaced air dryer, replaced bunk heater fan, top up fluids	CAD	29712.0	1063964.0
Dec 26, 2024	Air system repair		1200.00	Monthly, oil change, fuel filters, replaced worklights, replaced dust shield, replace purge valve, replaced air dryer, replaced bunk heater fan, top up fluids	CAD	29712.0	1063964.0
Dec 26, 2024	Monthly Insp.		1200.00	Monthly, oil change, fuel filters, replaced worklights, replaced dust shield, replace purge valve, replaced air dryer, replaced bunk heater fan, top up fluids	CAD	29712.0	1063964.0
Dec 26, 2024	Fuel Filter Replacement		1200.00	Monthly, oil change, fuel filters, replaced worklights, replaced dust shield, replace purge valve, replaced air dryer, replaced bunk heater fan, top up fluids	CAD	29712.0	1063964.0
Dec 26, 2024	Work Light Replacement		1200.00	Monthly, oil change, fuel filters, replaced worklights, replaced dust shield, replace purge valve, replaced air dryer, replaced bunk heater fan, top up fluids	CAD	29712.0	1063964.0
Dec 26, 2024	Oil Change		1200.00	Monthly, oil change, fuel filters, replaced worklights, replaced dust shield, replace purge valve, replaced air dryer, replaced bunk heater fan, top up fluids	CAD	29712.0	1063964.0
Feb 21, 2025	Rear Wheel Hub Replacement		1900.00	Oil change, monthly, fuel filters, air filters, greased, replaced RH Axle 4 hub, repaired RH signal and brake lights, Torque RH Axle 4 wheels	CAD	30146.0	1081902.0
Feb 21, 2025	Monthly Insp.		1900.00	Oil change, monthly, fuel filters, air filters, greased, replaced RH Axle 4 hub, repaired RH signal and brake lights, Torque RH Axle 4 wheels	CAD	30146.0	1081902.0
Feb 21, 2025	Fuel Filter Replacement		1900.00	Oil change, monthly, fuel filters, air filters, greased, replaced RH Axle 4 hub, repaired RH signal and brake lights, Torque RH Axle 4 wheels	CAD	30146.0	1081902.0
Feb 21, 2025	Grease Unit		1900.00	Oil change, monthly, fuel filters, air filters, greased, replaced RH Axle 4 hub, repaired RH signal and brake lights, Torque RH Axle 4 wheels	CAD	30146.0	1081902.0
Feb 21, 2025	Electrical Wiring Repair		1900.00	Oil change, monthly, fuel filters, air filters, greased, replaced RH Axle 4 hub, repaired RH signal and brake lights, Torque RH Axle 4 wheels	CAD	30146.0	1081902.0
Feb 21, 2025	Torque Wheels		1900.00	Oil change, monthly, fuel filters, air filters, greased, replaced RH Axle 4 hub, repaired RH signal and brake lights, Torque RH Axle 4 wheels	CAD	30146.0	1081902.0
Feb 21, 2025	Oil Change		1900.00	Oil change, monthly, fuel filters, air filters, greased, replaced RH Axle 4 hub, repaired RH signal and brake lights, Torque RH Axle 4 wheels	CAD	30146.0	1081902.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Feb 21, 2025	Air Filter Replacement		1900.00	Oil change, monthly, fuel filters, air filters, greased, replaced RH Axle 4 hub, repaired RH signal and brake lights, Torque RH Axle 4 wheels	CAD	30146.0	1081902.0
Mar 3, 2025	GPS REPAIR		50.00	Upgraded GPS	CAD	30222.0	1084361.0
Mar 20, 2025	Windshield Replacement		462.00	New DS/PS Windshield	CAD	30316.0	1088305.0
Mar 28, 2025	Steady Bearing Replacement		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Mar 28, 2025	PT- TK Pressure Test (P)		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Mar 28, 2025	PT - Leakage TK insp. (K)		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Mar 28, 2025	PT - Internal TK insp. (I)		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Mar 28, 2025	PT - External TK insp. (V)		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Mar 28, 2025	Monthly Insp.		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Mar 28, 2025	Fuel Filter Replacement		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Mar 28, 2025	Work Light Replacement		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Mar 28, 2025	Grease Unit		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Mar 28, 2025	Oil Change		1400.00	Monthly, oil change, fuel filters, greased, replaced rear steady bearing, replaced 2 work lights, replaced 1 hatch seal and inspected other 3 hatch seals, Tank Test VKIP	CAD	30375.0	1091103.0
Apr 2, 2025	Fuel System Repair		900.00	Service call, computer diagnostics, replace fuel filter separator	CAD	30376.0	1091152.0
Apr 2, 2025	Service Call		900.00	Service call, computer diagnostics, replace fuel filter separator	CAD	30376.0	1091152.0
Apr 2, 2025	Run Diagnostics		900.00	Service call, computer diagnostics, replace fuel filter separator	CAD	30376.0	1091152.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Apr 28, 2025	Torque Wheels		13449.00	CVIP, oil change, monthly, fuel filters, greased, new cell booster, replaced axle 1,2,4 shocks, replaced axle 2 tires, replaced axles 2 diff output seal, replaced axle 3 diff input seal, replaced abs valves above aies 3/4, replaced wheel seals axle 1 LR axle 2 L, replaced flew pipe after turbo, replaced ubolt and torque arm axle 3 R, replaced 3" and 1.5" hoses, annual hose testing, adjusted all brakes, torqued all wheels to 500 ft/lbs	CAD	30585.0	1100546.0
Apr 28, 2025	Tire Replacement		13449.00	CVIP, oil change, monthly, fuel filters, greased, new cell booster, replaced axle 1,2,4 shocks, replaced axle 2 tires, replaced axles 2 diff output seal, replaced axle 3 diff input seal, replaced abs valves above aies 3/4, replaced wheel seals axle 1 LR axle 2 L, replaced flew pipe after turbo, replaced ubolt and torque arm axle 3 R, replaced 3" and 1.5" hoses, annual hose testing, adjusted all brakes, torqued all wheels to 500 ft/lbs	CAD	30585.0	1100546.0
Apr 28, 2025	Oil Change		13449.00	CVIP, oil change, monthly, fuel filters, greased, new cell booster, replaced axle 1,2,4 shocks, replaced axle 2 tires, replaced axles 2 diff output seal, replaced axle 3 diff input seal, replaced abs valves above aies 3/4, replaced wheel seals axle 1 LR axle 2 L, replaced flew pipe after turbo, replaced ubolt and torque arm axle 3 R, replaced 3" and 1.5" hoses, annual hose testing, adjusted all brakes, torqued all wheels to 500 ft/lbs	CAD	30585.0	1100546.0
Jun 12, 2025	Dust Shield Replacement		750.00	Monthly, oil change, greased, fuel filters, replaced RH fender signal lights, repaired wiring, replaced dustshield LH4	CAD	30856.0	1113330.0
Jun 12, 2025	Monthly Insp.		750.00	Monthly, oil change, greased, fuel filters, replaced RH fender signal lights, repaired wiring, replaced dustshield LH4	CAD	30856.0	1113330.0
Jun 12, 2025	Fuel Filter Replacement		750.00	Monthly, oil change, greased, fuel filters, replaced RH fender signal lights, repaired wiring, replaced dustshield LH4	CAD	30856.0	1113330.0
Jun 12, 2025	Grease Unit		750.00	Monthly, oil change, greased, fuel filters, replaced RH fender signal lights, repaired wiring, replaced dustshield LH4	CAD	30856.0	1113330.0
Jun 12, 2025	Electrical Wiring Repair		750.00	Monthly, oil change, greased, fuel filters, replaced RH fender signal lights, repaired wiring, replaced dustshield LH4	CAD	30856.0	1113330.0
Jun 12, 2025	Marker Light Replacement		750.00	Monthly, oil change, greased, fuel filters, replaced RH fender signal lights, repaired wiring, replaced dustshield LH4	CAD	30856.0	1113330.0
Jun 12, 2025	Oil Change		750.00	Monthly, oil change, greased, fuel filters, replaced RH fender signal lights, repaired wiring, replaced dustshield LH4	CAD	30856.0	1113330.0
Jun 27, 2025	Air system repair		700.00	Replaced R4 air bag	CAD	30933.0	1116628.0
Jul 20, 2025	Repair turn signal		78.00	repaired wiring to rear DS signal light	CAD	31026.0	1120224.0
Jul 20, 2025	Electrical Wiring Repair		78.00	repaired wiring to rear DS signal light	CAD	31026.0	1120224.0
Jul 31, 2025	Monthly Insp.		550.00	Monthly inspection, oil change, fuel filters, tire repair	CAD	31055.0	1122879.0
Jul 31, 2025	Fuel Filter Replacement		550.00	Monthly inspection, oil change, fuel filters, tire repair	CAD	31055.0	1122879.0
Jul 31, 2025	Grease Unit		550.00	Monthly inspection, oil change, fuel filters, tire repair	CAD	31055.0	1122879.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Jul 31, 2025	Tire Service		550.00	Monthly inspection, oil change, fuel filters, tire repair	CAD	31055.0	1122879.0
Jul 31, 2025	Oil Change		550.00	Monthly inspection, oil change, fuel filters, tire repair	CAD	31055.0	1122879.0
Aug 6, 2025	Service Call		65.00	Service call nisku, replaced Axle3 LH Brake Pot	CAD	31104.0	1123327.0
Aug 6, 2025	Brake Pot Replacement		65.00	Service call nisku, replaced Axle3 LH Brake Pot	CAD	31104.0	1123327.0
Sep 3, 2025	Oil Filter Replacement		550.00	engine oil and filter change, fuel filters changed, greased, top up fluids, installed p/s steer dust cover, installed AZ p/s, AH d/s dust cover, secured d/s front mud flap	CAD	31237.0	1128659.0
Sep 3, 2025	Top up fluids		550.00	engine oil and filter change, fuel filters changed, greased, top up fluids, installed p/s steer dust cover, installed AZ p/s, AH d/s dust cover, secured d/s front mud flap	CAD	31237.0	1128659.0
Sep 3, 2025	Fuel Filter Replacement		550.00	engine oil and filter change, fuel filters changed, greased, top up fluids, installed p/s steer dust cover, installed AZ p/s, AH d/s dust cover, secured d/s front mud flap	CAD	31237.0	1128659.0
Sep 3, 2025	Grease Unit		550.00	engine oil and filter change, fuel filters changed, greased, top up fluids, installed p/s steer dust cover, installed AZ p/s, AH d/s dust cover, secured d/s front mud flap	CAD	31237.0	1128659.0
Sep 3, 2025	Other Maintenance		550.00	engine oil and filter change, fuel filters changed, greased, top up fluids, installed p/s steer dust cover, installed AZ p/s, AH d/s dust cover, secured d/s front mud flap	CAD	31237.0	1128659.0
Sep 3, 2025	Oil Change		550.00	engine oil and filter change, fuel filters changed, greased, top up fluids, installed p/s steer dust cover, installed AZ p/s, AH d/s dust cover, secured d/s front mud flap	CAD	31237.0	1128659.0
Sep 25, 2025	Other Maintenance		100.00	diagnose brake pot leak, replaced diaphragm + clamp	CAD	31376.0	1134102.0
Sep 25, 2025	Brake Inspection		100.00	diagnose brake pot leak, replaced diaphragm + clamp	CAD	31376.0	1134102.0
Oct 15, 2025	Radiator Replacement		600.00	service call, coolant leak, towing to shop, unloaded fluid and drop pup, order rad, replace rad, top up fluids, change 4 tires axle 4 LH/RH	CAD	31472.0	1137889.0
Oct 15, 2025	Tires Replacement		600.00	service call, coolant leak, towing to shop, unloaded fluid and drop pup, order rad, replace rad, top up fluids, change 4 tires axle 4 LH/RH	CAD	31472.0	1137889.0
Oct 15, 2025	Service Call		600.00	service call, coolant leak, towing to shop, unloaded fluid and drop pup, order rad, replace rad, top up fluids, change 4 tires axle 4 LH/RH	CAD	31472.0	1137889.0
Oct 15, 2025	Top up fluids		600.00	service call, coolant leak, towing to shop, unloaded fluid and drop pup, order rad, replace rad, top up fluids, change 4 tires axle 4 LH/RH	CAD	31472.0	1137889.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Oct 28, 2025	Oil Filter Replacement		300.00	monthly insp, oil change, oil filter change, greased and checked over	CAD	31545.0	1141263.0
Oct 28, 2025	Monthly Insp.		300.00	monthly insp, oil change, oil filter change, greased and checked over	CAD	31545.0	1141263.0
Oct 28, 2025	Fuel Filter Replacement		300.00	monthly insp, oil change, oil filter change, greased and checked over	CAD	31545.0	1141263.0
Oct 28, 2025	Grease Unit		300.00	monthly insp, oil change, oil filter change, greased and checked over	CAD	31545.0	1141263.0
Oct 28, 2025	Oil Change		300.00	monthly insp, oil change, oil filter change, greased and checked over	CAD	31545.0	1141263.0
Dec 20, 2025	Oil Filter Replacement		1900.00	monthly insp, oil change, oil filter change, changed fuel filters, greased, check all fluids, replaced governor, replaced air dryer, replaced fan hub, replaced clutch brake, adjusted clutch release bearing, added meth pot	CAD	31915.0	1155825.0
Dec 20, 2025	Replace Clutch Brake Disc		1900.00	monthly insp, oil change, oil filter change, changed fuel filters, greased, check all fluids, replaced governor, replaced air dryer, replaced fan hub, replaced clutch brake, adjusted clutch release bearing, added meth pot	CAD	31915.0	1155825.0
Dec 20, 2025	Air Dryer Replacement		1900.00	monthly insp, oil change, oil filter change, changed fuel filters, greased, check all fluids, replaced governor, replaced air dryer, replaced fan hub, replaced clutch brake, adjusted clutch release bearing, added meth pot	CAD	31915.0	1155825.0
Dec 20, 2025	Monthly Insp.		1900.00	monthly insp, oil change, oil filter change, changed fuel filters, greased, check all fluids, replaced governor, replaced air dryer, replaced fan hub, replaced clutch brake, adjusted clutch release bearing, added meth pot	CAD	31915.0	1155825.0
Dec 20, 2025	Fuel Filter Replacement		1900.00	monthly insp, oil change, oil filter change, changed fuel filters, greased, check all fluids, replaced governor, replaced air dryer, replaced fan hub, replaced clutch brake, adjusted clutch release bearing, added meth pot	CAD	31915.0	1155825.0
Dec 20, 2025	Grease Unit		1900.00	monthly insp, oil change, oil filter change, changed fuel filters, greased, check all fluids, replaced governor, replaced air dryer, replaced fan hub, replaced clutch brake, adjusted clutch release bearing, added meth pot	CAD	31915.0	1155825.0
Dec 20, 2025	Other Maintenance		1900.00	monthly insp, oil change, oil filter change, changed fuel filters, greased, check all fluids, replaced governor, replaced air dryer, replaced fan hub, replaced clutch brake, adjusted clutch release bearing, added meth pot	CAD	31915.0	1155825.0
Dec 20, 2025	Oil Change		1900.00	monthly insp, oil change, oil filter change, changed fuel filters, greased, check all fluids, replaced governor, replaced air dryer, replaced fan hub, replaced clutch brake, adjusted clutch release bearing, added meth pot	CAD	31915.0	1155825.0
Dec 31, 2025	Replace seal		700.00	replace windshield, wash, axle seal replace	CAD	31951.0	1158077.0
Dec 31, 2025	Windshield Replacement		700.00	replace windshield, wash, axle seal replace	CAD	31951.0	1158077.0
Feb 7, 2026	Replace hose		50.00	replaced 80" hose in pump box	CAD	32167.0	1166612.0

Equipment: Unit #58

Date	Service Tasks	Vendor	Cost	Notes	Currency	Engine Hours	Odometer (km)
Feb 18, 2026	Service Call		250.00	service call, diagnose air issues bypass ppv, check over air system, repaired air leak @ transmission	CAD	32243.0	1170095.0
Feb 18, 2026	Air system repair		250.00	service call, diagnose air issues bypass ppv, check over air system, repaired air leak @ transmission	CAD	32243.0	1170095.0
Feb 21, 2026	Other Maintenance		100.00	Replaced wash fluid pump	CAD	32271.0	1171466.0
Mar 17, 2026	TK Thickness Test		100.00	Tank test VKT	CAD	32407.0	1178442.0
Mar 17, 2026	PT - Leakage TK insp. (K)		100.00	Tank test VKT	CAD	32407.0	1178442.0
Mar 17, 2026	PT - External TK insp. (V)		100.00	Tank test VKT	CAD	32407.0	1178442.0