

VO: 170375 - Running Repairs 24 (8670 HR)				Closed
Notes: null				
Item: 188839 - TIL Running Repairs 2024				
10/17/2024	2	SCHAUB, THOMAS	Unit had hydraulic leak . Checked over unit cleaned area . Had operator work unit . Found leak at metal line going in to hydraulic filter housing in front of front axle . Got line back in place temporarily. Unit got trucked to shop for that and other repairs needed	
10/11/2024	4.5	SCHAUB, THOMAS	Drove to unit . Filled trans and installed new fill tube cap. Checked unit for engine oil leak . Found leaking rear crank seal . Hooked up computer and checked for acu 27 code . Found broken bolt in hitch . Ordered new one had it delivered and installed new bolt	
9/27/2024	1.5	DU PLESSIS, RYNO	Assemble hitch with new hardware, replace coupler	
9/25/2024	1.5	SCHAUB, THOMAS	Drove to unit removed broken bolts from hitch ordered new ones	
9/23/2024	2	SCHAUB, THOMAS	Drove to unit installed new step and new hitch pin	
9/13/2024	1	BOBEY, ALEX	Check out leaks on the machine, looks like the front main seal on engine has failed. Engine oil blowing all over front structure. Check out and order some hitch hoses at the rear that are leaking.	
Item: 188024 - Check over				
8/29/2024	2	BOBEY, ALEX	Quick static checks on unit. Check fluids and charging. ACU fault active for ACU calibration. Tried to run with service advisor but unable to complete.	
VO: 164407 - MOB (8670 HR)				Closed
Item: 182297 - MOB				
240522-877-				
VO: 164104 - (250) FARM TRACTOR STANDARD PROGRAM				Open
Item: 145244 - (250) FARM TRACTOR STANDARD PROGRAM				
6/8/2026	5	MINTER, TANNER	take steps apart, straighten/ repair step parts, re assemble steps	
VO: 160173 - Demob (8655 HR)				Closed
Item: 178902 - Demob				
5/17/2024	2.5	YACUK, JONATHON	Looked over unit checked levels started unit tested cab functions marked down damages on demob sheet.	
5/17/2024	1	DU PLESSIS, RYNO	Install TIL radio	
4/12/2024	0.5	GAUDLEY, MATTHEW	Changed bulbs in roof lights	
4/11/2024	3	GAUDLEY, MATTHEW	Went and got unit brought up to shop went threw Demob sheet found small chips in hood roof work light was burnt out looked for light bulbs going to get one from automotive shop in the morning we are out, fire extinguisher was expired replaced, checked all fluids and carried on with sheet. Changed all oil plugs in disk that was attached to grease nipples checked wheel bearings and disk scrapers hitch pin that holds scraper to tractor is rubbed almost in half brought unit to wash bay so welders can check it in the morning	
VO: 139305 - Welding repairs (8655 HR)				Closed



00877 [DEERE 9320 4WD TRACTOR]

Equipment History From August 18, 2018 to August 19, 2026

Item: 157806 - Welding repairs					
8/3/2023	4	TOPHAM, JULIAN	Repair crack in hydraulic cylinder		
VO: 138188 - ACU code 27.. (8655 HR)					Closed
Item: 156734 - ACU code 27..					
7/24/2023	2	PORTER, SHELDON	Install harness to svc SCU code gone ACU code 27 now active .. ACU calibration required .. cannot successfully calibrate .code doesn't effect machine performance..		
VO: 137729 - Demob (8655 HR)					Closed
Item: 156284 - Demob					
7/19/2023	4	HANSON, KELSEY	Demob machine, replace lights. Checklist		
VO: 135909 - No heater blower and ACP calibration (8655 HR)					Closed
Item: 154483 - No heater blower and ACP calibration					
7/8/2023	10	PORTER, SHELDON	Calibrate ACU.. it took several attempts to get it to calibrate throttle.. Acu 27 code cleared.. SC0 140 code active.. low voltage to scv4 .. fourth hydraulic control switch on arm rear.. found the outputs from circuit board not correlating with harness to switch . Power and ground not matching wiring schematic.. attempted to move pins in connector.. damaged connector ordered new connector. Machine functions fine just there's a hydraulic fault light on .. hooked tractor to disc.. fabricated hose holder and installed on disc		
7/7/2023	1	PORTER, SHELDON	Install new throttle potentiometer and attempted to calibrate.. failed		
7/4/2023	9	PORTER, SHELDON	Trace wiring to blower motor found pins melted at 6 pin connector behind cab.. spliced in spade connector by pacing oem connector for 283 circuit blower motor supply.. reassemble cab panels.. attempted to calibrate acu.. unable to calibrate throttle control .. tested circuits ordered a potentiometer		
VO: 133418 - No start (8655 HR)					Closed
Item: 152011 - No start					
6/9/2023	2	ELLIOTT, TRAVIS	Boost unit to move. Lights left on. Replace master lockout		
VO: 133459 - Hydraulic hoses and miscellaneous repairs (8655 HR)					Closed
Item: 152052 - Hydraulic hoses and miscellaneous repairs					
6/11/2023	12	MALANOWICH, CRAIG	Diagnostic code and repair seat harness check a/c		
6/11/2023	12	PURCHA, GEORGE (WES)	Diagnostic codes repaired seat harness check A/C		
6/10/2023	12	MALANOWICH, CRAIG	Build and replace hydraulic hoses, code diagnostic, repair seat pressure switch		
6/10/2023	12	PURCHA, GEORGE (WES)	Build and replace hydraulic hoses Diagnostic codes Pressure switch in seat repair		
6/9/2023	2	MALANOWICH, CRAIG	Boosted bring over to wash bay and Chang burnt out lights		
6/9/2023	2	PURCHA, GEORGE (WES)	Boost and check charging system lights		
VO: 132319 - Tractor won't lift implement (8655 HR)					Closed
Item: 150923 - Tractor won't lift implement					
5/31/2023	4	WARREN, KEITH	Set up work area Repaired wiring problem are rest arm controller is functioning properly, ordered auxiliary valve supply line		



00877 [DEERE 9320 4WD TRACTOR]

Equipment History From August 18, 2018 to August 19, 2026

5/30/2023	3.5	WARREN, KEITH	Set up work area found that unit was having arm rest control failure cods started troubleshooting suspected wiring problem	
VO: 126601 - (500) FARM TRACTOR STANDARD PROGRAM (8655)				Closed
Item: 139576 - (500) FARM TRACTOR STANDARD PROGRAM				
230412-877-				
VO: 126124 - Hood will not latch (8564 HR)				Closed
Item: 144760 - Hood will not latch				
4/8/2023	2.5	RIEHL, NATHAN	Go to rms9 stuck on rout and had to be towed in. Found hood striker missing. Build a replacement hood latches now.	
VO: 125866 - Boost (8520 HR)				Closed
Item: 144501 - Boost				
4/5/2023	2	FORREST, BRANDON	Unit was stone dead. Master & work lights left on. Boost batteries. Unit is up	
VO: 120972 - (250) FARM TRACTOR STANDARD PROGRAM (8380)				Closed
Item: 135722 - (250) FARM TRACTOR STANDARD PROGRAM				
877 (250H) 02-23-				
VO: 120608 - Won't go into park (8520 HR)				Closed
Item: 139214 - Won't go into park				
3/25/2023	2	NAUMANN, KEVIN	Removed the old shifter and put new shifter parts together and installed it back on unit got unit running and tested it is going into park and holding in park now	
3/5/2023	1	NAUMANN, KEVIN	Travel to the unit and checked out why not going into park needs new shifter	
2/23/2023	1	GOODMAN, JAYDEN	Drive to unit. Unit went into park with no issue	
VO: 118631 - Rad loose (8237 HR)				Closed
Item: 137229 - Rad loose				
2/7/2023	1	FOWLIE, JORDAN	Rad is loose, secure rad by tightening bolts and rubber bushings	
VO: 118438 - Work lights (8203 HR)				Closed
Item: 137031 - Work lights				
2/5/2023	2	WARD, DEVIN	Work lights on machine are all out, inspected unit, drove back to the yard for bulbs, replaced all work light bulbs and repaired wiring sent unit back to work	
VO: 117951 - Unit won't go into park (8144 HR)				Closed
Item: 136537 - Unit won't go into park				
2/1/2023	1	RIDLAND, JADEN	Operator stuck in cab, safe unit out, inspect, detent spring was popped out, re-install and test.	
2/1/2023	1	HEWITT, TYLER	Repair park brake	
VO: 117806 - Oil leak (8262 HR)				Closed
Item: 136409 - Oil leak				
2/20/2023	4	HUDSON, TREY	Inspect Ty to get running check for codes none logged	
2/13/2023	2	MOSER, ALEX	Install hydraulic line, call for hydraulic fluid to be filled. Had to go back to unit and test after hydraulic fluid filled and check for leaks. No leak.	
2/12/2023	1.5	HEWITT, TYLER	Removed damaged hose, build new one. Got pulled off before could install.	



00877 [DEERE 9320 4WD TRACTOR]

Equipment History From August 18, 2018 to August 19, 2026

2/9/2023	1	BARRETT, JOHN	Check for oil leak. Found steering line leaking. Marked line with tag and lock out.	
2/1/2023	3	NAUMANN, KEVIN	Installed the new steering line and moved unit out of a big water hole got hydraulic oil topped up and checked for more leaks found the feed line running to the valve bank on the rear of the machine is leaking bad out of one of the crimps removed line capped off so unit can still pull a drag need to make hydraulic line	
1/30/2023	1	NAUMANN, KEVIN	Removed the blown line on right hand steering cylinder to be sent out to have new one made	
VO: 117136 - (1000) FARM TRACTOR STANDARD PROGRAM (8069				Closed
Item: 131417 - (1000) FARM TRACTOR STANDARD PROGRAM				
2023-01-				
VO: 116922 - Weld plate on tire drag on inside pin in tire (8042 HR)				Closed
Item: 135504 - Weld plate on tire drag on inside pin in tire				
1/24/2023	2	HERDA, MIKE	Clean old plate up,Weld plate to inside tire puller	
VO: 114976 - Won't start (7990 HR)				Closed
Item: 133550 - Won't start				
1/7/2023	1	NAUMANN, KEVIN	Changed up the batteries and it fired up	
VO: 114773 - RH rear wheel weight (7990 HR)				Closed
Item: 133350 - RH rear wheel weight				
1/5/2023	2	NAUMANN, KEVIN	Put the right rear wheel weight back on the hub	
1/5/2023	1	FOWLIE, JORDAN	Instal wheel weight	
VO: 113255 - Won't start (7854 HR)				Closed
Item: 131790 - Won't start				
12/18/2022	1	NAUMANN, KEVIN	Heat and boost got machine going	
VO: 112881 - (250) FARM TRACTOR STANDARD PROGRAM (7816				Closed
Item: 128638 - (250) FARM TRACTOR STANDARD PROGRAM				
877 (250H) 12-13-				
VO: 112745 - Drag (7816 HR)				Closed
Item: 131273 - Drag				
12/13/2022	1	WARD, DEVIN	Remove drag shackle	
VO: 111795 - Cab heat (7749 HR)				Closed
Item: 130307 - Cab heat				
12/5/2022	1	WARD, DEVIN	Operator complaint of low heat in cab, checked over unit, covered engine cooler with cardboard	
VO: 111448 - Hydraulic leak (7676 HR)				Closed
Notes: null				
Item: 130741 - Hyd leak				
12/9/2022	3	FOWLIE, JORDAN	Remove blown hyd hose, go to FHO build hose return to unit and instal hose	
Item: 129930 - Hydraulic leak				
12/9/2022	2	WHEELDON, BROCK	Remove blown hose and install new hose	



00877 [DEERE 9320 4WD TRACTOR]
Equipment History From August 18, 2018 to August 19, 2026

12/2/2022	5	WARD, DEVIN	Operator, complaint of hydraulic leak at rear of tractor, drove out to machine, inspected unit, hydraulic line is blow at crimp, pulled line through out from front of tractor, built line back at fho, installed new line, ran machine and checked for leaks, had hydraulic oil topped off	
VO: 110194 - (500) FARM TRACTOR STANDARD PROGRAM (7569)				Closed
Item: 122468 - (500) FARM TRACTOR STANDARD PROGRAM				
2022-11-				
VO: 108615 - Needs grill cover (7749 HR)				Closed
Item: 127048 - Needs grill cover				
VO: 106983 - Broken interior door handle (7543 HR)				Closed
Item: 125367 - Broken interior door handle				
Notes: Parts ordered				
11/5/2022	2	TOMASZEWSKI, DALE	Replaced damaged door latch	
VO: 104189 - (250) FARM TRACTOR STANDARD PROGRAM (7326)				Closed
Item: 119746 - (250) FARM TRACTOR STANDARD PROGRAM				
2022-10-				
VO: 103713 - Bent bottom step cutting tire when turning (7347 HR)				Closed
Notes: Maintenance team reviewed deficiencies 10/21/2022				
Item: 121923 - Bent bottom step cutting tire when turning				
10/20/2022	0.5	THRONBERG, KANE	Inspected and already fixed	
10/18/2022	1.5	WHYBREW, DANIEL	Disassemble steps Straighten bent rails and mounting brackets. Reassembled steps Weld repaired lower broken bracket.	
VO: 103794 - Leaking quick connects (7283 HR)				Closed
Item: 122003 - Leaking quick connects				
10/5/2022	3	HUTCHINSON, LUCAS	Installed 4 new female quick connects in valves.	
VO: 103359 - Weak horn (7347 HR)				Closed
Notes: Reviewed by maintenance team 10/18/22				
Item: 121574 - Weak horn				
VO: 103364 - Bolts missing on top step (7347 HR)				Closed
Notes: Maintenance team reviewed deficiencies 10/21/2022				
Item: 121579 - Bolts missing on top step				
10/18/2022	0.5	WHYBREW, DANIEL	Filled in missing bolts in step to operating station.	
VO: 102837 - Hyd leak (7160 HR)				Closed
Item: 121050 - Hyd leak				
9/28/2022	3	FOWLIE, JORDAN	Drive to unit wait for dozer to blade me a path, find hyd leak, take off line and go to FHO and make up hose come back and put it on	
VO: 102763 - Belt (7155 HR)				Closed
Item: 120973 - Belt				
9/27/2022	1	MARQUIS, DANIEL	Tight alternator belt	



00877 [DEERE 9320 4WD TRACTOR]

Equipment History From August 18, 2018 to August 19, 2026

VO: 101776 - Pin for hitch stuck (7055 HR)				Closed
Item: 119988 - Pin for hitch stuck				
9/21/2022	1.5	FOWLIE, JORDAN	Jammed pin for hitch. Free it up and get it out	
VO: 101560 - (2000) FARM TRACTOR STANDARD PROGRAM (7055				Closed
Item: 117750 - (2000) FARM TRACTOR STANDARD PROGRAM				
2022-09-				
VO: 100213 - September 2022 - Running Repairs (7035 HR)				Closed
Notes: null				
Item: 119659 - Drag cables				
9/18/2022	1	WARD, DEVIN	Laborers need assistance flipping tow cable for drag, remove good shackles from another drag, cut damaged shackle off of drag	
Item: 118624 - Step broken				
9/12/2022	6	SPARKS, BRADLEY	Cut step apart and repaired brackets and fab new bottom step	
9/9/2022	1	RIEHL, NATHAN	Go check on issue welders need to build a new step return to yard and clean up.	
Item: 118324 - Lights				
9/7/2022	1	HOLTZ, AUSTIN	Burnout rear lights. Changed bulbs.	
9/7/2022	1.5	TOMASZEWSKI, DALE	Repair rear work lights	
VO: 99668 - (250) FARM TRACTOR STANDARD PROGRAM (6827 HR)				Closed
Item: 116098 - (250) FARM TRACTOR STANDARD PROGRAM				
2022-09-				
VO: 97985 - August 2022 - Running Repairs (6682 HR)				Closed
Notes: null				
Item: 116583 - Unit died				
8/23/2022	2	TOMASZEWSKI, DALE	Boost unit and check charging system. Unit is producing 14vdc. Sent back to work. Suspect unit was stalled and not put in park to start	
Item: 116051 - Hydraulic couplers leaking				
8/20/2022	2.5	TOMASZEWSKI, DALE	Repair hyd leaks	
8/18/2022	3.5	RIEHL, NATHAN	Meeting go find unit found parts incorrect. Make parts list and send in.	
VO: 98030 - (500) FARM TRACTOR STANDARD PROGRAM (6609 HR)				Closed
Item: 113223 - (500) FARM TRACTOR STANDARD PROGRAM				
877 (500HR) 08-18-				
VO: 97405 - Hitch (6528 HR)				Closed
Item: 115485 - Hitch				
8/13/2022	1	DAVIDSON, MIKE	New bolts to hold hitch	
VO: 96201 - Charging (6472 HR)				Closed
Item: 114274 - Charging				
8/3/2022	2	HUTCHINSON, LUCAS	Installed new alternator and tested. Charging 14 v	
8/1/2022	2	HUTCHINSON, LUCAS	Charge light coming on found alternator not charging. Need to order alternator	



VO: 95743 - Broken hitch (6440 HR)				Closed
Item: 113754 - Broken hitch				
7/27/2022	10.5	HERDA, MIKE	Take part off.cut grind and weld parts together.put back on	
7/27/2022	2.5	THRONBERG, KANE	Put hitch back together, load up and go and install on unit	
VO: 95805 - Hard bar (6440 HR)				Closed
Item: 113820 - Hard bar				
7/27/2022	1	DAVIDSON, MIKE	Look to see if it can be welded taken off or fixed on the machine	
VO: 95381 - Leak (6399 HR)				Closed
Item: 113377 - Leak				
7/23/2022	3	DAVIDSON, MIKE	Hydraulic leak went to yard to build hose had to send for one to be built Got hose back and put on by the end of day	
VO: 95195 - Lights (6369 HR)				Closed
Item: 113186 - Lights				
7/21/2022	3	TOMASZEWSKI, DALE	Repair work lights and wiring to rear work lights	
VO: 95167 - 2way (6369 HR)				Closed
Item: 113158 - 2way				
7/21/2022	1.5	MARQUIS, DANIEL	Replace antenna and check lights will need more bulb	
VO: 95232 - (250) FARM TRACTOR STANDARD PROGRAM (6367 HR)				Closed
Item: 110283 - (250) FARM TRACTOR STANDARD PROGRAM				
2022-07-				
VO: 94578 - Boost (6331 HR)				Closed
Item: 112564 - Boost				
7/15/2022	0.5	MEYER, DUSTIN	Boosted unit and checked charging system. Unit is charging. Left running for operations to take and let batteries charge.	
VO: 93543 - April 2022 - Running Repairs (5701 HR)				Closed
Item: 102504 - Engine oil leak				
4/26/2022	6	WARD, DEVIN	Drove out to machine, set up amd was immediately call back to the yard for an incident meeting, packed up and drove back to the yard, sat through meeting, drove back out to machine, installed fan, tensioner and belts, ran machine after half an hour of running at high idle still no oil leaks, cleaned and installed covers and shields, installed hood mount, packed up and left site, right side hood shock was broken ordered part, unit is up	
4/24/2022	6	SPARKS, BRADLEY	Build puller for Mechanic to get front Pulley off of motor	
4/24/2022	4	WARD, DEVIN	Drove out to machine, cleaned out tapped holes on crank shaft dampener with a tap, used custom made puller to remove dampener, removed remains of front crank seal from front housing and dampener, cleaned mounting surfaces, installed new front crank seal, installed dampener torqued dampener in place at 140ft/lb, got pulled out of site, drove back to laydown	



00877 [DEERE 9320 4WD TRACTOR]

Equipment History From August 18, 2018 to August 19, 2026

4/23/2022	4	WARD, DEVIN	Drove out to machine, attempted to remove crankshaft dampener with two jaw and three jaw pullers , tools measurements to build custom hbar puller back at laydown, got stuck in the sand had to wait to get pulled out	
4/22/2022	4.5	WARD, DEVIN	Gathered parts, drove out to machine, removed covers and panels, removed fan belt and tensioner, removed fan, was call off for another job will return latter	
4/21/2022	2	WARD, DEVIN	Inspected machine for engine oil leak at front, found machine is leaking from front main seal, Will order parts for machine	
Item: 102226 - Coolant leak				
4/20/2022	2	MACLEOD, CHRISTIAN	Ran unit up and checked for leaks	
4/20/2022	2.5	MOSER, ALEX	Replace coolant hose on Right-side	
4/19/2022	2	MACLEOD, CHRISTIAN	Found line from water pump to tank broke replaced line	
Item: 101474 - Check over				
4/13/2022	2.5	GAGNE, DALE	Check fluids start warm blow out rads check tire pressure	
VO: 93544 - May 2022 - Running Repairs (5870 HR)				Closed
Item: 107255 - Hydraulics				
5/31/2022	8	DAVIDSON, MIKE	Blew Hydraulics line from rear of tractor to front pain in the ass hose	
Item: 106278 - Electrical				
5/22/2022	2	DAVIDSON, MIKE	Electrical problems lose wire on slow burn fuse check out fuel issue too had service but fuel filter was not changed drain water separator	
Item: 103948 - Repair lights				
5/3/2022	2	TOMASZEWSKI, DALE	Repair wiring to rear lights and replace burnt out bulbs	
Item: 103660 - Good struts				
5/2/2022	1	TOMASZEWSKI, DALE	Seat inspection	
5/1/2022	2	WALKER, BRAD	Install hood strut	
VO: 93545 - June 2022 - Running Repairs (6175 HR)				Closed
Item: 110198 - Fuel issue				
6/24/2022	3	PARKER, TYLER	Change fuel filters Prime system Crank no start Losing prime Inspect and find leak at separator bowl Lube oring tighten bowl Prime Start unit Order oring	
Item: 110161 - Codes				
6/24/2022	1	MEYER, DUSTIN	Went to unit and checked codes. Ecu 59 coming up, only happened 3 times and it's for fuel pressure moderately high. Let operator continue to run.	
Item: 110009 - Hyd lines hanging down				
6/23/2022	1	FOWLIE, JORDAN	Drive to trappers cabin, tie up all hyd lines for tractor and disc attachment	
Item: 107966 - No start, remove Implement				
6/5/2022	1	WARD, DEVIN	Machine apparently does not start, drove out to machine, started tractor, showed operators how to drop the implement	
Item: 107728 - Hydraulic leak				



6/3/2022	8	WARD, DEVIN	Hydraulic leak coming from remote pressure line behind cab, remove covers and clamps, had hydraulic oil tank sucked out to prevent spill onto the ground, remote load sense line had been pinched and also had a slow leak, removed lines and capped open hydraulics, built new lines back at fho, ran lines through machine, replaced old o-rings, installed lines, had hydraulic oil filled, ran and tested machine	
Item: 106445 - Plow bolts				
6/26/2022	12	SPARKS, BRADLEY	Build wrench for mechanic to get bolts loose	
5/23/2022	2	DAVIDSON, MIKE	Bolts on disc came lose	
Item: 101642 - Drag				
6/25/2022	1	MARQUIS, DANIEL	Remove shackles and relocate	
4/14/2022	6	BERKHOLTZ, RILEY	Cut 2 8M long pipes and cut holes in ends for clevis for drag	
4/14/2022	5	KEAST, GREG	Cut pipe into sections for drags, cut holes for shackles	
VO: 92385 - (1000) FARM TRACTOR STANDARD PROGRAM (6175				Closed
Item: 106089 - (1000) FARM TRACTOR STANDARD PROGRAM				
2022-06-				
VO: 88491 - (250) FARM TRACTOR STANDARD PROGRAM (5828 HR)				Closed
Item: 97977 - (250) FARM TRACTOR STANDARD PROGRAM				
2022-05-				
VO: 81056 - (500) FARM TRACTOR STANDARD PROGRAM (5662 HR)				Closed
Item: 95896 - (500) FARM TRACTOR STANDARD PROGRAM				
2022-03-				
VO: 79035 - (250) FARM TRACTOR STANDARD PROGRAM (5459 HR)				Closed
Item: 65590 - (250) FARM TRACTOR STANDARD PROGRAM				
2022-02-				
VO: 78320 - Transmission codes (5296 HR)				Closed
Item: 95098 - Transmission codes				
2/17/2022	1	WARD, DEVIN	Ran and warmed up machine, transmission throws codes when put in gear, worked hydraulics to heat up transmission oil, codes went away, no stored codes on service advisor, ran and tested machine	
VO: 77991 - Fuel issues (5464 HR)				Closed
Item: 94719 - Fuel issues				
2/25/2022	2	NAUMANN, KEVIN	Changed the leaking hand pump plus the check valve in the return line fuel was leaking back to the tank tested and working good	
2/25/2022	1	THRONBERG, KANE	Replace fuel check valve	
2/14/2022	3	NAUMANN, KEVIN	Charged the batteries and bled the fuel system the Han primer leaks bad ordered a new one and the check valve for the return to top bleeding back to the tank	
2/14/2022	3	THRONBERG, KANE	Filled filters half with diesel, half with meltdown and got primed and fired up	
VO: 71690 - Oil leaks (5248 HR)				Closed



00877 [DEERE 9320 4WD TRACTOR]

Equipment History From August 18, 2018 to August 19, 2026

Item: 88058 - Oil leaks				
12/21/2021	2	DOMIANCZUK, JOHN	Unit has engine oil leaks tighten up lines and check over	
VO: 70896 - No fuel cap (5170 HR)				Closed
Item: 87233 - No fuel cap				
12/14/2021	3	TOMASZEWSKI, DALE	Heat and boost unit	
12/14/2021	1	THRONBERG, KANE	Put bag over fuel fill port	
VO: 65426 - Oil Leak (5155 HR)				Closed
Item: 81561 - Oil Leak				
10/25/2021	1	BARRETT, JOHN	Noticed oil on front of engine right side. Need to clean and locate leak source.	
VO: 65432 - No start (5155 HR)				Closed
Item: 81567 - No start				
10/25/2021	1	TOMASZEWSKI, DALE	Repair no start and hook up disk	
VO: 64042 - Hydraulic leak (5155 HR)				Closed
Item: 80170 - Hydraulic leak				
10/10/2021	2	MITCHELL, JORDAN	Machine leaking oil from the quick connector valves on the hitch. Took off plate to get part numbers and ordered new inserts for the quick connectors and new hose ends	
VO: 61335 - Broken bolt (5085 HR)				Closed
Item: 77420 - Broken bolt				
9/10/2021	4	YOUNG, DELLON	Fixed the disc hitch and got 2 new hoses made up	
9/10/2021	3	KRASOWSKI, STEVEN	Welding repair on disc	
VO: 60916 - Lights (5054 HR)				Closed
Item: 76982 - Lights				
9/5/2021	2	YOUNG, DELLON	Started to replace lights. Had to run back to the laydown to get more lights	
VO: 60859 - Low power (5054 HR)				Closed
Item: 76924 - Low power				
9/5/2021	3	HODGSON, VAUGHN	Troubleshoot low power problem and fix lights	
VO: 59492 - Leaking hose (4993 HR)				Closed
Item: 75493 - Leaking hose				
8/19/2021	3	HENWOOD, SABASTIAN	Installed new hose No leaks Level good	
VO: 59486 - Boost unit (4993 HR)				Closed
Item: 75487 - Boost unit				
8/19/2021	3	ELLIOTT, TRAVIS	Check levels. Boost unit. Batteries too dead. Have new batteries brought out. Replace batteries and start	
VO: 59489 - Repair hyd leak (4993 HR)				Closed
Item: 75490 - Repair hyd leak				
8/20/2021	1.5	FEDORUK, MIKE	Reseal control valve coupler cartridges	
8/19/2021	3	POUDRIER, JOE	Help hook unit to disc and test. Found pin hole in hose. Removed hose and rebuilt it.	
VO: 47893 - Premobe (4897 HR)				Closed



Item: 63027 - Premobe				
4/7/2021	2	GOLOS, SHAWN	check over premobe	
VO: 46171 - (500) FARM TRACTOR STANDARD PROGRAM (4993 HR)				Closed
Item: 60814 - (500) FARM TRACTOR STANDARD PROGRAM				
210506 - 877 -				
VO: 42966 - MOB 210129 SYN (4402 HR)				Closed
Item: 56979 - MOB 210129 SYN				
210129 - 877 -				
VO: 37068 - Repair to MOB (3531 HR)				Closed
Item: 50004 - Repairs to MOB unit				
2/15/2021	2	HANSON, KELSEY	diangose fogging windows	
2/6/2021	3	HANSON, KELSEY	repair seat	
1/27/2021	4	ALLAN, ROB	replace draw bar hitch, clean cab glass, install belly tarp and front screen tarp. clean off debris for trucking.	
1/27/2021	1	MINTER, TANNER	finish build up/ square up hitch, install hitch assembly, weld chain onto pin,	
1/25/2021	1.5	MINTER, TANNER	remove hold htch assembly, clean up hitch, paint	
1/22/2021	1.5	MINTER, TANNER	install brackets/ side covers, modify bracket, clean up work area	
1/21/2021	1	ALLAN, ROB	adjust tire inflation pressures	
1/21/2021	9.5	MINTER, TANNER	finish fitting brackets, remove brackets from tractor, cuut fit and tac stiffeners, weld out brackets, round corners, grind down sharp edges, make handles for side pannells, measure tire clearence to make sure bump stops are correct, weld pin keeper on rear hitch, clean up work area	
1/20/2021	8.5	MINTER, TANNER	make parts for brackets/ build brackets for winter side gaurds	
1/19/2021	9.5	MINTER, TANNER	make room/ move unit into bay, remove bump stops/ build up bump stops, put bump stops back on, build up bump stop pads, make parts/ fit parts to make mounts for winter sides, clean up work area	
1/7/2021	6.5	ALLAN, ROB	move out hub on back left. check levels and remove front bumper plastic torque wheels, and drive unit around yard and repeat until hubs remain tight. check for transmission errors. while operating. grease steady bearing.	
1/6/2021	9.5	ALLAN, ROB	position tractor to line up axle shaft turning tool. block up one wheel at a time. clean up axle shafts with a wire wheel, tap pusher bores. strike free wedges and move wheel hubs out on three wheels and torque hubs to 450 lbs. re position 3 times.	
12/19/2020	3	ALLAN, ROB	install turbo, re connect lines and fittings. supplied drain gasket wrong, search for gasket, find proper. install. prelube turbo. check fluid levels, and test operation. top up trans/hyd oil. back uint out of shop.	
12/16/2020	6	ALLAN, ROB	clean up head area, route remove and replace rocker arm on rocker shaft. install assembly with new hardware and torque to yield bolts. install injector harness. setup valve lash and injector lash.	



00877 [DEERE 9320 4WD TRACTOR]

Equipment History From August 18, 2018 to August 19, 2026

12/2/2020	9.5	ALLAN, ROB	move unit and retorque wheels. repeat until wedges maintain torque. drill out broken fasteners on rad and extract. rethread and replace several rive nuts.	
12/1/2020	9.5	ALLAN, ROB	replace clutch position micro switches. read up on adjustment. calibrate positions. block up front of tractor with yellow stands, loosen up hubs and break free wedges, move wheels out. and torque. make repairs to coolant recovery tank mounting.	
11/30/2020	9.5	ALLAN, ROB	inspect turbo and find bearings worn out. remove turbo and send to NH diesel. remove parts to gain access to valve cover and adjust valve lash. find cyl#2 exhaust rocker arm roller pitting and flaking. roll engine to TDC #1 and pin. back off valves remove rocker shaft. order parts. clamp and secure block heater. install cab surround plastics. replace exhasut pipeing retainer hardware. replace loom and secure air restriction sensor and engine oil pressure sensor. replace fuse box cover, replace drivers window weatherstrip	
11/27/2020	9.5	ALLAN, ROB	replace sill guard from repairs, install right side window. shim and adjust air intake to close lid. replace multifunction switch for horn, connect loadsense line. route and securw lines. extract siezed bolt for hose clamps. secure front diff return line. remove left door window weatherstrip. remove and replace block heater cord. install stump pan. troubleshoot pcu code 21 for clutch signal mismatch and test switches.	
11/26/2020	9.5	ALLAN, ROB	remove right cab window assembly to gain access to right side cab fairing for repairs. remove lower sill plate for repairs and straighten out. remove right fuel tank top and side covers to remove debris and replace broken hardware. replace blown rear window shocks. remove rear fairing for repairs. vacuum and dig out debris from around fuel tank. Mount fire ext over rear axle	
11/25/2020	9.5	ALLAN, ROB	perform 2000hr service, fill fuel tank, hydraulics, trans (replace trans sight glass), fill diffs, and engine. replace alt belt and tensioner. replace fan belt. install fan guards and hood supports. adjust latch. install fairing below cab. and complete fuel tank guards and support adjustments. replace load sense line to rear hydraulic control valve. dry fit and adjust fuel tank cross over guard.	
11/25/2020	1	MINTER, TANNER	weld in stiffener for gaurd, build mounting plate for fire ext	
11/24/2020	9.5	ALLAN, ROB	assemble and adjust brackets and guards to hold fuel tank in place, handrails and ladder assembly. drill out and extract broken bolts holding stump pan and fuel crossover guard.	
11/24/2020	2.5	MINTER, TANNER	repair/ cut out section of walk way, starighten bent support, test fit, straighten bent fuel gaurd/support	
11/23/2020	9	ALLAN, ROB	repair wiring harness over gudeon and rear axle. assemble and install left fuel tank and guarding. straighten out to fit.	
11/23/2020	1	MINTER, TANNER	finish repairing catwalk	
11/20/2020	9.5	ALLAN, ROB	remove right armrest clean out garbage from inside. tighten loose hardware. found loose spring and neutral safety switch. test switches for operation. install repaired roof marker lights. install repaired hood. check cab clutch and brake switches. re-assemble dash console. clean up wiring and secure. replace floor mat and sound deadener. repair wire harness on back of trans.	

11/20/2020	0.5	MINTER, TANNER	straighten tarp for fenders	
11/19/2020	9.5	ALLAN, ROB	repair right side wiring for signals and markers. replaced bulbs and repaired roof marker housings. repaired wiring air intake housing to right over width marker/signal. rubbed through. replaced trans cooler suction hose. removed broken trans sight glass assembly. troubleshoot trans wiring (multiple bypass at main harness bulkhead connector. repair wiring to park solenoid .	
11/19/2020	5.5	MINTER, TANNER	straighten/ repair bent and broken pannells	
11/18/2020	7	ALLAN, ROB	remove cab floor and hardware, vacuum out. dis-assemble steering column and troubleshoot horn operation. find micro switch failed. remove signal stat assembly. check load center and troubleshoot loose right console controls. and loose switches.	
11/18/2020	3.5	MINTER, TANNER	straighten / repair bent pannells,	
11/17/2020	9.5	ALLAN, ROB	remove fuel crossover gauarding. remove signal arm and guarding and remove fuel tank. cleanup dirt/debris. remove left steering cylinder. remove crushed hose from trans pump, remove cracked hood. remove fan finger guards to gain access to worn belt tensioner. inspect for leak at engine filler neck. clean out cab, check operation of everything and make parts list.	
11/16/2020	9.5	ALLAN, ROB	remove cab access stair case and fuel tank guarding for repairs. drain trans to remove crushed suction pipe. drain fuel tanks to remove left saddle tank. inspect unit.	
Item: 50003 - repairs to start unit and remove disc				
11/13/2020	3	ALLAN, ROB	rig up 780 and take to tractor in yard. check starting circuit for faults and ensure start signal turns on/off properly. load circuit with light bulb. replace faulty master disconnect. install starter and start. verify proper function. unit has transmission issues. sweep off and bring in shop.	
11/12/2020	1.5	ALLAN, ROB	rig up and install starter and batteries. start unit. find starter running on. and trans flashing codes. shut down. remove starter.	
11/10/2020	2	ALLAN, ROB	start 780 and welder grab batt booster. try to start unit. find starter defective. remove starter and batteries to bring inside and charge. remove disc from rear hitch.	
VO: 31990 - check over wash lights (845 HR)				Closed
Item: 43953 - check over wash lights				
8/28/2020	1	DU PLESSIS, RYNO	get unit fired up to be hauled off site	
7/11/2020	10	PURCHA, GEORGE (WES)	wash check lights hook up to disc	
VO: 28867 - repair hyd hoses (831 HR)				Closed
Item: 39233 - repair hyd leaks				
2/21/2020	5	WAKELAM, PARKER	repair hydraulic leaks	
VO: 28951 - A Service (831 HR)				Closed
Item: 39353 - A Service				
VO: 25818 - Syncrude January 2020 Running Repairs (797 HR)				Closed
Item: 34746 - Inspect RHF Tire and repair as required.				

1/8/2020	2	WASCHUK, AARON	Inspect RHF Tire for seperation. Seperation confirmed. Advised tire crew and removed unit from service.	
Item: 34507 - Repair/Replace Tire Tow Cables				
2/6/2020	2	OBRIGEWITCH, CHASE	repair and boost	
1/6/2020	4	WASCHUK, AARON	Inspect tow cables. Broken and frayed. Source parts. Travel to PCY and pick up parts. Return to site. Install new cables and test operation.	
VO: 25054 - running repairs (447 HR)				Closed
Item: 33468 - fill low tire ..valve stem leaking				
1/3/2020	2	WASCHUK, AARON	Inspect tire for leaks. Filled to spec and released to operations. Rim bent previously from running on a flat tire	
12/28/2019	3	WANAMAKER, CURTIS	Repair hardware that holds tire to cable	
VO: 24569 - Syncrude December 2019 Running Repairs (3720 HR)				Closed
Item: 32846 - Inspect and Repair Seat As Necessary				
12/17/2019	4	WASCHUK, AARON	Rewire/Replumb seat to operate once required parts arrived. Test operation.	
12/16/2019	4	WASCHUK, AARON	Diagnose and Repair Seat Operation. Wiring and Air system completely destroyed due to running with no air. Repair as rquired and order parts needed.	
Item: 32329 - Bent steps, fron tand back lights out, no horn, no spill kit				
12/22/2019	2	WASCHUK, AARON	Replace broken step and adjust fluid levels.	
VO: 23945 - remove outside wheel assemblies (3660 HR)				Closed
Item: 32072 - remove outside wheel assemliies				
12/13/2019	4	WASCHUK, AARON	Diagnose unit for no start/repair as necessary	
12/8/2019	4	PORTER, SHELDON	remove outside wheel assemblies to avoid debris from getting stuck in between..tarp in	
VO: 23064 - fix lights (3531 HR)				Closed
Item: 30905 - Engine Exhaust				
12/1/2019	2	MALANOWICH, CRAIG	chang out air box and exsust	
11/30/2019	5	MILLER, JASON	exhaust and air box	
11/27/2019	3	PURCHA, GEORGE (WES)	order parts air intake exhaust oil lines	
11/27/2019	3	MALANOWICH, CRAIG	check for leaks oder line	
11/26/2019	3	PURCHA, GEORGE (WES)	check over unhook disc order parts	
11/26/2019	2	MALANOWICH, CRAIG	repair lights	
VO: 21522 - B-Service (3495 HR)				Closed
Item: 28794 - B - Service				
12/1/2019	4	MILLER, JASON	replace exhaust and air box	
VO: 17819 - Demob (3422 HR)				Closed
Item: 24116 - Demob				
Notes: Proceeded to DeMob after fixing hydraulic fittings and flat tire to move stuff from around Kello-Bilt disk. Completed the DeMob inspection sheet.				
17778.pdf				
8/13/2019	3	LEBLANC, ROCH	Demob #877 and Kello bilt # D77 and repairs	



00877 [DEERE 9320 4WD TRACTOR]
Equipment History From August 18, 2018 to August 19, 2026

VO: 11386 - Change alternator (3414 HR)				Closed
Item: 15308 - Change alternator				
4/17/2019	2	SAUNDERS, AUSTIN	Change alternator	
VO: 10931 - No start (3389 HR)				Closed
Item: 14729 - No start				
4/9/2019	2	COSTA, CHRISTOPHER	No start	
VO: 10884 - Replace coupler valves (3389 HR)				Closed
Item: 14676 - Replace coupler valves				
4/8/2019	3	COSTA, CHRISTOPHER	Replace coupler valves	
Item: 14675 - Repair filter housing				
4/8/2019	2	COSTA, CHRISTOPHER	Replace filter lines	
VO: 9952 - Fill up tire (3383 HR)				Closed
Item: 13505 - Fill Tire				
3/24/2019	2	SAUNDERS, AUSTIN	Fill tire	
VO: 9979 - C-Service (3380 HR)				Closed
Item: 13533 - C-Service				
877-Service(9979)-				
VO: 7994 - Fill RR duals up (3324 HR)				Closed
Item: 11039 - Fill RR duals up				
2/15/2019	1	WRUBLESKI, JONATHAN	Fill RR duals up	
VO: 7998 - Install fuel primer/ prime fuel (3324 HR)				Closed
Item: 11043 - Diagnose no start				
2/15/2019	3	HANSON, KELSEY	Replace fuel primer pump	
VO: 7738 - Ordered parts (3335 HR)				Closed
Item: 10680 - Ordered parts				
Notes: Waiting for parts				
2/11/2019	2	MASON, JONATHAN	Waiting for parts	
VO: 7639 - Prime fuel system/ boost (3266 HR)				Closed
Item: 10537 - Machine was ran out of fuel and misc codes				
Notes: Bleed fuel system, boost , remove air from air locked head. Purge out air, repeat. Run machine check for codes return back to work. Also had a complaint for				
2/9/2019	2.5	HANSON, KELSEY	Bleed air from fuel system check for codes	
VO: 7543 - No Start (3266 HR)				Closed
Item: 10426 - No Start				
2/8/2019	3	HOLDEN, JOSHUA	No Start	
Item: 8471 - Seat won't hold air				
Notes:				
VO: 7562 - No start (3330 HR)				Closed
Item: 10445 - No start				



00877 [DEERE 9320 4WD TRACTOR]
Equipment History From August 18, 2018 to August 19, 2026

Notes:				
2/8/2019	8	MASON, JONATHAN	No start	
VO: 7424 - Check trans fault codes (3266 HR)				Closed
Item: 10276 - Check trans fault codes				
Notes: Parts previously ordered				
2/6/2019	1	DEMATTOS, DAKOTA	Check trans fault codes	
VO: 7458 - Coolant leak (surge tank) (3266 HR)				Closed
Item: 10028 - Coolant leak (surge tank)				
2/5/2019	2	NEMETZ, STACY	Coolant leak (surge tank)	
2/4/2019	10	NEMETZ, STACY	Coolant leak (surge tank)	
VO: 7326 - Transmission code (3325 HR)				Closed
Item: 10131 - Transmission code				
2/18/2019	2.5	NEMETZ, STACY	Transmission Code	
2/5/2019	6	NEMETZ, STACY	Transmission code	
VO: 7322 - B Service (3215 HR)				Closed
Item: 10094 - B Service				
877-Service-				
VO: 6235 - No start (3050 HR)				Closed
Item: 8721 - No start				
1/10/2019	1.5	MACRAE-GARDNER, CONNOR	Boost unit	
VO: 6089 - Tighten front gang (3043 HR)				Closed
Item: 8450 - Tighten front gang				
1/4/2019	5	WRUBLESKI, JONATHAN	Tighten front gang	
VO: 6030 - Hyd leak (3020 HR)				Closed
Item: 8364 - Hyd leak				
1/2/2019	2	WRUBLESKI, JONATHAN	Hyd leak	
VO: 5483 - Install radiator (2958 HR)				Closed
Item: 7567 - Install radiator				
12/18/2018	3	HODGSON, VAUGHN	Install radiator	
12/17/2018	6	HODGSON, VAUGHN	Replace radiator	
VO: 4660 - Cutting codes (2941 HR)				Closed
Item: 6295 - Cutting codes				
11/25/2018	2	LITTLE, JAMES (MIKE)	Cutting codes	
VO: 4568 - Leaks (2930 HR)				Closed
Item: 6187 - Leaks on back block				
11/23/2018	1	KELL, KELSEY	Repaired leak	