

VO: 218138 - make sale ready

Open

Item: 239537 - make sale ready			
6/18/2026	2.5	MINTER, TANNER	repair brackets, straighten /repair railing
6/18/2026	9	HILLS, KYLE	remove fender brackets and straighten and weld up cracks. fix RH handrail on and off machine heat and comealong, tie up wires and hoses hanging.
6/17/2026	7	HILLS, KYLE	bring into bay and set boom on stand, quick attach not working or backwards. try but hoses leaking, remove leaking hoses for quick attach. remove holding valve and reseal all fittings, build 2 new hoses and shorten the length, test at all angles. quick attach won't work test voltage at solenoid and can ear sol. clicking. trace lines and see they go back to tilt cylinder. test and quick attach works no leaks and is the right way.

VO: 211727 - Replace fuel injectors

Open

Item: 233021 - Replace fuel injectors			
6/6/2026	3	BEISEL, JASON	Install hood side covers checked fluids test ran outside
6/5/2026	12	BEISEL, JASON	Install injectors rocker arms Set valves and injectors Installed valve cover exhaust and air filter hosing and hood Topped off fluids and started machine
6/4/2026	8	BEISEL, JASON	Clean top of head injectors cups cyl and injectors look up all specs
3/13/2026	6	BEISEL, JASON	Clean up parts make parts list clean head and injector cups
3/12/2026	12	BEISEL, JASON	Get machine running move into shop Pull hood air filter housing exhaust and valve cover Remove rocker shafts injectors and injector sleeves Had to build puller for sleeves

VO: 210629 - Machine stoped running

Open

Item: 231919 - Machine stoped running			
3/11/2026	2	BEISEL, JASON	Get heat on unit charge battery's
3/4/2026	5	GOLOS, SCOTT	Install new filters housing and prime system Get machine running and run around yard Machine dies when it goes into head load Won't restart as if it's losing prime 70psi fuel pressure on low side when dying Install clear line on delivery from transfer pump to head - solid fuel Put on return side and has lots of air Ordered injector cups
3/4/2026	2	GOLOS, SHAWN	Help with troubleshooting
3/4/2026	3	MACCONNELL, DOUGLAS	Diagnosis fuel issues
3/3/2026	8	GOLOS, SCOTT	Wire in and hoses up pump
3/3/2026	3	PETERS, MICHAEL	Fabbed primer pump mount
2/28/2026	4	GOLOS, SCOTT	Loop delivery and return lines around fuel filter Install ball valve in return line Get running and move into shop Remove fuel filter assembly and look for issues Found that the stem wasnt allowing fuel to flow thru to outlet side Order filter assembly
2/28/2026	4	GOLOS, SHAWN	Troubleshoot and get running. Get into shop and order parts



01115 [DEERE 744J WHEEL LOADER]
Equipment History From August 25, 2016 to August 19, 2026

2/27/2026	3	GOLOS, SCOTT	Machine died on hill Check fuel supply - no fuel at all Blow back thru line and clear blockage pressure tank and still barely any fuel Heat fuel tank and get good flow but nothing across filter Heat for night	
2/27/2026	3	GOLOS, SHAWN	Troubleshoot no start	
2/27/2026	4	HOLTZ, AUSTIN	Primed machine after it got low on fuel/ran out of fuel/froze up	
VO: 209348 - Filters				Open
Item: 230644 - Filters				
2/11/2026	2	MOORCROFT, ANDREW	Finish Completeing service	
VO: 209177 - (2000) SERVICE - LOADER STANDARD PROGRAM				Open
Item: 230475 - (2000) SERVICE - LOADER STANDARD PROGRAM				
VO: 206157 - replace belts and pulleys				Open
Item: 227419 - replace belts and pulleys				
12/31/2025	12	MUROWCHUK, MEL	replace belts idler pulleys tensioners repair leak at quick attach	
VO: 205276 - Install winter covers				Open
Item: 226539 - Install winter covers				
1/18/2026	1.5	MICHAUD, DANIEL	Used loader to assist in was bay moving cooler pack around	
12/15/2025	2	BEISEL, JASON	Install canvas on radiator and hood	
VO: 198414 - (500) SERVICE - LOADER STANDARD PROGRAM				Closed
Item: 219344 - (500) SERVICE - LOADER STANDARD PROGRAM				
260202-1115-				
2/9/2026	2	MOORCROFT, ANDREW	Check on filter order still waiting on rest of filters to complete service	
2/2/2026	4	MOORCROFT, ANDREW	Start service	
1/29/2026	1	MOORCROFT, ANDREW	Look for filters and order what is needed	
VO: 192756 - (4000) PM - LOADERS				Open
Item: 213109 - (4000) PM - LOADERS				
8/14/2025	4	PETERS, MICHAEL	Straightened bent quick attach parts, ground everything up and welded piece back on	
VO: 189329 - (250) SERVICE - LOADER STANDARD PROGRAM				Closed
Item: 209320 - (250) SERVICE - LOADER STANDARD PROGRAM				
250903-1115-				
VO: 189398 - No start (24465 HR)				Closed
Item: 209386 - No start				
5/7/2025	1	GOLOS, SCOTT	Charge batteries Bleed air out of low side fuel system Pinch off return line and start machine Leave running for charge and check for start Good	
5/7/2025	1	BRACE, AARON	Boosted unit with other loader and primed air out of fuel system got unit running	
5/6/2025	4	COOK, CHAD	Install new fuel lift pump and low pressure fuel regulator Prime fuel system Unit will not start	
5/6/2025	4	PROUDFOOT, BRADLEY	Prime unit replace check valve follow diagnostic tree still no start ran out of time	
VO: 189200 - No start (24465 HR)				Closed
Item: 209199 - No start				

5/5/2025	2	COOK, CHAD	Remove fuel pump	
5/4/2025	7	COOK, CHAD	Diag for no start Replace weak batteries Install rebuilt starter Test for fuel flow. Fuel is flowing at 55psi, kin spec is 110psi Order pump	
VO: 187475 - back left tire flat (24196 HR)				Closed
Item: 207455 - back left tire flat				
4/15/2025	2	KEAST, RUSSELL	installed new back left o ring and buffed rim	
4/15/2025	2	CHRISTENSEN, TRAVIS	installed new lrft rear o ring and cleaned and buffed rim	
VO: 182750 - (1000) SERVICE - LOADER STANDARD PROGRAM				Closed
Item: 202529 - (1000) SERVICE - LOADER STANDARD PROGRAM				
250503-1115-				
5/4/2025	6	MICHAUD, DANIEL	Assisted tech with service, greased unit Unit would not start after service, primed fuel and bled fuel lines of air, still no start, checked fuses and charged batteries, still no start.	
5/3/2025	7	GRAY, JAMES	Service and grease unit no start after Service troubleshoot no start found low fuel pressures to and from pump . Parts ordered	
5/2/2025	1	GRAY, JAMES	Pulled to service to find out we don't have any filters for unit . Ordered filters	
VO: 181562 - Replace seat (23930 HR)				Closed
Item: 201338 - Replace seat				
2/9/2025	4	WANAMAKER, CURTIS	Replace operator seat, modify to fit new.	
VO: 179667 - (250) SERVICE - LOADER STANDARD PROGRAM				Closed
Item: 199254 - (250) SERVICE - LOADER STANDARD PROGRAM				
250219-1115-				
2/19/2025	4	MICHAUD, DANIEL	Picked filters and service, had to re prime fuel system 3 times to keep it running	
2/19/2025	3	COCHLIN, RYAN	Assist with getting fuel primed and getting unit started. Bleed all lines and prime filter housing.	
1/22/2025	3	GRAY, JAMES	Change trans,hyd,fuel filters that were missing from kit at service time . Run machine up to temp in yard check levels and for leaks	
VO: 175726 - Cab repairs (23395 HR)				Closed
Item: 194895 - Cab repairs				
12/20/2024	6	FOSTER, COLIN	Repaired steering column	
12/2/2024	3	FOSTER, COLIN	Went through cab as per Erick and made parts list for repairing cab	
VO: 175484 - Trans slipping/poping out of gear (23395 HR)				Closed
Item: 194651 - Trans slipping/poping out of gear				
12/20/2024	6	FOSTER, COLIN	Ran unit in yard, no faults. Replaced batteries and replaced 1 batter cable end. Calibrated Trans 2 times.	
12/19/2024	9	FOSTER, COLIN	Pulled codes. Checked Trans speed sensors wiring all checks fine. Checked clutch pressures and within spec.	
12/2/2024	4	FOSTER, COLIN	Bring unit in and change Trans filters. Cut filters and inspected no material found. Calibrated Trans again	



01115 [DEERE 744J WHEEL LOADER]

Equipment History From August 25, 2016 to August 19, 2026

11/29/2024	6	FOSTER, COLIN	Limp unit into shop. Checked oil levels and codes. Checked wiring to Trans. Warmed up unit and calibrated Trans. Ordered new Trans filter so I can cut ones on unit. Waiting for filters	
VO: 171815 - (500) SERVICE - LOADER STANDARD PROGRAM				Closed
Item: 190378 - (500) SERVICE - LOADER STANDARD PROGRAM				
250117-1115-				
1/18/2025	3	GRAY, JAMES	Service and grease. Remove broken grease lines and replace with nipples on steering cylinders wrong filters Fuel,trans,hyd	
1/18/2025	3	BUSU, RADU GABRIEL	-Sample front and rear diff;sample hydraulic oil; top up hydraulic oil; -Replaced ineer and outer air filter - Replaced engine oil filter	
12/13/2024	2	GRAY, JAMES	Change engine oil and filters Fuel filters air filters grease driveline, change hyd filters, trans filters	
VO: 170000 - Broken railings and pin retainers (23117 HR)				Closed
Item: 188426 - Broken railings and pin retainers				
9/5/2024	2	PETERS, MICHAEL	Cut pieces for pin retainers. Straightened handrails	
9/5/2024	3	COLUSSI, RODNEY	Weld new quick attach pin retainers. Weld cracked and bent railings	
VO: 165094 - Fabricate battery cover (23117 HR)				Closed
Item: 182983 - Fabricate battery cover				
6/9/2024	8	MENZIES, TYLER	Cut and fabricate new cove for battery bend weld hinges cut bolt holes and slots for lock and paint and install	
VO: 164097 - (250) SERVICE - LOADER STANDARD PROGRAM				Closed
Item: 182046 - (250) SERVICE - LOADER STANDARD PROGRAM				
241004-1115-				
10/4/2024	3	KAY, CODY	250 hrs Service and Change out hydraulic lines Locking cylinders for the attachments	
VO: 157490 - Pm service (23117 HR)				Closed
Item: 176207 - Pm service				
3/12/2024	4	GRAY, JAMES	2000 hr service Drain and sample all oils. Change all filters, couple filters missing in kit went got them . Changed all oils . Greased unit and filled auto greaser that was empty, blew out hvac box while cab filters were out . List of repairs in cab needs windshield, seat back and shifter falling off also found the output yolk from park brake to front diff is really sloppy on splines	
VO: 157580 - (2000) LOADER STANDARD PROGRAM (23117 HR)				Closed
Item: 176289 - (2000) LOADER STANDARD PROGRAM				
240311-1115-				
VO: 152315 - TS coolant in base (23056 HR)				Closed
Item: 170993 - TS coolant in base				
2/29/2024	4	MUROWCHUK, MEL	install bucket cylinder install seat bottom	
2/21/2024	3	WANAMAKER, CURTIS	Install steer cylinders and hook up grease lines	
1/19/2024	6	MUROWCHUK, MEL	remove steering and bucket cylinders	



01115 [DEERE 744J WHEEL LOADER]
Equipment History From August 25, 2016 to August 19, 2026

1/19/2024	6	SIDOR, JERRY	cheak steering clys bypassing oil tilt cly leaking remove clys send out for repairs	
1/18/2024	12	MUROWCHUK, MEL	bleed out get running check over order parts	
1/17/2024	12	WANAMAKER, CURTIS	Install new water pump and refill system, change engine oil. Start and run engine, unit stalled , attempt to prime fuel system, appears to be air locked. Multiple attempts at priming fuel system, move A frame bearing on 1461 set up for machining, remove return tube off hoist valve. Clean up tooling end of shift	
1/15/2024	6	WANAMAKER, CURTIS	Unhook drive line and push unit into shop, 3/4 tires flat. Blow snow off unit and inspect. Pressure up rad to 10psi, slow leak but system holds overall, remove oil fill cap and slide camera down inspected front gear train and verify leaking water pump front seal, remove water pump, confirm worn bearing / seal submit parts list. Tire crew longed up for repairs. Will need to flush engine oil	
1/15/2024	6	SIDOR, JERRY	pull machine into shop cheak engine for coolant in oil found water pump seal leaking	
VO: 149339 - (250) LOADER STANDARD PROGRAM (23056 HR)				Closed
Notes: No service sheet				
Item: 168007 - (250) LOADER STANDARD PROGRAM				
VO: 149369 - Pm service (23056 HR)				Closed
Item: 168037 - Pm service				
12/3/2023	1	GRAY, JAMES	Assist labour on pm service. Engine oil/filter , fuel , air filters . No cab filters in kit	
VO: 148447 - Install new rad (23056 HR)				Closed
Item: 167100 - Install new rad				
12/1/2023	1	RAIRIE, JOHN	Install side panels run and take out of shop.	
11/21/2023	6	SEWELL, ALEXANDER	Finish aligning everything up, Pressure test system to check for leaks, run machine, check for leaks, Clean work space	
11/20/2023	12	SEWELL, ALEXANDER	Remove panels Unbolt rad support and coolers Remove engine bay cover and rad support Clean around rads Install new rad, hook up lines Pressure test rad-good Install rad support and cover	
VO: 148309 - Install fuel pump (23056 HR)				Closed
Item: 166960 - Install fuel pump				
11/18/2023	4	HANSON, KELSEY	Remove lift pump. Diagnose why no start and find broken coupler.	
VO: 148312 - Install new fuel pump (23056 HR)				Closed
Item: 166963 - Install new fuel pump				
11/19/2023	5	HANSON, KELSEY	Install new lift pump Diagnose no start. Install new relief in filter housing Boost and try to start Ended up putting 100psi of fuel pressure to get air lock out got the loader running and it restarts fine	
11/19/2023	4	SEWELL, ALEXANDER	Install new fuel pump, align pump up Hook up fuel lines, start machine Let machine run, pull into shop	
11/18/2023	3	SEWELL, ALEXANDER	Remove old pump, unbolt fuel lines, remove accessories drive to clear fuel pump from hydraulic tank, Inspect for wear	

VO: 148189 - No start (23056 HR) Closed

Item: 166839 - No start			
2/21/2024	2	SIDOR, JERRY	install steering cly
1/17/2024	6	SIDOR, JERRY	try to get engine started won't run
12/1/2023	3	SEWELL, ALEXANDER	Check relief for back to tank Clean up and install, Prime fuel system Run machine, checks for leaks
11/21/2023	6	SEWELL, ALEXANDER	Runs, try re start, doesn't fire, Charge battery's Grab laptop to go over fuel system break down, put manual gauge inline from pump to head, Pressure up system, fire machine up Idles at 75psi and builds with throttle Remove pickup tube from tank clean line. Check flow to pump Full return line to see if it bleeds overnight
11/17/2023	4	SEWELL, ALEXANDER	Pressure checks fuel system, Clear lines, Clean fuel filter bowl, Check fuel tank for debris Remove inline fuel filter Inspect check valve Charge battery's Order new fuel filter and fuel pump
11/17/2023	4	HANSON, KELSEY	Help with priming abs boosting loader. Find out fuel system is only pushing out 25psi. Order parts
11/16/2023	4	SEWELL, ALEXANDER	No start, charge batteries Clean out fuel lines and fuel filters, bypass inline filter, Still no start Check for fuel in line and filters Further T/S needed

VO: 148087 - T/S RAD leaking (23056 HR) Closed

Item: 166736 - T/S RAD leaking			
1/3/2024	3	SAMPSON, BRIAN	Check rad for leak , pressure test cooling system , found that coolant was going into the oil pan , tagged unit out and let Erik and guy know .
11/15/2023	2	SEWELL, ALEXANDER	Top up rad, cold pressure test cooling system, pin hole leaks in rad. Jump machine to get it running. Order parts

VO: 135642 - Service (23056 HR) Closed

Item: 154217 - Service			
7/2/2023	3	RAIRIE, JOHN	Service
7/2/2023	3	BRACE, AARON	Serviced fuel oil and air

VO: 133659 - No start (23056 HR) Closed

Item: 152249 - No start			
1/19/2024	12	SAMPSON, BRIAN	Repaired leaking check valve in fuel line , Jerry cleaned and re sealed fuel filter housing , bled system and got unit running . Tested steering cylinders for leaks , removed both steering cylinders and lift cylinder to be sent out and re sealed . Locked unit out in front line up
1/18/2024	12	SIDOR, JERRY	engine won't start took fuel filter asy apart and clean and put back on got it running changed engine oil and filter
1/18/2024	6	SAMPSON, BRIAN	Bleed fuel system and try to get unit running
10/9/2023	3	PORTER, SHELDON	Machine ran out of fuel.. bleed and start
7/2/2023	6	HAGEY, ANTHONY	Prime fuel system check for filters for other services no filters found need to order



6/12/2023	4	ELLIOTT, TRAVIS	Check over. Crank no start. Grab fuel truck and fuel up. Bleed fuel system. No change. Check low side pressure. Slow to build 23 psi. Spec 20. Billed again, no change. Dead head transfer pump. Pressure fluctuates between 120-95 psi. Reconnect lines to head. Block off return to tank. Main pressure struggles to build 50 psi. Spec 85-90 psi. Remove high pressure relief. Poppet moves freely but no tension in snap ring. Looks like debris went through high pressure relief. Could not get unstuck. Order new relief and missing screen and retest. Parts ordered	
6/11/2023	1.5	LAVERS, DYLAN	No start. Checked fuses checked/cracked fuel lines has fuel pressure from return line. Checked coolant and engine oil.	
6/11/2023	1	HAGEY, ANTHONY	Check to see why loader won't start unsure tagged loader out and told Eric about it	
VO: 132691 - rad leaking (11584 HR)				Closed
Item: 151295 - rad leaking				
5/31/2023	6	SAMPSON, BRIAN	Remove and replace leaking rad, had charge air cooler re welded for cracks	
5/31/2023	6	SIDOR, JERRY	pressure check rad has pin holes in it , remove rad and replace it , fill with coolant and check for leaks	
VO: 132427 - Intercooler rairs (11584 HR)				Closed
Item: 151028 - Intercooler rairs				
5/31/2023	1.5	SUPER, NEIL	Repair intercooler ,aluminum welds were not welded	
VO: 126079 - Transmission slipping (11584 HR)				Closed
Item: 144715 - Transmission slipping				
4/7/2023	3	PORTER, SHELDON	Check levels and machine operation.. calibrate transmission clutch's	
VO: 119222 - Aultnator (11584 HR)				Closed
Item: 137824 - Aultnator				
2/11/2023	2	PURCHA, GEORGE (WES)	Locate boost change alutnator	
VO: 116553 - Fire up (11584 HR)				Closed
Item: 135135 - Fire up				
1/20/2023	2	WARREN, KEITH	Start up	
VO: 110872 - U joints (11584 HR)				Closed
Item: 129343 - U joints				
11/27/2022	3	SOLOMON, BRYAN	replaced u-joints	
11/27/2022	2	SAMPSON, BRIAN	Remove rear driveline and change u joints as per Craig , installed new ones and greased	
VO: 109519 - D service (11584 HR)				Closed
Item: 127961 - D service				
12/5/2022	12	KAY, CODY	Did a D service	
11/15/2022	9	PURCHA, GEORGE (WES)	Change oils filters hydraulic leaks	
11/15/2022	13	MALANOWICH, CRAIG	D service fixes leaks	
11/15/2022	12	KAY, CODY	D services	
VO: 96419 - Steering column (11584 HR)				Closed
Item: 114498 - Steering column				



8/4/2022	1.5	BREWER, AL	Steering column loose . Checked out and found it was disconnected from adjustment cylinder. Reconnected to cylinder and it works well not .	
VO: 82790 - Replace rad (11584 HR)				Closed
Item: 99885 - Replace rad				
3/31/2022	6	SIDOR, JERRY	finish rad install, fill with coolant	
3/31/2022	5	FOSTER, COLIN	Finish rad install and run unit	
3/30/2022	6	SIDOR, JERRY	remove rad is leaking	
3/30/2022	4	FOSTER, COLIN	Start removing rad	
VO: 77258 - heater not working (11584 HR)				Closed
Item: 93963 - heater not working				
2/7/2022	3	SIDOR, JERRY	heater motor not working, changed heater motor works now	
VO: 47001 - D Service (11584 HR)				Closed
Item: 62047 - D Service				
3/25/2021	12	CASAULT, ETHAN	Completed a D service on 744 wheel loader (1115) Replaced D10 bogey pins on track frames	
VO: 43320 - Minor repairs. (11584 HR)				Closed
Item: 57362 - Minor repairs.				
3/26/2021	12	CASAULT, ETHAN	Replaced grease lines on forks, got the wheel loader running and made sure all the fluids were at the right levels, replaced window wiper and did the timing on 898 and completed a Mobe sheet, took of engine bay panels on 1334	
2/6/2021	12	REYNOLDS, ROY	Repair cab heater.Renew work lights and repair wiring.Locate coolant leak. Order parts.	
VO: 43297 - remove and install rad change lights (11584 HR)				Closed
Item: 57337 - remove and install rad change lights				
3/15/2021	6	FOSTER, COLIN	installed old rad and got unit running, proper rad is ordered.	
3/15/2021	6	SIDOR, ANTHONY	remove and install rad	
3/14/2021	4	FOSTER, COLIN	start rad removal	
3/14/2021	4	SIDOR, ANTHONY	remove rad	
2/6/2021	12	OBRIEN, BILL	remove and install rad replace lights	
VO: 34956 - noisy fan hub (11584 HR)				Closed
Item: 47539 - noisy fan hub				
9/29/2020	9	MUROWCHUK, MEL	rebuild fan hub install hub fan shrouding and condenser	
9/27/2020	3	MUROWCHUK, MEL	disassemble fan hub assembly	
9/26/2020	2	SIDOR, JERRY	remove fan hub assy. and order parts	
VO: 31860 - no oil pressure (11584 HR)				Closed
Item: 43780 - no oil pressure				
7/17/2020	6	MUROWCHUK, MEL	steam out engine bay install engine gaurds and doors hook up rear lighting	
7/16/2020	12	MUROWCHUK, MEL	install ac rad install hood clean fuel lines and system top up oils start	
7/15/2020	12	MUROWCHUK, MEL	install harmonic balancer front crank seal fan pulleys and belts install hard nose hook up rad and coolers	



01115 [DEERE 744J WHEEL LOADER]

Equipment History From August 25, 2016 to August 19, 2026

7/14/2020	12	MUROWCHUK, MEL	reseal engine oil cooler install new relief housing hook up fuel and coolant lines re o ring trans lines replace dipstick tube	
7/13/2020	12	MUROWCHUK, MEL	install new oil pump install front cover install harmonic balancer wrong part remove harmonic balancer	
7/6/2020	10	MUROWCHUK, MEL	dissassemble cooler clean up valving install pump spin up check for oil pressure order parts	
7/5/2020	10	MUROWCHUK, MEL	check relief valve remove front cover remove oil pump	
VO: 31817 - remove engine to repair for no engine oil pressure				Closed
Item: 43726 - remove engine to repair for no engine oil pressure				
7/2/2020	4	PORTER, SHELDON	remove engine	
7/1/2020	4	PORTER, SHELDON	release brakes tow into shop ..start disassembly	
VO: 30992 - will not start (11584 HR)				Closed
Item: 42674 - will not start				
4/26/2020	5	SIDOR, JERRY	machine would not . found fuel hose not good. macke up new hose install, blead fuel systeam got it running	
VO: 19654 - hydraulic leak (11584 HR)				Closed
Item: 26634 - hydralic leak				
Item: 26633 - hydraulic leak				
9/25/2019	3	PURCHA, GEORGE (WES)	order fittings tap and cleen holes assemble top fluids run to test	
VO: 13248 - D SERVICE (11584 HR)				Closed
Item: 17802 - D SERVICE				
5/21/2019	6	VAN ZWYNDREGT, ANDREW	PREFORM D SERVICE, CHANGE ALL FILTERS, CHANGE ALL OILS	
5/21/2019	6	MALANOWICH, CRAIG	Peform D service	
Item: 17743 - perform D service				
5/21/2019	5	FOSS, TEDDIE	D service, fill yard lube truck w/ fluids,	
VO: 7536 - repair grease lines (11584 HR)				Closed
Item: 10417 - repair grease lines				
2/8/2019	4	ALLMANN, TED	repair grease lines	
2/8/2019	6	SIDOR, JERRY	repair grease lines and top off fuilids	
VO: 4868 - Repair broken pin keeper and fabricate pin locks (11584				Closed
Item: 6641 - Repair broken pin keeper and fabricate pin locks				
12/1/2018	4	COLUSSI, RODNEY	Repair broken pin keeper and fabricate pin locks	
VO: 3643 - won't go into forward or reverse (11584 HR)				Closed
Item: 4999 - won't go into forward or reverse				
10/28/2018	2	PURCHA, GEORGE (WES)	trace wires remove shifter inspect order parts	
10/28/2018	2	TRUDEL, GUY	troubleshoot, found fwd rev controller switch short to ground. ordered parts	
VO: 2180 - Repairs to Fork Quick Attach (11584 HR)				Closed
Item: 2993 - Repairs to Fork Quick Attach				
8/6/2018	6	KNUDSLIEN, RICK	Repair Fork Quick Attach	