

NO2-8
SEP

VO: 215198 - Fuel				Open
Item: 236541 - Fuel				
6/15/2026	7	GOLOS, SHAWN	Remove fan, shroud, guards and fuel pump. Install pump, lines, etc. Try and get running. Troubleshoot code	
4/29/2026	2	MOORCROFT, ANDREW	Assist mechanic with loader	
VO: 215206 - No start				Open
Item: 236549 - No start				
8/18/2026	6	HILLS, KYLE	move out of washbay and install bucket, fix bad leak coming from brake valve pressure switch.	
8/17/2026	2	HILLS, KYLE	inspect in wash bay. lift bucket and safety to open hood and wash. bring in battery box.	
8/14/2026	4.5	HILLS, KYLE	put unit back together move into washbay.	
8/13/2026	8.5	HILLS, KYLE	finally get unit started, runs with a miss. keeps pulling air from somewhere. check all connections double check stand pipe in tank and remove suction hose and pressure up. get running again raw fuel leaking out exhaust. Crack injectors to see if any are air locked, find #3 getting no fuel with miss suspect injector. remove injector #3 and find tip half gone and plunger hanging out the side. can blow air right through. get new injector, clean bore install and hook up. engine fired right up, runs good. suck up all implements and drive around to get hot, shut off and restarted numerous times.	
8/12/2026	8.5	HILLS, KYLE	conclude Engine Control Module is faulty. Find out we have warranty in it, remove and give info on what work was completed and Hours. install new backhoe safety lock bar and install park brake release bolts to proper spec. clean up tools. get new ecm back put on and start bleeding fuel system.	
8/11/2026	10	HILLS, KYLE	troubleshoot no start	
8/10/2026	10.5	HILLS, KYLE	troubleshoot no start issue.	
8/7/2026	10.5	HILLS, KYLE	remove beacon cable, finish putting cab back together. get new injection pump, time and install. prime system and get all codes cleared. attempt to start and no go. still not getting fuel. hook up laptop and have coolant temp sense code, also notice not much on controller. possibly need to be programed?	
8/6/2026	10.5	HILLS, KYLE	remove fuel pump from engine, drain overfilled engine oil and hydraulic oil. clean up hyd tank and find crack around filler neck. remove bolts from park brake release and find threads damaged. drill out and install time cert. put valve cover back on install orings and torque to spec, hook up CC vent line clean up wiring harness for engine control module.	
8/5/2026	10.5	HILLS, KYLE	con't troubleshooting no start issue, remove 2way and GPS as well as antennas. find fuel pump solenoid no good. start removing pump.	



00325 [DEERE 310SG LOADER BACKHOE]
Equipment History From July 9, 2015 to August 20, 2026

8/4/2026	8	HILLS, KYLE	make room in bay and get unit pushed in, check B2W and start fresh. read how to get codes, throttle position sensor needs to be calibrated, calibrated and code cleared. checked can wiring, no voltage going to fuel pump solenoid at start. start checking wiring and sensors that engine control unit looks at. crankshaft position sensor wiring good, sensor measures 0 resistance, spec is 2.7-3.3 k ohms.	
7/30/2026	4	GOLOS, SCOTT	Demob and remove decals for sale Died on trailer get running again	
7/30/2026	4	GOLOS, SHAWN	Demobe, remove decals, get running	
6/16/2026	3	GOLOS, SCOTT	Repair some wiring to fuel pump Prime and get running Install hood and other parts Top off all levels and move machine	
6/16/2026	4	GOLOS, SHAWN	bleed, get running, install hood, guarding, etc. Replace outrigger pads	
6/14/2026	4	GOLOS, SHAWN	Start to remove fuel pump	
6/14/2026	5	GOLOS, SCOTT	Injection pump replacement	
5/10/2026	3	GOLOS, SCOTT	Install new engine ecm Now displays ecm and parameters for engine Still no start has pump open circuit when starting Start to troubleshoot	
5/2/2026	9	GOLOS, SCOTT	Pick machine up and move out of back mud hole Check for no start Ecm won't switch from stop fuel mode has a bunch of CAN codes TS codes Ecm controller became unviewable after unhooking and checking wiring Order engine ecm after checking all wiring and has proper power,ground and can wiring and powers	
5/2/2026	12	HOLTZ, AUSTIN	Diagnosed no start	
4/29/2026	6	HOLTZ, AUSTIN	Diagnose no start issues	
4/5/2026	5	GOLOS, SCOTT	Get running for sale Won't start Prime system No signal going to pump	
VO: 193004 - (4000) PM - LOADERS				Open
Item: 213432 - (4000) PM - LOADERS				
VO: 179173 - (1000) SERVICE - LOADER BACKHOE STANDARD				Open
Item: 198759 - (1000) SERVICE - LOADER BACKHOE STANDARD PROGRAM				
VO: 170875 - Won't start (675 HR)				Closed
Item: 189379 - Won't start				
12/19/2024	2	SAMPSON, BRIAN	Got heaters on unit , primed fuel system and get unit running	
12/18/2024	2	SAMPSON, BRIAN	Troubleshoot for no start , found fuel transfer pump was leaking fuel everywhere. Ordered new pump . Installed new pump .	
9/22/2024	2	BEISEL, JASON	Machine was dead checked battery's they where ok checked fused found burnt ones and replaced unit started	
VO: 167652 - No start (9780 HR)				Closed
Item: 185916 - No start				
7/24/2024	6	HANSON, KELSEY	Machine wouldn't start. Found dead batteries. Our boost on. Still no start. Jumped the starter found park brake or gear selector workerd. Started the diagnosing process. Found tranni empty. Hyd super low. Still no fix. Chased wiring found bad fuse for fnr and park brake blown.	
VO: 165652 - Electrical issues (9780 HR)				Closed

Item: 183594 - Electrical issues				
6/19/2024	2	BRACE, AARON	Changed burnt out fuse	
VO: 164099 - (250) LOADER BACKHOE STANDARD PROGRAM (675				Closed
Item: 177683 - (250) LOADER BACKHOE STANDARD PROGRAM				
241029-325-				
12/14/2024	2	BUSU, RADU GABRIEL	Greased all joints and assist mechanich with service	
12/14/2024	3	GRAY, JAMES	Grease , inspect, change engine oil and filters, sample, unit has hyd leaks underneath but needs a good wash to locate	
10/29/2024	4	FRASER, MARKO	Carried out all round inspection, took oil samples, drained engine and transmission oils changed all filters then refilled oils and greased machine.	
10/29/2024	4	ALERTA, JERRIOJOE	Did the 250 with eng oil change and grease machine. Ordered eng air will replace when it arrives.	
VO: 158974 - (500) LOADER BACKHOE STANDARD PROGRAM (9780				Closed
Item: 172052 - (500) LOADER BACKHOE STANDARD PROGRAM				
240313-325-				
VO: 157626 - Service (9780 HR)				Closed
Item: 176336 - Service				
3/13/2024	5	GAUDLEY, MATTHEW	Greased unit drained front and rear diffs refilled both, removed fuel filters as well as oil went and searched for new filters drained oil and refilled took samples of all fluids went threw service sheet and completed air filter is a 2 piece filter 1 small 1 big we had the 1 small ordered the big as well as outside cab filter. Changed inside cab filter removed panels and installed filter reinstalled dash panels	
VO: 153868 - Door latches (9450 HR)				Closed
Item: 172534 - Door latches				
2/4/2024	1	BENNETT, SHEA	Assist John with tightening door latches for laborer	
2/4/2024	1.5	RAIRIE, JOHN	Remove plastic covers set and tighten latches replaced plastic covers.	
VO: 153502 - Replaced tire rod (9450 HR)				Closed
Item: 172164 - Replaced tire rod				
1/28/2024	10	KAY, CODY	Replaced old tyrone ends in center pin for front For the pivot. Replace grease line on top of front drive line. Fixed leak going off the transfer box. Replaced orange On dream plugs. Then check you joints to see how much play they had Still has over 50% of life left. Then had to order new bolts counterweight	
VO: 153393 - (250) Loader Backhoe Standard Program (9450 HR)				Closed
Item: 172049 - (250) Loader Backhoe Standard Program				
VO: 153020 - Service/misc. repairs (9450 HR)				Closed
Item: 171680 - Service/misc. repairs				
1/24/2024	6	BRACE, AARON	Serviced unit and did minor repairs	
VO: 152147 - Repair hydraulic leak (9450 HR)				Closed



00325 [DEERE 310SG LOADER BACKHOE]
Equipment History From July 9, 2015 to August 20, 2026

Item: 170822 - Repair hydraulic leak				
1/28/2024	2	KAY, CODY	Replace blade lift and tote hydraulic lines	
1/13/2024	3	RAIRIE, JOHN	Repair hydraulic leak	
VO: 147898 - charge light on (8869 HR)				Closed
Item: 166540 - charge light on				
11/10/2023	2	SIDOR, JERRY	cheak out charge system , change alternator, put cable back on master switch, fix front light	
VO: 147253 - (2000) LOADER BACKHOE STANDARD PROGRAM				Closed
Item: 165888 - (2000) LOADER BACKHOE STANDARD PROGRAM				
231031-325-				
VO: 142930 - Coolant (5865 HR)				Closed
Item: 161431 - Coolant				
9/13/2023	0.5	PATEY-BROWN, PATRICK	Topped up coolant jug	
VO: 136069 - Door repair (9450 HR)				Closed
Item: 154644 - Door repair				
1/29/2024	3	KAY, CODY	Put new hinge on door so So we'll shut properly, Made a new grease line. And replaced for the old one	
7/6/2023	2.5	RAIRIE, JOHN	Replace door latch. Door shock and doors hinge	
VO: 134691 - Service (5865 HR)				Closed
Item: 153264 - Service				
6/22/2023	2	BRUNTON, RYAN	Replaced oil fuld and air filters. Checked over.	
VO: 133192 - Fixing fuel leak (5865 HR)				Closed
Item: 151788 - Fixing fuel leak				
6/7/2023	2	RICHTER, RYAN	Replace fuel priming pump	
VO: 133262 - Dead battery (5865 HR)				Closed
Item: 151856 - Dead battery				
6/8/2023	2	HOSPERS, FOLKERT	Look for master switch could not find had to boost unit stone dead got started	
VO: 131896 - Replace right rear corner window (5865 HR)				Closed
Item: 150503 - Replace right rear corner window				
6/6/2023	1	KEYES, MITCHELL	Clean frame and glass apply urethane and install glass tape to hold till morning	
5/28/2023	1	KEYES, MITCHELL	Remove remaining seal, found glass ordered wrong side, return to shipping and talk with purchaser about mix up.	
VO: 130281 - A service (5865 HR)				Closed
Item: 148894 - A service				
5/14/2023	6	MALANOWICH, CRAIG	Change engine oil, fule filter and air filter, fule issue needs a new transfer pump	
5/14/2023	6	PURCHA, GEORGE (WES)	Fuel issues service	
VO: 129977 - Tilt hoses replaced/built (5865 HR)				Closed
Item: 148592 - Tilt hoses replaced/built				
5/12/2023	2	HAGEY, ANTHONY	Remove hoses take them to dirt shop and build new hoses and install the new ones	



00325 [DEERE 310SG LOADER BACKHOE]
Equipment History From July 9, 2015 to August 20, 2026

VO: 123805 - No power (5865 HR)				Closed
Item: 142422 - No power				
3/28/2023	3	SOLOMON, BRYAN	built new power cable, installed machine runs how ever massive fuel leak, got into shop found return line damaged, replaced. as well had a bad hyd line on bucket tilt, built and installed	
3/27/2023	4	SOLOMON, BRYAN	troubleshoot electrical for starting the unit, machine was hooked to 24v,changed fuses and found power cable was greened out as well. will build new one tomorrow	
3/20/2023	3	MALANOWICH, CRAIG	Trouble shoot no power issues order a new start	
VO: 102120 - Install back up light (5865 HR)				Closed
Item: 120330 - Install back up light				
9/23/2022	1	MALANOWICH, CRAIG	Install back up light	
VO: 95795 - Crank no start (5865 HR)				Closed
Item: 113809 - Crank no start				
7/26/2022	3	DUBITZ, ADAM	Machine would crank over but wouldn't start verified had fuel coming out of pump and injector lines, had no air shut off found out it was popped fuse for ecm communication	
VO: 95649 - boosted battery (5865 HR)				Closed
Item: 113657 - boosted battery				
7/26/2022	4	KAY, CODY	go to call Batteries dead after boosting the machine wouldn't get fuel fand out a fuse is burnt out so replace it	
VO: 70886 - oil pan gasket and transfer pump (5865 HR)				Closed
Item: 87223 - oil pan gasket and transfer pump				
12/14/2021	6	MALANOWICH, CRAIG	oil pan gasket, fix fule leak and change transfer pump	
VO: 63146 - New themastat (4795 HR)				Closed
Item: 79262 - New themastat				
10/2/2021	2	GIBSON, JASON	Changed thermastat Checked for leaks - tested ok	
10/2/2021	2	BRODIE, RODNEY	Assist with repairs	
10/1/2021	3	GIBSON, JASON	Installed new thermastat and gasket	
VO: 62615 - blower motor (4795 HR)				Closed
Item: 78705 - blower motor				
9/26/2021	5	MALANOWICH, CRAIG	top up colent trobleshot heat problem	
9/25/2021	9	PURCHA, GEORGE (WES)	trobleshot and repair blower motor and clean cab floor and exstract broken bolts	
9/25/2021	9	MALANOWICH, CRAIG	trobelsht and repair blower motor exstract broken bolts clean cab floor	