

VO: 221403 - Carriers				Open
Item: 242806 - Carriers				
8/15/2026	2	MACLEOD, CONNOR	Cleaned tracks removed work carrier roller, installed new carrier roller and torqued caps, ran out of time will complete other side tomorrow	
VO: 217774 - Clean cab				Open
Item: 239176 - Clean cab				
6/11/2026	12	EBORA, WENCESLAO	Clean cab	
VO: 212462 - DEMOB (6035 HR)				Closed
Notes: KEARL ->				
Item: 233753 - DEMOB				
260320-185-				
VO: 212086 - (250) SERVICE - CAT DOZER STANDARD PROGRAM				Open
Item: 233383 - (250) SERVICE - CAT DOZER STANDARD PROGRAM				
VO: 211685 - UC REPORT (5740 HR)				Closed
Item: 232978 - UC REPORT				
CWMS D9N 1JD03				
VO: 211244 - Ripper tooth				Open
Item: 232536 - Ripper tooth				
5/27/2026	2	EVANS, JODY	Put unit on loading ramp. Weld ublot to shank. Set up crane and install ripper shank. Pack up and park dozer	
3/7/2026	1	WESTERHOUD, BERT	Replace ripper tooth	
VO: 210744 - Smoke from rad area				Open
Item: 232034 - Smoke from rad area				
3/5/2026	2	FULLERTON, DERRICK	Replaced fan belt tensioner spring, pin, washers, stud, and nut. Ran unit tested ok	
3/1/2026	2	FULLERTON, DERRICK	Went to unit inspected found belt tensioner spring broken for fan belts. Noticed coolant around top of tank from running hot. Parts list completed unit down	
VO: 210583 - Tooth				Open
Item: 231873 - Tooth				
2/27/2026	1	WARD, DEVIN	Complaint of tooth worn out, grabbed new tooth from laydown, drove out to machine rnr tooth	
2/26/2026	1	WARD, DEVIN	Rnr ripper tooth sent back to work	
VO: 210165 - Prime fuel system				Open
Item: 231459 - Prime fuel system				
2/22/2026	3	GREENFIELD, CURTIS	Prime unit and troubleshoot loss of prime, found diaphragm in transfer pump failed, tested after temporary repair and order parts	
2/22/2026	2	MCCOLLUM, PATRICK	Went to machine pulled fuel bowl and filters full of ice. Cleaned primed machine fired up machine.	



00185 [CAT D9N DOZER]

Equipment History From April 24, 2018 to August 20, 2026

2/21/2026	1	GREENFIELD, CURTIS	Prime unit	
2/21/2026	1.5	MEYER, DUSTIN	Drove from pond 5 to rec dump and primed fuel system. Dozer ran out of fuel.	
VO: 210119 - GET				Open
Item: 231413 - GET				
2/25/2026	1	COLES, RYAN	Grabbed ripper tip from yard, removed old tip and installed new one	
2/25/2026	2	CHERRY, RYAN	Remove shank gaurd and search for new gaurd to install	
2/20/2026	2	GREENFIELD, CURTIS	Wait for dozer to come off pile, Replace ripper tip	
VO: 209732 - Poor heat				Open
Item: 231027 - Poor heat				
2/16/2026	1.5	OLSEN, KIRK	Check unit out, had no tarps. Go to yard and collect material. Tarp unit up.	
VO: 209652 - (500) SERVICE - CAT DOZER STANDARD PROGRAM				Closed
Item: 230948 - ((500) SERVICE - CAT DOZER STANDARD PROGRAM				
260316-185-				
3/16/2026	5.5	TINOCO LANDERO, ALEXANDRE	Performed 500 hr service	
VO: 209505 - Ice lug				Open
Item: 230801 - Ice lug				
3/10/2026	8	KLEMP, GRAHAM	Weld	
2/13/2026	6	BERKHOLTZ, RILEY	Clean tracks and weld ice lugs to worn undercarriage pattern	
VO: 208117 - Ripper functions not working (5518 HR)				Closed
Item: 229389 - Ripper functions not working				
260130-185-				
1/30/2026	3.5	CHERRY, RYAN	Install implement pump	
1/30/2026	3	MCLEAN, AIDAN	Drove to unit and got hydraulic oil filled. Got cold unit running and warmed up to temp. Checked hydraulic pilot pressure and main pressure. Both within spec. Installed floor boards.	
1/30/2026	4	HUDSON, TREY	Install new pump inspect hyd tank it's clean disassemble pump clean break on input shaft no need for further decontamination	
1/28/2026	2	CHERRY, RYAN	Test and order implement pump	
1/28/2026	2.5	HUDSON, TREY	Diag pump	
1/27/2026	5	CHERRY, RYAN	Check machine functions blade lift working ripper and tilt not working remove floor pans and test pressures no pressure on pilot system	
VO: 207922 - No start				Open
Item: 229193 - No start				
3/9/2026	2	COLES, RYAN	Machine was too cold to start, found working heater and installed on machine	
1/25/2026	2	MCLEAN, AIDAN	Charge and boost dead batteries.	
VO: 207680 - Tighten tracks				Open
Item: 228951 - Tighten tracks				
1/21/2026	2	STEINKE, BRENNAN	Tighten both tracks	



00185 [CAT D9N DOZER]
Equipment History From April 24, 2018 to August 20, 2026

VO: 207704 - Cold start				Open
Item: 228975 - Cold start				
3/9/2026	2	BURT, JORDAN	Boost and fire up unit	
3/8/2026	1.5	OLSEN, KIRK	Daily checks and cold start unit.	
2/19/2026	5	STONE, GREGORY	Tarpped in a headed unit and got running. Installed wiper blade and repaired stripped arm.	
1/25/2026	1	WARD, DEVIN	Boost and cold start machine for operations	
1/22/2026	1	OLSEN, KIRK	Cold start	
VO: 207420 - (250) SERVICE - CAT DOZER STANDARD PROGRAM				Closed
Item: 228695 - (250) SERVICE - CAT DOZER STANDARD PROGRAM				
260212-185-				
2/4/2026	2	BROWN, ISAAC	250h service + trans Dropped trans fluid did not have the right filters so service is not complete, added 80L of 10w40 ran out of time to fill the rest Trans filters need to be changed machine locked out	
2/4/2026	3	MARTZOUKOS, THANOS	250 hr service, drain trans	
VO: 207014 - Blower motor				Open
Item: 228288 - Blower motor				
1/13/2026	1	COOK, CHAD	Call for no blower motor No power to switch Reset circuit breaker	
VO: 206558 - Check over				Open
Item: 227820 - Check over				
8/15/2026	4	GOLOS, SCOTT	Chrck over and change carrier rollers	
3/20/2026	1	BURT, JORDAN	Demobed unit from kearl	
3/7/2026	1	OLSEN, KIRK	Daily inspections	
1/25/2026	1	BYRNE, LIAM	Unit dropped off in BOF. Check over unit, check all levels. Shut unit down as requested by ops foreman.	
1/21/2026	1	OLSEN, KIRK	Check over. Chip tracks out to tighten.	
1/7/2026	1	CRITCH, DAVID	Start unit check oils Alternator belt loose tighten belts ok	
1/6/2026	1	BYRNE, LIAM	Check over fluids on dozer.	
VO: 206479 - Mob in (5211 HR)				Closed
Notes: PCY -> KEARL				
Item: 227741 - Mob in				
260105-185-				
1/5/2026	2	OLSEN, KIRK	Unit had run out of fuel and died. Bleed system and boosted. Mob in checks.	
1/5/2026	3.5	CHERRY, RYAN	Mob In and prime fuel system after running out of fuel	
VO: 205985 - Dmob (5182 HR)				Closed
Notes: PCY -> KEARL				
Item: 227247 - Dmob				
260105-185-				
1/4/2026	10	SCHRAM, SHAWN	Set up work area, prep segments for welding. Weld up segments. Clean up shop area	



00185 [CAT D9N DOZER]

Equipment History From April 24, 2018 to August 20, 2026

1/4/2026	5	WHITE, DWAYNE	Install winter front, grab left side step from welding shop and install on machine, weld segments, clean up	
1/3/2026	8	SCHRAM, SHAWN	Make hoses for blade, grease unit, started welding segments.	
1/3/2026	3	WHITE, DWAYNE	Check over unit, grease machine including hard bar, found a few points that wouldn't take, replaced zerks and greased again, change out tilt cylinder line off stabilizer.	
1/1/2026	5	EVANS, JODY	Replaced #4 injector line. Get heater onto unit. Run and check for leaks. Install window breaker in cab. Change fire extinguisher. Bring into shop for service	
12/28/2025	8	MACLEOD, CONNOR	Edges wore, removed edges cleaned all mating surfaces flip edges, install new corner bits, top light burnt out, repaired Broken wire, removed step off side of dozer grab handle broken	
12/28/2025	9	EVANS, JODY	Finished off demob inspection. Troubleshoot the service meter wiring. Found that connection at alternator which supplies power to gauge was no good. Found a pigtail on a retired unit out back. Wired in and retest gauge Drill out and remove broke inside roller cap. Install new cap and bolts and torque bolts Assist Connor on swapping corner bits and flipping edges	
12/27/2025	3	MACLEOD, CONNOR	Heater was put on unit, let warm up for majority of the day, fired unit up and brought into shop, started dmob	
12/27/2025	5	EVANS, JODY	Get unit heated up and started outside. Clean snow off unit. Bring inside and start demob inspection.	
VO: 205510 - Steaming				Open
Item: 226773 - Steaming				
6/8/2026	4	YULO, FRANCIS ALBERT	Steam	
6/8/2026	4	RIVERA, AMIR	Full steam	
12/18/2025	12	YULO, FRANCIS ALBERT	Steam	
VO: 193556 - Final drive installation and fill (5160 HR)				Closed
Notes: null				
Item: 214055 - Final drive installation and fill				
6/27/2025	5	VIENNEAU, NATHAN	Installed and torqued segments and installed track	
6/26/2025	6	FIFE, ANDREW	Installed final drive and axle shaft, torqued mounting bolts and prepped for segments	
6/26/2025	3	LANDRY, TRAVIS	Helping mechanic with installation of final drive and fill of final with oil	
Item: 211305 - disassemble final drive and order parts				
6/26/2025	3	VIENNEAU, NATHAN	Help install final and fill with fluid	
6/12/2025	9.5	SMITH, DOUGLAS	start final drive assembly	
5/27/2025	5	SMITH, DOUGLAS	disassemble and order parts	
VO: 190020 - Segments (5160 HR)				Closed
Item: 210080 - Segments				
6/27/2025	12	FIFE, ANDREW	Installed segments, wrapped track	
5/14/2025	2	HOSPERS, FOLKERT	Crane off final drive order parts	
5/13/2025	6	HOSPERS, FOLKERT	Reinstall segments on last segment noticed cracked flange, split tracks and prep for final drive removal	



00185 [CAT D9N DOZER]
Equipment History From April 24, 2018 to August 20, 2026

VO: 189577 - Steam unit (5160 HR)				Closed
Item: 209602 - Steam unit				
5/8/2025	6	FELTHAM, IVAN	Steam Unit	
VO: 185177 - (1000) SERVICE - CAT DOZER STANDARD PROGRAM				Closed
Item: 205179 - (1000) SERVICE - CAT DOZER STANDARD PROGRAM				
260115-185-				
1/15/2026	3	STEINKE, BRENNAN	1000 hr service	
1/15/2026	3	BROWN, ISAAC	Did engine, fuel, finals, air, all samples	
VO: 184346 - Engine door damaged (5029 HR)				Closed
Item: 204341 - Engine door damaged				
3/11/2025	2	CHORNEYKO, CALVIN	Inspect damaged engine bay door. Pry door out from being jammed up. Once door is free banging out dents and straighten out. Test door to ensure it doesn't stick and latches properly.	
VO: 183434 - Radio (4902 HR)				Closed
Item: 203333 - Radio				
3/2/2025	1	SHEARER, KEELAN	Called to unit to replace radio. Found unit had radio already that worked good.	
VO: 183347 - Mob (4902 HR)				Closed
Item: 203246 - Mob				
3/2/2025	2	STUEBING, JEFF	Good to go. Two way radio repaired	
2/28/2025	3	WAKELAM, PARKER	Mob in unit	
VO: 183233 - MOB (4890 HR)				Closed
Notes: PCY -> MLX				
Item: 203132 - MOB				
250228-185-				
VO: 181462 - Demobe (4888 HR)				Closed
Notes: PCY -> MLX				
Item: 201238 - Demobe				
250226-185-				
2/8/2025	4	PROUDFOOT, BRADLEY	Heat unit up boost to start check over all levels replace fire extinguisher preformed demobe unit is a go	
VO: 175890 - (250) SERVICE - CAT DOZER STANDARD PROGRAM				Closed
Item: 195160 - (250) SERVICE - CAT DOZER STANDARD PROGRAM				
250319-185-				
3/19/2025	1	LANDRY, TRAVIS	Service completed	
VO: 175891 - (2000) PM - DOZER PROGRAM				Open
Item: 195161 - (2000) PM - DOZER PROGRAM				
8/16/2026	6	GOLOS, SCOTT	Demobe Remove welded on unit numbers Finish carrier rollers and tighten tracks Re and re front window	



00185 [CAT D9N DOZER]

Equipment History From April 24, 2018 to August 20, 2026

VO: 175929 - blade cracks (4872 HR) Closed

Item: 195200 - blade cracks			
12/5/2024	6	MACCONNELL, DOUGLAS	repair cracks in spill gaurd

VO: 175221 - LH pivot shaft (4858 HR) Closed

Item: 194376 - LH pivot shaft			
12/1/2024	6	WHITE, DWAYNE	Set up work area, put battery on charger, clean and prep surfaces, start unit, wrap track, install master pad, torque to spec, backfill lube truck, fill pivot shaft and frame oil, tighten track on left side, remove unit from stands, cleanup
12/1/2024	2	KAY, CODY	Undercarriage
11/30/2024	4	WHITE, DWAYNE	Set up work area, install frame, clean and prep parts, install pivot shaft retainer bolts and torque to spec, torque pinch bolts to spec, install trunnion and torque to spec, install carrier roller and torque to spec, grab tracks from outside and bring into shop, lay out tracks and hook up chain for install, batteries on unit are dead, will boost in the a.m. and finish wrapping tracks.
11/30/2024	4	KAY, CODY	Help put frame on Set up work area and help clean our area up
11/30/2024	6	FRASER, MARKO	Fitted left track frame.and trunnion.
11/29/2024	3	WHITE, DWAYNE	Set up work area, clean and prep surfaces, install new pivot shaft seal, shim down hardbar end for install, check that hardbar takes grease, went to hang frame and could not get to fit, grease seal cover plates are too thick, will reduce plate size in the morning and hang frame, clean up
11/26/2024	12	ALERTA, JERRIOE	Boost the unit, brought to shop removed front stomp pan and put the dozer on stands removed LH frame removed old pivot shaft seal. New one on order.

VO: 175035 - Boost to start (4872 HR) Closed

Item: 194101 - Boost to start			
12/5/2024	2	KAY, CODY	Fire machine up while it was warming up went and got a master pad. Then prepped everything to change out crack pad For new one then walk machine into shop, nog ripper, tooth out
11/26/2024	8	HOSPERS, FOLKERT	Boost unit cold start fire up unit bring to shop put on stands remove Left side track frame order new seal
11/24/2024	2	PROUDFOOT, BRADLEY	Boost to start run machine up returned to down line
11/24/2024	3	ALERTA, JERRIOE	Boost the machine

VO: 163496 - (500) DOZER STANDARD PROGRAM (4872 HR) Closed

Item: 148762 - (500) DOZER STANDARD PROGRAM			
241129--185-			
12/2/2024	12	KHAN, MUHAMMAD IMRAN	Service and general repair
12/1/2024	12	KHAN, MUHAMMAD IMRAN	Service and general maintenance
11/30/2024	8	WHITE, DWAYNE	Figure out filter list, grab filters from warehouse and bring to unit, perform service/ checks, document findings and fill out paperwork.



00185 [CAT D9N DOZER]
Equipment History From April 24, 2018 to August 20, 2026

11/30/2024	12	KHAN, MUHAMMAD IMRAN	Fixed undercarriage frame	
11/29/2024	12	KHAN, MUHAMMAD IMRAN	Undercarriage work	
11/26/2024	12	KHAN, MUHAMMAD IMRAN	Undercarriage work , change decals 1623	
10/16/2024	2	BENNETT, SHEA	Boost and move to down line (LH Pivot shaft seal)	

VO: 163497 - (1000) PM - DOZER PROGRAM (4872 HR)

Closed

Item: 180523 - (1000) PM - DOZER PROGRAM

241201-185-				
12/3/2024	7	WHITE, DWAYNE	Double check plugs and oils, tarp in engine bay, open taps, install new ripper tooth, run up machine and bring to operating temp, test drive and function test unit, torque stall, finish up paperwork and submit to Erick, park up unit outside shop as brush guards need welding and replacement track pad is expected to arrive tomorrow.	
12/2/2024	4	WHITE, DWAYNE	Finish checks, fill out paperwork, trouble shoot faulty horn and get working, trouble shoot electrical for hour meter and get working, install unit number decals, order up parts needed, top up pivot shaft oil, charge up batteries, machine isn't throwing heat, will address issue tomorrow, clean up.	
12/1/2024	6	WHITE, DWAYNE	Install hydraulic filters, sample and change oil in finals, top up engine oil, go over inspection checks and document findings, start working on deficiencies, clean up	