



WO: 214911 - (1000) PM - SMALL EXCAVATOR					Open
Item: 236252 - (1000) PM - SMALL EXCAVATOR					
WO: 212244 - Running repairs -26					Open
Item: 233535 - Running repairs -26					
3/19/2026	2.5	HAUGEN, DANE	Finished assembling hoe pack		
WO: 202853 - (350) SERVICE - TIL SMALL EXCAVATOR PROGRAM					Open
Item: 224090 - (350) SERVICE - TIL SMALL EXCAVATOR PROGRAM					
WO: 198226 - (4200) SERVICE - TIL SMALL EXCAVATOR PROGRAM					Closed
Item: 219068 - (4200) SERVICE - TIL SMALL EXCAVATOR PROGRAM					
251110-73035-					
11/10/2025	4	HOWARD, CHRISTOPHER	4200 hour service completed		
11/10/2025	4	SMITH, MITCHEL	Service		
WO: 192427 - (500) SERVICE - TIL SMALL EXCAVATOR PROGRAM					Closed
Item: 212772 - (500) SERVICE - TIL SMALL EXCAVATOR PROGRAM					
250901-73035-					
9/1/2025	3	VIENNEAU, NATHAN	Service complete		
9/1/2025	3	HOWARD, CHRISTOPHER	350 hour service completed		
WO: 188558 - Running Repairs 25					Open
Notes: null					
Item: 208549 - Running repairs 25					
3/18/2026	1.5	HAUGEN, DANE	Got in bay found parts and started to assemble		
2/25/2026	3.5	MACDONALD, BRIAN	Repair quick attach		
2/24/2026	10	MACDONALD, BRIAN	Wear plates		
2/23/2026	10.5	MACDONALD, BRIAN	Tamper base		
2/14/2026	10.5	MACDONALD, BRIAN	Fit and weld out base for hoe pac		
2/13/2026	11	MACDONALD, BRIAN	Quick attach rebuild		
2/7/2026	2.5	HAUGEN, DANE	Installed all new parts ordered onto hoe pack Installed new bearings and seals Installed cover plates installed motor and hoses, replaced breather		
1/23/2026	6.5	HAUGEN, DANE	Brought hoe pack in, disassembled, inspected and ordered parts, cleaned hoe pack as it's too cold to pressure wash, prepped all parts, cleaned bolts, cleaned bay, cleaned and put away all tools		
12/16/2025	1.5	DU PLESSIS, RYNO	Heat and start unit		
12/15/2025	2.5	BOBEY, ALEX	Heat and start unit. Find digging bucket for unit. Swap hoe pack off unit for digging bucket. Put hoe pac away.		
12/1/2025	1.5	DU PLESSIS, RYNO	Get unit started and warmed up to be loaded out		
11/28/2025	2.5	DU PLESSIS, RYNO	Get unit fired up and replace torn rubber , help move all gear		
11/26/2025	1.5	DU PLESSIS, RYNO	Warm up engine and get unit started		

Equipment History From August 10, 2018 to August 19, 2026

11/25/2025	2	DU PLESSIS, RYNO	Repair wiring to alternator	
11/20/2025	1	DU PLESSIS, RYNO	Reinstall final drive cover that fell off	
11/18/2025	2	DU PLESSIS, RYNO	Troubleshoot no start main fuse blown , trace wiring find and repair shorted wire , start machine	
11/17/2025	1.5	DU PLESSIS, RYNO	Replace blown out Oring on hoepack	
11/6/2025	6	YACUK, JONATHON	Hooked up hopack to crane unbolted all rubbers and removed one side. Lifted top section off of base. And set on pallet, put all bolts back into rubbers and put on pallet. Removed motor removed both bearing mounts and removed weight from inside. Put base on pallet and took to wash bay to get cleaned. Put back in welder bay and cleaned up around area	
11/5/2025	1.5	YACUK, JONATHON	Pulled apart ho pack and removed everything from bottom base. Got parts washed and put back in welding bay	
11/1/2025	1	BOBEY, ALEX	Started to work on replacing hoses. Pulled off for down machines.	
10/24/2025	2	BOBEY, ALEX	Travel to site and repair leaks. Replace leaking o rings and breather valve. Check oil level in case, good not over filled. Check out leak on control valve and order parts.	
10/23/2025	1	DU PLESSIS, RYNO	Install new Main fuses and clean up wiring	
10/22/2025	2	DU PLESSIS, RYNO	Troubleshoot no start main wiring harness shorted under engine blown main fuses order new parts Get machine started and offloaded	
10/21/2025	1.5	DU PLESSIS, RYNO	Replace missing brackets for aux tube and mount tube back in place	
10/21/2025	1.5	FIALA, CODY	New valve cover gasket and valve cover	
10/20/2025	1	DU PLESSIS, RYNO	Check out bent and loose tube on stick , straighten tube up need hardware to mount	
10/17/2025	1	FIALA, CODY	Hoe pack rubbers. Got to site and changed out rubbers	
10/16/2025	1	FIALA, CODY	Engine oil leak. Pulled stump pan no leaks on bottom end. Came up to and could see the oil is coming from oil fill cap. Will order fill cap.	
10/14/2025	10	MACDONALD, BRIAN	Hoe pac	
10/5/2025	2	BOBEY, ALEX	Travel to site, replace valve cover gasket	
10/1/2025	1	DU PLESSIS, RYNO	Lookup parts and help figure out where engine oil leak was coming from	
10/1/2025	2	FIALA, CODY	Leak on unit. Headed to site from Beaumont. Got to site, engine oil leaking from valve cover and no seal on oil filter. Ordered seal, and oil filter. Will replace valve cover when it arrives.	
9/29/2025	1.5	FIALA, CODY	Headed to site from ft Sask to copperhaven for blown hoe pack...hoe pack is fine. Changed relief valve out. Perfect amount of oil in case. Couplers and motor are good. Tested several times and no leaks. Operate normally.	
9/22/2025	2.5	YACUK, JONATHON	Switched over quick attach plate to a different ho pack.	
9/20/2025	2	BOBEY, ALEX	Grab parts at the shop. Travel to site and replace broken crankcase filter vent elbows and tubes.	
9/19/2025	2.5	BOBEY, ALEX	Travel to site. Check out leaks. Order parts. Swap bucket over to spare hoe pac. Tension up belts due to squealing.	
9/5/2025	0.5	BOBEY, ALEX	Bucket swap from ho pac.	

9/2/2025	3	BOBEY, ALEX	Grab batteries from the shop. Travel to site and load test batteries, replace, prime/start. Return to shop.	
9/1/2025	2	BOBEY, ALEX	Called by lube team. Travel to site. Lube guys did service and said unit died. Get unit started by boosting/priming. Will replace batteries Tuesday morning.	
8/29/2025	1.5	DU PLESSIS, RYNO	Replace hoepack quick couplers	
8/29/2025	2	SCHWABE, STEPHEN	Travel to and from site, repair aux controls for how pac	
8/22/2025	3	SCHWABE, STEPHEN	travel to and from site, replace injector and test for leaks, will have to monitor for a hydraulic leak,	
8/21/2025	1	FIALA, CODY	Hoe pack seizing up. Got there and coupler came undone. Operator noticed diesel from engine top. Number 3 injector leaking diesel. Ordered injector and 4 seals. Noticed hydraulic leak coming from swing motor. Soaked in brake clean. Steve is going to the machine in the morning as I am off. I filled him in. Also spoke with Cole there foreman and he knows not to run the machine tomorrow until Steve is done.	
8/19/2025	0.5	BOBEY, ALEX	Reinstall stump pan.	
8/15/2025	1	FIALA, CODY	Come by site to check on some gear. Hoe pack was low on oil/ topped him up. I had to make a motor out of 2 for this hoe pack on Tuesday. Operator was complaining it wasn't hitting as hard as it should. Once I topped up the hydraulic oil it seemed to make a harder impact. Still waiting for seal kits for other motors. Once I get them in I will build a motor and come and swap this one out.	
8/11/2025	1	FIALA, CODY	Waited for machine to come over then had to move it out of the way. Changed hoe pack rubbers.	
8/6/2025	1.5	DU PLESSIS, RYNO	Install new pins and retainers for 3 lost teeth	
8/1/2025	2	DU PLESSIS, RYNO	Check out hydraulic leak replace blown quick coupler check oil good	
7/31/2025	1.5	DU PLESSIS, RYNO	Replace stripped wedge hardware	
7/15/2025	3	FIALA, CODY	Came to shop this morning, installed bearings, o rings and filled pack with oil. Used retaining compound on the bearings. Then torqued the outer plates to 225 and motor mount bolts to 145 as spec sheet says. Took to site and tested worked good.	
7/14/2025	5.5	FIALA, CODY	Hoe pack is making noise. Got to site, checked oil in the machine, added half a pale of 10w. Then checked oil in hoe pack it was full. Pulled motor off hoe pack and bearings were falling out. Called Johnny, removed hoe pack in to my truck and brought back to shop. Didn't have matching hoe pack. So removed motor and bearings. Ordered bearings and prepped covers o rings and gasket for reinstallation. Waited for bearings.	
7/10/2025	1	DU PLESSIS, RYNO	Check out low power and leaks on hoepack , check motor , coupler is failing on oil supply side	
7/10/2025	1.5	FIALA, CODY	Left ellerslie headed to unit. Got to unit, ordered quick coupler, changed hoe pack rubber. Cooker arrived, changed coupler. Tested unit. No leaks	
7/8/2025	1	FIALA, CODY	Drove to site, found leak on hoe pack. Replace 2 O rings. Installed new fire extinguisher.	
7/1/2025	1.5	DU PLESSIS, RYNO	Check out and fuel hydraulic leak	
6/11/2025	1.5	DU PLESSIS, RYNO	Replace ignition switch and blow out plug radiator and screens	



73035 [DEERE 160C LC EXCAVATOR]

Equipment History From August 10, 2018 to August 19, 2026

6/7/2025	2	DU PLESSIS, RYNO	18528hours , Check out low power issues, injector 2 leaking , remove and replace injector and line seals , troubleshoot machine shutting down intermittent, ignition switch is separating order switch ,	
5/28/2025	0.5	SCHAUB, THOMAS	Installed new ac tensioner	
5/27/2025	1.5	DU PLESSIS, RYNO	Check out rattle and squeal coming from engine bay , AC tensioner failed , remove belt and tensioner or new	
5/26/2025	0.5	SCHAUB, THOMAS	Topped up engine oil	
5/12/2025	1	DU PLESSIS, RYNO	18373hours remove and replace fuel sender	
5/10/2025	1.5	DU PLESSIS, RYNO	Repair swing leak , replace hoepack motor and drain case down , fuel too full to replace sender	
5/8/2025	1	BOBEY, ALEX	Check out fuel level sensor issue. Order sender.	
5/5/2025	2	SCHAUB, THOMAS	Looked over for hydrolic leak . Found loose line at swing mortar. Tightened fitting and filled hydrolic tank . Changed out latch on front window	
5/2/2025	1	DU PLESSIS, RYNO	Replace coolant switch	
4/30/2025	1	DU PLESSIS, RYNO	Replace, wedge nut Troubleshoot machine, not revving up all the way found operator running machine on economy mode	
4/29/2025	4.5	DU PLESSIS, RYNO	18273hours install new temp sensor , waterpump and thermostat , run unit up troubleshoot water temp alarm going off , ord new water temp switch	
4/28/2025	2.5	DU PLESSIS, RYNO	Troubleshoot no vibe on hoepack , valve issue , swap hoses on solenoid valve to keep unit running ord new valve , Return to machine and troubleshoot overheating	
4/24/2025	1.5	SCHAUB, THOMAS	Looked at over heat on startup and front window latch . Drove to shop	
WO: 188407 - Running repairs 25 (18250 HR)				Closed
Item: 208393 - Running repairs 25				
4/26/2025	2	DU PLESSIS, RYNO	18267hours remove and replace fan pulley , spacer , bolts and belt run unit up to temp - good	
WO: 187503 - (250) SERVICE - TIL SMALL EXCAVATOR PROGRAM				Closed
Item: 207483 - (250) SERVICE - TIL SMALL EXCAVATOR PROGRAM				
250612-73035-				
WO: 184818 - VALVE SET (17872 HR)				Closed
Item: 204823 - VALVE SET				
250313-73035-				
WO: 183962 - Running Repairs 25 (18198 HR)				Closed
Notes: null				
Item: 203925 - Go over and repair				
250313-73035-				
4/14/2025	4	YACUK, JONATHON	Brought in units ho pack remade all 4 hoses with new orings. Installed new lines. Fixed cracks for rubber mount. Installed new rubber. Pulled ho pack out and loaded on truck. Tightened up bolts and moved some hoses on machine eng.	
4/14/2025	2.5	SCHMIDT, ETHAN	Clean tracks,Weld step,re adjust pipe,fix coolant leak,tighten gasket	
4/14/2025	2.5	SCHAUB, THOMAS	Drove to unit changed turbo line . Drove back to shop	



Equipment History From August 10, 2018 to August 19, 2026

3/25/2025	3.5	YACUK, JONATHON	Pulled machine forward to line up finals drained and changed out oil. Mounted eng cover belly pan. Ran machine and pulled out of shop. And put in lineup	
3/24/2025	6	YACUK, JONATHON	Installed new valve with new o rings mounted new switch in left are installed valve and all covers. Lifted seat into cab. And bolted down seat. Filled ac system cleaned up around area	
3/24/2025	6	SCHMIDT, ETHAN	Fix bracket,re charge ac get oil samples,do running repairs	
3/21/2025	9	YACUK, JONATHON	Removed left side arm panels removed broken switch, and pulled out pilot valve and capped all lines. Made parts went check list of cab tested ducting made sure all functions worked. Fixed wiring on boom light and cleaned up ground cleaned upbaround area.	
3/20/2025	9	YACUK, JONATHON	Fixed cracks on panels whiped down and cleaned out air ducting on the inside. Installed all cab pieces and hooked up all harnesses to controls. Installed grommets behind heater box in floor. Blew off chair. Installed new louvers in ducting Fixed wiring going to right side controls. Went through cab list. Cleaned up around area.	
3/19/2025	8.5	YACUK, JONATHON	Cleaned up around area of shop swept up floor and threw out garbage. Started putting cab back together. Fixed Olastic pieces installed heater box and hooked up blower section to box. Hooked up coolant and ac lines. Plugged in all connections. Ordered new inside door cab latch. Made covered grommets and rubber plate for hyd lock lever. Cleaned up around area.	
3/17/2025	7	YACUK, JONATHON	Removed foam off of heater box door flaps cleaned off all glue and and put new foam stripping down. Fixed broken plastic mounting for ac lines. Installed doors in heater box. And put box back together. Installed new gasket on charged air tube and put all piping back together on top of eng. Cleaned up around area	
3/14/2025	10.5	YACUK, JONATHON	Torqued down valve cover. Removed door flaps in heater box soaked in water with detergent to get rid of smell on foam. Pucked all filters and Started 3000 hr service on unit. Changed all filters, drained eng oil and swing took samples of oils. Filled up eng and swing. Put new hyd cap on mount. Changed orings on hyd tank covers. Cleaned up around area	
3/13/2025	9.5	YACUK, JONATHON	Cleaned up around area threw out garbage.removed charged air pipe and and intake air. Disconnected some harnesses removed valve cover and did a valve set. Finished cleaning some fins on the ac core for inside the cab. Cut oil filter open to inspect for debris. Washed and cleaned floor mat. Grabbed cab filters from sea can. Cleaned up around area	
3/13/2025	9	YACUK, JONATHON	Cleaned inside of air ducting and cleaned off panels. Installed harnesses and air ducting. Installed new louvers. Put all covers back on fixed cover panels tightened up all bolts and hooked up right side arm. Cleaned up around area	
3/12/2025	10.5	YACUK, JONATHON	Soaked heater core in water and soap to clean the foam and all fins. Sprayed down cab and cleaned walls and floor. Removednruht side travel line. Fixed wiring for light on boom. Messured and cut perforated metal to build a screen to cover hole beside cab. Changed out orings on pilot pump. Topped up hyd tank. Checked all levels. Cleaned up around area	
3/12/2025	9.5	SCHMIDT, ETHAN	Go over machine,make list	



	3/11/2025	7.5	YACUK, JONATHON	Removed heater box from cab. Split heater box open and found mouse nest cleaned and washed down housing and inside. Made up parts list for cab repairs fixed fins on ac core. And blew out hooked back up to heater box. Cleaned up area area.	
	3/7/2025	9.5	YACUK, JONATHON	Started unit and moved into shop. Started to take apart the cab to find mouse nest. Removed front bottom window, removed seat. Removed all ducting and panel covers. Lifted electrical panel to the side used camera to find mouse nest inside of heater box. Cleaned up around area	
WO: 171421 - (3000) SERVICE - TIL SMALL EXCAVATOR PROGRAM					Closed
	Item: 189962 - (3000) SERVICE - TIL SMALL EXCAVATOR PROGRAM				
	250401-73035-				
WO: 167452 - (250) SERVICE - TIL SMALL EXCAVATOR PROGRAM					Closed
	Item: 185697 - (250) SERVICE - TIL SMALL EXCAVATOR PROGRAM				
	240924-73035-				
WO: 161951 - (500) TIL SMALL EXCAVATOR PROGRAM (17500 HR)					Closed
	Item: 178667 - (500) TIL SMALL EXCAVATOR PROGRAM				
	240720-73035-				
	7/20/2024	2	WURBAN, ZACHERY	Service unit at alces 17500 hrs	
WO: 161952 - (3000) PM - SMALL EXCAVATOR (19347 HR)					Closed
	Item: 180448 - (3000) PM - SMALL EXCAVATOR				
	260422-73035 -				
	4/23/2026	2.5	BOBEY, ALEX	Finish PM inspection.	
	4/22/2026	6	BOBEY, ALEX	Check fluids. Boost unit to get running. Start on PM Inspection.	
	3/7/2025	10	SCHMIDT, ETHAN	Go through a inspection with machine	
WO: 161356 - Running repairs 24 (17872 HR)					Closed
	Item: 179987 - Running repairs 24				
	12/12/2024	1.5	DU PLESSIS, RYNO	Finish and test ether aid install	
	12/5/2024	1.5	DU PLESSIS, RYNO	Install ether aid unit and repair outside wiring test-good waiting on fittings	
	11/29/2024	2	DU PLESSIS, RYNO	Repair wiring disaster and Start ether aid install need solenoid	
	11/26/2024	1	DU PLESSIS, RYNO	Reseal blown out seal at hoepack connection	
	11/25/2024	1.5	DU PLESSIS, RYNO	Warm and start up machine to be loaded out	
	11/19/2024	2	DU PLESSIS, RYNO	18158 hours Check out hard starting and loss of power at end of the day , run machine up and check over , everything ran and functions good no faults , battery light came on ord alternator , one battery test at 72% and other 96%replace alternator , order cold start assist parts	
	11/18/2024	1.5	DU PLESSIS, RYNO	Check out no start and get unit going	
	11/15/2024	2	DU PLESSIS, RYNO	Check out hoepack stop working , supply coupler backed off , return to unit to troubleshoot battery light on repair wiring and return unit to work	
	11/1/2024	0.5	DU PLESSIS, RYNO	Remove stuck wedge	
	10/31/2024	1.5	DU PLESSIS, RYNO	Check out inlet restriction fault , Blow out and ord new air filters , change air filters	



Equipment History From August 10, 2018 to August 19, 2026

10/19/2024	1	SCHAUB, THOMAS	Drove to unit blew out air filter . Air restriction light keeps coming on for a couple seconds then goes off . Going to have to check sensors and wiring	
10/18/2024	1.5	SCHAUB, THOMAS	Removed leaking hose . Had new one made and delivered . Installed hose	
10/9/2024	4	SCHAUB, THOMAS	Drove to unit . Replaced crank sensor . Did not fix issue . Whent through wiring found open in wire at connector . Ordered new connector installed . Fixed issue . Drove to shop	
10/8/2024	1.5	SCHAUB, THOMAS	Drove to unit checked for running rough and stalling . Hooked up computer found crank sensor codes . Ordered new sensor	
10/1/2024	2	BOBEY, ALEX	Travel to site. Pull valve cover and check top end. Look at valve clearances, all are close to spec. #1 intake is about 0.004" over spec possible cam wear. 17,890 hours.	
9/24/2024	1	DU PLESSIS, RYNO	Repair leak at couplers	
9/11/2024	1	DU PLESSIS, RYNO	Replace broken coupler	
8/23/2024	1	SCHAUB, THOMAS	Removed one isolator and replaced . A few of the inside bolts were hard to get loose	
8/1/2024	0.5	BOBEY, ALEX	Repair clamp for stick cylinder.	
7/31/2024	1	DU PLESSIS, RYNO	Replace wiper blade and arm assembly, set park position and adjust wiper sensor	
7/26/2024	1.5	DU PLESSIS, RYNO	Replace start relay, troubleshoot, chattering relay in cab found loose connection at alternator for intermittent battery light repair connector	
7/25/2024	2	DU PLESSIS, RYNO	Troubleshoot no start and no wipers ord new relay and wiper arm assembly, jump relay to get unit going	
7/22/2024	3	YACUK, JONATHON	Drove to site. Removed inside cab pieces and opened up air box vacuumed up all mice nest I could find sucked out every vent put everything back together and cleaned up mess	
7/12/2024	1.5	DU PLESSIS, RYNO	Install new hoepack motor and ord hoses	
6/13/2024	1.5	DU PLESSIS, RYNO	Install new left-hand side auxiliary Tube	
6/12/2024	1	DU PLESSIS, RYNO	Repair travel alarm wiring at connector , adjust front window for wiper to work	
6/11/2024	1.5	DU PLESSIS, RYNO	Flow test aux hydraulics 25gpmcheck Call Carson valves everything seems good	
5/27/2024	2	DU PLESSIS, RYNO	Replace leaking hose check oil flow for hoe pack with flow meter, drill out orifice set flow to 25 gallons per minute	
5/26/2024	1.5	DU PLESSIS, RYNO	Look into low hoepack power , will need flow meter, measure up leaking hoses to be build	
4/27/2024	2	DU PLESSIS, RYNO	Build new hole pack hose and install top-up hydraulic oil -12 hose 84"OL -16 male pipe to -12orfs female	
WO: 159947 - (250) TIL SMALL EXCAVATOR PROGRAM (17216 HR)				Closed
Item: 143349 - (250) TIL SMALL EXCAVATOR PROGRAM				
240401-73035-				
WO: 157288 - Winter repairs 24 (17872 HR)				Closed
Item: 176004 - Winter repairs 24				
2/5/2025	2.5	SCHAUB, THOMAS	Installed and torqued oil pan	
4/17/2024	1	DU PLESSIS, RYNO	Replace window rollers	
4/16/2024	1.5	DU PLESSIS, RYNO	Install new pigtail on attachment, pressure sensor, harness	
4/15/2024	2	DU PLESSIS, RYNO	Get top window to latch and not leak , ord window rollers and check out auto idle not working	



73035 [DEERE 160C LC EXCAVATOR]

Equipment History From August 10, 2018 to August 19, 2026

	3/28/2024	1.5	DU PLESSIS, RYNO	Help figure out why service truck crane stopped working and help install boom cylinder	
	3/28/2024	3.5	LAKUSTA, CARSON	installed boom cylinder and lines, checked fluid levels.	
	3/12/2024	2.5	DU PLESSIS, RYNO	Get unit fired up and move out to check fuel leak , leak repaired , help pull right side boom cylinder to be resealed	
	3/12/2024	7.5	LAKUSTA, CARSON	took boom cylinder off machine to be sent out, fixed injector leak, cleaned cab.	
WO: 124724 - (2000) TIL SMALL EXCAVATOR PROGRAM (16868 HR)					Closed
	Item: 124937 - (2000) TIL SMALL EXCAVATOR PROGRAM				
	73035 2000h.pdf				
WO: 106553 - (500) TIL SMALL EXCAVATOR PROGRAM (16788 HR)					Closed
	Item: 115165 - (500) TIL SMALL EXCAVATOR PROGRAM				
	101722 - 73035 -				
WO: 97083 - (250) TIL SMALL EXCAVATOR PROGRAM (16360 HR)					Closed
	Item: 99837 - (250) TIL SMALL EXCAVATOR PROGRAM				
	73035 (250HR) 08-				
WO: 97084 - (2000) TIL SMALL EXCAVATOR PROGRAM (15944 HR)					Closed
	Item: 77741 - (2000) TIL SMALL EXCAVATOR PROGRAM				
WO: 86811 - TIL 2022 running repairs (17079 HR)					Closed
	Item: 104218 - TIL 2022 running repairs				
	12/5/2023	2	DU PLESSIS, RYNO	Check out oil leak , repair engine oil filter leak and top up oil , fuel leak parts list made	
	9/27/2023	1.5	DU PLESSIS, RYNO	Reinstall Dogbone to quick attach install new retaining bolts	
	9/26/2023	3	DU PLESSIS, RYNO	17132hours Check out fuel leak and ord new injector, #4 leaking . Remove and replace injector number 4 replace leak off-line	
	8/31/2023	1.5	DU PLESSIS, RYNO	Remove cross threaded wedge bolts and replace with new	
	8/17/2023	1.5	DU PLESSIS, RYNO	Check out seat not working complaint, seat was adjusted to max weight	
	7/28/2023	1.5	DU PLESSIS, RYNO	Repair door lock not working and latch jamming up	
	7/6/2023	0.5	DU PLESSIS, RYNO	Repair horn wiring	
	6/11/2023	1.5	DU PLESSIS, RYNO	checkout overheating issue , blowout rads and screens, run up to temp no more overheating	
	5/25/2023	0.5	YACUK, JONATHON	Put the bucket lock in and tightened down.	
	5/24/2023	1.5	YACUK, JONATHON	Dug out bucket from the back. Put bucket on. And ordered square nuts.	
	4/11/2023	4	DU PLESSIS, RYNO	Reseal pump control side	
	3/24/2023	4	DU PLESSIS, RYNO	Repair wiring disaster in the cab, troubleshoot wipers not working set wiper-enable switch up	
	3/23/2023	2.5	DU PLESSIS, RYNO	Pull cab apart and replace cab filter housing assembly, reassemble cab , start fixing hydraulic leaks, look into wiper not working	
	3/13/2023	3	DU PLESSIS, RYNO	Fire and warm up machine , pump lol cab apart to access blower motor , clean out garbage from motor and cab , motor runs good now , assemble cab , ord parts for hydraulic leak at pumps and for air duct repairs	
	10/21/2022	1	DU PLESSIS, RYNO	Install new hydraulic return filter cover	
	10/20/2022	2	DU PLESSIS, RYNO	Clean engine bay, find leak and replace filter seal	

Equipment History From August 10, 2018 to August 19, 2026

10/18/2022	1	DU PLESSIS, RYNO	Install temp repair on hydraulic return filter cover	
10/17/2022	0.5	DU PLESSIS, RYNO	Pull cracked hydraulic return filter cover	
10/11/2022	2	DU PLESSIS, RYNO	Remove and replace engine harness	
10/7/2022	0.5	BOBEY, ALEX	Replace smashed quick coupler	
9/27/2022	0.5	BOBEY, ALEX	Hoe pack loose, replace damaged square nuts on attachment adapter.	
9/23/2022	3	DU PLESSIS, RYNO	Troubleshoot machine died and no start, fuel pump solenoid open fault, make temporary wire jumper to fuel pump , repair and clean damaged pin at ecm connector and order new harnesses	
9/6/2022	2	DU PLESSIS, RYNO	Replace broken motor and straighten hand rail, find and repair fuel leak at injector	
9/2/2022	1.5	DU PLESSIS, RYNO	Remove and replace blown hoepack hoses	
8/25/2022	1.5	DU PLESSIS, RYNO	Remove and replace short hoepack hoses, top up oil	
8/23/2022	1.5	DU PLESSIS, RYNO	Remove and replace turbo oil supply hose	
8/17/2022	1	DU PLESSIS, RYNO	Remove and replace leaking turbo oil supply line and order proper hose	
8/16/2022	1	DU PLESSIS, RYNO	Check out oil leak, order hose for turbo oil supply	
8/9/2022	2	CLARKE, THOMAS	Luber service	
7/25/2022	1	DU PLESSIS, RYNO	Repair hydraulic leak at hoepack	
7/19/2022	1	BOBEY, ALEX	Replace rad cap and run machine. Not overheating currently.	
7/18/2022	2	BOBEY, ALEX	Travel to machined for overheat. Blow out screens and rads and check fluids. Unit is still overheating after digging. The cooling system is not building pressure. Put on gauge and system builds pressure while working. Pressure tested cap and cooling system Order parts.	
7/11/2022	0.5	DU PLESSIS, RYNO	Find leak and get hose made and brought out	
6/25/2022	2	DU PLESSIS, RYNO	Install new Fuel water separator filter assembly	
6/17/2022	2	DU PLESSIS, RYNO	Install new fuel cooler and hookup cooler hoses	
6/8/2022	1.5	DU PLESSIS, RYNO	Reseal all fuel supply line fittings	
6/6/2022	3	DU PLESSIS, RYNO	Troubleshoot machine died while travelling, go over fuel system , found fuel pump solenoid wires rubbed through on oil pan, repair wiring and order fuel line seals	
6/3/2022	1	BOBEY, ALEX	Blow out cooling group. Remove screens and clean for running hot.	
5/31/2022	2	DU PLESSIS, RYNO	Remove and replace engine oil filter head and filter , drain and change engine oil, fill up coolant run and check for leaks - good	
5/31/2022	0.5	MACLEAN, RONALD	Change engine oil filters and fuel filter	
5/30/2022	2.5	BOBEY, ALEX	Travel to site and check for cause of machine stalling out. Started up and test ran. Confirm problem. Ran machine out of pale and found no issues with running anymore. Drop pans and run tank line directly to transfer pump bypassing fuel cooler. Problem went away. Look up parts and put back in service till parts arrive.	
5/27/2022	2	DU PLESSIS, RYNO	Check out engine oil leak, remove leaking filter , clean up filter head threads and reinstall ord parts , repair AC compressor wiring	
5/24/2022	1	DU PLESSIS, RYNO	Check out and repair wipers not working	
5/9/2022	1	DU PLESSIS, RYNO	Bolt down aux steel tubes on boom	



73035 [DEERE 160C LC EXCAVATOR]

Equipment History From August 10, 2018 to August 19, 2026

	5/7/2022	1	DU PLESSIS, RYNO	Tie up steel aux tubes and order clamp and hardware	
	5/7/2022	1	BOBEY, ALEX	Replace coolant overheat temperature sending switch.	
	5/6/2022	1	BOBEY, ALEX	Travel to site and replace fuel filters. Engine running well.	
	5/5/2022	0.5	DU PLESSIS, RYNO	Repair fuel leak on fuel. Pump	
	5/5/2022	2	BOBEY, ALEX	Travel to site. Check for cause of no start. Bleed system and check if fuel prime. Start unit and low idle is rough. Repair fuel leak and run. Will change fuel filter tomorrow am.	
WO: 77658 - Winter repairs 2021 (15792 HR)					Closed
	Item: 94382 - Winter repairs 2021				
	4/27/2022	0.5	BOBEY, ALEX	Start up unit first thing and warm up. Move to line up for Ken to haul.	
	4/27/2022	1	DU PLESSIS, RYNO	Change bucket and get ready to be hauled out	
	4/5/2022	4.5	DU PLESSIS, RYNO	Shim linkages , replace oil return pipe and gasket from turbo , repair fuel leaks and install stump pans	
	4/4/2022	4	DU PLESSIS, RYNO	Replace hard fuel lines , run new fuel return hose , replace antenuator line and repair suction leaks	
	2/11/2022	2	DU PLESSIS, RYNO	Go over ,make parts list and ord parts	
WO: 73726 - Paint complete (15790 HR)					Closed
	Item: 90174 - Prep and Paint				
	1/18/2022	5.5	WIEST, KYLE	Unmask, assemble, touch ups and decals	
	1/18/2022	5	TOOPE, JONAH	Unmask touch ups reassemble and decals	
	1/17/2022	7	WIEST, KYLE	Mask all yellow, paint all grey	
	1/17/2022	7	TOOPE, JONAH	Mask yellow sand and paint grey	
	1/15/2022	2.5	WIEST, KYLE	Mask black and paint yellow	
	1/15/2022	2	TOOPE, JONAH	Mask black spray yellow	
	1/14/2022	6.5	WIEST, KYLE	Complete all masking, paint track frame black	
	1/14/2022	6	TOOPE, JONAH	Prep and paint black	
	1/13/2022	3	WIEST, KYLE	Blow down, Cleaning, and sanding cab.	
	1/13/2022	3.5	TOOPE, JONAH	Blow down prep cab	
	Item: 90173 - Prep and Sandblast				
	1/13/2022	5	WIEST, KYLE	Finish sandblast, unmask, blow down, bring inside.	
	1/13/2022	5	TOOPE, JONAH	Blast unmask and blow down	
	1/12/2022	9.5	WIEST, KYLE	Remove mirrors, lights, rear engine hood, prep for blast and begin sandblasting unit	
	Item: 90172 - wash unit				
	1/27/2022	1	MACLEAN, RONALD	Install hydraulic filter	
	1/11/2022	4	WIEST, KYLE	Wash unit and track into paint shop	
WO: 61652 - (500) EXCAVATOR 12-16 TON & MINI PROGRAM					Closed
	Item: 61659 - (500) EXCAVATOR 12-16 TON & MINI PROGRAM				
	091321-73035-				
WO: 47337 - 2021 TIL Running Repairs (15788 HR)					Closed



Equipment History From August 10, 2018 to August 19, 2026

Item: 62428 - 2021 TIL Running Repairs				
12/3/2021	3	MACLEAN, RONALD	D plus service	
12/3/2021	3	YACUK, JONATHON	d+ service	
11/18/2021	1.5	DU PLESSIS, RYNO	Go over machine	
11/18/2021	2	BOBEY, ALEX	Go over unit for recommended repair and begin making up parts list.	
11/3/2021	2.5	DU PLESSIS, RYNO	Troubleshoot leak, ord in arts, pick up and install new fuel transfer pump 15928hours	
10/22/2021	1.5	DU PLESSIS, RYNO	Replace blown hose	
10/21/2021	1.5	DU PLESSIS, RYNO	Check out hydraulic leak, remove and replace hose, make new hose at the shop	
10/20/2021	1	DU PLESSIS, RYNO	Remove and replace broken h link pin retainer	
10/19/2021	1.5	BOBEY, ALEX	Check for hydraulic leak on stick. Resealed RH shut off manifold on stick.	
10/7/2021	1	DU PLESSIS, RYNO	Check out and repair 2way static complaint	
10/1/2021	2	DU PLESSIS, RYNO	Repair leaks and replace hose on hoepack	
9/30/2021	1	DU PLESSIS, RYNO	Remove and replace wiper arm and blade	
9/30/2021	0.5	BOBEY, ALEX	Check for cause of cigarette lighter not working. Removed an checked wiring. Replaced fuse.	
9/29/2021	1	DU PLESSIS, RYNO	Get wiper working and order new wiper arm and blade	
9/28/2021	1	DU PLESSIS, RYNO	Swap over to hoepack and repair coupler threads, and top up engine oil	
9/16/2021	2	BOBEY, ALEX	Replace intake hose from union to compressor side of turbo, replace LH cab mirror.	
9/13/2021	2	MACLEAN, RONALD	D service	
9/11/2021	2	BOBEY, ALEX	Check for cause of fuel leak. Got unit hot and stalled out. Found number two injector is leaking externally. Look up parts and order. Walk hoe to laydown and remove swap dig to clean up bucket.	
9/10/2021	2	BOBEY, ALEX	Drive to site and reseal #2 injector. Bend back lip on fuel tank and repair lock-in cap.	
8/18/2021	2	BOBEY, ALEX	Drive to site and replace hoe pack hose from bulk head to motor.	
7/29/2021	1.5	DU PLESSIS, RYNO	Replace busted mirror and torn rubber	
7/12/2021	1	BOBEY, ALEX	Install LH cab mirror at site.	
7/10/2021	0.5	BOBEY, ALEX	Inspect damaged mirror. Ordered a new mirror assembly for LH front of cab. Parts ordered 7/10/21.	
6/29/2021	1.5	DU PLESSIS, RYNO	Go through cooling system and ensure proper operation	
6/28/2021	1	DU PLESSIS, RYNO	Blow out rads and clean radiator screens	
6/24/2021	3	DU PLESSIS, RYNO	replace hoepack hose and run new power for 2way	
6/23/2021	1.5	DU PLESSIS, RYNO	Check out hydraulic leak and build new hoses	
6/4/2021	3.5	SCHWABE, STEPHEN	check over unit, replace alternator belt, found alternator pulley was out of line with the other pulleys causing the belt to loose one rib, updated pulley/fan were unavailable so i spaced the pulley with a washer to bring the pulley in line with the fan hub	
4/23/2021	1	DU PLESSIS, RYNO	Install stick cylinder	
4/23/2021	3.5	FULLER, JOHNATHAN	cleaning on washpad	
4/23/2021	4	JEANNOTTE, COLIN	install stick cylinder, clean flanges, replace seals, paint new weld	
4/16/2021	2	DU PLESSIS, RYNO	Pull stick cylinder and send out for repair, remove steel tubes for welding repair	



73035 [DEERE 160C LC EXCAVATOR]

Equipment History From August 10, 2018 to August 19, 2026

	4/14/2021	0.5	KURKA, DORIAN	cleaned cab	
WO: 41741 - A Service (15257 HR)					Closed
	Item: 55582 - A Service				
	210106 - 73035 -				
WO: 40211 - winter repairs 2020 (15227 HR)					Closed
	Item: 53716 - winter repairs 2020				
	2/4/2021	1	DU PLESSIS, RYNO	go to install frost teeth, teeth not needed when i got to machine	
	2/3/2021	1.5	CLARKE, THOMAS	check over, greased and fueled the unit, moved into a parking spot	
	2/3/2021	3	DU PLESSIS, RYNO	troubleshoot no lights, repair wiring, get unit running, change out bucket and get unit ready to work	
	1/29/2021	6.5	DU PLESSIS, RYNO	prime and fire up machine check for fuel leaks, troubleshoot and repair oil level light on intermittent , check oil pressure sensor wiring and sensor for proper function , read up on setting low idle , install panels and guards and move machine out of shop ,	
	1/28/2021	5	DU PLESSIS, RYNO	install all new injectors , reseal intake tubes , prime fuel system , repair leaks on pilot valve	
	1/27/2021	12	DU PLESSIS, RYNO	check and adjust valve clearance, remove injectors , replace leaking hoses , reseal back of pilot valve	
	1/26/2021	2	DU PLESSIS, RYNO	get unit running and moved into shop, start investigating bad engine sample	
	1/7/2021	6.5	DU PLESSIS, RYNO	repair stump pans, install right side control valve hoses replace leaking pilot lines, compete oil change paperwork , check pins and bushings and get unit moved to wash pad	
	1/6/2021	4.5	DU PLESSIS, RYNO	service machine -A- 15257hours , sprit and reseal swing motor	
	1/5/2021	7	DU PLESSIS, RYNO	replace rhs cab window, repair boom light wiring, tidy up wiring to swing motor, remove hoses from control valve and get hoses made start to re install	
	1/4/2021	1	DU PLESSIS, RYNO	get machine fired up and moved into shop	
	12/21/2020	1.5	DU PLESSIS, RYNO	get unit fired up and moved , clean up glass and ord new right side cab window, repair coolant leak at lower rad hose	
WO: 37211 - 2016-2018 Service History (13180 HR)					Closed
	Item: 50168 - 2016-2018 Service History				
	2016-2018 - 73035 -				
WO: 37327 - 2019 Service History (13965 HR)					Closed
	Item: 50288 - 2019 Service History				
	2019 - 73035 -				
WO: 32325 - running repairs 2020 (15168 HR)					Closed
	Item: 44401 - running repairs 2020				
	11/2/2020	2	DU PLESSIS, RYNO	get access to cab adjust inside oor lever to be able to lock and unlock cab	
	10/30/2020	1.5	DU PLESSIS, RYNO	install new door catch , inside lever , cables and lock assembly	
	10/20/2020	1	DU PLESSIS, RYNO	repair hydraulic leak on hoe pack	
	10/15/2020	2.5	DU PLESSIS, RYNO	repair engine oil leak , find and start repairing hydraulic leaks	



Equipment History From August 10, 2018 to August 19, 2026

	10/9/2020	2.5	DU PLESSIS, RYNO	remove window to get in cab, repair hyd leak on hoe pack, install window and get door latch working, ord parts	
	10/7/2020	1.5	DU PLESSIS, RYNO	find and repair hydraulic leak on suction tubes	
	10/6/2020	1.5	DU PLESSIS, RYNO	repair hydraulic leak on valve bank	
	9/29/2020	3	BEERWORT, JOHNNY	went and repair couple for aux	
	9/26/2020	3	DU PLESSIS, RYNO	troubleshoot and repair ho pack not working and hydro locking , replace ho pack motor	
	9/11/2020	2	DU PLESSIS, RYNO	remove bucket teeth go pick up correct teeth and install paddle teeth on bucket	
	9/4/2020	2.5	DU PLESSIS, RYNO	replace boom lift cylinder hoses	
	8/28/2020	2	DU PLESSIS, RYNO	seal off fuel tank at hand rail bolts, repair 2 way wiring , replace pinched hose on hoe pack , replace torn hoe pack rubber	
	8/26/2020	2.5	DU PLESSIS, RYNO	replace 2way radio , replace alternator (14782hours) , get unit running	
	8/20/2020	1	DU PLESSIS, RYNO	replace 2way	
	8/7/2020	3.5	DU PLESSIS, RYNO	repair coolant and engine oil leak, fill coolant and top up engine oil run machine up no leaks	
	7/30/2020	5	DU PLESSIS, RYNO	take cab apart to access heater box and blower motor, remove debris and clean out unit re assemble	
	7/28/2020	2	DU PLESSIS, RYNO	troubleshoot overheating issue blow out rad screens and rads	
	7/28/2020	4	BEERWORT, JOHNNY	Installed new aux coupler and hose, repaired coolant leak, fixed fuel leak, looked at monitor fault,	
	7/24/2020	1	DU PLESSIS, RYNO	replace bucket wedge nuts	
WO: 31681 - overheating (14532 HR)					Closed
	Item: 43549 - overheating				
	6/23/2020	1.5	DU PLESSIS, RYNO	blow out rads	
WO: 31470 - install gps (14396 HR)					Closed
	Item: 43318 - install gps				
	6/10/2020	1.5	DU PLESSIS, RYNO	finish vision link gps install	
	6/9/2020	4	DU PLESSIS, RYNO	install GPS system to track hours	