



L15-3
SEP

VO: 196693 - (350) SERVICE - TIL TRACKED LOADER STANDARD				Open
Item: 217447 - (350) SERVICE - TIL TRACKED LOADER STANDARD PROGRAM				
VO: 194129 - (4000) PM - LOADERS				Open
Item: 214629 - (4000) PM - LOADERS				
VO: 192104 - (250) SERVICE - TIL TRACKED LOADER STANDARD				Closed
Item: 212397 - (250) SERVICE - TIL TRACKED LOADER STANDARD PROGRAM				
250806-71044-				
8/6/2025	1.5	WURBAN, ZACHERY	Service unit at 7280	
VO: 185608 - Bucket repair (6564 HR)				Closed
Item: 205610 - Bucket repair				
3/27/2025	2	YACUK, JONATHON	Finished welding on last 2 pieces, cleaned up area and moved unit outside into line up.	
3/26/2025	0.5	SCHMIDT, ETHAN	Weld bottoming plates	
3/26/2025	6	YACUK, JONATHON	Welded on new wear strips on bottom back of bucket. Cleaned up around area	
3/25/2025	3	YACUK, JONATHON	Pulled machine into shop, tacked on wear strips to bottom off bucket. Cut 4 more pieces of flat bar started to weld wear bars	
3/24/2025	3	YACUK, JONATHON	Messured pieces of metal to weld on bottom of bucket for wear strips. Brought in piece and cut to length cleaned up around area.	
VO: 184820 - (250) TIL TRACKED LOADER STANDARD PROGRAM				Closed
Item: 204825 - (250) TIL TRACKED LOADER STANDARD PROGRAM				
250313-71044-				
VO: 184821 - (1000) SERVICE - TIL TRACKED LOADER STANDARD				Closed
Item: 204826 - (1000) SERVICE - TIL TRACKED LOADER STANDARD PROGRAM				
250606-71044-				
6/6/2025	2	WURBAN, ZACHERY	Service unit at 6915	
4/15/2025	2	MACLEAN, RONALD	Check unit add tranny fluid boost unit for taking to job site	
VO: 184519 - Running Repairs 25				Open
Notes: null				
Item: 209741 - Running repairs 25				
9/4/2025	6	BOBEY, ALEX	Continue with misc machine repairs. Repair hydraulic reversing fan circuit and test. Remount fuel cooler. Repair wiring in engine bay.	
9/3/2025	12	BOBEY, ALEX	Continue checking over the machine. Start working on engine fan reversing not working. Parts for bucket arrived. Press new bearings into loader arms. Install new pins, seals, shims, and dust seals. Grease bucket linkages. Continue with reverse fan diagnostics. Order misc parts for loader.	
9/2/2025	4.5	BOBEY, ALEX	Finish removing damaged bushings. Clean up metal from area. Continue checking over the machine.	



71044 [DEERE 755K TRACK LOADER]

Equipment History From August 15, 2022 to August 19, 2026

8/14/2025	2.5	FIALA, CODY	headed to site to install lights from a ways back. Got to lauderdale and track loader wasn't there. Ryno said it might be at the Greisbach dump. So I went to greisbach and made my way into the dump. Removed panels and Then could access lights. Removed old lights made deutsch connectors on both lights and then mounted lights onto track loader cab. Secured and then reassembled panels.	
7/31/2025	7.5	FIALA, CODY	Drove to site removed all stump pans and seen a fair amount of engine oil. Could not tell where the oil was coming from as there was mud and dirt covering everything. Needed it steamed to see where oil was coming from. contacted Guy, he had Hayden come out with steamer. Waited for Hayden to show up so I went through the machine and removed all the stump pans, took off the outside hose and had a hell of a time getting the back one off. It had a 90 on it up against the engine block. Finally got the hose off, covered the fittings and then Hayden pressure washed the bottom out. Waited for hoses to arrive. Installed hoses got engine up to temp and checked for leaks. No leaks were found. Zip tied hoses with handcuffs to Keep them from rubbing on eachother. Then put stump pans on. Headed for home	
7/10/2025	1.5	BOBEY, ALEX	Travel to site and replace fan filter.	
7/8/2025	1	FIALA, CODY	Lights burnt out on track loader. Right side corroded and connection broken inside light housing. Needs new light. Stuck in traffic on henday.	
6/10/2025	1.5	DU PLESSIS, RYNO	Check out engine oil leak, top up oil setup wash truck	
5/30/2025	1	BOBEY, ALEX	Check out no a/c. Top up charge and order hoses and boost gasket.	
5/10/2025	2	DU PLESSIS, RYNO	Check out no AC , top up system and get #3 condenser fan wiring repaired , check out joystick complaint , will have to replace	
Item: 204521 - Running Repairs 25				
9/10/2025	2	BOBEY, ALEX	Remove and replace drain plugs and vents on hydrostatic tank. Remove and replace washer fluid tank and pumps.	
8/29/2025	12	BOBEY, ALEX	Continue with pulling siezed pins from bucket. Had to gouge out more material and weld on nuts to get 40T puller ram on pins. Build tooling to pull pins out due to length. Pins were extremely stuck, finally came out. Back up machine and check bores on loader arms. Order parts and clean up the area.	
8/29/2025	9.5	MACDONALD, BRIAN	Bucket and pins	
8/28/2025	9.5	BOBEY, ALEX	Move trailers blocking unit in. Check over unit. Bucket bearings/pins failed. Tried to pull pins with 40T ram but no success. Get pins lanced with Brian. Clean up area, will attempt to pull tomorrow.	
8/28/2025	6.5	MACDONALD, BRIAN	Bucket and pins	
7/4/2025	3	BOBEY, ALEX	Travel to machine. Hydraulic filter came off. Ordered filter and oil to site. Installed new filter and filled 60L of hydraulic oil. Had to go back to the machine because the operator thought it was still leaking, no leak the leak coming from the stump pans was residual oil.	

7/1/2025	2	FIALA, CODY	Drove to site. Spoke with Roman, started to pour rain for about 20 minutes, waited for there safety meeting and to open up the gate. Bolt was stripped. So I torched off both bolts. Installed new tooth, bolts, nuts, keepers and pins. Wrapped upbttools and headed to next site.	
6/21/2025	4	DU PLESSIS, RYNO	Remove hoses and valves to flip cab , disassemble valve and inspect as cab would not lift , reassemble and prime , flip cab and replace botch AC hoses from compressor , vacuum system and recharge 1.7kg	
6/11/2025	2	DU PLESSIS, RYNO	Bump up AC charge until the rest of the parts show up	
6/10/2025	3.5	SCHAUB, THOMAS	Loaded pressure washer on to truck . Filled tank . Drove to unit and washed engine bay . Drove to shop unloaded truck	
6/2/2025	2	BOBEY, ALEX	Travel to site. Change out fan filter and cut filter. No metal in filter. Install new and RTS.	
5/29/2025	3	SCHAUB, THOMAS	Drove to unit for coolant leak topped up coolant ro find leak . Had a small blown hose ordered hose had it delivered installed filled coolant and ran unit	
5/26/2025	1	SCHAUB, THOMAS	Drove to unit topped up ac	
5/20/2025	1.5	SCHAUB, THOMAS	Drove to unit installed new lhs tooth and installed new 2 way mic	
5/16/2025	1	DU PLESSIS, RYNO	Install rear cab hose guards	
3/24/2025	3	SCHMIDT, ETHAN	Cutting metal for backing plates,grind rust off bucket	
3/17/2025	2	BOBEY, ALEX	Get machine started and brought back inside. prep surface and install new rear window.	
3/14/2025	6.5	BOBEY, ALEX	Recover and charge A/C. Replace o rings on compressor lines. Test A/C. Flip cutting edges. Top off pivot shafts. Cut out cracked window on rear cabin and prep surface for replacement. Move machine outside and clean up area.	
3/13/2025	9.5	BOBEY, ALEX	Complete inspection. Help Dallas with service. Replace door latches. Replace condenser fans and test. Replace horn. Replace reverse alarm, drop and clean out all stump pans. Replace rear wiper blade. Remove cutting edges. Measure hardbar pins. Worst was 0.055" play. Replace burnt out work lights.	

VO: 164988 - Running repairs 24 (6564 HR)

Closed

Item: 182878 - Running repairs 24				
3/13/2025	4.5	MACLEAN, RONALD	Remove old decals and apply new ones	
3/12/2025	4.5	BOBEY, ALEX	Machine dead. Boost and warm up. Bring machine inside for inspection. Start inspection.	
9/26/2024	3.5	SCHAUB, THOMAS	Loaded parts . Drove to unit . Had wrong teeth . Ordered the right teeth . Removed old teeth . 4 keepers stripped . Had to use air hammer to remove . Had new teeth brought to me and installed	
8/15/2024	1	DU PLESSIS, RYNO	Boost machine as key was left on check charging system good	
7/4/2024	1	DU PLESSIS, RYNO	6298hours install rebuilt bucket tilt cylinder	
6/27/2024	2	LAKUSTA, CARSON	Inspect leak from lift cylinder.	
6/27/2024	1.5	DU PLESSIS, RYNO	Pull bucket cylinder to get sent out to repair a leak at position sensor	
6/26/2024	1.5	DU PLESSIS, RYNO	Calibrate pump and motor threshold's	



71044 [DEERE 755K TRACK LOADER]

Equipment History From August 15, 2022 to August 19, 2026

6/18/2024	5.5	YACUK, JONATHON	Reassembled bucket cylinder installed on machine and hook up all lines. Put guards back on, topped up hyd oil and eng oil. Ran and looked for any leaks. Finished oil service of draining final drives. And moved out side.	
6/17/2024	6.5	YACUK, JONATHON	Looked over unit. Started 500hr oil change. Cleaned up cab	
6/13/2024	4	YACUK, JONATHON	Drained hyd tank. Opened up inspection port. Cleaned out tank. Installed new gasket. And tank breather filter. Filled back up with oil.	
6/11/2024	3.5	YACUK, JONATHON	Cleaned up cylinder tube's and capped ends. Drained out hyd oil from tank. Removed filters and cut open. Put new hyd oil back into tank and cleaned up around area.	
6/10/2024	6.5	YACUK, JONATHON	Disconnected hyd lines and electrical line from tilt cylinder. Pulled rod out of cylinder and looked at piston for damages. Drained hyd oil from machine and cut open filter cleaned of cylinder and put on pallet. Cleaned up around machine.	
6/7/2024	1	DU PLESSIS, RYNO	Check out hydraulic leak , bucket tilt cylinder has broken bolts and rod gouged	
VO: 161791 - (500) TIL TRACKED LOADER STANDARD PROGRAM				Closed
Item: 161625 - (500) TIL TRACKED LOADER STANDARD PROGRAM				
2024-06-18 - 71044 -				
VO: 143130 - (250) TIL TRACKED LOADER STANDARD PROGRAM				Closed
Item: 130583 - (250) TIL TRACKED LOADER STANDARD PROGRAM				
230913-71044-				
VO: 136127 - TIL Running Repairs 2023 (6116 HR)				Closed
Item: 154701 - TIL Running Repairs 2023				
11/27/2023	2	DU PLESSIS, RYNO	Find and repair hydrostatic oil leak , top up oil	
10/25/2023	1	DU PLESSIS, RYNO	Replace air inlet temp pressure and humidity sensor	
10/24/2023	1	DU PLESSIS, RYNO	Check out engine oil leak clean up and tighten engine oil filter reinstall panels put unit back to work	
10/21/2023	1	DU PLESSIS, RYNO	Replace outer teeth pins that backed out	
10/19/2023	2	DU PLESSIS, RYNO	Forced regen - successful 6054hours	
10/17/2023	1.5	DU PLESSIS, RYNO	Check out intake air restriction fault , check wiring as fault is intermittent and air filter is fairly clean , ord sensor	
10/3/2023	1	DU PLESSIS, RYNO	Check out low air flow in cab , blow out clogged filters	
9/28/2023	1	DU PLESSIS, RYNO	Tighten up heater hose clamps a lot edge of the cab that was weeping	
9/27/2023	3	DU PLESSIS, RYNO	Find and repair hydraulic leak right travel motor hose to pump and adaptor	
9/16/2023	2	DU PLESSIS, RYNO	Check out fault for air intake restriction, fault went inactive and could not get fault to return , check all temps and sensors-good will monitor , check out weird noises coming from fan , remove rocks from fan shroud pinging around	
9/13/2023	1.5	CLARKE, THOMAS	Lube service	
9/5/2023	1.5	DU PLESSIS, RYNO	Check out engine running hot and air intake restriction fault , blow out rads and air filter , run machine and faults have not returned	
9/5/2023	0.5	BOBEY, ALEX	Tightened up cab mounting bolts.	

7/6/2023	4.5	BOBEY, ALEX	Load up oils and parts at shop. Travel to site and inspect for leak. Drop all stump pans, tilt cab and run unit. Appears that all of the leaking oil from the pans was residual oil from previous repair. Put unit back together for work tomorrow AM.	
VO: 130759 - Winter repairs 22 (5630 HR)				Closed
Item: 149370 - Winter repairs 22				
6/21/2023	2.5	DU PLESSIS, RYNO	Install hydraulic pilot valve joystick, run up to temp , more responsive and not sticky anymore	
6/20/2023	4	DU PLESSIS, RYNO	Remove ,disassemble and inspect and clean, adjust and reassembled hydraulic pilot valve assembly	
6/9/2023	1.5	DU PLESSIS, RYNO	Check out loss of hyd functions, repair leak and refill hydraulic oil	
6/8/2023	1	DU PLESSIS, RYNO	Check out vet faults , repair rubbed through harness	
5/25/2023	4	BEERWORT, JOHNNY	changed return hyd hose, put cab down and installed belly pans, moved outside on wash pad.	
5/24/2023	8	BEERWORT, JOHNNY	installed all new exhausrt manifold stud and reasmbled engine and egr cooler.	
5/23/2023	8	MACDONALD, BRIAN	Exhaust manifold bolts	
5/20/2023	2	BEERWORT, JOHNNY	worked on removing broken stud in head.	
5/20/2023	4	MACDONALD, BRIAN	Exhaust manifold broken bolts	
5/19/2023	1.5	DU PLESSIS, RYNO	Help strip to do exhaust manifold gaskets, ord more parts	
5/19/2023	6	BEERWORT, JOHNNY	pulled turbo and exhaust manifold	
VO: 112050 - (2000) TIL TRACKED LOADER STANDARD PROGRAM				Closed
Item: 117296 - (2000) TIL TRACKED LOADER STANDARD PROGRAM				
121125 - 71044				
VO: 99225 - (250) TIL TRACKED LOADER STANDARD PROGRAM				Closed
Item: 83908 - (250) TIL TRACKED LOADER STANDARD PROGRAM				
082422-71044-				
VO: 89663 - 2022 TIL running repairs (5630 HR)				Closed
Item: 107374 - 2022 TIL running repairs				
11/25/2022	3	CLARKE, THOMAS	2000 hr Lube service at 8008	
10/12/2022	2	DU PLESSIS, RYNO	5602hours , troubleshoot squealing noises, found broken exhaust manifold stud and exhaust leak causing noise when hot , check out joystick loose complaint	
9/27/2022	1.5	BOBEY, ALEX	Travel to site for machine derated. Engine light is on. Check monitor codes and found engine coolant low. Raise cab and found heater box under seat leaking coolant. Drop heater box from bottom of cab and inspect. No leaks inside. Suspect that spring clamp on hoses to rad is leaking. Hoses as new, replace spring clamps with worn gear clamps. Fill coolant.	
9/21/2022	1	DU PLESSIS, RYNO	Find hydraulic leak, remove and reinstall leaking hyd filter	
9/9/2022	1.5	DU PLESSIS, RYNO	Check out machine derated , Ollie coolant , tighten up leaking heater hose and fill coolant, run machine no leaks	
9/2/2022	2	DU PLESSIS, RYNO	Cut out and replace rubbed through heater hoses under cab, top up coolant and run machine no leaks present	

8/31/2022	2	DU PLESSIS, RYNO	Check out machine derated, fill up coolant and find leak, pinch off hoses to keep machine running , force regen	
8/29/2022	2	DU PLESSIS, RYNO	Check out machine defraged, had logged faults for high air filter differential pressure and high coolant temp , clear faults and blow out radiator and filters, run machine no active faults returned	
8/25/2022	4	BOBEY, ALEX	Travel to machine and hook up for faults. Faults for High soot load, high calculated soot load, and exhaust filter temperature module loss of communication. Hook up service advisor and ran unit through regen twice, completed both times. Wiggle test wiring and check plugs for loose pins or corrosion. Could not replicate problem. Cleared codes and return unit to work.	
8/22/2022	3.5	YACUK, JONATHON	did a 250 service	
8/22/2022	2	CLARKE, THOMAS	Lube service	
8/12/2022	1.5	DU PLESSIS, RYNO	Check out cab shaking complaint, seat cab properly and tighten up rear cab bolts after cleaning out holes	
8/12/2022	0.5	MACLEAN, RONALD	Change hydraulic and fan filter	
8/11/2022	1	DU PLESSIS, RYNO	Pick cab and reinstall cab tilt cylinder pin	
8/11/2022	2.5	BOBEY, ALEX	Go to Greggs Nisku with sample hose. Travel to site and install hose on machine. Fill hydraulic oil with engine oil. Run machine. Repair cab tilt cylinder top pin. Cab bushings are blown out.	
8/10/2022	1.5	DU PLESSIS, RYNO	Troubleshoot and find hydraulic leak	
8/10/2022	2.5	BOBEY, ALEX	Travel to site and remove leaking hose from main pump to RH side travel motor.	
7/29/2022	1	DU PLESSIS, RYNO	Check out fan filter restriction light flashing machine oil was cold and fault when away after 5 mins running	
7/21/2022	0.5	DU PLESSIS, RYNO	Check out noise when lifting full bucket , grease machine - no more noise	
6/28/2022	1.5	DU PLESSIS, RYNO	Start troubleshooting machine tracking to the left	
6/20/2022	2	DU PLESSIS, RYNO	Troubleshoot 3471.4 fault, found bad connection on engine harness	
6/14/2022	4	DU PLESSIS, RYNO	Remove and replace dosing control valve harness, run up to temp, no active faults	
6/9/2022	3.5	DU PLESSIS, RYNO	Troubleshoot plugged dpf filter and unable to regen , found wiring issue at the dosing control valve, repair wiring and order new jumper harness , folk regen for service and put unit back to work 5033hrs	
6/3/2022	5.5	BOBEY, ALEX	Travel to site and replace 7th injector. Hang after treatment module with crane so regen can be ran for testing. Top up coolant and monitor all parameters KOEO with unit cold. No abnormalities found. Started unit and warmed up - put into service regen. Ran complete service regen and monitored from cab: temps, pressures, EGR, and turbo circuits all operating correctly. Faults all went inactive. Cleared faults and idled to cool down. Remove after treatment module and reinstall onto hood. Reinstall hood panels. Updated ECU software version. Notify foreman and put back into service.	



71044 [DEERE 755K TRACK LOADER]
Equipment History From August 15, 2022 to August 19, 2026

6/1/2022	6.5	BOBEY, ALEX	Travel to site and check for cause of stop engine light. Unit had a plugged DPF. Started up and inspect with service advisor. Will need to down machine to dig into repair. Walk unit out of ditch and around site to get to lay down, machine was derated so it was very slow. Remove Doser injector and test for leakage, none found. Cleaned and reinstalled. Reset DPF cals and remove hoods. Remove DPF and DOC and inspect, perform snap test on engine and nothing excessive found. Reinstall components and run service regen. Regen went fine for 20 mins then suddenly lost DOC outlet temp. Suspect injector is failing. Order parts and pack up.	
----------	-----	-------------	--	--