



H02-94
SEP

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

SEMI (WATER)

Maintenance Request / Report Form

Information

405

Grand Prairie - Shop

Thursday, June 18th 2026, 4:38 PM (MDT -06:00)

Unit Information

Date: June 18, 2026

Select Unit Number: 405

KMs: # 124734

Hours: # 12753.5

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Transmission Flush
Replace PTO shifter gasket
Refill fresh transmission oil
Test PTO have it run in the yard for 2 hrs and check for leaks and transmission fluid level

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Fixed

Location of repairs being completed:

Pick the location where the repairs were completed:

FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:



John Klatt

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome, Jason Brown, Jon Archibald.

Signatures

John Klatt, *Mechanic*



June 18th 2026, 4:38 PM (MDT -06:00)



55.3092614, -118.7966435

A handwritten signature in black ink, appearing to be 'John Klatt'.



Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-771'

SEMI (WATER)

Maintenance Request / Report Form

Information

405

Grand Prairie - Shop

Sunday, June 14th 2026, 8:35 AM (MDT -06:00)

Unit Information

Date: June 14, 2026

Select Unit Number: 405

KMs: # 124711

Hours: # 12752

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

- Delete emissions system from unit.
- Remove all aftertreatment filters and install custom fab exhaust piping with muffler, install EGR block off plates.
- Replace oil pan and gaaskit.
- Perform full service (0w40)
- with new
- OIL,both fuel,both air,cabin air and coolant filters. ADD new coolant
- Replace hydraulic filter
- Right side windshield replaced.
- Replace in tank fuel level sensor.
- Drop truck off at kenworth to get fan hub not shutting off issue diagnosed and repaired via (AC pressure sensor overlay wire).
- Put new clamp on left exhaust stack.
- adjust clutch.
- REtorque all wheels and put lug nut indicators back on.
- Test drive unit.

Serial/Part # if applicable: No Response

Urgency of Repairs:

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Grande Prairie Shop

☒ FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:

 Dewitt [David] Steinbrenner

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome, Jason Brown, Jon Archibald.

Signatures

Dewitt [David] Steinbrenner, *Mechanic/Driller*

 June 14th 2026, 8:35 AM (MDT -06:00)

P. I.



GREATWEST KENWORTH LTD



7202 98th STREET
CLAIRMONT, AB T8X 5B1
(780) 532-1595

Sold To: BROTHERS HDD INC
15466 2002 23 AVE

Ship To: BROTHERS HDD INC
2002 23 AVE

CUSTOMER INVOICE

Work Order

SG3028939

WAINWRIGHT, AB T9W 0B8

WAINWRIGHT, AB T9W 0B8

Date: 06-12-26

Page 1 of 2

UNIT # 405

780 214-7711

Year	Make / Model	Serial Number	License	Mileage	Unit/Stock
2013	KENWORTH / T800	1NKDX4TX6DR958685		124693K	405
Delivery Mileage	Delivery Date	Engine Model / Serial #	Transmission Model/Serial #		
	03-04-13	ISX / 79558669	RTLO18918B / S0938863		
CPL/ARRG	Rear Ratio	Rear Axle Model / Serial #	Rear Axle Model / Serial # 2		
		T69-170HP HNO3915256			

Engine Hours	Reefer Hours	Standby Hours	P.O. Number	Open Date / Time	Complete	Service Writer
12751.0	0.0	0.0	16786	06-12-26 / 10:37AM	06-12-26	REN*RMK

Memo	DAVE STEINBRENNER 403-350-6068 FORSHEE379@OUTLOOK.COM
------	--

Tax ID Date: Tax ID:

- 1 DIAGNOSE ENGINE FAN STAYS RUNNING WHEN UNIT IS RUNNING
CAUSE:

OPEN IN CONTROL CIRCUIT FOR A/C HIGH PRESSURE SWITCH FAN CONTROL.

CORRECTION:

TECH 227- BROUGHT UNIT INTO SHOP AND CONFIRM CUSTOMER COMPLAINT, ENGINE FAN WONT SHUT OFF, CONNECT CUMMINS INSITE AND MONITOR PARAMETERS, FOUND FAN CONTROLLED ON BY A/C. CHECK FOR P/S FLUID TEMP, CIRCUIT HAS BEEN DELETED, CHECK A/C HIGH PRESSURE SWITCH, INSPECT PINS AND FOUND NO DAMAGE OR SPREADING. CHECK A/C HIGH PRESSURE SWITCH, SWITCH IS IN CLOSED POSITION, JUMP WIRES FOR A/C PRESSURE SWITCH AND FOUND SAME RESULT, FAN RUNNING, CHECK SCHEMATIC AND REMOVE OEM ENGINE HARNESS CONNECTOR AND FOUND DAMAGED WIRE IN CONNECTOR NOT RELATED TO CIRCUIT, REPAIRED WIRE. OHM TESTED CIRCUIT, HAD OPEN CIRCUIT ON CONTROL WIRE TO A/C PRESSURE SWITCH, RETURN WIRE IN SPEC AT 0 OHMS. REMOVE SECTION OF HARNESS TO INSPECT CONTROL WIRE, COULD NOT FIND ANY DEFECTS, WILL NEED TO REPLACE OEM ENGINE HARNESS OR RUN OVERLAY TO REPAIR. ALSO FOUND ENGINE RUN TIME FOR A/C SET TO 3 MINUTES, RECOMMEND SETTING TO 60S.

TOTAL LABOR

410.00

- 2 RUN OVERLAY FOR HIGH PRESSURE A/C SWITCH
CAUSE:
OPEN CIRCUIT ON FAN CONTROL WIRE.

CORRECTION:

TECH 227- RUN OVERLAY FROM OEM ECM CONNECTOR TO HIGH RPESSURE A/C SWITCH FOR FAN CONTROL, SECURE ALL WIRING AND REPLACE PINS, SEALS AND CONNECTOR AT HIGH PRESSURE SWITCH AS CONNECTOR WAS BROKEN. TEST OPERATION OF ENGINE FAN, FOUND FAN NOW OPERATING PROPERLY, CONNECT TO INSITE AND CHANGE FAN RUN TIME FROM 3 MINUTES TO 60S AND PROGRAM PARAMETER.

UNIT # 405



Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

SEMI (WATER TRUCK)

Maintenance Request / Report Form

Information

405

Grand Prairie - Shop

Monday, June 8th 2026, 4:19 PM (MDT -06:00)

Unit Information

Date:  June 2, 2026

Select Unit Number:  405

KMs:  124633

Hours:  12748

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Cvip, transmission cooler leaking, needs to be deleted, water tank cracked

-replaced transmission cooler, flushed transmission
-full service

Dave and John finished truck off

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:



Grande Prairie Shop



FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:



Luke Jacobsen

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome, Jason Brown, Jon Archibald.

Signatures

Luke Jacobsen, *Mechanic*



June 8th 2026, 4:19 PM [MDT -06:00]



55.3094432, -118.7971597



SAMI (WATER TRUCK)

Maintenance Request / Report Form

Information

405

Grand Prairie - Shop

Saturday, January 17th 2026, 6:55 AM (MST -07:00)

Unit Information

Date: January 5, 2026

Select Unit Number: 405

KMs: # 121537

Hours: # 12011

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Fuel tank dented and leaking, mix pump valve leaking, replace gps

- replaced gps
- replaced hydraulic valve
- replaced valve hoses (cracked)
- replaced pump box heater hoses
- replaced pump box heater
- replaced passenger fuel tank and straps
- replaced tire

Tank ladder needs aluminum welding done

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Grande Prairie Shop

Requested By:

Worker Requesting Repairs: Luke Jacobsen

Signatures

Luke Jacobsen, Mechanic



January 17th 2026, 6:55 AM (MST -07:00)



55.309467, -118.7972031

A handwritten signature in black ink, appearing to be 'AJ' or similar.



SEMI (WATER)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-771

Maintenance Request / Report Form

Information

405

Conoco DL 2511-002

Sunday, November 23rd 2025, 1:18 PM [MST -07:00]

Unit Information

Date: November 23, 2025

Select Unit Number: 405

KMs: # 118727

Hours: # 11617

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

Repairs Required

Description of Repairs Required (attach photos):

Drive chains for truck

FROM FIST SHOP

Serial/Part # if applicable: = N/A

Urgency of Repairs:

Select priority level of repairs:

☒ Low Priority - Repair at earliest convenience

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft St. John Shop

Requested by:

Worker Requesting Repairs:



Jason Robins

Signatures

Jason Robins, *Laborer*



November 23rd 2025, 1:18 PM [MST -07:00]

A handwritten signature in black ink, appearing to read 'J. Robins'.



SEMI (WATER)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 405

 BHDD Shop

 Wednesday, November 26th 2025, 12:13 PM [MST -07:00]

Unit Information

Date:  November 13, 2025

Select Unit Number:  405

KMs:  117450

Hours:  11550

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Pto pump leaking, hydraulic control valve leaking

- removed pump bolted to pto, got part number for replacement
- replaced bowie pump control valve
- replaced pto filter

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

Requested By:

Worker Requesting Repairs:



Luke Jacobsen

Signatures

Luke Jacobsen, *Mechanic*



November 26th 2025, 12:13 PM (MST -07:00)



52.7250933, -111.8422056

A handwritten signature in black ink, appearing to be 'LJ' or similar, located on the right side of the page.



WATER TRUCK

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

405

BHDD Shop

Wednesday, October 29th 2025, 7:31 AM [MDT -06:00]

Unit Information

Date:  October 22, 2025

Select Unit Number:  405

KMs:  116089

Hours:  11488

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Brake pot leaking
-drove to tofield
-replaced brake pot

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

Requested By:

Worker Requesting Repairs:



Luke Jacobsen

Signatures

Luke Jacobsen, *Mechanic*



October 29th 2025, 7:31 AM (MDT -06:00)



52.8514406, -110.8420841

A handwritten signature in black ink, appearing to be 'LJ' or similar, located on the right side of the page.



SEKI (WATER TRUCK)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 405

 BHDD Shop

 Thursday, September 25th 2025, 7:53 AM [MDT -06:00]

Unit Information

Date:  September 25, 2025

Select Unit Number:  405

KMs:  114993

Hours:  11429.9

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

 Replaced inside interior light / LUKE RIGHT MIRROR

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Wainwright Shop

Requested by:

Worker Requesting Repairs:



Chase Atkinson

Signatures


Chase Atkinson, *Laborer*



September 25th 2025, 7:53 AM (MDT -06:00)



52.8483433, -110.845834

A handwritten signature in black ink, appearing to be 'Chase Atkinson', written over a faint dotted signature line.



SEMI (WATER)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 405

 BHDD Shop

 Tuesday, September 16th 2025, 9:33 AM (MDT -06:00)

Unit Information

Date:  September 16, 2025

Select Unit Number:  405

KMs:  1234

Hours:  1234

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

Repairs Required

Description of Repairs Required (attach photos):

 Steering tires

INTEGRAL

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ High Priority - Required within 1-2 days

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Wainwright Shop

Requested by:

Worker Requesting Repairs:



Jason Robins

Signatures

Jason Robins, *Laborer*



September 16th 2025, 9:33 AM [MDT -06:00]

A handwritten signature in black ink, appearing to read 'Jason Robins', written over a faint, illegible background.

Integra Tire Wainwright Ltd.
1613 - 1st Street Wainwright AB T9W 1L5

PH: 780-842-1500
FX: 780-842-1520

SOLD TO:
BRO001
BROTHERS HDD INC
2002 23 AVE

Invoice WAIR069120 (Copy)

SHIP TO
SAME

DATE: 25 Sep 16

Wainwright
T9W 0B8

AB

TEL:

FAX:

TEL: 780.214.7711

PAGE: 1

YEAR	MAKE	MODEL	ENGINE
2013	KENWORTH	T800	
PLATE NO	VIN	ODOMETER	UNIT NO.
CNM6247	1NKDX4TX6DR958685	114933	405
TIME IN	PROMISED	TERMS	P.O.
9:42 AM		NET 30	
		WRITTEN BY	TAG
		HR	

QTY	ITEM/DESCRIPTION	SIZE	TAX	NET	EXT.PRICE
2	44007	425/65R22.5	G	678.75	1357.50
	WESTLAKE AT557 165K 20L				
2	TTAB2		G	14.00	28.00
	TIRE RECYCLING FEE - AB (Medium Truck, ETC)				
2	COWB CHANGE OVER WIDE BASE JAR DF		G		105.10
2	TEC545D	VALVE	G	9.95	19.90
	MISC O-RING VALVE				
1	tlgal	TIRE LIFE	G	49.95	49.95
	MISC TIRE LIFE				
1	SHP		G	12.98	12.98
	SHOP SUPPLIES				
TOTAL DISCOUNT GIVEN---> 294.22					
GST Registration# 820001915RT0001					
**WARNING, WHEEL MANUFACTURERS RECOMMEND CHECKING THE TORQUE ON FASTENERS ON PASSENGER CARS/LIGHT TRUCKS AT 30-50 KM AND MEDIUM TRUCKS AT 80-160 KM AFTER EACH WHEEL REMOVAL AND INSTALL. THIS SERVICE IS PROVIDED FREE OF CHARGE. PLEASE SEE US TO HAVE THIS DONE. FAILURE TO DO SO MAY RESULT IN A WHEEL OFF SITUATION. AIR SET AT _____ WHEEL NUTS HAND TORQUED _____ FT. LBS					
GST EXEMPT #:		PST EXEMPT #:			

PARTS:	1427.35
LABOUR:	105.10
OTHER:	40.98
SUB-TOTAL:	1573.43
GST:	78.69
PST:	N/C
TOTAL:	1652.12



SEMI (WATER)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

405

BHDD Shop

Tuesday, September 16th 2025, 7:33 AM (MDT -06:00)

Unit Information

Date: September 16, 2025

Select Unit Number: 405

KMs: 1234

Hours: 1234

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

Repairs Required

Description of Repairs Required (attach photos):

Battery shut off switch isn't working **LUKE**

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ High Priority - Required within 1-2 days

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Wainwright Shop

Requested By:

Worker Requesting Repairs: Jason Robins

Signatures

Jason Robins, *Laborer*

September 16th 2025, 7:33 AM (MDT -06:00)



SEMI (WATER TRUCK)

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

405

O.B. Colony CM-Marwayne 2506-001

Friday, June 6th 2025, 9:02 AM [MDT -06:00]

Unit Information

Date: June 6, 2025

Select Unit Number: 405

KMs: # 67016

Hours: # 109812

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

- FLOAT FOR TANK


Repairs Required

Description of Repairs Required (attach photos):

Mixing hopper not working properly

Serial/Part # if applicable:

No Response



Urgency of Repairs:

Select priority level of repairs:

☒ Low Priority - Repair at earliest convenience

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Wainwright Shop

Requested By:

Worker Requesting Repairs:

 Howard Ferron

Signatures

Howard Ferron, *Laborer*

 June 6th 2025, 9:02 AM (MDT -06:00)





Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

SEMI

Maintenance Request / Report Form

Information

405

BHDD Shop

Wednesday, May 7th 2025, 3:16 PM [MDT -06:00]

Unit Information

Date: April 16, 2025

Select Unit Number: 405

KMs: # 66876

Hours: # 10960

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Checkover, cvip

- replaced rear axle front left wheel seal
- replaced hydraulic return hose from water pump box
- tightened fitting on passenger fuel tank
- removed left middle axle, suspension hanger
- installed new suspension frame bracket with new hardware
- installed new pivot bushing
- installed wheels
- sent to northern truck and trailer for an alignment.
- rear water tank valve heater leaking coolant, welder repaired

ALIGNMENT DONE

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Standard Priority - Required within 3-5 days

Location of repairs being completed:

Pick the location where the repairs were completed:



Wainwright Shop

Requested By:

Worker Requesting Repairs:



Luke Jacobsen

Signatures

Luke Jacobsen, *Mechanic*



May 7th 2025, 3:16 PM (MDT -06:00)



52.8513355, -110.8421554



MAINTENANCE WORK ORDER

Nº 3399

UNIT #: 405
ENGINE HOURS: 10958
MILEAGE: 66876
WORK LOCATION: Wainwright
WORK REQUESTED: _____

ORDER DATE: Mar 18 2025
COMPLETED DATE: Mar 20 2025
JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: ~~Service~~ Repair Pto cooler fan

TECH COMMENTS: _____

LABOUR DESCRIPTION: _____ HOURS

Diagnose Pto switch wiring, replaced corroded connectors 3
replaced fuse, Adjusted pto air switch

Installed pump box water pump 3

LABOUR TOTAL 6

PARTS & MATERIALS

P.O. # QUANTITY PRICE AMOUNT

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Ron

WORK COMPLETED BY: Mike Jackson

UNIT RETURNED TO SERVICE: Mar 20 2025

OVERALL CONDITION OF UNIT: Good

ADDITIONAL COMMENTS: _____



SEMI

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

405

Fsj shop

Monday, February 24th 2025, 12:17 PM [MST -07:00]

Unit Information

Date: February 24, 2025

Select Unit Number: 405

KMs: # 106389

Hours: # 10903

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Request - Request shop assistance in facilitating repairs.

COMPLETED
FTST KIRK.

Repairs Required

Description of Repairs Required (attach photos):

Front drive axle output seal leaking



Serial/Part # if applicable: ≡ No Response

Urgency of Repairs:

Select priority level of repairs:

☒ Standard Priority - Required within 3-5 days

Location of repairs being completed:

Pick the location where the repairs were completed:

☒ Ft St. John Shop

Requested By:

Worker Requesting Repairs:  Kirk Bauming

Signatures

Kirk Bauming, *Construction Coordinator - BC*

 February 24th 2025, 12:17 PM (MST -07:00)

 56.228941, -120.8336431





SEMI

Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information



405



FSJ Shop



Wednesday, April 2nd 2025, 1:24 PM (MDT -06:00)

Unit Information

Date:



February 24, 2025

Select Unit Number:



405

KMs:



106389

Hours:



10903

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.



Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):



Oil change, fuel filters, grease truck, replace front diff output seal, replace air dryer desiccant filter, replace air dryer purge valve

Serial/Part # if applicable:



No Response

Urgency of Repairs:

Select priority level of repairs:



Low Priority - Repair at earliest convenience

Location of repairs being completed:

Pick the location where the repairs were completed:



Ft St. John Shop


Requested by:

Worker Requesting Repairs:



Kirk Bauming

Additional Photos



Signatures

Kirk Bauming, *Construction Coordinator - BC*



April 2nd 2025, 1:24 PM [MDT -06:00]



56.2288068, -120.8346605



Brothers HDD Inc.
2002 23 Avenue,
Wainwright, Alberta
T9W 0B8
780-214-7711

SEMI (WATER)

Maintenance Request / Report Form

Information

405

Grand Prairie - Shop

Tuesday, February 3rd 2026, 4:02 PM [MST -07:00]

Unit Information

Date: January 30, 2026

Select Unit Number: 405

KMs: # 121784

Hours: # 12245

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

Not building air

Jan 30

- replaced air compressor
- fixed air line leak
- replaced low beam light

Feb3

- brought to shop
- removed air compressor
- installed with new gasket
- fixed air leaks behind dash

Serial/Part # if applicable: No Response

Urgency of Repairs:

Select priority level of repairs:

 Completed

Location of repairs being completed:

Pick the location where the repairs were completed:

 Field Repaired

FULL SERVICE COMPLETED? Check the box if Oil /Filters & inspection are performed.

Requested By:

Worker Requesting Repairs:

 Luke Jacobsen

Request submitted to:

After signing Request Form be sure to: Request Signature or Approval Tab and select either from the Given Names below: Ron Jerome Dan Fontaine Jon Archibald

Signatures

Luke Jacobsen, *Mechanic*

 February 3rd 2026, 4:02 PM (MST -07:00)

 55.3092776, -118.7972046





Brothers HDD Inc
2002 23 Avenue
Wainwright, Alberta
T9W 0B8
780-214-7711

Maintenance Request / Report Form

Information

 405

w/o #000146

 BHDD Shop

 Tuesday, March 25th 2025, 2:38 PM (MDT -06:00)

Unit Information

Date:  January 15, 2025

Select Unit Number:  405

ENTERED
MAR 26 2025

KMs: # 0

Hours: # 10906

Please choose from list to identify if this is a request for Maintenance? Or if you are Reporting on maintenance completed.

☒ Maintenance Report - Field completion of maintenance.

Repairs Required

Description of Repairs Required (attach photos):

-  Engine service
 - oil and oil filter
 - fuel filters
 - complete check over
 - *completed by Kirk B*

Serial/Part # if applicable:  No Response

Urgency of Repairs:

Select priority level of repairs:

☒ High Priority - Required within 1-2 days

Location of repairs being completed:

Pick the location where the repairs were completed:

Requested By:

Worker Requesting Repairs:



Chad Marsh

Signatures

Ron Jerome, *Supervisor*



March 25th 2025, 2:38 PM [MDT -06:00]



52.8515713, -110.8419083

A handwritten signature in black ink, consisting of a stylized 'X' shape with a horizontal line extending to the left.



ENTERED
FEB 11 2025
CC

MAINTENANCE WORK ORDER

Nº 2769

UNIT #: 405
ENGINE HOURS: 9888
MILEAGE: _____
WORK LOCATION: FSJ
WORK REQUESTED: Jason/Chad

ORDER DATE: Nov. 18/24
COMPLETED DATE: Nov. 27/24
JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: Rebuild Bowtie pump, Change mission pump drain valve,
Full service and grease, replace exhaust tube and clamps.
Replace bottom Red hose, drain/refill Rad

TECH COMMENTS: _____

LABOUR DESCRIPTION:

HOURS

Kirk

LABOUR TOTAL _____

PARTS & MATERIALS

	P.O. #	QUANTITY	PRICE	AMOUNT	00
<u>Bowie pump parts (gears, bushings, gaskets)</u>	<u>#10777</u>	<u>1</u>		<u>\$960</u>	
<u>Pump drain parts</u>	<u>#10759</u>	<u>1</u>		<u>\$12.42</u>	
<u>Fuel/Oil/Air Filters</u>	<u>#10810</u>			<u>\$417.75</u>	

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Kirk

WORK COMPLETED BY: Kirk

UNIT RETURNED TO SERVICE: Nov. 27/24

OVERALL CONDITION OF UNIT: Good

ADDITIONAL COMMENTS: _____



22305

CORP

3300 3"

UNIT #405

RED L \$ 2131.11
LASH \$ 2003.



W. E. B. DUBOIS

1303

204-724

11-22-68

11:18

FRF



CHAD

C

108

COOLING FAN
~~HND~~ MOTOR
HND

Chad Marsh (Brothers) >

Today 11:15 AM

#4058

KRISTON

Ron could you please
line up this stuff for me
please . I come back up
here on January 30th
I have a R6 body I am
going to need 16" arms
cutters

LUCAS

18" arms, cutters

VIPER

And 24" hole opener 🙄

New chains for chain
wrench mine are old
have not been replaced
sic I was one tmx we
keep breaking them.

BECKO

Shayne said to send you
the list. Please and thank
you very much I
appreciate what you do
for us.

lol



Text Message



11:36

SCM



S



Shayne (Brothers) >



405
CHAD

LASH (LLOYD)
ORDERED FEB 4
TRISTAN
\$ 585.93 + \$ 30.00 FRT
1-2 DAYS

Dallas Larson
Brothers HDD

DL >

Today 11:36 AM

BUDDA

1" & 5/8 Allen wrench on
a 1/2"

THURSDAY, @NAPA

Drive socket please



iMessage



SEAL

01

03 2760

TYPE VA18 AP70/LL 36A 12V

Italy No WO 640452



MAINTENANCE REQUEST FORM

UNIT#

405

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED

NEEDS 2WAY RADIO

● MIA PUMP NEEDS RACKING 1 HOUR

AIR LEAKS
~~AIR DRYER~~ LEAKING ABS LIGHT IS ON

● 4" BUTTERFLY VALVE FOR MIA PUMP NEEDS
ADJUSTMENT
ADJUSTED DOESN'T OPEN ALL THE WAY

● DRAIN VALVE NEEDS REPLACED ON 1 HOUR

MIA PUMP

CORY-TIRE GOOD ✓
STEERING TIRES ARE IN REALLY BAD!

SHAPE WEARING ON OUTSIDE EDGES

● CORY / CBASE

2 TOTAL

REQUESTED BY:


JASON ROBINS

DATE:

RECHARGE A/C

220
405

THESE ARE THE
RESULTS OF THE
ANALYSIS OF THE
SAMPLES TAKEN
ON THE 10th OF
MAY 1964.
THE RESULTS ARE
AS FOLLOWS:
1. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:
2. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:
3. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:
4. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:
5. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:
6. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:
7. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:
8. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:
9. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:
10. THE
CONCENTRATION OF
THE ELEMENTS
IN THE SAMPLES
IS AS FOLLOWS:



MAINTENANCE REQUEST FORM

UNIT# 405

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED

INSTALL WINTER EXHAUST (CHROME STACKS
TO BOGGIE BAY)

BOWIE PUMP PACKING (LEAK)

ABS LIGHT MIDDLE AXLE / LEFT WHEEL SPEED SENSOR

4" MAIN BUTTERFLY VALVE

BOWIE PUMP REPLACEMENT (REBUILD)

*CHROME TIRES?

REQUESTED BY:

DATE:



9706

MAINTENANCE WORK ORDER

Nº 2768

UNIT #: 405 - Plate CNM6247
ENGINE HOURS: ~~1244~~ 9888 hrs
MILEAGE: _____
WORK LOCATION: Fort Saint John Shop
WORK REQUESTED: CUSA Inspection

ORDER DATE: Nov. 18/24
COMPLETED DATE: Nov. 25/24
JOB #: _____

W.O. TYPE (Circle): PM CVIP **Reactive**

REPAIRS REQUIRED: Replace Rear Axle left Brake pot, Rear Axle left ABS sensor
Set-up all brakes, tie-up loose wires, top-up coolant

TECH COMMENTS: _____

LABOUR DESCRIPTION:

HOURS

Jack up, remove rear axle left tires/drum/shoes. Replace ABS
sensor and Brake pot, set all brakes, check tire pressures and
Fill Steer to 110psi

* Torque wheel to 300 ft/lbs - retorque within 30km

LABOUR TOTAL _____

PARTS & MATERIALS

	P.O.#	QUANTITY	PRICE	AMOUNT
<u>ABS wheel sensor</u>	<u>#10771</u>	<u>1</u>		<u>75.73</u>
<u>Brake pot 3030 piggyback</u>		<u>1</u>		<u>57.49</u>

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Kirk B WORK COMPLETED BY: Kirk BUNIT RETURNED TO SERVICE: Nov. 25/24 OVERALL CONDITION OF UNIT: Good

ADDITIONAL COMMENTS: _____



MAINTENANCE REQUEST FORM

UNIT# 405

HRS/KM

DESCRIPTION OF REPAIRS REQUIRED
BASE RADIO
FIRE EXT
WINTER EXHAUST

REQUESTED BY:

DATE:

ADDITIONAL COMMENTS:



MAINTENANCE WORK ORDER

N^o 1672UNIT #: 405ENGINE HOURS: 8962MILEAGE: 94538WORK LOCATION: Shop

WORK REQUESTED: _____

ORDER DATE: Sept 25-23COMPLETED DATE: Sept 25-23

JOB #: _____

W.O. TYPE (Circle): PM CVIP ReactiveREPAIRS REQUIRED: Broken Ign Key

TECH COMMENTS: _____

LABOUR DESCRIPTION: _____ HOURS

Remove Broken Ky get Ky cut 3LABOUR TOTAL 3

PARTS & MATERIALS P.O. # QUANTITY PRICE AMOUNT

Foggy lock and glass 4005 _____PARTS & MATERIALS TOTAL 12.00WORK AUTHORIZED BY: Car WORK COMPLETED BY: CarUNIT RETURNED TO SERVICE: Sept 25 23 OVERALL CONDITION OF UNIT: OK

ADDITIONAL COMMENTS: _____



**Eagle Lock & Glass
Services Ltd.**

Eagle Lock & Glass Services Ltd.

2005 14 Avenue

Wainwright AB T9W 1T9

780-842-9134

eaglelock2022@outlook.com

GST/HST Registration No.: 709502702RT0001

INVOICE

BILL TO

Brothers HDD

INVOICE

4261

DATE

25/09/2023

TERMS

Net 30

DUE DATE

25/10/2023

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
25/09/2023	Key Cut by Code	Unit# 405 Cory Rubyk PO 4005	1	30.00	30.00
	Double sided key Cut		1	10.00	10.00

SUBTOTAL

40.00

GST @ 5%

2.00

TOTAL

42.00

BALANCE DUE

\$42.00

Payment Options:

Cheque payable to:

Eagle Lock & Glass Services Ltd.

Etransfer: eaglelock2022@outlook.com

Page 1 of 1



MAINTENANCE WORK ORDER

Nº 1664

UNIT #: 4105
ENGINE HOURS: 8656-0
MILEAGE: 57273 mi
WORK LOCATION: Edson
WORK REQUESTED: _____

ORDER DATE: July 19 2023
COMPLETED DATE: July 21 2023
JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED:

Coolant leak out heater control valve
Boiler pump packing

TECH COMMENTS:

LABOUR DESCRIPTION:

Replace Valves
Boiler pump Packing

HOURS

3
2

LABOUR TOTAL

PARTS & MATERIALS

Packing Stack
Valve Kenworth

P.O. # QUANTITY PRICE AMOUNT

PARTS & MATERIALS TOTAL

WORK AUTHORIZED BY: _____

WORK COMPLETED BY: CoyUNIT RETURNED TO SERVICE: July 21 23OVERALL CONDITION OF UNIT: Good

ADDITIONAL COMMENTS: _____

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue

Edmonton, AB

T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:

Kenworth Lloydminster

6101 - 63 Avenue

Lloydminster, Alberta T9V 3T6

Phone: 780-871-0950

Invoice: **04LP355578**

Date / Time: 7/19/2023 12:46:43PM

Parts Order: 355578

Customer: 12301

Branch: Lloyd

Invoice Total: \$ 256.18

*** Charge ***

Page 1 of 1

Bill To: BROTHERS HDD INC.

2002 - 23 AVE

WAINWRIGHT, AB T9W 0B8

Ship To: BROTHERS HDD INC.

2002 - 23 AVE

WAINWRIGHT, AB T9W 0B8

Office Phone: (780) 875-8845

Fax: (780) 875-6474

Email: ahopaluk@brothershdd.ca

Customer P/O: 3580

Invoiced By: rabellana

Delivery Method: JASON KING

Supplier	Part / Misc	Description / Ref Number	U/M	Quantity	Price	Ext Price
P0100	SR2000013	VALVE ASSY-WATER	EA	1	\$243.98	\$243.98

Bin Location: REM

Customer Tax ID: 847576063RT0001

GST/HST Number: R101577278

Detail Tax Info:

GST REGISTRATION NUMBER: R101577278

Total: \$12.20
\$12.20

Invoice Subtotal: **\$243.98**

Total Tax: **\$12.20**

Invoice Total: \$256.18

Payment Method:

Charge

Payment Terms:

Net 15th of month

Due Date:

08/15/2023

2013 KW T800

1NKDX4TX6DR958685

Please Provide Proof Of Purchase For Returns. A Minimum Restocking Charge of 15% May Be Assessed At Our Discretion. No Return On Electrical Components or Special Ordered Parts.

Cores Not Drained and Cleaned Will Be Subject To A Cleaning Fee. Cores Must Be Returned Within 9 Months of Purchase Date. All Cores Are Subject To Vendor's Core Return Criteria.

Prices Quoted Are Valid For 30 Days On In Store, In Stock Items Only.

UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

If the balance due isn't paid within Edmonton Kenworth's credit terms, I agree to pay interest at the rate of 2% per month (24% per annum).

SIGNATURE: _____

PRINT NAME: _____



MAINTENANCE WORK ORDER

Nº 1093

UNIT #: 405
ENGINE HOURS: 8624
MILEAGE: 57 265
WORK LOCATION: Edson Area
WORK REQUESTED: _____

ORDER DATE: July 6 23
COMPLETED DATE: July 7 23
JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: HYD cooling Fan stopped working.
coolant leak

TECH COMMENTS: _____

LABOUR DESCRIPTION:	HOURS
<u>Tightened Rad hoses for coolant leak.</u>	<u>1</u>
<u>O Replaced Hobbs PSI switch</u>	<u>1</u>

LABOUR TOTAL _____

PARTS & MATERIALS	P.O. #	QUANTITY	PRICE	AMOUNT
<u>Hobbs PSI switch (stock)</u>				

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: Conl WORK COMPLETED BY: Conl

UNIT RETURNED TO SERVICE: July 7 23 OVERALL CONDITION OF UNIT: OK

ADDITIONAL COMMENTS: _____



MAINTENANCE WORK ORDER

N^o 1705

UNIT #: 405

ENGINE HOURS:

MILEAGE: 55838

WORK LOCATION: Brother HDD Shop

WORK REQUESTED:

ORDER DATE: Feb/6/23

COMPLETED DATE: Feb/6/23

JOB #:

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: replacing coolant hoses

TECH COMMENTS: the brackets that are holding the water tank on are cracked

LABOUR DESCRIPTION: took out and put in 3 new coolant hoses

HOURS

6.5

LABOUR TOTAL

PARTS & MATERIALS

5/8 hose

P.O. #	QUANTITY	PRICE	AMOUNT
2712	50ft		

PARTS & MATERIALS TOTAL

WORK AUTHORIZED BY: Chase Atkinson

WORK COMPLETED BY: Chase

UNIT RETURNED TO SERVICE: ~~OK~~

OVERALL CONDITION OF UNIT:

ADDITIONAL COMMENTS: Need to fix brackets that hold the water tank on



MAINTENANCE WORK ORDER

N^o 1050UNIT #: 405

ENGINE HOURS: _____

MILEAGE: 55838KM

WORK LOCATION: _____

WORK REQUESTED: WAINWRIGHT STOPORDER DATE: JAN 26/2023COMPLETED DATE: FEB 9/2023

JOB #: _____

W.O. TYPE (Circle): PM CVIP Reactive

REPAIRS REQUIRED: _____

TECH COMMENTS: _____

LABOUR DESCRIPTION:

HOURS

- HELP CHASE A. WITH COOLANT LINE REPAIRMENT/ROD (1)- RUN / TEST AND CHECK COOLANT SYSTEMUNDER PRESSURE ROD (1)- SECURE COOLANT HOSES AND INSULATION AROUNDVALVES ROD (2)

LABOUR TOTAL 6

PARTS & MATERIALS

B & B INVOICE # 1-4562160

PARTS & MATERIALS TOTAL _____

WORK AUTHORIZED BY: CORY RWORK COMPLETED BY: RON J, CHASE A, CORY RUNIT RETURNED TO SERVICE: FEB 9/2023

OVERALL CONDITION OF UNIT: _____

ADDITIONAL COMMENTS: _____
