



F20-2
AUG

Mechanic Work Order

Information



RTK-06



Foster Creek



Sunday, July 19th 2026, 6:50 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number



RTK-06

General Information

Date



July 18, 2026

Tech Name



Brandon German

Last service done @ [HR/KM]:



No Response

Next service due @ [HR/KM]:



No Response

Odometer:



0

Hours:



6908

Repair

Repair Description



install new boost coupler, blow out cooler pack.

Location



ntr

Hours



1

Parts

Signatures

Brandon German, Mechanic LC

July 19th 2026, 6:50 AM (MDT -06:00)

51.0447331, -114.0718831

B.G



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, July 18th 2026, 8:20 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 July 17, 2026

Tech Name

 Brandon German

Last service done @ {HR/KM}:

 No Response

Next service due @ {HR/KM}:

 No Response

Odometer:

 0

Hours:

 6902

Repair

Repair Description

 low power complaint, found EGR block off plate gasket blown out, replaced.

Location

 ntr

Hours

 1

Parts

Signatures

Brandon German, *Mechanic LC*

 July 18th 2026, 8:20 AM [MDT -06:00]

B.G

Kirby Mckay, *Project Manager*

 Approved
 July 18th 2026, 3:35 PM [MDT -06:00]

KM



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, July 18th 2026, 8:36 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 July 17, 2026

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 6904

Repair

Repair Description

 now that unit has all its exhaust pressure to build boost it blew intercooler boot, cut tear out of boot. installed back on to unit. tapped boot up over another part of boot that looked like it was about to blow. put unit back into service it lasted 2.5hrs. then blew again. parts here at end of day will fix tomorrow

Location

 NTR

Hours

 1

Parts

Signatures

Brandon German, *Mechanic LC*

 July 18th 2026, 8:36 AM [MDT -06:00]

B.G

Kirby Mckay, *Project Manager*

 Approved

 July 18th 2026, 3:34 PM [MDT -06:00]

KW



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, July 18th 2026, 8:20 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 July 17, 2026

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 6902

Repair

Repair Description

 low power complaint, found EGR block off plate gasket blown out, replaced.

Location

 ntr

Hours

 1

Parts

Signatures

Brandon German, Mechanic LC

 July 18th 2026, 8:20 AM [MDT -06:00]

B.G

Kirby McKay, Project Manager

 Approved

 July 18th 2026, 3:35 PM [MDT -06:00]

KM



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Friday, July 17th 2026, 10:29 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 July 16, 2026

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 6897

Repair

Repair Description

 blown remote grease line going to LH box lift cylinder rod eye. removed line, built at shop when i went to get lexan for HLTH-22. installed line when i went back up north.

Location

 ntr

Hours

 1

Parts

Signatures

Brandon German, *Mechanic LC*

 July 17th 2026, 10:29 AM [MDT -06:00]

B.G.

Kirby Mckay, *Project Manager*

 Approved

 July 17th 2026, 4:17 PM [MDT -06:00]

KM



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, July 4th 2026, 3:00 PM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 June 30, 2026

Tech Name

 Mitchell Teer

Last service done @ {HR/KM}:

 No Response

Next service due @ {HR/KM}:

 No Response

Odometer:

 0

Hours:

 6770

Repair

Repair Description

 travel to unit, blew out rads on unit.

Location

 foster creek

Hours

 2

Parts

Signatures

Mitchell Teer, HL Contract Mechanic

 July 4th 2026, 3:00 PM (MDT -06:00)





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Sunday, June 28th 2026, 1:14 PM (MDT -06:00)

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 June 26, 2026

Tech Name

 Mitchell Teer

Last service done @ {HR/KM}:

 No Response

Next service due @ {HR/KM}:

 No Response

Odometer:

 0

Hours:

 6754

Repair

Repair Description

 travel to unit T/S hyd leak, found leak and repaired leak.

Location

 foster creek

Hours

 2

Parts

Signatures

Mitchell Teer, HL Contract Mechanic

June 28th 2026, 1:44 PM (MDT -06:00)

A handwritten signature in black ink, appearing to be 'MT', written over a horizontal line.



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Tuesday, June 16th 2026, 11:41 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 June 16, 2026

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 6721

Repair

Repair Description

 ran out west, install new fuel cap, run back to laydown

Location

 w44 bridge

Hours

 2

Parts

Signatures

Brandon German, *Mechanic LC*

 June 16th 2026, 11:41 AM [MDT -06:00]

 55.0436864, -110.526464

Kirby Mckay, *Project Manager*

 Approved

 June 16th 2026, 2:31 PM [MDT -06:00]

Ryan Findlay, *Safety*

 June 17th 2026, 8:43 AM [MDT -06:00]

B.G

KM





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, June 13th 2026, 8:21 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 June 12, 2026

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 6720

Repair

Repair Description

 run out west to check on noise complaint on unit, checked for exhaust leaks, went for ride in unit has the typical squeel on boost, unit is good to use.

Location

 WTR W42 "RML 4B"

Hours

 2

Parts

Signatures

Brandon German, *Mechanic LC*

 June 13th 2026, 8:21 AM (MDT -06:00)

 51.0447331, -114.0718831

B.G

Kirby Mckay, *Project Manager*

 Approved

 June 16th 2026, 5:28 AM (MDT -06:00)

KM



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, June 13th 2026, 8:24 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 June 12, 2026

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 6721

Repair

Repair Description

 fuel leak on unit, leave tent and run out west, fuel cap leaked, 3rd time its happend on this truck, orderd new cap, cleaned up diesel, drained 40L out of unit. cleaned up cap matting surfaces greased surfaces, installed washers to make cap grab tighter.

Location

 W43 bridge

Hours

 2

Parts

Signatures

Brandon German, *Mechanic LC*

 June 13th 2026, 8:24 AM [MDT -06:00]

 51.0447331, -114.0718831

B.G

Ryan Findlay, *Safety*

 June 13th 2026, 2:40 PM [MDT -06:00]



Kirby Mckay, *Project Manager*

 Approved

 June 16th 2026, 5:29 AM [MDT -06:00]

KM



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Wednesday, May 20th 2026, 7:53 AM (MDT -06:00)

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 May 19, 2026

Tech Name

 Brandon German

Last service done @ {HR/KM}:

 No Response

Next service due @ {HR/KM}:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 fire up and check over RTK-05/06/07/08. all run with no leaks, and ice cold ac, tires looked good, cleared all codes on units. RTK-06/08 have a code for HVAC filter blower.

Location

 HLC Laydown yard

Hours

 3

Parts

Signatures

Brandon German, *Mechanic LC*

 May 20th 2026, 7:53 AM [MDT -06:00]

BG

Kirby Mckay, *Project Manager*

 Approved

 May 20th 2026, 3:24 PM [MDT -06:00]

KM



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Wednesday, May 6th 2026, 8:06 AM (MDT -06:00)

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 April 21, 2026

Tech Name

 Mitchell Teer

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 6696

Repair

Repair Description

 replaced engine oil hose from block to filter and orings

Location

 foster

Hours


 2

Parts

Signatures

Mitchell Teer, HL Contract Mechanic

 May 6th 2026, 8:06 AM (MDT -06:00)





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Tuesday, March 10th 2026, 9:10 PM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 March 10, 2026

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 6505

Repair

Repair Description

 wiper washer sprayer shooting straight up, adjusted sprayer to hit window properly

Location

 north pit

Hours

 1

Parts

Signatures

Brandon German, *Mechanic LC*

 March 10th 2026, 9:10 PM [MDT -06:00]

B.G.

Steven Orcutt, *Project Manager*

 Approved
 March 11th 2026, 6:00 AM [MDT -06:00]





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Wednesday, February 18th 2026, 11:16 AM (MST -07:00)

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 February 17, 2026

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 wiper arm stripped, removed arm and cut pinch gap bigger so it grabs tighter, cut groves in motor pivot. installed arm again.

Location

 NTR borrow pit

Hours

 2

Parts

Signatures

Brandon German, *Mechanic LC*

February 18th 2026, 11:16 AM [MST -07:00]

B.G

Steven Orcutt, *Project Manager*

Approved

February 18th 2026, 12:06 PM [MST -07:00]





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Monday, February 2nd 2026, 10:13 PM [MST -07:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 February 2, 2026

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 5939

Repair

Repair Description

 Install emissions module, reassemble sheet metal, install exhaust cover/stack, crawl under unit and loop DEF injector coolant lines. fire unit up check over for leaks park in back yard. unit will be good to return to service once i decide what to do with

Location

 HLC Laydown Yard

Hours

 4

Parts

Signatures

Brandon German, *Mechanic LC*

 February 2nd 2026, 10:13 PM [MST -07:00]

B.G

Steven Orcutt, *Project Manager*

 Approved

 February 3rd 2026, 10:51 AM [MST -07:00]



 55.05958, -110.5286075



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Sunday, February 1st 2026, 9:33 PM [MST -07:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 February 1, 2026

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 5939

Repair

Repair Description

 Hollowed out exhaust filters are back, reassemble emissions module, module ready to install back on to unit

Location

 HLC Laydown Yard

Hours

 1

Parts

Signatures

Brandon German, *Mechanic LC*

 February 1st 2026, 9:33 PM [MST -07:00]

B.G

Steven Orcutt, *Project Manager*

 Approved

 February 2nd 2026, 10:30 AM [MST -07:00]





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, January 31st 2026, 9:57 PM [MST -07:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 31, 2026

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 5939

Repair

Repair Description

 install egr block off plate on exhaust manifold, broke 2 bolts had to extract install egr block off plates on intake. pull unit out. disassemble emissions module to extract SCR, DOC, DPF from emissions module to send out to get cleaned out.

Location

 HLC Laydown yard

Hours

 5

Parts

Signatures

Brandon German, *Mechanic LC*

 January 31st 2026, 9:57 PM (MST -07:00)

 55.0564889, -110.4918409

Steven Orcutt, *Project Manager*

 Approved

 February 2nd 2026, 10:46 AM (MST -07:00)

B.G.





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, January 31st 2026, 9:53 PM [MST -07:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 30, 2026

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 5939

Repair

Repair Description

 low ash rest done, ready for delete guy, pulled tune off unit sent off to delete guy, Removed sheet metal to access emissions module, ready to pull module once delete tune is ready, penetrating oil all bolts that need to be removed. flash delete tune into unit, fire it up.

Location

 HLC Laydown yard

Hours

 3

Parts

Signatures

Brandon German, *Mechanic LC*

 January 31st 2026, 9:53 PM [MST -07:00]

Steven Orcutt, *Project Manager*

 Approved

 February 2nd 2026, 10:48 AM [MST -07:00]

 55.05958, -110.5286075

B.G





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Tuesday, January 13th 2026, 6:41 AM (MST -07:00)

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 12, 2026

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 5932

Repair

Repair Description

 ran def pressure up test failed, removed def suction line, ran line from a def jug on ground to dosing unit, ran pressure up test again unit built 130psi right away. connected old system ran test and failed. ordered new def suction lines, inline filter housing and filter set for DEF header.

Location

 BP26

Hours

 3

Parts

Signatures

Brandon German, *Mechanic LC*

 January 13th 2026, 6:41 AM [MST -07:00]

 55.0606059, -110.5287758

B.G

Steven Orcutt, *Project Manager*

 Approved

 January 13th 2026, 2:47 PM [MST -07:00]

 50.3555952, -113.9898079





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Monday, January 12th 2026, 7:15 AM [MST -07:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 11, 2026

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

— unit throwing low def pressure codes, ran DEF pressure up test unit only building 23psi, replaced inline filter, and DEF dosing unit filter. ran pressure up test built 150 psi, code gone, test drove unit to bp26 as i was turning into pit code came back. got a ride back to my service truck and brought DEF header filter. ran pressure up test only building 15 psi. removed out feed line from dosing unit got def fluid and air, wasn't getting consistent flow, removed def header replaced pick up filter, old one was broken off. reused old sock, checked pick up pipes for leaks. reassembled tested, still low pressure. pressurized DEF tank with air with inline filter to dosing unit line off got def flow. capped lines and pressurized cant see any def lines leaking. going to run a remote supply to dosing unit tomorrow if it builds pressure with remote tank trucks DEF system has a issue, if it doesn't pressure up dosing unit bad.

Location

— HLC laydown Yard/BP26

Hours

8

Parts

Signatures

Brandon German, *Mechanic LC*

 January 12th 2026, 7:15 AM (MST -07:00)

 55.0606008, -110.5287841

Steven Orcutt, *Project Manager*

 Approved

 January 12th 2026, 4:16 PM (MST -07:00)

 51.0447331, -114.0718831

B.G





Equipment Maintenance & Service Tracker

Information

RTK-06

Head Office

Wednesday, November 26th 2025, 2:41 PM [MST -07:00]

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

RTK-06

General Info

Date

September 7, 2025

Current Hours or Kilometers

5739 HRS WARRANTY

Next Service Due Hours or Kilometers

WARRANTY STEERING CYLINDER

Brief Description of Work Done on Unit

WARRANTY

Attach Copy of Service & Maintenance Sheet

20251126145656491.pdf View



Brandt Tractor Ltd.
#5, 360 Mackenzie Blvd.
Fort McMurray, AB
T8H 1C4
(780) 791-8635

Service
Invoice



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
25SEP25	08	1055223

SOLD TO:
HEART LAKE FIRST NATIONS
STK # 01855223
G/L # 105-00-0008
S/N # 1DW410EBHMF709233

PAGE 1
DATE 1
WARRANTY
CUSTOMER

HEART LAKE FIRST NATIONS
CONSTRUCTION LTD 1666340
BOX 2228
LAC LA BICHE, AB T0A 2C0

POUCHART ORDER NO.	PHONE NUMBER	INVOICE NO.	DATE OF ORDER	DATE OF INVOICE
RTK-06	780-623-2935	1055223	04	07SEP25
DATE	MODEL	SEAL NO.	QUANTITY	UNIT
JD	410E II	1DW410EBHMF709233	RTK-06	5739
DARCY 780-623-1508				

REPLACE GREASE SEALS AT ROD END OF STEERING CYLINDERS

COMPLAINT:
CUSTOMER COMPLAINED STEERING CYLINDER
LEAKING

CAUSE:
CAUSE - BLOWN SEAL

CORRECTION:
0.5 INSPECT UNIT, FOUND ROD END OF
STEERING CYLINDERS LEAKING FROM GREASE
SEAL.
2.25 REMOVE STEERING CYLINDER PINS.
CLEAN GREASE. REMOVE SEALS. CLEAN BORES
& ROD END USING PARTS CLEANER &
COMPRESSED AIR. REASSEMBLE WITH NEW
SEALS. REINSTALL PINS. RUN UNIT TO
VERIFY PROPER OPERATION & LEAK NO
LONGER PRESENT, PROBLEM CORRECTED.
PG

2 N T288923 SEAL XY
4 N AT454030 SEAL XY
** TOTAL LABOR **
ENVIRONMENTAL FEE

>>--> SEG# 04 PRT LAB MSC TOTAL

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL	

PAST DUE INTEREST 1.12% PER MONTH (18% ANNUAL, MINIMUM CHARGE OF \$1.50).

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your
employee may operate above machines for purposes of testing, inspection, or delivery at my risk. I agree to
pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express receipt
then it is acknowledged on above machine to secure the amount for repair thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine
placed with them for storage, sales, repair or while field testing.

X SIGNATURE DATE

CUSTOMER COPY

14-1111C



Brandt Tractor Ltd.
#5, 360 MacKenzie Blvd.
Fort McMurray, AB
T9H 4C4
(780) 791-6635

Service Invoice



JOHN DEERE

SOLD TO:

HEART LAKE FIRST NATIONS
STK # 01855223
G/L # 105-00-0008
S/N # 1DW410EBHMF709233

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.
86232935

INVOICE DATE	BRANCH	INVOICE NO.
25SEP25	08	1855223

S
H
I
P
T
O
HEART LAKE FIRST NATIONS
CONSTRUCTION LTD 1666340
BOX 2228
LAC LA BICHE, AB T0A 2C0

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
RTK-06	780-623-2935	1855223	03	07SEP25	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	410E II	1DW410EBHMF709233	RTK-06	5739	DARCY 780-623-1508

DESCRIPTION	AMOUNT
REPAIR LEAK AT MID DIFF OUT PUT PINION SEAL COMPLAINT: CUSTOMER COMPLAINED LEAK FROM DIFF CAUSE: CAUSE -BLOWN SEAL CORRECTION: 0.5INSPECT UNIT TO FIND LEAK COMING FROM MID DIFF OUTPUT PINION SEAL 3REMOVE DRIVESHAFT & YOKE. REMOVE PINION SEAL. INSTALL NEW SEAL. REINSTALL DRIVESHAFT & YOKE. RUN UNIT TO VERIFY PROPER OPERATION & LEAK NO LONGER PRESENT, PROBLEM CORRECTED COMPLICATIONS--- 0.48BOLT BOLT IN YOKE, WELD NUT & EXTRACT BROKEN BOLT PG 1 N R94919 WASHER XY 1 N YZ502231 O-RING XY 1 N 19M8485 CAP SCREXY 1 N YZ122257 SEAL XY 4 N R114105 SCREW ** TOTAL LABOR ** ENVIRONMENTAL FEE >>--> SEG# 03 PRT LAB MSC TOTAL	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM), MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X

SIGNATURE

DATE

QST # 1226957240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY	

LP-1132C

CUSTOMER COPY

THIS TOTAL

Signatures

Richard Wilson, *Parts Manager*

 November 26th 2025, 2:41 PM (MST -07:00)

 55.0085288, -111.7148701

RW



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Thursday, November 6th 2025, 8:49 AM [MST -07:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 November 5, 2025

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 check over unit, confirm heater works, greased unit

Location

 coyote den

Hours

 2

Parts

Signatures

Brandon German, *Mechanic LC*

 November 6th 2025, 8:49 AM [MST -07:00]

 55.0607237, -110.528692

Steven Orcutt, *Project Manager*

 November 10th 2025, 9:25 AM [MST -07:00]

 51.8491944, -113.6333076

B. G

SO



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Friday, September 26th 2025, 9:21 AM (MDT -06:00)

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 September 25, 2025

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 coolant drip under unit into spill tray at laydown, loose hose clamp on esbar coolant line replaced clamp its stripped, pressurized coolant systems checked for more leaks

Location

 HLC laydown yard

Hours

 2

Parts

Signatures

Brandon German, *Mechanic LC*

 September 26th 2025, 9:21 AM [MDT -06:00]

 55.0606928, -110.5286813

B.G

Steven Orcutt, *Project Manager*

 Approved

 September 27th 2025, 2:49 PM [MDT -06:00]

 53.5560192, -113.5378432

SO



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, September 20th 2025, 7:16 AM (MDT -06:00)

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 September 19, 2025

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 replace grease nipples not taking grease, greased unit.

Location

 RML4B

Hours

 1

Parts

Signatures

Brandon German, *Mechanic LC*

 September 20th 2025, 7:16 AM [MDT -06:00]

 55.0607319, -110.5286087

B.G

Steven Orcutt, *Project Manager*

 Approved

 September 23rd 2025, 12:53 PM [MDT -06:00]

 51.067252, -114.1350027

SO



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Sunday, June 29th 2025, 6:35 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 June 28, 2025

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Leaking fuel, fuel cap Leaking, cleaned o-ring reinstalled, clean up spill.

Location

 WTR

Hours

 2

Parts

Signatures

Brandon German, *Mechanic*

 June 29th 2025, 6:35 AM [MDT -06:00]

 55.0605861, -110.5288046

B.G

Steven Orcutt, *Project Manager*

 Approved

 July 4th 2025, 8:07 AM [MDT -06:00]

 53.4268254, -113.7754245





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Wednesday, June 25th 2025, 6:52 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 June 24, 2025

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Wiper arm out of adjustment falling off window, adjusted, wiper blade broken, installed new wiper blade.

Location

 WTR

Hours

 1

Parts

Signatures

Brandon German, *Mechanic*

 June 25th 2025, 6:52 AM [MDT -06:00]

 55.0605793, -110.5288035

B.G

Steven Orcutt, *Project Manager*

 Approved

 June 26th 2025, 12:32 PM [MDT -06:00]

 51.1487021, -114.066704





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Tuesday, May 20th 2025, 7:30 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 May 19, 2025

Tech Name

 Lane Peters

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Drive to unit, inspect and find small leak coming from hyd line under cab
Remove hose clamps to access fitting, snug up and test, no leaks, install hose clamps.

Location

 Foster

Hours

 2

Parts

Signatures

Lane Peters, *Mechanic*

 May 20th 2025, 7:30 AM (MDT -06:00)

Barrett Norman, *Project Manager*

 May 20th 2025, 8:26 AM (MDT -06:00)

 51.0899888, -114.0309302

LP

BN



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Sunday, May 18th 2025, 6:56 AM [MDT -06:00]

Equipment and Maintenance Tracking

Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 May 17, 2025

Tech Name

 Lane Peters

Last service done @ {HR/KM}:

 No Response

Next service due @ {HR/KM}:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Look at unit, small oil leak from overtop of front diff that looks as if it has been a slow leak for a long time. clean all oil very well, can't find leak. Test drive unit, go for a few rounds, but can't see any new leak.

Location

 Foster

Hours

 2

Parts

Signatures

Lane Peters, *Mechanic*

 May 18th 2025, 6:56 AM [MDT -06:00]

LP

Barrett Norman, *Project Manager*

 May 18th 2025, 4:11 PM [MDT -06:00]

 51.067252, -114.1350027

BN

Barrett Norman, *Project Manager*

 May 18th 2025, 4:11 PM [MDT -06:00]

 51.067252, -114.1350027

BN



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Friday, April 4th 2025, 9:43 AM [MDT -06:00]

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 April 3, 2025

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 5628

Odometer:

 0

Hours:

 5129

Repair

Repair Description

 Fire unit up, inspect, didn't see any leaks, there's oil residue on front diff and valve bank from leak previously repaired, ran box up and down, units good.

Location

 Coyote den

Hours

 1

Parts

Signatures

Brandon German, *Mechanic*



April 4th 2025, 9:43 AM (MDT -06:00)



55.0606421, -110.5287482

B.G



Third Party Equipment Repair & Maintenance Tracker

Information

 RTK-06

 Head Office

 Wednesday, March 12th 2025, 2:25 PM (MDT -06:00)

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

Basic Information

Date of Repair

 March 5, 2025

Company or Name of Third Party Doing Maintenance or Repair

 LOCATION CATS

Provide a quick description of what was done to the unit

 INSPECTION AND OIL CHANGE

Attach a PDF Copy of the Work Order or Invoice

 20250312143602587.pdf [View](#)



Articulated Truck Inspection Record

PDI-0100

✓ P = Pass F = Fail R = Repaired N/A = Not Applicable

UNIT #: HL R1K-06 ODOMETER: NSD-5628 ENGINE HOURS: 3128 DATE: 11/28/23

		P	F	R	N/A		P	F	R	N/A
1	LOCKOUT IN PLACE	✓				28	TRANSMISSION OIL LEVEL / INTERNALS FLUID LEVELS	✓		
2	WHEEL CHOCKS IN PLACE	✓				29	ENGINE COOLANT FLUID LEVEL	✓		
3	OIL SAMPLES					30	ENGINE OIL FLUID LEVEL	✓		
4	OVERALL MACHINE LOOSE OR MISSING NUTS & BOLTS, LOOSE GUARDS, CLEANLINESS	✓				31	RADIATOR DEBRIS, DAMAGE, LEAKS	✓		
5	LIGHTS BROKEN LAMPS, LENSES, OPERATION	✓				32	OVERALL ENGINE COMPARTMENT TRASH OR DIRT BUILDUP, LEAKS	✓		
6	STEERING HYDRAULIC SYSTEM LEAKS, WORN HOSES, DAMAGED LINES	✓				33	ALL HOSES CRACKS, WEAR SPOTS, LEAKS	✓		
7	UNDERNEATH MACHINE LEAKS, DAMAGE, PEOPLE WORKING	✓				34	ALL BELTS TIGHTNESS, WEAR, CRACKS	✓		
8	TIRES, RIMS, HUB, STEM CAPS INFLATION, LEAKS, DAMAGE, WEAR	✓				35	CAB INTERIOR CLEANLINESS	✓		
9	BRAKES, SUSPENSION LEAKS, DAMAGE, WEAR	✓				36	ROLL OVER PROTECTION SYSTEM DAMAGE	✓		
10	GRAB IRONS, STEPS, HANDHOLDS CONDITION AND CLEANLINESS	✓				37	GAUGES, LIGHTS, SWITCHES DAMAGE, OPERATION	✓		
11	BATTERY COMPARTMENT CONNECTIONS, FLUID LEVEL	✓				38	SEAT BELT, BUCKLE & MOUNTING DAMAGE, WEAR, ADJUSTMENT	✓		
12	AIR FILTER CONDITION	✓				39	SEAT ADJUSTMENT AND COVER	✓		
13	WINDSHIELD WIPERS & WASHERS WEAR, DAMAGE, FLUID LEVEL	✓				40	HORN, BACKUP ALARM, LIGHTS PROPER FUNCTION	✓		
14	FIRE EXTINGUISHER CHARGE, DAMAGE	✓				41	WINDOWS AND MIRRORS CONDITION, CLEAN, ADJUST	✓		
15	FUEL TANK, HYDRAULIC TANK LEVEL, LEAKS	✓				42	DROP BOX FLUIDS / INTERNALS	✓		
16	BODY DAMAGE, WEAR, DISTORTION	✓				43	PREHEAT / BLOCK HEATER / ENGINE HEATER OPERATION	✓		
17	WELDS, CASTINGS; MOUNTING BOLTS AND PADS CRACKS; DAMAGED BOLTS OR PADS	✓				44	SPILL KIT PROVIDED	✓		
18	ALL AXLES LEAKS, DAMAGE, WEAR	✓				45	DAILY INSPECTION BOOKLET			✓
19	FRAME & HOIST CYLINDERS CRACKS, LEAKS, DAMAGE, WEAR	✓				46	FIRE EXTINGUISHER, CONDITION, DATE, TAG, LOCK, MOUNT	✓		
20	SUSPENSION CYLINDERS LEAKS, MEASURE CYLINDER HEIGHT	✓				47	INSPECTION TAG DATE			PASS
21	MASTER SWITCH	✓				48	FIRE EXTINGUISHER NUMBER			
22	MASTER VHF INSTALLED AND TESTED	✓				49	AIR CONDITIONING OPERATION			✓
23	HEATING OPERATION	✓				50	GPS			✓
24	SERVICE DECAL	✓				51	FILL FUEL ADD CONDITIONER			✓
25	NEXT SERVICE DUE @				5628	52	FUEL CAP LANYARD			✓
26	BOX EMPTY	✓				53	VALVE SET			✓
27	FLOOR MAT CONDITION	✓				54	POSITIVE AIR OPERATION			✓

chemco	Articulated Truck Inspection Record	PDI-0100
---------------	-------------------------------------	----------

✓ P = Pass F = Fail R = Repaired N/A = Not Applicable

TIRE PRESSURE (If not recorded on prescribed Alberta Inspection Record)			
LF:	RF:	LM:	RM:
		LR:	RR:

CHARGING SYSTEM TEST			
VOLTS:	AMPS:	RPM:	

FUEL LEVEL/CLEANING		TEST / DRIVE													
		TEST	[] or TEST DRIVE []												
CLEANING <table border="1"> <tr> <th></th> <th>Date</th> <th>Time</th> <th>Signature</th> </tr> <tr> <td>Washed (Fine Cleaned)</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Disinfectant Mist (Clubroot)</td> <td></td> <td></td> <td></td> </tr> </table>			Date	Time	Signature	Washed (Fine Cleaned)				Disinfectant Mist (Clubroot)				Comments:	
	Date	Time	Signature												
Washed (Fine Cleaned)															
Disinfectant Mist (Clubroot)															
		Technician (Print Name)	Technician Signature												

MAINTENANCE REQUIRED/REMARKS CHANGE OIL, FUEL, FUEL SEPARATOR, FILTERS CHANGE OIL FILTERS - RE 572785 - RE 230986 - DZ 112918 - RE 39465	CAB AND AIR
---	-------------

INSPECTION REPORT SIGN-OFF	
Dave Wilson Technician (Print Name)	 Technician Signature
	Supervisor's Signature

Signatures

Richard Wilson, *Parts Manager*

 March 12th 2025, 2:25 PM (MDT -06:00)

 55.008421, -111.7149753

RW



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Friday, March 7th 2025, 7:12 PM [MST -07:00]

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 March 6, 2025

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Oil leak on ground from front axle location. Leaks coming from STUMP valve area, jack cab up found loose hose, replaced hose o-ring. Cleaned up oil dropped cab.

Location

 HLC laydown yard

Hours

 2

Parts

Information

RTK-06

Foster Creek

Wednesday, February 19

Equipment and Maintenance

This is a new equipment track

Equipment Unit Number

General Information

Date

Tech Name

Last service done @ [HR/KM]:

Next service due @ [HR/KM]:

Odometer:

Hours:

Repair

Repair Description

Location

Hours

Parts

Signatures

Brandon German, *Mechanic*

March 7th 2025, 7:12 PM [MST -07:00]

55.0606628, -110.5287668

Steven Orcutt, *Project Manager*

March 8th 2025, 7:30 PM [MST -07:00]

54.475634, -110.2053483

B. G

Sto



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Wednesday, February 19th 2025, 7:46 PM [MST -07:00]

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 February 18, 2025

Tech Name

 Wyatt Feland

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 drove out to unit and removed panels. Disconnected batteries and removed and changed batteries. Tested unit.

Location

 Foster

Hours

 2

Parts

Signatures

Wyatt Feland, *Mechanic*



February 19th 2025, 7:46 PM (MST -07:00)



55.060589, -110.5289358

A handwritten signature in black ink, appearing to be 'Wyatt Feland'.



Third Party Equipment Repair & Maintenance Tracker

Information

RTK-06

Head Office

Monday, February 3rd 2025, 12:56 PM [MST -07:00]

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

RTK-06

Basic Information

January 31, 2025

LOCATION CATS

Company or Name of Third Party Doing Maintenance or Repair

Provide a quick description of what was done to the unit

500 HRS SERVICE AND INSPECTION NSD 5166 HRS

Attach a PDF Copy of the Work Order or Invoice

20250203130458983.pdf [View](#)

4666

NSD 1/1/66

Date: Jan 31st		Unit: R1K-06		Inspector: Brandon German		Hours: 4666	
Is a PM required within the next 100 hrs? (Yes/No)		If yes, perform or arrange PM.		VS D5166			
Inspection List:	Pass/Fail	Repaired (Initial)	Inspection List:	Pass/Fail	Repaired (Initial)		
Blade cutting edge, moldboard, bucket, GET	✓		Fuel tank	✓			
Bucket or blade cylinders	✓		Hydraulic oil tank	✓			
Hydraulic quick couplers (if equipped)	✓		Auto lube	✓			
Blade arm, trunnion, stick, boom	✓		Fire extinguisher expire date	✓			
Underneath of machine	✓		Windshield wipers & washer	✓			
Overall undercarriage	✓		Pivot shaft	✓			
Idlers & rollers	✓		Batteries & hold downs	✓			
Drive Sprockets	✓		Master shutoff	✓			
Track Assembly	✓		Mirrors & windows	✓			
Corking % remaining	✓		Weather fronts	✓			
Ripper (if equipped)	✓		ROPS & cab guarding	✓			
Ripper Shank	✓		Seat	✓			
Winch (if equipped)	✓		Seat belts & mounting	✓			
Steps & Handholds	✓		Gauges, Indicator lights, cameras	✓			
Overall machine & body	✓		Codes	✓			
Engine Oil	✓		Radio (AM/FM/2way) GPS & antennas	✓			
Transmission Oil	✓		Overall cab interior	✓			
Engine Coolant %	✓		Spill kit & first aid kit	✓			
Air filters (Inner, outer & cab)	✓		Heater / AC °C	✓			
Radiator	✓		Decals & signage	✓			
Fuel water separator	✓		Hydraulic & travel testing	✓			
Positive air shut off	✓		Lockout bars & safety switches	✓			
All hoses & fittings	✓		Webasto & proheat heaters	✓			
All belts	✓		Window break	✓			
Exhaust	✓		SNOW CAT ONLY				
Alternator Output volts	✓		Lap & Shoulder seatbelt	✓			
Overall engine compartment	✓		Skid shoes	✓			
Comments:							
performed 500 hr service							
fuel wouldn't flow thru fuel filter							
Inspector Signature: Brandon German AS Print: Brandon German							

Y = Pass F = Fail R = Repaired N/A = Not Applicable

FLUIDS	CHECKED	CHANGED	QUANTITY ADJUSTED	STATUS
Engine Oil				
Transmission Oil				
Hydraulic Oil				
Final Drive L. Front				
Final Drive L. Center				
Final Drive L. Rear				
Final Drive R. Front				
Final Drive R. Center				
Final Drive R. Rear				
Differential Front				
Differential Center				
Differential Rear				
Drop Box / Transfer Case				
Brake Fluid - 5 Containers				
Coolant				

FILTERS	CHECKED	CHANGED	PART #
Engine Oil			
Fuel			
Transmission			
Hydraulic			
Inner Air			
Outer Air			
Cab Filter (Inner/Outer)			

Performed 500 hr service replaced engine oil/filters, replaced fuel filters and cabin air filters, engine air was dirty replaced

Signatures

Richard Wilson, Parts Manager

February 3rd 2025, 12:56 PM (MST -07:00)

55.0085397, -111.7148029

RW



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Saturday, February 1st 2025, 7:29 PM (MST -07:00)

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 31, 2025

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Performed 500hr service, fuel system wouldn't bleed couldn't get fuel threw final fuel filter. Installed old filter and fuel flowed threw and bleed right away

Location

 W42

Hours

 3

Parts

Signatures

Brandon German, Mechanic

February 1st 2025, 7:29 PM [MST -07:00]

55.0606004, -110.5287852

B.G



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Wednesday, January 29th 2025, 6:58 PM [MST -07:00]

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 28, 2025

Tech Name

 Wyatt Feland

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Drove out to unit and installed grease fittings and remote grease lines.

Location

 Foster

Hours

 1

Parts

Signatures

Wyatt Feland, *Mechanic*

 January 29th 2025, 6:58 PM (MST -07:00)

 55.0606737, -110.5289886





Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Sunday, January 26th 2025, 8:04 PM (MST -07:00)

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 25, 2025

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Replace grease lines Install exhaust

Location

 WTR

Hours

 1

Parts

Signatures

Brandon German, *Mechanic*



January 26th 2025, 8:04 PM (MST -07:00)



55.0606011, -110.5287842

B.G



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Sunday, January 26th 2025, 7:57 PM [MST -07:00]

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 24, 2025

Tech Name

 Brandon German

Last service done @ [HR/KM]:

 No Response

Next service due @ [HR/KM]:

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Install new head light

Location

 WTR

Hours

 1

Parts

Signatures

Brandon German, *Mechanic*



January 26th 2025, 7:57 PM (MST -07:00)



55.0606011, -110.5287842

B.G



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Friday, January 24th 2025, 7:16 PM (MST -07:00)

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 23, 2025

Tech Name

 Brandon German

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 Check out exhaust pipe. It melted exhaust lines. Found pipe over stretched and broken internally

Location

 W42

Hours

 1

Parts

Signatures

Brandon German, *Mechanic*

 January 24th 2025, 7:16 PM [MST -07:00]

 55.0605983, -110.5287824

B.G



Mechanic Work Order

Information

 RTK-06

 Foster Creek

 Wednesday, January 15th 2025, 5:55 PM (MST -07:00)

Equipment and Maintenance Tracking

This is a new equipment tracking feature. Please follow the drop downs to add your equipment. This will allow all documents filled out for a unit to be linked to the unit number. Thank you.

Equipment Unit Number

 RTK-06

General Information

Date

 January 14, 2025

Tech Name

 Wyatt Feland

Last service done @ (HR/KM):

 No Response

Next service due @ (HR/KM):

 No Response

Odometer:

 0

Hours:

 0

Repair

Repair Description

 drove out to unit. Opened panels and inspected to find where leak was coming from. Water pump on wabasto wasn't installed properly. Removed wabasto and changed oring. And installed a bolt to secure it properly.

Location

 Foster

Hours

 3

Parts

Signatures

Wyatt Feland, *Mechanic*

 January 15th 2025, 5:55 PM [MST -07:00]

 55.0541174, -110.490544



Date	Unit # Ger	Repair Description Repair
2024-01-08	850-02	Tighten hoses on front
2024-01-08	Ct-1578	Drove to site and and flipped over middle ripper shank
2024-01-08	HT-8017	Night switch melted bypassed and hooked directly to battery need eyelets to build new battery cables
2024-01-08	WT-8291	Tightened packing nut. Repaired broken air line.
2024-01-08	MG-6317	Changed sandvix tips
2024-01-08	HLRTK-09	Fire up at amine
2024-01-08	Sc-0195	Drove out to site for u it no start had to put booster on it and let it charge and finally got it going
2024-01-08	W720	Melting fuzes in fuzes box ACC option circuit overloaded removed 2-way from circuit hard wired to battery remove pump box heater from constant power circuit to key on circuit removed work lights from ACC option circuit to fog light fuze. Temperature of fuzes now under control
2024-01-08	HLGR-30	Drove out to unit. Removed light a found it was wrong one so ordered proper light. Changed front marker light.
2024-01-08	MG-6317	Swap at Sandvik teeth 15'''
2024-01-08	HLRTK-05	Checked all fluids. Started all equipment at amine.
2024-01-08	ADT-0794	Find exhaust leak clamp at turbo leaking can also see exhaust leak at manifold
2024-01-08	HLWT-10	Pulled bleed screw out to make sure thereâ€™s no air bubbles and ran outside. Diagnose why temp is reading lower then normal on the guage.
2024-01-08	HLGR-30	Swap out front amber try swapping rear amber
2024-01-08	HLD850-02	Tightened loosed fittings
2024-01-08	Hld750-09	Looked at unit for transmission code
2024-01-08	HLRTK-06	Start at amine
2024-01-08	CT-0520	Changed out rear lights
2024-01-08	Mst-1575	Had to fix crane
2024-01-08	WT-9715	Get running
2024-01-08	CT-0794	Find exhaust leak under hood and reset clamp at the turbo.
2024-01-08	CT-0520	Install new rear lights
2024-01-08	WT-2538	Charged batteries. Boosted unit.

Date	Unit # General	Repair Description Repair
2024-01-19	HLGR-30	Unit had code for trans solenoid 3 Did reset on unit and clear codes and code never came back on sounds like a computer glitch but will monitor talked to Curtis about issue and common for wiring harness
2024-01-19	LCCT-2301	Fuel lift pump/ primer pump was leaking removed pump Installed new pump and bled air out of fuel system Boosted unit and got running Unit is good to run
2024-01-19	CT-0915	Removed old ripper teeth Installed new ripper teeth 2x- R350P teeth 2x pins 2x retainers
2024-01-19	HLD450-04	Unit had code come up Code was for hi pressure wrong Talked to Curtis could be a rail pressure sensor or rail relief
2024-01-19	HLWT-11	Heated box fan motor wasn't working Found some bad connections on switch and fan didn't sound healthy Is working now though
2024-01-19	CT-3171	Unit had coolant leak tightened hose clamp and topped up coolant Fuel system had air in it so bled system and started unit
2024-01-19	HLRTK-06	Front LH tire was a little low Filled tired up and unit is good to go
2024-01-19	HLGR-31	Pre work Inspection fire up missing first aid kit fire extinguisher expired.
2024-01-19	CT-1517	Pre work inspection light out put blade on guard on blade not install properly
2024-01-19	HE-0327	Install thumb cyl
2024-01-19	850-01	Attempt to install ripper cyl didn't have fittings
2024-01-19	WT-2101	Investigate leak @ cab leveling valve
2024-01-19	LCCT-1321	Jump start make sure isn't leaking line #6 was dripping tighten.
2024-01-19	CT-6133	Install newer batteries used thawed out and charged batteries from HE-0095 needs wabasco screen
2024-01-19	HLTH-17	Fire up equipment at pit 26
2024-01-19	HLD850-02	Fire up equipment at Amine
2024-01-19	Lcct-2991	Drove to site for hydraulic cover leaking noticed filter cover and fill cap were both leaking ordered new seals
2024-01-19	He-0095	Drove to site to check unit for leaks while heater was on it and took coolant t sample
2024-01-19	Hlgr-31	Drove to site for lose fitting

Date	Unit # Gen	Odom	Hours	Repair Description Repair
2024-01-31	Adt-0741	0	0	Drove to location for coolant leak found was a coolant t heater hose went back to the shop for hose and coolant a d repaired unit then had to go back for coolant cuz didn't have enough then the same thing happened 3 loads in spent most of the day fixing coolants leaks on same unit
2024-01-31	Adt-3576	0	0	Drove to site from transmission low on fluid
2024-01-31	Adt-0305	0	0	Drove to site for coolant leak had to remove panels and that coolant leak was under cab
2024-01-31	CT-3208	0	0	Swap on new ripper tooth
2024-01-31	CT-0305	0	0	Repair coolant leak rubbed threw hoze going to heater core from engine block
2024-01-31	ADT-3576	0	0	Add transmission oil no leak on ground if oil level drops again inspect diffs for acess oil from leaking brake
2024-01-31	ADT-0325	0	0	Repair out lights found starter dead in machine tested needs new starter.
2024-01-31	ADT-0923	0	0	Remove winter fronts from rock trucks at amine
2024-01-31	Ct-3204	0	0	Cut off old and install new ripper tooth
2024-01-31	HE-0205	0	0	Looked at for code that came up on dash was for travel alarm unable to plug in/ access machines service section requires a password.
2024-01-31	ADT-0305	0	0	Drive to unit find leaking coolant hose. Pinch lines cut off leaking half and splice new line together. Top up and run no leaks
2024-01-31	ADT-0325	0	0	Get clearance lights working. Starter no good on unit test and canâ€™t get it to spin
2024-01-31	ADT-0741	0	0	Remove winter front off of units at bp17. Put behind seats
2024-01-31	ADT-3576	0	0	Low transmission oil top up oil run unit around to work out air bubbles get filled and run around level good.
2024-01-31	HLRTK-06	0	0	Pull weather fronts at pit 17
2024-01-31	He-0205	0	0	Drive to unit operate to try and bring up code code will not appear.
2024-01-31	ADT-0794	0	0	Remove winter fronts from trucks at a mine put behind seats
2024-01-31	HE-0095	0	0	Pull front window
2024-01-31	He-0095	0	0	Remove front window frame from unit
2024-01-31	Fit- 0589	0	0	Charge batteries and get unit running to be hauled out
2024-01-31	All arc #07	0	0	Fill front right tire was off Bead.
2024-01-31	HLRTR-01	0	0	Drive to units check fluids and fire up

Date	Unit #	Gei	Odometer	Hours	Repair Description	Repair
2024-02-01	HLLd-02	0	0		Assisted in removing cylinders and hoses on grapple attachment	
2024-02-01	Hlrtk-05	0	0		Drove to site for leaking hoses and diagnosed issue and ordered the parts	
2024-02-01	Hlrtk-06	0	0		Drove to site for exhaust leak diagnosed issue and waited for answer is they wanted to run it or not	
2024-02-01	Ct-0915	0	0		Drove to site and changed out ripper teeth used 2 350 series teeth and 2 pins and 2 keepers	

Date	Unit # Gener	Repair Description Repair
2024-02-03	HLLD-02	Re-install rebuilt cylinders on mat forks
2024-02-03	CT-3204	Swap on new ripper tooth
2024-02-03	ADT-0325	Diagnose out headlights install temporary switch.
2024-02-03	CT-1517	Install rebuilt blade angle cylinders
2024-02-03	CT-0915	Install new pad with 4 new bolts
2024-02-03	HLD750-10	Inspect lights
2024-02-03	U587	Replaced LH taillight bulb Now taillight works
2024-02-03	WT-5034	Air truck up since it won't run Help Andy winch truck onto trailer and tie truck down
2024-02-03	LCCT-0367	Topped up trans fluid Unit was down 15 litres
2024-02-03	HE-2112	Unit has codes for fuel filters and was in power reduced mode Drained fuel/water separator and tried unit and ran for 15 min and coded again Changed fuel filters and unit has not coded yet
2024-02-03	HLRTK-06	Unit had codes on unit for high doc inlet temp Also found multiple exhaust leaks
2024-02-03	531	Drained tidy tank and sucked out Refilled tidy tank Drained truck fuel and filled Still has codes for fuel in water code needs sensor
2024-02-03	Ct-0817	Free up siezed positive air shutoff and get moving freely. Makeup a handle for end of cable and install in unit test and it works as it should.
2024-02-03	ADT-0325	Figure out wiring from broken switch Get lights working temporarily until switch is ordered
2024-02-03	CT-3204	Tighten tracks on unit
2024-02-03	Ct-1517	Drive to unit install rebuilt cylinders Have to modify line gaurds to fit new fittings. Install lines and gaurds top up oil run unit top up oil no leaks.
2024-02-03	CT-0915	Have to find bolts drive to unit. Remove old pad bolts with torch remove pad and install new. Torque bolts to spec
2024-02-03	HLLD-02	Install all cylinders onto mat grapple Hook up lines and test works good no leaks top up with oil Clean off oil from grapple and cylinders

Date	Unit # Gener	Repair Description Repair
2024-02-04	LCCT-1626	Top up trans on unit 10L of 10w oil Unit had codes Master switch was shut off before DEF was purged Other code was for EGR valve but was not active
2024-02-04	HLTH-18	
2024-02-04	CT-1517	Shanks on ripper were on bottom holes put shanks in top holes Unit had low fuel pressure code Removed supply line from tank to filter and no fuel came out
2024-02-04	HLD750-11	blew line and had good fuel coming out then Something in tank
2024-02-04	HE-2112	Unit has code for fuel filter Blew out fuel lines and will monitor unit
2024-02-04	HLRTK-06	Helped Curtis put EGR pipe on unit and with exhaust leaks
2024-02-04	HE-0095	Operator though pin was walking out it's a counter sunk pin all is good
2024-02-04	Ct 0831	Change ripper teeth on unit
2024-02-04	CT-2437	Change ripper teeth on unit Drive to unit remove leaking hose for aux controls LHS of boom. Install new line top up oil and test no leaks
2024-02-04	HLTH-19	Bring truck into shop drain all coolant. Remove and replace 2 bad coolant lines on unit. change out stripped and leaking hose clamps on other lines Refill with coolant run unit and bleed wire from system top off with coolant. Repair fuel leak from walrus. Changed out
2024-02-04	ADT-0923	wrong 2 way antenna
2024-02-04	CT-2437	Swap on new ripper teeth
2024-02-04	CT-0831	Replace ripper teeth Remove broken hood hinge and install new one When hood was broken headlight harness got caught and wires were tore LHS headlights not working. Cut out multiple broken sections and splice in new wire with butt connectors do not have Kenworth spades on hand. Tape up and secure works good
2024-02-04	HLWT-09	
2024-02-04	HLTH-19	Replace leaking hoze blow dirt out of cab tighten tracks.
2024-02-04	U525	Replace starter Replaced 2 hozes going to heater core tighten heater hoze connections repair diesel leak from walrus fill/bleed coolant system.
2024-02-04	ADT-0923	
2024-02-04	HLWT-09	Replace hood hinges
2024-02-04	HLWT-10	Fire up all heart lake water trucks turn box heaters on all pumps are froze

Date	Unit #	General	Odometer	Hours	Repair Description	Repair	Location
2024-02-05	HLWT-09	0	0	Box light/ driver side front work light wasn't working Found bad connection			Foster Creek
2024-02-05	ADT-5091	0	0	Both LH rear tires were low topped up and will monitor			Foster Creek
2024-02-05	HLRTK-06	0	0	Unit had codes for Emissions Code said DPF fault Talked to Curtis and tried to trouble shoot a bit He will come look at it			Foster Creek
2024-02-05	HLRTK-05	0	0	Front differential was making noise Look a video for Curtis to sent to John Deere			Foster Creek
2024-02-05	ADT-0794	0	0	Unit needed a parked regen but operator pressed button to many times Performed manual regen on unit and it went through Unit had event code for trans calibration Performed calibration and was successful			Foster Creek
2024-02-05	HLGR-30	0	0	Removed and installed new Sanvik teeth 35x- Sanvik teeth			Foster Creek
2024-02-05	LCCT-1626	0	0	Unit has fuel leak Found supply line for webasto fell off and was venting through line Reattached line and unit is good to go			Foster Creek
2024-02-05	HLD750-11	0	0	Unit still has 3/4 tank of a tank of fuel Blew out supply line to filter housing will run unit more till it's down more then suck it out Took sample of fuel and will see if there is lots of water in it			Foster Creek
2024-02-05	CT-1517	0	0	Replace blown ripper hoze			North
2024-02-05	HLWT-09	0	0	look at out pump box lights			Peanut lake
2024-02-05	CT-2435	0	0	Tighten tracks			North

Date	Unit Number General Information	Repair Description Repair
2024-03-13	Dozers -> CT-0817	Replace main pump feed hose
2024-03-13	Excavators -> HE-0205	Blow out rad and air filters diagnose fast over heat
2024-03-13	Loader & Skid Steer -> HLSS-02	Replace final drive oils Reseal final drive cover
2024-03-13	Excavators -> LCHE-0327	Replace Sweating oil
2024-03-13	Miscellaneous -> 8011-024	Clean up shop put away hydraulic fittings organize bolt bin on shop truck
2024-03-13	Graders -> HLGR-30	Drove out to site and removes grader tire and had a pickup follow me out so we could put the the tire in the back to take to town
2024-03-13	U426	Tidy tank switch was bad found spare switch in truck and installed now tidy tank works
2024-03-13	Rock Truck -> RTK-08	Low Rear LH tire was low Topped up tire and will monitor
2024-03-13	Rock Truck -> RTK-06	Tighten wiper arm and a adjust position
2024-03-13	Excavators -> LCHE-0189	Went out to site for fuel leak found the tank was leaking had it hauled back to yard
2024-03-13	Dozers -> CT-0520	Unit was dead Boosted unit so it could be moved back to lay down
2024-03-13	Graders -> HLGR-30	Front RH tire broke valve stem Removed tire and loaded into pickup to be sent to town
2024-03-13	Company Service Trucks -> HLSV-08	I stalled new washer sprayers and hose on to unit and tested
2024-03-13	Excavators -> LCHE-0189	Unit had fuel leak from tank Sucked and emptied tank out Removed tank from unit to be repaired
2024-03-13	Dozers -> CT-0304	Went out to site for lose bolts found trunnion bolts were lose and one was missing so I tighten them all and ordered a bolt and nut
2024-03-13	Dozers -> CT-1896	Went out to site and diagnosed oil leak had to remove panels and that and found was blown o-ring was able to contain cuz it was small leak and get it out of the cut
2024-03-13	Company Service Trucks -> Mst-157	Cleaned out unit

Date	Unit Number General Information	Repair Description Repair
2024-03-18	Excavators -> HLTH-18	Drive to unit install wedge bolts
2024-03-18	Dozers -> LCCT-1626	Drive to unit install bolt in trunion arm Start doing service have to drive back and get fuel filters as service kit didn't have any. Complete oil change on unit
2024-03-18	HLD750-10	Drive to unit Extract broken grease fittings install new fittings
2024-03-18	Dozers -> CT-7771	Drive to unit complete engine service on unit
2024-03-18	ADT-2563	Drive to unit complete engine oil service
2024-03-18	HLRTK-06	Bring unit back to yard complete engine oil service on unit. Proper oils are being ordered to complete the rest of the service.
2024-03-18	Company Service Trucks -> U524	Chipped mud out from area and Repaired diff breather.
2024-03-18	Dozers -> CT-7771	Loaded all filters for unit. Drove out to unit and ran unit and took samples. Changed oil fuel air and cab filters. Changed engine oil and ran unit.
2024-03-18	Dozers -> LCCT-1626	Searched and loaded filters for unit. Drove out to unit and ran and took oil samples. Changed all filters and engine oil. Found broken grease zerks extracted them and changed. Topped up hydraulic oil.
2024-03-18	Rock Truck -> ADT-2563	Fired up unit and brought into shop. Took oil samples and changed oil fuel and air filters. Changed engine oil.
2024-03-18	Company Service Trucks -> U173-1	Cleaned out all old filters and garbage from unit and filled up engine oil tank.

Date	Unit Number General Information	Repair Description Repair
2024-03-31	Rock Truck -> RTK-06	Replace axles oils finish inspecting unit
2024-03-31	Miscellaneous -> 8011-024	Pull trucks out clean shop floor up dispose of oils gets
2024-03-31	Loader & Skid Steer -> HLSS-02	Look at high idle on unit
2024-03-31	Rock Truck -> RTK-09	Installed 2-way radio/ hard mounted radio Finished
2024-03-31	Loader & Skid Steer -> HLLD-02	Swap over grapple Matt forks look at front washer fluid
2024-03-31	Rock Truck -> RTK-07	Inspect fill axles
2024-03-31	Rock Truck -> RTK-10	Installed decals and service sticker Checked all fluid levels Checked over unit/ checklist Filled auto lube canister/ made new line for air pump to fill Repaired

Date	Unit Number General Information	Repair Description Repair
2024-06-21	Loader & Skid Steer -> HLSS-01	Diagnosed where hydraulic oil leak was coming from. Came from quick couplers on loader arm and the mower attachment. Removed fittings and got told to get new ones in LLB but ran into issues in LLB so went and installed fitting back onto unit.
2024-06-21	Dozers -> HL850-02	Replace broken grease nipples
2024-06-21	Packers -> CE-1007	Operator complained about weak AC tightend AC belt checked pressures was alittle low topped off system found low air flow coming out of vents cabin air filters were plugged blew out and AC improved ordered new filters
2024-06-21	Company Service Trucks -> U562	No AC check engine light in dash cleared codes checked pressures compressor wasn't turning on. Found fuze was pulled. Installed fuze AC started working
2024-06-21	Shop Time -> Shop Time - 8011-025	Repaired generator in shop reinstalled spare tires onto deck trailers
2024-06-21	Rock Truck -> RTK-06	Operator complained about a weird noise discovered blown out turbo base gasket
2024-06-21	Company Service Trucks -> U090-1	Replace burnt out headlight
2024-06-21	Dozers -> HL850-02	Replace Sweating blade down hose on LH side. Had one in stock pre built
2024-06-21	Dozers -> LCCT-1626	Unit dropped to 900RPM on operator wouldn't rev up again look up codes from display found code for bad signal from throttle switch.
2024-06-21	Dozers -> CT-0613	Blew out engine air filter Tightened tracks
2024-06-21	Rock Truck -> ADT-2593	Unit had codes Tried hooking laptop up but laptop is not working Reset machine and
2024-06-21	Argos -> AR-1934	Drilled out old rivets on exhaust heat shield Installed new rivets and installed
2024-06-21	Loader & Skid Steer -> HLLD-02	Installed window frame back in unit Adjusted door latch
2024-06-21	Argos -> AR-2467	Cleaned battery terminals and cables Installed new battery Still waiting for
2024-06-21	Packers -> CE-0089	Trans oil temp was getting hot Blew out rad and wasn't too dirty Noticed operator had unit in 2nd gear in very soft material Operated unit in first great for rest of the day

Date	Unit Number General Information	Repair Description
2024-07-09	Packers -> CE-1007	Replace air governor
2024-07-09	Graders -> HLGR-31	Build blade Re-bushing
2024-07-09	Dozers -> LCCT-1626	Blade quick connector
2024-07-09	Dozers -> HL850-01	Clear codes from
2024-07-09	Rock Truck -> ADT-0794	Look at broken rad cover
2024-07-09	Rock Truck -> ADT-0923	Look at warning light for
2024-07-09	Tandem Axle Floater -> HLWT-09	Weld spray bar bracket
2024-07-09	Company Service Trucks -> U232	Flat tire swap on spare
2024-07-09	Graders -> HLGR-31	Look at oil leak see what
2024-07-09	Rock Truck -> RTK-06	Look at box not dumping
2024-07-09	Tractor W Blade -> FIT-6676	Get unit ready to low bed
2024-07-09	Tandem Axle Truck -> HLWT-11	Unit doesn't have a
2024-07-09	Tractor W Blade -> FIT-0729	Fueled unit up Adjusted
2024-07-09	Shop Time -> Shop Time - 8011-025	Wait on site to repair

Date	Unit Number General Information	Repair Description Repair
2024-08-01	Rock Truck -> RTK-06	Replace hydraulic filter cut it apart to look for debris
2024-08-01	Shop Time -> Shop Time - 8011-025	Man down
2024-08-01	Packers -> HLP-04	Replace fuel pump didn't fix issue diagnose more
2024-08-01	Company Service Trucks -> DF0718	Retorque lug nuts
2024-08-01	Excavators -> HE-0205	Swap on new clean up bucket send put bucket out
2024-08-01	Company Service Trucks -> U440	Pull leaking tidy tank
2024-08-01	Rock Truck -> ADT-0792	Transmission solenoid issue
2024-08-01	New Item	Emissions fault
2024-08-01	Excavators -> HLTH-17	Replace blown coolant hose
2024-08-01	New Item -> New Item.1	CE-0688. Operator had transmission light come on and buzzer for transmission overheating. Drove to unit and put temp gun on transmission temperature was at 270 F. Transmission was overheated. Pulled
2024-08-01	Dozers -> LCCT-0867 (GPS-EQP)	Drove to LLB to get parts for unit.
2024-08-01	Shop Time -> Shop Time - 8011-025	Wait for equipment to break

Date	Unit Number General	Repair Description Repair
2024-11-10	Argos -> PA-3018 R	Complaint was that chains were loose and something raddling. Removed all floor panels and inspected chains and tensioners but couldn't find anything abnormal. Took unit for a test drive and heard the raddling and found it was a spacer in the secondary clutch that
2024-11-10	Argos -> PA-3013 R	Removed floor panels. Removed track and rear LHS tire. Removed axle assemble and cleaned all parts. Installed new bearings/parts into unit and installed new axle shaft. Installed new tensioner pucks and rear chain. Re-installed track onto unit and inflated all
2024-11-10	Rock Truck -> RTK-09	Go to coyote den to pick up unit. Drive unit to laydown and inspected unit. Greased driveshaft and pinion yoke seals. Found grease line broken so ordered one
2024-11-10	Rock Truck -> RTK-07	Drove unit from coyotes den to laydown. Started Inspection on unit and found cracked air
2024-11-10	Rock Truck -> RTK-06	performed 500hr service greased truck esbar broken throwing fuel pump code found bad connection fixed fuel pump throwing codes for short circuited water pump unplugged pump changed to open circuit code plugged in spare water pump esbar fired up and
2024-11-10	Tandem Axle Truck -> V	belly tarp truck drain water tank winterize pump drained and filled with washer fluid
2024-11-10	Rock Truck -> ADT-086	grab unit from coyote den to shop to go threw unit had no heat heater taps were shut off
2024-11-10	Rock Truck -> RTK-09	Inspected unit adjusted door on engine compartment ordered pin for door latch on other side fixed leaking coolant hose filled auto greaser tightened a few bolts and brackets
2024-11-10	Rock Truck -> RTK-07	Inspected unit adjusted door on engine compartment primed coolant heater fuel system tightened up some brackets for hoses rerouted vhf ant greased unit
2024-11-10	Rock Truck -> RTK-06	Inspected unit fixed leaking washer hose lubed engine bay doors as they where tight removed rocks away from def tank and hoses on frame rails removed broken grease lines
2024-11-10	Packers -> HLP-05	Operator said he could smell coolant Went unit and couldn't find any leak Unit was full on coolant so unit was over full
2024-11-10	Argos -> PA-3941 R	Installed 12 volt plug on unit
2024-11-10	Tandem Axle Truck -> V	Did inspection on unit Started draining unit Replaced flex pipe on heated tank Installed winter fronts Mounted 2-way radio Greased unit fully

[illegible]

[illegible]

Mechanic Work Order

Unit # HLRTK-06 S/N:

[illegible]



Mechanic Work Order

Unit #		Lab #	Donator	Date	Location	Technician	Hours
HL-RTK-08				SEP 24/22	Foster	Randy E	2
Box went Lower, Check Sensor							
at rear of unit. Remove							
chunks of clay from around sensor.							
wires look like they have							
been pinched.							

Unit #		Lab #	Donator	Date	Location	Technician	Hours
Box went Lower, Check Sensor							
at rear of unit. Remove							
chunks of clay from around sensor.							
wires look like they have							
been pinched.							



Mechanic Work Order

[illegible]

Mechanic Work Order

90-2127H

S/N:

Odometer

Hours

1665 bis

[illegible]

Mechanic Signature:

[illegible]

Mechanic Work Order

NSD@ 2036 hrs

Unit # RTK-06 S/N: _____Odometer

Hours 1536 hrs

[illegible]

Parts

Mechanic ID:

Mechanic Signature: _____

[illegible]

Mechanic Work Order

437K-06

Outcomes

Flourish

General Description

Only

Location

Tech Name:

Comment

Lab 4

go out to unit for Box

OCT 21/22

Foster.

Randy E

5

issue. Active code. Rollout
 Rejection active. Contact Brandt

Perform Trouble Shooting found Damaged
wiring harness

Brandt came out to check wires
of #1 Drive fear out put shaft locking.

Parts	Quantity	Unit Price	Total Price
1. 1000	1000	1000	1000
2. 1000	1000	1000	1000
3. 1000	1000	1000	1000
4. 1000	1000	1000	1000
5. 1000	1000	1000	1000
6. 1000	1000	1000	1000
7. 1000	1000	1000	1000
8. 1000	1000	1000	1000
9. 1000	1000	1000	1000
10. 1000	1000	1000	1000
11. 1000	1000	1000	1000
12. 1000	1000	1000	1000
13. 1000	1000	1000	1000
14. 1000	1000	1000	1000
15. 1000	1000	1000	1000
16. 1000	1000	1000	1000
17. 1000	1000	1000	1000
18. 1000	1000	1000	1000
19. 1000	1000	1000	1000
20. 1000	1000	1000	1000
21. 1000	1000	1000	1000
22. 1000	1000	1000	1000
23. 1000	1000	1000	1000
24. 1000	1000	1000	1000
25. 1000	1000	1000	1000
26. 1000	1000	1000	1000
27. 1000	1000	1000	1000
28. 1000	1000	1000	1000
29. 1000	1000	1000	1000
30. 1000	1000	1000	1000
31. 1000	1000	1000	1000
32. 1000	1000	1000	1000
33. 1000	1000	1000	1000
34. 1000	1000	1000	1000
35. 1000	1000	1000	1000
36. 1000	1000	1000	1000
37. 1000	1000	1000	1000
38. 1000	1000	1000	1000
39. 1000	1000	1000	1000
40. 1000	1000	1000	1000
41. 1000	1000	1000	1000
42. 1000	1000	1000	1000
43. 1000	1000	1000	1000
44. 1000	1000	1000	1000
45. 1000	1000	1000	1000
46. 1000	1000	1000	1000
47. 1000	1000	1000	1000
48. 1000	1000	1000	1000
49. 1000	1000	1000	1000
50. 1000	1000	1000	1000
51. 1000	1000	1000	1000
52. 1000	1000	1000	1000
53. 1000	1000	1000	1000
54. 1000	1000	1000	1000
55. 1000	1000	1000	1000
56. 1000	1000	1000	1000
57. 1000	1000	1000	1000
58. 1000	1000	1000	1000
59. 1000	1000	1000	1000
60. 1000	1000	1000	1000
61. 1000	1000	1000	1000
62. 1000	1000	1000	1000
63. 1000	1000	1000	1000
64. 1000	1000	1000	1000
65. 1000	1000	1000	1000
66. 1000	1000	1000	1000
67. 1000	1000	1000	1000
68. 1000	1000	1000	1000
69. 1000	1000	1000	1000
70. 1000	1000	1000	1000
71. 1000	1000	1000	1000
72. 1000	1000	1000	1000
73. 1000	1000	1000	1000
74. 1000	1000	1000	1000
75. 1000	1000	1000	1000
76. 1000	1000	1000	1000
77. 1000	1000	1000	1000
78. 1000	1000	1000	1000
79. 1000	1000	1000	1000
80. 1000	1000</		

Qty.	Parts #
------	---------

Mechanlo ID:

Description

Mechanic's Signature: _____

STKORD

Results

1. Kelly Thompson