



75010 [DEERE 7215R TRACTOR]
Equipment History From July 10, 2018 to August 19, 2026

504-26
SEP

VO: 215404 - Running repairs -26				Open
Item: 236747 - Running repairs -26				
6/13/2026	2	BOBEY, ALEX	Scan unit for reported codes. Several counts transmission overload in manual mode stored. Take unit for drive and can't replicate, possibly operator is running IVT system incorrectly with throttle. Go through proper operation with Foreman.	
6/11/2026	1.5	HAUGEN, DANE	Replaced disc tire, picked up own parts from yard	
6/9/2026	1.5	BOBEY, ALEX	Lube team reported leak on front of engine. Cleaned up and ran. Front cover is leaking but it's minor. Will repair when engine can be pulled.	
5/20/2026	0.5	HAUGEN, DANE	Installed missing battery box latch	
5/14/2026	3.5	HAUGEN, DANE	Replaced broken window latch Replaced cracked fuel cooler and installed missing battery cover Ordered parts to finish battery cover job	
5/12/2026	1	HAUGEN, DANE	Removed broken scraper for disc and inspected where rock had been jammed between tires. Need parts	
5/5/2026	1	HAUGEN, DANE	-Topped up coolant and eng oil -operator was new and asking questions so went over how to check fluids on tractor	
4/30/2026	2.5	HAUGEN, DANE	-inspected before machine went to site -cleaned area where looks like there was a leak -Ran hot and drove around. No leaks showing themselves - got previously ordered parts from Billy. Inquired about installing them and was told tractor will be leaving any minute. Will install on site	
VO: 199719 - 500 Hour service (7495 HR)				Closed
Item: 220875 - 500 Hour service				
VO: 199727 - (350) SERVICE - TIL TRACTOR PROGRAM				Open
Item: 220883 - (350) SERVICE - TIL TRACTOR PROGRAM				
9/24/2025	1.5	VIENNEAU, NATHAN	Service complete. Alces	
9/23/2025	1.5	VIENNEAU, NATHAN	Service complete. Alces	
9/23/2025	1.5	HOWARD, CHRISTOPHER	500 hr service completed	
VO: 190967 - (1000) SERVICE - TIL TRACTOR PROGRAM (7495 HR)				Closed
Item: 211156 - (1000) SERVICE - TIL TRACTOR PROGRAM				
250923-75010-				
VO: 187514 - (OIL CHANGE) SERVICE - TIL TRACTOR PROGRAM				Closed
Item: 207494 - (3) SERVICE - TIL TRACTOR PROGRAM				
250403-75010-OIL				
VO: 185694 - Running Repairs 25				Open
Notes: null				
Item: 205696 - Running repairs				
11/6/2025	3	BOBEY, ALEX	Winter repair list and parts look up.	
9/20/2025	0.5	BOBEY, ALEX	Air up front tires.	



75010 [DEERE 7215R TRACTOR]
Equipment History From July 10, 2018 to August 19, 2026

9/5/2025	1.5	DU PLESSIS, RYNO	Check out unit bogging down complaint Setup auto speed parameters so unit Revs to 1800 not 1400	
8/5/2025	2	FIALA, CODY	Drove to site, spoke with Ryno had to go to shop to grab tire and then head back to site to install tire on disc. All done	
5/8/2025	2	DU PLESSIS, RYNO	Wire radio back into my truck that was installed into tractor	
4/25/2025	1	DU PLESSIS, RYNO	Air up low RR tire	
4/8/2025	0.5	SCHAUB, THOMAS	Installed light top left	
4/3/2025	5.5	SCHAUB, THOMAS	Installed accessory drive shaft and pulley installed belt and guard. Installed side pannels . Changed oil in front final drives . Striatened bracket for electric hydrolic pump on rear of machine	
4/2/2025	6.5	SCHAUB, THOMAS	Installed timing cover front seal coolant hose. Filled coolant Replaced rhs steer cylinder Installed new water pump belt Installed front accessory drive shaft and pulley Installed front belt and guards Changes out two lights	
4/1/2025	9.5	SCHAUB, THOMAS	Removed front assessorry cover and assessorry drive shaft . Drained coolant . Had to make a short bolt for puller to remove crank pully . Removed front cover and cleaned front cover	
3/31/2025	1.5	SCHAUB, THOMAS	Road unit to shop start disassembly	
3/26/2025	4.5	SCHAUB, THOMAS	Drove to unit checked over unit . Made list and ordered parts	
VO: 185236 - Demob (6678 HR)				Closed
Notes: FHO -> SGY				
Item: 205238 - Demob				
250321-75010-				
3/21/2025	1	FORREST, BRANDON	Demob complete	
3/20/2025	1	WEKWERT, CONRAD	Demob	
3/20/2025	2.5	HOFFMAN, RYLAN	Check over checklist, machine couldn't be started. Needs some heat.	
VO: 185287 - No start (6678 HR)				Closed
Item: 205289 - No start				
3/21/2025	1	FORREST, BRANDON	Boost unit. Start up	
VO: 184277 - (250) SERVICE - TIL TRACTOR PROGRAM (6891 HR)				Closed
Item: 204240 - (250) SERVICE - TIL TRACTOR PROGRAM				
250525-75010-				
4/10/2025	0.5	MACLEAN, RONALD	Move to main shop	
4/3/2025	1.5	MACLEAN, RONALD	Redecal hood	
3/31/2025	5.5	MACLEAN, RONALD	Put tips stickers in all machines in yard	
VO: 184078 - Oil leak under cab (6650 HR)				Closed
Item: 204041 - Oil leak under cab				
3/9/2025	4	TOMASZEWSKI, DALE	Travel to unit to repair oil leak. Fire unit and check. Found leak under cab. Remove floor and checked. Found sensor oring was blown out. Replace oring and check for leaks. None noted. Assemble cab and pack up	



75010 [DEERE 7215R TRACTOR]
Equipment History From July 10, 2018 to August 19, 2026

VO: 180542 - (500) SERVICE - TIL TRACTOR PROGRAM (6668 HR)				Closed
Item: 200185 - (500) SERVICE - TIL TRACTOR PROGRAM				
250311-75010-				
3/10/2025	3	DEWOLFE, DANIEL	500 hr service	
3/10/2025	3	FAHRENSCHON, JACKSON	Serviced tractor	
3/10/2025	3	DE KLEYNE, RYAN	Completed 500 hour service on unit.	
3/8/2025	1	DE KLEYNE, RYAN	Tried picking filters for service but don't have most in stock	
VO: 178997 - Tire (6382 HR)				Closed
Item: 198580 - Tire				
1/13/2025	2	WHEELDON, BROCK	Tires flat. Attempt to air up but is blown. Notify supervisor	
VO: 177694 - Beacon (6309 HR)				Closed
Item: 197190 - Beacon				
1/2/2025	1	BERKENBOSCH, KEVIN	Drive to location. Install new beacon and test.	
12/29/2024	1	WHEELDON, BROCK	Beacon turns on but won't flash. Send picture to supervisor to order new beacon.	
VO: 176168 - Park brake sump code/ won't move (6564 HR)				Closed
Item: 195460 - Park brake sump code/ won't move				
2/18/2025	2	TOMASZEWSKI, DALE	Cold start	
2/13/2025	4	WOOKEY, COLTON	Went to unit, set up, replaced broken reverse solenoid on transmission, installed new valve bank cover, had to heat and boost unit to get running, ran and tested unit, checked for leaks, no leaks, cleaned up work area	
2/4/2025	6	WOOKEY, COLTON	Went to unit, set up, installed heater on unit, waited to warm up unit, got unit running, warmed up, checked unit, had code for rear synchronizer solenoid, no reverse, troubleshot, found solenoid broken, due to cover hitting solenoids, looked up parts, ordered parts, cleaned up work area, went back to lay down	
1/30/2025	2	WEKWERT, CONRAD	Change solenoid for park brake sump. Test- good	
1/24/2025	3	WHEELDON, BROCK	Get to machine and park brake releases as it should. Check wiring and everything looks good. Drive for 10 minutes with no issues. Search for solenoid part number. Order parts	
1/10/2025	2	WHEELDON, BROCK	Sump code came back in. Remove guard at solenoids. Check wiring and looks good. Assure plug is seated on solenoid. Code no longer active. Drive around for 15 mins with no issue.	
12/16/2024	4	WHEELDON, BROCK	Assemble new pigtail. Install solenoid and new pig tail. Boost unit and test.	
12/13/2024	3	WHEELDON, BROCK	Grab parts and travel to unit at rms 5. Remove solenoid to assure which pins to use. Go back to yard for 18 gauge wire but only had 16. Attempt to build pigtail but unable to with 16 gauge. Put parts back in seacan	
12/11/2024	2	WEKWERT, CONRAD	Go to install new connector and pins. New pins physically too big to fit in the back of the connector. Order pins John Deere ag dealer unsure of correct pins for connector order multiple pins, cover and bolts in cab, when looking at connector from the back red wire goes in left side, black wire goes in right side.	



75010 [DEERE 7215R TRACTOR]

Equipment History From July 10, 2018 to August 19, 2026

12/8/2024	2.5	WEKWERT, CONRAD	Park brake sump solenoid code and won't turn park brake off or go into gear. Locate solenoid on side of transmission remove cover find wires going into connector rubbed through on cover. Order new pins and a connector to repair.	
VO: 175567 - Steering codes (6202 HR)				Closed
Item: 194734 - Steering codes				
12/1/2024	2	DUNFORD, WYATT	Get into monitor, run diagnostics find steering code for low secondary steering pressure, pump wont turn on if oil colder the. -10, run pump in monitor test code went away. Clear all codes Machine also needs glow plugs looked at	
VO: 175466 - No start (6492 HR)				Closed
Item: 194633 - No start				
2/2/2025	3	WRUBLESKI, JONATHAN	Replace starter and heat and boost unit	
1/31/2025	3	WRUBLESKI, JONATHAN	Heat and boost unit Starter motor failed	
1/25/2025	1	BERKENBOSCH, KEVIN	Drive to unit in drilling. Unit move wait for directions boost unit.	
1/5/2025	2	BERKENBOSCH, KEVIN	Drive to drilling and get unit running	
1/2/2025	1	WHEELDON, BROCK	Heat and boost	
12/27/2024	3	WEKWERT, CONRAD	Change batteries	
11/29/2024	3	KEAST, GREG	Put heat on engine, plug block heater into welder, warm everything up, hook boost pack up, start tractor for operations	
VO: 175289 - (250) SERVICE - TIL TRACTOR PROGRAM (6465 HR)				Closed
Item: 194455 - (250) SERVICE - TIL TRACTOR PROGRAM				
250130-75010-				
1/30/2025	1	UGOT, JOHN	Get eng sample. Change cab filter. Inspect the machine	
1/30/2025	1	BANZUELA, ERIC	250hr service drilling	
VO: 167090 - (250) SERVICE - TIL TRACTOR PROGRAM (6202 HR)				Closed
Item: 185282 - (250) SERVICE - TIL TRACTOR PROGRAM				
241122-75010-				
11/22/2024	4	WURBAN, ZACHERY	2000 hr service at 6202hrs Full service prior to use up north Out of bay and plugged in for weekend delivery	
VO: 165215 - 2024 running repairs (6202 HR)				Closed
Item: 183104 - 2024 running repairs				
11/26/2024	1	YACUK, JONATHON	Tarped off hood and put heater underneath. Started machine and checked operating temp oil levels. And pulled in front of shop	
11/22/2024	1.5	DU PLESSIS, RYNO	Heat and get unit started and moved to tamarack yard	
11/22/2024	4	SCHAUB, THOMAS	Pulled in unit for inspection . Found faulty block heater cord changed cord . Found leaking fuel line changed seal . Installed cat tarp to front of unit	
11/5/2024	1	YACUK, JONATHON	Tarped are hood and put heater underneath. Started machine and checked operating oil levels. Pulled in front of shop and plugged in.	
9/17/2024	1	BOBEY, ALEX	Travel to site and pull blow steering line. Measure and send in specs.	



75010 [DEERE 7215R TRACTOR]
Equipment History From July 10, 2018 to August 19, 2026

9/17/2024	3.5	SCHAUB, THOMAS	Change hose on front steer cylinder . Filled trans	
8/22/2024	1.5	DU PLESSIS, RYNO	Install and test wheel angle sensor no active faults	
7/29/2024	1	DU PLESSIS, RYNO	Tighten up loose hitch bolts	
7/18/2024	1	DU PLESSIS, RYNO	Check out steer sensor fault clean corroded pins and monitor	
6/14/2024	1.5	DU PLESSIS, RYNO	Check out hydraulic leak replace blown O-ring on pressure sensor	
6/11/2024	2	SCHWABE, STEPHEN	Load oil and travel to site, check for leaks and repair leaking pipe on right side control valve, top up oil and run unit to verify oil level	
VO: 161780 - (500) TIL TRACTOR PROGRAM (5931 HR)				Closed
Item: 152694 - (500) TIL TRACTOR PROGRAM				
240714-75010-				
VO: 134116 - (250) TIL TRACTOR PROGRAM (5581 HR)				Closed
Item: 109816 - (250) TIL TRACTOR PROGRAM				
230611-75010-				
VO: 129280 - Running repairs 2023 (5800 HR)				Closed
Item: 147912 - Running repairs 2023				
5/27/2024	1.5	DU PLESSIS, RYNO	Check out steering fault clean corroded pins. I'm steering sensor.	
8/17/2023	1	DU PLESSIS, RYNO	Check out weird noises coming from drive train , suspension was bottoming out	
7/21/2023	1.5	DU PLESSIS, RYNO	Replace top hitch bracket	
7/14/2023	1	DU PLESSIS, RYNO	Straighten and repair bent steps	
7/8/2023	2	BOBEY, ALEX	Build hose, travel to site and replace hitch line and o rings.	
5/18/2023	1	DU PLESSIS, RYNO	Repair bent step	
5/16/2023	0.5	BOBEY, ALEX	Replace steering angle sensor	
5/11/2023	1	DU PLESSIS, RYNO	Check out fault , waiting on parts , build new hose holder on disc	
5/10/2023	2	DU PLESSIS, RYNO	Check out intermittent steering angle sensor fault , test wiring -checked out good and fault went inactive	
5/6/2023	2	DU PLESSIS, RYNO	Check out hydraulic leak, remove steering hose with pin hole and get new hose made at green line , install new hose	
VO: 128325 - Winter repair (6175 HR)				Closed
Item: 146961 - Winter repair				
11/21/2024	2	SCHAUB, THOMAS	Drove to unit . Tarped in unit started heating . Had issues with heater . Did not get unit running	
4/29/2023	2	BOBEY, ALEX	Replace batteries. Check over unit. Move unit and disc to wash pad.	
4/27/2023	1	MACLEAN, RONALD	Pick up from main shop to til shop,boost unit weak battery pre trip check for levels	
4/27/2023	1	BOBEY, ALEX	Travel to main yard with Ronny. Boost and warm up unit. Escort back to tamarack yard.	
VO: 91923 - (1000) TIL TRACTOR PROGRAM (5105 HR)				Closed
Item: 98553 - (1000) TIL TRACTOR PROGRAM				
061522-75010-				
VO: 86607 - Running repairs 2022 (5371 HR)				Closed

Item: 103992 - Running repairs 2022				
10/21/2022	1	BOBEY, ALEX	Replace engine harness connectors that were damaged.	
10/13/2022	1	BOBEY, ALEX	Check coolant. Boost unit. Move unit outside and get to operating temperature. No faults returned for exhaust. Park unit.	
10/12/2022	3	BOBEY, ALEX	Install EGR crossover tube and EGR cooler. Install all coolant and fuel pipes for cooler plate. Install turbo feed and drain lines. Fill up coolant and start unit to warm up. Pulled off for service call.	
10/8/2022	1.5	BOBEY, ALEX	Clean mating surfaces and bolts. Clean up studs and spacers. Install and torque down manifold onto cylinder head. Pulled off for service call.	
10/4/2022	6	MACDONALD, BRIAN	Remove exhaust manifold bolts	
10/1/2022	5.5	BOBEY, ALEX	Remove turbo oil lines and mounting bolts. Remove fixtures and manifold from machine, begin removing the broken bolts from the manifold.	
9/30/2022	3	BOBEY, ALEX	Clear space in overhang and start to remove exhaust manifold. Drained coolant.	
9/27/2022	3	BOBEY, ALEX	Travel to site for report of regen issue. Got to site and found fault code 1209.07 active for engine. Popped hood and found tube for manifold pressure sensor snapped off of exhaust manifold. Heated with oxy/acy and attempt to remove. Would not move with easy out. Disconnect disc so unit can be swapped out with spare. Travel to shop and order parts.	
9/10/2022	1.5	BOBEY, ALEX	Travel to site and replace hood latch lock.	
9/1/2022	4	FEREDAY, JACKSON	Bring two pales of TXMto site. Fill oil. Did not have enough oil. Go back to shop get more pales. Add three pales. When started after the third site glass jumped right up. So emptied one pale out of tractor. Opened valve. Closed valve. Drive around. Still too much oil. Emptied another pale out. Opened vale closed valve. Seemed good. Drove around. Checked again and was good to go. Added three full pales. Alex added one before I got there	
9/1/2022	2	BOBEY, ALEX	Inspect hood not closing. Latch is getting stuck, worn out. Unstuck and order parts. Started machine and hose blew. Order hose and install. Organize labourer to come out with oil to fill up.	
7/19/2022	0.5	BOBEY, ALEX	Air up LH tire.	
6/15/2022	0.5	DU PLESSIS, RYNO	Check over to ensure no damage to machine after fuel was stolen	
6/15/2022	4	MACLEAN, RONALD	Service all samples taken	
6/6/2022	4	DU PLESSIS, RYNO	Remove and replace front right axle seal 5104hours	
5/31/2022	1.5	DU PLESSIS, RYNO	Remove and replace fuel sender	
5/26/2022	5	DU PLESSIS, RYNO	Troubleshoot 27.04 fault code, for EGR circuit fault check all wiring and replace connector, fault still returned intermittently, remove and replace EGR valve and gaskets , no more faults	
5/20/2022	1.5	DU PLESSIS, RYNO	Check out seat won't air up pickup parts from Brandt , replace cracked seat switch	
5/17/2022	1.5	BOBEY, ALEX	Travel to site and inspect issue with coolant temp gauge. Clean corrosion on wiring, check connectors, no faults really found. Informed operator of what gauge cluster symbols mean.	
5/13/2022	1	DU PLESSIS, RYNO	Remove and replace right cab suspension cylinder hose	
5/12/2022	1.5	BOBEY, ALEX	Build hose and drive to site and install for RH suspension cylinder.	

5/11/2022	2	DU PLESSIS, RYNO	Repair hitch pin that was stuck , check fault codes none active and clean off steer angle sensor	
5/3/2022	1.5	DU PLESSIS, RYNO	Set transmission and rpm to manual mode to give operator more control when in soft conditions	
VO: 81550 - (250) TIL TRACTOR PROGRAM (4827 HR)				Closed
Item: 91996 - (250) TIL TRACTOR PROGRAM				
031122-75010-				
VO: 80753 - check over and repair unit that was in Ft mac (5000 HR)				Closed
Item: 98310 - repair steering column tilt				
5/24/2022	1.5	DU PLESSIS, RYNO	Repair steering tilt bushing that walked out	
5/16/2022	1	DU PLESSIS, RYNO	Install steer column tilt pin and bushings	
3/29/2022	1	MACLEAN, RONALD	Add hydraulic after repair	
3/28/2022	1	MACLEAN, RONALD	Service final drives and transmission oil	
3/17/2022	2	SCHWABE, STEPHEN	cut and install tilt bearing, install column and covers	
3/16/2022	4	SCHWABE, STEPHEN	disassemble steering column, look into parts and found it to be to expensive to replace all the worn parts, order brass bushings and drill out column pivot then cut and install bushing	
Item: 98134 - trouble shoot dpf code and oil leaking from intake piping				
3/28/2022	5	SCHWABE, STEPHEN	clear codes, try to reset emissions codes, try to do forced regen after dpf/doc were cleaned	
3/28/2022	3	DU PLESSIS, RYNO	Check out DPF codes , get machine to do a recovery regeneration, codes still active after regen but machine is out of service mode , parked regen can now be performed	
3/22/2022	7.5	SCHWABE, STEPHEN	install valve cover, assemble and install dpf/mount, air piping, exhaust, coolant tank, brackets,	
3/17/2022	1.5	SCHWABE, STEPHEN	clean up, install intake piping and guards	
3/15/2022	8	SCHWABE, STEPHEN	remove charge air cooler to send out for leak and oil build up, remove dpf/doc to send out for cleaning, remove air piping to inspect turbos	
Item: 97676 - replace broken axle housing				
3/22/2022	2	SCHWABE, STEPHEN	clean and install rear wheel weight and tire and rim, torque wheel and wedges	
3/18/2022	1.5	SCHWABE, STEPHEN	repair leak from cab suspension vavle block, install cab suspension mount	
3/17/2022	6	SCHWABE, STEPHEN	install shims and planetary carrier, torque retainer bolt to 670 and install lock plate, clean parts and buff flanges, apply sealant and install ring gear and axle then install axle housing, make seal installer for axle seal, torque bolts to 185, clean and install weights and wheel	
3/15/2022	4	SCHWABE, STEPHEN	make rolling torque tool, set up and measure for shims, clean up	
3/14/2022	12	SCHWABE, STEPHEN	remove cab suspension on right side, remove axle housing, press out shaft, find bearing number to source a bearing locally that brandt cannot supply, clean parts, cut off old bearings and press on new seal race and outer axle bearing, install races in new housing, make parts list for extra parts needed	
3/14/2022	1	DU PLESSIS, RYNO	Help disassemble	
3/11/2022	7	SCHWABE, STEPHEN	move parts and benches to make room for unit in the shop, plug in, top up transmission oil, move unit into shop, jack up and pull tire and wheel weights, clean axle housing	
Item: 97675 - check over and repair unit that was in Ft mac				



4/2/2022	1.5	DU PLESSIS, RYNO	Install hood brace and get hood to open and close without getting caught	
3/29/2022	5	SCHWABE, STEPHEN	warm up to do parked regen, test drive unit, bleed cab suspension,	
3/29/2022	1.5	DU PLESSIS, RYNO	Bleed cab suspension	
3/28/2022	5	SCHWABE, STEPHEN	install side guards, top up oils and change front final drive oils, replace front suspension cylinder bearings and install cylinders with new pins, reset run suspension	
3/26/2022	1	SCHWABE, STEPHEN	assemble suspension cylinder	
3/25/2022	3	SCHWABE, STEPHEN	reseal and assemble left suspension cylinder, reseal right cylinder and wrap up to wait for missing seal from seal kit, clean up	
3/24/2022	12	SCHWABE, STEPHEN	install intercooler, weld on nut and remove lower right suspension cylinder pin, clean cylinders, disassemble left cylinder/ make wrench for piston and remove piston, install hood, remove repair and install left rear cab suspension cylinder mount	
3/23/2022	11	SCHWABE, STEPHEN	remove left front final drive clean and inspect gears reinstall cover, remove knuckle replace axle seal, made seal installer, install tire, reseal left steering cylinder, remove left front suspension cylinder had to heat and weld a nut to pull the lower pin	
3/22/2022	1.5	SCHWABE, STEPHEN	install new latch in left front cab guard/ new side guard, jack up and remove left front tire prep to replace inner axle seal	
3/21/2022	7	SCHWABE, STEPHEN	repair cracks in left rear engine guard, install and hookup right rear cab cylinder, install cab cross brace, remove reseal and install right steering cylinder, remove left steering cylinder	
3/16/2022	6	SCHWABE, STEPHEN	remove exhaust mount and valve cover, check and adjust valve lash, make up parts list	
3/11/2022	1	SCHWABE, STEPHEN	check over for repairs needed	
3/11/2022	4	MACLEAN, RONALD	D service	

VO: 79373 - Cold start (4832 HR) Closed

Item: 96275 - Cold start				
2/26/2022	1.5	MASON, JONATHAN	Drove to unit put heat on	

VO: 79378 - Heat unit for start up (4832 HR) Closed

Item: 96280 - Heat unit for start up				
2/26/2022	1	MOCKE, SEAN	Heat unit for start up	

VO: 78149 - Reinstall RH Rear Wheel Weights (4832 HR) Closed

Item: 94926 - Reinstall RH Rear Wheel Weights				
2/16/2022	6	FOISY, STEVEN	Drive out to unit, found weight completely off Rh rear. Removed bolt from left wheel weight to go get hardware to reinstall. Waited for escorts from gate 8 to 9 and back both times. Used comealong to pull weight back up into position and turned with aligning bars. Had to use a few extra washers as the bolts I found at the warehouse were slightly too long. Unit shuts down for exhaust filter restriction if left in park but if you put it in gear it will stay running. Disconnected tires from rear hitch and left heat setup on unit and shut back down.	

VO: 75498 - (500) TIL TRACTOR PROGRAM (4702 HR) Closed

Item: 73454 - (500) TIL TRACTOR PROGRAM				
2022-01-				

VO: 73514 - 2022 January Repairs (4832 HR)				Closed
Notes: null				
Item: 91648 - 2 way				
1/22/2022	1	MOCKE, SEAN	New antenna end with travel	
Item: 91573 - Engine codes				
1/21/2022	3	WIPF, JACOB	Troubleshoot engine codes	
Item: 90879 - No start				
1/18/2022	2	MACDONALD, MATTHEW	Heat unit tried cranking start instanly started smoking night shift must of been cranking on it for while order starter	
1/16/2022	1	MOCKE, BRUCE	Start	
Item: 90502 - Broken hitch				
1/13/2022	5	SCHINDEL, BRIAN	Fix broken hitch	
1/13/2022	1	MACELHERON, GEORGE	Remove broken hitch for welder and reinstall when welded	
Item: 90185 - Hydraulic leak				
1/11/2022	6	MOCKE, SEAN	Strip panels and remove hard lines to reach leaking line. Travel back to laydown and make new hose and install. Wait for escorts to gate 7	
Item: 90025 - Monitor not working.				
1/12/2022	2	MOCKE, SEAN	Repair monitor with replacement of fuse, plug in all panels plugs back in and re mounted 2 way radio on side pillar because it's to heavy for panel	
1/9/2022	3	RANTA, CLAYTON	Commandarm monitor and arm rest controller not working. Blown fuse. R&R fuse and take tractor for a drive to see if issues comes back. Tested fine. Wait for escort to and from unit.	
Item: 89954 - Heat and charge, frozen fuel				
2/15/2022	2	MOCKE, SEAN	Wheel needs to be removed to repair wheel ballast. Heat and charge for start up	
2/15/2022	2.5	MOCKE, BRUCE	Wheel needs to be removed to repair wheel ballast. Heat and charge for start up	
1/10/2022	3	HAMMOND, CHRIS	Drive to area set up area troubleshoot coolant leak and hyd leak repair lines	
1/9/2022	2	MOCKE, SEAN	Fuel system frozen, heat and charge batteries ,add conditioner and change fuel filters	
VO: 72863 - Mob in (4442 HR)				Closed
Item: 89254 - Mob in				
2022-01-				
1/2/2022	2	MOCKE, SEAN	Escorted in to nse to mob in and repair oil leak, with travel	
VO: 60429 - Til running repairs 2021 (4399 HR)				Closed
Item: 76486 - Til running repairs 2021				
12/23/2021	1	BOBEY, ALEX	Bring unit into shop with Jackson and make up winter front.	
12/23/2021	2.5	MACLEAN, RONALD	Run heaters take in shop for block heater and winter fronts	
12/23/2021	1	FEREDAY, JACKSON	start up winter guard	
10/4/2021	1	DU PLESSIS, RYNO	Reinstall roof console that fell down	

9/28/2021	1	BOBEY, ALEX	Operator reported fault code coming onto monitor. Went to unit but couldn't replicate issue. Removed cab interior panels and cab exterior panels, wiggle test on all harnesses. Putting unit back to work until problem comes back.	
9/24/2021	2	DU PLESSIS, RYNO	Troubleshoot wiring faults and machine not moving , disconnect and clean pins and connectors to cab module	
9/22/2021	1	DU PLESSIS, RYNO	Check out warning lights on display	
9/8/2021	0.5	BOBEY, ALEX	Replace headlight bulb.	
8/31/2021	1	DU PLESSIS, RYNO	Replace rear window latch and catch assembly	
8/30/2021	2	DU PLESSIS, RYNO	Find and repair hydraulic leak, top up oils	
VO: 47339 - 2021 TIL Running Repairs (4232 HR)				Closed
Item: 62430 - 2021 TIL Running Repairs				
6/30/2021	1	DU PLESSIS, RYNO	check out AC complaint	
6/29/2021	4	BOBEY, ALEX	Service call for LH rear wheel weight. Drive to Greggs to get proper hardware. Remount weight to rim base. Reinstall fender.	
6/27/2021	3	KUIPERS, AARON	Fuel, fluids, Grease	
6/24/2021	0.5	DU PLESSIS, RYNO	trpair broken side cover and ord parts for cab	
6/11/2021	1	DU PLESSIS, RYNO	Install left outer hub and wheel	
VO: 46147 - (500) FARM TRACTOR STANDARD PROGRAM (3892 HR)				Closed
Item: 60770 - (500) FARM TRACTOR STANDARD PROGRAM				
210518 - 75010 -				
VO: 41491 - winter repairs 2020 (3711 HR)				Closed
Item: 55278 - winter repairs 2020				
3/19/2021	2	DU PLESSIS, RYNO	pull steering column and replace pins and bushings	
2/22/2021	3	DU PLESSIS, RYNO	install aux hyd valves and new seals , reseal coolant lines to turbo, install panels and covers, move unit out	
2/17/2021	8.5	DU PLESSIS, RYNO	pill front right wheel assembly, check u joints, remove and replace axle seal , drain front diff , install right hub and axle assembly and fill front diff, install wheel and torque, set unit on ground , pull rear aux valves and reseal	
2/16/2021	2.5	DU PLESSIS, RYNO	get unit fired up and warmed up, move into shop and get on stands	
1/20/2021	4	DU PLESSIS, RYNO	get unit running repair transmission leak on left side and pull right steer cylinder to reseal	
1/15/2021	2	DU PLESSIS, RYNO	air up front right tire and inspect for leaks, ord parts to reseal front right axle	
VO: 37334 - 2019 Service History (2970 HR)				Closed
Item: 50295 - 2019 Service History				
2019 - 75010 -				
VO: 33072 - running repairs 2020 (3650 HR)				Closed
Item: 45284 - running repairs 2020				
10/13/2020	2	DU PLESSIS, RYNO	install right side solenoid valves cover , get machine fired up	
10/7/2020	1	DU PLESSIS, RYNO	boost unit	



75010 [DEERE 7215R TRACTOR]
Equipment History From July 10, 2018 to August 19, 2026

10/5/2020	1	DU PLESSIS, RYNO	give machine a quick once over to go back to work	
10/2/2020	1.5	DU PLESSIS, RYNO	go over unit and ord parts,	
9/19/2020	1.5	DU PLESSIS, RYNO	replace TPS and foot control pedal run unit no faults	
9/17/2020	1	DU PLESSIS, RYNO	remove throttle position sensor to get part numbers and re install, replace blown lights on hood	
8/31/2020	1	DU PLESSIS, RYNO	check out low power complaint	
8/29/2020	2	DU PLESSIS, RYNO	troubleshoot throttle issues, ord parts	
8/13/2020	2	DU PLESSIS, RYNO	check out oil leak, look up and ord parts	
VO: 31469 - troubleshoot low coolant level alarm and install wiper				Closed
Item: 43317 - troubleshoot low coolant level alarm and install wiper arm				
6/9/2020	1.5	DU PLESSIS, RYNO	troubleshoot low coolant level alarms, top up coolant to monitor, install missing wiper arm	
VO: 31395 - 2020 Service Program (3297 HR)				Closed
Item: 43219 - D Service				
Item: 43218 - B Service				
200609 - 75010 - A				
6/9/2020	2	GRAY, JAMES	B service HRS- 3300 change engine oil and filters check fr diff levels , grease driveline	
VO: 31260 - air up tires (3204 HR)				Closed
Item: 43026 - air up tires				
5/19/2020	1	DU PLESSIS, RYNO	check and air up all tires	
VO: 15667 - troubleshoot machine kicking into neutral (2628 HR)				Closed
Item: 21013 - troubleshoot tractor going into neutral				
7/6/2019	2.5	VAHEY, NOEL	machine going into neutral intermitently cleared all fault codes ran tractor but it did not do it	
VO: 12638 - Running repair and maintenance 2019 (2639 HR)				Closed
Item: 17001 - Running Repair				
11/15/2019	3	DEIB, ZACHARY	Run and inspect 75010 and attached disc 75012. Remove frozen dirt from disc.	
8/21/2019	4	DEIB, ZACHARY	Remove leaking disc cylinder hoses. Go get new ones made and shortened. Install new hoses.	
8/16/2019	3	POLLARD, DAVID	check and tighten lug nuts	
7/17/2019	2.5	POLLARD, DAVID	service unit @ 2970hrs	
7/17/2019	2.5	BENIUK, RYLEY	service	
7/15/2019	1	DEIB, ZACHARY	Check up on machine after work done by Martin Deere line. Scan for any New fault codes, Was told machine was running better.	
7/11/2019	5.5	DEIB, ZACHARY	Remove powertrain/hydraulic filter and cut open to inspect. Meet martin deere line at machine and go through symptoms and fault codes appearing/past history.	
7/10/2019	4	POLLARD, DAVID	top up coolant and trans/hyd; drove all the way back from plamondon as mechanic wouldnt top up	
7/10/2019	4	BENIUK, RYLEY	top up fluids	
7/9/2019	6	DEIB, ZACHARY	Go on ride along so operator can show me how unit is operating. Begin to remove steer cyl for reseal, Order one and go pick up from John deere warehouse. Return and replace cylinder.	



75010 [DEERE 7215R TRACTOR]

Equipment History From July 10, 2018 to August 19, 2026

7/8/2019	8.5	DEIB, ZACHARY	Inspect unit, begin to troubleshoot fault codes and unit intermittently not wanting to move. Go pick up parts from Martin deereline. Return to machine, Replace powertrain/hydraulic filter. Bring to shop and cut open. Finding rubber and steel filings.	
VO: 11782 - get work ready (2628 HR)				Closed
Item: 15901 - service and repairs				
5/6/2019	7.5	HILLS, KYLE	work with martin mechanic bring in once done put on hood all other covers put cab back together grease take outside tighten all gangs on disc install locks park	
5/1/2019	10	HILLS, KYLE	get valve cover installed torque to spec start putting dpf junk back on engine get all together install hoses to steer lines fill engine with oil pressure test coolant system fill with coolant recheck for codes start unit check for leaks	
4/30/2019	6	HILLS, KYLE	get parts put in last steel line get hoses made start working on putting eng back together	
4/29/2019	8	HILLS, KYLE	get steel steer lines removed remove 2 other hoses thast are leaking get new ones made reinstall start putting in new changeup steel lines for some reason they all wanted to end up in the same place put all but 1 in loose and bent them slightly to fit in nice built a backing plate for clamp got lines clamped got hose and fittings made 3 hoses 1 steel line b.o	
4/26/2019	10	HILLS, KYLE	fix bent step change fuel filters and remove crankcase canister remove hood, drain coolant, evacuate a/c remove parts necessary to get to valve cover removevalve cover set valves order parts required to reassemble	
4/25/2019	7.5	HILLS, KYLE	get disc hooked up bring tractor and disc into shop get filters together for service has some leaks solenoid on trans leaks steering lines off orbital are leaking remove covers and air filter box to access get some parts ordered check belts tensioners put plastic covers back on eng ecm plugs	
Item: 15824 - communication issue				
5/2/2019	7	HILLS, KYLE	start engine and no communication codes are back find all controllers check all connectors for green can find nothing try laptop but not ag equipment on it	
4/25/2019	2.5	HILLS, KYLE	remove cover from under steps clean all connections off fuses and switches unplug all controllers plg everything back in start no alarms or lights go in check codes no active clear all	
4/24/2019	2.5	HILLS, KYLE	check levels get running all kinds of codes and blinking lights won't move start troubleshooting	
VO: 2353 - repair crash damage (2628 HR)				Closed
Item: 3242 - repair damaged front hood				
9/5/2018	2	HILLS, KYLE	grease unit take out clean up complete paper work	
9/4/2018	6.5	HILLS, KYLE	get ecm programmed by martin take out have code fix bring in and service install panel	
8/31/2018	2.5	HILLS, KYLE	complete repairs fix coolant leaks install front shroud hook up lights test lights install isolator	
8/30/2018	9.5	HILLS, KYLE	install reman alt and a/c compressor install drive shaft front drive bearing run all electrical buil	
8/29/2018	8	HILLS, KYLE	change plugs into ecm on harness fix some wires install shroud and fan onto aux drive install aux dr	
8/28/2018	2	HILLS, KYLE	go through parts swap over headlight parts one to other	



75010 [DEERE 7215R TRACTOR]

Equipment History From July 10, 2018 to August 19, 2026

8/23/2018	8.5	HILLS, KYLE	remove front grill and support remove lights and brackets repair chassis harness all broken wires	
8/22/2018	6.5	HILLS, KYLE	remove front aux drive set up take fan and shroud off make parts list and order	
8/21/2018	2	HILLS, KYLE	remove some broken parts see whats needed make parts list	
VO: 2207 - Running repairs and maintenance (2628 HR)				Closed
Item: 3038 - Running repairs				
5/8/2019	1	DEIB, ZACHARY	Inspect complaints of fault codes appearing. Require service advisor for more information.	
10/23/2018	1	DEIB, ZACHARY	Remove opposite fender and store both in hard.	
10/16/2018	1.5	DEIB, ZACHARY	Remove bent fender and mount plate. Check over unit, tighten up loose hardware on disc.	
8/21/2018	4	DEIB, ZACHARY	Examine damage to tractor by dozer. Prep and move onto trailer.	
8/8/2018	2	DEIB, ZACHARY	Look over tractor and disc. Tightened multiple loose hardware on disc.	