

VO: 217636 - fix for sale

Open

Item: 239037 - fix for sale				
6/17/2026	3.5	HILLS, KYLE	cleaned up moved unit outside and parked, put mats away and cleaned up floor.	
6/16/2026	10	HILLS, KYLE	clean up cutting edges and frog. remove fire ext and bracket. install new corners and hardware, flip edges. clean out engine belly pan and get washed, install. straighten access panel in center pan and install. loosen tracks to remove rear carrier rollers, install 2 new ones and clean up.	
6/15/2026	10.5	HILLS, KYLE	take unit outside and test functions and look for leaks. all functions work properly. bring back inside and change broken track pad (remove one from scrap set). Put gauges on A/C not blowing cold. set stands under c frame and cut off all bolts for cutting edges, remove edges and set blade on ground.	
6/12/2026	10.5	HILLS, KYLE	complete joystick boot install, fix push to connect hose connection. fill hydraulic tank and fire machine, test blade lift cylinders. get blade cleaned up and ready for install. use forklift and install blade/c-frame. install lift cylinders and test all blade functions and everything seems to work fine. check for leaks and reinstall floor in cab. top up hydraulic level.	
6/11/2026	10.5	HILLS, KYLE	clean up trunion and blade socket to mount blade. install hydraulic filter and screen into tank and fill with oil. change engine oil filter and fill with oil. change door latches and fix both door hold back latches, change travel joystick boot.	
6/10/2026	1	MINTER, TANNER	remove numbers	
6/10/2026	10.5	HILLS, KYLE	clean out hydraulic tank, clean suction strainer and covers. make parts list, install new engine oil drain valve in pan. remove blade lift spool, clean up and inspect valve lands. remove screens and inspect from fittings for spool activation, screens were ok, found a plugged orifice on blade raise side of spool. pretty sure this would cause the stuck in the up position problem, also the spool was in backwards.	
6/9/2026	9	HILLS, KYLE	get parts ordered for engine oil drain, and control valve so i can run unit fully to see what's wrong. get ends ordered to make hose for P.T filter, make hose and install. go over unit and make def list. to see what they want fixed. look at b2w and try to sort out what's been done.	
6/8/2026	8	HILLS, KYLE	lay mats and bring unit inside. bring blade in and set on blocks. missing all blade mounting hardware. investigate leaks, engine oil drain pan leaking, powertrain hose from pump to filter leaking and someone is to stupid to think zipties will hold an stc style fitting and hose together. Way to go Buddy!! Remove front pan and floor in cab. Drain engine oil work on getting My Komatsu for parts.	

VO: 209541 - Remove blade

Open

Item: 230837 - Remove blade				
5/21/2026	2	BOBEY, ALEX	Get unit set up and blade positioned. Went looking for hardware but got told to put job on hold for 1553 instead.	



01442 [KOMATSU D65PX-17 DOZER]

Equipment History From May 9, 2017 to August 19, 2026

4/5/2026	3	GOLOS, SCOTT	Get running	
2/13/2026	4	GOLOS, SCOTT	Remove blade	
2/13/2026	4.5	GOLOS, SHAWN	Remove blade	
VO: 195963 - Daily check over (14768 HR)				Closed
Item: 216648 - Daily check over				
7/28/2025	1	MONTGOMERY, ANDREW	Daily shift change and fluid top ups	
VO: 195239 - Engine blow by (14768 HR)				Closed
Item: 215818 - Engine blow by				
7/19/2025	3	FRANKLIN, SCOTT	Removed old crank case breather and sent parts a part number waited for new breather, installed and ran unit for 1/2 hour , still has slight blow by when putting hand on oil fill tube , as per Cory we will send to work see if any codes come back	
VO: 195045 - Tilt cylinder Guard repairs (14768 HR)				Closed
Item: 215618 - Tilt cylinder Guard repairs				
7/16/2025	6	CARTER, DUSTIN T	Drive from syncrude back to base mine, get directions to unit. Drive to unit repair cylinder guards help install	
VO: 194907 - Overheat (14768 HR)				Closed
Item: 215476 - Overheat				
7/18/2025	4	TYSHYNSKI, KYLE	Travel, check water pump play, check belt and components, run unit to over heat and check flow through rads, unit blowing oil out dipstick tube and excessive blow by threw tube	
7/16/2025	10	SYMINGTON, TYRELL	Ran unit couldn't get to over heat checked with temp gun 88C too 37C bottom. Rad working fine. Checked fan speed speed okay matches rpm/temp. Pressure tested rad cap cap failed need new one. Had low rail pressure code flash up while testing	
7/14/2025	5	ULRIKSEN, CONRAD	Travel to unit. Run unit till got hot. Couldn't get an over temp warning but not pushing big piles. Dropped coolant and checked thermostat and water pump. Thermostat is opening correctly and pump was in great shape. Blew through lines and wait for service for top off. Bleed system and run up started to get up to temp but blew hydraulic line. Removed line. Travel back.	
7/13/2025	6	ULRIKSEN, CONRAD	Travel to unit and prep for wash. Had to fix pressure washer before kid could wash. Start checking over unit and found engine oil low wait for service to top off. Run unit for a couple hours couldn't get an overheat code but unit was hot. Blew off pilot line had to wait for oil.	
VO: 194048 - Demob (14748 HR)				Closed
Notes: SMS ->				
Item: 214549 - Demob				
7/2/2025	2	MEGLEY, KYLE	Travel to unit, inspect per demob checklist.	
VO: 193218 - Intermittent hydraulics (14748 HR)				Closed
Item: 213669 - Intermittent hydraulics				
6/22/2025	6	SYMINGTON, TYRELL	Swapped tilt pilot lines with blade function. lowered blade. Removed tilt and blade lift spools no debris or abnormalities found. Topped up oil ran unit everything functions properly	



VO: 193032 - Hydraulic lines (14768 HR)					Closed
Item: 213468 - Hydraulic lines					
7/15/2025	3	WIPF, JACOB	Install hydraulic lines		
6/21/2025	10.5	ULRIKSEN, CONRAD	Travel to unit. Continue troubleshooting hydraulic issues. Blade control joystick lift side springs are weaker and float function doesn't work just functions as blade lower. Brakes don't function on unit. Cleaned out all ports lines and joystick yet same problems. Unit does have lots of contaminants in system due to being open so long. Found water dirt and a worm in pilot system. Travel back.		
6/20/2025	3.5	ULRIKSEN, CONRAD	Travel out to unit. Install new pilot lines on control valve. Check over unit and fire up and test functions. Blade lift and low spool kept sticking in the raise position. Pulled spool cap ends off and inspect and clean ends. Found lots of dirt water and bugs inside cap ends. Spool freely moved back and forth in valve block. Put caps back together and retest functions and same results. Possibly due to high contamination in hydraulic system. Travel back.		
VO: 189892 - Drained fuel and hydraulic (14748 HR)					Closed
Item: 209933 - Drained fuel and hydraulic					
5/12/2025	1	PADERES, EDTROY	Drained fuel and hydraulic		
5/12/2025	1.5	GREEN, BRANDON	Draining fuel and hyd oil plus travel time		
VO: 189482 - No ac (14768 HR)					Closed
Item: 209481 - No ac					
7/17/2025	3	LITTLE, JAMES (MIKE)	Drive to unit pull vacuum, unit held vacuum charged ac system		
7/16/2025	2	SYMINGTON, TYRELL	Replaced dryer started charging ac ran out of time		
5/7/2025	3.5	MOCKE, BRUCE	Check over AC system. Found low refrigerant vac an pressurized to check for leaks none found. Added dye an recharge system ac blowing at 8° in cab		
VO: 188719 - Steamed (14748 HR)					Closed
Item: 208718 - Steamed					
7/13/2025	4	TORRAVILLE, EVAN	Steamed		
4/29/2025	3	BENNETT, ADAM	Steamed uncarrriage and body		
VO: 188423 - Chipped (14748 HR)					Closed
Item: 208409 - Chipped					
4/26/2025	1	BENNETT, ADAM	Dug out tracks.and clean out garbage in the cab		
VO: 187875 - Fuel valve (14748 HR)					Closed
Item: 207852 - Fuel valve					
4/19/2025	2	HOSPERS, FOLKERT	Replace fuel valve		
VO: 187434 - Partial steam (14748 HR)					Closed
Item: 207418 - Partial steam					
4/14/2025	8	OLIVER, WILLIAM	Water in steamer froze so I had to thaw it out and then I Steamed the left side of the dozer		
VO: 184727 - Lo3 (14748 HR)					Closed
Item: 204732 - Lo3					



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

7/3/2025	8	MAKI, DANIEL	Troubleshoot and repair for no brakes	
6/16/2025	12	MAKI, DANIEL	Repair seat Assemble cab Charge a/c Top up coolant	
6/10/2025	12	MAKI, DANIEL	Assemble machine, order parts for leaking hoses	
6/9/2025	12	MAKI, DANIEL	Assemble machine Start unit Repair leaks	
6/8/2025	12	MAKI, DANIEL	Continue assembling machine	
6/8/2025	4	MEGLEY, KYLE	Travel to unit, setup crane, hoist cab into place, wrap up and travel back.	
6/7/2025	12	MAKI, DANIEL	Assemble machine	
6/6/2025	12	MAKI, DANIEL	Continue assembling machine	
6/5/2025	12	MAKI, DANIEL	Start assembling machine	
5/14/2025	11.5	MAKI, DANIEL	Continue disassembly of machine. Removed coupler Bag and tag everything	
5/13/2025	4	WIPF, JACOB	Remove cab	
5/13/2025	3	TYSHYNSKI, KYLE	Travel, helping remove cab from unit	
5/13/2025	12	MAKI, DANIEL	Disassembly machine	
5/12/2025	12	MAKI, DANIEL	Troubleshoot no hydraulic function Coupler failed Start disassembly of machine	
4/1/2025	4	LITTLE, JAMES (MIKE)	Troubleshoot codes order parts limiter valve for fuel system	
3/17/2025	2	LITTLE, JAMES (MIKE)	Remove panels to start testing make connector to test fuel pressure called off job	
3/15/2025	2	MOCKE, SEAN	Change air filters and code gone. Hydraulic temperature sensor open, order parts and door latch handle for RH door	
VO: 184490 - UNDERCARRIAGE REPORT (39 PCNT)				Closed
Item: 204493 - UNDERCARRIAGE REPORT				
Sun #1442				
VO: 181842 - Codes (14686 HR)				Closed
Item: 201617 - Codes				
3/9/2025	4	LITTLE, JAMES (MIKE)	Fuel system need to order parts	
2/21/2025	2	MOCKE, SEAN	Reassemble panels and covers, seat and cab. Plug in Hydraulic temp sensor. Not getting gears LO4 pt controller fault. Needs further troubleshooting	
2/20/2025	1	TYSHYNSKI, KYLE	Travel, install new ecm inside cab	
2/13/2025	3.5	ULRIKSEN, CONRAD	Travel to unit for codes. Found low rail pressure and hyd temp sensor open active. Checked rail pressure and unit was making same or above command pressure. Checked hyd sensor and tested good. Had 5V at sensor plug. Checked for continuity at STC1 plug against pin 14 on plug as manual says. Power train controller was deemed faulty as troubleshooting procedure.	
VO: 181704 - Cold start (14640 HR)				Closed
Item: 201481 - Cold start				
2/11/2025	2	HOSPERS, FOLKERT	Unit will not start had to prime system and boost got it going	
VO: 181499 - (250) SERVICE - DOZER KOMATSU PROGRAM				Open
Item: 201275 - (250) SERVICE - DOZER KOMATSU PROGRAM				
5/9/2025	2	MAKI, DANIEL	Perform de-mobilization	



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

VO: 181194 - Over heating (14640 HR)				Closed
Item: 200932 - Over heating				
2/11/2025	3	MOCKE, BRUCE	Change hydraulic tank sensor and hydraulic drain down to the proper level replace cab mirror. Left heat trailer on.	
2/6/2025	2	ULRIKSEN, CONRAD	Travel to unit and run up to temp. Rads were clean but hyd oil temp sensor was faulty only possibly causing the engine fan to be running 350-400 rpm lower than spec. Ordered parts.	
VO: 180642 - No start (14346 HR)				Closed
Item: 200318 - No start				
1/31/2025	1	MEGLEY, KYLE	Travel to unit for complaint of no start. Found unit would almost start but wouldn't run. Check pos air shutdown - ok. Added meltdown to fuel tank and cycled primer pump, got unit running. Checked unit after 30 min running - no issues. Left running at half throttle for ops.	
VO: 179815 - Clean out DEF filter (14332 HR)				Closed
Item: 199392 - Clean out DEF filter				
1/22/2025	6	FENTON, GARNET	Remove the DEF exhaust filter clean it out reinstall filter.	
VO: 179456 - Edges and regen (14332 HR)				Closed
Item: 199043 - Edges and regen				
250121-1442-				
1/21/2025	3	FENTON, GARNET	Do a delete on engine.	
1/18/2025	3	MOCKE, SEAN	Flip edges and do regen with travel	
1/18/2025	2	CARTER, DUSTIN T	Help mechanic flip edges on machine	
VO: 178947 - (500) SERVICE - DOZER KOMATSU PROGRAM (14640				Closed
Item: 198531 - (500) SERVICE - DOZER KOMATSU PROGRAM				
250208-1442-				
VO: 178824 - Derate (14315 HR)				Closed
Item: 198410 - Derate				
1/15/2025	3	TYSHYNSKI, KYLE	Travel, low fuel pressure code, checked wiring and sensors seems all good, blew lines back to tank and tested unit, couldn't get code to activate, debris in tank	
1/11/2025	3	MOCKE, SEAN	Kept derating and low fuel rail pressure code. Vacuum on tank, cleaned tank breather out to release Vacuum. Test and ok	
VO: 178485 - Ice lug (14276 HR)				Closed
Item: 198054 - Ice lug				
1/10/2025	4	HANSON, JORDAN	Chip out frozen track frames. Change out 3 broken track pads. Cork new pads.	
1/8/2025	5	CARTER, DUSTIN T	Finish cutting old lugs off, pick up most of the cut off lugs to throw out. Clean up grouzers install new lugs	
1/7/2025	10	HANSON, JORDAN	Cut off old corks on track pads. Clean up grouzers. Install new corks.	
VO: 178077 - Start up (14194 HR)				Closed
Item: 197588 - Start up				
1/4/2025	0.5	ULRIKSEN, CONRAD	Travel to unit to boost. Found the gear lever in the fwd position. Started.	



1/3/2025	2	ULRIKSEN, CONRAD	Put heat on unit and charge. Fire up.	
VO: 177737 - Check engine codes (14332 HR)				Closed
Item: 197233 - Check engine codes				
1/17/2025	2	MOCKE, SEAN	Preform regen and code cleared but low rail pressure still present, blew from filter back to tank and code cleared for an hour then returned. Needs further troubleshooting	
1/11/2025	2	HOSPERS, FOLKERT	Check over issues found oil to have ice on dipstick request for oil change to do further diagnoses	
12/29/2024	2	MEGLEY, KYLE	Travel to unit - complaint of derate, warnings on dash. No active codes, most recent stored codes for rail pressure. Ran unit, unable to duplicate issue. Changed both fuel filters and blew air back to tank through fuel line, primed system and ran unit at full throttle for another 20 minutes - still unable to duplicate issue, no active codes. Cleanup.	
VO: 177757 - (OIL CHANGE) SERVICE - DOZER KOMATSU				Closed
Item: 197253 - (OIL CHANGE) SERVICE - DOZER KOMATSU PROGRAM				
241227-1442-OIL				
VO: 177535 - Hardbar inspection (14160 HR)				Closed
Item: 197019 - Hardbar inspection				
12/26/2024	1	MOCKE, SEAN	Dig all frozen lumps off. 1/4" play at center, sides are fine	
VO: 176663 - Codes (14160 HR)				Closed
Item: 196058 - Codes				
12/25/2024	2.5	ULRIKSEN, CONRAD	Travel to unit. Check over and found coolant in engine oil. Wait for service and flushed engine and put in fresh oil. Checked code and found it to be fuel rail pressure sensor. Checked sensor and found one plug full of dirt cleaned and closed up.	
12/19/2024	2	MEGLEY, KYLE	Travel to unit - complaint of LO3 error. Checked active codes thru service monitor, active codes for fuel rail pressure and hyd temp sensor error. Compared desired and actual rail pressures while operating - no issues. Shut off and reset unit - codes gone and don't return. Added a bottle of fuel conditioner to tank.	
12/14/2024	5	TYSHYNSKI, KYLE	Travel, got to unit no codes active but recently logged, rail pressure low and hyd oil temp error, testing unit got hyd temp error code to activate, removed panels checking wiring and cleaning plugs, also for rail pressure sensor, reassembled and tested no codes active, repaired wiring for seat belt sensor	
VO: 176227 - (250) SERVICE - DOZER KOMATSU PROGRAM (14280				Closed
Item: 195547 - (250) SERVICE - DOZER KOMATSU PROGRAM				
250110-1442-				
VO: 175823 - Corks (13915 HR)				Closed
Item: 195025 - Corks				
12/4/2024	12	WIPF, DANIEL	Cork pads	
VO: 175703 - Edges (13915 HR)				Closed
Item: 194872 - Edges				



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

12/2/2024	3	RANTA, CLAYTON	Replace edges	
12/2/2024	4	HANSON, JORDAN	Load edges. Take old bolt off machine back to warehouse to get mounting hardware. Remove old edges. Clean surfaces. Install new edges.	
VO: 175685 - Unit died (13915 HR)				Closed
Item: 194854 - Unit died				
12/2/2024	2	MOCKE, SEAN	Heat and bleed fuel system and test drive, could not get dozer to shut down like it has been, heated and poured methohydrate through fuel tank breather, suction when removed breather	
VO: 175383 - Low fuel pressure (13915 HR)				Closed
Item: 194550 - Low fuel pressure				
11/28/2024	1	LITTLE, JAMES (MIKE)	Change fuel filters	
VO: 174436 - Mob in (13782 HR)				Closed
Notes: PCY -> SMS				
Item: 193410 - Mob in				
241116-1442-				
11/16/2024	2.5	ULRIKSEN, CONRAD	Travel to unit. Mob in unit.	
VO: 174187 - (3000) PM - DOZER PROGRAM				Open
Item: 201002 - L03 ENGINE CODE				
Item: 200364 - RIGHT INSIDE DOOR LATCH BROKEN				
3/7/2025	3.5	LITTLE, JAMES (MIKE)	Disassemble door see what parts needed ordered parts, remove broken bolts from cab air filter cover install new bolts	
Item: 200363 - FIRE EXTINGUISHER BRACKET BROKEN				
Item: 193135 - (3000) PM - DOZER PROGRAM				
10/3/2025	3	YULO, FRANCIS ALBERT	Steam	
2/5/2025	1	RANTA, CLAYTON	Blow out rads	
VO: 174247 - Demo (13777 HR)				Closed
Item: 193196 - Demo				
11/12/2024	2	KAY, CODY	DemoThe machine found out rear lights burnt out, replace them	
VO: 173484 - Belly pan (13777 HR)				Closed
Item: 192245 - Belly pan				
11/2/2024	2	MENZIES, TYLER	Fabricate new bell pan	
VO: 173309 - Track frames (13777 HR)				Closed
Item: 192045 - Track frames				
11/2/2024	7	PROUDFOOT, BRADLEY	Belly pan placed on new stump pan made from template checked and topped up all fluids take unit of stands demobe unit is a go	
11/2/2024	7	WHITE, DWAYNE	Install stump pan, fan up template for missing belly pan and bring to welding shop, install belly pan, remove dozer from blocking, fill pivot shaft and top up hydraulic to proper levels, demobe unit, complete paperwork and submit, park up unit in the up line.	



01442 [KOMATSU D65PX-17 DOZER]

Equipment History From May 9, 2017 to August 19, 2026

11/1/2024	11	PROUDFOOT, BRADLEY	Press and remove bottom LH ripper pin from lack of grease drill grease holes out clean surfaces hammer pin back into place install side panels clean work area	
11/1/2024	11	WHITE, DWAYNE	Set up work area, support ripper table, press out pin, clean up bore and inspect, bore looks good, drill out pin and clean debris out of cavity, install pin, pin take grease, grab panels from laydown, install engine panels and put floor back together, pull unit out of shop, clean up, bring unit back into shop and set up machine to install stump pans, frame has a slight bow so pan will not seat properly, modify pan to fit, will install tomorrow first thing.	
10/31/2024	9.5	PROUDFOOT, BRADLEY	1442 replace 2 grease lines replace blade HYD hose unwrap and wrap tracks clean surfaces torque pinch bolts and tracks LH/Rh	
10/31/2024	12	WHITE, DWAYNE	Set up work area, install grease fitting and lines for equalizer bar, install pinch guards and torque to spec, install missing cylinder guard, replace broken door cover, install missing louvre, bring tracks into shop and clean out for install, wrap tracks both sides, install master pads and torque to spec, remove unit from stands, tighten tracks to spec, grease machine, lower left ripper pin won't take grease due to broken zerk, change out zerk and pin will still not take, remove fitting and use pick to clean out debris, install zerk and pin will still not take, will need to remove pin and address issue tomorrow, clean up	
10/29/2024	6	KAY, CODY	Undercarriage	
10/29/2024	4	HOSPERS, FOLKERT	Install track frames	
10/25/2024	6	KNUDSLIEN, DONALD	Repair track frame	

VO: 173231 - UNDERCARRIAGE REPORT (59 PCNT) Closed

Item: 191949 - UNDERCARRIAGE REPORT				
D65PX #1442				

VO: 172654 - Linebore track frame hard bar mount (13772 HR) Closed

Item: 191258 - Linebore track frame hard bar mount				
10/28/2024	8	PETERS, MICHAEL	Complete lineboring	
10/27/2024	12	PETERS, MICHAEL	Machining hardbar mounts	
10/26/2024	1	PETERS, MICHAEL	Machining track frame hardbar mounts	
10/25/2024	12	PETERS, MICHAEL	Machining hardbar bores	
10/24/2024	9	PETERS, MICHAEL	Determined cause of misalignment, set up frame and marked out to compensate for damage, started welding bores.	
10/22/2024	4	PETERS, MICHAEL	Completed machining, delivered to U/C shop	
10/21/2024	12	PETERS, MICHAEL	Lineboring hardbar mounts	
10/20/2024	12	PETERS, MICHAEL	Machining hardbar mounts	

VO: 172683 - Fabricate stands (13772 HR) Closed

Item: 191301 - Fabricate stands				
10/22/2024	5	TOPHAM, JULIAN	Weld out stands and clean up work area	
10/21/2024	12	TOPHAM, JULIAN	Cut steel Fit and tack	
10/21/2024	3	MENZIES, TYLER	Help fabricate dozer stand cutting material	



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

VO: 172514 - Track frame repair (13772 HR)				Closed
Item: 191118 - Track frame repair				
10/24/2024	1	PANGANIBAN, RONALD (ALLAN)	Measure bors.	
10/24/2024	4	ALERTA, JERRIOJOE	Tried putting the Lh frame on and run into some problem had to take the frame off and the RH side for welders to take some measurements and took the LH side frame to welding shop.	
10/24/2024	4	KAY, CODY	Install left side track frame when installing the frame would not line up with equalizer bar, bracket, that holds the pin to the equalizer bar. Was out of line had to take frame off and got the welders to re measure and sent it to the welding bay	
10/23/2024	3	ALERTA, JERRIOJOE	Prep & clean for LH frame to be installed	
10/23/2024	3	KAY, CODY	Clean and prepped left side pivot shaft put new retainering ring empire shaft seal on and cleaned up surface and frame	
10/20/2024	9	PANGANIBAN, RONALD (ALLAN)	Fabricated cylinder guard.	
10/19/2024	12	PANGANIBAN, RONALD (ALLAN)	Repaired track frame.	
10/18/2024	6	PANGANIBAN, RONALD (ALLAN)	Repairing track frame/hard bar.	
10/18/2024	12	KNUDSLIEN, DONALD	Repair track frame	
10/17/2024	1	KAY, CODY	Walk to and from the steam bay into the shop	
VO: 172449 - Broken pinch bolt connection (13772 HR)				Closed
Item: 191053 - Broken pinch bolt connection				
10/18/2024	12	SMITH, MITCHEL	Removed left track frame Inspected welds on right track frame Inspected hard bar pin clearance found that it is almost out of spec PM machine inspection Cleaned up	
10/18/2024	4	WHITE, DWAYNE	Set up work area, clean surfaces for frame removal, remove left side frame, take frame and sheared pinch plate to wash bay, take over to welding shop, clean surfaces of right side and inspect, no cracks found on right side frame.	
10/17/2024	5	SMITH, MITCHEL	Put machine on stands Split track/removed track	
10/17/2024	5	WHITE, DWAYNE	Pull unit up to shop, shovel out tracks, bring inside, put unit on stands, release track tension, split tracks and pull out side, start looking into issues with frames, found left side pinch bolt bracket is completely sheared off frame, clean up	
10/16/2024	3	SMITH, MITCHEL	Removed panels for machine to be washed Labeled and put panels in blue bin Put bin by catfish corner	
10/16/2024	3	BENNETT, SHEA	Strip for wash. Panels placed in blue pin and brought to Catfish storage.	
VO: 171736 - Fiip edges (13772 HR)				Closed
Item: 190155 - Fiip edges				
10/3/2024	2	NAUMANN, KEVIN	Flipped the cutting edge and installed new corner bits and hardware	
VO: 171676 - Mob in (13772 HR)				Closed



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

Notes: PCY -> MLX				
Item: 190226 - Mob in				
10/5/2024	1	DUNFORD, WYATT	Mob in inspection. Find major failure of track frame, advise supervisor, continue inspection, find missing stump pan and low fluids	
VO: 171603 - Demob (13772 HR)				Closed
Notes: MLX -> PCY				
Item: 190153 - Demob				
241003-1442-				
10/3/2024	2	MCLEAN, AIDAN	Perform demob inspection. Found cutting edges need to be flipped and front lights out. Found fuse blown, front RH light ground connector melted off light housing. Replaced fuse and front LH light worked again.	
10/3/2024	3	NAUMANN, KEVIN	Find unit and did a demob	
VO: 171604 - Flip edges (13772 HR)				Closed
Item: 190154 - Flip edges				
10/3/2024	2	NAUMANN, KEVIN	Flipped the cutting edge and installed new corner bits and hardware	
VO: 171195 - No heat (13772 HR)				Closed
Item: 189715 - No heat				
9/26/2024	2	STUEBING, JEFF	No heat. Locate unit. Turn on taps. Ensure heat operates as should. Units good to go	
VO: 169949 - UNDERCARRIAGE REPORT (39 PCNT)				Closed
Item: 188375 - UNDERCARRIAGE REPORT				
D65PX #1442.pdf				
VO: 168802 - Codes (13680 HR)				Closed
Item: 187161 - Codes				
8/15/2024	3	STUEBING, JEFF	Install exhaust sensor. Assemble unit. Check for faults. No faults. Units a go	
8/15/2024	1	NAUMANN, KEVIN	Unit needed a park regen and the codes went away	
VO: 168803 - Rear cab lights not working (13680 HR)				Closed
Item: 187162 - Rear cab lights not working				
8/15/2024	2	NAUMANN, KEVIN	Repaired the wiring going to the rear work lights they work good now called unit up	
VO: 168865 - Exhaust sensor (13680 HR)				Closed
Item: 187222 - Exhaust sensor				
8/15/2024	3	CHORNEYKO, CALVIN	Assist with exhaust sensor install and reinstall all removed doors and components.	
VO: 165651 - Engine oil leak around crankcase breather tubing				Closed
Item: 183593 - Engine oil leak around crankcase breather tubing				
240813-1442-				
8/15/2024	5	NAUMANN, KEVIN	Finish putting unit back together after the valve cover gasket was changed ran unit to check for leaks tested good no leaks	
8/14/2024	6	WARREN, KEITH	Reassembled unit	
8/14/2024	10	ELDRIDGE, KENNETH	Installed exhaust filter hood and remaining parts. Left doors off waiting for parts	

8/13/2024	9	BILSKY, DANIEL	-assemble unit	
8/12/2024	12	BILSKY, DANIEL	-set up to bar engine over, found I had wrong tool -travel to laydown for proper turning tool -check and adjust valve lash -install valve cover with new seal -start assembling unit	
8/11/2024	5	BILSKY, DANIEL	-remove egr crossover pipe -remove valve cover and rocker box -clean and install new rocker seal and torque bolts to spec	
7/10/2024	5	BILSKY, DANIEL	-remove DOF mount plates -disconnect and main engine harness out of the way -remove turbo outlet -remove crank case filter -order parts	
7/9/2024	6	NAUMANN, KEVIN	Travel out to the unit removed parts to access the valve cover where the leak is coming from ordered parts to put DPF filter back in the unit	
7/9/2024	9	BILSKY, DANIEL	-clean oil/ oil at from top of engine -pressure up cooling system. Monitor and check for leaks. All good -run unit to temp and check leaks. Bad engine oil leak from top rear of engine. No coolant leak -pressure cooling system again while at temp. No leaks -travel to laydown and pick up parts -start disassembly to access valve cover	
6/25/2024	6	FIFE, ANDREW	Repaired leak travel	
6/20/2024	2	FIFE, ANDREW	Tested for leaks, found valve cover leaking at the rear of the engine. Checked valve cover bolt tightness. Removed fill cap to ensure crankcase pressure was not pushing oil past seal. Ordered new valve cover gasket.	
6/19/2024	2	FIFE, ANDREW	Checked for leaks, checked routing of hoses in parts diagram	
VO: 165666 - (2000) SERVICE - DOZER KOMATSU PROGRAM				Closed
Item: 183619 - (2000) SERVICE - DOZER KOMATSU PROGRAM				
241208-1442-				
12/8/2024	1.5	ULRIKSEN, CONRAD	Travel to unit to break final plugs loose. Travel back to unit for damper oil.	
VO: 163115 - (250) SERVICE - DOZER KOMATSU PROGRAM (13664				Closed
Item: 181163 - (250) SERVICE - DOZER KOMATSU PROGRAM				
2024-06-18 - 1442 -				
VO: 162259 - (500) DOZER KOMATSU PROGRAM (13385 HR)				Closed
Item: 178524 - (500) DOZER KOMATSU PROGRAM				
240509-1442-				
VO: 162260 - (2000) PM - DOZER PROGRAM (13777 HR)				Closed
Item: 181539 - CUTTING EDGES NEED REPLACING				
10/3/2024	4	MCLEAN, AIDAN	Re and re corner bits, hardware and flip center cutting edges.	
Item: 180586 - (2000) PM - DOZER PROGRAM				
10/20/2024	12	SMITH, MITCHEL	Extracted broken bolts on cabinets Replaced right front light housing all light now work Installed bushings and seals in hard bar Installed hard bar Removed shims from c-frame Found dirt packed into grease ports on hard bar and c frame, cleaned out cleaned out window tracks Cleaned up	



01442 [KOMATSU D65PX-17 DOZER]

Equipment History From May 9, 2017 to August 19, 2026

10/20/2024	12	WHITE, DWAYNE	Set up work area, remove worn components out of hard bar, clean and prep surfaces, grab parts from warehouse, install new bearings and bushing into hard bar, install hardbar onto unit, re attach right side frame, remove old carrier rollers on right side frame, clean and prep bores, install new carrier rollers, torque to spec, fix front right light, remove shims from c frame push arms to tighten up pinch, clean up	
10/19/2024	12	SMITH, MITCHEL	Found undercarriage tolerance specs/made up parts list Rollers 85% Idlers 50% Carrier rollers need to be replaced Removed segments Buffed all around finals/new segments Installed new segments torqued to 400ft/lbs Cleaned up	
10/19/2024	12	WHITE, DWAYNE	Finish up PM checklist and document findings, measured undercarriage, rollers at 85%, idlers at 50%, carriers need replacing, segments need replacing, look up parts and submit list, grab segment kit from carrier rollers in stock and bring to shop, remove old segments, clean and prep finals and parts for install, install segments on both sides, torque to spec, remove hard bar, clean up	
10/18/2024	6	WHITE, DWAYNE	Work on PM checklist, document findings, look up equalizer bar movement tolerances on computer, 135 thou of movement measured in center pin, let Erick know our findings, clean up	
Item: 175406 - WORK EQUIP SYSTEM ERROR				
241018-1442-				
VO: 162096 - VGT codes (13438 HR)				Closed
Item: 180772 - VGT codes				
5/20/2024	2	GOODMAN, JAYDEN	Checked over. Monitored values, vgt and egr solenoids unresponsive. Checked wiring and found plug not seated, plugged in and tested	
5/20/2024	2	SHEARER, KEELAN	Went to unit to check out L03 code for VGT. Found loose connectors on wiring to VGT. Sent back to work.	
5/20/2024	1	CHORNEYKO, CALVIN	Diagnose vgt/ egr code. Inspected unit and found connector from egr to be pulled out. Plugged back in and code went away and did not return.	
5/4/2024	6	MCDONALD, OWEN	Troubleshoot kvgt codes, drove to unit. Inspected harness. Performed continuity test to lift and egr solenoid. Found broken wire on egr solenoid harness. Found signal wire pulled out of duetch connector on kvgt codes. Repaired. Tested. Both codes gone. Called unit up	
VO: 160480 - Battery light on (13238 HR)				Closed
Item: 179215 - Battery light on				
4/15/2024	3	NAUMANN, KEVIN	Travel out to the unit and trouble shoot the battery light on and found a broken wire in the harness to the alternator repaired the wire and light went out	
VO: 160517 - (RESAMPLE) DOZER KOMATSU PROGRAM (13238 HR)				Closed
Item: 179252 - (RESAMPLE) DOZER KOMATSU PROGRAM				
240415-1442-				
VO: 159810 - (250) DOZER KOMATSU PROGRAM (13163 HR)				Closed
Item: 175921 - (250) DOZER KOMATSU PROGRAM				
240405-1442-				

VO: 159224 - Blade not going up and down properly (13130 HR)
Closed

Item: 177932 - Blade not going up and down properly			
3/31/2024	6	ELDRIDGE, JOSEPH	Drove to unit and set up work area, removed lines from blade lift and lower spool valve, removed spool valve from unit, polished up spool, cleaned out valves on either end of spool, reassembled, tested for proper function, blade still did not function 100% properly, recommend replacing spool to repair correctly. Reassembled all body panels.
3/31/2024	4	NAUMANN, KEVIN	Travel out to the unit removed the spoil valve and polished it there is some scratches on it installed the spoil back in the valve the blade is still working the same as before Cullen said send it back to work put panels back on the side and send back to work
3/30/2024	6	ELDRIDGE, JOSEPH	Drove to unit, tested blade operation, found blade is not stopping when lifting when control is returned to center, also found hesitation on blade lower function, went through hydraulic and electrical schematics to understand system, checked pilot pressures and main pump pressure, found pressures well within specification, good power at solenoid valves, removed pilot lines from blade tilt function and swapped them onto blade lift and lower spools, tested for operation of blade lift and lower, found unit still has the exact same issue when operating with different pilot circuit installed, looked up parts for blade lift and lower spool.
3/30/2024	8	ELDRIDGE, KENNETH	Blade not functioning properly up and down. Removed joystick checked for and debris. Had the filters cut open didn't find anything. Removed solenoid valves cleaned the screens. Crossed with nights
3/30/2024	6	NAUMANN, KEVIN	Helped Joe with diagnosing the problem with the blade no going up and down properly

VO: 159114 - Replace turbocharger (13113 HR)
Closed

Item: 177822 - Replace turbocharger			
240328-1442-			
3/28/2024	8	ELDRIDGE, JOSEPH	Drove to unit, set up work area, removed panels, removed intake and exhaust pipes, removed heat shields and guards, waited for service to drain coolant, removed coolant and oil lines, removed oil control manifold from top of turbo, removed turbo mounting nuts, removed turbo, removed mounting studs, one was seized, had to heat to remove. Swapped coolant and oil fittings to new turbo, installed turbo with new gasket and studs reinstalled all other pieces using new o-rings. Had coolant re-filled and ran unit. No codes returned.

VO: 159017 - Clean out pans (13113 HR)
Closed

Item: 177725 - Clean out pans			
3/26/2024	2	ELDRIDGE, JOSEPH	Removed pans from unit, cleaned out peat and mud.

VO: 158637 - Check over (13130 HR)
Closed

Item: 177354 - Check over			
3/29/2024	2	ELDRIDGE, KENNETH	Checked unit over after it was warmed up didn't find any leaks put unit to work
3/21/2024	5	MINTO, SANTINO	Checked over unit, was told issue with blade functions no issues oops just need to let the unit warm up before running it

VO: 158559 - Vgt codes (13113 HR)
Closed



01442 [KOMATSU D65PX-17 DOZER]

Equipment History From May 9, 2017 to August 19, 2026

Item: 177272 - Vgt codes				
3/28/2024	4.5	STUEBING, JEFF	Remove turbo Install new. Test unit. Good to go	
3/22/2024	5	ELDRIDGE, JOSEPH	Found active codes for VGT, did not have adapters to hook up gauges for oil pressure, removed oil lines and checked for debris, removed VGT actuator and attempted to move veins manually, could not get veins to move without tapping on the arm with a hammer, veins in turbo are seized. Re-assembled all removed pieces so unit can be ran and moved if necessary.	
3/22/2024	8	MINTO, SANTINO	Unit throwing a CA2387 code KVGT servo err, checked over unit, have to drive back and forth to lay down to get service to use internet to look up procedures, need two Komatsu test fittings to test oil pressures to the VGT, everything I've checked leads to the turbo needing to be replaced	
3/22/2024	5	GOODMAN, JAYDEN	Do reasearch on code. Pull actuator off , inspected screens. Veins extremely stiff.	
3/21/2024	3	CHORNEYKO, CALVIN	L03 codes, vgt servo error. Ran unit and checked for code, inspected wiring and found some wires to be rubbed through which could be cause of code. Adjusted wires as to not rub together. Ran unit and no code came up. Once unit got warm code came back. Further diagnostics required.	
VO: 157206 - (1000) DOZER KOMATSU PROGRAM (12948 HR)				Closed
Item: 174031 - (1000) DOZER KOMATSU PROGRAM				
240308-1442-				
VO: 157061 - Engine oil leak (12948 HR)				Closed
Item: 175777 - Engine oil leak				
3/9/2024	2	BELL, CORY	Look up and order parts for valve cover reseal.	
3/8/2024	3	BELL, CORY	Drive to unit at pond 3. Fire unit up, inspect for leaks. Remove left side engine bay panels. Clean off suspect area of leak. Let unit run and get hot. Found leak coming from the very rear end on the driver side valve cover seal leaking. Reinstall panels.	
VO: 156574 - Cutting edges (12897 HR)				Closed
Item: 175283 - Cutting edges				
3/5/2024	1	BELL, CORY	Chip mud from blade and inspect cutting edges	
VO: 156371 - Light repair (12875 HR)				Closed
Item: 175077 - Light repair				
3/4/2024	3	WHYBREW, DANIEL	Morning start up. Drive out to unit Repaired rear work lamp mounting bracket.	
VO: 156218 - Changed hydraulic temperature sensor (12828 HR)				Closed
Item: 174924 - Changed hydraulic temperature sensor				
3/1/2024	2	WHYBREW, DANIEL	Wait for unit to come available Change out sensor, checked monitor: code for hydraulic fault is not active. Put unit back to work.	
VO: 156088 - Codes diag (12798 HR)				Closed
Item: 174791 - Codes diag				



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

2/29/2024	3	ELDRIDGE, JOSEPH	Drove out to unit, set up work area, troubleshoot L01 code hydraulic temp sensor open circuit, found faulty temperature sensor, part ordered.	
2/29/2024	4	BELL, CORY	Trouble shoot fault codes	
VO: 155355 - (250) DOZER KOMATSU PROGRAM (12648 HR)				Closed
Item: 172587 - (250) DOZER KOMATSU PROGRAM				
240222-1442-				
VO: 153921 - (500) DOZER KOMATSU PROGRAM (12288 HR)				Closed
Item: 163359 - (500) DOZER KOMATSU PROGRAM				
240202-1442-				
VO: 153922 - (RESAMPLE) DOZER KOMATSU PROGRAM (12288 HR)				Closed
Item: 172588 - (RESAMPLE) DOZER KOMATSU PROGRAM				
240202-1442-				
VO: 153534 - MOB (12275 HR)				Closed
Item: 172196 - MOB				
240131 - 1442 -				
VO: 153558 - MOB (12275 HR)				Closed
Item: 172221 - MOB				
1/31/2024	2	MCDONALD, OWEN	Install radio, MOB inspection	
VO: 150359 - Inspection (12089 HR)				Closed
Item: 169035 - Inspection				
12/19/2023	1	BRACE, AARON	Inspection	
12/19/2023	1	KAY, CODY	Inspection	
12/18/2023	5	LAVERS, DYLAN	Got parts. Replace grease nipples that was not taking grease. Installed A/M FM radio signal antenna. does as it should. Blow out whipe down cab had some help checking hard bar . Hard bar has some play nothing major. Along with side frame pins. Installed track tensioner valve adjusted tracks. Chipped tracks for clean transport	
12/17/2023	8	LAVERS, DYLAN	Inspected unit. Warmed machine tested functions. Tested heat. Replaced fire extinguisher. Tag missing. Greased unit. Noticed tracks a little loose. Track adjuster valve not taking grease, lower ripper pin nipple missing . Switched nipple from one side to the other to add grease to pin. check oils check final, engine oil, hyd. ect. Cleaned cabin precleaner. Tested radio noticed A/M F/M radio no signal just static.. bent exhaust stack.. re-shaped exhaust tip Inspected undercarriage. 70% life left.	
VO: 150153 - Ice lug (12089 HR)				Closed
Item: 168828 - Ice lug				
12/14/2023	6.5	PETERS, MICHAEL	Ice lugged	
12/14/2023	6.5	MENZIES, TYLER	Ice lugging	
VO: 142756 - (250) DOZER KOMATSU PROGRAM (11971 HR)				Closed
Item: 115147 - (250) DOZER KOMATSU PROGRAM				



230824-1442-				
VO: 132109 - Service/ general repairs (11768 HR)				Closed
Item: 150714 - Service/ general repairs				
6/2/2023	1.5	VANROSSUM, TYLER	install wipers, tires down and move into yard, clean up bay	
6/1/2023	8.5	VANROSSUM, TYLER	finish service, install window rubber, test ac, remove pin in front right rod end clean and reassemble, grease, service report and sample paperwork,	
5/31/2023	4.5	VANROSSUM, TYLER	move int oyard and warm up, bring into shop and service/pull samples	
5/29/2023	0.5	VANROSSUM, TYLER	check levels, move to wash bay, order filters	
VO: 132923 - (2000) DOZER KOMATSU PROGRAM (11768 HR)				Closed
Item: 151523 - (2000) DOZER KOMATSU PROGRAM				
230601-1442-Oil				
VO: 99621 - Running repairs (12089 HR)				Closed
Item: 117701 - Running repairs				
10/5/2023	1	DU PLESSIS, RYNO	Repair lace blamed angle switch	
9/29/2023	1	DU PLESSIS, RYNO	Pull joystick handle apart to install new angle switch wrong switch ordered reinstall	
9/28/2023	0.5	DU PLESSIS, RYNO	Check out blade angle on it own , ord new switch	
9/9/2023	0.5	BOBEY, ALEX	Travel to site to replace joystick harness. Got there and wrong parts. Order correct ones.	
9/7/2023	2	BOBEY, ALEX	Check into angle implement faults. Switch is damaged, check wiring and it looks good. Faults are inactive. Order switch.	
8/21/2023	1	DU PLESSIS, RYNO	Replace broken inside de door latch handle assembly	
8/19/2023	0.5	BOBEY, ALEX	Show Dallas how to use service menu to reset faults for filters etc.	
7/19/2023	3.5	BOBEY, ALEX	Remove dpf, wait for parts, Replace DPF filter. Reset exhaust software. New calibration is also available for ecu but it needs to be done with good internet connection.	
7/17/2023	2	DU PLESSIS, RYNO	Force regen and install til 2way	
7/15/2023	1	DU PLESSIS, RYNO	check out regen complaint, machine requested 1 regen will monitor frequency	
12/12/2022	1.5	DU PLESSIS, RYNO	Put heat on engine and fire up machine to be hauled out	
10/7/2022	2	BOBEY, ALEX	Travel to site. Replace edges.	
10/3/2022	9	DU PLESSIS, RYNO	11628hours , remove and replace all 6 injectors , reassemble machine, prime fuel system and do fire up, machine started easy and quick ran machine up to temp , park machine and fire up after sitting - fired up as it should	
10/3/2022	5.5	FEREDAY, JACKSON	Pick up parts. Go to site. Put fuel lines on. But dpf bracket on. And filter. Put covers on. Put hood on. Put to section of grill on. Clean up tools	
10/1/2022	1.5	DU PLESSIS, RYNO	Pull hoods and KDPF	
9/30/2022	2.5	DU PLESSIS, RYNO	Help troubleshoot CA559 low fuel rail pressure fault . Test fuel return leakage on pressure limiter valve- in spec , supply pump - in spec and injectors not in spec normal return is 70ml/60sec and actual return was 1200ml/60sec	
9/30/2022	3	BOBEY, ALEX	Pack up truck and travel to site. Hook up insite and perform HPF system testing. Not able to build more then 14,000psi. Test return manifolds and found high injector return flow.	



01442 [KOMATSU D65PX-17 DOZER]

Equipment History From May 9, 2017 to August 19, 2026

9/29/2022	2	DU PLESSIS, RYNO	Remove and replace fuel suction control valve on fuel pump, run machine up to temp, no active faults or bogging down , running 100psi supply fuel pressure and 57Mpa at idle and 160MPa at stall	
9/26/2022	5	BOBEY, ALEX	Pack up all tools and travel to site. Inspect machine and it is hard starting. Stored faults for common rail pressure low. Inspect rail relief valve leakage and it is okay. Remove fuel filter and set up test port to test low side pressure. Reading 95psi at idle and 105-115psi stalled. Remove injection pump and remove head. Cam is good, tappets good. Pump has old ceramic tappets recommend replacing with stainless. Suspect issue is related to fuel metering. Could not replicate issue. Remove tank Strainer and clean. Order FP actuator. Put machine back together so it can work.	
9/16/2022	1.5	DU PLESSIS, RYNO	Check out implements won't move, machine had fault for implement system erratic intermittent or incorrect, fault was clearEd before I arrived at the machine	
9/2/2022	2.5	DU PLESSIS, RYNO	Check out machine died while operating, hard starting complaint, fault CA0559 for low rail pressure was logged , fuel filter was overdue for replacement, remove and replace and returned unit to work 11468hours	
VO: 97064 - (250) DOZER KOMATSU PROGRAM (11315 HR)				Closed
Item: 82168 - (250) DOZER KOMATSU PROGRAM				
1442 (250HR) 08-				
VO: 96421 - Lube Service (11315 HR)				Closed
Notes: null				
Item: 114500 - Lube Service				
8/3/2022	3	CLARKE, THOMAS	Lube service was done at 11315 hours on unit.	
VO: 88309 - TIL radio (10937 HR)				Closed
Item: 105861 - TIL radio				
6/28/2022	0.5	DU PLESSIS, RYNO	Repair 2 way complaint	
5/19/2022	0.5	BOBEY, ALEX	Install TIL 2 way.	
5/19/2022	1	DU PLESSIS, RYNO	Tshoot 2way not working there was 24v wired to radio , Wire in 12v inverter to 2way	
VO: 85951 - trouble shoot and repair transmission (10937 HR)				Closed
Item: 103252 - trouble shoot and repair transmission				
7/19/2022	0.5	MACLEAN, RONALD	Sample transmission	
5/20/2022	1	DU PLESSIS, RYNO	10937hours remove and replace trans filter to be cut and inspected	
5/12/2022	7	SCHWABE, STEPHEN	drop pan and change damper oil, warm up unit and preform clutch calibration, calibration failed multiple times on the 10th out of 11 steps, ran unit and then tried again and it completed the calibration 2 times in a row, adjust ac belt	
5/11/2022	5	SCHWABE, STEPHEN	travel to site, test drive unit for vibration on shifts between 1st and 2nd in auto, read manuals to find the proper function of the torque converter lock up clutch	
5/9/2022	4	SCHWABE, STEPHEN	replace 2 top cab lights, move unit out and test run found no issues, bring unit in shop and patch a hole in the side of the left idler , move unit out and clean shop of all the mud tracked.	

5/6/2022	6	SCHWABE, STEPHEN	replace barrel end bearing, clean out grease holes in rod end bearing,install cylinder/blade	
5/5/2022	3.5	SCHWABE, STEPHEN	fill transmission, set brake linkage, check brake release pressure and service pressure, install floor and floor mat, cut and remove pin for blade tilt cylinder	
4/29/2022	11	SCHWABE, STEPHEN	adjust brakes, torque stall and test brakes, found brakes holding properly and no transmission slippage, pull and inspect filter and screens, very minor clutch and metal found in all but not enough to prove a major failure, install screens and new filter, install belly pan, move blade in and clean parts, order parts to install blade so we can send unit out for testing	
4/29/2022	6	AVISON, LYLE	T-shoot trans/brake issue, re-adjust brake linkage and stall, check filters and drain oils	
4/28/2022	7	SCHWABE, STEPHEN	check over and test run unit, found weak brakes the contamination in the filter may be from failing brake discs but will need further testing to verify, move unit into shop and clean up mud, found brakes not adjusted properly and are only applying at about 70% with the service brake pedal	
VO: 84594 - Strip unit to low bed to golden spike (10870 HR)				Closed
Item: 101786 - Strip unit to low bed to golden spike				
4/26/2022	0.5	DU PLESSIS, RYNO	Off load blade	
4/14/2022	2	WAKELAM, PARKER	Finish taking blade off	
4/13/2022	6	WAKELAM, PARKER	Get unit running. Start taking blade off. Pins siezed in bearings had hell of a time pressing pins out is to gouge pin out. One pin on angle cylinder will have to be replaced as I tried to notch bearing out to get pin movement and couldn't	
VO: 82751 - Edges (10870 HR)				Closed
Item: 99844 - Edges				
3/29/2022	3	MACLEOD, CHRISTIAN	Replaced edges on unit	
VO: 77756 - February running repairs Lyux Creek 2022 (10870 HR)				Closed
Item: 94482 - February running repairs Lyux Creek 2022				
2/18/2022	2	SZYBUNKA, EDWARD	Go to unit install track adjuster's and adjust tracks for hauling out.	
2/12/2022	2	SZYBUNKA, EDWARD	Called to unit has LO4 code, check codes has SCR efficiency low, def problem and engine controller partial data lose. Checked wiring at engine ECM, forced a burn on unit come back about.5 hr later and codes gone, suspect def partially froze once def started flowing unit is fine and no more LO4 code. " NOTE " unit needs tracks adjusted, need engine panel handles, edges need flipping.	
VO: 66023 - November 2021 Running Repairs - Lynx Creek (10870				Closed
Item: 82187 - November 2021 Running Repairs - Lynx Creek				
11/22/2021	4	WAKELAM, PARKER	Find def leak run tests and clear codes	
11/12/2021	1	WAKELAM, PARKER	Try to fix body panel, broken bolts in unit, couldn't finish.	
11/11/2021	4	WAKELAM, PARKER	Install upper rad hose, put cab together, run unit check for leaks, install pannels.	
11/5/2021	5	WAKELAM, PARKER	Repair line and it still locked - took all heater hose out of unit and replaced with new heater hose that won't get hard and break	



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

11/4/2021	4	WAKELAM, PARKER	Chase coolant leak, had to tear cab apart to get underneath to find leak. Hose off heater core parts ordered	
VO: 65953 - Service October 31, 2021 (10851 HR)				Closed
Notes: null				
Item: 82116 - Service				
10/31/2021	3.5	ATES, CHRISTOPHER	oil change	
Item: 74705 - (1000) DOZER KOMATSU PROGRAM				
103121-1442-				
VO: 63185 - October 2021 Running Repairs Lynx Creek (10851 HR)				Closed
Item: 79298 - October 2021 Running Repairs - Lynx Creek				
10/31/2021	5	FOSS, TEDDIE	Service unit	
10/21/2021	3	SZYBUNKA, EDWARD	No lights on unit, replace bulbs and repair ground wire, replace left had rear hood latch and replace cotter pins on ripper shank pin.	
VO: 60534 - September 2021 Running Repairs - Lynx Creek (10648				Closed
Item: 76596 - September 2021 Running Repairs - Lynx Creek				
9/22/2021	2	WAKELAM, PARKER	Tighten track up	
9/19/2021	1	WAKELAM, PARKER	Torque axel bolts to 500ft/lbs	
9/18/2021	10	WAKELAM, PARKER	Install final drive pull idler and re shim, put idler back in. Wrap tracks and fill with oil	
VO: 58582 - (500) DOZER KOMATSU PROGRAM (10622 HR)				Closed
Item: 69352 - (500) DOZER KOMATSU PROGRAM				
210809 - 1442 -				
8/9/2021	4	FOSS, TEDDIE	Service unit #1442	
VO: 57853 - August 2021 Running Repairs - Lynx Creek (10632 HR)				Closed
Item: 73761 - August 2021 Running Repairs - Lynx Creek				
8/27/2021	1	SZYBUNKA, EDWARD	Load up parts in parts truck and have taken o SMS Equipment.	
8/26/2021	5	SZYBUNKA, EDWARD	Finish grinding out around bolt holes so can get socket on and remove bolts. Remove one segment and lift out finial drive with broken hub.	
8/24/2021	5	SZYBUNKA, EDWARD	Assemble track tensioner and install into track frame. Remove ripper shank r/h side and spin r/h track off to get at finial drive,	
8/12/2021	1.5	SZYBUNKA, EDWARD	Called to unit r/h track will not adjust, changed grease nipple will not even attempt to move get to lay down, track adjuuster pilled up.	
8/12/2021	1.5	CLARKE, THOMAS	Track slacking off; assist mechanics	
8/10/2021	1.5	WAKELAM, PARKER	Try to hyd press oil into bearings on cylinder as lube techs can't get grease in them, put 6000psi and it wouldn't come through	
VO: 55306 - July 2021 Running Repairs - Lynx Creek (10354 HR)				Closed
Item: 71085 - July 2021 Running Repairs - Lynx Creek				
7/12/2021	1.5	SZYBUNKA, EDWARD	Called to unit two way radio dont work no power, pack up tools again and go to unit found fuse blown replace fuse and radio works fine.	



01442 [KOMATSU D65PX-17 DOZER]

Equipment History From May 9, 2017 to August 19, 2026

7/4/2021	2	WAKELAM, PARKER	Get unit to go into manual shift mode instead of automatic	
VO: 53610 - (500) DOZER KOMASTU PROGRAM (10110 HR)				Closed
Item: 58880 - (500) DOZER KOMATSU PROGRAM				
2021-06-				
6/10/2021	2	NICOLAY, CHAD	A Service	
VO: 53021 - Remove cab for cab strut replacement (10109 HR)				Closed
Notes: null				
Item: 68667 - Remove cab for cab strut replacement				
6/9/2021	3	HANSON, KELSEY	Add oils and coolant grease	
6/6/2021	12	HANSON, KELSEY	Install cab	
6/5/2021	12	HANSON, KELSEY	Remove cab for strut install	
6/4/2021	4	HANSON, KELSEY	Remove odds and needs to remove cab	
6/3/2021	5	HANSON, KELSEY	Start cab removal. Drain fluids	
VO: 52657 - June 2021 Running Repairs - Lynx Creek (10117 HR)				Closed
Item: 68281 - June 2021 Running Repairs - Lynx Creek				
6/13/2021	1	HANSON, KELSEY	Repair 2 way	
6/11/2021	4	HANSON, KELSEY	Install new edges. Tighten up a few loose hoses, test run. Install misc paneling	
6/10/2021	3	HANSON, KELSEY	Replace hyd lines to control valve test for leaks	
6/8/2021	5	HANSON, KELSEY	Install ripper onto machine.	
6/7/2021	10	HANSON, KELSEY	Install ripper. Assemble cab	
VO: 51199 - May 2021 Running Repairs - Lynx Creek (9997 HR)				Closed
Item: 66767 - Ripper bushings and pins				
5/23/2021	3	SZYBUNKA, EDWARD	Cut out old bushing and clean bores and press in new bushings for ripper table mounting for machine.	
VO: 50311 - Repair cab air filter box (9953 HR)				Closed
Item: 65812 - Repair cab air filter box				
5/12/2021	2	HANSON, KELSEY	Repair cab filter	
VO: 48467 - Diagnose no a/c (9802 HR)				Closed
Item: 63716 - Diagnose no a/c				
4/22/2021	2	HANSON, KELSEY	Install ac belt, numb up system	
4/17/2021	3	HANSON, KELSEY	Diagnose no a/c, source out parts	
VO: 47805 - April 2021 Running Repairs Lynx Creek (9884 HR)				Closed
Item: 64814 - Inspect and Repair Loose Corner Bit				
Notes:				
4/30/2021	2	WASCHUK, AARON	Travel to machine and inspect corner bit. Bolts broken off. Travel and get hardware. Return and remove. Clean frog and bit up (paint still on). Install bit. Clean up.	
Item: 64431 - Inspect Unit for Lack of a Seat Belt. Repair Dust Ejector Cover				
Notes:				



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

4/28/2021	1.5	WASCHUK, AARON	Installed ordered parts. Install seatbelt assembly and swap out failed dust ejector assembly.	
4/26/2021	2	WASCHUK, AARON	Travel to machine and inspect unit for lack of a seat belt. Sourced and Ordered parts. Inspected dust ejector cover. Bolt threads stripped, base cracked and collector cracked. Patched and sourced replacement parts.	
Item: 62920 - Inspect and Repair for Engine Shutdown/Will not Restart				
4/13/2021	9	SZYBUNKA, EDWARD	Install new speed sensor and adapter and check all wiring resistance and voltage to speed sensor as per Komatsu troubleshooting all resistances and voltage ok. Change last chance filter and install floor panels and check all fluids and start unit and warm up. Run dozer around for 1 hr and no codes come up for transmission speed. Install ripper mounting plate on back of unit and torque up mounting bolts to 1500 ft lbs for 6 large bolts and 700 for 10 smaller bolts and had red locktight on bolts. Install floor matt in unit and cleaning up ripper control valve.	
4/12/2021	10	SZYBUNKA, EDWARD	Continue to cut out pins and press out with 60 ton ram. Remove ripper and table as one assembly and remove ripper mounting plate off back of machine to get at transmission speed sensor.	
4/5/2021	2	WASCHUK, AARON	Travel to machine and Inspect for engine shut down and will not restart. Determined the roda deco valve had tripped. Reset and returned to service.	
Item: 62919 - Inspect for Irratic Transmission Operation				
4/14/2021	2	SZYBUNKA, EDWARD	Install ripper valve and install tear covers over valve.	
4/12/2021	2	WASCHUK, AARON	Assist with Ripper Removal as requested. Cut and Press out table pins.	
4/11/2021	6	SZYBUNKA, EDWARD	start removing ripper off unit so can get at transmission speed sensor, had to press out pins to remove link arms off and start on ripper table pins.	
4/7/2021	3	FOSS, TEDDIE	Re-Check Trans Fluid Level, Remove last chance screen	
4/6/2021	4	WASCHUK, AARON	Travel to the machine and inspect for lack of forward or reverse motion. Ran unit after checking fluid levels and leak checking . Ran unit to the laydown to further inspect. Removed panels, seat and seat base to gain transmission access. Drain and inspect scavenging screen, filter, last chance filter, etc. Check electrical operation of components. Found the transmission output speed sensor to be out of range. Source and order parts required. Ripper removal may be necessary to change the sensor.	
4/6/2021	4	FOSS, TEDDIE	Drain Trans, sample oil, remove & check all screens, change filter	
VO: 42392 - Replace undercarriage (9693 HR)				
Item: 56344 - Replace undercarriage				
2/12/2021	8	FOSS, TEDDIE	Assist mechanics with undercarriage replacement	
2/12/2021	10	WASCHUK, AARON	Grind track pads and cork unit as requested.	
2/12/2021	10	SZYBUNKA, EDWARD	Grind pads and cork unit	
2/11/2021	10	WASCHUK, AARON	Get unit running. Inspect/attempt to mount track gaurds. Too badly bent/twisted. Wrap tracks. Hook up and torqued to spec. Ran in carrier rollers and set for optimal wear.	

Closed

2/11/2021	10	SZYBUNKA, EDWARD	Cut rock guards as per instructions supplied by SMS and try to get up in place, were so badly bent up decided with arron that we are losing a battle with then and didnt put up because were so badly bent up. Get tracks and wrap and torque up track, temp was still -38 out side so took longer than normal.	
2/10/2021	6	WASCHUK, AARON	Install Idler and Shim to spec. Heat and collapse RH track adjuster. Prep for track install	
2/10/2021	8	SZYBUNKA, EDWARD	Drill out track frame and install inserts and hank rollers and torque up roller bolts to 325 ft lbs. install idler and shim .	
2/9/2021	4	WASCHUK, AARON	Repad side frame sections required for undercarrige rebuild.	
2/9/2021	3	SZYBUNKA, EDWARD	breaking track guards out of frozen ground and trying to get frost fighters to work.	
2/8/2021	10	SZYBUNKA, EDWARD	picking up parts for unit to take to lynx creek	
2/5/2021	6	WASCHUK, AARON	Thaw side frames and clear frozen debris from the track adjuster bores. Install LH idler and Track adjuster. Shim as necessary.	
2/4/2021	4	WASCHUK, AARON	Continue Undercarrige Rebuild. Replace Idler wear strips as necessary/build up worn slider section and grind down.	
2/1/2021	2	WASCHUK, AARON	Prepare cores/tracks for shipping. Wrap and strap tracks, etc.	
1/31/2021	2	WASCHUK, AARON	Assist with Undercarrige/Source and order parts required to complete undercarrige.	
1/31/2021	4.5	RIEHL, NATHAN	Continue work on undercarrige overhaul	
1/30/2021	3	WASCHUK, AARON	Assist with Undercarrige Re/Re	
1/30/2021	7.5	RIEHL, NATHAN	Continue undercarrige overhaul	
1/29/2021	6	SZYBUNKA, EDWARD	Finish getting rollers in place and looked up torqe valve for roller bolts, pack up tools and clean up garbage.	
1/29/2021	4	RIEHL, NATHAN	Continue on undercarrige replacement	
1/28/2021	4	SZYBUNKA, EDWARD	start installing rollers on unit.	
1/28/2021	6	RIEHL, NATHAN	Continue undercarrige overhaul	
1/27/2021	8.5	SZYBUNKA, EDWARD	Block up unit, split tracks and try to remove with skidsteer would not pull tracks. Had to get 644K john deer loader from area 24 to pull tracks off unit. Removed all rollers and cleaned track frames, brought rollers over and brought idlers over. Went through all hardware and found only had 14 roller bolts, called mike and he got roller bolts from SMS Chetwyn and Ft Saint John, labour went to Dawson and is picking up bolts from Cheteyn and labour will go to Ft Saint John in A.M. for parts.	
1/27/2021	6.5	RIEHL, NATHAN	Work on undercarrige overhaul	

VO: 42028 - A Service (9567 HR)
Closed
Item: 55890 - A Service
210107 - 1442 - A
VO: 40692 - January 2021 Running Repairs (9687 HR)
Closed
Item: 56060 - Repair rock guard

1/24/2021	6	RIEHL, NATHAN	Continue with rock guard repair	
1/23/2021	1	SZYBUNKA, EDWARD	start removing broken bolts from rock guards.	



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

1/23/2021	2	RIEHL, NATHAN	Start repairing rock guard.	
Item: 54821 - Diagnose and Repair L04 Code (Alternator Failed)				
1/10/2021	2	WASCHUK, AARON	Install alternator. Function test output of component. All okay. Return to service	
1/9/2021	2	WASCHUK, AARON	Diagnose and repair L04 code. Alternator bearings seizing up. Source and order parts required. Remove Alternator and await replacement.	
Item: 54820 - Diagnose and Repair Coolant Leak				
1/9/2021	1	WASCHUK, AARON	Troubleshoot and Repair Coolant Leak. Balance tube between cores cracked/leaking. Removed and replaced as necessary. Test operation. All okay.	
Item: 54609 - Inspect and Repair Track Gaurds				
1/6/2021	2	WASCHUK, AARON	Inspect and Repair Track Gaurd as Necessary. (bolts broken/missing)	
Item: 54541 - Replace ripper shank				
1/20/2021	1.5	SZYBUNKA, EDWARD	Pin fell out and ripper shank fell out, look for pin and shank, found pin and shank used crane and picked up shank, bring dozer to service truck. Lift shank into place and install pin and weld to 5/8" bolts to pin.	
1/5/2021	2	SZYBUNKA, EDWARD	replace ripper shank	
1/5/2021	1	RIEHL, NATHAN	ripper shank fell out	
Item: 54355 - Replace Segments				
1/7/2021	2	SZYBUNKA, EDWARD	Replace cornor bits and flip edges and ripper teeth	
1/4/2021	6	WASCHUK, AARON	Re and Re Segments and Track assembly. Torque all to OEM spec. Return to service.	
1/3/2021	9	WASCHUK, AARON	Split Tracks/Remove Gaurds and Replace RH Segments. Extract Broken Bolts for Gaurds.	
Item: 54354 - Inspect and Repair Engine Noise (Idler Hub Failing)				
1/3/2021	3	WASCHUK, AARON	Assemble Fan Idler and Install on machine.	
1/1/2021	3	WASCHUK, AARON	Disassemble Fan Idler/Source Parts	
VO: 39919 - Re and Re Ripper Shank (9514 HR)				Closed
Item: 53380 - Re and Re Ripper Shank				
12/17/2020	2	WASCHUK, AARON	Locate Ripper Shank. Travel to the machine and install as necessary.	
VO: 38710 - November Running Repairs - Lynx Creek (9374 HR)				Closed
Item: 51864 - Ripper shank				
11/29/2020	2	SZYBUNKA, EDWARD	pick up ripper shankand take to unit and install make up pin and install cotter pins.	
VO: 38129 - MOB (9181 HR)				Closed
Item: 51181 - MOB				
201103 - 1442 -				
VO: 37825 - Failed starter (9291 HR)				Closed
Item: 50847 - Failed starter				
11/21/2020	4.5	SZYBUNKA, EDWARD	Re and Re starter, change over crank protection solenoid and change wiring. Install starter and hook up all wiring.	
11/18/2020	1	SZYBUNKA, EDWARD	Bendix only spinned, not engage flywheel. Removed r/h cover and best on starter - unit started. Reported issue to supervision	



01442 [KOMATSU D65PX-17 DOZER]

Equipment History From May 9, 2017 to August 19, 2026

VO: 37229 - 2017 Service History (4595 HR)				Closed
Item: 50186 - 2017 Service History				
2017 - 1442 -				
VO: 36840 - Inspection and prep for work (9181 HR)				Closed
Item: 49754 - Inspection and prep for work				
11/4/2020	2	SZYBUNKA, EDWARD	Inspect for work	
VO: 36664 - INSTALL 2 WAY RADIO (9181 HR)				Closed
Item: 49565 - INSTALL 2 WAY RADIO				
11/3/2020	1.5	SZYBUNKA, EDWARD	Install 2 way radio and test.	
VO: 36616 - Install corner bits (9140 HR)				Closed
Item: 49499 - Install corner bits				
11/1/2020	1	SZYBUNKA, EDWARD	Go to campsite ad remove corner bits and clean frog and bits and install.	
VO: 34259 - install cyd and grease pins (9140 HR)				Closed
Item: 46726 - install cyd and grease pins				
9/11/2020	3	PURCHA, GEORGE (WES)	instal cylinders pop grease pins	
9/11/2020	3	MALANOWICH, CRAIG	install both tilt cyd and grease pin, free up seized pin	
VO: 33330 - get machine bring into shop and cheak over for repairs				Closed
Item: 45594 - get machine bring into shop and cheak over for repairs needed and minor repairs				
8/21/2020	12	SIDOR, JERRY	removed both angel clys to be sent out for repairs	
8/20/2020	2	SIDOR, JERRY	get machine running start to cheak over for repairs needed	
VO: 27439 - Repair incident damage (9140 HR)				Closed
Item: 36969 - Repair incident damage				
Notes:				
2/19/2020	4.5	HODGSON, VAUGHN	Got machine running, can't pull axles to get moved, thinking transmission charge pump is picking up oil	
2/17/2020	6	SPEAGER, ALFRED	Fire up try get to move	
2/12/2020	4	SPEAGER, ALFRED	Fuel froze start won't move	
2/7/2020	4	SPEAGER, ALFRED	Wiring checked	
2/1/2020	4	HANSON, KELSEY	Check over oils	
1/29/2020	4	SPEAGER, ALFRED	Check order parts	
VO: 26526 - Unit shut off during the night, (9060 HR)				Closed
Item: 35580 - Not running, batteries dead				
1/21/2020	3	HANSON, KELSEY	Tighten tracks, repair light whitening, check codes	
1/16/2020	4	ELLERTON, SHAWN	Not running	
VO: 26307 - D Service (8945 HR)				Closed
Item: 35178 - D Service				
VO: 24181 - Frozen solid (9140 HR)				Closed
Item: 32379 - Frozen solid				



01442 [KOMATSU D65PX-17 DOZER]
Equipment History From May 9, 2017 to August 19, 2026

2/12/2020	2	ELLIOTT, TRAVIS	Boost and cold start	
1/28/2020	7	KRASOWSKI, STEVEN	Remove unit from swamp	
1/15/2020	4	KRASOWSKI, STEVEN	Heat unit to start then force regen	
1/12/2020	2	KRASOWSKI, STEVEN	Ripper teeth	
12/15/2019	3	KRASOWSKI, STEVEN	Boost unit frozen solid	
12/12/2019	3	ELLERTON, SHAWN	Frozen	
VO: 23835 - Broken window (9060 HR)				Closed
Item: 31942 - Broken window				
1/13/2020	3	KRASOWSKI, STEVEN	Replace seat fix arm rest	
12/8/2019	3	ELLERTON, SHAWN	Replace door	
12/6/2019	3	ELLERTON, SHAWN	Window	
VO: 22806 - C - Service (8690 HR)				Closed
Item: 30571 - C - Service				
VO: 22518 - Ice lug (8689 HR)				Closed
Item: 30235 - Ice lug				
11/19/2019	7	PETERS, MICHAEL	Chip out and lug R/S	
11/18/2019	12	PETERS, MICHAEL	Chip and lug out L/S	
VO: 20944 - Mobin (8448 HR)				Closed
Item: 28205 - Mobin				
10/23/2019	3	FENTON, COLBY	Mobin	
VO: 20094 - Service - B (8349 HR)				Closed
Notes: Service - B				
Item: 27165 - Service - B				
Notes: Service - B				
VO: 18742 - Service A (8042 HR)				Closed
Item: 25389 - Service A				
VO: 18131 - Running repairs (8810 HR)				Closed
Item: 28276 - 1442				
Notes: Replace lights, diagnose wiring for lights				
10/24/2019	2.5	FENTON, COLBY	Replace lights	
Item: 24540 - Check edges				
12/2/2019	2	KRASOWSKI, STEVEN	Lights	
11/28/2019	3	KRASOWSKI, STEVEN	Edges	
10/7/2019	5	HODGSON, VAUGHN	Change edges	
9/6/2019	3	ESSIAMBRE, CHAD	Install blade and winch cable	
9/3/2019	4	HODGSON, VAUGHN	Edges and misc small jobs	
9/2/2019	6	HODGSON, VAUGHN	Track guard falling off	
8/23/2019	1.5	WRUBLESKI, JONATHAN	Check all dozer edges on site	



01442 [KOMATSU D65PX-17 DOZER]

Equipment History From May 9, 2017 to August 19, 2026

VO: 18020 - Service - D (7864 HR)				Closed
Item: 24390 - Service - D				
Notes: Service - D				
VO: 16121 - Mob (7560 HR)				Closed
Item: 21605 - Mob				
VO: 14261 - cut off ice lug (7466 HR)				Closed
Item: 19238 - cut off ice lug				
6/10/2019	3	MALANOWICH, CRAIG	cut ice lugs off track	