



F1006 [CMI C250 HURRICANE MULCHER]
Equipment History From September 11, 2024 to August 20, 2026

R04-57
SEP

VO: 220083 - 250HR SERVICE DONE AT DEEP REDUCTION MECH				Closed
Notes: GREASED UNIT, CHANGED ENG OIL, FINAL DRIVE OIL, CAB AND ENG OIL FILTER				
Item: 241483 - 250HR SERVICE DONE AT DEEP REDUCTION MECH				
260720 - F1006 -				
VO: 220084 - (500) SERVICE PROGRAM - MULCHERS				Open
Item: 241484 - (500) SERVICE PROGRAM - MULCHERS				
VO: 212000 - OFF RENT DEFICIENCIES (Mid-Lite)				Open
Item: 233299 - OFF RENT DEFICIENCIES (Mid-Lite)				
VO: 211915 - END OF RENTAL INSPECTION (1640 HR)				Closed
Notes: MIDLITE -> TCG				
Item: 233209 - END OF RENTAL INSPECTION				
260313-F1006-END				
VO: 211258 - Replace suction control valve				Open
Item: 232550 - Replace suction control valve				
3/7/2026	10	BEISEL, JASON	Test run machine Replace scv valve and check valve Set up door latch Set up and reinstall door seal on roof vent Repaired hyd leak	
VO: 210511 - START OF RENTAL INSPECTION (1384 HR)				Closed
Notes: TCG -> MIDLITE				
Item: 231801 - START OF RENTAL INSPECTION				
260219-F1006-				
VO: 205118 - No 2 speed				Open
Item: 226380 - No 2 speed				
12/14/2025	4	MACLEOD, CONNOR	Had to go to wash bay to jack cab back down after unit was done being washed, installed 2 new headlights, installed belly pans back on unit	
12/13/2025	4	MACLEOD, CONNOR	2 speed wasn't working, repaired wiring, stripped panels and jacked up cab for was	
12/13/2025	7	GOLOS, SCOTT	No 2 speed Repair wiring for 2 speed Test Remove panel and lift cab for washing	
VO: 205215 - JOINT RENTAL INSPECTION (1384 HR)				Closed
Notes: SMS -> MIDLITE CONSTRUCTION				
Item: 225455 - JOINT RENTAL INSPECTION				
251129-F1006-				
VO: 201783 - No 2 way or lights				Open
Item: 223020 - No 2 way or lights				



F1006 [CMI C250 HURRICANE MULCHER]
Equipment History From September 11, 2024 to August 20, 2026

10/26/2025	4	SYMINGTON, TYRELL	Drove to unit no 2 way. Installed head unit. Existing power wires too short. Built extension. Tested unit wouldn't power up. Found blown fuse replaced fuse treated unit. Fuse would blow everytime positive connection was made. Had to run own power source. Didn't have fuse holder. Cut old fuse holder out from ground wire made harness ran wires hooked up wires properly in slots on headliner for power sources. Tested 2 way and lights. Both function properly.	
VO: 201738 - Install and plumb mulcher door				Open
Item: 222975 - Install and plumb mulcher door				
10/24/2025	4	GOLOS, SCOTT	Install cylinders and hosing for mulcher head door	
VO: 201686 - Dmob				Open
Item: 222922 - Dmob				
11/29/2025	5	SMITH, KIRK	Demob unit for rental. Top up low coolant. Clean out tracks of frozen dirt so it could be tied down to the lowbed	
10/24/2025	5	MACLEOD, CONNOR	Installed cylinders and plumb mulcher head guard	
10/23/2025	4	MACLEOD, CONNOR	Dmob unit, install and plumb guards	
VO: 201655 - Welding repairs				Open
Item: 222891 - Welding repairs				
10/23/2025	8	MENZIES, TYLER	Cut off old hinges and remove pins install new hinges and install guard to mulcher	
VO: 169154 - Repairs and mob (1353 HR)				Closed
Item: 187504 - Repairs and mob				
10/6/2024	3	BENNETT, SHEA	Install new base for seat	
10/6/2024	3	KAY, CODY	Check oils and check mobile machine all functions were working had to Order fan belt due to wrong. One was ordered first	
9/9/2024	0.5	ELLIOTT, TRAVIS	Look up and order parts	
9/4/2024	2	ELLIOTT, TRAVIS	Repair all wiring to front lights. Run ground wire into control dash rather than grounding through light brackets. Clean up and tie up wiring	
9/3/2024	5	ELLIOTT, TRAVIS	Clean up wiring in cab. Drop control panel. Remove panels. Tilt cab. Run 2-way wiring through rops with machine harness. Replace hardware with washers. Remove and clean battery tray. Secure batteries. Clean up hoses under cab. Separate to prevent rubbing. Tie up pressure gauge test lines. Tie up harnesses in engine bay. Reassemble cab interior. Adjust access panel hinges.	
8/21/2024	4	HANSON, KELSEY	Tidy up machines leaks. Cap off misc lines and cyclinders not being used. Bolt down the cab. Repair lights and look over machine to ok for work.	
VO: 169156 - Remove mulcher gate (1353 HR)				Closed
Item: 187506 - Remove mulcher gate				
9/11/2024	9	HANSON, KELSEY	Remove gate. Inspections	
8/26/2024	3	HANSON, KELSEY	Cap of winch lines. Grease machine.	
8/20/2024	6	HANSON, KELSEY	Remove mulcher gate and hyd cylinders. Cap off misc hyd lines	



F1006 [CMI C250 HURRICANE MULCHER]
Equipment History From September 11, 2024 to August 20, 2026

VO: 167857 - Inspection after purchase / General repairs (1353 HR)				Closed
Item: 186137 - Inspection after purchase / General repairs				
9/21/2024	3	BEISEL, JASON	Install teeth and switch covers	
7/29/2024	4	MOGG, ERIC	Complete inspection after purchase. Go over machine and fill out inspection. Mark cracks on machine. See paperwork for details. (Rmt302)	