



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8203
Invoice Number:
PO Number:

H15-1
SEP

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Feb 18, 2026 3:21 PM	#41 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X3HJ988601
Actual Start Date:	Wed, Feb 18, 2026 3:21 PM	License Plate:	
Expected Completion Date:		Operator:	Matthew Toews
Actual Completion Date:	Thu, Feb 19, 2026	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,005,561km
Status:	Completed	Secondary Meter:	23,394hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Truck Preventative Maintenance Inspection	\$42.00	\$0.00	\$42.00
Roper Gorgichuk (Contact)	1 hr \$42.00		\$42.00
Engine Oil & Filter Replacement	\$10.50	\$363.76	\$374.26
Roper Gorgichuk (Contact)	0.25 hrs \$42.00		\$10.50
MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	44 L \$6.88		\$302.72
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$61.04		\$61.04
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$7.25	\$0.00	\$7.25

Item		Labor	Parts	Subtotal
Chad Caouette (Contact) 0.25 hrs \$29.00				\$7.25
↳ Check Diff and Trans Oil		\$7.25	\$0.00	\$7.25
Chad Caouette (Contact) 0.25 hrs \$29.00				\$7.25
↳ Inspect and Service Trailer Hitch		\$7.25	\$0.00	\$7.25
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
Chad Caouette (Contact) 0.25 hrs \$29.00				\$7.25
↳ Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
Allan Bates (Contact) 0.25 hrs \$31.00				\$7.75
↳ Torque Wheels		\$7.25	\$0.00	\$7.25
Verify wheels are properly torqued				
Chad Caouette (Contact) 0.25 hrs \$29.00				\$7.25
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00				\$22.50
↳ Grease Unit		\$7.25	\$4.67	\$11.92
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
Chad Caouette (Contact) 0.25 hrs \$29.00				\$7.25
MNACHV259119-652 (Part) · Main 1 ea \$4.67				\$4.67
STARPLEXEP1 WinterGREASE				
🔧 air dryer cartridge		\$10.50	\$25.43	\$35.93
Roper Gorgichuk (Contact) 0.25 hrs \$42.00				\$10.50
950011-G3 (Part) · Main 1 ea \$25.43				\$25.43
Fleet Spec Air Dryer Cartridge Same As ABPN1335130010860				
🔧 Fuel Filters Replacement		\$10.50	\$110.29	\$120.79
Roper Gorgichuk (Contact) 0.25 hrs \$42.00				\$10.50

Item	Labor	Parts	Subtotal
BALPF46081 (Part) - Main (Archived) BALDWIN FUEL FILTER	1 ea		\$45.27
	\$45.27		
NTXDBF6776 (Part) - Main FUEL FILTER SPIN ON S/AS BF46129	1 ea		\$65.02
	\$65.02		

DESCRIPTION

SUMMARY

Subtotal	\$644.15
Labor	\$140.00
Parts	\$504.15
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$644.15

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#15928 trailer work lights flickering Reported Feb 17, 2026 by Matthew Toews trailer work lights not working properly possibly the plug on the truck side		
#15902 produced heat coming up with f14 not firing have to start manually Reported Feb 13, 2026 by Matthew Toews		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7618
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Nov 26, 2025 2:16 PM	#41 2017 Kenworth W900
Scheduled Start Date:		VIN/SN: 1XKWD40X3HJ988601
Actual Start Date:	Wed, Nov 26, 2025 2:16 PM	License Plate:
Expected Completion Date:		Operator: Matthew Toews
Actual Completion Date:	Thu, Nov 27, 2025	Type: Tandem
Duration:	1 day	Group:
Repair Priority Class:	Scheduled	Odometer: 1,000,016km
Status:	Completed	Secondary Meter: 23,196hr
Issued By:	Kurt Kerekanich	
Assigned to:		
Vendor:		
Labels:		

LINE ITEMS

Item	Labor	Parts	Subtotal
 Front RH bumper light repair	\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact)	0.25 hrs		\$7.00
 Installed used grommet	\$28.00		
 #14715 · passenger side running light out signal still working			
 #14777 · [Inspection] Clearance Lights Generated by the failed inspection item "Clearance Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Nov 26, 2025 at 3:26 PM MST			
 #14776 · [Inspection] Signal Lights Generated by the failed inspection item "Signal Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Nov 26, 2025 at 3:26 PM MST			
 cab light repair	\$14.00	\$60.70	\$74.70
 Ricky Peters (Contact)	0.5 hrs		\$14.00
 Installed one new cab light in front Rh, Rear RH.	\$28.00		
 FGRTLEDCAB (Part) · Main CAB LIGHT LED 42 DIO	2 ea \$30.35		\$60.70

Item	Labor	Parts	Subtotal
 Front RH fender light repair	\$14.00	\$0.00	\$14.00
 Ricky Peters (Contact)  0.5 hrs			\$14.00
 Repaired corroded wires.  \$28.00			
 #14715 · passenger side running light out signal still working			
 #14777 · [Inspection] Clearance Lights Generated by the failed inspection item "Clearance Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Nov 26, 2025 at 3:26 PM MST			
 #14776 · [Inspection] Signal Lights Generated by the failed inspection item "Signal Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Nov 26, 2025 at 3:26 PM MST			
 Truck Preventative Maintenance Inspection	\$30.75	\$0.00	\$30.75
 Kurt Kerekanich (Contact)  0.75 hrs			\$30.75
  \$41.00			
 #14775 · [Inspection] Winter Front Clips Generated by the failed inspection item "Winter Front Clips" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Nov 26, 2025 at 3:26 PM MST			
 Engine Oil & Filter Replacement	\$0.00	\$0.00	\$0.00
 No change due sticker put on window			
 Air System Leaks	\$21.00	\$180.34	\$201.34
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
 Ricky Peters (Contact)  0.75 hrs			\$21.00
 Installed new quick release  \$28.00			
 FGRPC14696B (Part) · Main  1 ea			\$6.40
 1/4"X3/8" PUSH TO CON  \$6.40			
 FGRPC146810C (Part) · Main  2 ea			\$23.40
 5/8 PIPE TO 3/8 PUSH  \$11.70			
 FGR112C (Part) · Main  1 ea			\$0.94
 BRASS CLOSE NIPPLE 3  \$0.94			
 BENOR289714X (Part) · Main  1 ea			\$148.15
 Truck Quick Release Valve  \$148.15			
 FGR120CB (Part) · Main  1 ea			\$1.45
 ADAPTER 3/8 X 1/4  \$1.45			
 Check Diff and Trans Oil	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)  0.25 hrs			\$9.75
  \$39.00			

Item	Labor	Parts	Subtotal
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.00	\$0.00	\$9.00
👤 JOE NEMEC (Contact)	0.1 hrs \$90.00		\$9.00
↳ Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
👤 Allan Bates (Contact)	0.25 hrs \$31.00		\$7.75
↳ Torque Wheels Verify wheels are properly torqued	\$9.75	\$0.00	\$9.75
👤 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.50	\$4.67	\$24.17
👤 Joseph Pitney (Contact)	0.5 hrs \$39.00		\$19.50
🔧 MNACHV259119-652 (Part) - Main STARPLEX EP1 Winter GREASE	1 ea \$4.67		\$4.67

DESCRIPTION

SUMMARY

Subtotal	\$410.71
Labor	\$165.00
Parts	\$245.71
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$410.71

Issue	Assigned	Due
#14774 [Inspection] Stack Bushings Reported 9 months ago by Kurt Kerekanich • Truck Preventative Maintenance Checklist by Kurt Kerekanich Generated by the failed inspection item "Stack Bushings" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Nov 26, 2025 at 3:26 PM MST		
#14653 coolant leak Reported Nov 18, 2025 by Matthew Toews coolant leak looks to be coming off the rad somewhere noticed the leak after engine heater ran seams to have stopped for now.		
#14638 cab light passenger side is out Reported Nov 17, 2025 by Matthew Toews		
#13759 smooth talker arm broken Reported Sep 11, 2025 by Stephen Noel smooth talker phone holder doesn't hold a phone have to use an elastic to keep phone in place		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7511
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Nov 5, 2025 2:05 PM	#41 2017 Kenworth W900
Scheduled Start Date:		VIN/SN: 1XKWD40X3HJ988601
Actual Start Date:	Wed, Nov 5, 2025 2:05 PM	License Plate:
Expected Completion Date:		Operator: Matthew Toews
Actual Completion Date:	Thu, Nov 6, 2025	Type: Tandem
Duration:	1 day	Group:
Repair Priority Class:	Scheduled	Odometer: 988,537km
Status:	Completed	Secondary Meter: 23,002hr
Issued By:	JOE NEMEC	
Assigned to:		
Vendor:		
Labels:		

LINE ITEMS

Item	Labor	Parts	Subtotal
 Cab Light Lhs Out	\$10.00	\$30.35	\$40.35
 Ernesto Ablog (Contact)	0.25 hrs \$40.00		\$10.00
 FGRTLEDCAB (Part) - Main CAB LIGHT LED 42 DIO	1 ea \$30.35		\$30.35
 Hydraulic Filter Replacement	\$7.25	\$36.01	\$43.26
 Chad Caouette (Contact)	0.25 hrs \$29.00		\$7.25
 BALPT9187 (Part) - Main HYDRAULIC COOLER FILT S/AS FGR350001	1 ea \$36.01		\$36.01
 Compressor Stainless Line Clamp	\$10.00	\$0.00	\$10.00
 Ernesto Ablog (Contact)	0.25 hrs \$40.00		\$10.00
 Replaced clamp			
 Truck Preventative Maintenance Inspection	\$30.00	\$0.00	\$30.00

Item	Labor	Parts	Subtotal
Ernesto Ablog (Contact) 0.75 hrs \$40.00			\$30.00
Clutch Brake Replacement	\$20.00	\$0.00	\$20.00
Ernesto Ablog (Contact) 0.5 hrs \$40.00 Removed clutch brake and checked,still good			\$20.00
Engine Heater Repair F30	\$120.00	\$136.20	\$256.20
Ernesto Ablog (Contact) Replaced fan motor and installed tried and F 52 fault code replaced igniter and running good 3 hrs \$40.00			\$120.00
PWR25.2106.01.1300 (Part) · Main 1 ea \$110.22 ESPAR GLOW PIN 12VD5			\$110.22
PWR20.1820.99.0001.0A (Part) · Main 1 ea \$25.98 ESPAR FAN GASKET			\$25.98
Engine Oil & Filter Replacement	\$10.00	\$360.08	\$370.08
Ernesto Ablog (Contact) 0.25 hrs \$40.00			\$10.00
NXTDBL7900 (Part) · Main 1 ea \$61.04 OIL FILTER HIGH EFFICIENCY S/AS BD50000			\$61.04
MXF5W40 (Part) · Main 42 L \$7.12 ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER			\$299.04
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$14.00	\$49.73	\$63.73
Ricky Peters (Contact) 0.5 hrs \$28.00 Installed new unloader hose			\$14.00
GWKG50-1064-04-016 (Part) · Main 1 ea \$49.73 UNLOADER HOSE ASSEMBLY S/AS K342-255-016			\$49.73
Check Diff and Trans Oil	\$7.25	\$0.00	\$7.25
Chad Caouette (Contact) 0.25 hrs \$29.00			\$7.25
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$7.25	\$0.00	\$7.25

Item	Labor	Parts	Subtotal
 Chad Caouette (Contact)  ✓	0.25 hrs \$29.00		\$7.25
 Tire Condition and Pressure Inspection Check all tires	\$6.25	\$0.00	\$6.25
 Jayden Binet (Contact)	0.25 hrs \$25.00		\$6.25
 Torque Wheels Verify wheels are properly torqued	\$7.25	\$0.00	\$7.25
 Chad Caouette (Contact)  ✓	0.25 hrs \$29.00		\$7.25
 Walk Around Inspection	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00

DESCRIPTION

SUMMARY

Subtotal	\$891.12
Labor	\$278.75
Parts	\$612.37
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$891.12

Issue	Assigned	Due
#14474 engine heater has loud noise while running Reported Nov 4, 2025 by Matthew Toews loud humming noise not ideal while resetting		
#14500 [Inspection] Clearance Lights Reported 10 months ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Clearance Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Nov 5, 2025 at 3:39 PM MST		
#14499 [Inspection] Clutch Brake Condition Reported 10 months ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Clutch Brake Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Nov 5, 2025 at 3:39 PM MST		
#14498 [Inspection] Hydraulic Oil Level Reported 10 months ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Nov 5, 2025 at 3:39 PM MST		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7419
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Oct 29, 2025 5:00 PM	#41 2017 Kenworth W900	
Scheduled Start Date:	Wed, Oct 29, 2025 5:02 PM	VIN/SN: License Plate:	1XKWD40X3HJ988601
Actual Start Date:	Wed, Oct 29, 2025 5:02 PM	Operator: Type: Group:	Matthew Toews Tandem
Expected Completion Date:			
Actual Completion Date:	Wed, Oct 29, 2025 5:02 PM	Odometer: Secondary Meter:	983,701km 22,908hr
Duration:			
Repair Priority Class:	Non-Scheduled		
Status:	Completed		
Issued By:	Roper Gorgichuk		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Broken bolt exhaust manifold	\$88.50	\$260.32	\$348.82
Roper Gorgichuk (Contact)	0.5 hrs		\$21.00
I helped	\$42.00		
JOE NEMEC (Contact)			\$67.50
Opened hood and could hear leak at idle, could see black streaks from cylinder 6 and top bolt sitting crooked broke off. Removed broken bolt and replaced all manifold bolts and gaskets	0.75 hrs \$90.00		
GWK4965698CUM (Part) - Main	12 ea		\$124.44
MANIFOLD MOUNTING BOLT GENERALLY USED IN SETS OF 12	\$10.37		
GWK5486657CUM (Part) - Main	4 ea		\$106.76
EXHAUST MANIFOLD GASK	\$26.69		
GWK3682940CUM (Part) - Main	1 ea		\$29.12
GASKET- EXHAUST MANIF	\$29.12		

Item	Labor	Parts	Subtotal
------	-------	-------	----------

#14392 · high pitch squealing noise

high pitch squealing noise when accelerating and jaking when there's 20 + pounds of boost best guess is exhaust leak

DESCRIPTION

SUMMARY

Subtotal	\$348.82
Labor	\$88.50
Parts	\$260.32
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$348.82



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7344
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Thu, Oct 16, 2025 10:58 AM	#41 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X3HJ988601
Actual Start Date:	Thu, Oct 16, 2025 10:58 AM	License Plate:	
Expected Completion Date:		Operator:	Matthew Toews
Actual Completion Date:	Thu, Oct 16, 2025 10:58 AM	Type:	Tandem
Duration:		Group:	
Repair Priority Class:	Scheduled	Odometer:	980,231km
Status:	Completed	Secondary Meter:	22,804hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Truck Preventative Maintenance Inspection	\$31.50	\$0.00	\$31.50
Roper Gorgichuk (Contact)	0.75 hrs \$42.00		\$31.50
#14178 · engine heater maintenance required			
#14200 · front diff leaking from diff housing output side			
Inspection plate bolt's broken	\$41.00	\$0.00	\$41.00
Kurt Kerekanich (Contact)	1 hr		\$41.00
Drill out broken bolt and adjusted clutch	\$41.00		
#14252 · [Inspection] Adjust clutch Generated by the failed inspection item "Clutch Brake Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Oct 16, 2025 at 2:46 PM MDT			
A1L Hub Oil	\$21.00	\$3.25	\$24.25
Roper Gorgichuk (Contact)	0.5 hrs \$42.00		\$21.00

Item	Labor	Parts	Subtotal
 FGR3303024 (Part) · Main HUBCAP GASKET 1 ea \$3.25			\$3.25
 #14187 · drivers side steer hub oil still contaminated water in oil			
 Engine Oil & Filter Replacement  No change due	\$0.00	\$0.00	\$0.00
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$10.50	\$0.00	\$10.50
 Roper Gorgichuk (Contact) 0.25 hrs \$42.00			\$10.50
 Check Diff and Trans Oil	\$10.25	\$0.00	\$10.25
 Kurt Kerekanich (Contact) 0.25 hrs \$41.00			\$10.25
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$10.50	\$0.00	\$10.50
 Roper Gorgichuk (Contact) 0.25 hrs \$42.00			\$10.50
 Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
 Torque Wheels Verify wheels are properly torqued	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
 Walk Around Inspection	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$10.25	\$0.00	\$10.25
 Kurt Kerekanich (Contact) 0.25 hrs \$41.00			\$10.25

Item	Labor	Parts	Subtotal
 Head Light Repair	\$10.25	\$0.00	\$10.25
 Kurt Kerekanich (Contact)	0.25 hrs		\$10.25
 fixed broken wire	\$41.00		
 #14253 · [Inspection] Lhs headlight wire Generated by the failed inspection item "Head Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Oct 16, 2025 at 2:46 PM MDT			

DESCRIPTION	SUMMARY	
	Subtotal	\$188.50
	Labor	\$185.25
	Parts	\$3.25
	Labor Markup	+ \$0.00 (0.0%)
	Parts Markup	+ \$0.00 (0.0%)
	Warranty Credits	- \$0.00 (0.0%)
	Discount	- \$0.00 (0.0%)
	Tax	+\$0.00 (0.0%)
	Total	\$188.50



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7313
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Thu, Oct 9, 2025 9:24 AM	#41 2017 Kenworth W900
Scheduled Start Date:		VIN/SN: 1XKWD40X3HJ988601
Actual Start Date:	Thu, Oct 9, 2025 9:24 AM	License Plate:
Expected Completion Date:		Operator: Matthew Toews
Actual Completion Date:	Thu, Oct 9, 2025 9:24 AM	Type: Tandem
Duration:		Group:
Repair Priority Class:	Scheduled	Odometer: 976,595km
Status:	Completed	Secondary Meter: 22,725hr
Issued By:	JOE NEMEC	
Assigned to:		
Vendor:		
Labels:		

LINE ITEMS

Item	Labor	Parts	Subtotal
 Engine Oil & Filter Replacement	\$10.50	\$235.76	\$246.26
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00		\$10.50
 NXTDBL7900 (Part) - Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$61.04		\$61.04
 MXF15W40 (Part) - Main ENGINE OIL, 15W40 BUL	42 L \$4.16		\$174.72

DESCRIPTION

SUMMARY

Subtotal	\$246.26
Labor	\$10.50
Parts	\$235.76
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$246.26



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7217
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Sep 30, 2025 10:33 AM	#41 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X3HJ988601
Actual Start Date:	Tue, Sep 30, 2025 10:33 AM	License Plate:	
Expected Completion Date:		Operator:	N/A
Actual Completion Date:	Thu, Oct 2, 2025	Type:	Tandem
Duration:	2 days	Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	973,141km
Status:	Completed	Secondary Meter:	22,643hr
Issued By:	MICHAEL ABLOG		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Replace 2 wire male	\$10.00	\$6.10	\$16.10
 Ernesto Ablog (Contact)	0.25 hrs \$40.00		\$10.00
 GRO82-1021 (Part) · Main 4 POLE MALE PLUG	1 ea \$6.10		\$6.10
 Truck Preventative Maintenance Inspection	\$22.00	\$0.00	\$22.00
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 CVIP	\$97.75	\$0.00	\$97.75
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 Kurt Kerekanich (Contact)	0.75 hrs \$41.00		\$30.75
 JOE NEMEC (Contact)	0.5 hrs \$90.00		\$45.00

Item	Labor	Parts	Subtotal
 #13971 · CVIP			
 Fuel Pump Actuator	\$22.00	\$445.09	\$467.09
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 GWK4307411RX (Part) · Main FUEL PUMP ACTUATOR	1 ea \$445.09		\$445.09
 #13970 · Fuel pump actuator Failed			
 Engine Heater Repair	\$22.00	\$0.00	\$22.00
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 repaired corroded power wire.			
 #13758 · engine heater not working the preheat engine heater there's no power to it can't set timer			
 #13968 · Engine heater Keeps blowing fuse			
 Unloader Airline Leaking	\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)	0.25 hrs \$44.00		\$11.00
 replaced 1/4" fitting			
 #13969 · Unloader line leaking Air comp unloader airline leaking by frame rail			
 Lh Hood Fender Light	\$22.00	\$110.90	\$132.90
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 GROG5543 (Part) · Main HI COUNT 2 SIDED LED	1 ea \$110.90		\$110.90
 Steer Shocks Replacement	\$22.00	\$194.78	\$216.78
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 GWKB71-6009 (Part) · Main STEER SHOCK	2 ea \$97.39		\$194.78
 Replace Toolbox Latch Lhs	\$20.00	\$26.35	\$46.35
 Ernesto Ablog (Contact)	0.5 hrs \$40.00		\$20.00
 LGM3304804 (Part) · Main DOOR LATCH SS T HANDL	1 ea \$26.35		\$26.35

Item	Labor	Parts	Subtotal
#13780 · tool boxes won't open the tool boxes are locked cannot be unlocked are seized with dirt and dust			
Engine Fan Running Steady	\$11.00	\$0.00	\$11.00
MICHAEL ABLOG (Contact) 0.25 hrs harness clip missing for A/C compressor. zip tied. \$44.00			\$11.00
#13972 · Engine fan On a lot check ac pressure sensor and wiring			
Engine Oil & Filter Replacement No change due	\$0.00	\$0.00	\$0.00
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$11.00	\$0.00	\$11.00
MICHAEL ABLOG (Contact) 0.25 hrs \$44.00			\$11.00
Check Diff and Trans Oil	\$7.00	\$0.00	\$7.00
Ricky Peters (Contact) 0.25 hrs \$28.00			\$7.00
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$11.00	\$0.00	\$11.00
MICHAEL ABLOG (Contact) 0.25 hrs \$44.00			\$11.00
Tire Condition and Pressure Inspection Check all tires	\$25.00	\$0.00	\$25.00
Jayden Binet (Contact) 1 hr \$25.00			\$25.00
Torque Wheels Verify wheels are properly torqued	\$11.00	\$0.00	\$11.00
MICHAEL ABLOG (Contact) 0.25 hrs \$44.00			\$11.00
Walk Around Inspection	\$11.00	\$0.00	\$11.00
MICHAEL ABLOG (Contact) 0.25 hrs \$44.00			\$11.00
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$11.00	\$4.67	\$15.67

Item

Labor

Parts

Subtotal

 MICHAEL ABLOG (Contact)

0.25 hrs

\$11.00

\$44.00

 MNACHV259118-652 (Part) - Main
STARPLEX EP2 TUBE Summer Grease

1 ea

\$4.67

\$4.67

DESCRIPTION

SUMMARY

Subtotal \$1,134.64

Labor \$346.75

Parts \$787.89

Labor Markup + \$0.00 (0.0%)

Parts Markup + \$0.00 (0.0%)

Warranty Credits - \$0.00 (Fixed)

Discount - \$0.00 (0.0%)

Tax +\$0.00 (0.0%)

Total \$1,134.64



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5964
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Mar 19, 2025 1:45 PM	#41 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X3HJ988601
Actual Start Date:	Wed, Mar 19, 2025 1:45 PM	License Plate:	
Expected Completion Date:		Operator:	Stephen Trimble
Actual Completion Date:	Thu, Mar 20, 2025	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	964,927km
Status:	Completed	Secondary Meter:	22,453hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$28.50	\$0.00	\$28.50
 Joseph Pitney (Contact)	0.75 hrs \$38.00		\$28.50
 Adjust Fifth Wheel Jaws	\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact)	0.25 hrs \$38.00		\$9.50
 Left side work light facing out	\$19.00	\$21.95	\$40.95
 Joseph Pitney (Contact)	0.5 hrs \$38.00		\$19.00
 MNALW4232 (Part) · Main WORK LIGHT UNI-BOND	1 ea \$21.95		\$21.95
 Right side bumper light	\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact)	0.25 hrs \$38.00		\$9.50

Item	Labor	Parts	Subtotal
 Clutch linkage loose	\$19.00	\$47.55	\$66.55
 Joseph Pitney (Contact)	0.5 hrs \$38.00		\$19.00
 FGR462ESK4022 (Part) · Main CLUTCH ROD END RH S/A	1 ea \$47.55		\$47.55
 A2L brake shoes	\$28.50	\$67.85	\$96.35
 Joseph Pitney (Contact)	0.75 hrs \$38.00		\$28.50
 FGRXSS504709E2K (Part) · Main BRAKE SHOE DRIVE16.5X	1 ea \$67.85		\$67.85
 replace hydraulic filter	\$9.50	\$34.43	\$43.93
 Joseph Pitney (Contact)	0.25 hrs \$38.00		\$9.50
 BALPT9187 (Part) · Main HYDRAULIC COOLER FILT S/AS FGR350001	1 ea \$34.43		\$34.43
 Secure rubber on body module	\$9.50	\$13.12	\$22.62
 Joseph Pitney (Contact)	0.25 hrs \$38.00		\$9.50
 FGRM593674 (Part) · Main BATTERY BOX WASHER	1 ea \$13.12		\$13.12
 Clean left fuel tank vent	\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact)	0.25 hrs \$38.00		\$9.50
 Engine Oil & Filter Replacement	\$9.50	\$352.96	\$362.46
 Joseph Pitney (Contact)	0.25 hrs \$38.00		\$9.50
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$61.04		\$61.04
 MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	41 L \$7.12		\$291.92
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact)	0.25 hrs \$38.00		\$9.50

Item	Labor	Parts	Subtotal
↳ Check Diff and Trans Oil	\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact) 0.25 hrs \$38.00			\$9.50
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact) 0.25 hrs \$38.00			\$9.50
↳ Tire Condition and Pressure Inspection Check all tires	\$6.00	\$0.00	\$6.00
 Jayden Binet (Contact) 0.25 hrs \$24.00			\$6.00
↳ Torque Wheels Verify wheels are properly torqued	\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact) 0.25 hrs \$38.00			\$9.50
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.00	\$4.67	\$23.67
 Joseph Pitney (Contact) 0.5 hrs \$38.00			\$19.00
 MNACHV259119-652 (Part) - Main STARPLEX EP1 Winter GREASE 1 ea \$4.67			\$4.67

DESCRIPTION

SUMMARY

Subtotal	\$780.03
Labor	\$237.50
Parts	\$542.53
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$780.03

Issue	Assigned	Due
#11695 [Inspection] left breather needs cleaning Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Fuel Tank Breathers" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 20, 2025 at 7:56 AM MDT		
#11696 [Inspection] front hymn loose Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Clutch Linkage Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 20, 2025 at 7:56 AM MDT		
#11698 [Inspection] change filter Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 20, 2025 at 7:56 AM MDT		
#11693 [Inspection] right bumper Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Signal Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 20, 2025 at 7:56 AM MDT		
#11694 [Inspection] DS facing out not working Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Work Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 20, 2025 at 7:56 AM MDT		
#11692 [Inspection] right bumper light out Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Clearance Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 20, 2025 at 7:56 AM MDT		
#11697 [Inspection] A2L brake shoes Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Brake Lining Thickness 5/16"" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 20, 2025 at 7:56 AM MDT		
#11699 [Inspection] needs adjustment Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "5th Wheel and Slider Play" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 20, 2025 at 7:56 AM MDT		
#11654 Signal light Reported Mar 17, 2025 by Stephen Trimble Front bumper PS signal light not working		