



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #6395
Invoice Number:
PO Number:

H15-2
SEP

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, May 27, 2025 4:26 PM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Tue, May 27, 2025 4:26 PM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Thu, May 29, 2025	Type:	Tri Drive
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	683,831km
Status:	Completed	Secondary Meter:	33,517hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Replace left roof marker	\$19.00	\$30.35	\$49.35
Joseph Pitney (Contact)	0.5 hrs \$38.00		\$19.00
FGRTLED CAB (Part) · Main CAB LIGHT LED 42 DIO	1 ea \$30.35		\$30.35
Truck Preventative Maintenance Inspection	\$28.50	\$0.00	\$28.50
Joseph Pitney (Contact)	0.75 hrs \$38.00		\$28.50
Replace left work light	\$19.00	\$21.95	\$40.95
Joseph Pitney (Contact)	0.5 hrs \$38.00		\$19.00
MNALW4232 (Part) · Main WORK LIGHT UNI-BOND	1 ea \$21.95		\$21.95
Adjust Fifth Wheel Jaws	\$9.50	\$0.00	\$9.50

Item	Labor	Parts	Subtotal
Joseph Pitney (Contact) 0.25 hrs \$38.00			\$9.50
Replace washer nozzles	\$19.00	\$35.56	\$54.56
Joseph Pitney (Contact) 0.5 hrs \$38.00			\$19.00
GWKW603 (Part) · Main WINDSHIELD WASHER NOZZLE 2 ea \$17.78			\$35.56
Engine Oil & Filter Replacement	\$9.50	\$223.28	\$232.78
Joseph Pitney (Contact) 0.25 hrs \$38.00			\$9.50
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000 1 ea \$61.04			\$61.04
MXF15W40 (Part) · Main ENGINE OIL 15W40 BUL 39 L \$4.16			\$162.24
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$7.25	\$0.00	\$7.25
Allan Bates (Contact) 0.25 hrs \$29.00			\$7.25
Check Diff and Trans Oil	\$7.25	\$0.00	\$7.25
Allan Bates (Contact) 0.25 hrs \$29.00			\$7.25
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.75	\$0.00	\$9.75
Roper Gorgichuk (Contact) 0.25 hrs \$39.00			\$9.75
Tire Condition and Pressure Inspection Check all tires	\$7.25	\$0.00	\$7.25
Allan Bates (Contact) 0.25 hrs \$29.00			\$7.25
Torque Wheels Verify wheels are properly torqued	\$7.25	\$0.00	\$7.25
Allan Bates (Contact) 0.25 hrs \$29.00			\$7.25

Item	Labor	Parts	Subtotal
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.25	\$4.67	\$11.92
 Allan Bates (Contact) 0.25 hrs \$29.00			\$7.25
 MNACHV259118-652 (Part) · Main STARPLEX EP2 TUBE Summer Grease 1 ea \$4.67			\$4.67

DESCRIPTION

SUMMARY

Subtotal	\$488.81
Labor	\$173.00
Parts	\$315.81
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$488.81

Issue	Assigned	Due
#12456 Hydraulic leak Reported May 27, 2025 by Jake Badger From hydraulic fan cooler reservoir box.		
#12457 Windshield wipers sprayers Reported May 27, 2025 by Jake Badger They keep becoming loose and out of position, sliding/disconnecting.		
#12473 [Inspection] check hydraulic cooler for leaks Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Hydraulic Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on May 28, 2025 at 7:50 AM MDT		
#12472 [Inspection] left work light replace Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Work Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on May 28, 2025 at 7:50 AM MDT		
#12469 [Inspection] adjustment required Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "5th Wheel and Slider Play" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on May 28, 2025 at 7:50 AM MDT		
#12470 [Inspection] replace nozzles Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Windshield Wiper and Spray" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on May 28, 2025 at 7:50 AM MDT		
#12471 [Inspection] left roof marker Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Clearance Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on May 28, 2025 at 7:50 AM MDT		
#12468 [Inspection] low Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on May 28, 2025 at 7:50 AM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #6287
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, May 6, 2025 1:40 PM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Tue, May 6, 2025 1:41 PM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Wed, May 7, 2025	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	680,281km
Status:	Completed	Secondary Meter:	33,369hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Truck Preventative Maintenance Inspection	\$28.50	\$0.00	\$28.50
Ernesto Ablog (Contact)	0.75 hrs \$38.00		\$28.50
Mud Flap Replacement	\$19.00	\$0.00	\$19.00
MICHAEL ABLOG (Contact)	0.5 hrs \$38.00		\$19.00
Hyd.Cooler Leaking	\$57.00	\$0.00	\$57.00
Ernesto Ablog (Contact)	1.5 hrs		\$57.00
Found pressure hose fitting on fan motor.replaced hose (used)	\$38.00		
Coolant Leaks Repair	\$9.50	\$0.00	\$9.50
MICHAEL ABLOG (Contact)	0.25 hrs		\$9.50
tightened clamps and replaced one	\$38.00		
Both Exhaust Pipe Cracked	\$34.38	\$0.00	\$34.38

Item	Labor	Parts	Subtotal
Chad Caouette (Contact) 1.25 hrs welded cracked exhaust pipes \$27.50			\$34.38
A3Lhs Slack 90	\$47.50	\$135.35	\$182.85
Ernesto Ablog (Contact) 1.25 hrs Replaced slack adjuster and zipped cut 1/4 on brake pot rod. \$38.00			\$47.50
FGR40020233 (Part) · Main 1 ea SLACK ADJUSTER 10 SPL \$135.35			\$135.35
Air Dryer Cartridge Replacement	\$9.50	\$22.20	\$31.70
MICHAEL ABLOG (Contact) 0.25 hrs \$38.00			\$9.50
WSTN1335130010860 S/AS AC1001 (Part) · Main (Archived) 1 ea AIR DRYER CARTRIDGE \$22.20			\$22.20
Fuel Filter Replacement	\$19.00	\$109.21	\$128.21
MICHAEL ABLOG (Contact) 0.5 hrs \$38.00			\$19.00
NTXDBF6776 (Part) · Main 1 ea FUEL FILTER SPIN ON S/AS BF46129 \$65.02			\$65.02
BALPF46081 (Part) · Main (Archived) 1 ea BALDWIN FUEL FILTER \$44.19			\$44.19
Lhs Windshield Cracked	\$19.00	\$58.93	\$77.93
MICHAEL ABLOG (Contact) 0.5 hrs \$38.00			\$19.00
GWKDW1164-30 (Part) · Main 1 ea WINDSHIELD, DS \$58.93			\$58.93
Driver Seat Shock	\$19.00	\$0.00	\$19.00
MICHAEL ABLOG (Contact) 0.5 hrs replaced with old seat \$38.00			\$19.00
Lhs Convex Mirror Loose	\$9.50	\$0.00	\$9.50
MICHAEL ABLOG (Contact) 0.25 hrs replaced missing screw. \$38.00			\$9.50
Engine Oil & Filter Replacement Tagged unit as it did not have hours for oil change	\$0.00	\$0.00	\$0.00
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.50	\$0.00	\$9.50

Item		Labor	Parts	Subtotal
 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00			\$9.50
 Check Diff and Trans Oil		\$6.88	\$0.00	\$6.88
 Chad Caouette (Contact)	0.25 hrs \$27.50			\$6.88
 Inspect and Service Trailer Hitch		\$9.50	\$0.00	\$9.50
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00			\$9.50
 Tire Condition and Pressure Inspection		\$7.25	\$0.00	\$7.25
Check all tires				
 Allan Bates (Contact)	0.25 hrs \$29.00			\$7.25
 Torque Wheels		\$6.88	\$0.00	\$6.88
Verify wheels are properly torqued				
 Chad Caouette (Contact)	0.25 hrs \$27.50			\$6.88
 Walk Around Inspection		\$9.50	\$0.00	\$9.50
 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00			\$9.50
 Grease Unit		\$9.50	\$4.67	\$14.17
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00			\$9.50
 MNACHV259118-652 (Part) - Main	1 ea			\$4.67
STARPLEX EP2 TUBE Summer Grease				\$4.67
 Ps work light		\$13.75	\$0.00	\$13.75
 Chad Caouette (Contact)	0.5 hrs			\$13.75
 found broken wire for work light repaired				\$27.50
 Air Dryer Purge Valve Replacement		\$13.75	\$134.95	\$148.70
 Chad Caouette (Contact)	0.5 hrs			\$13.75
 replaced purge valve				\$27.50
 BENK022105 (Part) - Main	1 ea			\$134.95
AD-IP VALVE PURGE				\$134.95

DESCRIPTION

SUMMARY

Subtotal	\$823.70
Labor	\$358.39
Parts	\$465.31
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$823.70

Issue	Assigned	Due
#12252 Work light Reported May 6, 2025 by Jake Badger Passenger side not working properly, will work and then will not work. Needs to be fixed/replaced.		
#12257 Driver seat Reported May 6, 2025 by Jake Badger Shock out of place, top part not connected properly.		
#12242 Coolant Reported May 6, 2025 by Jake Badger Kept having low fluid, needed to add.		
#12238 Mud flap Reported May 6, 2025 by Jake Badger Passenger rear needs to be replaced. Damaged.		
#12137 Driver side round mirror Reported Apr 26, 2025 by Jake Badger Worn out, won't stay in any position, very loose and wobbly		
#12136 Hydraulic fan cooler box Reported Apr 26, 2025 by Jake Badger Leaking while loading and especially while unloading		
#12239 Fuel gauge Reported May 6, 2025 by Jake Badger Accurate/inaccurate. Will work properly, then won't, will show less than there actually is, and will also show empty with gas light on when the truck is not close to being empty. Needs to be fixed/replaced.		
#12256 Steering/suspension components Reported May 6, 2025 by Jake Badger There's been some noise/play every so often, mostly during bumpy road conditions, and some turns.		
#12197 Driver side windshield Reported May 1, 2025 by Jake Badger Very bad rock chip/cracks		
#12274 [Inspection] Air Dryer Condition Reported over 1 year ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Air Dryer Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on May 6, 2025 at 3:30 PM MDT		
#12273 [Inspection] Hydraulic Oil Level Reported over 1 year ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on May 6, 2025 at 3:30 PM MDT		

- #12272 [Inspection] Windshields
Reported over 1 year ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog
Generated by the failed inspection item "Windshields" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on May 6, 2025 at 3:30 PM MDT
- #12271 [Inspection] Seats
Reported over 1 year ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog
Generated by the failed inspection item "Seats" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on May 6, 2025 at 3:30 PM MDT
- #12270 [Inspection] Mirrors
Reported over 1 year ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog
Generated by the failed inspection item "Mirrors" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on May 6, 2025 at 3:30 PM MDT
- #12269 [Inspection] Hydraulic Leaks
Reported over 1 year ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog
Generated by the failed inspection item "Hydraulic Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on May 6, 2025 at 3:30 PM MDT
- #12268 [Inspection] Exhaust Leaks
Reported over 1 year ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog
Generated by the failed inspection item "Exhaust Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on May 6, 2025 at 3:30 PM MDT
- #12267 [Inspection] Slack Adjusters
Reported over 1 year ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog
Generated by the failed inspection item "Slack Adjusters" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on May 6, 2025 at 3:30 PM MDT
- #12250 ABS
Reported May 6, 2025 by Jake Badger
Indicators on in cluster
- #12003 [Inspection] Adjust free play
Reported over 1 year ago by Roper Gorgichuk • Truck Preventative Maintenance Checklist by Roper Gorgichuk
Generated by the failed inspection item "Clutch Free Play" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Apr 16, 2025 at 8:09 AM MDT



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #6147
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Apr 15, 2025 2:53 PM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Tue, Apr 15, 2025 2:53 PM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Thu, Apr 17, 2025	Type:	Tri Drive
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	677,260km
Status:	Completed	Secondary Meter:	33,234hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Convex Mirror Replacement Replace Convex Mirror	\$19.50	\$41.40	\$60.90
 Roper Gorgichuk (Contact)	0.5 hrs \$39.00		\$19.50
 GWKSH8S01FH (Part) · Main CONVEX MIRROR 8"	1 ea \$41.40		\$41.40
 hydraulic oil low	\$78.00	\$1,660.58	\$1,738.58
 Roper Gorgichuk (Contact)  Drain oil and replaced filter. Filled and ran hydraulics. Replaced orbital on the trailer.	2 hrs \$39.00		\$78.00
 FLO151B2051 (Part) · Main DANFOSS PUMP, LARGE #12 ORB Ports	1 ea \$1,557.63		\$1,557.63
 MNACHV255675-448 (Part) · Main AW32 HYDRAULIC OIL	25 L \$3.57		\$89.25

Item	Labor	Parts	Subtotal
 BALBT8443 (Part) · Main HYDRAULIC FILTER GARD S/AS P565059	1 ea \$13.70		\$13.70
 #12001 · [Inspection] Hydraulic oil low Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Apr 16, 2025 at 8:09 AM MDT			
 Truck Preventative Maintenance Inspection	\$39.00	\$13.99	\$52.99
 Roper Gorgichuk (Contact)	1 hr \$39.00		\$39.00
 NAPGOP9210W (Part) · Main LED MINI BULB	1 ea \$13.99		\$13.99
 Windshield Washer System Inspect	\$5.85	\$0.00	\$5.85
 Roper Gorgichuk (Contact)  Fixed the nozzle	0.15 hrs \$39.00		\$5.85
 #12005 · [Inspection] Windshield spray nozzle on the DS Generated by the failed inspection item "Windshield Wiper and Spray" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Apr 16, 2025 at 8:09 AM MDT			
 Adjust Clutch Freeplay	\$58.50	\$0.00	\$58.50
 Roper Gorgichuk (Contact)	1.5 hrs \$39.00		\$58.50
 #12002 · [Inspection] Adjust clutch Generated by the failed inspection item "Clutch Brake Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Apr 16, 2025 at 8:09 AM MDT			
 adjust clutch brake gap	\$9.75	\$0.00	\$9.75
 Roper Gorgichuk (Contact)	0.25 hrs \$39.00		\$9.75
 #12002 · [Inspection] Adjust clutch Generated by the failed inspection item "Clutch Brake Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Apr 16, 2025 at 8:09 AM MDT			
 Replace tie rod assembly	\$68.25	\$382.35	\$450.60
 Roper Gorgichuk (Contact)	1.75 hrs \$39.00		\$68.25
 FGRQT108SB (Part) · Main TIE ROD CROSS TUBE ASSEMBLY S/AS GWK220TR129	1 ea \$382.35		\$382.35
 #12004 · [Inspection] Tie rod ends have play Generated by the failed inspection item "Tire Rod and Ends" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Apr 16, 2025 at 8:09 AM MDT			
 Engine Oil & Filter Replacement	\$7.25	\$223.28	\$230.53

Item		Labor	Parts	Subtotal
Allan Bates (Contact)	0.25 hrs \$29.00			\$7.25
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$61.04			\$61.04
MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL	39 L \$4.16			\$162.24
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$7.25	\$0.00	\$7.25
Allan Bates (Contact)	0.25 hrs \$29.00			\$7.25
Check Diff and Trans Oil		\$7.25	\$0.00	\$7.25
Allan Bates (Contact)	0.25 hrs \$29.00			\$7.25
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$6.25	\$0.00	\$6.25
Ricky Peters (Contact)	0.25 hrs \$25.00			\$6.25
Tire Condition and Pressure Inspection Check all tires		\$7.25	\$0.00	\$7.25
Allan Bates (Contact)	0.25 hrs \$29.00			\$7.25
Torque Wheels Verify wheels are properly torqued		\$9.75	\$0.00	\$9.75
Roper Gorgichuk (Contact)	0.25 hrs \$39.00			\$9.75
Walk Around Inspection		\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$7.25	\$0.00	\$7.25
Allan Bates (Contact)	0.25 hrs \$29.00			\$7.25
exhaust pipe missing bolt on heat shield		\$6.88	\$0.00	\$6.88

Item	Labor	Parts	Subtotal
Chad Caouette (Contact) missing bolt on RHS replaced bolt	0.25 hrs		\$6.88
	\$27.50		

DESCRIPTION	SUMMARY
	Subtotal Labor Parts Labor Markup Parts Markup Warranty Credits Discount Tax Total
	\$2,682.08 \$360.48 \$2,321.60 + \$0.00 (0.0%) + \$0.00 (0.0%) - \$0.00 (0.0%) - \$0.00 (0.0%) +\$0.00 (0.0%) \$2,682.08

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#11977 Hydraulic reservoir box Reported Apr 15, 2025 by Jake Badger Located behind truck cab, is leaking somewhere.		
#11979 Passenger exhaust stack Reported Apr 15, 2025 by Jake Badger Located vertically beside passenger side of truck cab, makes a noise of something rattling in or around it, also sounds like loose rattling debris inside of it somewhere. Mostly only makes this sound with high pressure exhaust.		
#11978 Driver side round mirror Reported Apr 15, 2025 by Jake Badger Loose or broken, does not stay in place.		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #6075
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Apr 2, 2025 2:16 PM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Wed, Apr 2, 2025 2:16 PM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Wed, Apr 2, 2025 2:16 PM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Scheduled	Odometer:	674,096km
Status:	Completed	Secondary Meter:	33,060hr
Issued By:	Roper Gorgichuk		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
engine heater repair Diagnosis and repair engine heater.	\$58.50	\$2.20	\$60.70
Roper Gorgichuk (Contact)	1.5 hrs		\$58.50
Ended up running a wire from the battery box to the heater	\$39.00		
GRO82-2166 (Part) · Main FUSE HOLDER	1 ea \$2.20		\$2.20

DESCRIPTION

SUMMARY

Subtotal	\$60.70
Labor	\$58.50
Parts	\$2.20
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$60.70



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5996
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Mar 26, 2025 10:30 AM	#27 2015 Kenworth T800	
Scheduled Start Date:	Wed, Mar 26, 2025 10:29 AM	VIN/SN: License Plate:	1XKDP4EX1FR972824
Actual Start Date:	Wed, Mar 26, 2025 10:30 AM	Operator: Type: Group:	Jake Badger Tri Drive
Expected Completion Date:			
Actual Completion Date:	Mon, Mar 31, 2025	Odometer: Secondary Meter:	674,095km 33,060hr
Duration:	5 days		
Repair Priority Class:	Scheduled		
Status:	Completed		
Issued By:	Joseph Pitney		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 LS air cleaner light 2nd from bottom	\$6.25	\$8.45	\$14.70
 Ricky Peters (Contact)	0.25 hrs \$25.00		\$6.25
 FGR12716002A (Part) - Main JETCO 2" AMBER LED FORT GARY NOT SELLING ANYMORE	1 ea \$8.45		\$8.45
 S cam tube ubolt s loose A2R. A3 both A4 both	\$19.00	\$11.00	\$30.00
 Joseph Pitney (Contact)	0.5 hrs \$38.00		\$19.00
 FGRMUC25R (Part) - Main MUFFLER CLAMP 2 1/2	4 ea \$2.75		\$11.00
 DS windshield replace	\$19.00	\$53.30	\$72.30
 Joseph Pitney (Contact)	0.5 hrs \$38.00		\$19.00

Item		Labor	Parts	Subtotal
 GWKDW1164-30 (Part) · Main WINDSHIELD, DS	1 ea \$53.30			\$53.30
 RS hood marker only couple leds left change		\$25.00	\$0.00	\$25.00
 Ricky Peters (Contact)  Wired in used light on front.	1 hr \$25.00			\$25.00
 Truck Preventative Maintenance Inspection		\$28.50	\$0.00	\$28.50
 Joseph Pitney (Contact)	0.75 hrs \$38.00			\$28.50
 Engine Oil & Filter Replacement		\$6.25	\$352.96	\$359.21
 Ricky Peters (Contact)	0.25 hrs \$25.00			\$6.25
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$61.04			\$61.04
 MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER\$7.12	41 L \$291.92			\$291.92
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact)	0.25 hrs \$38.00			\$9.50
 Check Diff and Trans Oil		\$19.00	\$0.00	\$19.00
 Joseph Pitney (Contact)  A3 diff down 7 litres of fluid	0.5 hrs \$38.00			\$19.00
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact)	0.25 hrs \$38.00			\$9.50
 Tire Condition and Pressure Inspection Check all tires		\$7.25	\$0.00	\$7.25
 Allan Bates (Contact)	0.25 hrs \$29.00			\$7.25
 Torque Wheels Verify wheels are properly torqued		\$7.25	\$0.00	\$7.25

Item		Labor	Parts	Subtotal
 Allan Bates (Contact)	0.25 hrs \$29.00			\$7.25
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$19.00	\$4.67	\$23.67
 Joseph Pitney (Contact)	0.5 hrs \$38.00			\$19.00
 MNACHV259119-652 (Part) · Main STARPLEX EP1 Winter GREASE	1 ea \$4.67			\$4.67

DESCRIPTION

SUMMARY

Subtotal	\$628.38
Labor	\$198.00
Parts	\$430.38
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$628.38

Issue	Assigned	Due
#11769 [Inspection] DS wind shield replace Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Windshields" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 26, 2025 at 11:33 AM MDT		
#11772 [Inspection] A2R A3 both A4 both s cam bolts loose Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Scam and Bushings" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 26, 2025 at 11:33 AM MDT		
#11771 [Inspection] RS work light out Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Work Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 26, 2025 at 11:33 AM MDT		
#11770 [Inspection] left air cleaner light 2nd from bottom RS hood marker light Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Clearance Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 26, 2025 at 11:33 AM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5962
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Mar 19, 2025 11:16 AM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Wed, Mar 19, 2025 11:16 AM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Wed, Mar 19, 2025 11:16 AM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	672,562km
Status:	Completed	Secondary Meter:	32,986hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Dash Cam Repair	\$18.00	\$0.00	\$18.00
 JOE NEMEC (Contact)	0.2 hrs		\$18.00
 Replaced missing SD card	\$90.00		
 Replace PTO and Gearpump	\$261.00	\$2,831.70	\$3,092.70
 Ernesto Ablog (Contact)	2 hrs		\$76.00
 Rebuilt PTO	\$38.00		
 JOE NEMEC (Contact)			\$90.00
 Replaced hydraulic filter, helped cycle hydraulics and wash off mess from oil foaming over.			
	1 hr		
	\$90.00		
 Kurt Kerekanich (Contact)	2.5 hrs		\$95.00
 Swapped PTO and Gear Pump	\$38.00		
 DPIPL12702BPBB (Part) · Main (Archived)	1 ea		\$1,826.95
MUNCIE GEAR PUMP, 27	\$1,826.95		

Item		Labor	Parts	Subtotal
 FGR3P282X (Part) · Main	1 ea			\$169.42
OUTPUT PTO SHAFT 7/8	\$169.42			
 FGR2P778 (Part) · Main	1 ea			\$297.45
PTO OUTPUT GEAR, 680	\$297.45			
 FGR9P60 (Part) · Main	1 ea			\$55.45
PTO IDLER SHAFT. 680	\$55.45			
 FGR550221 (Part) · Main	2 ea			\$25.60
PTO BEARING RACE S/AS 15245T	\$12.80			
 FGR550397 (Part) · Main	1 ea			\$33.15
PTO BEARING #15126	\$33.15			
 FGR550439 (Part) · Main	1 ea			\$46.56
PTO CLUSTER GEAR BEAR S/AS 21075T	\$46.56			
 FGR22P1272 (Part) · Main	4 ea			\$5.72
PTO BEARING CAP GASKE	\$1.43			
 FGR3784478 (Part) · Main	4 ea			\$4.48
PTO CAPSCREW SH .312-	\$1.12			
 BALBT8443 (Part) · Main	1 ea			\$13.70
HYDRAULIC FILTER GARD S/AS P565059	\$13.70			
 FGR550532 (Part) · Main	1 ea			\$33.15
PTO BEARING REAR OUTP	\$33.15			
 MNACHV255675-448 (Part) · Main	35 L			\$124.95
AW32 HYDRAULIC OIL	\$3.57			
 MXFCD50 (Part) · Main	18 L			\$195.12
TRANSMISSION OIL	\$10.84			
 PS convex		\$19.00	\$41.52	\$60.52
 Joseph Pitney (Contact)	0.5 hrs			\$19.00
	\$38.00			
 GWKSH8S01FH (Part) · Main	1 ea			\$41.52
CONVEX MIRROR 8"	\$41.52			

DESCRIPTION

SUMMARY

Subtotal	\$3,171.22
Labor	\$298.00
Parts	\$2,873.22
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$3,171.22



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5888
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Mar 5, 2025 11:54 AM	#27 2015 Kenworth T800	
Scheduled Start Date:	Wed, Mar 5, 2025 11:54 AM	VIN/SN: License Plate:	1XKDP4EX1FR972824
Actual Start Date:	Wed, Mar 5, 2025 11:54 AM	Operator:	Jake Badger
Expected Completion Date:		Type:	Tri Drive
		Group:	
Actual Completion Date:	Fri, Mar 7, 2025	Odometer:	670,682km
Duration:	2 days	Secondary Meter:	32,809hr
Repair Priority Class:	Scheduled		
Status:	Completed		
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 A4R Airbag	\$38.00	\$21.72	\$59.72
 Kurt Kerekanich (Contact)	1 hr		\$38.00
 Repaired base plate for airbag	\$38.00		
 HVE85171 (Part) · Main	1 ea		\$21.72
AIR BAG BOTTOM PLATE,	\$21.72		
 #11549 · [Inspection] A4 rhs air bag bracket bent Generated by the failed inspection item "Air Bag Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Mar 6, 2025 at 10:19 AM MST			
 A2 LH brakes	\$38.00	\$173.84	\$211.84
 Kurt Kerekanich (Contact)	1 hr		\$38.00
	\$38.00		
 FGRXSS504709E2K (Part) · Main	1 ea		\$67.85
BRAKE SHOE DRIVE16.5X	\$67.85		
 GWKDB1657B (Part) · Main	1 ea		\$105.99
BRAKE DRUM 16.5 X 7 S/AS GWK16792X	\$105.99		

Item	Labor	Parts	Subtotal
#11551 · [Inspection] Replace a2 lhs drum and shoes Generated by the failed inspection item "Brake Lining Thickness 5/16" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Mar 6, 2025 at 10:19 AM MST			
hydraulic oil low	\$9.50	\$0.00	\$9.50
Kurt Kerekanich (Contact) 0.25 hrs			\$9.50
Half cup low	\$38.00		
#11548 · [Inspection] Hydraulic oil low Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Mar 6, 2025 at 10:19 AM MST			
Light Repair Repair Lights	\$50.00	\$7.78	\$57.78
Ricky Peters (Contact) 2 hrs			\$50.00
Replaced RH taillight wire,pig tail	\$25.00		
734A2 (Part) · Main 3 WIRE ARTIC SUPERFLEX S/AS 3663	3 ft		\$3.18
	\$1.06		
FGR94707 (Part) · Main LED SURESEAL PLUG ASS	1 ea		\$4.60
	\$4.60		
#11553 · [Inspection] No rh tail lights Generated by the failed inspection item "Tail Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Mar 6, 2025 at 10:19 AM MST			
Exhaust Bellow Broken	\$20.63	\$537.16	\$557.79
Chad Caouette (Contact) 0.75 hrs			\$20.63
replaced bellow clamps and gaskets	\$27.50		
GWKM66-9393-0320 (Part) · Main (Archived) PIPE BELLOWS 4 TORSIONAL	1 ea		\$430.81
	\$430.81		
GWK2866636CUM (Part) · Main EXHAUST GASKET 4"	3 ea		\$57.33
	\$19.11		
GWK90-0012 (Part) · Main V BAND CLAMP	3 ea		\$49.02
	\$16.34		
#11552 · [Inspection] Exhaust bellow broke Generated by the failed inspection item "Exhaust Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Mar 6, 2025 at 10:19 AM MST			
A2 out put nut loose	\$19.50	\$24.90	\$44.40
Roper Gorgichuk (Contact) 0.5 hrs			\$19.50
	\$39.00		
SPI1707018X (Part) · Main STRAP KIT SPL170	1 ea		\$24.90
	\$24.90		

Item	Labor	Parts	Subtotal
#11550 · [Inspection] A2 output yoke loose Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Mar 6, 2025 at 10:19 AM MST			
PS windshield	\$13.75	\$54.95	\$68.70
Chad Caouette (Contact) 0.5 hrs	\$13.75		
	\$27.50		
GWKDW1163-30 (Part) · Main WINDSHIELD , PS	1 ea		\$54.95
	\$54.95		
#11554 · [Inspection] Ps windshield Generated by the failed inspection item "Windshields" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Mar 6, 2025 at 10:19 AM MST			
Truck Preventative Maintenance Inspection	\$39.00	\$0.00	\$39.00
Roper Gorgichuk (Contact) 1 hr	\$39.00		
ABS Repair	\$39.00	\$169.30	\$208.30
Roper Gorgichuk (Contact) 1 hr	\$39.00		
Replaced A1 rhs sensor and A4 lhs sensor	\$39.00		
FGR4410309102 (Part) · Main ABS SENSOR KIT, 90 DE	1 ea		\$95.35
	\$95.35		
FGR4410309172 (Part) · Main SENSOR ABS KIT, STRAI	1 ea		\$73.95
	\$73.95		
Engine Oil & Filter Replacement	\$9.75	\$345.84	\$355.59
Roper Gorgichuk (Contact) 0.25 hrs	\$9.75		
	\$39.00		
MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	40 L		\$284.80
	\$7.12		
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea		\$61.04
	\$61.04		
Air System Leaks	\$9.75	\$0.00	\$9.75
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
Roper Gorgichuk (Contact) 0.25 hrs	\$9.75		
	\$39.00		
Check Diff and Trans Oil	\$6.88	\$0.00	\$6.88
Chad Caouette (Contact) 0.25 hrs	\$6.88		
	\$27.50		

Item	Labor	Parts	Subtotal
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.50	\$0.00	\$9.50
👤 Kurt Kerekanich (Contact) 0.25 hrs \$38.00			\$9.50
↳ Tire Condition and Pressure Inspection Check all tires	\$12.50	\$0.00	\$12.50
👤 Ricky Peters (Contact) 0.5 hrs \$25.00			\$12.50
↳ Torque Wheels Verify wheels are properly torqued	\$7.25	\$0.00	\$7.25
👤 Allan Bates (Contact) 0.25 hrs \$29.00			\$7.25
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$6.88	\$4.67	\$11.55
👤 Chad Caouette (Contact) 0.25 hrs \$27.50			\$6.88
📦 MNACHV259119-652 (Part) - Main 1 ea \$4.67 STARPLEX EP1 Winter GREASE			\$4.67

DESCRIPTION

SUMMARY

Subtotal	\$1,692.55
Labor	\$352.39
Parts	\$1,340.16
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,692.55



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5735
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Feb 11, 2025 11:08 AM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Tue, Feb 11, 2025 11:09 AM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Wed, Feb 12, 2025	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	665,815km
Status:	Completed	Secondary Meter:	32,579hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$19.00	\$0.00	\$19.00
 MICHAEL ABLOG (Contact)	0.5 hrs \$38.00		\$19.00
 Headlights Repair	\$19.00	\$0.00	\$19.00
 MICHAEL ABLOG (Contact)	0.5 hrs \$38.00		\$19.00
 Hydraulic Cap Stripped	\$125.00	\$100.38	\$225.38
 Ricky Peters (Contact)	5 hrs \$25.00		\$125.00
 BALBT8443 (Part) · Main HYDRAULIC FILTER GARD S/AS P565059	1 ea \$13.70		\$13.70
 WABGDLOU-309001202 (Part) · Main GARDNER DENVER COOLER CAP	1 ea \$86.68		\$86.68
 Eye Wash Sticker Replacement	\$9.50	\$0.00	\$9.50

Item	Labor	Parts	Subtotal
MICHAEL ABLOG (Contact) 0.25 hrs \$38.00			\$9.50
A3Lh Dust Shield Loose	\$9.50	\$0.00	\$9.50
MICHAEL ABLOG (Contact) replaced bolts 0.25 hrs \$38.00			\$9.50
A2Rh Shock Loose	\$6.25	\$0.00	\$6.25
Ricky Peters (Contact) Tightened bolt 0.25 hrs \$25.00			\$6.25
#11262 · [Inspection] A2Rh Shock loose Generated by the failed inspection item "Shocks" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Feb 11, 2025 at 11:52 AM MST			
Exhaust Crack Repair	\$19.00	\$37.34	\$56.34
MICHAEL ABLOG (Contact) removed down pipe and welded a plate over the crack. 0.5 hrs \$38.00			\$19.00
GWK2866337CUM (Part) · Main EXHAUST GASKET 5" CIR 2 ea \$18.67			\$37.34
#11263 · [Inspection] Exhaust crack rh Generated by the failed inspection item "Exhaust Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Feb 11, 2025 at 11:52 AM MST			
Engine Oil & Filter Replacement	\$19.00	\$345.84	\$364.84
MICHAEL ABLOG (Contact) 0.5 hrs \$38.00			\$19.00
MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER 40 L \$7.12			\$284.80
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000 1 ea \$61.04			\$61.04
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.50	\$0.00	\$9.50
Kurt Kerekanich (Contact) 0.25 hrs \$38.00			\$9.50
Check Diff and Trans Oil	\$6.25	\$48.35	\$54.60
Ricky Peters (Contact) a3 low 0.25 hrs \$25.00			\$6.25
MNACHV223030953 (Part) · Main DELO S-G XDM 75W90 SYNTHETIC GEAR OIL 7590 5 L \$9.67			\$48.35

Item	Labor	Parts	Subtotal
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.50	\$0.00	\$9.50
👤 MICHAEL ABLOG (Contact) 0.25 hrs \$38.00			\$9.50
↳ Tire Condition and Pressure Inspection Check all tires	\$6.00	\$0.00	\$6.00
👤 Jayden Binet (Contact) 0.25 hrs \$24.00			\$6.00
↳ Torque Wheels Verify wheels are properly torqued	\$6.00	\$0.00	\$6.00
👤 Jayden Binet (Contact) 0.25 hrs \$24.00			\$6.00
↳ Walk Around Inspection	\$9.50	\$0.00	\$9.50
👤 MICHAEL ABLOG (Contact) 0.25 hrs \$38.00			\$9.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$12.50	\$0.00	\$12.50
👤 Ricky Peters (Contact) 0.5 hrs \$25.00			\$12.50

DESCRIPTION

SUMMARY

Subtotal	\$817.41
Labor	\$285.50
Parts	\$531.91
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$817.41



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5591
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Jan 21, 2025 4:43 PM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Tue, Jan 21, 2025 4:44 PM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Wed, Jan 22, 2025	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	663,567km
Status:	Completed	Secondary Meter:	32,364hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$13.75	\$0.00	\$13.75
 Chad Caouette (Contact)	0.5 hrs		\$13.75
	\$27.50		
 Engine Oil & Filter Replacement	\$9.50	\$357.69	\$367.19
 MICHAEL ABLOG (Contact)	0.25 hrs		\$9.50
	\$38.00		
 NXTDBL7900 (Part) - Main	1 ea		\$58.65
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$58.65		
 MXF5W40 (Part) - Main	42 L		\$299.04
ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	\$7.12		
 Air System Leaks	\$6.88	\$0.00	\$6.88
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			

Item		Labor	Parts	Subtotal
Chad Caouette (Contact) 0.25 hrs \$27.50				\$6.88
↳ Check Diff and Trans Oil		\$6.88	\$0.00	\$6.88
Chad Caouette (Contact) 0.25 hrs \$27.50				\$6.88
↳ Inspect and Service Trailer Hitch		\$9.50	\$0.00	\$9.50
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
MICHAEL ABLOG (Contact) 0.25 hrs \$38.00				\$9.50
↳ Tire Condition and Pressure Inspection		\$7.25	\$0.00	\$7.25
Check all tires				
Allan Bates (Contact) 0.25 hrs \$29.00				\$7.25
↳ Torque Wheels		\$6.00	\$0.00	\$6.00
Verify wheels are properly torqued				
Jayden Binet (Contact) 0.25 hrs \$24.00				\$6.00
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00				\$22.50
↳ Grease Unit		\$6.88	\$4.67	\$11.55
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
Chad Caouette (Contact) 0.25 hrs \$27.50				\$6.88
MNACHV259119-652 (Part) · Main 1 ea \$4.67				\$4.67
STARPLEX EP1 Winter GREASE				
🔧 Engine Air Filter Replacement		\$6.88	\$172.86	\$179.74
Chad Caouette (Contact) 0.25 hrs \$27.50				\$6.88
replaced air filters				
NTXP625287 (Part) · Main 2 ea \$86.43				\$172.86
AIRFILTER T800				
🔧 Cab Air Filter		\$6.88	\$30.28	\$37.16
Chad Caouette (Contact) 0.25 hrs \$27.50				\$6.88

Item	Labor	Parts	Subtotal
 GWKCF19501C (Part) · Main CAB AIR FILTER C/W CR	1 ea \$30.28		\$30.28
 Fuel Filter Replacement	\$9.50	\$108.27	\$117.77
 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00		\$9.50
 NTXDBF6776 (Part) · Main FUEL FILTER SPIN ON S/AS BF46129	1 ea \$64.31		\$64.31
 BALPF46081 (Part) · Main (Archived) BALDWIN FUEL FILTER	1 ea \$43.96		\$43.96
 exhaust clamp loose  Clamp under RHS steps	\$6.88	\$0.00	\$6.88
 Chad Caouette (Contact)	0.25 hrs \$27.50		\$6.88
 hydraulic cooler leaking	\$190.00	\$0.00	\$190.00
 Kurt Kerekanich (Contact)  Replaced rad with good used and all new hoses	5 hrs \$38.00		\$190.00

DESCRIPTION

SUMMARY

Subtotal	\$983.05
Labor	\$309.28
Parts	\$673.77
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$983.05

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#11050 Hydraulic return hose Reported Jan 21, 2025 by Jake Badger Located between truck and trailer, passenger side, very slow leak, sweating out fluid.		
#11063 [Inspection] Cab Air Filter Reported over 1 year ago by Chad Caouette - Truck Preventative Maintenance Checklist by Chad Caouette Generated by the failed inspection item "Cab Air Filter" on the "Truck Preventative Maintenance Checklist" form submitted by Chad Caouette on Jan 22, 2025 at 8:10 AM MST		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5448
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Jan 1, 2025 1:53 PM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Wed, Jan 1, 2025 1:53 PM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Fri, Jan 3, 2025	Type:	Tri Drive
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	659,215km
Status:	Completed	Secondary Meter:	32,144hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Light Repair Repair Lights	\$9.75	\$0.00	\$9.75
 Roper Gorgichuk (Contact)  Fixed wires for signal lights on lhs and fog lamps	0.25 hrs \$39.00		\$9.75
 A1 output seal leaking	\$117.00	\$102.45	\$219.45
 Roper Gorgichuk (Contact)	3 hrs \$39.00		\$117.00
 SPI1707018X (Part) · Main STRAP KIT SPL170	2 ea \$24.90		\$49.80
 SPI210737 (Part) · Main OUTPUT SEAL EATON DIF	1 ea \$52.65		\$52.65
 A2 oily from vent tube	\$9.75	\$11.30	\$21.05
 Roper Gorgichuk (Contact)  Replaced breather	0.25 hrs \$39.00		\$9.75

Item	Labor	Parts	Subtotal
 FGRKIT2902 (Part) · Main BREATHER & TUBE KIT, 1 ea \$11.30			\$11.30
 Hydraulic Cooler Repair	\$19.00	\$10.71	\$29.71
 Joseph Pitney (Contact)  Installed new bolts at bottom of rad and installed bolt to hold fan guard on. 0.5 hrs \$38.00			\$19.00
 MNACHV255675-448 (Part) · Main AW32 HYDRAULIC OIL 3 L \$3.57			\$10.71
 Replace steady bearing	\$38.00	\$109.10	\$147.10
 Joseph Pitney (Contact) 1 hr \$38.00			\$38.00
 SPI10094142 (Part) · Main STEADY BEARING, S/AS 1 ea \$109.10			\$109.10
 Oil leak rear tranny gasket	\$38.00	\$46.91	\$84.91
 Joseph Pitney (Contact)  drop trans fluid replace aux counter shaft gasket fill tranny 1 hr \$38.00			\$38.00
 GWK4307247 (Part) · Main TRANS AUX.CTRSHAFT CO 1 ea \$5.57			\$5.57
 GWK4302320 (Part) · Main TRANS CTRSHAFT COVER 1 ea \$41.34			\$41.34
 Coolant Leak at Engine Heater	\$9.50	\$0.00	\$9.50
 Joseph Pitney (Contact) 0.25 hrs \$38.00			\$9.50
 Truck Preventative Maintenance Inspection	\$28.50	\$0.00	\$28.50
 Joseph Pitney (Contact) 0.75 hrs \$38.00			\$28.50
 Check Diff and Trans Oil	\$9.75	\$51.20	\$60.95
 Roper Gorgichuk (Contact)  A3 diff was low 0.25 hrs \$39.00			\$9.75
 MXF7590 (Part) · Main (Archived) 75W90 SYN BLEND 5 L \$10.24			\$51.20
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.50	\$0.00	\$9.50

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)	0.25 hrs \$38.00			\$9.50
↳ Tire Condition and Pressure Inspection Check all tires		\$7.25	\$0.00	\$7.25
 Allan Bates (Contact)	0.25 hrs \$29.00			\$7.25
↳ Torque Wheels Verify wheels are properly torqued		\$7.60	\$0.00	\$7.60
 Joseph Pitney (Contact)	0.2 hrs \$38.00			\$7.60
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$19.00	\$0.00	\$19.00
 Joseph Pitney (Contact)	0.5 hrs \$38.00			\$19.00
↳ Engine Oil & Filter Replacement		\$6.25	\$343.45	\$349.70
 Ricky Peters (Contact)	0.25 hrs \$25.00			\$6.25
 NXTDBL 7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$58.65			\$58.65
 MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	40 L \$7.12			\$284.80
↳ Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$9.75	\$14.90	\$24.65
 Roper Gorgichuk (Contact)	0.25 hrs \$39.00			\$9.75
 FGR12103 (Part) · Main HALDEX DRAIN VALVE. 3	1 ea \$14.90			\$14.90
 GPS System Repair		\$19.50	\$0.00	\$19.50
 Roper Gorgichuk (Contact)  GPS was stuck on sat, unhooked module from truck to drain battery then reconnected a couple days later and called in for them to check it. Working again for now second time we have had to do it on this unit.	0.5 hrs \$39.00			\$19.50

DESCRIPTION

SUMMARY

Subtotal	\$1,070.62
Labor	\$380.60
Parts	\$690.02
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,070.62

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#10802 [Inspection] replace steady bearing Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 2, 2025 at 8:25 AM MST		
#10804 [Inspection] low Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 2, 2025 at 8:25 AM MST		
#10801 [Inspection] leak at engine heater Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Coolant Hose Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 2, 2025 at 8:25 AM MST		
#10803 [Inspection] A1 output seal A2 wet from breather tube Reported over 1 year ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Diff and Trans Breathers" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 2, 2025 at 8:25 AM MST		
#10789 Mh3 cooler Reported Dec 31, 2024 by JOE NEMEC Rad and fan guard loose		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5340
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Dec 11, 2024 1:21 PM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Wed, Dec 11, 2024 1:21 PM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Fri, Dec 13, 2024	Type:	Tri Drive
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	655,765km
Status:	Completed	Secondary Meter:	31,957hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$28.50	\$0.00	\$28.50
 Ernesto Ablog (Contact)	0.75 hrs \$38.00		\$28.50
 A2Lhs brake pot	\$50.00	\$148.90	\$198.90
 Ricky Peters (Contact)	2 hrs		\$50.00
 Installed new brake pot.	\$25.00		
 FGRLCP3030 (Part) · Main	1 ea		\$148.90
LIFESEAL 2.5. BRAKE P	\$148.90		
 #10518 · [Inspection] Brake Pot Condition			
Generated by the failed inspection item "Brake Pot Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Dec 11, 2024 at 4:37 PM MST			
 Clutch Brake Adjustment	\$38.00	\$0.00	\$38.00

Item	Labor	Parts	Subtotal
Ernesto Ablog (Contact) Adjusted clutch brake gap, replaced bottom clutch linkage and reset upper linkage 1 hr			\$38.00
	\$38.00		
A2Rhs shock loose	\$6.25	\$0.00	\$6.25
Ricky Peters (Contact) Installed new bolt 0.25 hrs	\$25.00		\$6.25
Hydraulic Filter Replacement	\$6.25	\$13.70	\$19.95
Ricky Peters (Contact) 0.25 hrs	\$25.00		\$6.25
BALBT8443 (Part) · Main HYDRAULIC FILTER GARD S/AS P565059 1 ea	\$13.70		\$13.70
#10517 · [Inspection] Hydraulic Oil Level Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Dec 11, 2024 at 4:37 PM MST			
A2 Output Seal	\$47.50	\$90.72	\$138.22
MICHAEL ABLOG (Contact) 1.25 hrs	\$38.00		\$47.50
SPI210737 (Part) · Main OUTPUT SEAL EATON DIF 1 ea	\$52.65		\$52.65
SPI1707018X (Part) · Main STRAP KIT SPL170 1 ea	\$24.90		\$24.90
SPI128049 (Part) · Main DIFF INPUT NUT 1 ea	\$13.17		\$13.17
Engine Oil & Filter Replacement	\$9.50	\$336.33	\$345.83
Ernesto Ablog (Contact) 0.25 hrs	\$38.00		\$9.50
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000 1 ea	\$58.65		\$58.65
MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER 39 L	\$7.12		\$277.68
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$6.25	\$0.00	\$6.25
Ricky Peters (Contact) 0.25 hrs	\$25.00		\$6.25

Item	Labor	Parts	Subtotal
↳ Check Diff and Trans Oil	\$12.50	\$96.70	\$109.20
Ricky Peters (Contact) 0.25 hrs \$25.00			\$6.25
Ricky Peters (Contact) 0.25 hrs \$25.00 Added oil to A3			\$6.25
MNACHV223030953 (Part) · Main 10 L DELO S-G XDM 75W90 SYNTHETIC GEAR OIL 7590 \$9.67			\$96.70
↳ Inspect and Service Trailer Hitch	\$9.50	\$0.00	\$9.50
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.			
MICHAEL ABLOG (Contact) 0.25 hrs \$38.00			\$9.50
↳ Tire Condition and Pressure Inspection	\$6.00	\$0.00	\$6.00
Check all tires			
Jayden Binet (Contact) 0.25 hrs \$24.00			\$6.00
↳ Torque Wheels	\$7.25	\$0.00	\$7.25
Verify wheels are properly torqued			
Allan Bates (Contact) 0.25 hrs \$29.00			\$7.25
↳ Walk Around Inspection	\$9.50	\$0.00	\$9.50
MICHAEL ABLOG (Contact) 0.25 hrs \$38.00			\$9.50
↳ Grease Unit	\$9.50	\$9.34	\$18.84
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.			
MICHAEL ABLOG (Contact) 0.25 hrs \$38.00			\$9.50
MNACHV259118-652 (Part) · Main 2 ea STARPLEX EP2 TUBE Summer Grease \$4.67			\$9.34

Subtotal	\$942.19
Labor	\$246.50
Parts	\$695.69
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$942.19



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5303
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Dec 4, 2024 4:16 PM	#27 2015 Kenworth T800	
Scheduled Start Date:		VIN/SN:	1XKDP4EX1FR972824
Actual Start Date:	Wed, Dec 4, 2024 4:16 PM	License Plate:	
Expected Completion Date:		Operator:	Jake Badger
Actual Completion Date:	Wed, Dec 4, 2024 4:16 PM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	653,979km
Status:	Completed	Secondary Meter:	31,875hr
Issued By:	Roper Gorgichuk		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 engine heater repair Diagnosis and repair engine heater.	\$9.75	\$537.12	\$546.87
 Roper Gorgichuk (Contact)	0.25 hrs \$39.00		\$9.75
 PWR25.2596.25.0100.2 (Part) - Main D12 COOLANT PUMP	1 ea \$537.12		\$537.12

DESCRIPTION

SUMMARY

Subtotal	\$546.87
Labor	\$9.75
Parts	\$537.12
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$546.87