



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8830
Invoice Number:
PO Number:

H/15-3
SEP

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Thu, May 28, 2026 2:12 PM	#52 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWP4EX7KR955710
Actual Start Date:	Thu, May 28, 2026 2:12 PM	License Plate:	
Expected Completion Date:		Operator:	Bill Bromley
Actual Completion Date:	Fri, May 29, 2026	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	436,367km
Status:	Completed	Secondary Meter:	24,227hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$42.00	\$0.00	\$42.00
 Roper Gorgichuk (Contact)	1 hr \$42.00		\$42.00
 AC Repair	\$21.00	\$13.34	\$34.34
 Roper Gorgichuk (Contact)	0.5 hrs \$42.00		\$21.00
 GWKCN26400 (Part) · Main SPADE TERMINAL 16-20	2 ea \$3.05		\$6.10
 GWKCN50200 (Part) · Main WEATHERTITE SEAL	2 ea \$3.62		\$7.24
 Engine Oil & Filter Replacement	\$10.50	\$239.27	\$249.77
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00		\$10.50
 MXF15W40 (Part) · Main ENGINE OIL 15W40 BUL	42 L \$4.16		\$174.72

Item		Labor	Parts	Subtotal
 NXTDBL7900 (Part) - Main				\$64.55
OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea			
	\$64.55			
 Air System Leaks		\$7.75	\$0.00	\$7.75
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.				
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
 Check Diff and Trans Oil		\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
 Inspect and Service Trailer Hitch		\$10.50	\$0.00	\$10.50
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 Roper Gorgichuk (Contact)	0.25 hrs			\$10.50
	\$42.00			
 Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
 Torque Wheels		\$10.50	\$0.00	\$10.50
Verify wheels are properly torqued				
 Roper Gorgichuk (Contact)	0.25 hrs			\$10.50
	\$42.00			
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs			\$22.50
	\$90.00			
 Grease Unit		\$7.75	\$4.67	\$12.42
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
 MNACHV259118-652 (Part) - Main	1 ea			\$4.67
STARPLEX EP2 TUBE Summer Grease	\$4.67			
 hood pin RHS		\$10.50	\$173.46	\$183.96

Item		Labor	Parts	Subtotal
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 GWKL65-1013R (Part) · Main HOOD PIN GUIDE ASSY R	1 ea \$173.46			\$173.46
 Positive Air Shutdown Repair		\$21.00	\$15.30	\$36.30
 Roper Gorgichuk (Contact)	0.5 hrs \$42.00			\$21.00
 3005530 (Part) · Main (Archived) 30A Circuit Breaker SAME AS 822193 Bought As No Grote Were Available.	1 ea \$15.30			\$15.30
 Replace both wiper blades		\$10.50	\$22.70	\$33.20
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 GWK66-150 (Part) · Main (Archived) BLADES WINTER WIPER	2 ea \$11.35			\$22.70
 #17235 · [Inspection] rhs wiper blade Generated by the failed inspection item "Windshield Wiper and Spray" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on May 28, 2026 at 3:49 PM MDT				
 Hydraulic Filter Replacement		\$10.50	\$32.90	\$43.40
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 BALBT443 (Part) · Main OIL FILTER	1 ea \$32.90			\$32.90
 Replace Rhs Convex Mirror		\$10.50	\$36.07	\$46.57
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 GWKSH8S01FH (Part) · Main CONVEX MIRROR 8"	1 ea \$36.07			\$36.07
 #17236 · [Inspection] rhs convex mirror Generated by the failed inspection item "Mirrors" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on May 28, 2026 at 3:49 PM MDT				
 AC Belt Tensioner		\$42.00	\$309.00	\$351.00
 Roper Gorgichuk (Contact)	1 hr \$42.00			\$42.00
 GWK89448 (Part) · Main BELT TENSIONER A/C	1 ea \$244.76			\$244.76

Item	Labor	Parts	Subtotal
 GWK89120 (Part) · Main IDLER PULLEY A/C	1 ea \$64.24		\$64.24

DESCRIPTION

SUMMARY

Subtotal	\$1,099.71
Labor	\$253.00
Parts	\$846.71
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,099.71

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#17238 [Inspection] A/C Line Condition/Rad Reported 3 months ago by Roper Gorgichuk · Truck Preventative Maintenance Checklist by Roper Gorgichuk Generated by the failed inspection item "A/C Line Condition/Rad" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on May 28, 2026 at 3:49 PM MDT		
#17237 [Inspection] shut down nor working Reported 3 months ago by Roper Gorgichuk · Truck Preventative Maintenance Checklist by Roper Gorgichuk Generated by the failed inspection item "Positive Air function" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on May 28, 2026 at 3:49 PM MDT		
#17218 A/c Reported May 27, 2026 by Kurt Kerekanich Driver reports no a/c		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8574
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Apr 14, 2026 9:18 AM	#52 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWP4EX7KR955710
Actual Start Date:	Tue, Apr 14, 2026 9:18 AM	License Plate:	
Expected Completion Date:		Operator:	Bill Bromley
Actual Completion Date:	Thu, Apr 16, 2026	Type:	Tri Drive
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	434,559km
Status:	Completed	Secondary Meter:	24,037hr
Issued By:	Kurt Kerekanich		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Alternator Replacement	\$41.00	\$326.60	\$367.60
 Kurt Kerekanich (Contact)	1 hr \$41.00		\$41.00
 FGR8600889 (Part) · Main ALTERNATOR DELCO REMY	1 ea \$326.60		\$326.60
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
 Engine Oil & Filter Replacement  No oil change	\$0.00	\$0.00	\$0.00
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.75	\$0.00	\$9.75

Item	Labor	Parts	Subtotal
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Check Diff and Trans Oil	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
↳ Torque Wheels Verify wheels are properly torqued	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.50	\$4.67	\$24.17
 Joseph Pitney (Contact) 0.5 hrs \$39.00			\$19.50
 MNACHV259119-652 (Part) · Main STARPLEX EP1 Winter GREASE 1 ea \$4.67			\$4.67
 DS westcoast mirror replacement	\$19.50	\$52.96	\$72.46
 Joseph Pitney (Contact) 0.5 hrs \$39.00			\$19.50
 GWKMDS2 (Part) · Main MIRROR HEATED SILVER 1 ea \$52.96			\$52.96
 A2 output seal leaking	\$87.75	\$466.19	\$553.94
 Joseph Pitney (Contact) 0.75 hrs  remove yoke ordered new one \$39.00			\$29.25

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)				\$58.50
 remove seal install new seal and speedy sleeve assemble driveline and grease				
		1.5 hrs		
		\$39.00		
 SPI170-4-641-1 (Part) · Main		1 ea		\$332.75
END YOKE OUTPUT INTER		\$332.75		
 FGRKIT2638 (Part) · Main		1 ea		\$33.49
ROCKWELL PINION NUT/W		\$33.49		
 FGRA11205Y2729 (Part) · Main		1 ea		\$99.95
PINION SEAL FORWARD OUTPUT S/AS AS2729.		\$99.95		
 Air Filters Replacement		\$29.25	\$216.38	\$245.63
 Joseph Pitney (Contact)		0.75 hrs		\$29.25
		\$39.00		
 NTXP625128 (Part) · Main		2 ea		\$216.38
AIR FILTER W900		\$108.19		

DESCRIPTION	SUMMARY
	Subtotal \$1,362.30
	Labor \$295.50
	Parts \$1,066.80
	Labor Markup + \$0.00 (0.0%)
	Parts Markup + \$0.00 (0.0%)
	Warranty Credits - \$0.00 (0.0%)
	Discount - \$0.00 (0.0%)
	Tax +\$0.00 (0.0%)
	Total \$1,362.30

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#16734 [Inspection] DS westcoast mirror replace Reported 4 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Mirrors" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Apr 14, 2026 at 10:27 AM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8442
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Mar 25, 2026 5:29 PM	#52 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWP4EX7KR955710
Actual Start Date:	Wed, Mar 25, 2026 5:29 PM	License Plate:	
Expected Completion Date:		Operator:	Bill Bromley
Actual Completion Date:	Thu, Mar 26, 2026	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	432,992km
Status:	Completed	Secondary Meter:	23,899hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
 Engine Oil & Filter Replacement	\$9.75	\$332.87	\$342.62
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$64.55		\$64.55
 MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	39 L \$6.88		\$268.32
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.75	\$0.00	\$9.75

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Check Diff and Trans Oil		\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Inspect and Service Trailer Hitch		\$9.75	\$0.00	\$9.75
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Torque Wheels		\$9.75	\$0.00	\$9.75
Verify wheels are properly torqued				
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Grease Unit		\$19.50	\$4.67	\$24.17
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 Joseph Pitney (Contact)	0.5 hrs \$39.00			\$19.50
 MNACHV259119-652 (Part) · Main	1 ea			\$4.67
STARPLEX EP1 Winter GREASE				
 replace 2way antenna		\$39.00	\$90.00	\$129.00
 Joseph Pitney (Contact)	1 hr \$39.00			\$39.00
 VECSPNMOHFFME (Part) · Main	1 ea			\$30.00
ANTENNA CABLE 17' 2-W S/AS NMOKHFUDFME				
 VECOP1229W (Part) · Main	1 ea			\$60.00
ANTENNA, 2-WAY				
 Adjust Fifth Wheel Jaws		\$9.75	\$0.00	\$9.75

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 replace A/C belt		\$19.50	\$43.21	\$62.71
 Joseph Pitney (Contact)	0.5 hrs \$39.00			\$19.50
 GWK5060640 (Part) · Main A/C BELT	1 ea \$43.21			\$43.21

DESCRIPTION

SUMMARY

Subtotal	\$666.75
Labor	\$196.00
Parts	\$470.75
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$666.75

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#16437 [Inspection] fifth wheel adjustment required Reported 5 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "5th Wheel and Slider Play" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 26, 2026 at 8:14 AM MDT		
#16436 [Inspection] a/c belt replacement Reported 5 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Belt Tension and Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 26, 2026 at 8:14 AM MDT		
#16428 Two way antenna Reported Mar 25, 2026 by JOE NEMEC Driver reports missing.		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8331
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Thu, Mar 5, 2026 2:30 PM	#52 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWP4EX7KR955710
Actual Start Date:	Thu, Mar 5, 2026 2:31 PM	License Plate:	
Expected Completion Date:		Operator:	Bill Bromley
Actual Completion Date:	Fri, Mar 6, 2026	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	430,631km
Status:	Completed	Secondary Meter:	23,674hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
 Engine Oil & Filter Replacement	\$9.75	\$332.87	\$342.62
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 NXTDBL7900 (Part) · Main	1 ea		\$64.55
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$64.55		
 MXF5W40 (Part) · Main	39 L		\$268.32
ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	\$6.88		
 Air System Leaks	\$9.75	\$0.00	\$9.75
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			

Item	Labor	Parts	Subtotal
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Check Diff and Trans Oil	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Tire Condition and Pressure Inspection Check all tires	\$6.25	\$0.00	\$6.25
 Jayden Binet (Contact) 0.25 hrs \$25.00			\$6.25
↳ Torque Wheels Verify wheels are properly torqued	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Walk Around Inspection	\$7.80	\$0.00	\$7.80
 Joseph Pitney (Contact) 0.2 hrs \$39.00			\$7.80
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.50	\$4.67	\$24.17
 Joseph Pitney (Contact) 0.5 hrs \$39.00			\$19.50
 MNACHV259119-652 (Part) · Main STARPLEX EP1 Winter GREASE 1 ea \$4.67			\$4.67
 A2 output seal leaking	\$39.00	\$99.95	\$138.95
 Joseph Pitney (Contact) 1 hr \$39.00			\$39.00
 FGRA11205Y2729 (Part) · Main PINION SEAL FORWARD OUTPUT S/AS AS2729. 1 ea \$99.95			\$99.95
 A3 input seal leaking	\$58.50	\$96.10	\$154.60
 Joseph Pitney (Contact) 1.5 hrs \$39.00  replaced output and input short shaft up			\$58.50

Item	Labor	Parts	Subtotal
 FGR11205X2728 (Part) · Main PINION SEAL, FORWARD INPUT S/AS GWKAS2728	1 ea \$96.10		\$96.10
 broken wire reverse alarm  Repair wire	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 Fuel Filters Replacement	\$19.50	\$113.32	\$132.82
 Joseph Pitney (Contact)	0.5 hrs \$39.00		\$19.50
 P581299 (Part) · Main Fuel filter same as K37-1029 & PF46081	1 ea \$44.56		\$44.56
 NTXDBF6776 (Part) · Main FUEL FILTER SPIN ON S/AS BF46129	1 ea \$68.76		\$68.76
 DS air tank strap broken	\$39.00	\$294.62	\$333.62
 Joseph Pitney (Contact)  remove bracket under battery box to replace both straps that hold the air tanks	1 hr \$39.00		\$39.00
 GWKG84-1007 (Part) · Main (Archived) Air Tank Strap Air Tanks Under Battery Box. Non Stock ORDER AS NEEDED ONLY.	2 ea \$147.31		\$294.62

DESCRIPTION

SUMMARY

Subtotal	\$1,218.83
Labor	\$277.30
Parts	\$941.53
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,218.83

Issue	Assigned	Due
#16152 [Inspection] A2 output seal leaking A3 input seal leaking Reported 6 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 5, 2026 at 3:23 PM MST		
#16151 [Inspection] broken wire at alarm Reported 6 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Back up alarm" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Mar 5, 2026 at 3:23 PM MST		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8172
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Thu, Feb 12, 2026 11:58 AM	#52 2019 Kenworth W900	
Scheduled Start Date:	Thu, Feb 12, 2026 11:58 AM	VIN/SN: License Plate:	1XKWP4EX7KR955710
Actual Start Date:	Thu, Feb 12, 2026 11:58 AM	Operator:	Bill Bromley
Expected Completion Date:		Type:	Tri Drive
		Group:	
Actual Completion Date:	Fri, Feb 13, 2026	Odometer:	427,912km
Duration:	1 day	Secondary Meter:	23,398hr
Repair Priority Class:	Scheduled		
Status:	Completed		
Issued By:	Roper Gorgichuk		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Dash Cam Mount	\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)	0.25 hrs		\$11.00
 cleaned out old glue and added new tape	\$44.00		
 #15876 · Dash cam needs to ge recounted.			
 Air Filter Light Rhs	\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)	0.25 hrs		\$11.00
 repaired wiring	\$44.00		
 Truck Preventative Maintenance Inspection	\$42.00	\$0.00	\$42.00
 Roper Gorgichuk (Contact)	1 hr		\$42.00
 topped up hydraulic oil	\$42.00		
 Engine Oil & Filter Replacement	\$11.00	\$336.24	\$347.24
 MICHAEL ABLOG (Contact)	0.25 hrs		\$11.00
	\$44.00		

Item		Labor	Parts	Subtotal
 NXTDBL7900 (Part) · Main	1 ea			\$61.04
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$61.04			
 MXF5W40 (Part) · Main	40 L			\$275.20
ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	\$6.88			
 Air System Leaks		\$7.25	\$0.00	\$7.25
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.				
 Chad Caouette (Contact)	0.25 hrs			\$7.25
	\$29.00			
 Check Diff and Trans Oil		\$7.25	\$0.00	\$7.25
 Chad Caouette (Contact)	0.25 hrs			\$7.25
	\$29.00			
 Inspect and Service Trailer Hitch		\$11.00	\$0.00	\$11.00
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 MICHAEL ABLOG (Contact)	0.25 hrs			\$11.00
	\$44.00			
 Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
 Torque Wheels		\$14.50	\$0.00	\$14.50
Verify wheels are properly torqued				
 Chad Caouette (Contact)	0.5 hrs			\$14.50
	\$29.00			
 Walk Around Inspection		\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)	0.25 hrs			\$11.00
	\$44.00			
 Grease Unit		\$11.00	\$0.00	\$11.00
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 MICHAEL ABLOG (Contact)	0.25 hrs			\$11.00
	\$44.00			

DESCRIPTION

SUMMARY

Subtotal	\$480.99
Labor	\$144.75
Parts	\$336.24
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$480.99



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8004
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Jan 21, 2026 4:21 PM	#52 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWP4EX7KR955710
Actual Start Date:	Wed, Jan 21, 2026 4:22 PM	License Plate:	
Expected Completion Date:		Operator:	Bill Bromley
Actual Completion Date:	Fri, Jan 23, 2026	Type:	Tri Drive
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	425,244km
Status:	Completed	Secondary Meter:	23,199hr
Issued By:	Kurt Kerekanich		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
 ABS Repair	\$44.00	\$95.35	\$139.35
 MICHAEL ABLOG (Contact)			\$44.00
 abs codes for A4Rh, A3Rh and Steer Rh. replaced sensor A4Rh, checked A3Rh wires and gap, repaired broken wires for Steer Rh. plugged in laptop and cleared codes.			
	1 hr \$44.00		
 FGR4410309102 (Part) - Main	1 ea \$95.35		\$95.35
ABS SENSOR KIT, 90 DE			
 Engine Oil & Filter Replacement	\$9.75	\$329.36	\$339.11
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75

Item		Labor	Parts	Subtotal
 NXTDBL7900 (Part) · Main	1 ea			\$61.04
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$61.04			
 MXF5W40 (Part) · Main	39 L			\$268.32
ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	\$6.88			
↳ Air System Leaks		\$11.00	\$0.00	\$11.00
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.				
 MICHAEL ABLOG (Contact)	0.25 hrs			\$11.00
	\$44.00			
 #15557 · Losing air overnight				
Check for leaks				
↳ Check Diff and Trans Oil		\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)	0.25 hrs			\$11.00
	\$44.00			
↳ Inspect and Service Trailer Hitch		\$11.00	\$0.00	\$11.00
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 MICHAEL ABLOG (Contact)	0.25 hrs			\$11.00
	\$44.00			
↳ Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
↳ Torque Wheels		\$17.00	\$0.00	\$17.00
Verify wheels are properly torqued				
 Chad Caouette (Contact)	0.25 hrs			\$7.25
	\$29.00			
 Joseph Pitney (Contact)	0.25 hrs			\$9.75
	\$39.00			
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs			\$22.50
	\$90.00			
↳ Grease Unit		\$19.50	\$4.67	\$24.17
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 Joseph Pitney (Contact)	0.5 hrs			\$19.50
	\$39.00			

Item	Labor	Parts	Subtotal
 MNACHV259119-652 (Part) · Main STARPLEX EP1 Winter GREASE	1 ea \$4.67		\$4.67
 CVIP	\$44.00	\$0.00	\$44.00
 MICHAEL ABLOG (Contact)  got all measurements	1 hr \$44.00		\$44.00
 A3 temp wire repair	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 A4 temp wire repair	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 adjust clutch brake gap	\$19.50	\$0.00	\$19.50
 Joseph Pitney (Contact)	0.5 hrs \$39.00		\$19.50
 #15569 · [Inspection] clutch brake gap adjustment Generated by the failed inspection item "Clutch Brake Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 22, 2026 at 7:52 AM MST			
 Adjust Fifth Wheel Jaws	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 #15571 · [Inspection] fifth wheel adjustment required Generated by the failed inspection item "5th Wheel and Slider Play" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 22, 2026 at 7:52 AM MST			
 PS windshield replacement	\$19.50	\$54.95	\$74.45
 Joseph Pitney (Contact)	0.5 hrs \$39.00		\$19.50
 GWKDW1163-30 (Part) · Main WINDSHIELD , PS	1 ea \$54.95		\$54.95
 #15568 · [Inspection] PS windshield replacement Generated by the failed inspection item "Windshields" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 22, 2026 at 7:52 AM MST			
 Pressure test cooling system	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)  checked all around for leaks seems coolant on floor from previous vehicle	0.25 hrs \$39.00		\$9.75

Item	Labor	Parts	Subtotal
------	-------	-------	----------

#15570 · [Inspection] coolant on floor under rad pressure test system

Generated by the failed inspection item "Coolant Level" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 22, 2026 at 7:52 AM MST

check DS door seal

\$11.00

\$0.00

\$11.00

MICHAEL ABLOG (Contact)

0.25 hrs

\$11.00

glued back together

\$44.00

#15556 · DS door seal

Glue in seal keeps falling out

A3R brake drum and shoes

\$19.50

\$162.64

\$182.14

Joseph Pitney (Contact)

0.5 hrs

\$19.50

\$39.00

GWKDB1657B (Part) · Main

1 ea

\$105.99

BRAKE DRUM 16.5 X 7 S/AS GWK16792X

\$105.99

FGRXSS714707QPK (Part) · Main

1 ea

\$56.65

BRAKE SHOE16.5X7" Q+

\$56.65

DESCRIPTION	SUMMARY	
	Subtotal	\$982.22
	Labor	\$335.25
	Parts	\$646.97
	Labor Markup	+ \$0.00 (0.0%)
	Parts Markup	+ \$0.00 (0.0%)
	Warranty Credits	- \$0.00 (Fixed)
	Discount	- \$0.00 (0.0%)
	Tax	+\$0.00 (0.0%)
	Total	\$982.22



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7884
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Fri, Jan 2, 2026 7:51 AM	#52 2019 Kenworth W900	
Scheduled Start Date:	Fri, Jan 2, 2026 7:52 AM	VIN/SN: 1XKWP4EX7KR955710 License Plate:	
Actual Start Date:	Fri, Jan 2, 2026 7:52 AM	Operator: Bill Bromley Type: Tri Drive Group:	
Expected Completion Date:			
Actual Completion Date:	Fri, Jan 2, 2026 7:52 AM	Odometer: 423,137km Secondary Meter: 22,991hr (voided meter)	
Duration:			
Repair Priority Class:	Scheduled		
Status:	Completed		
Issued By:	Joseph Pitney		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 A3 temp wire repair	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 A3 Output Yoke Nut Loose	\$19.50	\$0.00	\$19.50
 Joseph Pitney (Contact)	0.5 hrs \$39.00		\$19.50
 A3 input seal leaking	\$68.25	\$87.40	\$155.65
 Joseph Pitney (Contact)			\$68.25
 jack up axle remove driveshaft then yoke had to use puller remove old seal clean bore remove speedy sleeve from yoke and install new one install seal lube yoke and install put up driveshaft			
	1.75 hrs \$39.00		
 FGR11205X2728 (Part) - Main	1 ea		\$87.40
PINION SEAL, FORWARD INPUT S/AS GWKAS2728	\$87.40		

Item	Labor	Parts	Subtotal
 Positive air wire broken under dash	\$14.00	\$17.65	\$31.65
 Ricky Peters (Contact) 0.5 hrs  Installed new toggle switch \$28.00			\$14.00
 FGR558210 (Part) · Main 1 ea SWITCH TOGGLE WATERPR \$17.65			\$17.65
 A2 temp pigtail replacement	\$9.75	\$12.35	\$22.10
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
 FGR6451000 (Part) · Main 1 ea DIFF SENSOR HARNESS, S/AS GWK3823256 \$12.35			\$12.35
 Reverse alarm wire broken at alarm	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact) 0.75 hrs \$39.00			\$29.25
 Engine Oil & Filter Replacement	\$11.00	\$340.66	\$351.66
 MICHAEL ABLOG (Contact) 0.25 hrs \$44.00			\$11.00
 NXTDBL7900 (Part) · Main 1 ea OIL FILTER HIGH EFFICIENCY S/AS BD50000 \$61.04			\$61.04
 MXF5W40 (Part) · Main 41 L ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER \$6.82			\$279.62
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
 Check Diff and Trans Oil	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.75	\$0.00	\$9.75

Item	Labor	Parts	Subtotal
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Torque Wheels Verify wheels are properly torqued	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Walk Around Inspection	\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.50	\$4.67	\$24.17
Joseph Pitney (Contact) 0.5 hrs \$39.00			\$19.50
MNACHV259119-652 (Part) - Main STARPLEX EP1 Winter GREASE 1 ea \$4.67			\$4.67

DESCRIPTION

SUMMARY

Subtotal	\$722.73
Labor	\$260.00
Parts	\$462.73
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$722.73

Issue	Assigned	Due
#15249 [Inspection] A3 input seal leaking...A3 output nut loose Reported 8 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 2, 2026 at 7:49 AM MST		
#15248 [Inspection] wire broken at alarm Reported 8 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Back up alarm" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 2, 2026 at 7:49 AM MST		
#15247 [Inspection] wire broken at switch under dash Reported 8 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Positive Air function" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 2, 2026 at 7:49 AM MST		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7735
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Thu, Dec 11, 2025 10:08 AM	#52 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWP4EX7KR955710
Actual Start Date:	Thu, Dec 11, 2025 10:08 AM	License Plate:	
Expected Completion Date:		Operator:	Bill Bromley
Actual Completion Date:	Fri, Dec 12, 2025	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	422,143km
Status:	Completed	Secondary Meter:	22,658hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Air to Air Clamps	\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)	0.25 hrs		\$11.00
 tightened clamps	\$44.00		
 #14989 - [Inspection] Rh air to air clamps loose Generated by the failed inspection item "Air to Air Boots and Clamps" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Dec 11, 2025 at 11:51 AM MST			
 Rh Headlight Wire Repair	\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)	0.25 hrs		\$11.00
 DS Stack Pin	\$14.50	\$64.33	\$78.83
 Chad Caouette (Contact)	0.5 hrs		\$14.50
 replaced bush stack pin	\$29.00		
 GWKM13-1011 (Part) - Main EXHAUST BUSHING SPHER	1 ea		\$20.28
	\$20.28		

Item	Labor	Parts	Subtotal
 GWKEM75-69000HTATR (Part) · Main EXHAUST MOUNT BUSHING	1 ea \$44.05		\$44.05
 #14988 · [Inspection] Lh stack bushings Generated by the failed inspection item "Stack Bushings" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Dec 11, 2025 at 11:51 AM MST			
 ds mirror replacement	\$49.00	\$81.95	\$130.95
 Ricky Peters (Contact)	1.75 hrs \$28.00		\$49.00
 FGR1246364LED (Part) · Main MIRROR, 7" X 16" HEATED LED	1 ea \$81.95		\$81.95
 #14991 · [Inspection] Lh Side mirror replacement Generated by the failed inspection item "Mirrors" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Dec 11, 2025 at 11:51 AM MST			
 Check engine heater circuits	\$22.00	\$0.00	\$22.00
 MICHAEL ABLOG (Contact)			\$22.00
 main plug to the engine heater is packed with dialectic grease. brake cleaned all of it off and plugged it back in		0.5 hrs \$44.00	
 Crossmember Bolts	\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)	0.25 hrs \$44.00		\$11.00
 replaced bolt			
 #14987 · [Inspection] Crossmember bolt behind transmission Generated by the failed inspection item "Cross Member and Frame Cracks" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Dec 11, 2025 at 11:51 AM MST			
 Truck Preventative Maintenance Inspection	\$22.00	\$0.00	\$22.00
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 Air Dryer Cartridge Replacement	\$7.00	\$20.41	\$27.41
 Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
 WSTN1335130010860 S/AS AC1001 (Part) · Main (Archived) AIR DRYER CARTRIDGE	1 ea \$20.41		\$20.41
 #14986 · [Inspection] Air dryer cartridge replacement Generated by the failed inspection item "Air Dryer Condition" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Dec 11, 2025 at 11:51 AM MST			
 Lh Hood Pin Cracked	\$11.00	\$63.35	\$74.35
 MICHAEL ABLOG (Contact)	0.25 hrs \$44.00		\$11.00
 replaced bracket and pin			

Item	Labor	Parts	Subtotal
HVE87096 (Part) · Main HOOD PIN BRACKETS CUS			\$42.50
	1 ea		
	\$42.50		
FGRM17402 (Part) · Main HOOD PIN AUTOMAN	1 ea		\$20.85
	\$20.85		
#14990 · [Inspection] Lh hood pin bracket cracked Generated by the failed inspection item "Hood Operation" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Dec 11, 2025 at 11:51 AM MST			
Fuel Filters Replacement	\$11.00	\$110.29	\$121.29
MICHAEL ABLOG (Contact)	0.25 hrs		\$11.00
	\$44.00		
BALPF46081 (Part) · Main (Archived) BALDWIN FUEL FILTER	1 ea		\$45.27
	\$45.27		
NTXDBF6776 (Part) · Main FUEL FILTER SPIN ON S/AS BF46129	1 ea		\$65.02
	\$65.02		
Engine Oil & Filter Replacement	\$11.00	\$343.12	\$354.12
MICHAEL ABLOG (Contact)	0.25 hrs		\$11.00
	\$44.00		
MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	41 L		\$282.08
	\$6.88		
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea		\$61.04
	\$61.04		
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$7.00	\$0.00	\$7.00
Ricky Peters (Contact)	0.25 hrs		\$7.00
	\$28.00		
Check Diff and Trans Oil	\$11.00	\$0.00	\$11.00
MICHAEL ABLOG (Contact)	0.25 hrs		\$11.00
	\$44.00		
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$7.25	\$0.00	\$7.25
Chad Caouette (Contact)	0.25 hrs		\$7.25
	\$29.00		


Item	Labor	Parts	Subtotal
↳ Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
👤 Allan Bates (Contact)	0.25 hrs \$31.00		\$7.75
↳ Torque Wheels Verify wheels are properly torqued	\$7.75	\$0.00	\$7.75
👤 Allan Bates (Contact)	0.25 hrs \$31.00		\$7.75
↳ Walk Around Inspection	\$11.00	\$0.00	\$11.00
👤 MICHAEL ABLOG (Contact)	0.25 hrs \$44.00		\$11.00
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$11.00	\$0.00	\$11.00
👤 MICHAEL ABLOG (Contact)	0.25 hrs \$44.00		\$11.00
🔧 Repair left exhaust stack	\$43.50	\$23.65	\$67.15
👤 Chad Caouette (Contact)	1.5 hrs \$29.00		\$43.50
🔧 FGRSW50A3 (Part) · Main EXHAUST CLAMP 5" SS	1 ea \$23.65		\$23.65

DESCRIPTION

SUMMARY

Subtotal	\$993.85
Labor	\$286.75
Parts	\$707.10
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$993.85

Issue	Assigned	Due
#14957 [Inspection] Above Defects have been Repaired Reported 9 months ago by Bill Bromley • Daily (Pre-Trip Inspection) by Bill Bromley Generated by the failed inspection item "Above Defects have been Repaired" on the "Daily (Pre-Trip Inspection)" form submitted by Bill Bromley on Dec 10, 2025 at 5:47 AM MST		
#14863 [Inspection] A3 lhs shock Reported 9 months ago by Roper Gorgichuk • Truck Preventative Maintenance Checklist by Bill Bromley Generated by the rejection of resolved Issue #14707 on the Truck Preventative Maintenance Checklist submitted by Bill Bromley on Dec 3, 2025 at 6:57 AM		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7703
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Sat, Dec 6, 2025 9:34 AM	#52 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWP4EX7KR955710
Actual Start Date:	Sat, Dec 6, 2025 8:30 AM	License Plate:	
Expected Completion Date:		Operator:	Bill Bromley
Actual Completion Date:	Sat, Dec 6, 2025 8:30 AM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	420,114km
Status:	Completed	Secondary Meter:	22,561hr
Issued By:	MICHAEL ABLOG		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Rh Low Beam Out	\$66.00	\$296.15	\$362.15
MICHAEL ABLOG (Contact)	1.5 hrs \$44.00		\$66.00
GWK0551771 (Part) - Main SPEAKER LOW,HEATED	1 ea \$296.15		\$296.15

DESCRIPTION

SUMMARY

Subtotal	\$362.15
Labor	\$66.00
Parts	\$296.15
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$362.15



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7584
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Thu, Nov 20, 2025 1:26 PM	#52 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWP4EX7KR955710
Actual Start Date:	Thu, Nov 20, 2025 1:26 PM	License Plate:	
Expected Completion Date:		Operator:	Bill Bromley
Actual Completion Date:	Fri, Nov 21, 2025	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	418,151km
Status:	Completed	Secondary Meter:	22,385hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$42.00	\$0.00	\$42.00
 Roper Gorgichuk (Contact)	1 hr \$42.00		\$42.00
 Phone Booster Repair Or Replace Repair or replace phone booster  Check phone booster dispatch reported it not working well.	\$31.50	\$0.00	\$31.50
 Roper Gorgichuk (Contact)  Swapped antenna and checked power to module	0.75 hrs \$42.00		\$31.50
 Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs \$31.00		\$7.75
 Torque Wheels Verify wheels are properly torqued	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75

Item	Labor	Parts	Subtotal
	\$22.50	\$0.00	\$22.50
↳ Walk Around Inspection			
JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
↳ Grease Unit	\$19.50	\$4.67	\$24.17
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.			
Joseph Pitney (Contact) 0.5 hrs \$39.00			\$19.50
MNACHV259119-652 (Part) · Main 1 ea \$4.67 STARPLEX EP1 Winter GREASE			\$4.67
↳ Engine Oil & Filter Replacement	\$0.00	\$0.00	\$0.00
No oil change			
↳ Air System Leaks	\$9.75	\$0.00	\$9.75
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Check Diff and Trans Oil	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
↳ Inspect and Service Trailer Hitch	\$9.75	\$0.00	\$9.75
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.			
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
🔧 Drivers fog light	\$19.50	\$185.14	\$204.64
Joseph Pitney (Contact) 0.5 hrs \$39.00			\$19.50
GWKLED500 (Part) · Main 1 ea \$185.14 AUXILIARY DRIVING LAM			\$185.14
#14706 · [Inspection] Fog Lights Generated by the failed inspection item "Fog Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Nov 21, 2025 at 8:38 AM MST			
🔧 Engine Heater Repair F33	\$105.00	\$38.43	\$143.43

Item	Labor	Parts	Subtotal
Roper Gorgichuk (Contact) Replaced fan cover and replaced coolant temp sensors. Swapped water pump as well 2.5 hrs \$42.00			\$105.00
PWR25.2435.99.0103.0D (Part) · Main TPD COVER 1 ea \$38.43			\$38.43
A2 Lhs shock leaking	\$29.25	\$103.15	\$132.40
Joseph Pitney (Contact) 0.75 hrs \$39.00			\$29.25
90045812 (Part) · Main SHOCK , NEWAY 9004580 1 ea \$103.15			\$103.15
#14707 · [Inspection] A3 lhs shock Generated by the failed inspection item "Shocks" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Nov 21, 2025 at 8:38 AM MST			
coolant leak repair	\$63.00	\$24.23	\$87.23
Roper Gorgichuk (Contact) Replaced EGR pipe o-ring from spares. And replaced coolant line along the frame 1.5 hrs \$42.00			\$63.00
GWK3683607CUM (Part) · Main SEAL, MOLDED 1 ea \$4.07			\$4.07
MNACHV227811-492 (Part) · Main CHEVRON DELO 50/50ELC ANTIFREEZE 2 ea \$10.08			\$20.16

DESCRIPTION

SUMMARY

Subtotal	\$734.62
Labor	\$379.00
Parts	\$355.62
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$734.62

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#14681 Driving lights need to be adjusted and driver side one replaced. Reported Nov 19, 2025 by Bill Bromley		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7537
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Nov 11, 2025 8:29 AM	#52 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWP4EX7KR955710
Actual Start Date:	Mon, Nov 10, 2025 9:30 AM	License Plate:	
Expected Completion Date:		Operator:	Bill Bromley
Actual Completion Date:	Mon, Nov 10, 2025 9:30 AM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	416,940km
Status:	Completed	Secondary Meter:	22,263hr
Issued By:	MICHAEL ABLOG		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Lh Windshield Replacement	\$11.00	\$58.93	\$69.93
 MICHAEL ABLOG (Contact)	0.25 hrs \$44.00		\$11.00
 GWKDW1164-30 (Part) - Main WINDSHIELD, DS	1 ea \$58.93		\$58.93
 Cab Detail	\$220.00	\$0.00	\$220.00
 MICHAEL ABLOG (Contact)	5 hrs \$44.00		\$220.00

• DESCRIPTION

SUMMARY

Subtotal	\$289.93
Labor	\$231.00
Parts	\$58.93
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$289.93