



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8981
Invoice Number:
PO Number:

H15-4
SEP

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Jun 23, 2026 9:30 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Tue, Jun 23, 2026 9:30 AM	License Plate:	
Expected Completion Date:		Operator:	N/A
Actual Completion Date:	Wed, Jun 24, 2026	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	604,383km (voided meter)
Status:	Completed	Secondary Meter:	17,155hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Engine Air Filter Replacement	\$15.50	\$178.30	\$193.80
 Allan Bates (Contact)	0.5 hrs \$31.00		\$15.50
 NTXP625287 (Part) - Main AIR FILTER T800	2 ea \$89.15		\$178.30
 Truck Preventative Maintenance Inspection	\$31.50	\$0.00	\$31.50
 Ernesto Ablog (Contact)	0.75 hrs \$42.00		\$31.50
 Star link not working	\$21.00	\$0.00	\$21.00
 Ernesto Ablog (Contact)  Replaced switch (used beacon switch)	0.5 hrs \$42.00		\$21.00
 Fuel Filters Replacement	\$10.50	\$113.32	\$123.82
 Ernesto Ablog (Contact)	0.25 hrs \$42.00		\$10.50

Item		Labor	Parts	Subtotal
 P581299 (Part) · Main	1 ea			\$44.56
Fuel filter same as K37-1029 & PF46081	\$44.56			
 NTXDBF6776 (Part) · Main	1 ea			\$68.76
FUEL FILTER SPIN ON S/AS BF46129	\$68.76			
 Air Dryer Cartridge Replacement		\$7.75	\$25.43	\$33.18
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
 950011-G3 (Part) · Main	1 ea			\$25.43
Fleet Spec Air Dryer Cartridge Same As ABPN1335130010860	\$25.43			
 Clutch Pedal Not Returning		\$42.00	\$66.69	\$108.69
 Ernesto Ablog (Contact)	1 hr			\$42.00
 Replaced bottom needle bearing	\$42.00			
 GWK1R812 (Part) · Main	1 ea			\$32.39
INNER RACE / CLUTCH	\$32.39			
 GWKHJ122012 (Part) · Main	1 ea			\$34.30
NEEDLE BEARING / CLUT	\$34.30			
 Engine Oil & Filter Replacement		\$0.00	\$0.00	\$0.00
 No change due				
 Air System Leaks		\$7.75	\$0.00	\$7.75
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.				
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
 Check Diff and Trans Oil		\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
 Inspect and Service Trailer Hitch		\$0.00	\$0.00	\$0.00
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 Not due for greasing				
 Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
 Allan Bates (Contact)	0.25 hrs			\$7.75
	\$31.00			
 Torque Wheels		\$7.75	\$0.00	\$7.75
Verify wheels are properly torqued				

Item		Labor	Parts	Subtotal
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$7.75	\$4.67	\$12.42
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 MNACHV259118-652 (Part) - Main STARPLEX EP2 TUBE Summer Grease	1 ea \$4.67			\$4.67

DESCRIPTION

SUMMARY

Subtotal	\$577.91
Labor	\$189.50
Parts	\$388.41
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$577.91

Issue	Assigned	Due
#17479 [Inspection] Clutch Linkage Condition Reported 2 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Clutch Linkage Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Jun 23, 2026 at 2:57 PM MDT		
#17478 [Inspection] Air Dryer Condition Reported 2 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Air Dryer Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Jun 23, 2026 at 2:57 PM MDT		
#17420 Steer chain has bent tensioner Reported Jun 18, 2026 by Todd Moore Steer chain is hanging on the passenger side, the tensioning arm you use to tighten the chain is bent		
#17421 Starlink not working Reported Jun 18, 2026 by Todd Moore Worked fine for both days I was in the truck until the last hour or two. Quit showing up in the network options in my devices.		
#17362 Pro heat not working Reported Jun 10, 2026 by Todd Moore Shows an error code when you try to set it, runs for a few seconds, then shuts down		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8745
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, May 11, 2026 8:54 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Mon, May 11, 2026 8:54 AM	License Plate:	
Expected Completion Date:		Operator:	N/A
Actual Completion Date:	Tue, May 12, 2026	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	683,120km
Status:	Completed	Secondary Meter:	17,086hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Truck Preventative Maintenance Inspection	\$42.00	\$0.00	\$42.00
Roper Gorgichuk (Contact)	1 hr \$42.00		\$42.00
Engine Oil & Filter Replacement	\$10.50	\$222.63	\$233.13
Roper Gorgichuk (Contact)	0.25 hrs \$42.00		\$10.50
MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL	38 L \$4.16		\$158.08
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$64.55		\$64.55
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$10.50	\$0.00	\$10.50

Item	Labor	Parts	Subtotal
Roper Gorgichuk (Contact) 0.25 hrs \$42.00			\$10.50
Check Diff and Trans Oil	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$10.50	\$0.00	\$10.50
Roper Gorgichuk (Contact) 0.25 hrs \$42.00			\$10.50
Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Torque Wheels Verify wheels are properly torqued	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Walk Around Inspection	\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
transmission output yoke seal	\$152.25	\$161.32	\$313.57
Chad Caouette (Contact) removed drive line and steady bearing removed output yoke removed worn seal replaced yoke seal reinstalled yoke and drive line 5.25 hrs \$29.00			\$152.25
FGRK2918 (Part) · Main TRANS OUTPUT SEAL 1 ea \$44.62			\$44.62
SPI2507018X (Part) · Main SPL250-BEARING RETAIN 2 ea \$26.80			\$53.60
GWKK4122 (Part) · Main TRANSMISSION OUTPUT N 1 ea \$43.80			\$43.80

Item		Labor	Parts	Subtotal
	FGR2507411 (Part) · Main NUT FLANGE SPL140/25 Yellow Painted Ring	1 ea \$19.30		\$19.30
	A1Rhs Brake Shoes	\$105.00	\$1,011.05	\$1,116.05
	Roper Gorgichuk (Contact)	2.5 hrs \$42.00		\$105.00
	FGRXSS504709E2K (Part) · Main BRAKE SHOE DRIVE16.5X	1 ea \$67.85		\$67.85
	GWKBEN314146 (Part) · Main MINOR BRAKE HARDWARE SAME AS E10760	1 ea \$18.40		\$18.40
	GWK817009 (Part) · Main RETAINER COLLAR FRONT	1 ea \$28.24		\$28.24
	FGRCM10082213 (Part) · Main T800 STEER HUB/LOADED	1 ea \$844.35		\$844.35
	MNACHV223030953 (Part) · Main DELO S-G XDM 75W90 SYNTHETIC GEAR OIL 7590	1 L \$9.78		\$9.78
	WST 10045883.00 (Part) · Main WHEEL SEAL, STEER, SAME AS RM-S05	1 ea \$42.43		\$42.43
	#17062 · [Inspection] transmission out put yoke leaking Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on May 11, 2026 at 10:01 AM MDT			
	#17061 · [Inspection] A1 rhs brake shoes splitting Generated by the failed inspection item "Brake Lining Thickness 5/16" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on May 11, 2026 at 10:01 AM MDT			

DESCRIPTION

SUMMARY

Subtotal	\$1,779.25
Labor	\$384.25
Parts	\$1,395.00
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,779.25



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8611
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Apr 20, 2026 3:41 PM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Mon, Apr 20, 2026 3:41 PM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Tue, Apr 21, 2026	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	600,772km
Status:	Completed	Secondary Meter:	16,956hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$42.00	\$0.00	\$42.00
 Roper Gorgichuk (Contact)	1 hr \$42.00		\$42.00
 Engine Oil & Filter Replacement	\$10.50	\$222.63	\$233.13
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00		\$10.50
 MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL	38 L \$4.16		\$158.08
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$64.55		\$64.55
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$10.50	\$0.00	\$10.50

Item		Labor	Parts	Subtotal
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 Check Diff and Trans Oil		\$10.50	\$0.00	\$10.50
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Tire Condition and Pressure Inspection Check all tires		\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Torque Wheels Verify wheels are properly torqued		\$10.50	\$0.00	\$10.50
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$10.50	\$4.67	\$15.17
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 MNACHV259119-652 (Part) · Main STARPLEXEP1 Winter GREASE	1 ea \$4.67			\$4.67
 Weld cracks on cooler mount		\$21.00	\$0.00	\$21.00
 Roper Gorgichuk (Contact)	0.5 hrs \$42.00			\$21.00
 Transmission Cooler Replacement		\$105.00	\$1,194.16	\$1,299.16
 Roper Gorgichuk (Contact)	2.5 hrs \$42.00			\$105.00
 GWKK3966 (Part) · Main HEAT EXCHANGER TRANS	1 ea \$1,031.56			\$1,031.56

Item	Labor	Parts	Subtotal
MXFCD50 (Part) - Main TRANSMISSION OIL	15 L		\$162.60
	\$10.84		

DESCRIPTION

SUMMARY

Subtotal	\$1,679.96
Labor	\$258.50
Parts	\$1,421.46
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,679.96



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8570
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Apr 13, 2026 10:50 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Mon, Apr 13, 2026 10:50 AM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Mon, Apr 13, 2026 10:50 AM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	598,737km
Status:	Completed	Secondary Meter:	16,860hr
Issued By:	Kurt Kerekanich		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Replace Signal Stat	\$20.00	\$154.89	\$174.89
Ernesto Ablog (Contact)	0.5 hrs \$40.00		\$20.00
GWKGW27764 (Part) - Main SWITCH-TURN SIGNAL LEVER SAME ASTL80030	1 ea \$154.89		\$154.89

PARTS (not linked to a Service Task)

Part	Quantity	Unit cost	Subtotal
GWKC5720S (Part) - Main WASHER RESERVOIR CAP	1 ea	\$3.95	\$3.95

DESCRIPTION

SUMMARY

Subtotal	\$178.84
Labor	\$20.00
Parts	\$158.84
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$178.84

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#16697	Turn signals not working Reported Apr 11, 2026 by Michael Clarke Turn signal lever not working	
#16696	Turn signals not working Reported Apr 11, 2026 by Michael Clarke Turn signal lever broke. Need replace	
#16698	Turn signals not working Reported Apr 11, 2026 by Michael Clarke Signal lever broken need replace	



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8462
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Mar 31, 2026 7:59 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Tue, Mar 31, 2026 7:59 AM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Tue, Mar 31, 2026 7:59 AM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Scheduled	Odometer:	596,955km
Status:	Completed	Secondary Meter:	16,766hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$21.75	\$0.00	\$21.75
 Chad Caouette (Contact)	0.75 hrs		\$21.75
	\$29.00		
 Engine Oil & Filter Replacement	\$7.25	\$319.11	\$326.36
 Chad Caouette (Contact)	0.25 hrs		\$7.25
	\$29.00		
 MXF5W40 (Part) · Main	37 L		\$254.56
ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER			\$6.88
 NXTDBL7900 (Part) · Main	1 ea		\$64.55
OIL FILTER HIGH EFFICIENCY S/AS BD50000			\$64.55
 Air System Leaks	\$10.50	\$2.15	\$12.65
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			

Item		Labor	Parts	Subtotal
Roper Gorgichuk (Contact) 0.25 hrs fixed air leak going relay valve above axle 3 \$42.00				\$10.50
FGR14624 (Part) · Main 1 ea UNION 1/4" \$2.15				\$2.15
↳ Check Diff and Trans Oil		\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00				\$9.75
↳ Inspect and Service Trailer Hitch		\$7.25	\$0.00	\$7.25
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
Chad Caouette (Contact) 0.25 hrs \$29.00				\$7.25
↳ Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
Allan Bates (Contact) 0.25 hrs \$31.00				\$7.75
↳ Torque Wheels		\$9.75	\$0.00	\$9.75
Verify wheels are properly torqued				
Joseph Pitney (Contact) 0.25 hrs \$39.00				\$9.75
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00				\$22.50
↳ Grease Unit		\$19.50	\$4.67	\$24.17
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
Joseph Pitney (Contact) 0.5 hrs \$39.00				\$19.50
MNACHV259119-652 (Part) · Main 1 ea STARPLEX EP1 Winter GREASE \$4.67				\$4.67
🔧 air to air bushing rh side		\$14.50	\$0.00	\$14.50
Chad Caouette (Contact) 0.5 hrs replaced worn out air to air bushings with used exhaust bushings \$29.00				\$14.50
🔧 A4 RHS Brake Pads		\$42.00	\$0.00	\$42.00

Item	Labor	Parts	Subtotal
Roper Gorgichuk (Contact) inspected brakes, wheel seal and drum. found the orange air line going to the quick release valve wasn't installed properly fixed fitting. checked brake operations 1 hr \$42.00			\$42.00
ds fog light out	\$14.50	\$185.14	\$199.64
Chad Caouette (Contact) fog light burnt out replaced light 0.5 hrs \$29.00			\$14.50
GWKLED500 (Part) - Main AUXILIARY DRIVING LAM 1 ea \$185.14			\$185.14
Check Steer Alignment	\$53.25	\$0.00	\$53.25
Chad Caouette (Contact) 0.75 hrs \$29.00			\$21.75
Roper Gorgichuk (Contact) adjust A4 axle it was out an inch checked drive alignment and drive to steer alignment 0.75 hrs \$42.00			\$31.50

DESCRIPTION

SUMMARY

Subtotal	\$751.32
Labor	\$240.25
Parts	\$511.07
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$751.32

Issue	Assigned	Due
#16486 Truck passenger side rear drive axle almost caught fire a week ago Reported Mar 30, 2026 by Michael Clarke Tires need to be pulled off. Brake drum needs to be pulled off and pads and springs need inspecting. 5th time this axle has been worked on or looked at. Please inspect well. Don't want a fire.		
#16485 Truck pulls to the right Reported Mar 30, 2026 by Michael Clarke Truck pulls to the right.		
#16484 Hydraulic elbow on hydraulic in out lever leaking Reported Mar 30, 2026 by Michael Clarke Hydraulic elbow in pump box leaking. Might only needing tightening. Did not have big enough wrench. Did not want to make it worse if worn out		
#16433 Rear axle passenger side brake on truck almost caught fire again Reported Mar 26, 2026 by Michael Clarke Rear axle passenger side axle every shift want to drag and catch fire. Good thing I stopped and it was cooking.		
#16483 Front spot light burnt out Reported Mar 30, 2026 by Michael Clarke One out of 2 fog. Spot lights burn out		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8349
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Mar 10, 2026 8:17 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Tue, Mar 10, 2026 8:17 AM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Fri, Mar 13, 2026	Type:	Tri Drive
Duration:	3 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	593,348km
Status:	Completed	Secondary Meter:	16,566hr
Issued By:	Ernesto Ablog		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Exhaust Bellows Broken	\$28.00	\$387.52	\$415.52
 Ricky Peters (Contact)	1 hr \$28.00		\$28.00
 NTX1000-FB0320 (Part) - Main FLEX BELLOWS CUMMINS	1 ea \$350.00		\$350.00
 GWK90-0012 (Part) - Main V BAND CLAMP	1 ea \$17.15		\$17.15
 GWK2866636CUM (Part) - Main EXHAUST GASKET 4"	1 ea \$20.37		\$20.37
 #16228 - [Inspection] Below pipe leaking Generated by the failed inspection item "Exhaust Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT			
 DS Winshield Replacement	\$20.00	\$58.93	\$78.93
 Ernesto Ablog (Contact)	0.5 hrs \$40.00		\$20.00

Item		Labor	Parts	Subtotal
 GWKDW1164-30 (Part) · Main	1 ea			\$58.93
WINDSHIELD, DS	\$58.93			
 #16188 · Crack in driver's side windshield				
Windshield cracked. Does not impede sight.				
 #16230 · [Inspection] Ds window				
Generated by the failed inspection item "Windshields" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT				
 A4Rhs Brake Pot & Slack		\$56.00	\$305.80	\$361.80
 Ricky Peters (Contact)	2 hrs			\$56.00
	\$28.00			
 FGR40020234 (Part) · Main	1 ea			\$154.90
SLACK ADJUSTER 6" 28	\$154.90			
 FGRLCP3030 (Part) · Main	1 ea			\$148.90
LIFESEAL 2.5, BRAKE P	\$148.90			
 FGRE1782 (Part) · Main	2 ea			\$1.00
CAM WASHER	\$0.50			
 FGRE3234 (Part) · Main	1 ea			\$1.00
SCAM LOCK RING	\$1.00			
 #16079 · Rear drive axle passenger side brake stuck on. Caged brake. Shaft was not taking grease so replaced nipple and regressed. Will stay caged off.				
Brake stuck was about to start smokin so caged it off. Rear drive axle passenger side. Proly the 4th time written up.				
 #16080 · Rear drive axle passenger side brake stuck on				
Caged brake pot. Replaced grease nipple on shaft. Would not take grease. Left caged. 4th? Time axle has been written up.				
 #16224 · [Inspection] Brake Pot Condition				
Generated by the failed inspection item "Brake Pot Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT				
 #16225 · [Inspection] Slack Adjusters				
Generated by the failed inspection item "Slack Adjusters" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT				
 A4 Both Airbag Worn Out		\$61.50	\$372.14	\$433.64
 Kurt Kerekanich (Contact)	1.5 hrs			\$61.50
	\$41.00			
 GWKAS95010 (Part) · Main	2 ea			\$372.14
AIR BAG NEWAY	\$186.07			
 #16223 · [Inspection] Air Bag Condition				
Generated by the failed inspection item "Air Bag Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT				
 A3 Both Airbags Worn out		\$61.50	\$372.14	\$433.64
 Kurt Kerekanich (Contact)	1.5 hrs			\$61.50
	\$41.00			

Item	Labor	Parts	Subtotal
GWKAS95010 (Part) · Main AIR BAG NEWAY	2 ea \$186.07		\$372.14
#16223 · [Inspection] Air Bag Condition Generated by the failed inspection item "Air Bag Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT			
A2 both airbags worn out	\$61.50	\$372.14	\$433.64
Kurt Kerekanich (Contact)	1.5 hrs \$41.00		\$61.50
GWKAS95010 (Part) · Main AIR BAG NEWAY	2 ea \$186.07		\$372.14
#16223 · [Inspection] Air Bag Condition Generated by the failed inspection item "Air Bag Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT			
Hydraulic Filter Replacement	\$7.00	\$14.71	\$21.71
Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
BALBT8443 (Part) · Main HYDRAULIC FILTER GARD S/AS P565059	1 ea \$14.71		\$14.71
Cab filter replacement	\$7.00	\$24.11	\$31.11
Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
GWKCF19501C (Part) · Main CAB AIR FILTER C/W CR	1 ea \$24.11		\$24.11
#16222 · [Inspection] Cab Air Filter Generated by the failed inspection item "Cab Air Filter" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT			
Stack Bushing RHS	\$20.00	\$63.00	\$83.00
Ernesto Ablog (Contact)	0.5 hrs \$40.00		\$20.00
GWKEM75-69000HTATR (Part) · Main EXHAUST MOUNT BUSHING	1 ea \$44.05		\$44.05
FGRM13109 (Part) · Main EXHAUST MOUNT BUSHING	1 ea \$18.95		\$18.95
#16227 · [Inspection] Stack Bushings Generated by the failed inspection item "Stack Bushings" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT			
Coolant Hoses Replacement	\$40.00	\$212.38	\$252.38

Item	Labor	Parts	Subtotal
Ernesto Ablog (Contact) Drain coolant and replaced 3" top hose and 1" long hose 1 hr \$40.00			\$40.00
GWKF50-1050-1050 (Part) · Main HOSE-RADIATOR, 16X105 1 ea \$102.91			\$102.91
GWKF04-6006 (Part) · Main COOLANT HOSE 2.5" 90 S/AS 56175250 1 ea \$109.47			\$109.47
#16229 · [Inspection] Coolant Hose Condition Generated by the failed inspection item "Coolant Hose Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT			
Truck Preventative Maintenance Inspection	\$30.75	\$0.00	\$30.75
Kurt Kerekanich (Contact) 0.75 hrs \$41.00			\$30.75
#16189 · Water in fuel separator On dash. Water in fuel separator. Prolly a bit of snow when fueling. I didn't want to try draining it and snap some thing. Left for days off.			
Lhs Draglink Worn Out	\$41.00	\$207.92	\$248.92
Kurt Kerekanich (Contact) 1 hr \$41.00			\$41.00
DLP3092S (Part) · Main (Archived) Drag Link T800 SAME AS L24VU844511A & GW22084 1 ea \$207.92			\$207.92
#16186 · Running the highway truck pulls to the right. Truck pulls to the right might need a steering arm? Bush is ok. Not doing highway speeds			
#16187 · Truck pulls to the right. Fine in the bush. Pulls to the right on the highway			
Engine Oil & Filter Replacement	\$10.00	\$319.11	\$329.11
Ernesto Ablog (Contact) 0.25 hrs \$40.00			\$10.00
MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER 37 L \$6.88			\$254.56
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000 1 ea \$64.55			\$64.55
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$14.00	\$0.00	\$14.00
Ricky Peters (Contact) 0.5 hrs \$28.00			\$14.00
Check Diff and Trans Oil	\$7.00	\$0.00	\$7.00

Item	Labor	Parts	Subtotal
Ricky Peters (Contact) 0.25 hrs \$28.00			\$7.00
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$7.00	\$0.00	\$7.00
Ricky Peters (Contact) 0.25 hrs \$28.00			\$7.00
Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Torque Wheels Verify wheels are properly torqued	\$7.25	\$0.00	\$7.25
Chad Caouette (Contact) 0.25 hrs \$29.00			\$7.25
Walk Around Inspection	\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$14.00	\$0.00	\$14.00
Ricky Peters (Contact) 0.5 hrs \$28.00			\$14.00

DESCRIPTION

SUMMARY

Subtotal	\$3,233.65
Labor	\$523.75
Parts	\$2,709.90
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$3,233.65

Issue	Assigned	Due
#16226 [Inspection] Drag Link Reported 6 months ago by Kurt Kerekanich • Truck Preventative Maintenance Checklist by Kurt Kerekanich Generated by the failed inspection item "Drag Link" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Mar 10, 2026 at 3:27 PM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8193
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Feb 17, 2026 10:56 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Tue, Feb 17, 2026 10:56 AM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Tue, Feb 17, 2026 10:56 AM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Scheduled	Odometer:	590,825km
Status:	Completed	Secondary Meter:	16,365hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Turn Signal Lever Replacement	\$20.00	\$149.80	\$169.80
 Ernesto Ablog (Contact)	0.5 hrs \$40.00		\$20.00
 FGR57775010 (Part) · Main (Archived) TURN SIGNAL LEVER	1 ea \$149.80		\$149.80
 Adjust Lh Air to Air Boot	\$20.00	\$0.00	\$20.00
 Ernesto Ablog (Contact)	0.5 hrs \$40.00		\$20.00
 Truck Preventative Maintenance Inspection	\$22.00	\$0.00	\$22.00
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 Lh Low Beam Repair	\$20.00	\$296.15	\$316.15
 Ernesto Ablog (Contact)  Replaced low beam	0.5 hrs \$40.00		\$20.00

Item	Labor	Parts	Subtotal
GWK0551771 (Part) · Main SPEAKER LOW,HEATED 1 ea \$296.15			\$296.15
#15938 · [Inspection] Lh Low beam out Generated by the failed inspection item "Head Lights" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Feb 17, 2026 at 11:32 AM MST			
Engine Oil & Filter Replacement	\$9.75	\$308.72	\$318.47
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER 36 L \$6.88			\$247.68
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000 1 ea \$61.04			\$61.04
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Check Diff and Trans Oil	\$7.00	\$0.00	\$7.00
Ricky Peters (Contact) 0.25 hrs \$28.00			\$7.00
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Tire Condition and Pressure Inspection Check all tires	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Torque Wheels Verify wheels are properly torqued	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Walk Around Inspection	\$22.50	\$0.00	\$22.50

Item	Labor	Parts	Subtotal
JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.50	\$4.67	\$24.17
Joseph Pitney (Contact) 0.5 hrs \$39.00			\$19.50
MNACHV259119-652 (Part) - Main STARPLEX EP1 Winter GREASE 1 ea \$4.67			\$4.67
A2 Output Yoke Nut Loose	\$29.25	\$0.00	\$29.25
Joseph Pitney (Contact) 0.75 hrs \$39.00			\$29.25

DESCRIPTION

SUMMARY

Subtotal	\$968.34
Labor	\$209.00
Parts	\$759.34
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$968.34

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#15937 [Inspection] Driveline and Steady Bearing Reported 6 months ago by MICHAEL ABLOG - Truck Preventative Maintenance Checklist by MICHAEL ABLOG Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Feb 17, 2026 at 11:32 AM MST		
#15763 Snapped off signal lever. Wipers still work. Reported Feb 4, 2026 by Michael Clarke Caught lever climbing into truck. Snapped off.		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7903
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Jan 5, 2026 5:09 PM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Mon, Jan 5, 2026 5:09 PM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Tue, Jan 6, 2026	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	588,971km
Status:	Completed	Secondary Meter:	16,183hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
Engine Oil & Filter Replacement No oil change required	\$0.00	\$0.00	\$0.00
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
Check Diff and Trans Oil	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75

Item	Labor	Parts	Subtotal
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
 Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
 Torque Wheels Verify wheels are properly torqued	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
 Walk Around Inspection	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.25	\$4.67	\$11.92
 Chad Caouette (Contact)  0.25 hrs \$29.00			\$7.25
 MNACHV259119-652 (Part) · Main STARPLEX EP1 Winter GREASE 1 ea \$4.67			\$4.67
 Fuel Filters Replacement	\$7.25	\$110.29	\$117.54
 Chad Caouette (Contact)  0.25 hrs \$29.00			\$7.25
 BALPF46081 (Part) · Main (Archived) BALDWIN FUEL FILTER 1 ea \$45.27			\$45.27
 NTXDBF6776 (Part) · Main FUEL FILTER SPIN ON S/AS BF46129 1 ea \$65.02			\$65.02
 check connection in work light socket	\$19.50	\$6.10	\$25.60
 Joseph Pitney (Contact)  replace plug soldered wire ends 0.5 hrs \$39.00			\$19.50
 GRO82-1021 (Part) · Main 4 POLE MALE PLUG 1 ea \$6.10			\$6.10
 A4R brake holding up	\$78.00	\$260.05	\$338.05

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)		1.25 hrs		\$48.75
	 replace relay valve	\$39.00		
 Joseph Pitney (Contact)				\$29.25
	 found QR valve leaking through exhaust port changed tried a number of applications of the service brakes did not find a problem	0.75 hrs \$39.00		
 FGR112D (Part) · Main		2 ea		\$3.10
	BRASS NIPPLE 1/2"	\$1.55		
 BEN803115 (Part) · Main		1 ea		\$105.10
	RELAY VALVE AIR BRAKE	\$105.10		
 BENOR289714X (Part) · Main		1 ea		\$148.15
	Truck Quick Release Valve	\$148.15		
 FGR546C (Part) · Main		1 ea		\$3.70
	SAE 45 ELB 3/8-3/8 MN	\$3.70		

DESCRIPTION

SUMMARY

Subtotal	\$589.61
Labor	\$208.50
Parts	\$381.11
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$589.61

Issue	Assigned	Due
#15170 Caged off back axle right side tractor Reported Dec 29, 2025 by Michael Clarke		
#15171 Brake pot on tractor right side rear axle. Caged off Reported Dec 29, 2025 by Michael Clarke Brake froze up was smokin good.		
#15284 Passenger rear axle brake pot caged. Reported Jan 5, 2026 by Michael Clarke Brake pot froze up. Tire almost caught fire. So caged. Check spring please		
#15306 [Inspection] possible fail A4R needs checking Reported 8 months ago by Joseph Pitney - Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Brake Pot Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 6, 2026 at 8:07 AM MST		
#15305 [Inspection] plug at trailer needs checking Reported 8 months ago by Joseph Pitney - Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Work Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 6, 2026 at 8:07 AM MST		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7823
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Dec 29, 2025 11:19 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Mon, Dec 29, 2025 11:20 AM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Mon, Dec 29, 2025 11:20 AM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	588,355km
Status:	Completed	Secondary Meter:	16,147hr
Issued By:	Kurt Kerekanich		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 ps low beam	\$20.50	\$296.15	\$316.65
 Kurt Kerekanich (Contact)	0.5 hrs		\$20.50
 Replace light	\$41.00		
 GWK0551771 (Part) · Main	1 ea		\$296.15
SPEAKER LOW,HEATED	\$296.15		

DESCRIPTION

SUMMARY

Subtotal	\$316.65
Labor	\$20.50
Parts	\$296.15
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$316.65



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7606
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Nov 24, 2025 4:27 PM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Mon, Nov 24, 2025 4:27 PM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Wed, Nov 26, 2025	Type:	Tri Drive
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	587,146km
Status:	Completed	Secondary Meter:	16,051hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
 Engine Oil & Filter Replacement	\$9.75	\$260.99	\$270.74
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 MNACHV259119-652 (Part) · Main STARPLEX EP1 Winter GREASE	1 ea \$4.67		\$4.67
 MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	36 L \$7.12		\$256.32
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.75	\$0.00	\$9.75

Item	Labor	Parts	Subtotal
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Check Diff and Trans Oil	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$7.25	\$0.00	\$7.25
Chad Caouette (Contact) 0.25 hrs \$29.00			\$7.25
Tire Condition and Pressure Inspection Check all tires	\$6.25	\$0.00	\$6.25
Jayden Binet (Contact) 0.25 hrs \$25.00			\$6.25
Torque Wheels Verify wheels are properly torqued	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Walk Around Inspection	\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.50	\$4.67	\$24.17
Joseph Pitney (Contact) 0.5 hrs \$39.00			\$19.50
MNACHV259119-652 (Part) · Main STARPLEX EP1 Winter GREASE 1 ea \$4.67			\$4.67
Replace Both Windshields	\$58.50	\$113.88	\$172.38
Joseph Pitney (Contact) 1.5 hrs \$39.00			\$58.50
GWKDW1164-30 (Part) · Main WINDSHIELD, DS 1 ea \$58.93			\$58.93
GWKDW1163-30 (Part) · Main WINDSHIELD , PS 1 ea \$54.95			\$54.95
#14749 · [Inspection] replace both windshield Generated by the failed inspection item "Windshields" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Nov 25, 2025 at 7:48 AM MST			

Item	Labor	Parts	Subtotal
 tighten right low beam	\$29.25	\$9.48	\$38.73
 Joseph Pitney (Contact) 0.75 hrs  replaced head light adjustment screws \$39.00			\$29.25
 GWKSTARR-AS2-50 (Part) · Main 2 ea HEADLIGHT ADJUSTMENT SCREW \$2.37			\$4.74
 GWKSTARR-AS2-50 (Part) · Main 2 ea HEADLIGHT ADJUSTMENT SCREW \$2.37			\$4.74
 #14732 · Front right side low beam loose Low beam out. Passenger side			
 #14751 · [Inspection] right side low beam loose Generated by the failed inspection item "Head Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Nov 25, 2025 at 7:48 AM MST			
 check left bumper bolt	\$19.50	\$0.00	\$19.50
 Joseph Pitney (Contact) 0.5 hrs  replaced bolt took out play \$39.00			\$19.50
 #14752 · [Inspection] check left side bolt for ware Generated by the failed inspection item "Bumper Bushing" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Nov 25, 2025 at 7:48 AM MST			
 clean mud on an around pedals	\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
 #14750 · [Inspection] mud on and around all pedals needs to be cleaned Generated by the failed inspection item "Foot Pedal Pivot Points" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Nov 25, 2025 at 7:48 AM MST			
 Rh Cab Shock Loose	\$10.50	\$0.00	\$10.50
 Roper Gorgichuk (Contact) 0.25 hrs  cab shock was not bolted on. bolt was installed but not into the shock \$42.00			\$10.50

DESCRIPTION

SUMMARY

Subtotal	\$640.27
Labor	\$251.25
Parts	\$389.02
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$640.27



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7500
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Nov 4, 2025 8:28 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Tue, Nov 4, 2025 8:28 AM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Wed, Nov 5, 2025	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	584,626km
Status:	Completed	Secondary Meter:	15,837hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Adjustment for fifth wheel	\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
 Cab shocks	\$56.00	\$117.10	\$173.10
 Ricky Peters (Contact)	2 hrs \$28.00		\$56.00
 FGR83031 (Part) · Main CAB SHOCK	2 ea \$58.55		\$117.10
 Back Up Alarm Doesn't Work	\$14.00	\$40.90	\$54.90
 Ricky Peters (Contact)	0.5 hrs \$28.00		\$14.00
 FGR575 (Part) · Main BACK UP ALARM 107DB S/AS 73090	1 ea \$40.90		\$40.90

Item	Labor	Parts	Subtotal
#14484 · [Inspection] Back up alarm Generated by the failed inspection item "Back up alarm" on the "Truck Preventative Maintenance Checklist" form submitted by Rickylynn Peters on Nov 4, 2025 at 9:46 AM MST			
AC Belt Replacement	\$14.00	\$176.21	\$190.21
Ricky Peters (Contact)	0.5 hrs \$28.00		\$14.00
VPS4120858X (Part) · Main CONTINENTAL XTREME HD BELT	1 ea \$133.00		\$133.00
GWK5060640 (Part) · Main A/C BELT	1 ea \$43.21		\$43.21
#14483 · [Inspection] Belt Tension and Condition Generated by the failed inspection item "Belt Tension and Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Rickylynn Peters on Nov 4, 2025 at 9:46 AM MST			
Engine Air Filter Replacement	\$21.00	\$178.30	\$199.30
Ricky Peters (Contact)	0.75 hrs \$28.00		\$21.00
NTXP625287 (Part) · Main AIR FILTER T800	2 ea \$89.15		\$178.30
Cab filter replacement	\$7.00	\$30.61	\$37.61
Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
GWKCF19501C (Part) · Main CAB AIR FILTER C/W CR	1 ea \$30.61		\$30.61
Air Dryer Cartridge Replacement	\$7.00	\$20.41	\$27.41
Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
WSTN1335130010860 S/AS AC1001 (Part) · Main (Archived) AIR DRYER CARTRIDGE	1 ea \$20.41		\$20.41
drivers wiper	\$7.00	\$10.80	\$17.80
Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
GWK66-150 (Part) · Main (Archived) BLADES WINTER WIPER	1 ea \$10.80		\$10.80
#14457 · Driver's side winshield wiper not wiping. New wiper blade needed. Driver's side			
Drive Tire Replacement	\$137.00	\$1,933.80	\$2,070.80
5 brand new and 7 95% take offs installed.			

Item		Labor	Parts	Subtotal
 Allan Bates (Contact)	2 hrs \$31.00			\$62.00
 Jayden Binet (Contact)	3 hrs \$25.00			\$75.00
 KALDT890 (Part) · Main ROAD X DRIVE TIRES 11R 245	5 ea \$386.76			\$1,933.80
 Clutch Adjustment		\$10.00	\$0.00	\$10.00
 Ernesto Ablog (Contact)	0.25 hrs \$40.00			\$10.00
 #14485 · [Inspection] clutch brake gap adjustment Generated by the rejection of resolved Issue #14203 on the Truck Preventative Maintenance Checklist submitted by Rickylynn Peters on Nov 4, 2025 at 10:35 AM				
 #14482 · [Inspection] Clutch Free Play Generated by the failed inspection item "Clutch Free Play" on the "Truck Preventative Maintenance Checklist" form submitted by Rickylynn Peters on Nov 4, 2025 at 9:46 AM MST				
 Truck Preventative Maintenance Inspection		\$21.00	\$0.00	\$21.00
 Ricky Peters (Contact)	0.75 hrs \$28.00			\$21.00
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Check Diff and Trans Oil		\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$6.25	\$0.00	\$6.25
 Jayden Binet (Contact)	0.25 hrs \$25.00			\$6.25
 Tire Condition and Pressure Inspection Check all tires		\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75

Item	Labor	Parts	Subtotal
#14458 · Tires Bald tires need tread.			
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
↳ Grease Unit	\$7.75	\$4.67	\$12.42
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.			
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
MNACHV259118-652 (Part) · Main 1 ea STARPLEX EP2 TUBE Summer Grease \$4.67			\$4.67
↳ Engine Oil & Filter Replacement	\$10.00	\$338.72	\$348.72
Ernesto Ablog (Contact) 0.25 hrs \$40.00			\$10.00
MXF5W40 (Part) · Main 39 L ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER \$7.12			\$277.68
NXTDBL7900 (Part) · Main 1 ea OIL FILTER HIGH EFFICIENCY S/AS BD50000 \$61.04			\$61.04
↳ Torque Wheels	\$13.25	\$0.00	\$13.25
Verify wheels are properly torqued			
Ricky Peters (Contact) 0.25 hrs \$28.00			\$7.00
Jayden Binet (Contact) 0.25 hrs \$25.00			\$6.25
🔧 Steer Tire Replacement	\$35.75	\$2.10	\$37.85
Ricky Peters (Contact) 0.25 hrs Removed wheels to go for changeover \$28.00			\$7.00
Jayden Binet (Contact) 0.25 hrs Buffed rims and installed after changeover \$25.00			\$6.25
JOE NEMEC (Contact) 0.25 hrs Hauled tires to Kal for changeover. New Bridgestone M864 tires installed. \$90.00			\$22.50
FGR6000 (Part) · Main 1 ea WHEEL NUT FLANGED .33 \$2.10			\$2.10
🔧 Re-Torque	\$67.50	\$0.00	\$67.50

Item	Labor	Parts	Subtotal
JOE NEMEC (Contact) Took unit for drive re-torqued wheels on whole unit and installed skid tags on trailer and caps on truck lug nuts.	0.75 hrs		\$67.50
	\$90.00		

DESCRIPTION

SUMMARY

Subtotal	\$3,340.87
Labor	\$487.25
Parts	\$2,853.62
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$3,340.87



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7331
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Oct 14, 2025 9:45 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Tue, Oct 14, 2025 9:46 AM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Tue, Oct 14, 2025 9:46 AM	Type:	Tri Drive
Duration:		Group:	
Repair Priority Class:	Scheduled	Odometer:	582,335km
Status:	Completed	Secondary Meter:	15,622hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
 Engine Oil & Filter Replacement	\$9.75	\$210.80	\$220.55
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$61.04		\$61.04
 MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL	36 L \$4.16		\$149.76
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.75	\$0.00	\$9.75

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Check Diff and Trans Oil		\$10.50	\$0.00	\$10.50
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 Inspect and Service Trailer Hitch		\$9.75	\$0.00	\$9.75
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Torque Wheels		\$10.50	\$0.00	\$10.50
Verify wheels are properly torqued				
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Grease Unit		\$10.50	\$4.67	\$15.17
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 MNACHV259118-652 (Part) · Main	1 ea \$4.67			\$4.67
STARPLEX EP2 TUBE Summer Grease				
 adjust clutch brake gap		\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 #14203 · [Inspection] clutch brake gap adjustment	Generated by the failed inspection item "Clutch Free Play" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Oct 14, 2025 at 10:24 AM MDT			
 PS westcoast mirror cracked		\$29.25	\$131.81	\$161.06
 Joseph Pitney (Contact)	0.75 hrs \$39.00			\$29.25

Item		Labor	Parts	Subtotal
 GWK140305 (Part) · Main	1 ea			\$131.81
REPLACEMENT MIRROR GLASS AND HEAT MOTO MIRRORS	\$131.81			
 #14202 · [Inspection] PS westcoast mirror cracked	Generated by the failed inspection item "Mirrors" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Oct 14, 2025 at 10:24 AM MDT			
 lift steer tires to grease kingpins		\$10.50	\$0.00	\$10.50
 Roper Gorgichuk (Contact)	0.25 hrs			\$10.50
	\$42.00			
 #14113 · When stopped. Turn steering wheel and it chatters.	Steering wheel vibrates and chatters when stopped and turning wheel both directions.			
 #14189 · Steering wheel chatters	Steering wheel vibrates. When sitting turning both ways. Needs steering box possibly.			

DESCRIPTION

SUMMARY

Subtotal	\$517.03
Labor	\$169.75
Parts	\$347.28
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$517.03



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7187
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Sep 24, 2025 10:30 AM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Wed, Sep 24, 2025 10:30 AM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Thu, Sep 25, 2025	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	580,116km
Status:	Completed	Secondary Meter:	15,426hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$42.00	\$0.00	\$42.00
 Roper Gorgichuk (Contact)	1 hr \$42.00		\$42.00
 Engine Oil & Filter Replacement	\$10.50	\$214.96	\$225.46
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00		\$10.50
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$61.04		\$61.04
 MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL	37 L \$4.16		\$153.92
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$10.50	\$0.00	\$10.50

Item		Labor	Parts	Subtotal
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
↳ Check Diff and Trans Oil		\$10.50	\$0.00	\$10.50
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
↳ Inspect and Service Trailer Hitch		\$10.50	\$0.00	\$10.50
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
↳ Tire Condition and Pressure Inspection		\$6.25	\$0.00	\$6.25
Check all tires				
 Jayden Binet (Contact)	0.25 hrs \$25.00			\$6.25
↳ Torque Wheels		\$13.25	\$0.00	\$13.25
Verify wheels are properly torqued				
 Ricky Peters (Contact)	0.25 hrs \$28.00			\$7.00
 Jayden Binet (Contact)	0.25 hrs \$25.00			\$6.25
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
↳ Grease Unit		\$10.50	\$4.67	\$15.17
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 MNACHV259118-652 (Part) · Main	1 ea \$4.67			\$4.67
STARPLEX EP2 TUBE Summer Grease				
 Air to Air Boot		\$10.50	\$39.18	\$49.68
 Roper Gorgichuk (Contact)	0.25 hrs \$42.00			\$10.50
 GWKHE8716 (Part) · Main	1 ea \$39.18			\$39.18
AIR-AIR BOOT 4"				

Item	Labor	Parts	Subtotal
#13964 · [Inspection] air to air boot Generated by the failed inspection item "Air Filter Boots and Clamps" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Sep 25, 2025 at 8:16 AM MDT			
#13963 · [Inspection] Air to Air Boots and Clamps Generated by the failed inspection item "Air to Air Boots and Clamps" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Sep 25, 2025 at 8:16 AM MDT			
zip tie air lines	\$31.50	\$0.00	\$31.50
Roper Gorgichuk (Contact) zip tied air compressor line off the trans cooler	0.75 hrs \$42.00		\$31.50
engine heater repair Diagnosis and repair engine heater.	\$10.50	\$0.00	\$10.50
Roper Gorgichuk (Contact) cleaned out the water pump. and ran the heater	0.25 hrs \$42.00		\$10.50
Tie Up Battery Cables By Oil Pan	\$10.50	\$0.00	\$10.50
Roper Gorgichuk (Contact)	0.25 hrs \$42.00		\$10.50

DESCRIPTION	SUMMARY
	Subtotal\$458.31 Labor\$199.50 Parts\$258.81 Labor Markup+ \$0.00 (0.0%) Parts Markup+ \$0.00 (0.0%) Warranty Credits- \$0.00 (0.0%) Discount- \$0.00 (0.0%) Tax+\$0.00 (0.0%) Total\$458.31

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#13733 Adjust Titan gauges to have spill alarm sound 2 cubes below spill. Reported Sep 10, 2025 by Scott Ritchie	JOE NEMEC	
#13954 Engine heater water pump Reported Sep 24, 2025 by JOE NEMEC		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7055
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Sep 2, 2025 4:55 PM	#77 2019 T800	
Scheduled Start Date:		VIN/SN:	1XKWDP4TX8LR961494
Actual Start Date:	Tue, Sep 2, 2025 4:55 PM	License Plate:	
Expected Completion Date:		Operator:	Michael Clarke
Actual Completion Date:	Wed, Sep 3, 2025	Type:	Tri Drive
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	577,786km
Status:	Completed	Secondary Meter:	15,219hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$28.50	\$0.00	\$28.50
 Ernesto Ablog (Contact)	0.75 hrs \$38.00		\$28.50
 Top up hydraulic oil	\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
 #13656 · [Inspection] Hydraulic Oil Level Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 3, 2025 at 8:08 AM MDT			
 Top rad bolts	\$19.00	\$0.00	\$19.00
 Ernesto Ablog (Contact)	0.5 hrs \$38.00		\$19.00
 5 inc Flex Pipe Clamp Leaking	\$19.00	\$12.20	\$31.20
 Ernesto Ablog (Contact)	0.5 hrs \$38.00		\$19.00
 Replaced clamp and put foil			

Item	Labor	Parts	Subtotal
FGR33225 (Part) · Main (Archived) 5" TORCTITE SS CLAMP 1 ea \$12.20			\$12.20
#13658 · [Inspection] Exhaust Leaks Generated by the failed inspection item "Exhaust Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 3, 2025 at 8:08 AM MDT			
A3 Input U joint Worn Out	\$21.00	\$164.25	\$185.25
Ricky Peters (Contact) 0.75 hrs \$28.00			\$21.00
SPI1707018X (Part) · Main STRAP KIT SPL170 1 ea \$25.95			\$25.95
SPISPL1704X (Part) · Main U JOINT 1 ea \$138.30			\$138.30
#13657 · [Inspection] Driveline and Steady Bearing Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 3, 2025 at 8:08 AM MDT			
Fuel Filters Replacement	\$9.50	\$65.02	\$74.52
Ernesto Ablog (Contact) 0.25 hrs \$38.00			\$9.50
NTXDBF6776 (Part) · Main FUEL FILTER SPIN ON S/AS BF46129 1 ea \$65.02			\$65.02
Fuel Filter Housing Broken	\$38.00	\$778.51	\$816.51
Ernesto Ablog (Contact) 1 hr \$38.00			\$38.00
Replaced fuel filter housing assembly			
GWKK37-1010-100111120 (Part) · Main FUEL FILTER HOUSING P 1 ea \$778.51			\$778.51
Engine Oil & Filter Replacement	\$9.50	\$214.96	\$224.46
Ernesto Ablog (Contact) 0.25 hrs \$38.00			\$9.50
NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000 1 ea \$61.04			\$61.04
MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL 37 L \$4.16			\$153.92
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$7.00	\$0.00	\$7.00

Item		Labor	Parts	Subtotal
 Ricky Peters (Contact)	0.25 hrs \$28.00			\$7.00
↳ Check Diff and Trans Oil		\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact)	0.25 hrs \$28.00			\$7.00
↳ Inspect and Service Trailer Hitch		\$9.50	\$0.00	\$9.50
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 Ernesto Ablog (Contact)	0.25 hrs \$38.00			\$9.50
↳ Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
↳ Torque Wheels		\$7.75	\$0.00	\$7.75
Verify wheels are properly torqued				
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
↳ Grease Unit		\$7.75	\$0.00	\$7.75
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75

DESCRIPTION

SUMMARY

Subtotal	\$1,455.69
Labor	\$220.75
Parts	\$1,234.94
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,455.69