



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #9376

Invoice Number:

PO Number:

H15-5
SEP

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Fri, Aug 28, 2026 8:28 AM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Fri, Aug 28, 2026 8:29 AM	License Plate:	
Expected Completion Date:		Operator:	N/A
Actual Completion Date:	Fri, Aug 28, 2026 8:29 AM	Type:	Tandem
Duration:		Group:	
Repair Priority Class:	Scheduled	Odometer:	1,431,958km
Status:	Completed	Secondary Meter:	30,843hr
Issued By:	Roper Gorgichuk		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 A3Rh Abs Repair	\$46.00	\$64.70	\$110.70
 MICHAEL ABLOG (Contact)	1 hr		\$46.00
 replaced sensor	\$46.00		
 FGR4410309102 (Part) · Main	1 ea		\$64.70
ABS SENSOR KIT, 90 DE	\$64.70		
 Air Leaks Repair	\$11.50	\$0.00	\$11.50
 Roper Gorgichuk (Contact)	0.25 hrs		\$11.50
 tighten main feed on air dryer	\$46.00		
 A3RH Torque Rod Bushings	\$42.00	\$89.80	\$131.80
 Kurt Kerekanich (Contact)	1 hr		\$42.00
	\$42.00		
 FGRTB6825 (Part) · Main	2 ea		\$89.80
V-ROD BUSHING TORQUE	\$44.90		
 Light Repair	\$11.50	\$0.00	\$11.50

Item	Labor	Parts	Subtotal
Roper Gorgichuk (Contact) swapped air cleaner light on ds 0.25 hrs \$46.00			\$11.50
A3 rh brakes	\$31.50	\$173.84	\$205.34
Kurt Kerekanich (Contact) 0.75 hrs \$42.00			\$31.50
FGRXSS504709E2K (Part) · Main BRAKE SHOE DRIVE16.5X 1 ea \$67.85			\$67.85
GWKDB1657B (Part) · Main BRAKE DRUM 16.5 X 7 S/AS GWK16792X 1 ea \$105.99			\$105.99

DESCRIPTION

SUMMARY

Subtotal	\$470.84
Labor	\$142.50
Parts	\$328.34
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$470.84



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #9151
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Jul 20, 2026 3:45 PM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Mon, Jul 20, 2026 3:45 PM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Tue, Jul 21, 2026	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,429,411km
Status:	Completed	Secondary Meter:	30,784hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
 Engine Oil & Filter Replacement	\$9.75	\$235.49	\$245.24
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 NXTDBL7900 (Part) - Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$64.55		\$64.55
 MXF15W40 (Part) - Main ENGINE OIL, 15W40 BUL	42 L \$4.07		\$170.94
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.75	\$0.00	\$9.75

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Check Diff and Trans Oil		\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Inspect and Service Trailer Hitch		\$9.75	\$0.00	\$9.75
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Tire Condition and Pressure Inspection		\$7.75	\$0.00	\$7.75
Check all tires				
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Torque Wheels		\$9.75	\$0.00	\$9.75
Verify wheels are properly torqued				
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Grease Unit		\$19.50	\$4.67	\$24.17
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 Joseph Pitney (Contact)	0.5 hrs \$39.00			\$19.50
 MNACHV259118-652 (Part) · Main	1 ea			\$4.67
STARPLEX EP2 TUBE Summer Grease				

DESCRIPTION

SUMMARY

Subtotal	\$367.91
Labor	\$127.75
Parts	\$240.16
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$367.91



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #9014
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Jun 29, 2026 10:50 AM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Mon, Jun 29, 2026 10:51 AM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Tue, Jun 30, 2026	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,421,259km
Status:	Completed	Secondary Meter:	30,598hr
Issued By:	Kurt Kerekanich		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 air to air bushing LHS	\$21.00	\$59.00	\$80.00
 Kurt Kerekanich (Contact)	0.5 hrs \$42.00		\$21.00
 FGRM203076 (Part) · Main AIR-AIR MOUNTING KIT	1 ea \$59.00		\$59.00
 exhaust clamp loose	\$31.50	\$19.58	\$51.08
 Kurt Kerekanich (Contact)	0.75 hrs \$42.00		\$31.50
 GWK90-0013 (Part) · Main CLAMP -V BAND 5"	1 ea \$19.58		\$19.58
 Truck Preventative Maintenance Inspection	\$21.00	\$0.00	\$21.00
 Kurt Kerekanich (Contact)	0.5 hrs \$42.00		\$21.00
 Engine Fan Belt Replacement	\$22.50	\$93.55	\$116.05

Item		Labor	Parts	Subtotal
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 VPS4120910X (Part) · Main CONTINENTAL XTREME HD BELT	1 ea \$93.55			\$93.55
 Engine Oil & Filter Replacement		\$10.50	\$243.63	\$254.13
 Kurt Kerekanich (Contact)	0.25 hrs \$42.00			\$10.50
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$64.55			\$64.55
 MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL	44 L \$4.07			\$179.08
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$10.50	\$0.00	\$10.50
 Kurt Kerekanich (Contact)	0.25 hrs \$42.00			\$10.50
 Check Diff and Trans Oil		\$10.50	\$0.00	\$10.50
 Kurt Kerekanich (Contact)	0.25 hrs \$42.00			\$10.50
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$10.50	\$0.00	\$10.50
 Ernesto Ablog (Contact)	0.25 hrs \$42.00			\$10.50
 Tire Condition and Pressure Inspection Check all tires		\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Torque Wheels Verify wheels are properly torqued		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50

Item	Labor	Parts	Subtotal
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$10.50	\$4.67	\$15.17
 Kurt Kerekanich (Contact)	0.25 hrs \$42.00		\$10.50
 MNACHV259118-652 (Part) · Main STARPLEX EP2 TUBE Summer Grease	1 ea \$4.67		\$4.67

PARTS (not linked to a Service Task)

Part	Quantity	Unit cost	Subtotal
 GWK2866337CUM (Part) · Main EXHAUST GASKET 5" CIR	1 ea	\$20.63	\$20.63

DESCRIPTION	SUMMARY
	Subtotal \$642.31 Labor \$201.25 Parts \$441.06 Labor Markup + \$0.00 (0.0%) Parts Markup + \$0.00 (0.0%) Warranty Credits - \$0.00 (0.0%) Discount - \$0.00 (0.0%) Tax +\$0.00 (0.0%) Total \$642.31

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#17550 [Inspection] Air to Air Mounts Reported 2 months ago by Kurt Kerekanich · Truck Preventative Maintenance Checklist by Kurt Kerekanich Generated by the failed inspection item "Air to Air Mounts" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Jun 29, 2026 at 2:09 PM MDT		
#17549 [Inspection] Loose clamp under step Reported 2 months ago by Kurt Kerekanich · Truck Preventative Maintenance Checklist by Kurt Kerekanich Generated by the failed inspection item "Exhaust Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Jun 29, 2026 at 2:09 PM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8977
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Jun 22, 2026 5:03 PM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Mon, Jun 22, 2026 5:04 PM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Mon, Jun 22, 2026 5:04 PM	Type:	Tandem
Duration:		Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	1,417,896km
Status:	Completed	Secondary Meter:	30,525hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Air leak A2 Airbag	\$46.50	\$219.38	\$265.88
 Allan Bates (Contact)	1.5 hrs \$31.00		\$46.50
 GWKHE2354 (Part) · Main HOSE ASSY 8 BAG 54" F	1 ea \$219.38		\$219.38
 Replace Air Drier	\$121.50	\$561.07	\$682.57
 JOE NEMEC (Contact)	1 hr \$90.00		\$90.00
 Kurt Kerekanich (Contact)	0.75 hrs \$42.00		\$31.50
 FGR120AA (Part) · Main ADAPTER 1/8X1/8 PIPE	1 ea \$1.40		\$1.40
 FGRPC14694A (Part) · Main ELBOW 90 1/4X1/8	1 ea \$5.00		\$5.00

Item

Labor

Parts

Subtotal

	FGR120CB (Part) - Main ADAPTER 3/8 X 1/4	2 ea \$1.45	\$2.90
	FGRPC1469SW8D (Part) - Main 1/2" X 1/2" SWIVEL PTC ELBOW	2 ea \$15.25	\$30.50
	FGRPC1469SW6B (Part) - Main 3/8X1/4P SWIVEL PUSH	1 ea \$8.95	\$8.95
	FGR109B (Part) - Main PLUG, 1/4"	2 ea \$0.86	\$1.72
	FGRPC14744B (Part) - Main PUSH TO CONN 1/4" ELB	1 ea \$5.65	\$5.65
	GWKBEN801266BXW (Part) - Main (Archived) AIR DRYER, AD-IS S/AS FGR5010696X	1 ea \$504.95	\$504.95

DESCRIPTION

SUMMARY

Subtotal	\$948.45
Labor	\$168.00
Parts	\$780.45
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$948.45



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8915
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Jun 9, 2026 9:29 AM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Tue, Jun 9, 2026 9:29 AM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Fri, Jun 12, 2026	Type:	Tandem
Duration:	3 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,413,088km
Status:	Completed	Secondary Meter:	30,425hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Turbo Replacement	\$90.00	\$2,070.55	\$2,160.55
 JOE NEMEC (Contact)	1 hr		\$90.00
 Replaced turbo and test drove unit.	\$90.00		
 TTD 171710.00 (Part) · Main (Archived)	1 ea		\$2,070.55
TURBO DELETED UNIT	\$2,070.55		
 Air Dryer Cartridge Replacement	\$10.00	\$25.43	\$35.43
 Ernesto Ablog (Contact)	0.25 hrs		\$10.00
	\$40.00		
 950011-G3 (Part) · Main	1 ea		\$25.43
Fleet Spec Air Dryer Cartridge Same As ABPN1335130010860	\$25.43		
 Valve Set	\$63.00	\$0.00	\$63.00
 Roper Gorgichuk (Contact)	1.5 hrs		\$63.00
	\$42.00		
 Truck Preventative Maintenance Inspection	\$30.00	\$0.00	\$30.00

Item	Labor	Parts	Subtotal
Ernesto Ablog (Contact) 0.75 hrs \$40.00			\$30.00
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Check Diff and Trans Oil	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$10.00	\$0.00	\$10.00
Ernesto Ablog (Contact) 0.25 hrs \$40.00			\$10.00
Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Torque Wheels Verify wheels are properly torqued	\$9.75	\$0.00	\$9.75
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
Walk Around Inspection	\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.75	\$4.67	\$12.42
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
MNACHV259118-652 (Part) - Main STARPLEX EP2 TUBE Summer Grease 1 ea \$4.67			\$4.67
Engine Oil & Filter Replacement	\$10.00	\$247.59	\$257.59
Ernesto Ablog (Contact) 0.25 hrs \$40.00			\$10.00

Item		Labor	Parts	Subtotal
 MXF15W40 (Part) · Main	44 L			\$183.04
ENGINE OIL, 15W40 BUL	\$4.16			
 NXTDBL7900 (Part) · Main	1 ea			\$64.55
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$64.55			
 replace charge air cooler		\$117.00	\$1,175.68	\$1,292.68
 Joseph Pitney (Contact)	3 hrs			\$117.00
	\$39.00			
 FGRM203076 (Part) · Main	1 ea			\$59.00
AIR-AIR MOUNTING KIT	\$59.00			
 GWKCACS1551TRP (Part) · Main	1 ea			\$1,116.68
COOLER-CHARGE AIR	\$1,116.68			
 A2R Airbag Replacement		\$93.00	\$241.55	\$334.55
 Allan Bates (Contact)	3 hrs			\$93.00
	\$31.00			
 GWKHE2354 (Part) · Main	1 ea			\$157.40
HOSE ASSY 8 BAG 54' F	\$157.40			
 GWKAS95410 (Part) · Main	1 ea			\$84.15
AIR BAG 8 BAG	\$84.15			

DESCRIPTION

SUMMARY

Subtotal	\$4,251.72
Labor	\$486.25
Parts	\$3,765.47
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$4,251.72

RESOLVED ISSUES(not linked to a Service Task)

Issue

Assigned Due

#17348 [Inspection] Air Dryer Condition

Reported 3 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog
Generated by the failed inspection item "Air Dryer Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Jun 9, 2026 at 10:40 AM MDT



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8776
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Fri, May 15, 2026 3:28 PM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Fri, May 15, 2026 3:28 PM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Mon, May 18, 2026	Type:	Tandem
Duration:	3 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,404,022km
Status:	Completed	Secondary Meter:	30,235hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
Engine Oil & Filter Replacement	\$9.75	\$235.11	\$244.86
Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
NXTDBL7900 (Part) - Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$64.55		\$64.55
MXF15W40 (Part) - Main ENGINE OIL, 15W40 BUL	41 L \$4.16		\$170.56
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$7.75	\$0.00	\$7.75

Item	Labor	Parts	Subtotal
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Check Diff and Trans Oil	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$7.25	\$0.00	\$7.25
Chad Caouette (Contact) 0.25 hrs \$29.00			\$7.25
Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Torque Wheels Verify wheels are properly torqued	\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
Walk Around Inspection	\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00			\$22.50
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.75	\$4.67	\$12.42
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
MNACHV259118-652 (Part) · Main STARPLEX EP2 TUBE Summer Grease 1 ea \$4.67			\$4.67
adjust clutch brake gap	\$19.50	\$0.00	\$19.50
Joseph Pitney (Contact) 0.5 hrs \$39.00			\$19.50
replace flex pipe under turbo	\$39.00	\$69.67	\$108.67
Joseph Pitney (Contact) 1 hr \$39.00			\$39.00
FGRSW50A3 (Part) · Main EXHAUST CLAMP 5" SS 2 ea \$23.65			\$47.30

Item	Labor	Parts	Subtotal
FGRP226147 (Part) · Main FLEXPIPE, 5" STAINLES S/AS FGR49035	0.09 ft		\$1.74
	\$19.35		
GWK2866337CUM (Part) · Main EXHAUST GASKET 5" CIR	1 ea		\$20.63
	\$20.63		

DESCRIPTION

SUMMARY

Subtotal	\$475.45
Labor	\$166.00
Parts	\$309.45
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$475.45

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#17132 [Inspection] flex pipe below turbo replace Reported 4 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Exhaust Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on May 19, 2026 at 7:54 AM MDT		
#17133 [Inspection] clutch adjustment required Reported 4 months ago by Joseph Pitney · Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Clutch Free Play" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on May 19, 2026 at 7:54 AM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8645
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Apr 27, 2026 9:46 AM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Mon, Apr 27, 2026 9:46 AM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Tue, Apr 28, 2026	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,398,720km
Status:	Completed	Secondary Meter:	30,140hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$21.75	\$0.00	\$21.75
 Chad Caouette (Contact)	0.75 hrs		\$21.75
 \$29.00	\$29.00		
 Engine Oil & Filter Replacement	\$0.00	\$0.00	\$0.00
 N/A			
 Air System Leaks	\$7.25	\$0.00	\$7.25
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
 Chad Caouette (Contact)	0.25 hrs		\$7.25
 \$29.00	\$29.00		
 Check Diff and Trans Oil	\$7.25	\$0.00	\$7.25
 Chad Caouette (Contact)	0.25 hrs		\$7.25
 \$29.00	\$29.00		

Item		Labor	Parts	Subtotal
↳ Inspect and Service Trailer Hitch	Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$7.25	\$0.00	\$7.25
👤 Chad Caouette (Contact)	0.25 hrs \$29.00			\$7.25
↳ Tire Condition and Pressure Inspection	Check all tires	\$7.75	\$0.00	\$7.75
👤 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
↳ Torque Wheels	Verify wheels are properly torqued	\$7.75	\$0.00	\$7.75
👤 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
↳ Grease Unit	Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.25	\$0.00	\$7.25
👤 Chad Caouette (Contact)	0.25 hrs \$29.00			\$7.25
🔧 Fuel Filter Replacement		\$14.50	\$113.32	\$127.82
👤 Chad Caouette (Contact)	0.5 hrs \$29.00			\$14.50
🔧 NTXDBF6776 (Part) · Main	1 ea \$68.76			\$68.76
FUEL FILTER SPIN ON S/AS BF46129				
🔧 P581299 (Part) · Main	1 ea \$44.56			\$44.56
Fuel filter same as K37-1029 & PF46081				
🔧 Hydraulic Filter Replacement		\$7.25	\$36.01	\$43.26
👤 Chad Caouette (Contact)	0.25 hrs \$29.00			\$7.25
🔧 replaced hydraulic filter				
🔧 BALPT9187 (Part) · Main	1 ea \$36.01			\$36.01
HYDRAULIC COOLER FILT S/AS FGR350001				
🔧 Rh Hood Pin Loose		\$35.50	\$20.85	\$56.35
👤 Chad Caouette (Contact)	0.5 hrs \$29.00			\$14.50
🔧 hood pin stud snapped replaced hood pin				

Item

Labor

Parts

Subtotal

	Roper Gorgichuk (Contact)	0.5 hrs		\$21.00
	 replaced lhs hood mount brakel and readjust the hood pins	\$42.00		
	FGRM17402 (Part) - Main	1 ea		\$20.85
	HOOD PIN AUTOMAN	\$20.85		

DESCRIPTION

SUMMARY

Subtotal	\$316.18
Labor	\$146.00
Parts	\$170.18
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$316.18



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8540
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Apr 6, 2026 3:31 PM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Mon, Apr 6, 2026 3:31 PM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Tue, Apr 7, 2026	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,394,638km
Status:	Completed	Secondary Meter:	30,065hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Rh Steer Axle Bearing Endplay Adjustment	\$22.00	\$13.03	\$35.03
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 FGR3303024 (Part) · Main HUBCAP GASKET	1 ea \$3.25		\$3.25
 MNACHV223030953 (Part) · Main DELO S-G XDM 75W90 SYNTHETIC GEAR OIL 7590	1 L \$9.78		\$9.78
 Fan Belt Replacement	\$11.00	\$98.17	\$109.17
 MICHAEL ABLOG (Contact)	0.25 hrs \$44.00		\$11.00
 VPS4120910X (Part) · Main CONTINENTAL XTREME HD BELT	1 ea \$98.17		\$98.17
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25

Item	Labor	Parts	Subtotal
	\$9.75	\$239.27	\$249.02
↳ Engine Oil & Filter Replacement			
Joseph Pitney (Contact) 0.25 hrs \$39.00			\$9.75
NXTDBL7900 (Part) · Main 1 ea \$64.55 OIL FILTER HIGH EFFICIENCY S/AS BD50000			\$64.55
MXF15W40 (Part) · Main 42 L \$4.16 ENGINE OIL, 15W40 BUL			\$174.72
↳ Air System Leaks	\$7.00	\$0.00	\$7.00
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
Ricky Peters (Contact) 0.25 hrs \$28.00			\$7.00
↳ Check Diff and Trans Oil	\$11.00	\$0.00	\$11.00
MICHAEL ABLOG (Contact) 0.25 hrs \$44.00			\$11.00
↳ Inspect and Service Trailer Hitch	\$18.00	\$0.00	\$18.00
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.			
MICHAEL ABLOG (Contact) 0.25 hrs \$44.00			\$11.00
Ricky Peters (Contact) 0.25 hrs \$28.00			\$7.00
↳ Tire Condition and Pressure Inspection	\$7.75	\$0.00	\$7.75
Check all tires			
Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
↳ Torque Wheels	\$11.00	\$0.00	\$11.00
Verify wheels are properly torqued			
MICHAEL ABLOG (Contact) 0.25 hrs \$44.00			\$11.00
↳ Walk Around Inspection	\$11.00	\$0.00	\$11.00
MICHAEL ABLOG (Contact) 0.25 hrs \$44.00			\$11.00

Item		Labor	Parts	Subtotal
↳ Grease Unit		\$7.00	\$4.67	\$11.67
	Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.			
👤 Ricky Peters (Contact)		0.25 hrs \$28.00		\$7.00
📦 MNACHV259119-652 (Part) · Main		1 ea		\$4.67
	STARPLEX EP1 Winter GREASE	\$4.67		
🔧 replace cab air filter		\$11.00	\$24.11	\$35.11
👤 MICHAEL ABLOG (Contact)		0.25 hrs \$44.00		\$11.00
📦 GWKCF19501C (Part) · Main		1 ea		\$24.11
	CAB AIR FILTER C/W CR	\$24.11		
🔧 replace A2 diff filter		\$7.00	\$6.30	\$13.30
👤 Ricky Peters (Contact)		0.25 hrs \$28.00		\$7.00
📦 BALB233 (Part) · Main		1 ea		\$6.30
	FILTER BALDWIN SPIN ON DIFF FILTER	\$6.30		
🔧 A3 temp sensor and pigtail		\$7.00	\$63.55	\$70.55
👤 Ricky Peters (Contact)		0.25 hrs \$28.00		\$7.00
📦 FGR6451000 (Part) · Main		1 ea		\$12.35
	DIFF SENSOR HARNESS, S/AS GWK3823256	\$12.35		
📦 FGR5055401 (Part) · Main		1 ea		\$51.20
	DIFF-TRANS TEMP SENSOR S/AS GWKQ21-1002	\$51.20		
🔧 Pressure Test Coolant System		\$14.00	\$0.00	\$14.00
👤 Ricky Peters (Contact)				\$14.00
	📁 Pressure tested for 15mins found the water pump hose clamps leaking.	0.5 hrs \$28.00		
🔧 Replace both windshield's		\$36.00	\$113.88	\$149.88
👤 MICHAEL ABLOG (Contact)		0.5 hrs \$44.00		\$22.00
👤 Ricky Peters (Contact)		0.5 hrs \$28.00		\$14.00
📦 GWKDW1163-30 (Part) · Main		1 ea		\$54.95
	WINDSHIELD , PS	\$54.95		
📦 GWKDW1164-30 (Part) · Main		1 ea		\$58.93
	WINDSHIELD, DS	\$58.93		

Item	Labor	Parts	Subtotal
 replace DS wiper blade	\$36.00	\$22.70	\$58.70
 MICHAEL ABLOG (Contact)	0.5 hrs \$44.00		\$22.00
 Ricky Peters (Contact)	0.5 hrs		\$14.00
 Installed new wiper on passenger side	\$28.00		
 GWK66-150 (Part) · Main (Archived)	2 ea		\$22.70
BLADES WINTER WIPER	\$11.35		
 replace DS washer nozzle	\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)			\$11.00
 clipped nozzle back in. adjusted wiper arm and stud broke. welded a new bolt.			
	0.25 hrs \$44.00		
 adjust clutch brake gap	\$11.00	\$0.00	\$11.00
 MICHAEL ABLOG (Contact)	0.25 hrs \$44.00		\$11.00
 A1Lh Hub Oil Milky	\$22.00	\$13.03	\$35.03
 MICHAEL ABLOG (Contact)	0.5 hrs		\$22.00
 drained oil and replaced gasket and plug	\$44.00		
 MNACHV223030953 (Part) · Main	1 L		\$9.78
DELO S-G XDM 75W90 SYNTHETIC GEAR OIL 7590	\$9.78		
 FGR3303024 (Part) · Main	1 ea		\$3.25
HUBCAP GASKET	\$3.25		
 CVIP	\$44.00	\$0.00	\$44.00
 MICHAEL ABLOG (Contact)	1 hr \$44.00		\$44.00

DESCRIPTION

SUMMARY

Subtotal	\$942.46
Labor	\$343.75
Parts	\$598.71
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$942.46

Issue	Assigned	Due
#16602 [Inspection] replacement required Reported 5 months ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Cab Air Filter" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Apr 7, 2026 at 7:55 AM MDT		
#16601 [Inspection] A1L replace hub oil Reported 5 months ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Front Hub Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Apr 7, 2026 at 7:55 AM MDT		
#16600 [Inspection] low pressure test cooling system Reported 5 months ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Coolant Level" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Apr 7, 2026 at 7:55 AM MDT		
#16599 [Inspection] clutch brake gap adjustment required Reported 5 months ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Clutch Brake Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Apr 7, 2026 at 7:55 AM MDT		
#16598 [Inspection] DS westcoast mirror replace Reported 5 months ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Mirrors" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Apr 7, 2026 at 7:55 AM MDT		
#16597 [Inspection] left wiper blade and washer nozzle Reported 5 months ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Windshield Wiper and Spray" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Apr 7, 2026 at 7:55 AM MDT		
#16596 [Inspection] replace both windshields Reported 5 months ago by Joseph Pitney • Truck Preventative Maintenance Checklist by Joseph Pitney Generated by the failed inspection item "Windshields" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Apr 7, 2026 at 7:55 AM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8387
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Mar 16, 2026 10:48 AM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Mon, Mar 16, 2026 10:48 AM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Tue, Mar 17, 2026	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,386,087km
Status:	Completed	Secondary Meter:	29,852hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$21.75	\$0.00	\$21.75
 Chad Caouette (Contact)	0.75 hrs \$29.00		\$21.75
 A3 Abs repair	\$174.00	\$155.37	\$329.37
 Both sides have codes			
 Chad Caouette (Contact)			\$174.00
 abs sensor on RHS broken at hub had to remove hub to replace sensor chased wires to find broken wire	6 hrs \$29.00		
 WST 10045887.00 (Part) - Main WHEEL SEAL DRIVE S/AS	1 ea \$47.73		\$47.73
 FGR3303111 (Part) - Main DRIVE AXLE HUBCAP GASKET	1 ea \$3.20		\$3.20
 FGR103430 (Part) - Main DRIVE AXLE STUD 5/8	8 ea \$4.10		\$32.80

Item		Labor	Parts	Subtotal
MNA257 5/8 (Part) · Main 8 ea AXLE NUT NYLOCK 5/8" \$0.38				\$3.04
FGR4410309102 (Part) · Main 1 ea ABS SENSOR KIT, 90 DE \$68.60				\$68.60
↳ Engine Oil & Filter Replacement		\$10.50	\$367.27	\$377.77
Roper Gorgichuk (Contact) 0.25 hrs \$42.00				\$10.50
MXF5W40 (Part) · Main 44 L ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER \$6.88				\$302.72
NXTDBL7900 (Part) · Main 1 ea OIL FILTER HIGH EFFICIENCY S/AS BD50000 \$64.55				\$64.55
↳ Air System Leaks		\$7.75	\$0.00	\$7.75
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.				
Allan Bates (Contact) 0.25 hrs \$31.00				\$7.75
↳ Check Diff and Trans Oil		\$7.75	\$0.00	\$7.75
Allan Bates (Contact) 0.25 hrs \$31.00				\$7.75
↳ Inspect and Service Trailer Hitch		\$7.25	\$0.00	\$7.25
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
Chad Caouette (Contact) 0.25 hrs \$29.00				\$7.25
↳ Tire Condition and Pressure Inspection		\$6.25	\$0.00	\$6.25
Check all tires				
Jayden Binet (Contact) 0.25 hrs \$25.00				\$6.25
↳ Torque Wheels		\$7.75	\$0.00	\$7.75
Verify wheels are properly torqued				
Allan Bates (Contact) 0.25 hrs \$31.00				\$7.75
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
JOE NEMEC (Contact) 0.25 hrs \$90.00				\$22.50

Item	Labor	Parts	Subtotal
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage	\$7.75	\$4.67	\$12.42
 Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
 MNACHV259119-652 (Part) · Main STARPLEX EP1 Winter GREASE 1 ea \$4.67			\$4.67
 Taillight repair	\$14.50	\$0.00	\$14.50
 Chad Caouette (Contact) 0.5 hrs  found and repaired broken taillight wire \$29.00			\$14.50
 A2 and A3 diff temp repair	\$21.75	\$24.70	\$46.45
 Chad Caouette (Contact) 0.75 hrs  replaced both diff sensor \$29.00			\$21.75
 FGR6451000 (Part) · Main DIFF SENSOR HARNESS, S/AS GWK3823256 2 ea \$12.35			\$24.70
 Wrap product pump	\$15.50	\$0.00	\$15.50
 Allan Bates (Contact) 0.5 hrs \$31.00			\$15.50
 Cab filter replacement	\$7.25	\$24.11	\$31.36
 Chad Caouette (Contact) 0.25 hrs  replaced filter \$29.00			\$7.25
 GWKCF19501C (Part) · Main CAB AIR FILTER C/W CR 1 ea \$24.11			\$24.11

DESCRIPTION

SUMMARY

Subtotal	\$908.37
Labor	\$332.25
Parts	\$576.12
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$908.37

Issue	Assigned	Due
#16290 [Inspection] Cab Air Filter Reported 6 months ago by Chad Caouette • Truck Preventative Maintenance Checklist by Chad Caouette Generated by the failed inspection item "Cab Air Filter" on the "Truck Preventative Maintenance Checklist" form submitted by Chad Caouette on Mar 16, 2026 at 1:48 PM MDT		
#16289 [Inspection] Product Pump Reported 6 months ago by Chad Caouette • Truck Preventative Maintenance Checklist by Chad Caouette Generated by the failed inspection item "Product Pump" on the "Truck Preventative Maintenance Checklist" form submitted by Chad Caouette on Mar 16, 2026 at 1:48 PM MDT		
#16288 [Inspection] Tail Lights Reported 6 months ago by Chad Caouette • Truck Preventative Maintenance Checklist by Chad Caouette Generated by the failed inspection item "Tail Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Chad Caouette on Mar 16, 2026 at 1:48 PM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8229
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Feb 23, 2026 11:19 AM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Mon, Feb 23, 2026 11:19 AM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Tue, Feb 24, 2026	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,376,521km
Status:	Completed	Secondary Meter:	29,620hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Rhs Low and High Beam Out	\$20.00	\$0.00	\$20.00
 Ernesto Ablog (Contact)	0.5 hrs		\$20.00
 Hardwired connections all corroded	\$40.00		
 A3 Diff Temp. Repair	\$7.00	\$12.35	\$19.35
 Ricky Peters (Contact)	0.25 hrs		\$7.00
 Installed new diff temp pig tail	\$28.00		
 FGR6451000 (Part) - Main	1 ea		\$12.35
DIFF SENSOR HARNESS, S/AS GWK3823256	\$12.35		
 Release Bearing Grease Line Off	\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact)	0.25 hrs		\$7.00
	\$28.00		
 High Beams Dim	\$20.00	\$0.00	\$20.00
 Ernesto Ablog (Contact)	0.5 hrs		\$20.00
 Hardwired connections corroded both sides	\$40.00		

Item	Labor	Parts	Subtotal
 Retorque Rhs Leafspring	\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact) 0.25 hrs  Torqued to 350ftlbs \$28.00			\$7.00
 Truck Preventative Maintenance Inspection	\$30.00	\$0.00	\$30.00
 Ernesto Ablog (Contact) 0.75 hrs \$40.00			\$30.00
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
 Check Diff and Trans Oil	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
 Engine Oil & Filter Replacement	\$7.00	\$367.27	\$374.27
 Ricky Peters (Contact) 0.25 hrs \$28.00			\$7.00
 NXTDBL7900 (Part) · Main 1 ea OIL FILTER HIGH EFFICIENCY S/AS BD50000 \$64.55			\$64.55
 MXF5W40 (Part) · Main 44 L ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER \$6.88			\$302.72
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact) 0.25 hrs \$28.00			\$7.00
 Tire Condition and Pressure Inspection Check all tires	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
 Torque Wheels Verify wheels are properly torqued	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact) 0.25 hrs \$31.00			\$7.75
 Walk Around Inspection	\$22.50	\$0.00	\$22.50

Item	Labor	Parts	Subtotal
JOE NEMEC (Contact)			\$22.50
	0.25 hrs \$90.00		
Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.75	\$4.67	\$12.42
Allan Bates (Contact)	0.25 hrs \$31.00		\$7.75
MNACHV259119-652 (Part) · Main STARPLEX EP1 Winter GREASE	1 ea \$4.67		\$4.67
Oil leak on oil pan	\$20.50	\$0.00	\$20.50
Kurt Kerekanich (Contact) After unit was serviced and pulled outside oil pan started leaking. Put vacuum on oil fill tube cleaned up leaking spot and used tech steel to repair oil pan.	0.5 hrs \$41.00		\$20.50

DESCRIPTION

SUMMARY

Subtotal	\$571.04
Labor	\$186.75
Parts	\$384.29
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$571.04

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#15953 Bunk heater Reported Feb 18, 2026 by JOE NEMEC Very noisy when starting up		
#15989 Hi beams Reported Feb 22, 2026 by JOE NEMEC Driver reports hi beams are dimmer than low beams		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #8117
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Feb 3, 2026 9:41 AM	#43 2017 Kenworth W900	
Scheduled Start Date:	Tue, Feb 3, 2026 9:41 AM	VIN/SN: License Plate:	1XKWD40X7HJ988603
Actual Start Date:	Tue, Feb 3, 2026 9:42 AM	Operator:	John Penner
Expected Completion Date:		Type:	Tandem
		Group:	
Actual Completion Date:	Wed, Feb 4, 2026	Odometer:	1,367,966km
Duration:	1 day	Secondary Meter:	29,385hr
Repair Priority Class:	Scheduled		
Status:	Completed		
Issued By:	Ricky Peters		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 A3 LH shock leaking	\$21.00	\$76.05	\$97.05
 Ricky Peters (Contact)	0.75 hrs \$28.00		\$21.00
 FGR85937 (Part) - Main SHOCK DRIVE 8 BAG SUS	1 ea \$76.05		\$76.05
 Clutch adjustment	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
 Gear Pump Bracket Bolts	\$9.00	\$0.00	\$9.00
 JOE NEMEC (Contact)	0.1 hrs \$90.00		\$9.00
 Tightened bolts			
 A1 LH shock	\$7.00	\$94.91	\$101.91
 Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00

Item	Labor	Parts	Subtotal
 GWKB71-6009 (Part) · Main STEER SHOCK	1 ea \$94.91		\$94.91
 Sirius xm antenna replacement	\$27.00	\$104.20	\$131.20
 JOE NEMEC (Contact)	0.3 hrs \$90.00		\$27.00
 GWKPP802458 (Part) · Main ANTENNA KIT RADIO	1 ea \$104.20		\$104.20
 Cab Air Filter	\$7.00	\$28.81	\$35.81
 Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
 GWKCF19501C (Part) · Main CAB AIR FILTER C/W CR	1 ea \$28.81		\$28.81
 Engine Air Filter Replacement	\$11.20	\$216.38	\$227.58
 Ricky Peters (Contact)	0.4 hrs \$28.00		\$11.20
 NTXP625128 (Part) · Main AIR FILTER W900	2 ea \$108.19		\$216.38
 Truck Preventative Maintenance Inspection	\$14.00	\$0.00	\$14.00
 Ricky Peters (Contact)	0.5 hrs \$28.00		\$14.00
 Engine Oil & Filter Replacement	\$9.75	\$356.88	\$366.63
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$61.04		\$61.04
 MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	43 L \$6.88		\$295.84
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact)	0.25 hrs \$28.00		\$7.00
 Check Diff and Trans Oil	\$9.75	\$0.00	\$9.75

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Inspect and Service Trailer Hitch		\$22.50	\$0.00	\$22.50
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Tire Condition and Pressure Inspection		\$6.25	\$0.00	\$6.25
Check all tires				
 Jayden Binet (Contact)	0.25 hrs \$25.00			\$6.25
 Torque Wheels		\$9.75	\$0.00	\$9.75
Verify wheels are properly torqued				
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Grease Unit		\$19.50	\$4.67	\$24.17
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
 Joseph Pitney (Contact)	0.5 hrs \$39.00			\$19.50
 MNACHV259119-652 (Part) - Main	1 ea			\$4.67
STARPLEX EP1 Winter GREASE				
 exhaust for engine heater		\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75

DESCRIPTION

SUMMARY

Subtotal	\$1,117.35
Labor	\$235.45
Parts	\$881.90
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,117.35

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#15401 Sat radio Reported Jan 12, 2026 by JOE NEMEC Check antenna no working		
#15738 [Inspection] Clutch Free Play Reported 7 months ago by Ricky Peters • Truck Preventative Maintenance Checklist by Ricky Peters Generated by the failed inspection item "Clutch Free Play" on the "Truck Preventative Maintenance Checklist" form submitted by Rickylynn Peters on Feb 3, 2026 at 10:22 AM MST		
#15737 [Inspection] Cab Air Filter Reported 7 months ago by Ricky Peters • Truck Preventative Maintenance Checklist by Ricky Peters Generated by the failed inspection item "Cab Air Filter" on the "Truck Preventative Maintenance Checklist" form submitted by Rickylynn Peters on Feb 3, 2026 at 10:22 AM MST		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #7944
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Jan 12, 2026 11:15 AM	#43 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X7HJ988603
Actual Start Date:	Mon, Jan 12, 2026 11:15 AM	License Plate:	
Expected Completion Date:		Operator:	John Penner
Actual Completion Date:	Tue, Jan 13, 2026	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,359,609km
Status:	Completed	Secondary Meter:	29,182hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$29.25	\$0.00	\$29.25
 Joseph Pitney (Contact)	0.75 hrs \$39.00		\$29.25
 Engine Oil & Filter Replacement	\$9.75	\$343.12	\$352.87
 Joseph Pitney (Contact)	0.25 hrs \$39.00		\$9.75
 NXTDBL7900 (Part) - Main	1 ea		\$61.04
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$61.04		
 MXF5W40 (Part) - Main	41 L		\$282.08
ENGINE OIL 5W40 BULK 200L STORED IN OIL DRUM FOR SUMMER	\$6.88		
 Air System Leaks	\$9.75	\$0.00	\$9.75
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Check Diff and Trans Oil		\$9.75	\$0.00	\$9.75
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 Inspect and Service Trailer Hitch	Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$7.00	\$0.00	\$7.00
 Ricky Peters (Contact)	0.25 hrs \$28.00			\$7.00
 Tire Condition and Pressure Inspection	Check all tires	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Torque Wheels	Verify wheels are properly torqued	\$7.75	\$0.00	\$7.75
 Allan Bates (Contact)	0.25 hrs \$31.00			\$7.75
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Grease Unit	Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.50	\$4.67	\$24.17
 Joseph Pitney (Contact)	0.5 hrs \$39.00			\$19.50
 MNACHV259119-652 (Part) - Main	1 ea \$4.67			\$4.67
	STARPLEX EP1 Winter GREASE			
 Fuel Filters Replacement		\$9.75	\$109.58	\$119.33
 Joseph Pitney (Contact)	0.25 hrs \$39.00			\$9.75
 P581299 (Part) - Main	1 ea \$44.56			\$44.56
	Fuel filter same as K37-1029 & PF46081			
 NTXDBF6776 (Part) - Main	1 ea \$65.02			\$65.02
	FUEL FILTER SPIN ON S/AS BF46129			
 Repair left fog light		\$0.00	\$185.14	\$185.14

Item		Labor	Parts	Subtotal
 Joseph Pitney (Contact)		0 hrs		\$0.00
 fog light dim checked power was good replaced light		\$39.00		
 GWKLED500 (Part) - Main		1 ea		\$185.14
AUXILIARY DRIVING LAM		\$185.14		
 #15413 - [Inspection] left light dim probably corrosion	Generated by the failed inspection item "Fog Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Joseph Pitney on Jan 12, 2026 at 12:46 PM MST			
 check sat radio antenna and radio		\$19.50	\$0.00	\$19.50
 Joseph Pitney (Contact)				\$19.50
 found the adapter that goes from antenna cable to radio was unscrewed on the cable side should work better now				
		0.5 hrs		
		\$39.00		

DESCRIPTION

SUMMARY

Subtotal	\$794.76
Labor	\$152.25
Parts	\$642.51
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$794.76