


R14-24
SEP



DATE July 3 2026

KM 95065 HRS _____

UNIT NUMBER SBS30

COMPLAINT: look over

CAUSE: _____


CORRECTION: Looked unit over
Replaced two set of Brakes (shoes + drum)
on #3 LTR on A
Replaced #3 L outside tire

Stocked Parts:

shoes (2) JRB040823
drums (2) BD102124

Repairs done by _____ Date: _____

Authorized by: _____



Retorque Notice

Tag # **2501**

Date: July 3rd 2006 WO#

Unit #: 585304 Odometer: 94065

Issued By: Mike

Initial Completed	(X) Install	Axle	Axle	(X) Install	Initial Completed
		1	1		
		2	2		
	X	3	3	X	
		4	4		
		5	5		

Comments: Please Retorque


Valley Printers # 26627

Retorque Completed

Date: _____ Odometer: _____

Name: _____ Signature: _____

Notice: Retorque must be completed within 150 km or the first available outside facility.
Initial each wheel for which retorque was done.



DATE June 12/26

KM 79605

HRS N/A

UNIT NUMBER SB530A

COMPLAINT: Light Short

CAUSE: _____

CORRECTION: found Light Short Lead LHS rear
Light bar wire was chafed through touching the
frame cut off wire and rewired that Light
bar


Stocked Parts:

7 wire 3 feet
DNB/16 x 1 Shrinktube

Repairs done by Care B.

Date: June 2nd / 26

Authorized by: _____



DATE June 8th

KM 83 939

HRS _____

UNIT NUMBER SB530

COMPLAINT: Service

CAUSE: _____

CORRECTION: - Greased - New brake shoes 5th LHS
- New light back of pup up top

Stocked Parts:

- LED2500-12RP

- PT6020

- Brake shoes - TRB100573-N16

Repairs done by Morgan

Date: _____

Authorized by: [Signature]