

F30-2
SEP

ROADSIDE SUPPLY LTD.

2007 GMC 7500**Maintenance Periods****Vin: 1GDL7C1B27F426575**

Wiper length:24"

Grease	Bi Weekly
Check Tire /Pressure	Monthly
Change Engine Oil/ Filter	8 000 km
Clean Machine	As Required
Check / Drain Fuel Separator	Monthly
Clean Air Filter/ Rad	Monthly

Maintenance Records

<u>DATE:</u>	<u>Hours/ Miles</u>	<u>Servicing Done</u>	<u>Comments</u>
Aug 8/2019	247560 km	Removed sides and rear door added winches and winch bar and put red white tape down the side and changed weight limit to 16000kg. added back up alarm	
Aug 12/2019	247600km	Alternator not charging and cables have corrosion them from alt to battery fuse connection and from batt connection to batteries corroded as well	Replaced alt and cleaned up terminals charging now 14 volts
Jan 15/2020	251706km	Changed engine oil 15 40 replaced fuel filter and p.s filter ordered water sep filter, greased driveline and steering. Tires 90psi.	
Feb 10 2020	251706km	cut out part of headache rack and put window mesh in so can see deck. replaced fuel tanks and got painted	
Feb 20 2020	251895 km	e brake not holding truck when in neutral found shoes and drum worn out in spots . Replaced shoes and drum cable in probably stretched so need new cable to make sure it is proper. It is holding truck right now.	
July 29/2020		Check engine light on p10027 exhaust valve control solenoid circuit performance bank 1	

Jan 8 2021	265991 km	wa jax replaced trans was shifting not properly. Now trans is shifting proper	replaced transmission
Feb 2 2021	260231 km	water pump was leaking replaced and filled now ok	
Feb 15 2021	262355 km	trans line was leaking at crimp after we got line replaced. Recrimped now ok	
April 5 2021		need oil change ordered filter should be in next week possible this?	
May 14 2021	270367 km	changed engine oil and p.s filter greased steering and driveline tires 100 psi. pass window doesn't go up	
May 17 2021	270367km	tested wiring harness on both doors and power going to motor on pass side window, pass switch failed. Need ohm meter check reistance in wire from switch to motor switch part number is 15047831 \$51.88 in stock	
June 1 2021	271346km	Tran line hose crimp didn't hold and lost trans oil. Got net line with welded JIC fittin on the end so can tighten line topped up fluid test drove seems ok.	
Oct 13 2021		alt wire broke at connector have to replace connector and	
feb 14 2022	278523km	water pump belt broke and over heated need new belt continetal belt 22464mk for water pump get at greggs.	replaced water pump belt running good now
March 8 2022	2780325km	Alt belt broke ac pump clutch seized	replaced belt blew new ac pump no good.
June 27 2022	284683km	Replaced rear pads and retorqued tires 500ftlbs. Got windshield replaced, patched bumper holes with flat bar made 7 pieces will prob have to remake it in winter good enough to pass cvip. Have to take in next week to get danny to inspectand sticker it.	
July 11 2022	284683km	Abs light came on checking abs sensors	abs sensor discontinued pt num is front: 20784539 rear part number 20784542
Nov 15 20222	289453km	washer pump not working driver tank strap broke greased steering and driveline	fixed gas tank strap had broken t bolt now good, replaced washer pump now ok. Replaced upper clearance lights on headache rack 2 not working ambers
Dec 8 2022	291265km	Right inner dual blew got 4 new recaps put on and torqued 475tlbs 110psi	

Feb 25 2023	298653km	Changed engine oil and greased steering and driveline.		
March 8 2023	299536km	Trans not shifting out of netraul trans light on and only the bottm N lights up on the shift pad.	33000km on trans. Wajax 2 yr unlimited km we are out of warranty 2 months.	
March 13 2023		Started truck warmed up no movement. Let sit rest of day . Fired up again truck shifts into gear took roadtest sluggish from 3 to 4th and takes forever to shift 4 to 5th rpm stays 2000rpm	took abs harness off abs moduale and got 3 of the 4 screws out 4th bolt head rounding. 4mm socket need to try strong smaller needle nose vice grips.	
March 15 2023		Code on truck: P2718 Pressure control pc system open P370C trans level sensor low imput P2720 Pressure control pc low circuit P0658 actutor supply voltage 1 low high driver ground	crawled undernieht and followe trans harness no breaks undernieth. Went up pass side found 5 wires rubbed through and corroded fixed all wires and check others where chaffing, buttomed up and moved wirse so not chaffing and replaced main batter connector	
Feb5 2024	300152km	right head light lens broken and left inner tire leaking took off and brought to kal to fix	replaced head lights and got tire fixed torqued to 500ftlbs 110 psi changed weight numbers to 14700 and added few more straps on deck	
march 15 2024	300684	replaced rear mud flap hanges and reinstalled flaps.		
June 18 2024		lack of power and lights on the dash are coming on, need to do oil change and grease on unit	Looked up lights low coolant casues engine shut off light to come on, toppe dcoolant and changed engine oil and replaced water sept filter and took intake tube off found lots of oil residu in the tubo line to cooler. And smokes likes crazy buring oil.	
			also need to replace left front brake rotor all	
Oct 1 2024		truck still runs like bag of shit white smoke plumming out and idle is below 500 rpm should be 800 pulled pins on connector out further so can make contact with the sensor. See if coolant light comes on or truck shuts off.		
Oct 2 2024		replaced coolant resivor sensor staying off for now		
Nov 4 2024		Took to western needed injectors they found sensor wire wasn't working replaced and the new coolant tank was casuing intermitent issues they reinstalled the old tank back on and will return or get credit from gmc on the new tank.		

[illegible]