



Autogermany
15227 119 Avenue Northwest
Edmonton, AB T5V 1S4
(780) 800-9123
contact@autogermany.ca
https://www.autogermany.ca/

247-1
SEP

Invoice for RO #13189

Service Advisor: Adrian Cocis

Posted Date: 07/23/25 at 05:09 PM MDT

Client: Rod McDonald

Vehicle: 2017 Mercedes-Benz CLS550 4Matic

Kostash Green Southwest
Edmonton, AB T6W 3J8
Phone: (780) 975-9550
Email: rnrig@icloud.com

2017 Mercedes-Benz CLS550 4Matic 4.7L
8Cyl GAS 278.922 Turbocharged
VIN: WDDJ9BB0HA192786
License: CMD-0154
Color: Black
Odometer In: 123982 / Out: 123993

RO # 13189
Time-In: 06/30/25 at 02:56 PM MDT

1 - ENGINE OIL SERVICE

Note: Completed engine oil service. Drained engine oil, removed and replaced engine oil filter. Filled engine with new oil. Reset service reminder.

Labor:	Engine oil service	
Parts:	Oil filter	1
	Drain Plug Gasket	1
	Liqui Moly Engine Oil 5W40 Leichtlauf	8
	Battery CR2025	1

✓ Approved on 07/16/25 at 08:13 AM MDT

Subtotal \$299.38 + est. Tax \$14.97

\$314.35

2 - VEHICLE HEALTH CHECK

Note: Performed vehicle health check. Please see report for details.
Topped up washer fluid.

<https://autogermany.autotext.me/Admin/microsite/index.php?id=RUBRYXVNTFaYzRDUk15enlaSEJsrkkaWVslQVoZE9MeTVBQ3Vnnp3TT0-&so=1>

Labor: Vehicle health check

✓ Approved on 07/16/25 at 08:13 AM MDT

0

0

3 - REPLACE EXPANSION TANK CAP

Note: Removed and replaced expansion tank cap.

Part:	Expansion tank cap	1
-------	--------------------	---

✓ Approved on 07/16/25 at 11:43 AM MDT

Subtotal \$72.78 + est. Tax \$3.64

\$76.42

4 - REPLACE RIGHT SIDE CAMSHAFT MAGNET SEALS

Note: Removed and replaced camshaft magnet o-rings, replaced magnet bolt and cleaned area to monitor.

Labor:	Replace magnet seals	
Parts:	O-Ring	2
	Camshaft Magnet Bolt	6

✓ Approved on 07/16/25 at 11:43 AM MDT

Subtotal \$279.30 + est. Tax \$13.97

\$293.27

5 - FOUR WHEEL ALIGNMENT

Note: Performed 4 wheel alignment. Adjusted toe and camber. Took vehicle for a test drive and found it is driving straight and not pulling to either side.

Labor: Four wheel alignment

✓ Approved on 07/16/25 at 11:43 AM MDT

Subtotal \$227.50 + est. Tax \$11.38

\$238.88

6 - REPLACE REAR SHOCK ABSORBERS

Note: Removed and replaced rear shock absorbers.

Labor:	Rear shock absorber replacement	
Parts:	Rear Left Shock Absorber	1
	Rear Right Shock Absorber	1

✓ Approved on 07/16/25 at 11:43 AM MDT

Subtotal \$3,720.92 + est. Tax \$186.05

\$3,906.97

7 - TRANSMISSION SERVICE

Note: Drained transmission oil from pan and torque converter. Removed and replaced pan/filter assembly. Replaced torque converter drain plug. Filled transmission with new fluid. Road tested and found vehicle is shifting properly and smoothly.

Labor:	Transmission Service	
Parts:	TopTec 1950 ATF MB 236.17	10
	Torque converter drain plug Mercedes	1
	Transmission pan/filter kit	1
	Pan Bolt	10

✓ Approved on 07/16/25 at 11:43 AM MDT

Subtotal \$1,267.87 + est. Tax \$63.39

\$1,331.26

8 - TRANSFER CASE SERVICE			
Note: Completed transfer case service.			
Labor:	Transfer case service		1
Parts:	TopTec 1950 ATF MB 236.17		1
	Drain Plug Gasket		
✓ Approved on 07/16/25 at 11:43 AM MDT		Subtotal \$171.08 + est. Tax \$8.55	\$179.63

9 - FRONT + REAR DIFFERENTIAL SERVICE			
Note: Completed front and rear differential service.			
Labor:	Front and rear differential service		2
Parts:	Gear oil 75W-85 GL-5 (Ester based full synth)		1
	Drain Plug Gasket		
✓ Approved on 07/16/25 at 11:43 AM MDT		Subtotal \$403.63 + est. Tax \$20.18	\$423.81

RO Fees			
Fee:	Materials and Consumables		\$150.00
		Subtotal \$150.00 + est. Tax \$7.50	\$157.50

Warranty: From the date of delivery for a period of 36 months or 40,000 kilometers, whichever comes first*, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All warranty repairs to be done at Autogermany only. This does not include towing charges or customer supplied parts. Neglect/abuse of vehicle will immediately void any and all warranties. Warranty is transferable to subsequent vehicle owner(s) as long as the vehicle continues to be serviced, maintained and repaired at Autogermany. Semi-annual inspection must be performed by Autogermany to retain the warranty. *Some limitations apply. This does not include wearable items including but not limited to brakes, belts, tires, hose, etc. Ask advisor for details on the specific part being installed. GST#: 744 546 516

Wheel nuts (bolts) tightness (torque) must be rechecked by AUTOGERMANY after 80 kilometers.

Once vehicle repairs are completed, customers will be notified promptly using the contact information provided at the time of service. Customers are expected to pick up their vehicles within 14 calendar days of this notification. Starting on the 15th day, a storage fee of \$20.00 per day will be applied to the total bill for each day the vehicle remains on the premises.

Work Authorization Signature:

Total Labor: \$2,493.75
 Total Parts: \$4,036.21
 Total Fees: \$150.00
 Discounts: -\$87.50
 Subtotal: \$6,592.46
 Taxes: \$329.62
 Grand Total: \$6,922.08
 BALANCE DUE: \$0.00

X 

✓ PAID

Payment History

Date	Customer Name	Payment Method	Amount	Payment Info	Transaction Details	Signature
07/23/25		Credit Card	\$6,922.08			

Invoice for RO #10973

Service Advisor: Adrian Cocks
 Posted Date: 07/04/24 at 03:09 PM MDT
 Client: Rod McDonald
 Vehicle: 2017 Mercedes-Benz CLS550 4Matic

Autogermany
 15227 119 Avenue Northwest
 Edmonton, AB T5V 1S4
 (780) 800-9123
 contact@autogermany.ca
<https://www.autogermany.ca/>



2017 Mercedes-Benz CLS550 4Matic 4.7L License: CMLD-0154 VIN: WDD1J9BB0HA192786 8CY GAS 278.922 Turbocharged Color: Black Odometer In: 114981 / Out: 114987	Kostash Green Southwest Edmonton, AB T6W 3J8 Phone: (780) 975-9550 Email: mring@icloud.com
RO # 10973 Time In: 06/27/24 at 09:06 AM MDT	

1 - ENGINE OIL SERVICE	
Labor: Engine oil service Liquid Moly Engine oil 5W30 Top Tec 4200 Oil filter Drain Plug Gaskets	Parts: 8 1 1
Approved on 06/27/24 at 09:35 AM MDT Subtotal \$285.05 + est. Tax \$14.25 \$299.30	

2 - REPLACE DRIVE BELT, TENSIONER AND PULLEYS	
Labor: Replace drive belt, tensioner, and pulleys Drive Belt Acc. Belt Idler Pulley Acc. Belt Idler Pulley Accessory Belt Tensioner Idler Pulley Idler Pulley (Water pump housing)	Parts: 1 1 1 1 1 1
Approved on 06/27/24 at 09:35 AM MDT Subtotal \$1,103.45 + est. Tax \$55.17 \$1,158.62	

3 - VEHICLE HEALTH CHECK	
Note: Performed vehicle health check. Please see report for details.	
Labor: Vehicle health check	Discount: -\$82.50
Approved on 06/27/24 at 09:35 AM MDT	

RO Fees	
Materials and Consumables Fee: \$83.31	Subtotal \$83.31 + est. Tax \$4.17 \$87.48

Warranty: From the date of delivery for a period of 36 months or 40,000 kilometers, whichever comes first*, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All warranty repairs to be done at Autogermany only. This does not include towing charges or customer supplied parts. Neglect/abuse of vehicle will immediately void any and all warranties. Warranty is transferable to subsequent vehicle owner(s) as long as the vehicle continues to be serviced, maintained and repaired at Autogermany. Semi-annual inspection must be performed by Autogermany to retain the warranty. *Some limitations apply. This does not include wearable items including but not limited to brakes, belts, tires/hose, etc. Ask advisor for details on the specific part being installed. GST #: 744 546 516

Wheel nuts (bolts) tightness (torque) must be rechecked by AUTOGERMANY after 80 kilometers.

Once vehicle repairs are completed, customers will be notified promptly using the contact information provided at the time of service. Customers are expected to pick up their vehicles within 14 calendar days of this notification. Starting on the 15th day, a storage fee of \$20.00 per day will be applied to the total bill for each day the vehicle remains on the premises.

Work Authorization Signature:

X 

Total Labor: \$511.50
Total Parts: \$959.50
Total Fees: \$83.31
Discounts: -\$82.50
Subtotal: \$1,471.81
Taxes: \$73.59
Grand Total: \$1,545.40
BALANCE DUE: \$0.00

✓ PAID

Payment History

Date	Customer Name	Payment Method	Amount	Payment Info	Transaction Details	Signature
07/04/24		Credit Card	\$1,545.40			



Autogermany
15227 119 Avenue Northwest
Edmonton, AB T5V 1S4
(780) 800-9123
contact@autogermany.ca
<https://www.autogermany.ca/>

Invoice for RO #10382

Service Advisor: Adrian Cocis
Posted Date: 03/27/24 at 03:20 PM MDT
Client: Rod McDonald
Vehicle: 2017 Mercedes-Benz CLS550 4Matic

Kostash Green Southwest Edmonton, AB T6W 3J8 Phone: (780) 975-9550 Email: rmrig@icloud.com	2017 Mercedes-Benz CLS550 4Matic 4.7L 8Cyl GAS 278.922 Turbocharged VIN: WDDLJ9BB0HA192786 License: CMD-0154 Color: Black Odometer In: 105540 / Out: 105853	RO # 10382 Time-In: 03/18/24 at 07:27 PM MDT
1 - VEHICLE INSPECTION - INSPECT BRAKES, CUSTOMER REPORTS THAT BRAKE PEDAL PULSATION IS PRESENT. Note: Performed vehicle health check. Please see report for details. Road tested the vehicle and verified customer's concern. Inspected the vehicle and found that front brakes rotors are warped. Recommended to replace front brake pads and rotors. Please see inspection report for more details. Labor: Vehicle health check		
✓ Approved on 03/20/24 at 08:47 AM MDT		Subtotal \$180.00 + est. Tax \$9.00 \$189.00
2 - REPLACE FRONT BRAKE PADS AND ROTORS Note: Performed replace front brake pads and rotor due to pulsation and bedding front brake system. Labor: Front brake pad and rotor replacement Parts: Front Brake Pad Set 1 Brake Pad Sensor 1 Front Brake Rotor 2		
✓ Approved on 03/20/24 at 04:03 PM MDT		Subtotal \$1,205.23 + est. Tax \$60.26 \$1,265.49
3 - MOUNT AND BALANCE 4 TIRES - Michelin PILOT SPORT A/S 4 Note: During balance all 4 tires found both front wheels have minor bend. Torque all 4 wheels to spec with tire pressure reset. however test drive vehicle at 110km/h found there are no vibration at the moment. Labor: Mount and balance 4 tires Parts: Michelin PILOT SPORT A/S 4 - 255/40/18 2 Michelin PILOT SPORT A/S 4 - 285/35/18 2		
✓ Approved on 03/20/24 at 04:03 PM MDT		Subtotal \$1,944.22 + est. Tax \$113.21 \$2,057.43
4 - BATTERY REPLACEMENT Labor: Replace battery Part: Battery AGM 80Ah 1		
✓ Approved on 03/25/24 at 08:26 AM MDT		Subtotal \$487.20 + est. Tax \$24.36 \$511.56
5 - BRAKE FLUID FLUSH AND BLEED Labor: BRAKE FLUID FLUSH AND BLEED Part: Brake fluid DOT 4 (Low viscosity) (1L) 1		
✓ Approved on 03/25/24 at 08:26 AM MDT		Subtotal \$207.16 + est. Tax \$10.36 \$217.52
6 - ENGINE OIL SERVICE Labor: Engine oil service Parts: Liqui Moly Engine oil 5W30 Top Tec 4200 8 Oil filter 1 Drain Plug Gasket 1		
✓ Approved on 03/25/24 at 08:26 AM MDT		Subtotal \$285.05 + est. Tax \$14.25 \$299.30
7 - ENGINE AIR FILTER REPLACEMENT Labor: Engine air filter replacement Part: Air Filter 2		
✓ Approved on 03/25/24 at 08:26 AM MDT		Subtotal \$201.56 + est. Tax \$10.08 \$211.64

8 - CABIN AIR FILTER REPLACEMENT

Note: During removal cabin air filter found one of the screws missing and interior temp sensor connector housing broken. Performed repair interior temp sensor at free and install missing screw back. New connector and pins may require

Labor:	Cabin air filter replacement	
	Repair temperature sensor wiring	
Parts:	Cabin Air Filter	1
	Connector housing	1
	Hex bolt	1
✓ Approved on 03/25/24 at 08:26 AM MDT		Subtotal \$275.31 + est. Tax \$13.77
		\$289.08

RD Fees

Fee:	Materials and Consumables	\$150.00
		Subtotal \$150.00 + est. Tax \$7.50
		\$157.50

Warranty: From the date of delivery for a period of 36 months or 40,000 kilometers, whichever comes first*, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All warranty repairs to be done at Autogermany only. This does not include towing charges or customer supplied parts. Neglect/abuse of vehicle will immediately void any and all warranties. Warranty is transferable to subsequent vehicle owner(s) as long as the vehicle continues to be serviced, maintained and repaired at Autogermany. Semi-annual inspection must be performed by Autogermany to retain the warranty. *Some limitations apply. This does not include wearable items including but not limited to brakes, belts, tires, hose, etc. Ask advisor for details on the specific part being installed. GST#: 744 546 516

Wheel nuts (bolts) tightness (torque) must be rechecked by AUTOGERMANY after 80 kilometers.

Once vehicle repairs are completed, customers will be notified promptly using the contact information provided at the time of service. Customers are expected to pick up their vehicles within 14 calendar days of this notification. Starting on the 15th day, a storage fee of \$20.00 per day will be applied to the total bill for each day the vehicle remains on the premises.

Work Authorization Signature:

Total Labor: \$1,347.00
Total Parts: \$3,438.73
Total Fees: \$150.00
Subtotal: \$4,935.73
Taxes: \$262.79
Grand Total: \$5,198.52
BALANCE DUE: \$0.00

X 

✓ PAID

Payment History

Date	Customer Name	Payment Method	Amount	Payment Info	Transaction Details	Signature
03/27/24		Credit Card	\$4,998.18	Auth: 002904	Chio	
03/20/24		Credit Card	\$200.34	Auth: 041177	Contactless	

Declined Jobs:**1 - REPLACE REAR SHOCK ABSORBERS**

X Declined on 03/20/24 at 02:31 PM MDT Subtotal \$3,420.38 + est. Tax \$171.02 **\$3,591.40**