



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment


## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

Invoice to:



|                          |                             |                   |                  |  |  |
|--------------------------|-----------------------------|-------------------|------------------|--|--|
| Branch<br><b>BRANDON</b> |                             |                   | <b>*REPRINT*</b> |  |  |
| Date<br><b>04/20/20</b>  | Time<br><b>22:14:49 (B)</b> | Page<br><b>01</b> |                  |  |  |
| Account No.              | Phone No.                   | Reference No.     |                  |  |  |
| [Redacted]               |                             |                   |                  |  |  |
| Ship Via                 | Purchase Order              |                   |                  |  |  |
| G.S.T. No.               |                             | [Redacted]        |                  |  |  |
| Credit Card No.          | Salesperson<br><b>J77</b>   |                   |                  |  |  |

## Description of Work and Parts

| STK#/FLEET# |              | HRS  | PIN/EIN   | WARRANTY DATE | HRS |
|-------------|--------------|------|-----------|---------------|-----|
| 142849      | 4530 FLOATER | 3177 | YCT033438 |               |     |
|             | 4530         |      |           |               |     |

Fold - - -

**\*\*Here at Rocky for your protection and ours we are wiping down  
\*\* every piece of equipment before and after we repair it.**

SEGMENT# 1 C 01861 NA 02/03/20 02/04/20  
RED SEAL REPAIRS  
12.5% OFF OF LABOUR = -\$1680.24 (WNTR WORKS DISC)  
12.5% OFF OF PARTS = -\$5356.15 (DISCOUNT)  
13000051

SEGMENT# 2 C 01861 NA 02/25/20 02/25/20  
REPLACE A/C CONDENSOR 5.40 HRS

### CORRECTION:

hook up gauges and evacuate system. system over charged at 6.3lbs.  
remove hood bracket and mount  
torched out seized bolts for hood mount  
opened hood and removed hood mount.  
removed hardware for upper condenser  
bottom hardware had to be heated and worked back and forth to get moving  
once free had to turn the bolts out an 1\8th of a turn at a time to get bolts out of corroded air to air housing.  
have to remove cooler box to change oil cooler.

|          |                |     |         |         |
|----------|----------------|-----|---------|---------|
| BN324152 | COOLER ASS     | 1 N | 1788.00 | 1788.00 |
| R32551C  | DEF FLUID 2.5G | 2   | 12.98   | 25.96   |
| 128483A1 | O-RING         | 3   | 2.53    | 7.59    |
| 47821526 | DRIER          | 1 S | 93.16   | 93.16   |
| 86641293 | SCREW          | 1   | 4.35    | 4.35    |
| 9827058  | O-RING         | 1   | 4.04    | 4.04    |

CONTINUED ON PAGE 02

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

Please Remit to:  
Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

## INVOICE

Ship to:

Invoice to:

|                          |                             |                   |
|--------------------------|-----------------------------|-------------------|
| Branch<br><b>BRANDON</b> |                             |                   |
| Date<br><b>04/20/20</b>  | Time<br><b>22:14:49 (B)</b> | Page<br><b>02</b> |
| Account No.              | Phone No.                   | Reference No.     |
|                          |                             |                   |
| Credit Card No.          | Salesperson<br><b>J77</b>   |                   |

### Description of Work and Parts

| STK#/FLEET# |              | HRS    | PIN/EIN   | WARRANTY DATE    | HRS   |         |
|-------------|--------------|--------|-----------|------------------|-------|---------|
| 142849      | 4530 FLOATER | 3177   | YCT033438 |                  |       |         |
|             | 4530         |        |           |                  |       |         |
| 9827059     |              | O-RING |           | 1                | 1.51  | 1.51    |
|             |              |        |           |                  | PARTS | 1924.61 |
|             |              |        |           |                  | LABOR | 729.00  |
| 13000051    |              |        |           | SEGMENT TOTAL==> |       | 2653.61 |

SEGMENT# 3 C 01861 NA 02/25/20 02/25/20  
REPLACE OIL COOLER 3.60 HRS

#### CORRECTION:

removed air cleaner and intake piping removed aspirator piping.  
used torch to heat and remove hydraulic lines and trans cooler lines from the oil cooler. cleaned pails and drained antifreeze. antifreeze is full of rust and system is over half empty.  
unbolted air to air and removed hooked cooler to crane and attempted to remove had to remove the engine fan first before removing the cooler box.  
once the fan was removed cooler box lifted out replaced oil cooler and assembled back onto the unit. installed new fan and bolted cooler box in applying never sieze to all bolts  
assembled unit back together topped up coolant and filled hydraulic system.  
installed ac condenser and new receiver drier vacuumed system down and checked for leaks. filled system to correct charge.  
test drove unit and checked for leaks

|          |            |     |         |         |
|----------|------------|-----|---------|---------|
| BN324333 | OIL COOLER | 1 N | 3336.00 | 3336.00 |
| 86592701 | WASHER     | 1   | 2.83    | 2.83    |

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

Invoice to:

|                 |                |               |
|-----------------|----------------|---------------|
| Branch          |                |               |
| Date            | Time           | Page          |
| Account No.     | Phone No.      | Reference No. |
| Ship via        | Purchase Order |               |
|                 |                | G.S.T. No.    |
| Credit Card No. | Salesperson    |               |
|                 | J77            |               |

## Description of Work and Parts

| STK#/FLEET# | HRS          | PIN/EIN | WARRANTY DATE    | HRS |         |
|-------------|--------------|---------|------------------|-----|---------|
| 142849      | 4530 FLOATER | 3177    | YCT033438        |     |         |
|             | 4530         |         |                  |     |         |
| 87019792    | WASHER       | 5       | 3.12             |     | 15.60   |
| 9824051     | O-RING       | 2       | 1.65             |     | 3.30    |
| 9991976     | O-RING       | 2       | 1.35             |     | 2.70    |
|             |              |         | PARTS            |     | 3360.43 |
|             |              |         | LABOR            |     | 486.00  |
| 13000051    |              |         | SEGMENT TOTAL==> |     | 3846.43 |

Fold - - -

|                                           |                   |     |                  |  |        |
|-------------------------------------------|-------------------|-----|------------------|--|--------|
| SEGMENT# 4 C 01861 NA                     | 02/25/20 02/25/20 |     |                  |  |        |
| REPLACE ENGINE FAN                        |                   |     | 2.50 HRS         |  |        |
| <u>CORRECTION:</u>                        |                   |     |                  |  |        |
| fan replaced during oil cooler change out |                   |     |                  |  |        |
| ANT1                                      | ENVIRO ANTIFRZ    | 60  | .18              |  | 10.80  |
| B30205C                                   | ANTI PREMIX 10L   | 6   | 26.45            |  | 158.70 |
| PFTC1/4                                   | cap               | 1   | 2.10             |  | 2.10   |
| 364357C2                                  | 3/8" HOSE         | 4   | 4.90             |  | 19.60  |
| 84255719                                  | FAN               | 1 N | 415.00           |  | 415.00 |
| 86980406                                  | BOLT              | 4 N | 3.35             |  | 13.40  |
|                                           |                   |     | PARTS            |  | 619.60 |
|                                           |                   |     | LABOR            |  | 337.50 |
| 13000051                                  |                   |     | SEGMENT TOTAL==> |  | 957.10 |

|                                                             |                   |     |          |  |       |
|-------------------------------------------------------------|-------------------|-----|----------|--|-------|
| SEGMENT# 5 C 01861 NA                                       | 02/25/20 02/25/20 |     |          |  |       |
| BATTERY CABLES                                              |                   |     | 4.80 HRS |  |       |
| <u>CORRECTION:</u>                                          |                   |     |          |  |       |
| removed corroded cables clean and polish battery leads      |                   |     |          |  |       |
| install new cables tie up cable along frame coat leads with |                   |     |          |  |       |
| battery saver                                               |                   |     |          |  |       |
| 47365538                                                    | CABLE BATTERY     | 1 N | 66.10    |  | 66.10 |
| 84423357                                                    | CABLE BATTERY     | 1 N | 42.80    |  | 42.80 |
| 84423367                                                    | CABLE BATTERY     | 1 N | 40.13    |  | 40.13 |

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

Please Remit to:  
Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

## INVOICE

Ship to:

Invoice to:

|                 |      |             |
|-----------------|------|-------------|
| Branch          |      |             |
| BRANDON         |      |             |
| Date            | Time | Page        |
| [REDACTED]      |      |             |
| Ac [REDACTED]   |      |             |
| SH [REDACTED]   |      |             |
| Credit Card No. |      | Salesperson |
|                 |      | J77         |

### Description of Work and Parts

| STK#/FLEET# |              | HRS   | PIN/EIN   | WARRANTY DATE    | HRS    |        |
|-------------|--------------|-------|-----------|------------------|--------|--------|
| 142849      | 4530 FLOATER | 3177  | YCT033438 |                  |        |        |
|             | 4530         |       |           |                  |        |        |
| 84423425    |              | CABLE | BATTERY   | 1 N              | 41.80  | 41.80  |
| 84423454    |              | CABLE | BATTERY   | 1 N              | 109.00 | 109.00 |
|             |              |       |           |                  | PARTS  | 299.83 |
|             |              |       |           |                  | LABOR  | 648.00 |
| 13000051    |              |       |           | SEGMENT TOTAL==> |        | 947.83 |

SEGMENT# 7 C 01861 NA 02/25/20 03/10/20

REPAIR ELECTRICAL

CORRECTION:

check grounds and harnesses inside cab and underneath cab  
verify grounds are tight harness in cab and outside of cab  
is corroded and weathered after checking harnesses pins  
cab fan is no longer cutting in and out

ADDITIONAL DESCRIPTION:

Cannot quote electrical Diagnosis and repair in this case.

|          |                |   |                  |        |
|----------|----------------|---|------------------|--------|
| 7081-PK  | RBBR MTNG BASE | 1 | 10.66            | 10.66  |
|          |                |   | PARTS            | 10.66  |
|          |                |   | LABOR            | 702.00 |
| 13000051 |                |   | SEGMENT TOTAL==> | 712.66 |

SEGMENT# 8 C 01861 NA 02/25/20 02/25/20

REPAIR FANS

14.00 HRS

CORRECTION:

removed pieces of debris, screen broke off lock collar bolts  
and attempted to remove lock collar  
removed lock collar with three jaw puller.  
when removing the housing i noticed its all cracked and  
missing pieces.  
removed fan assembly, bolts had been broken off in housing  
from previous owner

CONTINUED ON PAGE 05

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment


## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

Invoice to:



|                           |                             |                   |
|---------------------------|-----------------------------|-------------------|
| Branch<br><b>BRANDON</b>  |                             |                   |
| Date<br><b>04/20/20</b>   | Time<br><b>22:14:49 (B)</b> | Page<br><b>05</b> |
| Account No.               | Phone No.                   | Reference No.     |
| Ship to: [Redacted]       |                             |                   |
| Credit Card No.           |                             |                   |
| Salesperson<br><b>J77</b> |                             |                   |

## Description of Work and Parts

STK#/FLEET#

142849

4530 FLOATER  
4530

HRS

3177

PIN/EIN

YCT033438

WARRANTY DATE

HRS

Fold - - -

installed new bolts with silicone to prevent from turning  
built fan housing and assembled installed fan housing and  
motor. set lock collar.  
second fan removed screen and lock collar bolts broke off  
used puller to pull hub. noticed the motor would not turn  
attempted to use a bar to free up the motor.  
motor is seized and will not turn. removed fan housing it  
is rotten and crumbled apart  
installed new new fan housing and replaced broken bolts.  
removed fan motor had to heat  
fittings for them to come loose replaced fan motor and  
fittings installed motor and test run fans

|             |                 |      |         |         |
|-------------|-----------------|------|---------|---------|
| BN300265    | PLATE FAN MOUNT | 1 M  | 136.00  | 136.00  |
| BN35697C    | CORE-MOTOR      | 1-   | 264.00  | 264.00- |
| BN35697R    | MOTOR, HYD      | 1 M  | 2050.30 | 2050.30 |
| BN35697C    | CORE-MOTOR      |      | 264.00  | 264.00  |
| BN35698     | BUSH-TAPER 20MM | 2    | 63.53   | 127.06  |
| BN50138     | WASHER          | 18 N | 4.50    | 81.00   |
| BN50146     | WASHER          | 12 N | .86     | 10.32   |
| BN50254     | BOLT            | 12 N | 4.06    | 48.72   |
| BN50671     | BOLT 1/4X1 SS   | 30 N | 3.70    | 111.00  |
| BN50697     | BOLT            | 18 S | 1.53    | 27.54   |
| BN50759     | NUT             | 12 N | 4.35    | 52.20   |
| BN50769     | SCREW           | 20 N | 1.34    | 26.80   |
| BN55359     | NUT 1/4 S/S     | 30 N | 2.25    | 67.50   |
| BN68580     | FAN, GASKET     | 2 N  | 23.75   | 47.50   |
| FREIGHT     | SHIP-HANDLING   | 2    | 41.67   | 83.34   |
| G60800-0806 | fitting         | 2    | 3.50    | 7.00    |
| G60800-0810 | 8MFFOR-10MB     | 2    | 6.50    | 13.00   |
| G60800-1212 | ADAPTER         | 2    | 5.82    | 11.64   |

CONTINUED ON PAGE 06

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

Invoice to:

|                 |                |               |
|-----------------|----------------|---------------|
| Branch          |                |               |
| Date            | Time           | Page          |
| Account No.     | Phone No.      | Reference No. |
| Ship via        | Purchase Order |               |
| G.S.T. No.      |                |               |
| Credit Card No. | Salesperson    |               |
|                 | J77            |               |

## Description of Work and Parts

| STK#/FLEET#   | HRS              | PIN/EIN        | WARRANTY DATE | HRS |            |
|---------------|------------------|----------------|---------------|-----|------------|
| 142849        | 4530 FLOATER     | 3177 YCT033438 |               |     | Fold - - - |
|               | 4530             |                |               |     |            |
| HAR0806       | KEYSTOCK 1/4     | 4              | 4.64          |     | 18.56      |
| 1020540       | SCREEN           | 2 N            | 70.08         |     | 140.16     |
| 1020543       | SCREEN           | 2 S            | 226.51        |     | 453.02     |
| 48184649      | ROTOR            | 1 N            | 670.00        |     | 670.00     |
| 48184651      | ROTOR FAN CCW    | 1 N            | 665.00        |     | 665.00     |
| 5CS .375 NUTS | stainless nuts   | 12             | .20           |     | 2.40       |
| 5CS 1/4 FLAT  | stainless flat   | 6              | .10           |     | .60        |
| 5CS 1/4 LOCK  | 1/4 lock wash    | 24             | .15           |     | 3.60       |
| 5CS 1/4X3/4   | 1/4" bolt        | 6              | .20           |     | 1.20       |
| 87265707      | RH FAN HSG 6"    | 2 N            | 877.70        |     | 1755.40    |
| 87265708      | LH FAN HSG 6"    | 2 N            | 835.23        |     | 1670.46    |
| 87265721      | GROMMET          | 1 N            | 6.67          |     | 6.67       |
|               | PARTS            |                |               |     | 8287.99    |
|               | LABOR            |                |               |     | 1890.00    |
| 13000051      | SEGMENT TOTAL==> |                |               |     | 10177.99   |

SEGMENT# 9 C 01861 NA 02/25/20 03/18/20 18.00 HRS

### BELT TRACKING

### CORRECTION:

March 30 2020 BAF  
Removed LH dividers had a hard time getting it apart  
everything rusted  
Removed LH conveyor assembly  
March 31 2020 BAF  
Remove brackets from grease lines  
April 3 2020 BAF  
Set belt tracking  
replaced side seals on LH side  
April 6 2020 BAF  
Replaced front seal on left hand side

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

**Please Remit to:**  
Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

## INVOICE

Ship to:

C - [REDACTED]

Invoice to:

[REDACTED]

|                               |                              |                             |
|-------------------------------|------------------------------|-----------------------------|
| Branch<br>[REDACTED]          |                              |                             |
| Date<br>[REDACTED]            | Time<br>[REDACTED]           | Page<br>[REDACTED]          |
| Account No.<br>[REDACTED]     | Phone No.<br>[REDACTED]      | Reference No.<br>[REDACTED] |
| Ship via<br>[REDACTED]        | Purchase Order<br>[REDACTED] |                             |
| G.S.T. No.<br>[REDACTED]      |                              |                             |
| Credit Card No.<br>[REDACTED] | Salesperson<br>J77           |                             |

### Description of Work and Parts

| STK#/FLEET# |              | HRS  | PIN/EIN   | WARRANTY DATE | HRS |  |
|-------------|--------------|------|-----------|---------------|-----|--|
| 142849      | 4530 FLOATER | 3177 | YCT033438 |               |     |  |
|             | 4530         |      |           |               |     |  |

Fold - - -

Had to take side shield off again and cut so they would fit  
Installed manifold with new seal  
reinstalled divider bracket and motor  
April 7 2020 BAF  
Finished assembling

|          |                  |     |          |          |
|----------|------------------|-----|----------|----------|
| ZPX25223 | ADHESIVE         | 1   | 37.75    | 37.75    |
| 87267730 | VALVE, HYD       | 1 N | 12485.00 | 12485.00 |
|          | PARTS            |     |          | 12522.75 |
|          | LABOR            |     |          | 2430.00  |
| 13000051 | SEGMENT TOTAL==> |     |          | 14952.75 |

|                                             |                   |     |          |         |
|---------------------------------------------|-------------------|-----|----------|---------|
| SEGMENT#10 C 01861 NA                       | 02/25/20 03/19/20 |     |          |         |
| POLISH CYLINDERS                            |                   |     | 4.50 HRS |         |
| <u>CORRECTION:</u>                          |                   |     |          |         |
| polish cylinders with cloth to remove rust. |                   |     |          |         |
| use crocus cloth to work out pit marks      |                   |     |          |         |
| cylinders are all pitted beyond salvageable |                   |     |          |         |
| put cylinder in cab for customer            |                   |     |          |         |
| FREIGHT                                     | SHIP-HANDLING     | 1   | 15.00    | 15.00   |
| 87267313                                    | CYLINDER          | 1 N | 728.00   | 728.00  |
|                                             | PARTS             |     |          | 743.00  |
|                                             | LABOR             |     |          | 607.50  |
| 13000051                                    | SEGMENT TOTAL==>  |     |          | 1350.50 |

|                                               |                   |     |          |        |
|-----------------------------------------------|-------------------|-----|----------|--------|
| SEGMENT#11 C 01861 NA                         | 02/25/20 02/25/20 |     |          |        |
| GATE SEALS                                    |                   |     | 4.00 HRS |        |
| <u>CORRECTION:</u>                            |                   |     |          |        |
| unbolt gate wiper seals and install new seals |                   |     |          |        |
| set gap and install steel clamp               |                   |     |          |        |
| BN302681                                      | SEAL, RUBB        | 2 S | 53.25    | 106.50 |
| CONTINUED ON PAGE 08                          |                   |     |          |        |

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

**Please Remit to:**  
Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

## INVOICE

Ship to:

Invoice to:

|                 |                |               |
|-----------------|----------------|---------------|
| Branch          |                |               |
| Date            | Time           | Page          |
| Account No.     | Phone No.      | Reference No. |
| Ship via        | Purchase Order |               |
|                 |                | G.S.T. No.    |
| Credit Card No. | Salesperson    |               |
|                 | J77            |               |

### Description of Work and Parts

| STK#/FLEET# |               | HRS  | PIN/EIN   | WARRANTY DATE    | HRS |         |
|-------------|---------------|------|-----------|------------------|-----|---------|
| 142849      | 4530 FLOATER  | 3177 | YCT033438 |                  |     |         |
|             | 4530          |      |           |                  |     |         |
| BN307231    | SEAL, BOTTOM  | 2    |           | 40.25            |     | 80.50   |
| BN324817    | SEAL          | 4 N  |           | 81.25            |     | 325.00  |
| BN50212     | BOLT          | 8 N  |           | 3.35             |     | 26.80   |
| BN55359     | NUT 1/4 S/S   | 8 N  |           | 2.25             |     | 18.00   |
| BN68581     | GASK, VENTURI | 2 N  |           | 43.75            |     | 87.50   |
| FREIGHT     | SHIP-HANDLING | 2    |           | 30.00            |     | 60.00   |
|             |               |      |           | PARTS            |     | 704.30  |
|             |               |      |           | LABOR            |     | 540.00  |
| 13000051    |               |      |           | SEGMENT TOTAL==> |     | 1244.30 |

|                                                                   |                   |  |  |                  |  |         |
|-------------------------------------------------------------------|-------------------|--|--|------------------|--|---------|
| SEGMENT#12 C 01861 NA                                             | 02/25/20 03/18/20 |  |  |                  |  |         |
| AUTO-FOLD                                                         |                   |  |  | 8.00 HRS         |  |         |
| <u>CORRECTION:</u>                                                |                   |  |  |                  |  |         |
| unfold booms                                                      |                   |  |  |                  |  |         |
| left boom hinge seized bending cylinder and hinges                |                   |  |  |                  |  |         |
| used torch to cut bent seized pieces                              |                   |  |  |                  |  |         |
| removed the boom to bring into the shop.                          |                   |  |  |                  |  |         |
| cut off blown hydraulic hose and got hose made from parts         |                   |  |  |                  |  |         |
| was difficult to get hose started due to location of the fittings |                   |  |  |                  |  |         |
| installed hose and added 80 litres of bulk hytran                 |                   |  |  |                  |  |         |
| brought unit back inside                                          |                   |  |  |                  |  |         |
|                                                                   |                   |  |  | LABOR            |  | 1080.00 |
| 13000051                                                          |                   |  |  | SEGMENT TOTAL==> |  | 1080.00 |

|                       |                   |  |  |           |  |  |
|-----------------------|-------------------|--|--|-----------|--|--|
| SEGMENT#13 C 01861 NA | 02/25/20 03/19/20 |  |  |           |  |  |
| HYD LEAKS             |                   |  |  | 10.00 HRS |  |  |
| <u>COMPLAINT:</u>     |                   |  |  |           |  |  |
| hydraulic leaks       |                   |  |  |           |  |  |
| <u>CAUSE:</u>         |                   |  |  |           |  |  |

CONTINUED ON PAGE 09

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

**Please Remit to:**  
Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

## INVOICE

Ship to:

C [REDACTED]

Invoice to:

[REDACTED]

|                               |                              |                             |
|-------------------------------|------------------------------|-----------------------------|
| Branch<br>[REDACTED]          |                              |                             |
| Date<br>[REDACTED]            | Time<br>[REDACTED]           | Page<br>[REDACTED]          |
| Account No.<br>[REDACTED]     | Phone No.<br>[REDACTED]      | Reference No.<br>[REDACTED] |
| Ship via<br>[REDACTED]        | Purchase Order<br>[REDACTED] |                             |
| G.S.T. No.<br>[REDACTED]      |                              |                             |
| Credit Card No.<br>[REDACTED] | Salesperson<br>J77           |                             |

### Description of Work and Parts

| STK#/FLEET#                                                                                                                                                                                                                | HRS              | PIN/EIN        | WARRANTY DATE | HRS     | Fold - - - |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|----------------|---------------|---------|------------|
| 142849                                                                                                                                                                                                                     | 4530 FLOATER     | 3177 YCT033438 |               |         |            |
|                                                                                                                                                                                                                            | 4530             |                |               |         |            |
| <p>rusted lines</p> <p><u>CORRECTION:</u></p> <p>remove lines, heat needed to loosen stuck fittings, too damaged to reuse</p> <p>make 2 hoses to replace steel lines</p> <p>install hoses to cylinders and valve block</p> |                  |                |               |         |            |
| FREIGHT                                                                                                                                                                                                                    | FREIGHT          | 1              | 171.00        | 171.00  |            |
| FREIGHT                                                                                                                                                                                                                    | SHIP-HANDLING    | 1              | 10.00         | 10.00   |            |
| G25170-0406                                                                                                                                                                                                                | END              | 2              | 10.36         | 20.72   |            |
| G25230-1212                                                                                                                                                                                                                | fitting          | 1              | 19.15         | 19.15   |            |
| G25239-0406                                                                                                                                                                                                                | FITTING          | 2              | 23.00         | 46.00   |            |
| G25239-1212                                                                                                                                                                                                                | 12G-12FFORX90S   | 1              | 33.56         | 33.56   |            |
| OIL2                                                                                                                                                                                                                       | ENVIRO OIL>30    | 170            | .10           | 17.00   |            |
| 12G2                                                                                                                                                                                                                       | 3/4 hyd hose     | 4              | 9.46          | 37.84   |            |
| 4G2                                                                                                                                                                                                                        | 1/4 hyd hose     | 26             | 3.08          | 80.08   |            |
| 73341729                                                                                                                                                                                                                   | HYTRAN ULTA BUL  | 170            | 4.92          | 836.40  |            |
|                                                                                                                                                                                                                            | PARTS            |                |               | 1271.75 |            |
|                                                                                                                                                                                                                            | LABOR            |                |               | 540.00  |            |
| 13000051                                                                                                                                                                                                                   | SEGMENT TOTAL==> |                |               | 1811.75 |            |

SEGMENT#14 C 01861 NA 02/25/20 03/11/20 1.00 HRS

ADJUST HOOD LATCH

CORRECTION:

attempt to adjust hood latch. cable and latch break due to corrosion of the white metal.

removed and replace cable and latch.

had to order sticky ziptie anchors to keep cable free of grill

|          |                 |     |        |        |
|----------|-----------------|-----|--------|--------|
| FREIGHT  | SHIP-HANDLING   | 1   | 15.00  | 15.00  |
| 443297A1 | CABLE PULLING G | 1 N | 175.45 | 175.45 |

CONTINUED ON PAGE 10

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

C

Invoice to:

|                 |                    |               |
|-----------------|--------------------|---------------|
| Branch          |                    |               |
| Date            | Time               | Page          |
| Account No.     | Phone No.          | Reference No. |
| Ship via        | Purchase Order     |               |
|                 |                    | G.S.T. No.    |
| Credit Card No. | Salesperson<br>J77 |               |

## Description of Work and Parts

| STK#/FLEET# | HRS           | PIN/EIN        | WARRANTY DATE    | HRS    |  |
|-------------|---------------|----------------|------------------|--------|--|
| 142849      | 4530 FLOATER  | 3177 YCT033438 |                  |        |  |
|             | 4530          |                |                  |        |  |
| 86639105    | CLEVIS PIN M6 | 1 M            | 9.28             | 9.28   |  |
| 87550202    | LATCH HOOD    | 1 N            | 98.60            | 98.60  |  |
|             |               |                | PARTS            | 298.33 |  |
|             |               |                | LABOR            | 135.00 |  |
| 13000051    |               |                | SEGMENT TOTAL==> | 433.33 |  |

SEGMENT#15 C 04913 NA 02/25/20 02/03/20

WASH

### CORRECTION:

rinse unit for inspection.

13000051

|                  |       |
|------------------|-------|
| LABOR            | 76.95 |
| SEGMENT TOTAL==> | 76.95 |

SEGMENT#16 C 01861 NA 03/25/20 03/25/20

FAN SENSORS

4.00 HRS

### CORRECTION:

fan sensor assembly missing  
install new fan sensor assembly  
aim sensor pins corroded in connector  
remove and replace pins  
assemble and test fan speed operation all ok  
install screens and shields

|          |                 |     |        |        |
|----------|-----------------|-----|--------|--------|
| BN23453  | PLATE, MOU      | 1 N | 58.75  | 58.75  |
| BN50142  | WASHER          | 2 N | 3.99   | 7.98   |
| BN50212  | BOLT            | 2 N | 3.35   | 6.70   |
| BN50232  | 5/16-18X1 SS BL | 1 N | 4.79   | 4.79   |
| BN55359  | NUT 1/4 S/S     | 2 S | 2.25   | 4.50   |
| BN55361  | NUT             | 1   | .58    | .58    |
| FREIGHT  | SHIP-HANDLING   | 3   | 26.10  | 78.31  |
| 86986864 | PLATE, MOU      | 1 N | 217.00 | 217.00 |

CONTINUED ON PAGE 11

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

## INVOICE

Ship to:

Invoice to:

|                 |                |               |
|-----------------|----------------|---------------|
| Branch          |                |               |
| Date            | Time           | Page          |
| Account No.     | Phone No.      | Reference No. |
| Ship via        | Purchase Order |               |
|                 |                | G.S.T. No.    |
| Credit Card No. | Salesperson    |               |
|                 | J77            |               |

## Description of Work and Parts

| STK#/FLEET# | HRS             | PIN/EIN        | WARRANTY DATE    | HRS |         |
|-------------|-----------------|----------------|------------------|-----|---------|
| 142849      | 4530 FLOATER    | 3177 YCT033438 |                  |     |         |
|             | 4530            |                |                  |     |         |
| 87267658    | KIT, FAN SENSOR | 1              | 228.00           |     | 228.00  |
|             |                 |                | PARTS            |     | 606.61  |
|             |                 |                | LABOR            |     | 540.00  |
| 13000051    |                 |                | SEGMENT TOTAL==> |     | 1146.61 |

SEGMENT#17 C 01861 NA 03/25/20 03/25/20 12.00 HRS

### CORRECTION:

cleaned up pivot holes  
held up boom with fork lift  
applied neversieze and and installed new pins and snap rings  
installed new grease nipples and greased pins  
installed hinges bolts and new cylinder  
greased and test  
boom is bent from previous owner hitting something it doesnt  
fold well

|          |                 |     |        |        |
|----------|-----------------|-----|--------|--------|
| BN50594  | BOLT            | 1 N | 8.70   | 8.70   |
| BN50601  | PIN, SPLIT (COT | 2 N | 1.37   | 2.74   |
| BN52335  | CLIP            | 4 N | 11.25  | 45.00  |
| BN55363  | NUT             | 3 N | 2.85   | 8.55   |
| BN67861  | PIN             | 2 N | 62.35  | 124.70 |
| BN69466  | SPACER          | 1 N | 26.10  | 26.10  |
| FREIGHT  | SHIP - HANDLING | 3   | 12.96  | 38.88  |
| 87265962 | ARM             | 1 N | 232.00 | 232.00 |
| 87265964 | LINKAGE         | 1   | 90.75  | 90.75  |
| 87265965 | LINKAGE         | 1   | 90.75  | 90.75  |
| 87266458 | CYLINDER        | 1 N | 975.00 | 975.00 |
| 87310194 | BOLT            | 1 N | 20.30  | 20.30  |
| 87310196 | BOLT            | 1 N | 18.85  | 18.85  |
| 87310323 | NUT             | 2 N | 6.53   | 13.06  |

CONTINUED ON PAGE 12

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

## INVOICE

Ship to:

Invoice to:

|                 |                |               |
|-----------------|----------------|---------------|
| Branch          |                |               |
| Date            | Time           | Page          |
| Account No.     | Phone No.      | Reference No. |
| Ship via        | Purchase Order |               |
| G.S.T. No.      |                |               |
| Credit Card No. | Salesperson    |               |
|                 | J77            |               |

### Description of Work and Parts

| STK#/FLEET# | HRS          | PIN/EIN        | WARRANTY DATE    | HRS |         |
|-------------|--------------|----------------|------------------|-----|---------|
| 142849      | 4530 FLOATER | 3177 YCT033438 |                  |     |         |
|             | 4530         |                |                  |     |         |
| 87564720    | WASHER       | 4              | 3.70             |     | 14.80   |
|             |              |                | PARTS            |     | 1710.18 |
|             |              |                | LABOR            |     | 1620.00 |
| 13000051    |              |                | SEGMENT TOTAL==> |     | 3330.18 |

SEGMENT#18 C 01861 NA 03/27/20 03/27/20 8.00 HRS

CONVEYOR MOTORS

#### CORRECTION:

run up machine one motor is seized and not turning  
the other turns slightly till the belt bearings jam up.  
unbolted dividers and shields,  
removed conveyor decks cut bearings with torch and zip disc  
once removed rollers and belts roller rusted to much to  
allow  
proper tracking  
one belt is torn and the other is grooved  
installed all new bearings, rollers, belts and hardware  
set alignment and installed decks back into floater  
assembled new motors, hoses and hydraulic fittings.  
due to rust and and condition for frame had to shim deck  
lower on the one  
side to prevent belt damage  
installed new seals and gaskets on decking  
installed dividers and set clearances  
installed all new grease lines.  
ran up conveyors but they only turn a bit then stop.  
check hydraulic pressures and there is only a slight amount  
of pressure coming from the valve  
attempt to remove valve had to cut and chisel stem  
once the valve moved i noticed there wasnt enough sealing

CONTINUED ON PAGE 13

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

Please Remit to:  
Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

## INVOICE

Ship to:

Invoice to:

|                 |                |               |
|-----------------|----------------|---------------|
| Branch          |                |               |
| Date            | Time           | Page          |
| Account No.     | Phone No.      | Reference No. |
| Ship via        | Purchase Order |               |
| G.S.T. No.      |                |               |
| Credit Card No. | Salesperson    |               |
|                 | J77            |               |

### Description of Work and Parts

| STK#/FLEET# | HRS          | PIN/EIN | WARRANTY DATE | HRS |
|-------------|--------------|---------|---------------|-----|
| 142849      | 4530 FLOATER | 3177    | YCT033438     |     |
|             | 4530         |         |               |     |

Fold - - -

surface to  
install the new stem,  
marked all electrical connections and hydraulic hoses  
heated and removed all the hoses  
changed out hydraulic valve  
installed hoses and tested operation  
once running i had to adjust tracking on the left side  
conveyor.  
do complete run up of machine test all functions and  
operations.  
scr failure come up when testing found the sending unit was  
causing the faults,  
once going over unit the can system went offline after  
testing and pinning out harness  
removed fuse box and found the broken terminal  
the fuse box was pinned wrong  
swapped pins and temporarily patched harness

|          |                |      |         |         |
|----------|----------------|------|---------|---------|
| BN10500  | BRG. FLANGE 1" | 8 S  | 65.50   | 524.00  |
| BN15031  | CONV BELT      | 2 N  | 1508.00 | 3016.00 |
| BN21398A | COUPLING-MACH  | 4 N  | 143.00  | 572.00  |
| BN307227 | SEAL           | 2 M  | 21.75   | 43.50   |
| BN307229 | SEAL           | 4 N  | 37.34   | 149.36  |
| BN307230 | STRAP          | 4 N  | 58.00   | 232.00  |
| BN35805  | ADAPTER        | 8 N  | 13.50   | 108.00  |
| BN50146  | WASHER         | 4 N  | .86     | 3.44    |
| BN50212  | BOLT           | 8 N  | 3.35    | 26.80   |
| BN50237  | BOLT           | 16 N | 4.35    | 69.60   |
| BN50254  | BOLT           | 8 N  | 4.06    | 32.48   |
| BN50421  | SET SCREW      | 4 N  | 7.18    | 28.72   |
| BN50473  | SET SCREW      | 4 N  | 3.19    | 12.76   |

CONTINUED ON PAGE 14

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

Invoice to:

|                 |                |               |
|-----------------|----------------|---------------|
| Branch          |                |               |
| Date            | Time           | Page          |
| Account No.     | Phone No.      | Reference No. |
| Ship via        | Purchase Order |               |
| G.S.T. No.      |                |               |
| Credit Card No. | Salesperson    |               |

## Description of Work and Parts

| STK#/FLEET#    | HRS            | PIN/EIN        | WARRANTY DATE | HRS |          |
|----------------|----------------|----------------|---------------|-----|----------|
| 142849         | 4530 FLOATER   | 3177 YCT033438 |               |     |          |
|                | 4530           |                |               |     |          |
| BN50671        | BOLT 1/4X1 SS  | 24 M           | 3.70          |     | 88.80    |
| BN50759        | NUT            | 20 N           | 4.35          |     | 87.00    |
| BN53570        | NUT, BHD L     | 1 N            | 9.65          |     | 9.65     |
| BN55359        | NUT 1/4 S/S    | 24             | 2.25          |     | 54.00    |
| BN55361        | NUT            | 16 N           | .58           |     | 9.28     |
| BN65718        | HYDRO,MTR ROSS | 2 N            | 820.00        |     | 1640.00  |
| BN67999        | HOSE           | 4 N            | 45.00         |     | 180.00   |
| BN68186        | HOSE           | 4 N            | 52.25         |     | 209.00   |
| BN69951        | CAP            | 8 N            | .99           |     | 7.92     |
| CUSTDIS        | CUSTOMER DISC  | 2-             | 3.01          |     | 6.02     |
| FREIGHT        | SHIP-HANDLING  | 10             | 22.62         |     | 226.24   |
| G25230-0808    | FITTING        | 4              | 11.57         |     | 46.28    |
| SS .313NC      | stainless nut  | 6              | .25           |     | 1.50     |
| SS .375NC      | stainless nut  | 6              | .50           |     | 3.00     |
| 113-2299       | BOLT           | 10 N           | 3.19          |     | 31.90    |
| 219-402        | FITTING        | 8 N            | 10.50         |     | 84.00    |
| 343299A1       | SET SCREW      | 1 N            | 3.34          |     | 3.34     |
| 343498A1       | PULLEY         | 2 N            | 765.00        |     | 1530.00  |
| 343499A1       | PULLEY         | 2 N            | 655.00        |     | 1310.00  |
| 47471          | KEY, WOODRUFF  | 4              | 6.46          |     | 25.84    |
| 5CS 1/2 FLAT   | stainless wash | 12             | .35           |     | 4.20     |
| 5CS 1/4 FLAT   | stainless flat | 12             | .10           |     | 1.20     |
| 5CS 3/8 FLAT   | stainless wash | 12             | .15           |     | 1.80     |
| 5CS 5/16 FLAT  | stainless wash | 12             | .10           |     | 1.20     |
| 5CS 5/16 FLATS | stainless flat | 30             | .08           |     | 2.40     |
| 8G2            | 1/2 hyd hose   | 5              | 4.16          |     | 20.80    |
| 86580291       | ADAPTER        | 8 N            | 8.70          |     | 69.60    |
| 86633352       | CLAMP          | 1              | 27.61         |     | 27.61    |
|                | PARTS          |                |               |     | 10489.20 |
|                | LABOR          |                |               |     | 1080.00  |

CONTINUED ON PAGE 15

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

## Please Remit to:

Box 60, Site 520, RR #5  
Brandon, MB R7A 5Y5  
Tel: (204) 725-2273  
Fax: (204) 728-1813

# INVOICE

Ship to:

Invoice to:

|                 |                |               |
|-----------------|----------------|---------------|
| Branch          |                |               |
| Date            | Time           | Page          |
| Account No.     | Phone No.      | Reference No. |
| Ship via        | Purchase Order |               |
| G.S.T. No.      |                |               |
| Credit Card No. | Salesperson    |               |
|                 | J77            |               |

## Description of Work and Parts

| STK#/FLEET# |              | HRS  | PIN/EIN   | WARRANTY DATE    | HRS |          |
|-------------|--------------|------|-----------|------------------|-----|----------|
| 142849      | 4530 FLOATER | 3177 | YCT033438 |                  |     |          |
|             | 4530         |      |           |                  |     |          |
| 13000051    |              |      |           | SEGMENT TOTAL==> |     | 11569.20 |

| ***** WORK ORDER TOTALS ***** |           |
|-------------------------------|-----------|
| PARTS                         | 42849.24  |
| LABOR                         | 13441.95  |
| DISPOSAL FEE                  | 99.00     |
| SHOP SUPPLIES                 | 499.00    |
| WNTR WORKS DISC               | 1680.24-  |
| DISCOUNT                      | 5356.15-  |
| SUB TOTAL==>                  | 49852.80  |
| GST 825724032                 | 2492.78   |
| Less Deposit                  | 30114.01- |
| TOTAL CHARGE                  | 22231.57  |

I hereby certify that the goods shown on this invoice are farm implements, farm machinery or repair parts therefor, and will be used principally for farming.

Date

Purchaser's signature

Land Description: Sec\_\_\_\_\_ Twsp\_\_\_\_\_ R\_\_\_\_\_ M\_\_\_\_\_

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$\_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)