

Miss Elsa - XW82AD
 Engine Number - 80357433
 Year - 2022
 VIN Number - 6F5000000MA474736

Date		KM'S
2/23/2022	Purchased vehicle	
3/9/2022	Vehicle added to Mass Management Accreditation	
	Attended break down as requested, Check vehicle for air leak and find red brake valve faulty, Attend workshop to pick up new valve and return to vehicle, Replace valve and check operation	
3/14/2022	Advanced Auto Taree	
4/12/2022	Carried out B Service- 50L of oil needed	RPT 30000
5/10/2022	Carried out B Service- 50L of oil needed	RPT 48750
3/29/2022	2 x X15 Cab Badge	Cummins
6/21/2022	Carried out B Service- 50L of oil needed	RPT 79000
	Engine service, Change engine oil and oil filter, Change primary and secondary fuel filters, Inspect air filter, Check belts for tension and condition, Check battery terminals for tension and condition, Check coolant level and concentration	
7/29/2022	Cummins	
	Tune up, Inspect engine for oil leaks, Inspect for coolant leaks, Check and adjust belts, Pressure test CAC and Boost system, Check wastegate adjustment, Inspect air filter element, Test coolant and check level, Fill out service sticker and place	
9/28/2022	Cummins	149530
	Carried out A B and C service - 50L of oil needed, Changed diff oil and filter x 1, Torque drain and filler plugs	RPT 156800
10/6/2022	Fit customer own tyre x 2, Balance bag x 2	Double D
11/7/2022	Carried out B Service- 50L of oil needed	RPT 180000
12/7/2022	Carried out B Service- 50L of oil needed	RPT 203000
11/17/2022	Front and rear of trailer base, Short wiring in suzi coil, Supply and Truck Electrics	

	Locate truck in yard, attempt operation of trailer brake release button and found no fault, attach trailer to confirm and found red button to be operating with out fault, To confirm no issue connect to air gauges and ensure adequate air pressure supplied to trailer, Customer returned vehicle stating issue reoccurring, customer concern is air coming from red suzi coil when the red trailer brake button is depressed, Retest system and confirm correct operation, Red airline supplying constant tank pressure to trailer / pilot / releasing maxis. Blue line supplying air off of pedal to apply service brakes, reconnect to shop trailer, Trailer releasing immediately, No issue found, Spoke to driver and explained correct operation of the suzi lines for future usage	Brown and Hurley	
12/19/2022	Carried out B Service- 50L of oil needed	RPT	225000
1/27/2023	Labour supplied to remove clock and voltage gauge and replace parts, Parts supplied by the customer, Check and		
2/13/2023	test operation	Truck Electrics	
3/1/2023	Paid Reg - XW82AD	Vic Roads	
	Replace pinion sela on the front diff as leaking, Replace oil in both diffs and clean breather, Replace 4 batteries as faulty	Pitstop	
3/10/2023	Carried out B Service - 50L Of oil needed, Change transmission oil and filter, Changed diff oil and filters x 2,		
3/14/2023	Torque drain and filler plugs	RPT	255000
4/19/2023	Tap heater x 1	Brown and Hurley	
4/26/2023	Carried out B Service - 50L Of oil needed	RPT	280000
5/17/2023	Fit customer own tyre x 1, Wheel Balance x 1	Double D	
	Tune up, Inspect engine for oil leaks, Inspect for coolant leaks, Check and adjust belts, Pressure test CAC and Boost system, Check wastegate adjustment, Inspect air filter element, Test coolant and check level, Fill out service sticker		
5/26/2023	and place	Cummins	303400
5/31/2023	Carried out B Service - 50 L of oil needed	RPT	304000
7/3/2023	Carried out B Service - 50L of oil needed	RPT	328000
	Carried out B Service - 50L of oil needed, Serviced ice pack		
7/31/2023	motor	RPT	350000
7/31/2023	Fit customer own tyre x 4, Balance bag x 2	Double D	
9/12/2023	Pinion seal x 2	TRP	
	Carried out B Service - 50L of oil needed, Changed diff oil		
9/12/2023	and filter x 1, Torque drain and filler plug	RPT	377000
	Labour supplied to diagnose, remove and replace faulty		
9/15/2023	alternator, Check and test operation	Truck Electrics	
10/3/2023	Puncture Repair x 1	Double D	

10/9/2023	Mudguard x 2	TRP	
10/24/2023	Carried out B Service - 50L of Oil Needed	RPT	404500
11/14/2023	Carry out clutch adjustment	G & S Diesel	
12/1/2023	Carried out B Service - 50L of oil needed	RPT	426500

B Service and Tune, Check engine for oil and coolant leaks, Check power steering level, Replace engine oil and oil filter, Check oil sump plug- torque and mark, Check and replace crankcase breather filter if required, Replace doser pump air supply filter, Replace water separator filter on chassis and check micron rating, Replace fuel filter on engine, Replace water filter, Check air filter element and advise, Clean and inspect boost sensor, Test coolant and check level, Check batteries, terminals and load test, Check and adjust all belts, Grease vehicle and report, Check uni joints for excess movement and wear, Check hub oil level, Check gearbox oil level, Check diff oil level, Check brakes and adjust, Check clutch and adjust, Check all hoses and clamps, Check all lights and indicators, Connect onsite, carry out ECM download and check for fault codes, Carry out valve and injector adjustments, Pressure test CAC and boost system, Check wastegate adjustment, Fill washer bottle with additive and top up, Oil leaking at OEM oil filler hose, Fan belt and A/C belt rib starting to crack, A/C belt tensioner bearing stuck, did not rotate, Oil leaking at transmission, oil level ok for now, Turntable jaws need to be tightening and adjusted, Replaced A/C belt tensioner as it under warranty

1/31/2024	coverage, Replaced fan belt and A/C belt	Cummins	452842
2/19/2024	Front end wheel alignment	Pro Axle	

Brought unit into workshop, Jacked up steer axle, Spun the wheels - RHS not spinning evenly, Removed the wheel and drum and inspected, Found hub seal was leaking, Removed the hub and inspected bearings, Brakes were not contaminated so were cleaned up and reused, Fitted new hub seal and refitted hub, Carried out bearing adjustment as per procedure, Refitted wheel and tensioned wheel nuts, Lowered unit onto ground, Adjusted brakes and carried out

2/19/2024	brake test	Brown and Hurley	460239
3/8/2024	Tyre fitting x 4	Double D	
3/10/2024	Puncture Repair x 1	Double D	
3/26/2024	Carried out B Service - 50L of oil needed	RPT	484000
4/18/2024	Tyre fitting x 2, Balance bag x 2	Double D	

Carried out A B and C service - 50L of oil needed, Changed

4/26/2024	diff oil and filter x 2, Torque drain and filler plugs	RPT	500300
5/29/2024	Aerial x 2	TRP	