

N01-4 Saskatoon April



Box 460 • 100 Second Street South
 Davidson, SK S0G 1A0
 Phone: 306-567-3074 • Fax: 306-567-5435
 www.youngs.ca



Regina 306-585-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Wayburn 306-842-2629
 Windthorst 306-224-2110

Ship To:

Invoice To:

Branch DAVIDSON			*REPRINT*		
Date 11/24/25	Time 22:02:19 (B)	Page 01			
Account # KLJJO001	Phone #	Inv # W20784			
Ship Via	Purchase Order #				
Tax ID #					
					Salesperson 823

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH3784	Combine	2104	YGG233422		
	AF8240	1619	WAS 13380832		

SEGMENT# 1 C 64047 N/A 09/13/25 09/13/25

will not start

COMPLAINT:

will not start

CORRECTION:

combine will not start
 does not even click
 check fuses and they are all good
 check neutral start relay and it is good
 try calibrating MFH as it may not be in neutral causing no
 start but does not change anything
 check battery disconnect and not getting full voltage
 through disconnect, still wont start
 test batteries and they are only 640 CCA when they should
 be 1000CCA so replace batteries but still no start
 check voltage at 12V-24V relay and only getting 13 volts in
 and out of it
 check voltage up at starter and only getting 9 volts
 once in a while starter clicks but engine still does not
 crank
 try new 12-24 volt relay and still no crank
 use engine tool to turn over engine and engine will not
 even turn over, engine seized solid
 use hydraulics with tractor in field to lower feeder house
 of combine to separate it from straight cut header then use
 tractor to pull combine far enough back that it can be
 loaded onto trailer. NH

FRTOP	FREIGHT-OTHER	1	40.00	40.00
Polaris Labs Testing				

CONTINUED ON PAGE 02

• I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to the customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express technician's lien is acknowledged on the above noted equipment to secure the amount of repairs thereon. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only and are not binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranties, either expressed or implied, on any repairs performed on equipment that has been modified.

Received By

Thank You!
 We Appreciate Your Business

GST # 894516046

Leading The Way In A Thriving Agricultural Community!



Box 460 • 100 Second Street South
 Davidson, SK S0G 1A0
 Phone: 306-567-3074 • Fax: 306-567-5435
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Wetroun 306-946-3387
 Weyburn 306-842-2629
 Windthorst 306-224-2110

Ship To:

Branch DAVIDSON		
Date 11/24/25	Time 22:02:19 (B)	Page 02
Account # KLJJO001	Phone #	Inv # W20784
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 823

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH3784	Combine	2104	YGG233422		
	AF8240	1619	WAS 13380832		
SGENG1			OIL TEST KIT	1	35.85
SV			Service Call	73	1.85
	(Vehicle Fee)				
			PARTS		210.90
			LABOR		1554.19
11030099			SEGMENT TOTAL==>		1765.09

SEGMENT# 2 C 64047 QC 09/13/25 11/12/25

Young's Complimentary QuickCheck Inspection

COMPLAINT:

Young's Complimentary QuickCheck Inspection

ADDITIONAL DESCRIPTION:

	HRS
1. Young's Complimentary QuickCheck Inspection (QC) Perform complimentary QuickCheck Inspection Only items identified have been inspected.	0.15
Quantity	x1
	0.15

QC Inspection not carried out

SEGMENT# 3 C 64004 N/A 09/13/25 09/13/25

Engine seized

COMPLAINT:

Diagnose why engine seized

CORRECTION:

-took oil sample; drained engine oil and coolant;
 disconnected and lowered rear portion of hopper; removed

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and agents may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my/our Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to the customer is in place at all times while Young's Equipment Inc. is working on and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repair, storage, or other purposes, nor for accidents left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees are covered.
 • An express warranty claim is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the return and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically listed in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, either expressed or implied, on any repairs performed on equipment that has been modified.

Received By

X

Thank You!
 We Appreciate Your Business



Box 460 • 100 Second Street South
 Davidson, SK S0G 1A0
 Phone: 306-567-3074 • Fax: 306-567-5435
 www.youngs.ca



Regina 306-565-2405
 Assinibola 306-642-5991
 Chamberlain 306-638-4516
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629
 Windthorst 306-224-2110

Ship To:

Invoice To:

Branch DAVIDSON		
Date 11/24/25	Time 22:02:19 (B)	Page 03
Account # KLJJ0001	Phone #	Inv # W20784
Ship Via	Purchase Order #	
Tax ID #		
	Salesperson 823	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH3784	Combine	2104	YGG233422		
	AF8240	1619	WAS 13380832		

engine shields and blew buildup of material off engine; recovered refrigerant (5.64 lbs); removed catalyst and step assembly with crane; removed and disconnected all other components; removed engine with crane and placed on stands; removed oil pan and inspected fragments in bottom of pan; removed valve and cam covers; disposed of oil and coolant, mf

-installed new engine into unit with crane and secured in place; reinstalled catalyst with crane and mounted in place, had trouble attaching it on exhaust and took extra time; reinstalled wiring and hoses, it took a while to do as all the mounting brackets were not transferred from old engine; lifted step assembly with crane and reinstalled; reinstalled engine drain tube, rotor gearbox dipstick tube and lower engine access panels; filled rotor gearbox, and engine oil with new oil; filled with new coolant; bled air out of fuel lines and started engine, and checked for leaks; found that there was an exhaust leak and an alarm code for exhaust flap; checked exhaust flap and discovered that it had not been plugged in, plugged wiring in and secured it, rechecked for codes; loosened off exhaust clamps and tried adjusting clamp, still had leak; loosened off for second time and discovered that exhaust was not installed correctly and had to remove catalyst to correct; unbolted and lifted catalyst with crane, turned exhaust and secured in place, reinstalled catalyst and secured it in place; started engine and rechecked for leaks, none found; finished reinstalled engine shields, and hopper; vacuumed, and charged system a/c; adjusted park brake; cleaned up tools and wrote story, mf

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and agents may operate the above-mentioned vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 * It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-mentioned equipment.
 * Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc. employees at our risk.
 * An approved mechanic's lien is acknowledged on the above-mentioned equipment to secure the amount of repairs thereto. Taxes are cash on receipt of trucks. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 * Estimates are for the items specifically identified in the estimate only, and are non-binding.
 * Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Thank You!
 We Appreciate Your Business



Box 460 • 100 Second Street South
 Davidson, SK S0G 1A0
 Phone: 306-567-3074 • Fax: 306-567-5435
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629
 Windthorst 306-224-2110

Ship To:

Branch DAVIDSON		
Date 11/24/25	Time 22:02:19 (B)	Page 04
Account # KLJJ0001	Phone #	Inv # W20784
Ship Via		Purchase Order #
x ID #		
		Salesperson 823

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
UH3784	Combine	2104	YGG233422			
	AF8240	1619	WAS 13380832			
EHCOIL		ENVIRO CHARGE		32	.06	1.92
EHC2.5GL		EHC CHARGE		5	2.60	13.00
GLYCOL 1G 50/50		ENVIRO FEE		1	.99	.99
HC20		CLAMP, HOSE #20		1	1.51	1.51
R134A		REFRIGERANT		2	28.77	57.54
412650		WASHER, SPRING		1	2.04	2.04
47684294		GASKET		1 N	50.82	50.82
488100PBD		PAG 100w/EXTEND		2	4.39	8.78
5802499080R		REMAN ENGINE		1	89250.87	89250.87
5802499080C		CORE-REPLACEMENT			1890.00	1890.00
74643001US		10W40 BULK		25	5.82	145.50
76971JXYCA		OAT 50/50 3.79L		1	22.04	22.04
76971NXYUS		50/50 OAT 2.5G		5	57.91	289.55
77400001US		ULTRACTION BULK		7	5.92	41.44
83-6019PK		8" ZIP TIE		1	8.19	8.19
84438888		HEATER		1 N	408.07	408.07
84480617		UNION, 5/16"		1	9.98	9.98
84480618		UNION		2	10.14	20.28
86610201		RIVNUT M8		1	11.19	11.19
87105048		DRAINCOCK/TAP S		1	139.07	139.07
87643110		COUPLING		1 M	1753.37	1753.37
87668737		TIE, CABLE		15 S	6.58	98.70
87681209		NUT		3	1.44	4.32
965.471		COTTER PIN Sm		1	.31	.31
9804260		BOLT		1	3.17	3.17
						PARTS 94232.65
						LABOR 10268.40
11030099						SEGMENT TOTAL==> 104501.05

SEGMENT# 4 C 64015 NA

09/13/25 09/13/25

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. hereby releases from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repair, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereon. Taxes are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (2% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Received By

Thank You!
 We Appreciate Your Business

GST # 894516046

Leading The Way In A Thriving Agricultural Community!



Box 460 • 100 Second Street South
 Davidson, SK S0G 1A0
 Phone: 306-567-3074 • Fax: 306-567-5435
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629
 Windthorst 306-224-2110

Ship To:

Branch DAVIDSON		
Date 11/24/25	Time 22:02:19 (B)	Page 05
Account # KLJJO001	Phone #	Inv # W20784
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 823

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH3784	Combine	2104	YGG233422		
	AF8240	1619	WAS 13380832		
HAUL					
COMPLAINT:					
Haul unit					
CORRECTION:					
Sep 17: 8240 # YGG233422 (2104 hrs) IN					
SEMILOADED	Semi	24	7.75		186.00
(Hauling Loaded)					
11030099				PARTS	186.00
SEGMENT TOTAL==>					186.00

SEGMENT#	5 C 64047 N/A	09/13/25	09/13/25		
Fan tensioner and bushings					
COMPLAINT:					
replace customer supplied parts					
CORRECTION:					
remove fan pulley and replace with new bearings as well as new bushings in arm.NH					
ZK10	.1 LB METRIC	2	1.30		2.60
METRIC AND GR5 FINE THREAD					
14465981	O-RING	1 M	37.51		37.51
300388	BOLT	1	2.42		2.42
47623577	CAP	1	21.78		21.78
500350419	TENSIONER, BELT	1 O	289.98		289.98
504006261	TENSIONER, BELT	2	259.86		519.72
504046191	TENSIONER, BELT	1	314.03		314.03
86050279	NUT	1	1.74		1.74
PARTS					1189.78
LABOR					199.00
11030099	SEGMENT TOTAL==>				1388.78

CONTINUED ON PAGE 06

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-mentioned vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. or Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-mentioned equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repair, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at our risk.

An express mechanic's lien is acknowledged on the above-mentioned equipment to secure the amount of repair thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 24 percent cash (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturer do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

X

Thank You!
 We Appreciate Your Business

GST # 894516046

Leading The Way In A Thriving Agricultural Community!



Box 460 • 100 Second Street South
 Davidson, SK S0G 1A0
 Phone: 306-567-3074 • Fax: 306-567-5435
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-846-3387
 Weyburn 306-842-2629
 Windthorst 306-224-2110

Ship To:

Invoice To:

Branch DAVIDSON		
Date 11/24/25	Time 22:02:19 (B)	Page 06
Account # KLJJO001	Phone #	Inv # W20784
Ship Via	Purchase Order #	
Tax ID #		
	Salesperson 823	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH3784	Combine	2104	YGG233422		
	AF8240	1619	WAS 13380832		

***** WORK ORDER TOTALS *****

PARTS	95819.33
LABOR	12021.59
shop supplies	400.00
EST SOFTWARE FEE	75.00
SUB TOTAL==>	108315.92
GST 5%	5415.85
TOTAL ON ACCOUNT	113731.77

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and agents may operate the above-mentioned vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on and/or in possession of the above-noted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at our risk.
 • An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to retain the vehicle and/or delivery of equipment until such a point as balances have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

Thank You!
 We Appreciate Your Business

GST # 894516046

Leading The Way In A Thriving Agricultural Community!



Box 460 • 100 Second Street South
 Davidson, SK S0G 1A0
 Phone: 306-567-3074 • Fax: 306-567-5435
 www.youngs.ca



Regina 306-565-2405
 Assiniboia 306-642-5991
 Chamberlain 306-638-4516
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629
 Windthorst 306-224-2110

Ship To:

Branch DAVIDSON			*REPRINT*		
Date 09/29/25	Time 22:04:06 (B)	Page 01			
Account # KLJJO001	Phone #	Inv # W20733			
Ship Via	Purchase Order #				
Tax ID #					
					Salesperson 6SM

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH3784	Combine	2064	YGG233422		
	AF8240	1139	WAS 13380832		

SEGMENT# 1 C 64047 NA 09/08/25 09/08/25

ENG 4465 CODE

COMPLAINT:

ENG 4465 CODE

CORRECTION:

NH- drive to customers remove strainer from bottom of fuel tank and find chaff and dirt to come out of tank and strainer to be full, so replace strainer and then test combine, code still comes up so replace filters but code still comes up. so hook up fuel test kit on combine and test, only getting 110 PSI on gauges B and C so follow etim and it says gear pump failed internally so it needs fuel pump replaced.

th blow off combine
 remove crank case breather
 try to remove gear could not get shaft to hold
 remove gear pump in rear put washer in reinstall
 remove gear
 remove lines remove bracket
 remove pump
 time
 install new pump
 reinstall bracket and lines
 key on to bleed system
 install gear torque 196
 install breather and cover
 run check for leaks
 load up could not get to code out
 100 percent load was all i could get out

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and agents may operate the above-coded vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at any time. Young's Equipment Inc. is not responsible for any loss of use or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-coded equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above-coded equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

GST # 894516045

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business



Box 460 • 100 Second Street South
 Davidson, SK S0G 1A0
 Phone: 306-567-3074 • Fax: 306-567-5435
 www.youngs.ca



Regina 306-565-2405
 Assinibola 306-642-5991
 Chamberlain 306-638-4516
 Moose Jaw 306-694-1800
 Raymore 306-746-2288
 Watrous 306-946-3387
 Weyburn 306-842-2629
 Windthorst 306-224-2110

Ship To:

Branch DAVIDSON		
Date 09/29/25	Time 22:04:06 (B)	Page 02
Account # KLJJO001	Phone #	Inv # W20733
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 6SM

Invoice To:

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
UH3784	Combine	2064	YGG233422		
	AF8240	1139	WAS 13380832		

ADDITIONAL DESCRIPTION:

FUEL PUMP WAS REPLACED PREVIOUSLY, HOWEVER THIS WAS NOT WITHIN THE 2 YEAR REMAN WARRANTY PERIOD. DR SV

	Service Call	24	1.85	44.40
	(Vehicle Fee)			
47393252	STRAINER,	1	119.64	119.64
5801789515	SEALING RING CO	4	53.16	212.64
5802805240R	REMAN-FUEL INJ	1	6411.77	6411.77
5802805240C	CORE-FUEL INJ P		1.39	1.39
	PARTS			6789.84
	LABOR			1681.92
11030099	SEGMENT TOTAL==>			8471.76

SEGMENT# 2 C 64047 QC 09/08/25 09/11/25

Young's Complimentary QuickCheck Inspection

COMPLAINT:

Young's Complimentary QuickCheck Inspection

ADDITIONAL DESCRIPTION:

QC Inspection not carried out

***** WORK ORDER TOTALS *****

PARTS	6789.84
LABOR	1681.92
shop supplies	151.37
SUB TOTAL==>	8623.13
GST 5%	431.17
TOTAL ON ACCOUNT	9054.30

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-quoted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or adjusting at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-quoted equipment.
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for accidents left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
 • An express mechanic's lien is acknowledged on the above-quoted equipment to secure the amount of repair thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.
 • Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
 We Appreciate Your Business