

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3706	indicators, tail lights, wiring	14/03/2026	14/03/2026	1,000,000	0	0		Internal Workshop rewired tailgate light wiring rewired L/H dolly axle light wiring replaced 2x indicator lights & 2x stop taillights	\$0.00
T-493	Trailer Tyre	10/02/2026	10/02/2026	1,088,765	0	0		Internal Workshop Removed wheels, stripped and replaced tyres. Re-fit wheels and torqued wheel nuts to specification, checked all components for serviceability - all in working condition.	\$0.00
R-3408	Brakes, Suspension	05/02/2026	05/02/2026	1,087,664	0	0		Internal Workshop Removed and replaced shock on 3rd axle D/S, removed and replaced brake booster on 3rd axle P/S.	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3410	mudguard	04/02/2026	04/02/2026	1,087,664	0	0		Internal Workshop Removed and replaced damage mudguard, checked all components for serviceability - all in working condition.	\$0.00
T-491	Trailer Tyre	04/02/2026	04/02/2026	1,087,664	0	0		Internal Workshop Removed wheels, stripped and fit new tyres. Re-fit wheels and torqued wheel nuts to specification, checked all components for serviceability - all in working condition.	\$0.00
S-1946	A - 10K	19/01/2026	19/01/2026	1,083,540 10,528	0	0		Internal Workshop Completed "A" service.	\$0.00
S-1945	A - 10K	30/11/2025	30/11/2025	1,073,012 9,967	0	0		Internal Workshop Completed "A" service.	\$0.00
S-1944	A - 10K	28/09/2025	28/09/2025	1,063,045 10,034	0	0		Internal Workshop Completed "A" service.	\$0.00
S-1943	A - 10K	08/08/2025	08/08/2025	1,053,011 9,915	0	0		Internal Workshop Completed "A" service.	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3503	ELECTRICAL, mudguard	30/06/2025	30/06/2025	1,045,515	0	0		Internal Workshop Removed and replaced damaged taillight assemblies, installed new clearance lights, installed new j-bracket for mudguard arm on dolly 1st axle, repaired damaged wiring loom on dolly underneath ball-race.	\$0.00
S-1942	A - 10K	13/06/2025	13/06/2025	1,043,096 10,020	0	0		Internal Workshop Completed "A" service.	\$0.00
S-1941	A - 10K	28/04/2025	28/04/2025	1,033,076 9,969	0	0		Internal Workshop Completed "A" service.	\$0.00
T-379	Puncture	07/04/2025	07/04/2025	1,027,759		0		replaced 2 new tyres on l/h 2nd axle	\$0.00
S-1939	B - 50K	20/03/2025	20/03/2025	1,023,107 29,747	0	0		Internal Workshop Completed "A" service.	\$0.00
R-1867	TYRE	25/02/2025	25/02/2025	1,023,000	0	0		Internal Workshop Replaced L/H 2nd axle brakes as were worn	\$0.00
R-1827	TYRE	04/02/2025	04/02/2025	1,003,552	0	0		Internal Workshop put 2 new trailer tyres	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-1291	C - 100K Annual	18/12/2024	18/12/2024	993,360 25,385	0	0		Internal Workshop C service completed yearly inspection completed	\$0.00
S-1117	B - 50K	11/11/2024	11/11/2024	1,027,000 59,025		0		Internal Workshop	\$0.00
S-1116	A - 10K	11/11/2024	11/11/2024	987,000 19,025		0		Internal Workshop	\$0.00
R-978	Airbag, Chassis, tail lights	22/10/2024	22/10/2024	977,163	0	0		Internal Workshop checked trailer not going up after closing tailgate.found faulty soleniod switch and valve at tank.replaced test ok replaced faulty stop tail light on left rear.test ok had all cracks in chassis (front) welded up1 1 air solenoid 1 sv1 valve 1 stop tail light	\$0.00