VEHIC	LE MAI	NTEN	ANC	E SU	<b>VEHICLE MAINTENANCE SUMMARY - (ALL)</b>		The second secon		Generat	Generated by Transport Compliance PR(	mpliance PR(
Brims Transport	insport						Total for period	\$0.00	From	1/01/2024 To	31/10/202
					Job# DATE	MAINTENANCE TYPE		REPAIRER / STIDDLIED	IEB		
TRUCK										Work Orders 46	\$0.00
			REGO#		XO04XJ	BUILD DATE	092023			46	\$0.00
NO PICTI	NO PICTURE AVAILABLE		FLEET#		PM71	TARE WEIGHT	10160				
			MAKE		Kenworth	GVM / GCM	27830/97000				
			MODEL		T610SAR	NOTES					
A TRUCK SERVICE	VICE									16	r de la companya de l
W/ORDER	968020	KLMS	9682	/ HRS	9/02/2024	1st Service Completed.					\$0.00
W/ORDER	968021	KI MA	22/00	UBC							
											\$0.00
W/ORDER	968022	KLMS	52410	/ HRS	5/04/2024	A Service Completed.					\$0.00
W/ORDER	968023	KLMS	72677	/ HBC	17/01/2024						
						on pictor.					\$0.00
W/ORDER	968024	KLMS	96163	/ HRS	24/06/2024	A Service Completed					\$0.00
W/ORDER	968025	KLMS	127017 /	HRS	26/08/2024	a Service Completed					S C
Wednesday, 5 November 2025	ovember 2025	EN ER TANAMAN ANN ANN ANN ANN ANN ANN ANN ANN A	TOTAL PARTY OF THE			Brims Transport					Page 1 of

Page 1 of

	/2025 A Service Completed.	13/08/2025	5 / HRS	KLMS 347885	9680215	W/ORDER
	7/07/2025 A Service Completed.	7/07	5 / HRS	KLMS 323095	9680214	W/ORDER
	2/06/2025 A Service Completed.	2/06	96 / HRS	KLMS 300996	9680213	W/ORDER
	5/04/2025 A Service Completed.	5/04	52 / HRS	KLMS 279362	9680212	W/ORDER
	<b>27/03/2025</b> A Service Completed.	27/05	00 / HRS	KLMS 247000 /	9680210	W/ORDER
	27/02/2025 A Service Completed.	27/0:	225858 / HRS	KLMS 2258	968029	W/ORDER
	<b>30/12/2024</b> A Service Completed.	30/1	200510 / HRS	KLMS 2005	968028	W/ORDER
	<b>15/11/2024</b> A Service Completed.	15/1	993 / HRS	KLMS 173993	968027	W/ORDER
	<b>27/09/2024</b> A Service Completed.	27/0	210 / HRS	KLMS 145210	968026	W/ORDER
REPAIRER / SUPPLIER INVOICE #	DATE MAINTENANCE TYPE	Job#				

	B Service Completed  B Service Completed  B Service Completed.	27/09/2024 30/12/2024 27/03/2025 2/06/2025	247000 / HRS 300996 / HRS			
	B Service Completed  B Service Completed  B Service Completed.	27/09/2024 30/12/2024 27/03/2025	-	KINS 20	970026	W/ORDER
	B Service Completed  B Service Completed  B Service Completed.	27/09/2024 30/12/2024 27/03/2025	-			
	B Service Completed  B Service Completed	27/09/2024 30/12/2024		KLMS 24	970025	W/ORDER
	B Service Completed  B Service Completed	27/09/2024 30/12/2024				
	B Service Completed	27/09/2024	200510 / HRS	KLMS 20	970024	W/ORDER
	B Service Completed	27/09/2024				
			145210 / HRS	KLMS 14	970023	W/ORDER
	B Service Completed	24/06/2024	96163 / HRS	KLMS	970022	W/ORDER
	B Service Completed	5/04/2024	52410 / HRS	KLMS	970021	W/ORDER
8 \$0.00	B Service Completed.	9/02/2024	9682 / HRS	KLMS	970020	W/ORDER
					RVICE	8 TRUCK SERVICE
\$0.00	5 A Service Completed.	19/09/2025	3/492/ / HKS	VI AL	- 1	
REPAIRER / SUPPLIER INVOICE # TOTAL \$	E MAINTENANCE TYPE	JOD# DATE			9680716	W/ORDER

\$0.00			Annual Inspection Completed	3/02/2025	/5 / HRS	WLINIS 2126/5	202020	
\$0.00	1						969030	W/ORDER
								E TRIICK SERVICE
\$0.00			Custom air serviced @ 1080 hrs	2/06/2025	/ HRS	KLMS	996023	W/ORDER
\$0.00			Custom air serviced @ 722hrs.	27/02/2025	/ HRS	KLMS	996022	W/ORDER
\$0.00			Custom air serviced @ 539 hrs	30/12/2024	200510 / HRS	KLMS 200	996021	W/ORDER
\$0.00	4	- Found missing air cleaner and cover.	Custom Air service Completed 270 hrs - Found missing air cleaner and cover.	26/08/2024	127012 / HRS	KLMS 127	service 996020	Custom Air service W/ORDER 9960
\$0.00			C Service Completed	30/12/2024	200510 / HRS	KLMS 200	971021	W/ORDER
\$0.00	2		C Service Completed.	9/02/2024	9682 / HRS	KLMS	971020	W/ORDER
TOTAL \$	INVOICE #	REPAIRER / SUPPLIER	MAINTENANCE TYPE	Job# DATE	Jo		ERVICE	C TRUCK SERVICE

					Job#	DATE	MAINTENANCE TYPE	REPAIRER / CLIDBUED	
FAULT REPORT	ORT							NVOICE#	SOLOT SOLOT
W/ORDER	973020	KLMS	85405	/ HRS		6/06/2024	Lead springs cleaned and lubricated.		ch or
					1	6/06/2024	CHINDERAH	ERAH	\$0.00
W/ORDER	973021	KLMS	100549 / HRS	/ HRS		18/07/2024	Jaws jamming on truck		
					L	18/07/2024	CHINDERAH	ERAH	\$0.00
W/ORDER	973022	KLMS	177438 /	/ HRS		25/11/2024	Replaced damaged fuel tank step.		5
					1	25/11/2024	CHINDERAH	RAH	\$0.00
REPAIR								,	
W/ORDER	974020	KLMS	2345 /	HRS		25/01/2024	Pre delivery inspection completed. Installed tracker. Install air lines, trailer plug and ABS plug. Road tested .	ines, trailer plug and ABS plug.	\$0.00
W/ORDER	974021	KLMS	17475 /	HRS	N	20/02/2024	Replace suzi coils as snapped.		\$0.00
W/ORDER	974022	KLMS	52410 / HRS	HRS		5/04/2024	Replaced hub caps with new ones. Moved suzi tower back, put 90 bends on airlines and reran all the lines. Horn covers installed.	90 bends on airlines and reran all	\$0.00
W/ORDER	974023	KLMS	65671 /	HRS		2/05/2024	Replace ESOC inlet/leak test. Tighten stack bolts. Fix other rattles.	is,	\$0.00
W/ORDER	974024	KLMS	142840 /	HRS	2(	20/09/2024	Replace cold side and hot side intercooler hoses due to being broken Warranto	olos Morost.	

-
<
m
-
- 0
- 3
=
i D
S
0
01
~
10
-
0
-
ര
3
3
$\sim$
æ
-
0
2
:=
J

R 974025 KLMS 288950 / HRS 16/05/2025 R 974026 KLMS 343087 / HRS 6/08/2025 R 974027 KLMS 347885 / HRS 13/08/2025 R 975020 KLMS 173993 / HRS 15/11/2024 R 975021 KLMS 247000 / HRS 27/03/2025 R 975022 KLMS 247000 / HRS 27/03/2025	\$0.00		All drive tyres replaced.	2/06/2025	ACTIVITY SUCCESSO / FIRS		
R 974025 KIMS 288950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.  R 974026 KIMS 343087 / HRS 6/08/2025 Replace antenna on mirror  R 974027 KIMS 347885 / HRS 13/08/2025 Exhaust bracker loose at motor, tightened. All ok  975020 KIMS 173993 / HRS 15/11/2024 Steer tyres replaced.  975021 KIMS 247000 / HRS 27/03/2025 Steer tyres rotated Lto R				-		975023	W/ORDER
R 974025 KILMS 288950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.  R 974026 KILMS 343087 / HRS 6/08/2025 Replace antenna on mirror  R 974027 KILMS 347885 / HRS 13/08/2025 Exhaust bracket loose at motor, tightened. All ok  975020 KILMS 173993 / HRS 15/11/2024 Steer tyres replaced.	\$0.00		Drive tyres rotated.			9/5022	מאלים איני
R 974025 KLMS 28950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.  R 974026 KLMS 343087 / HRS 6/08/2025 Replace antenna on mirror  R 974027 KLMS 347885 / HRS 13/08/2025 Exhaust bracket loose at motor, tightened. All ok  975020 KLMS 173993 / HRS 15/11/2024 Steer tyres replaced.							
R 974025 KLIMS 288950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.  R 974026 KLIMS 343087 / HRS 6/08/2025 Replace antenna on mirror  R 974027 KLIMS 347885 / HRS 13/08/2025 Exhaust bracket loose at motor, tightened. All ok	\$0.00		Steer tyres rotated L to R			170616	27 O.O.C.
IDER     974025     KLMS     288950 / HRS     16/05/2025     Replace 3rd R/H lower step on rear tank due to damage.     TOWN REPAIRER / SUPPLIER     INVOICE # 10       IDER     974026     KLMS     343087 / HRS     6/08/2025     Replace antenna on mirror       DER     974027     KLMS     347885 / HRS     13/08/2025     Exhaust bracket loose at motor, tightened. All ok       DER     975020     KLMS     173993 / HRS     15/11/2024     Steer tyres replaced.						975021	W/ORDER
ADER     974025     KLMS     288950 / HRS     16/05/2025     Replace 3rd R/H lower step on rear tank due to damage.     REPAIRER / SUPPLIER     INVOICE # 10       IDER     974026     KLMS     343087 / HRS     6/08/2025     Replace antenna on mirror       DER     974027     KLMS     347885 / HRS     13/08/2025     Exhaust bracket loose at motor, tightened. All ok	\$0.00		steer tyres replaced.				
ADER 974025 KIMS 288950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.  TOER 974026 KIMS 343087 / HRS 6/08/2025 Replace antenna on mirror  DER 974027 KIMS 347885 / HRS 13/08/2025 Exhaust bracket loose at motor, tightened. All ok	\$0.00	4	Chortena		173993 /	975020	W/ORDER
974025 KLMS 288950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.  974026 KLMS 343087 / HRS 6/08/2025 Replace antenna on mirror  974027 KLMS 347885 / HRS 13/08/2025 Exhaust bracket loose at motor, tightened. All ok							TYRES
974025 KLMS 288950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.  974026 KLMS 343087 / HRS 6/08/2025 Replace antenna on mirror  974027 KLMS 347885 / HRS 13/08/2025 Exhaust bracket loose at motor, tightened. All ok	50:00						
974025 KLMS 288950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.  974026 KLMS 343087 / HRS 6/08/2025 Replace antenna on mirror	\$0.00		Exhaust bracket loose at motor, tightened. All ok	13/08/2025	347885	974027	W/ORDER
974025 KLMS 288950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.  974026 KLMS 343087 / HRS 6/08/2025 Replace antenna on mirror	40.00						
Job# DATE MAINTENANCE TYPE REPAIRER / SUPPLIER INVOICE # To 974025 KLMS 288950 / HRS 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.	\$0.00		Replace antenna on mirror	6/08/2025	343087 /	9/4026	W/OKUEK
Job# DATE MAINTENANCE TYPE REPAIRER / SUPPLIER INVOICE # TO 16/05/2025 Replace 3rd R/H lower step on rear tank due to damage.					1 2 2		
Job# DATE MAINTENANCE TYPE REPAIRER / SUPPLIER INVOICE #	\$0.00		Replace 3rd R/H lower step on rear tank due to damage.	C207 /C0/0T	1		
DATE MAINTENANCE TYPE	TOTAL \$	INVOICE #		16/05/	288950 / HRS	974025	W/ORDER
			MAINTENANCE TYPE		Jo		