



Vehicle History Detail

Fleet #	R05
Registration	XN90HK
Make	Volvo
Model	Volvo
VIN / Chassis #	YV2V0Y1C2KZ125759

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
02/07/2026	243,468 kms	A - A S-16871 Carried out A service as per service checklist			\$80.00
22/06/2026	243,468 kms	A - A S-16791 Carried out A service as per service checklist			\$80.00
09/04/2026	240,439 kms	A - A S-16376 Carried out A service as per service checklist			\$80.00
09/04/2026	240,439 kms	B - B S-16357 Carried out B service as per service checklist, changing engine oil and filters, changed fuel filters, checked belts and pulleys- OK. Greased and general inspection - OK. Steam cleaned chassis.	Workshop		\$434.56
27/03/2026	238,831 kms	Alternator R-3080 Trouble shoot battery light staying on. Diagnosed faulty alternator, ordered parts Justin Bailey supplied new alternator and tested charge rate - OK.	Workshop		\$868.00
25/03/2026	238,618 kms	A - A S-16267 Carried out A service as per service checklist			\$80.00
26/02/2026	235,157 kms	Damaged Mirror R-3047 Inspected then repaired mirror.	Workshop		\$80.00
14/01/2026	229,128 kms	A - A S-15946 Carried out A service as per service checklist			\$80.00
18/12/2025	226,363 kms	C - C Service S-15843 Carried out C service as per service checklist			\$80.00
18/12/2025	226,363 kms	Leaking radiator Core R-2953 Inspected and repaired coolant leak, diagnosed leaking top tank on radiator. Removed and replace radiator core, coolant hoses, and coolant, reassembled to spec. Also removed and replaced exhaust sensor cleaned and tested OK, rechecked - OK.	Workshop		\$2,694.53

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
18/12/2025	226,363 kms	A - A S-15842 Carried out A service as per service checklist			\$80.00
11/12/2025	225,283 kms	Haulmax 275/70R 22.5 T-891 Supply and fit four new tyres and dispose	Clarence Valley Tyres	1080990	\$2,332.00
26/11/2025		Hankook T-878 Supply and fit two new tyres and wheel balance	Clarence Valley Tyres	1080125	\$1,458.00
19/11/2025		Fit and dispose T-870 Fit and dispose one tyre	Clarence Valley Tyres	1079988	\$77.00
10/11/2025	220,954 kms	A - A S-15611 Carried out A service as per service checklist			\$80.00
30/09/2025	214,988 kms	A - A S-15407 Carried out A service as per service checklist			\$80.00
30/09/2025	214,988 kms	B - B S-15836 Carried out B service as per service checklist changing engine oil and filters and general checks			\$0.00
24/09/2025	214,068 kms	A - A S-15306 Carried out A service as per service checklist			\$80.00
08/09/2025	211,764 kms	A - A S-15305 Carried out A service as per service checklist			\$80.00
28/07/2025	202,940 kms	Engine oil leak. R-2713 Inspected and repaired oil leak down side of block behind filter housing. rained coolant removed fuel filter housing assembly and oil filter housing assembly, cleaned parts - removing and replacing leaking oil housing orings. Reassembled replacing orings, refitted fuel housing and refilled with coolant and bleed fuel system. Started and tested OK.	Workshop		\$572.89
01/07/2025	202,940 kms	A - A S-15309 Carried out A service as per service checklist			\$80.00
02/06/2025	198,707 kms	A - A S-14642 Carried out A service as per service checklist			\$80.00
29/05/2025	198,231 kms 9 hrs	brake R-2607 INSPECT FAULT CODES. FOUND MULTIPLE FAULT CODES FOR DRIVER SUPPORT AND BRAKE WARNINGS. MULTIPLE ECU'S REQUIRED SOFTWARE UPDATES. CARRIED OUT SOFTWARE UPDATES ON ACM, LPOS AND DACU. CARRIED OUT LPOS CALIBRATIONS AFTER UPDATES. ROAD TEST AND CHECK OPERATION ALL OK. L LABOUR BRAKE FAULT INSPECT FOR EGR LEAKS - RAIS CABIN AND INSPECT EGR CIRCUIT- CONFIRMED EGR LEAKING EXHAUST GAS FRON EGR HOUSING. REMOVE AND REPLACE EGR VALVE ASSEMBLY WITH NEW GASKETS. TENSION COMPONENTS AND CALIBRATE. CHECK OPERATION ALL OK.	Southside Truck Centre	661380	\$2,503.45
28/05/2025	197,335 kms	Brake fault. R-2596 Inspected brake fault - jacked up and checked all axles and removed wheels and iinspected brakes and wiring. Visually. Checking OK. Reassembled and booked into Southside.	Workshop		\$70.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
19/05/2025	197,335 kms	A - A S-14598 Carried out A service as per service checklist also steam clean chassis			\$0.00
22/04/2025	193,943 kms	A - A S-14438 Carry out A service as per service checklist			\$0.00
22/04/2025	193,943 kms	B - B S-14439 Carry out B service as per service checklist changing engine oil and filters steam clean chassis			\$0.00
31/03/2025		blinker R-2525 Inspected and repaired blinker r/h front replacing bulb tested ok	workshop		\$0.00
03/03/2025	187,723 kms	A - A S-14077 Carry out A service	Workshop		\$0.00
03/03/2025	187,723 kms	A - A S-14088 Carry out A service as per service checklist			\$0.00
25/02/2025	186,438 kms	A - A S-14087 Carry out A service as per service checklist			\$0.00
17/02/2025	185,894 kms	A - A S-14086 Carry out A service as per service checklist also removed and replaced water pump coolant hose to egr cooler tested ok			\$0.00
03/02/2025	184,101 kms	A - A S-14085 Carry out A service as per service checklist also inspected and repaired both side curtain rollers replacing bearings as required and memory strips cleaned and tested ok			\$0.00
14/01/2025	181,637 kms	A - A S-13918 Carry out A service as per service checklist			\$0.00
08/01/2025		micelin Multi T T-627 Supply and fit new tyres	Clarence Valley Tyres	1066300	\$1,550.00
09/12/2024	176,927 kms	C - C Service S-13724 Carry out C serve as per service checklist also checked max road speed set limit to 100 kms ok			\$0.00
09/12/2024	176,927 kms	A - A S-13720 Carry out A service as per service checklist			\$0.00
14/11/2024	173,164 kms	coolant header tank , washer bottle R-2387 Inspected and replaced coolant header tank due to perished and cracks in plastic ,also replaced washer water tank due to cracks in plastic tested ok	Workshop		\$0.00
13/11/2024	173,164 kms	A - A S-13475 Carry out A service as per service checklist			\$0.00
04/11/2024	172,166 kms	A - A S-13474 Carry out A service as per service checklist			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
16/10/2024		Haulmax 275/70R 22.5 T-577 Supply and fit four new tyres and disposal of tyres	Clarence Valley Tyres	1063374	\$1,832.00
08/10/2024	169,365 kms	A - A S-13472 Carry out A service as per service checklist			\$0.00
08/10/2024	169,365 kms	B - B S-13473 Carry out B service as per service checklist changing engine oil and filters steam clean chassis			\$0.00
09/09/2024	165,745 kms	A - A S-13096 Carry out A service as per service checklist removed and replaced fan belt tensioner ,noisy bearing also removed and replaced drivers side step assembly			\$0.00
15/08/2024	157,884 kms 3,808 hrs	Abssensor R-2281 DROVE TRUCK INTO THE WORK SHOP, CONNECTED PC AND FOUND INNACTIVE FAULT FOR ABSSENSOR. 1ST TEST DRIVE TOCHECK ALL SENSOR READING FOUND 1ST AXLE LH WHEEL SPEED SENSOR WAS READING 230KM WHILE ALL OTHERS WERE READING ROAD SPEED. DROVE BACK TO WORKSHOP AND REMOVED THE SENSOR AND RELEARNT ALL WHEEL SPEED SENSOR PARAMETERS. CLEARED FAULTS. TEST DROVE . ALL SPEED SENSORS READING CORRECTLY. RECHECKED FAULTS WITH NO ACTIVE FAULTS Recurring	Southside Truck Centre	655419	\$305.55
10/07/2024	157,719 kms	A - A S-12883 Carry out A service as per service checklist			\$0.00
26/06/2024	155,134 kms	drive tyres R-2247 Truck sent to CVT tyres inspected and replaced as required	CVT		\$0.00
26/06/2024		Fit and dispose T-514 Fit and dispose of tyre	Clarence Valley Tyres	1058981	\$77.00
20/06/2024	154,235 kms	tail light R-2238 Inspected and repaired brake light glob ,replacing globs as required	Workshop		\$0.00
04/06/2024	152,656 kms	A - A Service S-12599 Carry out A service as per service checklist			\$0.00
04/06/2024	152,656 kms	B - B S-12600 Carry out B service as per service checklist changing engine oil and filters changed air cleaner ,removed belt checking pulleys ok ,also repaired engine oil leak replacing remote mount oil filler tubes ,drained and refilled tailgate lifter oil steam cleaned chassis			\$0.00
03/06/2024	152,351 kms	A - A S-12587 Carry out A service as per service checklist			\$0.00
23/05/2024	151,236 kms	A - A S-12586 Carry out A service as per service checklist			\$0.00
27/03/2024	143,967 kms	A - A S-12585 Carry out A service as per service checklist			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
11/03/2024	143,014 kms	A - A S-12088 Carry out A service as per service checklist			\$0.00
08/02/2024		BFGoodrich 295/80R T-434 Supply and fit two new tyres and wheel balance	Clarence Valley Tyres	1053479	\$1,418.00
05/01/2024	141,076 kms	A - A S-11955 Carry out A service as per service checklist			\$0.00
30/11/2023	138,060 kms	add blue tank R-2011 DRAINED ADBLUE TANK, REMOVED TANK FROM CHASSIS, REMOVED AND REPLACED COMBINATION UNIT, RE INSTALLED TANK INTO CHASSIS, AND REFILLED WITH RECOVERED AD BLUE. CARRIED OUT TEST OF UNIT, PASSED TESTS, CARRIED OUT TEST DRIVE, ALL OK, NO FAULTS	Southside Truck Centre	651630	\$2,439.39
15/11/2023	138,060 kms	Sensor R-2008 connected tech tool to truck, found active fault for l/h front wheel speed sensor not corresponding / reading. removed l/h speed sensor, trace wiring of sensor back to ebs block, install new sensor and run harness, zip tie correctly to loom, cleared fault, carry out calibration of sensor, test, all good	Southside Truck Centre	651347	\$778.00
10/11/2023	138,349 kms	A - A S-11954 Carry out A service as per service checklist			\$0.00
10/11/2023	138,016 kms	CURTAIN LATCH R-2009 Removed and replaced l/h front curtain latch tested ok	Workshop		\$0.00
10/11/2023	138,349 kms	C - C Service S-11980 Carry out C service as per service checklist also checking max road speed limiter on road test set ok			\$0.00
19/10/2023	134,973 kms	EGR valve R-1989 EGR valve replace under warranty.	VCV Australia		\$0.00
09/10/2023	134,596 kms	A - A S-11361 Carry out A service as per service checklist			\$0.00
18/09/2023	133,011 kms	A - A S-11028 Carry out A service as per service checklist			\$0.00
23/08/2023	130,700 kms	A - A S-10920 Carry out A service as per service checklist			\$0.00
16/08/2023	130,220 kms	Fault R-1923 CARRIED OUT CYCLE ON HAND CONTROLLER, PUSHED UP, TRUCK WENT UP, PUSHED DOWN, TRUCK WENT DOWN., CONNECTED TECH TOOL TO TRUCK, OBTAINED FAULT CODES, ONLY 1 INCIDENT REGISTERED FOR HEIGHT CONTROL IREGULARITY FAULT, CLEARED FAULT CODES, CARRIED OUT DIAGNOSIS CYCLE TEST, PASSED, CARRIED OUT SOFTWARE UPDATE, AND THEN CARRIED OUT MULTIPLE, LENGTHY TEST DRIVES, CYCLING RIDE HEIGHT OVER 15 TIMES, TRAVELLING AT MULTIPLE HEIGHTS AND RE SCANNED, NO FAULTS LOGGED. RETURNED TO WORKSHOP, CHECKED ALL AIRBAGS, SUSPENSION ETC, VISUALLY INSPECTED ALL WIRING, NO FAULTS OR DAMAGE VISIBLE. CARRIED OUT FURTHER TEST DRIVES THE FOLLOWING DAY, EVERYTHING OK, TRUCK DIDN'T FAULT.	Southside Truck Centre	649706	\$619.05

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
31/07/2023	129,613 kms	B - B S-10917 Carry out B service as per service checklist changing engine oil and filters and steam clean chassis			\$0.00
19/07/2023	128,017 kms	A - A S-10916 Carry out A service as per service checklist			\$0.00
14/06/2023	125,987 kms	A - A S-10572 Carry out A service as per service checklist			\$0.00
08/05/2023	124,398 kms	A - A S-10571 Carry out A service as per service checklist			\$0.00
17/04/2023	120,611 kms	Ad Blue fault and engine light on R-1837 Removed and replaced NOX Sensor - retested and trick did not refault.	Southside Truck Centre	647543	\$1,324.91
17/04/2023	122,193 kms	A - A S-10570 Carry out A service as per service checklist			\$0.00
07/03/2023	117,379 kms	A - A S-10569 Carry out A service as per service checklist			\$0.00
24/02/2023		tail light repair R-1866 Inspected and repaired tail light as required replacing bulb	Workshop		\$0.00
20/02/2023	115,247 kms	A - A S-10116 Carry out A service as per service checklist			\$0.00
23/01/2023	111,474 kms	B - B S-10115 Carry out B service as per service checklist changing engine oil and filters			\$0.00
09/01/2023	109,456 kms	A - A S-9789 Carry out A service as per service checklist			\$0.00
19/12/2022	107,015 kms	A - A S-9794 Carry out A service as per service checklist change out fan belt and tensioner			\$0.00
07/11/2022	101,442 kms	A - A S-9475 Carry out A service as per service checklist			\$0.00
04/10/2022	96,476 kms	C - C Service S-9348 Carry out C service as per service checklist			\$0.00
04/10/2022	96,476 kms	A - A S-9322 Carry out A service as per service checklist			\$0.00
05/09/2022	92,644 kms	A - A S-9147 Carry out A service as per service checklist			\$0.00
05/09/2022	92,644 kms	B - B S-9148 Carry out B service as per service checklist changing engine oil and filters ,also changing inner and outer air cleaners ,and replacing air dryer filter cleaned and tested also fitted new horn buttons to steering wheel			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
11/08/2022	89,120 kms	A - A S-8906 Carry out A service as per service checklist also cleaned and test run ok			\$0.00
01/06/2022	78,898 kms	A - A S-8905 Carry out A service as per service checklist			\$0.00
10/05/2022	77,242 kms	A - A S-8904 Carry out A service as per service checklist			\$0.00
10/05/2022	77,242 kms	blinker repair, head light R-1638 Inspected and repaired r/h front light ,diagnose faulty light ,removed and replaced tested ok ,inspected r/h side blinker fault finding wire to blinker faulty repaired and tested ok	Workshop		\$0.00
07/04/2022	75,099 kms	A - A S-8295 Carry out A service as per service checklist			\$0.00
08/03/2022	72,782 kms	tailgate lifter solenoids, water pump R-1596 Inspected and repaired coolant leak dianose leaking water pump ,removed and replace pump with exchange unit ,also removed and replace tailgate lifter up and down solenoids tested ok	Workshop		\$0.00
08/03/2022	72,782 kms	B - B S-8133 Carry out B service as per service checklist changing engine oil and filters also steam clean chassis			\$0.00
08/03/2022	72,782 kms	A - A S-8132 Carry out A service as per service checklist			\$0.00
09/02/2022	69,908 kms	A - A S-8131 Carry out A service as per service checklist			\$0.00
12/01/2022	67,515 kms	A - A S-7810 Carry out A service as per service checklist			\$0.00
06/12/2021	64,567 kms	A - A S-7800 Carry out A service as per service checklist			\$0.00
08/11/2021	62,229 kms	A - A S-7567 Carry out A service as per service checklist also steam clean chassis			
11/10/2021	59,993 kms	C - C Service S-7470 Carried out C service as per service checklist jacking up checking front end and general inspections ok cleaned and tested ok			
11/10/2021	59,993 kms	A - A S-7410 Carry out A service as per service checklist also steam clean chassis			
01/09/2021	57,123 kms	A - A S-7238 Cary out A service as per service checklist also steam clean chassis			
26/08/2021	56,646 kms	B - B S-7234 Carry out B service as per service checklist changing engine oil and filters also steam clean chassis			

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
02/08/2021	54,554 kms	A - A S-7164 Carry out A service as per service checklist also steam clean chassis			
12/07/2021	53,016 kms	A - A S-7153 Carry out A service as per service checklist			
24/06/2021	51,853 kms	A - A S-6942 Carry out A service as per service checklist			
19/05/2021	49,241 kms	A - A S-6858 Carry out A service as per service checklist			
06/04/2021	45,590 kms	A - A S-6648 Carry out A service as per service checklist			
03/03/2021	43,317 kms	A - A S-6515 Carry out A service as per service checklist			
15/02/2021	42,042 kms	A - A S-6423 Carry out A service as per service checklist			
14/12/2020	37,807 kms	A - A S-6198 Carry out A service as per service checklist also steam clean chassis			
02/11/2020	34,697 kms	A - A S-6036 Carry out A service as per service checklist also steam clean chassis			
16/10/2020	33,756 kms	horn switch R-1202 Removed and replaced horn switch steering wheel also replacing l/h side front indicator and mirror cover due to hitting something	workshop		
06/10/2020	32,885 kms	A - A S-5923 Carry out A service as per service checklist also steam clean chassis			
06/10/2020	32,885 kms	C - C Service S-5953 Carry out C service as per service checklist also checking vehicle road speed limiter ok			
23/09/2020	32,041 kms	blinker indicator R-1187 Inspected and repaired l/h front side blinker indicator lamp replacing lamp	workshop		
01/09/2020	30,413 kms	A - A S-5833 Carry out A service as per service checklist			
04/08/2020	28,429 kms	A - A S-5700 Carry out A service as per service checklist			
01/07/2020	25,018 kms	B - B S-5555 Carry out B service as per service checklist changing engine oil and filters			
01/07/2020	25,018 kms	A - A S-5554 Carry out A service as per service checklist			

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
21/01/2020	10,724 kms	A - A S-5085 Carry out A service as per service checklist			
03/10/2019	7,347 kms	A - A S-4595 Carry out A service as per service checklist			
119 Records				Total:	\$22,474.33