

Work Order History Listing

W/O No ↓	Asset No	Asset Description	Description	Job Type	Finished Date
4759	303155-FFL1464	CATERPILLAR 988G	fire extinguisher testing replaced fire extinguishers 31/5 as part of service.	Correct	31/05/2024
 4749	303155-FFL1464	CATERPILLAR 988G	PM3 - Victoria Plant Pool - Caterpillar 988G & Repairs. Carry out PM3 Service + Defects and Fit new fire extinguisher. Locate broken grease lines & replaced. Removed and replaced hydraulic steering hose line. (Supply by Red...	PM	3/06/2024
 4604	303155-FFL1464	CATERPILLAR 988G	Check over FM radio cutting out. check outstanding WO replaced radio and aerial - stealth 3/5 - radio replacement to be charged to production as damage. Radio replaced by Stealth and auto greaser fixed.	PM	6/05/2024
 4007	303155-FFL1464	CATERPILLAR 988G	A/C N/W completed by Stealth 23.4.24 po-099366 inv. 00091547	Break	24/04/2024
 3806	303155-FFL1464	CATERPILLAR 988G	Safety lever for Transmisson & Bucket slow Check bucket controls. Stealth looking at 5.4.24 P/O:099030 Inv.0091724 repaired 5/4	Break	29/04/2024
 3767	303155-FFL1464	CATERPILLAR 988G	Ignition switch faulty Check machine for not starting and Found cab power solenoid faulty and Terminals on solenoid faulty. 32771hrs	Break	4/04/2024
 3731	303155-FFL1464	CATERPILLAR 988G	Beacon staying on. Stealth fixing 2.4.24 Completed by Stealth. P/O: 098942.	Break	2/04/2024
 3636	303155-FFL1464	CATERPILLAR 988G	Repairs - gears slipping Hyd levers radiator and intercooler clogged. Hyd moving on its own. Check and Operated machine found out lift raise kick out at middle. Installed laptop and Calibrated lift tilt position sensor. Tested an...		2/04/2024
 3179	303155-FFL1464	CATERPILLAR 988G	Controls playing up check for faulty controls and found lift sensor faulty. remove & replace sensor and calibrate bucket controls. 32731hrs	Correct	20/03/2024
3155	Tr120	Tr120 Twin Steer Tandem	PM1 & Repairs System automatically generates PM1, this WO to be closed, refer WO 3206 PM1 raised 20/3/24	PM	20/03/2024
 3121	303155-FFL1464	CATERPILLAR 988G	wiper needs adjusting check and adjusted wiper front test all ok greased manually all grease lines going to bucket pins 32714hrs	Correct	15/03/2024
2984	303155-FFL1464	CATERPILLAR 988G	PM1 - Victoria Plant Pool - Caterpillar 988G PM completed 32791 hrs	PM	16/04/2024
2969	303155-FFL1464	CATERPILLAR 988G	full grease check over auto Greaser top up trans oil 14.3.2024 manually greased one by one all grease lines going to bucket pins. to be checked and repaired grease fitting and dog bone to bucket broken	Correct	3/05/2024
 2681	303155-FFL1464	CATERPILLAR 988G	check auto greaser, check unit and topped up all ok	Break	9/02/2024
 2602	303155-FFL1464	CATERPILLAR 988G	Blown Hyd Hose (brake cooling system) - Reddy repaired 2/2/24 Check diff level - checked all ok check cab mounts - need replacing (1-2 day job) Side acess grills missing bolts - replaced Engine covers (between engine and r...	Break	5/02/2024
 2577	303155-FFL1464	CATERPILLAR 988G	PM2 - Victoria Plant Pool - Caterpillar 988G Carry out PM2 Service & Repairs. Cut & drill 2x 910lg. 50x50x6 angle for mud guards 32793hrs	PM	16/04/2024
2141	303155-FFL1464	CATERPILLAR 988G	Fuel leak from block on side of head completed WO 2602		14/02/2024
2140	303155-FFL1464	CATERPILLAR 988G	Radiator cap required replaced WO 2602.		14/02/2024
 2003	303155-FFL1464	CATERPILLAR 988G	PM1 - Victoria Plant Pool - Caterpillar 988G DG 23/11/2023 - Carry out PM1 service. MJS45491	PM	24/11/2023
 1854	303155-FFL1464	CATERPILLAR 988G	Bucket tooth missing Check with Luke DG 18/11/2023 - Replace 3 adaptors & 6 bucket teeth. Bucket requires 1 more adaptor changed & crack repaired. MJS45820 & MJS44405 DG 25/11/2023 - Gouge & weld crack in bucket...	Correct	16/12/2023
 1853	303155-FFL1464	CATERPILLAR 988G	Auto greaser not functioning Duplicated work order refer W/O 1068	Correct	23/11/2023
 1677	303155-FFL1464	CATERPILLAR 988G	Loader 3155 - Bucket repairs DG 09/11/2023 - Get wear plates ready for bucket repair. MJS42747 & MJS45804 DG 14/11/2023 - Repair bottom of bucket, weld on wear plates & replace 1 adaptor. MJS45811 & MJS42750 DG ...	Correct	15/11/2023
 1600	303155-FFL1464	CATERPILLAR 988G	Loader 3155 - Bucket teeth adaptors worn DG 28/10/2023 - Replace 2 worn adaptors on bucket. MJS47189 & MJS42738	Correct	30/10/2023
 1487	303155-FFL1464	CATERPILLAR 988G	Loader 3155 - PM4 service & replace GET. DG 13/10/2023 - Carry out PM4 service. MJS45076 DG 13/10/2023 - Build up adaptors for bucket teeth & replace teeth. MJS42725 DG 14/10/2023 - Continue PM4 service. MJS4507...	PM	17/10/2023
1164	303155-FFL1464	CATERPILLAR 988G	Loader 3087 PM4 service Work order has been duplicated	PM	8/09/2023
 1068	303155-FFL1464	CATERPILLAR 988G	Loader 3155 - Check auto greaser unit. DG 26/08/2023 - Check why auto greaser is not pumping but gauge is still green. on-going. MJS44025	Correct	14/02/2024
 1007	303155-FFL1464	CATERPILLAR 988G	Loader 3155 - Bucket tip missing from loader 17/08/2023 - Replaced bucket tips. Two adaptors worn so had to weld plate over tip keeper. MJS44323 replaced rear step	Correct	17/08/2023

Work Order History Listing

Search: 3155

Search

W/O No ↓	⋮	Asset No	⋮	Asset Description	⋮	Description	⋮	Job Type	⋮	Finished Date
 11632		303155-FFL1464		CATERPILLAR 988G		Wades, leaking top lift cylinder, remove, stripe, reseal and refit. tested all ok.		Break		3/02/2025
 11568		303155-FFL1464		CATERPILLAR 988G		Transmisson slipping Check transmission codes etc, wades to assess with laptop assisted cat tech run and tested machine. Conducted transmission calibration and pressure test trans pump all good. Run and tested operation o...		Break		3/03/2025
 11548		303155-FFL1464		CATERPILLAR 988G		Transmisson fault. check system, pressure test and recalibrate transmission - wades still faulting, William Adams attended site, checks system, recalibrated trans and tested. appears to be functioning better. Transmisson oil dr...		Break		28/02/2025
11412		303155-FFL1464		CATERPILLAR 988G		Replace teeth on bucket		PM		14/02/2025
11236		303155-FFL1464		CATERPILLAR 988G		Leaking tilt cylinder Wades to repair new gland seals required. removed cylinder, stripe and check, replace gland seals and retaining bolts. reassemble and test all ok.		Break		3/02/2025
 11026		303155-FFL1464		CATERPILLAR 988G		Faults list. (l/h working lamp n/w & front axle temp issue.) Checked and inspected l/h work light n/w. found out cut cable wires connection cut wires. put connection plug and re connected wiring harness. tested all good. Tem...		Correct		20/01/2025
 10854		303155-FFL1464		CATERPILLAR 988G		PM4 - Victoria Plant Pool - Caterpillar 988G Carry out PM4 Service. 33942hrs		PM		17/01/2025
 10631		303155-FFL1464		CATERPILLAR 988G		Not starting. Attended and inspected machine @ jobsite. Checked all fuses, checked batteries, checked e -stop one is stuck on. bypass it still not starting/cracking. Checked starter found out no power. Recommended elec to r...		Break		3/12/2024
10541		303155-FFL1464		CATERPILLAR 988G		noisy when operating bucket. Checked and inspected unusual sound @ bucket found out lift pins are noisy. Cleaned and removed plug both l/h & r/h/s lift pins refilled gear oil l/h & r/h/s. Installed back plugs. run & tested all g...		Correct		27/11/2024
 10379		303155-FFL1464		CATERPILLAR 988G		Oil leak. Pull off trans hose for replacement. Assisted and help Reddy fix removed & installed hydraulic hoses. Installed back all side wall covers.		Break		22/11/2024
 9826		303155-FFL1464		CATERPILLAR 988G		Transmisson fluid change - due to caution - oil sample Conducted PM 2 Service as per sheet. Drained trans oil and replaced all filters. Secured radiator wall panel. 33714hrs		PM		21/10/2024
9797		303155-FFL1464		CATERPILLAR 988G		Repair bucket. PB Teeth & pins ordered from Cat 4.10.24 done on mex 11412		Correct		17/03/2025
 9760		303155-FFL1464		CATERPILLAR 988G		Change trans fluid and filters, oil sample returned contamination oil levels for trans. duplicated WO 9826		PM		18/10/2024
9712		303155-FFL1464		CATERPILLAR 988G		PM1 - Victoria Plant Pool - Caterpillar 988G done pm2 service on mex: 9826		PM		21/10/2024
 9704		303155-FFL1464		CATERPILLAR 988G		New Tyres. New Tyres to be fitted 1/10 due to damage to two Tyres and worn out. replaced 1/10/24. 4 new tyres		Break		1/10/2024
 9703		303155-FFL1464		CATERPILLAR 988G		Oil leak & Stereo. Checked and inspected oil leak found out fuel hose line had pin hole. Called Reddy fix to fabricate hose & replaced. Removed top dash panel and fixed mounting of stereo then installed back. Washed machin...		Break		30/09/2024
9365		303155-FFL1464		CATERPILLAR 988G		Heel plate replacement on bucket. replaced 20/9 Luke		PM		20/09/2024
9353		303155-FFL1464		CATERPILLAR 988G		Fit new blue reverse lights Stealth's to install Installed 20/9		Safety		24/09/2024
 8602		303155-FFL1464		CATERPILLAR 988G		PM2 - Victoria Plant Pool - Caterpillar 988G Started PM2 Service. Finished PM2 Service. Removed & replaced cooler tap leaking. Removed & replaced wiper arm assy at front and fixed clogged jet sprayer at rear. Fit new dip sti...		PM		23/09/2024
7721		303155-FFL1464		CATERPILLAR 988G		Faults list. Auto leveling n/w. / Hose oil leak near trans & Front axle temp sensor needs replacing. getting done on Mex: 7511		Correct		24/07/2024
 7636		303155-FFL1464		CATERPILLAR 988G		PM1 - Victoria Plant Pool - Caterpillar 988G Carry out PM1 Service. Auto tilt leveling n/w, hose oil leak near trans & need to replace front axle temp sensor. No chance to fix defects production grab the machine. Mex raised for ...		PM		24/07/2024
 7511		303155-FFL1464		CATERPILLAR 988G		Auto leveling n/w. /Oil leak. / Warning lights & Front axle temp sensor u/s. Checked and located oil leak at oil sump gasket. Checked and inspected warning light. found out error 427-8 front axle oil temp sensor abnormal freq...		Break		26/08/2024
 5625		303155-FFL1464		CATERPILLAR 988G		Bucket curl control lever loosed in return position. Removed all wiring cables connected with the console and removed the cover. Removed and replaced spring at bucket curl control lever. Tested it and its good. Installed back ...		Correct		24/06/2024
5585		303155-FFL1464		CATERPILLAR 988G		Driver reported damaged wiper arm & blade. getting done on w/o:5525		Break		12/06/2024
 5525		303155-FFL1464		CATERPILLAR 988G		Gear lever for bucket controls playing up / Window washers n/w / Wiper arm bent & Heater n/w Bucket lever fixed and Windscreen washer fixed. Stealth fixed heater 11.6.24 P/o:100361. inv.00092713 Removed and replaced...		Break		12/06/2024
4759		303155-FFL1464		CATERPILLAR 988G		fire extinguisher testing replaced fire extinguishers 31/5 as part of service.		Correct		31/05/2024
 4749		303155-FFL1464		CATERPILLAR 988G		PM3 - Victoria Plant Pool - Caterpillar 988G & Repairs. Carry out PM3 Service + Defects and Fit new fire extinguisher. Locate broken grease lines & replaced. Removed and replaced hydraulic steering hose line. (Supply by Red...		PM		3/06/2024