

MARTEL'S DIESEL SERVICE (DRYDEN) LTD.

P.O. Box 814

Dryden, Ontario P8N 2Z4

Phone: (807) 937-5043 ~ Fax: (807) 937-5979

dieselservice@bellnet.ca

Tax ID# R10354 3021

Invoice



Plate ON CAT D6N LGP
Description
VIN GHS001178
Odometer 6,343

Invoice # 3779
Work Order # 12022
Service Advisor Flora Nelson
Technician Gerry Martel

Invoice Date 2022-10-26 8:26 AM
Appointment 2022-10-24 12:35 PM
Promised 2022-10-24 12:35 PM

Service

Parts

8T4192 - BOLT, 12 MM x 25 MM	24 Unit	\$1.56 / Unit	\$37.44 H
5P8245 HD - WASHER 1/2" HD	24 Unit	\$0.95 / Unit	\$22.80 H
196-7074 - WEAR STRIP	4 Unit	\$112.00 / Unit	\$448.00 H
196-7078 - WEAR STRIP	4 Unit	\$101.50 / Unit	\$406.00 H
8T0357 - BOLT 16 MM X 70 MM	64 Unit	\$4.95 / Unit	\$316.80 H
6V0937 - BOLT, SEGMENT	50 Unit	\$1.90 / Unit	\$95.00 H
7H3607 - SEGMENT NUT	50 Unit	\$2.06 / Unit	\$103.00 H
2S5658 - WASHER, 5/8	50 Unit	\$1.34 / Unit	\$67.00 H
571-6710 - CAP	2 Unit	\$125.55 / Unit	\$251.10 H
239-8090 - BLOCK	2 Unit	\$115.52 / Unit	\$231.04 H
8T0282 - BOLT	8 Unit	\$8.05 / Unit	\$64.40 H
9X8916 - BOLT	8 Unit	\$5.93 / Unit	\$47.44 H
5P8247 - 5/8" FLATWASHER	16 Unit	\$1.15 / Unit	\$18.40 H
6Y3908 - TOP ROLLER	2 Unit	\$275.00 / Unit	\$550.00 H
6V5686 - BOLT, 16 MM X 50 MM	16 Unit	\$3.85 / Unit	\$61.60 H
5P8247 - 5/8" FLATWASHER	16 Unit	\$1.15 / Unit	\$18.40 H
271-5995 - ROLLER GUARD	1 Unit	\$650.00 / Unit	\$650.00 H
		Sub	\$3,388.42

Labour

Pressure wash tractor and brought it into the shop. Checked pivot shaft and both sides are low on oil. The leak is a small amount from pivot shaft seal. Filled both sides up with oil. Released grease from track adjuster and raised onto stands. Removed track chains and removed all guarding. Had to heat with a rose bud over idler bolt to remove them and all the roller bolts. Removed roller guards and tapped out all the holes. Grind bottom of track frames and clean all the idler blocks and caps. Drill out and remove three broken idler bolts and fourteen roller bolts. Tapped out all threaded bolt holes. Installed bottom rollers and idlers with all new bolts. Removed all the old wear guides and installed all new wear guides. Removed four broken roller guard bolts and installed four new roller guards. Removed segments and cleaned hub. Re-installed segments and torqued all bolts. Installed and assembled track groups. Lowered machine off of stands. Greased track adjuster. Clean up.

63 Hour \$135.00 / Hour \$8,505.00 *H

Sub \$8,505.00

Freight

FREIGHT CHARGES
FREIGHT CHARGES

1 Unit	\$255.10 / Unit	\$255.10 H
1 Unit	\$45.36 / Unit	\$45.36 H
	Sub	\$300.46

Total Parts		\$3,688.88
Total Labor		<u>\$8,505.00</u>
Total Before Taxes & Miscellaneous Charges		\$12,193.88
(*) Shop Supplies		\$510.30 H
(H) Canadian Harmonized Sales Tax (13% HST)	13 %	<u>\$1,651.54</u>
Grand Total		\$14,355.72

██████████. charged \$14,355.72 to Account - 215 - ██████████. - Net 30 Days

Thanks for the Business!
I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature: _____