



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 11/20/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 1 of 2
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

**GEN28- Internal**

**COMPLAINT:**

28 DIAGNOSE ECU PROBLEM

**CORRECTION:**

Diagnosed ecu codes to be missing calibration numbers for doc and dpf. Had to reach out to dtac to get the numbers. Input numbers and engine derate and emissions codes went away. Looked up and diagnosed coolant pressure sensor code. Found that there was no supply voltage at the sensor. Traced wiring and found wires got hot and melted inside loom from exhaust heat. Replaced broken chunk of wire and routed wires farther from exhaust heat. Looked into last ecu code and found the egr valve was needing to be replace. Replaced egr valve and calibrated. Ran tractor to make sure code did not return.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
57M10321	Elec. Connector Terminal	3.00	4.76	4.76	\$14.28	N
TY26184	1/4" Slit Loom	2.00	1.46	1.46	\$2.92	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
<b>Labor: \$2,060.28</b>		<b>Parts: \$17.20</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$96.00</b>
						<b>Sub-Total: \$2,173.48</b>

**/1419139560RT Internal**

**COMPLAINT:**

29 REPLACE EGR COOLER

**CORRECTION:**

Removed exhaust side egr pipe and egr cooler was full of coolant. Egr cooler needs to be replaced. Drained coolant from engine and removed egr cooler piping and cooler. Installed new cooler and installed piping with new egr valve and gaskets. Filled engine with coolant and ran tractor to make sure of no leaks.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7803	Flange Head Cap Screw M8 X 70 GR10.9	3.00	4.48	4.48	\$13.44	N
DZ121743	EXHAUST GA	1.00	1,727.32	1,727.32	\$1,727.32	N
DZ121743-CR	CORE for:Exhaust Gas Recycling Valve	-1.00	139.00	139.00	(\$139.00)	N



Box 400  
 Highway 6  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2110  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone:  
Prv Phone:

Bus Phone:  
Prv Phone:

Invoice Number:  
 Invoice Date: 11/20/2024  
 Location:  
 Work Order Number:  
 Payment Type:  
 Page: 2 of 2

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2013 JD 9560R TRACTOR	3860	1RW9560RKCP006084	1RW9560RKCP006084	

/1419139560RT Internal		Quantity	List Price	Net Price	Extended Price	Taxed Ind
R526831	GASKET	4.00	22.18	22.18	\$88.72	N
R536559	Gasket	1.00	36.79	36.79	\$36.79	N
RE560117	Heat Exchanger	1.00	4,598.51	4,598.51	\$4,598.51	N
Miscellaneous SERVACCESS	Description SERVICE ACCESSORIES	1.00	53.10	53.10	\$53.10	N
<b>Labor: \$885.00</b>	<b>Parts: \$6,325.78</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$53.10</b>	<b>Sub-Total: \$7,263.88</b>		

Customer PO No:  
 Tax Exempt No:  
 Advisor:

<b>Labor:</b>	\$2,945.28
<b>Parts:</b>	\$6,342.98
<b>OL&amp;M:</b>	\$0.00
<b>Misc:</b>	\$149.10
<b>Grand Total:</b>	<b>\$9,437.36</b>

\*\*\* DOCUMENT COPY \*\*\*

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
	00	00	160	1	146887	USED AG EQUIPMENT
	07	40	382	1	10020	INTERNAL LABOR-AG
	00	00	178	17	10020	WORK IN PROCESS PARTS -MJ
	07	40	482	1	10020	COS INTERNAL LABOR-AG
	07	30	366	2	10020	JD PARTS-COUNTER
	00	00	166	7	10020	JD PARTS-MOOSE JAW
	07	40	544	1	10020	SUPPLIES EXPENSE
	07	30	466	2	10020	JD PARTS-COUNTER

**TERMS AND CONDITIONS**

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: .....Date: .....