



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 1 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/160048S670 Internal

COMPLAINT:

03 STRAIGHTEN TOP FEEDER HOUSE DOOR

CORRECTION:

REMOVED TOP FEEDERHOUSE DOOR, STRAIGHTENED THE SIDES AND THAN PUT IT IN THE PRESS AND STRAIGHTENED THE MIDDLE, COMPLETED

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$93.81		

/110596S670 Internal

COMPLAINT:

04 STRAIGHTEN STONE TRAP DOOR

CORRECTION:

REMOVED STONE TRAP DOOR, HAD TO PRESS IT OUT IN A FEW DIFFERENT SPOTS, REINSTALLED DOOR AND MECHANISM, COMPLETED

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$93.81		

/120301S670 Internal

COMPLAINT:

05 REPLACE 3 SINGLE POINT SHEAR BOLT

CORRECTION:

REMOVED BROKEN SHEAR BOLT AND INSTALLED NEW ONE, ADDED SPARES

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 2 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/120301S670 Internal

14M7264	Hex Lock Nut M4	3.00	0.52	0.52	\$1.56	N
19M9326	Socket Head Screw M4 X 30 GR12.9	3.00	2.12	2.12	\$6.36	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N
Labor: \$44.25	Parts: \$7.92	OL&M: \$0.00	Misc: \$2.66	Sub-Total: \$54.83		

/110049S670 Internal
 COMPLAINT:
 06 CHANGE OIL IN PRIMARY COUNTERSHAFT GEARCASE (OIL DIRTY)

CORRECTION:
 DRAINED OIL IN COUNTERSHAFT GEAR BOX, ADDED NEW OIL, VERIFIED CORRECT LEVEL, COMPLETED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6296	946ML 80W90 GL-5	2.00	15.99	15.99	\$31.98	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF50	ENVIRO FEE	2.00	0.50	0.50	\$1.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00	Parts: \$31.98	OL&M: \$0.00	Misc: \$11.62	Sub-Total: \$220.60		

/150029S670 Internal
 COMPLAINT:
 07 REPLACE CAB FILTERS AND CLEAN PLASTIC GRATE

CORRECTION:
 REMOVED AND REPLACED BOTH CAB FILTERS, CLEANED OUT GRATES, COMPLETED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 2/19/2025 Location: 06 Work Order Number: Payment Type: Account Page: 3 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/150029S670 Internal

L214634	Cab Ricirculation Air Filter	1.00	48.62	48.62	\$48.62	N
TA32591	Cab Fresh Air Filter	1.00	135.85	135.85	\$135.85	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N

Labor: \$53.10 Parts: \$184.47 OL&M: \$0.00 Misc: \$3.19 Sub-Total: \$240.76

/101801200S670 Internal

COMPLAINT:
 08 REPLACE FEED ACCELERATOR SUPPORT RIGHT AND LEFT (OFFSETS),(1 OR 2)

CORRECTION:
 REMOVED BENT SLATS, FOUND 3 BROKEN OFF BOLTS IN FEED ACCELERATOR, HAD TO REMOVE MOST OF THE SLATS, WAS ABLE TO DRILL 2/3 OUT AND EXTRACT THEM, TRIED DRILLING OUT THE 3RD ONE AND HEATING, CLEANED OUT FEED ACCELERATOR AND BLEW IT ALL OUT, WELDED A NUT TO BROKEN OFF BOLT AND EXTRACTED, REINSTALLED ALL REMOVED SLATS, FOUND THE FEED ACCELERATOR TO BE TICKING AFTER INSTALLING ALL SLATS, FOUND A BENT SLAT, REMOVED AND STRAIGHTENED IT, REINSTALLED TOP COVERS COMPLETED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7786	Flange Head Cap Screw M10 X 30 GR10.9	3.00	2.55	2.55	\$7.65	N
H166181	Beater Wing Support Offset Left	3.00	282.29	282.29	\$846.87	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N

Labor: \$531.00 Parts: \$854.52 OL&M: \$0.00 Misc: \$31.86 Sub-Total: \$1,417.38

/140319S670 Internal

COMPLAINT:
 09 REPLACE INNER CLEANING FAN SHEAVE AND DRIVE PINS (REAR HUB WORE AND SLOPPY)

CORRECTION:



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 4 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/140319S670 Internal

REMOVED BELT, AND OUTER SHEAVE, REMOVED INNER SHEAVE AND REPLACED, PRESSED OUT OLD PINS AND PRESSED NEW ONES IN, REINSTALLED BELT AND GREASED COMPLETED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
A-H161051	Sheave Assembly	1.00	358.17	358.17	\$358.17	N
R1964R	Dowel Pin	3.00	42.96	42.96	\$128.88	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N
Labor: \$442.50		Parts: \$487.05		OL&M: \$0.00		Misc: \$26.55
						Sub-Total: \$956.10

/110071S670 Internal

COMPLAINT:
10 REMOVE HALF LINK FROM CLEAN GRAIN PADDLE CHAIN AND ADJUST

CORRECTION:
REMOVED BELT, SPUN UNTIL I FOUND THE HALF LINK, REMOVED HALF LINK AND REATTACHED CHAIN, SET TENSION COMPLETED

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$0.00		OL&M: \$0.00		Misc: \$5.31
						Sub-Total: \$93.81

GEN11- Internal

COMPLAINT:
11 REPLACE CLEAN GRAIN CHAIN TENSION BOLT

CORRECTION:
CUT OUT BENT BOLT, INSTALLED NEW ONE, COMPLETED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 5 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

GEN11- Internal

19M8241	Hex Head Cap Screw M10 X 100 GR8.8	1.00	5.53	5.53	\$5.53	N
E63525	NUT	3.00	1.41	1.41	\$4.23	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N

Labor: \$88.50 Parts: \$9.76 OL&M: \$0.00 Misc: \$5.31 Sub-Total: \$103.57

/10040200S670 Internal

COMPLAINT:
 12 R&R OR REPLACE BATTERY(IES) (RH SIDE)

CORRECTION:
 REMOVED COVER, REMOVED BATTERY, BLEW OUT BOX, INSTALLED NEW BATTERY AND REINSTALLED COVER, COMPLETED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY25879A-PL	Wet Charged Battery,BCI 31,CCA 950	2.00	262.14	262.14	\$524.28	N
TY25879A-PL-CR	CORE for:Wet Charged Battery	-2.00	27.00	27.00	(\$54.00)	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N

Labor: \$177.00 Parts: \$470.28 OL&M: \$0.00 Misc: \$10.62 Sub-Total: \$657.90

/120018S670 Internal

COMPLAINT:
 13 REPLACE FUEL FILTERS, CLEAN FUEL PRE-SCREEN

CORRECTION:
 REPLACED FUEL FILTERS AND CLEANED STRAINER

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 6 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/120018S670 Internal

DZ112918	Secondary Engine Fuel Filter (Long)	1.00	228.91	228.91	\$228.91	N
DZ130550	Primary Engine Fuel Filter	1.00	225.31	225.31	\$225.31	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$454.22	OL&M: \$0.00	Misc: \$9.97	Sub-Total: \$596.94	

GEN14- Internal
 COMPLAINT:
 14 WELD HOLES IN REAR BOTTOM CHOPPER DOOR

CORRECTION:
 CUT OUT PLATES, WELDED 3 HOLES IN CHOPPER FLOOR, PAINTED COMPLETED

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62	

/120060S670 Internal
 COMPLAINT:
 15 REPLACE ENGINE AIR FILTERS

CORRECTION:
 REMOVED AND REPLACED ENGINE AIR FILTERS, CLEANED OUT HOUSING COMPLETED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE11090	Primary Air Filter	1.00	448.07	448.07	\$448.07	N



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 2/19/2025	Location: 06	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: Account	Page: 7 of 18
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/120060S670 Internal

HXE11091	Secondary Air Filter	1.00	316.16	316.16	\$316.16	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$764.23		OL&M: \$0.00		Misc: \$5.31
				Sub-Total: \$858.04		

/120000S670 Internal
 COMPLAINT:
 16 CHANGE ENGINE OIL AND FILTER

CORRECTION:
 DRAINED AND FILLED OIL, CHANGED FILTER, COMPLETED



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE509672	Engine Oil Filter Cartridge	1.00	47.42	47.42	\$47.42	N
TY26675	9.46L 15W40 PLUS 50 II	1.00	89.73	89.73	\$89.73	N
TY26679	18.9L 15W40 PLUS 50 II	1.00	170.86	170.86	\$170.86	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
EF300	ENVIRO FEE	1.00	3.00	3.00	\$3.00	N
EF50	ENVIRO FEE	1.00	0.50	0.50	\$0.50	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$308.01		OL&M: \$0.00		Misc: \$12.47
				Sub-Total: \$453.23		

GEN17- Internal
 COMPLAINT:
 17 WELD MOUNTING BRACKETS ON REAR ENGINE GULL WING DOOR (MOUNTING BRACKETS BROKEN OFF)



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 8 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

GEN17- Internal

CORRECTION:

REMOVED AND SUPPORTED ENGINE GULL WING DOOR, REMOVED HANDLE, CUT A SUPPORT PIECE OUT OF SCRAP, WELDED IT IN AND PAINTED, REINSTALLED HANDLE AND GULL WING, COMPLETED

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$281.43		

/15131S670 Internal

COMPLAINT:

18 REPLACE SHOE DRIVE SHAFT BEARINGS(NOT INCLUDING PITMANS)

CORRECTION:

REMOVED SLIP CLUTCH SHEAVE ON RIGHT HAND SIDE, REMOVED SPEED SENSOR TONE RING ON LH SIDE, LOOSENED OFF ALL GEARS AND BEARINGS, HAD TO HEAT UP AND TORCH 2 INNER BEARINGS OFF, CLEANED UP SHAFT, INSTALLED NEW BEARINGS AND LOCK COLLARS, SET GEAR MESH TO SPEC, REINSTALLED SHEAVE, GREASED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
JD8554	Eccentric Locking Collar	3.00	11.02	11.02	\$33.06	N
JD8665	1" Ball Bearing	4.00	24.83	24.83	\$99.32	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N
Labor: \$531.00	Parts: \$132.38	OL&M: \$0.00	Misc: \$31.86	Sub-Total: \$695.24		

/101801401S670 Internal

COMPLAINT:

19 REPLACE THRESHING SEPARATOR ELEMENTS (2 MATCHED SETS) (2 BROKEN)

CORRECTION:



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 9 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/101801401S670 Internal

REMOVED ALL CONCAVES AND 1 SEPERATOR GRATE, REPLACED 2 SETS OF ELEMENTS, TORQUED TO SPEC, REINSTALLED CONCAVES AND GRATE, COMPLETED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH216677	Threshing Elements Std Rows 3-5	2.00	539.64	539.64	\$1,079.28	N
Miscellaneous	DESCRIPTION	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
Labor: \$354.00		Parts: \$1,079.28	OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$1,454.52	

/170452S670 Internal

COMPLAINT:
 20 REPLACE LOADING AUGER GEARCASE DIPSTICK (DIPSTICK MISSING)

CORRECTION:
 REPLACED LOADING AUGER GEAR CASE DIPSTICK AND VERIFIED LEVEL

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH166047	Dipstick	1.00	42.44	42.44	\$42.44	N
Miscellaneous	DESCRIPTION	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	1.06	1.06	\$1.06	N
Labor: \$17.70		Parts: \$42.44	OL&M: \$0.00	Misc: \$1.06	Sub-Total: \$61.20	

/150052S670 Internal

COMPLAINT:
 21 REPLACE LOADING AUGER DRIVE COUPLER (WORE OUT AUGER SIDE)

CORRECTION:
 REMOVED LOADING AUGER, FOUND THE BEARING TO BE ROUGH, REMOVED AND REPLACED BEARING, ORDERED A NEW LOADING AUGER AND GOT THE WRONG ONE, ORDERED THE RIGHT ONE



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 2/19/2025 Location: 06 Work Order Number: Payment Type: Account Page: 10 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/150052S670 Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
A-AXE13122	Auger	1.00	1,214.50	1,214.50	\$1,214.50	N
A-H136186	Driver	1.00	83.92	83.92	\$83.92	N
JD10384	Ball Bearing	1.00	77.51	77.51	\$77.51	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N

Labor: \$265.50 Parts: \$1,375.93 OL&M: \$0.00 Misc: \$15.93 Sub-Total: \$1,657.36

GEN22- Internal

COMPLAINT:
 22 REPLACE MISSING BUBBLE UP AUGER FOLD ARM NUT

CORRECTION:
 INSTALLED MISSING NUT ON LOADING AUGER

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N

Labor: \$44.25 Parts: \$0.00 OL&M: \$0.00 Misc: \$2.66 Sub-Total: \$46.91

/140702S670 Internal

COMPLAINT:
 23 REPLACE WARNING LIGHT BULB (RH REAR TAIL LIGHT VERY DIM)

CORRECTION:
 CHECKED POWER AND GROUND, HAD POWER AND GROUND, REPLACED BULB

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 2/19/2025 Location: 06 Work Order Number: Payment Type: Account Page: 11 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/140702S670 Internal								
RE49778	BULB (3157)	2.00	3.74	3.74	\$7.48	N		
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>		
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N		
Labor: \$44.25	Parts: \$7.48	OL&M: \$0.00	Misc: \$2.66	Sub-Total: \$54.39				

GEN24- Internal
 COMPLAINT:
 24 REPLACE RH FRONT FEEDERHOUSE LIGHT (BURNT OUT)

CORRECTION:
 REMOVED BULB AND REPLACED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH208904	BULB	1.00	39.43	39.43	\$39.43	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
Labor: \$53.10	Parts: \$39.43	OL&M: \$0.00	Misc: \$3.19	Sub-Total: \$95.72		

/4010DS670 Internal
 COMPLAINT:
 25 REPLACE FRONT TURN SIGNAL, TAIL, WARNING (FLASHER) OR SIDE LIGHT BULB (LH FRONT SIGNAL LIGHT BURNT OUT)

CORRECTION:
 REMOVED AND REPLACED, COMPLETED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE185880	Bulb H9	1.00	42.88	42.88	\$42.88	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 12 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/4010DS670 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
Labor: \$53.10		Parts: \$42.88	OL&M: \$0.00	Misc: \$3.19	Sub-Total: \$99.17	

/10180250S670 Internal
 COMPLAINT:
 26 CONCAVE LEVEL, ADJUST, AND CALIBRATE

CORRECTION:
 REMOVED A SEPERATOR GRATE, SET CONCAVE AS PER MANUAL, REINSTALLED SEPERATOR GRATE COMPLETED

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N
Labor: \$221.25		Parts: \$0.00	OL&M: \$0.00	Misc: \$13.28	Sub-Total: \$234.53	

/142253S670 Internal
 COMPLAINT:
 27 REMOVE CHAFFER FRAME AND REPLACE SHOE SHAKER ARMS

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7291	Flange Nut M16	3.00	4.97	4.97	\$14.91	N
14M7299	Flange Nut M12	1.00	2.79	2.79	\$2.79	N
19M7820	Flange Head Cap Screw M12 X 100 GR10.9	1.00	9.67	9.67	\$9.67	N
19M7847	Flange Head Cap Screw M16 X 180 GR10.9	1.00	21.21	21.21	\$21.21	N
19M8486	Hex Head Cap Screw M16 X 180 GR10.9	1.00	21.48	21.48	\$21.48	N
AH219844	Shaker Arm Left	1.00	508.01	508.01	\$508.01	N



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 2/19/2025 Location: 06 Work Order Number: Payment Type: Account Page: 13 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/142253S670 Internal

H227582	Flange Head Capscrew M16 X 135	1.00	19.09	19.09	\$19.09	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$2,124.00		Parts: \$597.16		OL&M: \$0.00		Misc: \$96.00
				Sub-Total: \$2,817.16		

/15063S670 Internal

COMPLAINT:
 28 TORQUE NUT TO SPEC ON FEEDER HOUSE SLIP CLUTCH (NUT LOOSE)

CORRECTION:
 REMOVED COTTER PIN, TORQUED NUT, REINSTALLED COTTER PIN COMPLETED

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.12	2.12	\$2.12	N
Labor: \$35.40		Parts: \$0.00		OL&M: \$0.00		Misc: \$2.12
				Sub-Total: \$37.52		

GEN29- Internal

COMPLAINT:
 29 REPLACE SINGLE POINT ELECTRIC PLUG SNAP RING

CORRECTION:
 REPLACED SINGLE POINT SNAP RING, COMPLETED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H175881	SNAP RING	1.00	7.36	7.36	\$7.36	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 14 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

GEN29- Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N	
Labor: \$53.10	Parts: \$7.36	OL&M: \$0.00	Misc: \$3.19	Sub-Total: \$63.65			

GEN30- Internal
 COMPLAINT:
 30 FEEDER CHAIN LOWER TENSIONER SPROCKET BEARING LOOSE AND NOISY

CORRECTION:
 REMOVED SPROCKET, REPLACED, SET CHAIN TENSION, COMPLETED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE19940	Idler Sprocket.	1.00	92.46	92.46	\$92.46	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.72	3.72	\$3.72	N
Labor: \$61.95	Parts: \$92.46	OL&M: \$0.00	Misc: \$3.72	Sub-Total: \$158.13		

/140486S670 Internal
 COMPLAINT:
 31 ADJUST ALL BELTS AND CHAINS TENSIONS

CORRECTION:
 ADJUSTED ALL BELTS AND CHAINS, COMPLETED

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62		

/110081S670 Internal
 COMPLAINT:



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 15 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/110081S670 Internal
 32 R&R SIEVE AND CHAFFER TO CHECK FOR CRACKS
 (DO NOT NEED TO DO IF WE DO SEG 27)

CORRECTION:

OL&M Charges:

Description	Value
REPAIR CHAFFER ELEMENT	\$159.60
Labor: \$0.00	
Parts: \$0.00	
OL&M: \$159.60	
Misc: \$0.00	
Sub-Total: \$159.60	

/120014S670 Internal
 COMPLAINT:
 33 GREASE COMBINE

CORRECTION:
 COMPLETED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY6341	SD POLYUREA GREASE	1.00	10.54	10.54	\$10.54	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00						
Parts: \$10.54						
OL&M: \$0.00						
Misc: \$10.62						
Sub-Total: \$198.16						

/10180310S670 Internal
 COMPLAINT:
 34 R&R STS ROTOR FRONT BEARING

CORRECTION:



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 16 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/10180310S670 Internal

REMOVED TOP COVERS AND SHIELDS, REMOVED SIDE COVERS, REMOVED GREASE LINE AND SPEED SENSOR, REMOVED A CONCAVE AND INSTALLED A PIECE OF WOOD WITH A HYDRAULIC JACK ON TOP TO SUPPORT ROTOR, LOOSENED OFF BEARING SPEED SENSOR TONE RING AND REMOVED, LOOSENED BEARING AND BEGAN REMOVING, BEARING WAS SEIZED ONTO ROTOR, CLEANED SHAFT AND LUBED, USED AIR HAMMER AND PRY BARS TO SLOWLY WALK BEARING OFF OF ROTOR, ONCE BEARING WAS REMOVED I CLEANED AND DE BURRED SHAFT, INSTALLED NEW BEARING, REINSTALLED SPEED SENSOR AND COVERS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M7662	Hex Head Cap Screw M10 X 30 GR10.9	2.00	2.10	2.10	\$4.20	N
AXE42868	Bearing with Housing	1.00	568.69	568.69	\$568.69	N
H135891	Flange Lock Nut M10	2.00	2.26	2.26	\$4.52	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	47.79	47.79	\$47.79	N
Labor: \$796.50		Parts: \$577.41		OL&M: \$0.00		Misc: \$47.79
						Sub-Total: \$1,421.70

/GLOPCLEANS670 Internal

COMPLAINT:
 35 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:

___ WASH COMPLETE MACHINE (OPEN & WASH BEHIND ALL SHIELDS) ___ WAX IF REQUIRED ___ REMOVE ANY OTHER DEALER DECALS ___ INSTALL SCE DEALERSHIP DECALS ___ ALL FACTORY SAFETY AND MODEL DECALS IN GOOD CONDITION ___ REMOVE CAB FLOORMAT AND CLEAN MAT AND FLOOR ___ CLEAN SEAT AND REMOVE STAINS IF NECESSARY ___ VACUUM CAB THOROUGHLY ___ CLEAN INSTRUMENT PANEL, OPERATOR CONTROLS, UPHOLSTERY, AND AIR DELIVERY LOUVERS ___ CLEAN WINDOWS AND MOLDINGS (OPEN WINDOWS TO CLEAN EDGES WHERE APPLICABLE) ___ ELIMINATE ANY CAB ODORS AND INSTALL AIR FRESHENER IF REQUIRED ___ PAINT AREAS THAT ARE BADLY SCRATCHED/DAMAGED-INCLUDING BUCKETS, GRAPPLES, WHEELS, EXHAUST, PLATFORM AUGERS (COMPLETE AUGER), CHOPPER FINS, FEEDERHOUSE DRUMS, BALER PICKUPS

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 17 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/GLOPCLEANS670 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$1,872.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$96.00	Sub-Total: \$1,968.00	

/4GMTGUPGRADES670 Internal
 COMPLAINT:
 36 REMOVE 2G/3G MTG AND INSTALL NEW 4G MTG

CORRECTION:
 OLD/REMOVED MTG SN# PCMAMGA768899
 NEW/INSTALLED MTG SN# PCMA4RA869294
 replaced old mtg with new mtg and made sure it converted over. all okay

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
021TPC	JDLink R Modem 4G	1.00	311.00	311.00	\$311.00	N
14M7303	Flange Nut M6	2.00	0.87	0.87	\$1.74	N
19M10529	Hex Socket Button Screw M6 X 12 GR10.9	2.00	3.54	3.54	\$7.08	N
HXE174177	MTG Module Retianer Clip	1.00	9.81	9.81	\$9.81	N
HXE174178	MTG Bracket Adapter Mount	1.00	8.48	8.48	\$8.48	N
HXE174363	MTG Module Clip	2.00	7.05	7.05	\$14.10	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind



Box 129
 Highway 6 & 22
 Southey, SK S0G 4P0
 Phone: 306-726-2155
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 2/19/2025 Location: 06 Work Order Number: [REDACTED] Payment Type: Account Page: 18 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2012 JOHN DEERE S670	3245	1H0S670SJB0745608	1H0S670SJB0745608	

/4GMTGUPGRADES670 Internal					
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62 N
Labor: \$177.00		Parts: \$352.21	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$539.83

Customer PO No:	[REDACTED]
Tax Exempt No:	[REDACTED]
Advisor:	[REDACTED]

Labor: \$9,633.45
Parts: \$7,929.40
OL&M: \$159.60
Misc: \$537.79
Grand Total: \$18,260.24

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	147779			USED AG EQUIPMENT
06 40	382	1	815773			INTERNAL LABOR-AG
00 00	178	16	815773			WORK IN PROCESS PARTS -MJ
06 40	394	0	815773			OUTSIDE LABOR & MATERIAL
00 00	249	6	439724			PFW CLEARING ACCOUNT
06 40	482	1	815773			COS INTERNAL LABOR-AG
06 40	494	0	815773			OUTSIDE LABOR&MATERIAL
06 40	544	1	815773			SUPPLIES EXPENSE
06 30	366	2	815773			JD PARTS-COUNTER
00 00	166	6	815773			JD PARTS-MOOSE JAW
06 30	375	3	815773			PARTS SPECIAL HANDLING
06 30	466	2	815773			JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: